Available from

GPO Sales Program
Division of Technical Information and Document Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Printed copy price: \$9.00

and

National Technical Information Service Springfield, Virginia 22161

.

Title List of Documents Made Publicly Available

April 1-30, 1980

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	2
Domestic Licensing of Production and Utilization Facilities - Docket 50	8
Domestic Licensing of Special Nuclear Material – Docket 70	334
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions - Docket 71	349
Nondocketed Items	357
10CFR — Commission Meeting Records	357
ACRS — Advisory Committee on Reactor Safeguards	357
COMMISSION — NRC Commissioners	361
CONTRACT — NRC Contracts and Modifications	364
FOIA — Freedom of Information Act Requests and Releases	367
GEN TECH IS — Generic Technical Issues	375
I&E — Inspection and Enforcement	375
MISC — Public Document Room Miscellaneous	376
NUREG — NUREG Reports and Related Correspondence	378
ORG — Correspondence with Other Organizations	381
PR — Proposed Rule	382
PRM — Petition for Rulemaking	387
PROJ — Projects - Predocket Licensing	388
PT21 — Noncompliance Reports and Related Correspondence	388
QA999 — Quality Assurance Inspections	389
REGGD — Regulatory Guides	392
RES — Research and Technical Assistance Reports	393
REVIEW GRP — NRC Research Review Groups	395
SECY — Position Papers Before the Commission	395
STATE PROG — State Programs	396
TOPREP — Vendor Reports and Related Correspondence	398
WASTE MGT — Nuclear Waste Management	400
XPORTLIC — Export and Import Licenses	402
Personal Author Index	409
Corporate Source Index	443
Report Number Index	475
Cross Reference of Enclosures to Principal Documents	477
Appendix A - Definitions of Docket 50 Categories	495
Appendix R - Definitions of Nondocketed Categories	503

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:


1

P. Operating license stage documents & correspondence



7904170015 Forwards info on TMI:JM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations.



- I NRC/PDR Document category (see Appendix A)
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
 ACRS — Advisory Committee on Reactor Safeguards
 COMMISSION — NRC Commissioners
 CONTRACT — NRC Contracts and Modifications

FOIA - Freedom of Information Act Requests and Releases

GEN TECH IS - Generic Technical Issues

I&E - Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG - Correspondence with other organizations

PR - Proposed Rule PRM - Petition for Rulemaking PROJ - Projects-Predocket Licensing PT21 - Noncompliance Reports and Related Correspondence QA999 - Quality Assurance Inspections REGGD - Regulatory Guides RES - Research and Technical Assistance Reports REVIEW GRP - NRC Research Review Groups RM - Rulemakings SECY - Position Papers Before the Commission STATE PROG - State Programs

TOPREP - Vendor Reports and Related Correspondence

WASTE MGT - Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

(10)

The principal elements of the nondocketed items are:

(1) NUREG - NUREG Reports and Related Correspondence 7901060007 NUREG/CR-0161 "Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs. FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory. FIN A-2093. 78/11/30. 26pp. Available at NTIS.

- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on the next page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-039	Sheffield, IL, Nuclear Engineering Co.	1	40-8380	Rocky Mountain Energy Co.	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8452	Bear Creek Uranium Co.	6
27-048	Richland, WA, Nuclear Engineering Co.	2	40-8502	Irigaray Mine, Wyoming Mining Corp.	6
40-0215	S.F. Appliance, Ltd.	2	40-8584	Union 76 Minerals Exploration Co.	7
40-0261	Kerr-McGee Chemical Co.	3	40-8602	United Nuclear Corp.	7
40-0299	Union Carbide Corp.	3	40-8647	Kerr-McGee Corp.	7
40-0672	Nuclear Metals, Inc.	3	40-8675	Energy Fuels Nuclear, Inc	7
40-1162	Western Nuclear, Inc.	3	40-8681	Energy Fuels Nuclear, Inc.	7
40-1193	Babcock & Wilcox Co.	3	40-8698	Plateau Resources, Ltd.	8
40-1341	Edgemont Uranium Mine, TVA, and Mines	3	40-8721	Rocky Mountain Energy Co.	8
10.0051	Development, Inc.		40-8722	Brush-Wellman, Inc.	8
40-2061	West Chicago Facility, Kerr-McGee Corp.	4	40-8727	Kerr-McGee Nuclear Corp.	8
40-2259	Pathfinder Mines Corp.	4	40-8728	Teton Exploration Drilling Co., Inc.	8
40-2286	Westinghouse Electric Co.	4	40-8745	Ogle Petroleum	8
40-3453	Atlas Minerals	4	40-8760	Edlow International Corp.	8
40-4492	Federal American Partners (Mining)	5	40-8768	Kerr-McGee Nuclear Corp.	8
40-6329	Catholic Univ. of America	5		·	_
40-6622	Pathfinder Mines Corp.	5	50-2	Univ. of Michigan Research Reactor	8
40-6659	Petrotomics Co., Getty Oil Co.	5	50-3	Indian Point Station, Unit 1	9
40-7127	Univ. of Toledo	5	50-10	Dresden Nuclear Power Station, Unit 1	11
40-7982	Honeywell, Inc	5	50-13	Babcock & Wilcox Co. Critical Facility	14
40-8027	Kerr-McGee Corp.	6	50-18	Vallecitos Boiling Water Reactor	14
40-8064	Exxon Minerals Co. USA, Exxon	6	50-29	Yankee-Rowe Nuclear Power Station	14
10 0001	Corp.	Ü	50-30	Plum Brook Research Reactor Facility	15
40-8102	Exxon Minerals Co. USA, Exxon Corp	6	50-54	Union Carbide Research Reactor	16
10.0125	•		50-57	State Univ. of New York Research Reactor	16
40-8135	3M Co., Minnesota Mining and Manufacturing Co.	6	50-70	General Electric Test Reactor	16
40-8304	Wyoming Mining Corp.	6	50-73	General Electric Nuclear Test Reactor	16

Docket	Name	Page	Docket	Name	Page
50-111	North Carolina State Univ. Research	16	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	33
	Reactor		50-245	Millstone Nuclear Power Station, Unit 1	34
50-123	Univ. of Missouri Research Reactor	17	50-247	Indian Point Station, Unit 2	37
50-124	Virginia Polytech Institute Training Reactor	17	50-249	Dresden Nuclear Power Station, Unit 3	40
50-128	Texas A&M Univ. Research Reactor	17	50-250	Turkey Point Plant, Unit 3	42
50-133	Humboldt Bay Power Plant, Unit 3	17	50-251	Turkey Point Plant, Unit 4	46
50-137	Turkey Research Reactor	18			
50-142	UCLA Training Reactor	18	50-254	Quad-Cities Station, Unit 1	49
50-150	Ohio State Univ. Research Reactor	18	50-255	Palisades Nuclear Plant	51
50-151	Univ. of Illinois Research Reactor	18	50-259	Browns Ferry Nuclear Power Station, Unit 1	54
50-155	Big Rock Point Nuclear Plant	18	50-260	Browns Ferry Nuclear Power Station, Unit 2	56
50-160	Georgia Institute of Technology Research Reactor	21	50-261	H.B. Robinson Plant, Unit 2	59
50-163	General Atomic Co.	21	50-263	Monticello Nuclear Generating Plant	60
50-166	Univ. of Maryland Research Reactor	21	50-264	Dow Chemical Co.	62
50-170	National Naval Medical Center	21	50-265	Quad-Cities Station, Unit 2	62
50-171	Peach Bottom Atomic Power Station, Unit 1	21	50-266	Point Beach Nuclear Plant, Unit 1	64
50-182	Purdue Univ. Research Reactor	22	50-267	Fort St. Vrain Nuclear Generating Station	66
50-183	Vallecitos Experimental Superheat Reactor	22	50-268	Midwest Fuel Recovery Plant	67
50-184	National Bureau of Standards Reactor	22	50-269	Oconee Nuclear Station, Unit 1	67
50-189	University Training Reactor	22	50-270	Oconce Nuclear Station, Unit 2	70
50-193	Rhode Island & Providence Plantations	22	50-271	Vermont Yankee Nuclear Power Station	72
30-173	AEC	24	50-272	Salem Nuclear Generating Station, Unit 1	74
50-201	West Valley Reprocessing Plant	22	50-275	Diablo Canyon Nuclear Power Plant,	77
50-206	San Onofre Nuclear Station, Unit 1	23		Unit 1	
50-213	Haddam Neck Plant	25	50-276	Georgia Tech Research Reactor	80
50-219	Oyster Creek Nuclear Power Plant	27	50-277	Peach Bottom Atomic Power Station, Unit 2	80
50-220	Nine Mile Point Nuclear Station, Unit I	29	50-278	Peach Bottom Atomic Power Station,	82
50-224	Univ. of California Research Reactor	30	ro 000	Unit 3	
50-225	RPI Critical Experiment	30	50-280	Surry Power Station, Unit 1	84
50-228	Aerotest Radiography & Research Reactor	30	50-281	Surry Power Station, Unit 2	86
50-237	Dresden Nuclear Power Station, Unit 2	30	50-282	Prairie Island Nuclear Station, Unit 1	88
50-243	Oregon State Univ. Research Reactor	33	50-285	Fort Calhoun Station, Unit 1	90

Docket	Name	Page	Docket	Name	Page
50-286	Indian Point Station, Unit 3	91	50-329	Midland Plant, Unit 1	174
50-287	Oconee Nuclear Station, Unit 3	95	50-330	Midland Plant, Unit 2	175
50-289	Three Mile Island Nuclear Station, Unit 1	97	50-331	Duane Arnold Energy Center	177
50-293	Pilgrim Nuclear Power Station, Unit 1	108	50-332	Barnwell Reprocessing Plant	179
50-294	Michigan State Univ. Research Reactor	110	50-333	James A. Fitzpatrick Nuclear Power Plant	179
50-295	Zion Nuclear Power Station, Unit 1	110	50-334	Beaver Valley Power Station, Unit 1	181
50-296	Browns Ferry Nuclear Power Station, Unit 3	114	50-335	St. Lucie Plant, Unit 1	184
50-298	Cooper Nuclear Station	116	50-336	Millstone Nuclear Power Station, Unit 2	186
50-301	Point Beach Nuclear Plant, Unit 2	117	50-338	North Anna Power Station, Unit 1	188
50-302	Crystal River Nuclear Plant, Unit 3	119	50-339	North Anna Power Station, Unit 2	190
50-303	Crystal River Nuclear Plant, Unit 4	121	50-341	Enrico Fermi Atomic Power Plant, Unit 2	194
50-304	Zion Nuclear Power Station, Unit 2	121	50-344	Trojan Nuclear Plant	195
50-305	Kewaunee Nuclear Power Plant	124	50-346	Davis-Besse Nuclear Power Station, Unit 1	198
50-306	Prairie Island Nuclear Station, Unit 2	126	50-348	Joseph M. Farley Nuclear Plant, Unit 1	200
50-309	Maine Yankee Atomic Power Plant	128	50-351	Korea Research Reactor	202
50-311	Salem Nuclear Generating Station, Unit 2	130	50-352	Limerick Generating Station, Unit 1	202
50-312	Rancho Seco Nuclear Generating Station	132	50-353	Limerick Generating Station, Unit 2	203
50-313	Arkansas Nuclear One, Unit 1	135	50-354	Hope Creek Nuclear Station, Unit 1	205
50-315	Donald C. Cook Nuclear Power Plant,	138	50-355	Hope Creek Nuclear Station, Unit 2	206
	Unit 1		50-356	Univ. of Illinois LOPRA Research Reactor	207
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	140	50-358	William H. Zimmer Nuclear Station, Unit 1	207
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	142	50-361	San Onofre Nuclear Station, Unit 2	209
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	145	50-362	San Onofre Nuclear Station, Unit 3	211
50-320	Three Mile Island Nuclear Station, Unit 2	147	50-363	Forked River Nuclear Station, Unit 1	212
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	157	50-364	Joseph M. Farley Nuclear Plant, Unit 2	213
50-322	Shoreham Nuclear Power Station	159	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	214
50-323	Diablo Canyon Nuclear Power Plant,	161	50-367	Bailly Generating Station	216
	Unit 2		50-368	Arkansas Nuclear One, Unit 2	218
50-324	Brunswick Steam Electric Plant, Unit 2	163	50-369	William B. McGuire Nuclear Station, Unit 1	220
50-325	Brunswick Steam Electric Plant, Unit 1	165	50-370	William B. McGuire Nuclear Station,	222
50-327	Sequoyah Nuclear Plant, Unit 1	167		Unit 2	
50-328	Sequoyah Nuclear Plant, Unit 2	171	50-373	LaSalle County Station, Unit 1	223

Docket	Name	Page	Docket	Name	Page
50-374	LaSalle County Station, Unit 2	225	50-434	Surry Power Station, Unit 3	260
50-376	North Coast Nuclear Plant, Puerto Rico	226	50-435	Surry Power Station, Unit 4	260
50-382	Waterford Generating Station, Unit 3	226	STN-50-437	Floating Nuclear Plant	260
50-384	Indonesia Research Reactor	227	50-438	Bellefonte Nuclear Plant, Unit 1	260
50-387	Susquehanna Steam Electric Station, Unit 1	227	50-439	Bellefonte Nuclear Plant, Unit 2	262
50-388	Susquehanna Steam Electric Station, Unit 2	231	50-440	Perry Nuclear Power Plant, Unit 1	264
50-389	St. Lucie Plant, Unit 2	234	50-441	Perry Nuclear Power Plant, Unit 2	265
50-390	Watts Bar Nuclear Plant, Unit 1	236	50-443	Seabrook Nuclear Station, Unit 1	266
50-391	Watts Bar Nuclear Plant, Unit 2	238	50-444	Seabrook Nuclear Station, Unit 2	267
50-395	Virgil C. Summer Nuclear Station, Unit 1	239	50-445	Comanche Peak Steam Electric Station, Unit 1	269
50-397 50-400	WPPSS Nuclear Project, Unit 2 Shearon Harris Nuclear Power Plant,	241 243	50-446	Comanche Peak Steam Electric Station, Unit 2	275
50 401	Unit I	244	50-448	Douglas Point Nuclear Station, Unit 1	281
50-401	Shearon Harris Nuclear Power Plant, Unit 2	244	50-449	Douglas Point Nuclear Station, Unit 2	281
50-402	Shearon Harris Nuclear Power Plant, Unit 3	245	50-452	Greenwood Energy Center, Unit 2	281
50-403	Shearon Harris Nuclear Power Plant,	246	50-453	Greenwood Energy Center, Unit 3	281
	Unit 4	210	50-454	Byron Station, Unit 1	281
50-404	North Anna Power Station, Unit 3	247	50-455	Byron Station, Unit 2	282
50-405	North Anna Power Station, Unit 4	248	50-456	Braidwood Station, Unit 1	284
50-409	La Crosse Boiling Water Reactor	248	50-457	Braidwood Station, Unit 2	284
50-410	Nine Mile Point Nuclear Station, Unit 2	250	50-458	River Bend Station, Unit 1	285
50-412	Beaver Valley Power Station, Unit 2	251	50-459	River Bend Station, Unit 2	286
50-413	Catawba Nuclear Station, Unit 1	252	50-460	WPPSS Nuclear Project, Unit I	287
50-414	Catawba Nuclear Station, Unit 2	252	50-461	Clinton Power Station, Unit 1	288
50-416	Grand Gulf Nuclear Station, Unit 1	253	50-462	Clinton Power Station, Unit 2	288
50-417	Grand Gulf Nuclear Station, Unit 2	255	50-463	Fulton Generating Station, Unit 1	289
50-423	Millstone Nuclear Power Station, Unit 3	257	50-464	Fulton Generating Station, Unit 2	289
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	258	50-466	Allens Creek Nuclear Station, Unit 1	289
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	259	STN-50-470	CESSAR System 80	290
50-427	Alvin W. Vogtle Nuclear Plant, Unit 4	260	50-471	Pilgrim Nuclear Power Station, Unit 2	290
50-433	Univ. of California at Santa Barbara Research Reactor	260	STN-50-482	Wolf Creek Generating Station	291

Docket	Name	Page	Docket	Name	Page
STN-50-483	Calloway Plant, Unit 1	292	STN-50-523	Skagit Nuclear Power Project, Unit 2	318
STN-50-484	Tyrone Energy Park, Unit 1	293	50-524	Barton, Unit I	319
STN-50-485	Sterling Power Project Nuclear, Unit 1	293	50-525	Barton, Unit 2	319
STN-50-486	Calloway Plant, Unit 2	294	50-526	Barton, Unit 3	319
STN-50-488	Perkins Nuclear Station, Unit 1	295	50-527	Barton, Unit 4	319
STN-50-489	Perkins Nuclear Station, Unit 2	296	STN-50-528	Palo Verde Nuclear Station, Unit 1	319
STN-50-490	Perkins Nuclear Station, Unit 3	296	STN-50-529	Palo Verde Nuclear Station, Unit 2	320
STN-50-491	Cherokee Nuclear Station, Unit 1	297	STN-50-530	Palo Verde Nuclear Station, Unit 3	321
STN-50-492	Cherokee Nuclear Station, Unit 2	297	50-534	Wolsung I, Korea	322
STN-50-493	Cherokee Nuclear Station, Unit 3	298	50-537	Clinch River Breeder Reactor	322
STN-50-495	SWESSAR-PI	298	STN-50-546	Marble Hill Nuclear Station, Unit I	322
50-496	Montague Nuclear Power Station, Unit 1	299	STN-50-547	Marble Hill Nuclear Station, Unit 2	323
\$ 0-497	Montague Nuclear Power Station, Unit 2	299	50-548	Fort Calhoun Station, Unit 2	325
STN-50-498	South Texas Project, Unit 1	299	50-549	Greene County Nuclear Power Plant	325
STN-50-499	South Texas Project, Unit 2	304	STN-50-550	GESSAR-238-BOP Interface	325
50-500	Davis-Besse Nuclear Power Station, Unit 2	310	STN-50-553	Phipps Bend Nuclear Plant, Unit 1	325
50-501	Davis-Besse Nuclear Power Station, Unit 3	310	STN-50-554	Phipps Bend Nuclear Plant, Unit 2	326
STN-50-502	Haven Nuclear Plant, Unit 1	310	STN-50-556	Black Fox Station, Unit 1	328
STN-50-508	WPPSS Nuclear Project, Unit 3	310	STN-50-557	Black Fox Station, Unit 2	329
STN-50-509	WPPSS Nuclear Project Unit 5	311	50-564	Nuclear Fuels Recovery & Recycle Center	330
50-510	Blue Hills Station, Unit 1	311	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	330
50-511	Blue Hills Station, Unit 2	311	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	331
50-513	WPPSS Nuclear Project, Unit 4	311	STN-50-568	NEP Nuclear, Unit I	333
50-514	Pebble Springs Nuclear Plant, Unit 1	312	STN-50-569	NEP Nuclear, Unit 2	333
50-515	Pebble Springs Nuclear Plant, Unit 2	313	STN-50-574	Bagnac Nuclear Power Project, Philippines	333
STN-50-516	Jamesport Nuclear Station, Unit 1	313	STN-50-580	Erie Nuclear Plant, Unit 1	333
STN-50-517	Jamesport Nuclear Station, Unit 2	314	STN-50-581	Erie Nuclear Plant, Unit 2	333
STN-50-518	Hartsville Nuclear Plant, Unit 1	314	50-582	Sundesert, Unit 1	333
STN-50-519	Hartsville Nuclear Plant, Unit 2	315	50-583	Sundesert, Unit 2	333
STN-50-520	Hartsville Nuclear Plant, Unit 3	316	50-585	TRIGA Mark II	333
STN-50-521	Hartsville Nuclear Plant, Unit 4	317	STN-50-592	Palo Verde Nuclear Station, Unit 4	333
STN-50-522	Skagit Nuclear Power Project, Unit 1	318	STN-50-593	Palo Verde Nuclear Station, Unit 5	334

Docket	Name	Page	Docket	Name	Page
STN-50-596	New Haven Unit 1	334	70-1100	Combusion Engineering, Inc.	342
STN-50-597	New Haven, Unit 2	334	70-1113	General Electric Co.	342
50-599	Carroll Facility I	334	70-1143	Westinghouse Electric Corp.	343
50-600	Carroll Facility II	334	70-1151	Westinghouse Electric Corp.	343
70-0008	Battelle Columbus Laboratories	334	70-1193	Cimarron Facility, Kerr-McGee Corp	343
70-0025	Rockwell International	334	70-1201	UF-6 Conversion Facility, Babcock & Wilcox Co	344
70-0027	Babcock & Wilcox Co	334	70-1222	Univ. of Missouri	344
70-0033	Texas Instruments, Inc.	335	70-1222	Erie Mining Co.	344
70-0047	National Aeronautics & Space Administration	335	70-1227		344
70-0082	Nuclear Metals, Inc.	226		Albright College, Reading, PA	
70-0082	Univ. of Toledo	335	70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	344
70-0036	Babcock & Wilcox Co.	335	70-1308	Morris Operations, General Electric Co	345
70-0133	Nuclear Fuel Services, Inc.	335 337	70-1319	U.S. Nuclear, Inc.	346
70-0190	Catholic Univ.	338	70-1426	Transnuclear, Inc.	346
70-0364	Parks Township Site, Babcock &	338	70-1729	Fuel Recovery & Storage Station, Allied General Nuclear Service Corp.	346
	Wilcox Co.		70-1739	Tri-State Motor Transit Co.	346
70-0371	United Nuclear Corp.	340	70-2554	New England Medical Center, Boston, MA	346
70-0398	Dept. of Commerce	340	70-2322	Edlow International Co.	346
70-0572	Monsanto Research Corp.	340	70-2362	Brockton Hospital, Brockton, MA	346
70-0687	Union Carbide Corp.	340	70-2478	Transnuclear, Inc.	346
70-0696	General Services Administration	340	70-2479	Transnuclear, Inc.	347
70-0734	General Atomic Co.	340	70-2623	McGuire Spent Fuel Pool, Duke Power Co.	347
70-0754	Vallecitos Nuclear Center, General Electric Co.	341	70-2786	General Electric Co.	348
70-0820	United Nuclear Corp.	341	70-2805	Nissho-Iwai American Corp	348
70-0824	Babcock & Wilcox Co.	341	70-2845	Transnuclear, Inc.	348
70-0827	The Defiance College, Defiance, OH	341	70-2872	Reuter-Stokes	348
70-0925	Cimmaron Facility, Kerr-McGee Corp.	341	70-2909	Westinghouse Electric Corp.,	348
70-0984	Pacific Northwest Labortory	341		Power Systems	
70-1007	General Electric Co.	342	70-2917	Tennessee Valley Authority	348
70-1068	Univ. of Florida	342	70-2920	Alabama Power Co.	349
70-1089	Commonwealth of Pennsylvania	342	71-0005	Magnaflux Corp.	349

Docket	Name	Page	Docket	Name	Page
71-0009	Isomedix, Inc.	349	71-0380	General Electric Co	351
71-0013	Dept. of the Navy	349	71-0381	E L. Conwelt & Co.	351
71-0024	Hittman Nuclear & Development Corp.	349	71-0383	Model NLI 1/2 LWT Cask, NL Industries,	351
71-0035	Rockwell International	349		Ine	
71-0049	Dept. of the Navy	349	71-4824	Model: HA-10, Babcock & Wilcox Co.	351
71-0096	Pan American World Airways	349	71-5395	Model CC, Westinghouse Electric Corp.	351
71-0097	Nondestructive Testing Service	349	71-5607	Model: GE T-2, General Electric Co.	351
71-0102	Source Production & Equipment Co,	349	71-5796	Model: 181361, Picker Corp	351
	Inc.	- 12	71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co.	351
71-0107	Dept. of the Navy	349	71-5938	Model HNPF, General Atomic Co.	351
71-0116	Dept. of the Navy	350	71-5939	Model: GE-1500, General Electric Co.	351
71-0121	Neutron Products, Inc.	350	71-5942	Model GE-700, General Electric Co	352
71-0135	Babcock & Wilcox Co.	350	71-5971	Model: GE-200, General Electric Co.	352
71-0165	Dept. of the Navy	350	71-5979	Model: 5979, Alpha-Omega Services, Inc.	352
71-0170	General Electric Co.	350	71-5998	Model: GE-400, General Electric Co.	352
71-0180	Hartford Steam Boiler Co.	350			
71-0185	FBF, Inc.	350	71-6078	Model: 927 A1 & C1, Combustion Engineering Co.	352
71-0227	Tennessee Valley Authority	350	71-6144	Model: 6144, Nuclear Engineering Co.	352
71-0230	Babcock & Wilcox Co.	350	71-6272	Model: Poly Panther, Teledyne Fnergy Systems	352
71-0249	Nuclear Fuel Services, Inc.	350	71-6375	·	262
71-0250	Transnuclear, Inc.	350		Model PB-1, Chem-Nuclear Systems, Inc.	352
71-0252	Dayton X-Ray Co.	350	71-6387	Model: 60, Battelle Memorial Institute	352
71-0273	Dept. of the Navy	350	71-6400	Model: Super Tiger, Westinghouse Electric Corp	352
71-0367	Dept. of the Navy	350	71-6574	Model: HN-200, Hittman Nuclear &	352
71-0370	Amersham Corp.	351	21.6620	Development Corp.	250
71-0372	Boeing Co.	351	71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	352
71-0373	Dept. of the Navy, Naval Explosive Ordnance Disposal Facility	351	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	353
71-0375	Univ. of California	351	71-6717	Model: 6717 B	353
71-0377	Indiana & Michigan Electric Co.	351	71-9006	Model: 500 SU, Argonne National Laboratory	353
71-0378	Wisconsin Electric Power Co.	351	71-9007	Model: 520, Argonne National Laboratory	353
71-0379	Hittman Nuclear & Development Corp.,	351	71-9009	Model: FL 10-1, General Electric Co.	353
	Hittman Material & Medical Components, Inc.		71-9010	Model: NLI-1/2, NL Industries, Inc.	353

Docket	Name	Page	Docket	Name	Page
71-9011	Model: E-MEH-00-00004, Dept. of Transportation	353	71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	354
71-9015	Model: TN-8, Transnuclear, Inc.	353	71-9081	Model: CNS1-1600, Chem-Nuclear Systems, Inc.	354
71-9016	Model: TN-9, Transnuclear, Inc.	353	71-9089	Model: NH-100 S, Hitiman Nuclear &	354
71-9019	Model: BU-7, General Electric Co.	353	11-7007	Development Corp	35,
71-9020	Model: SL-10-1, Nuclear Containers, Inc.	353	71-9094	Model: CNSI-14-195-H, Chem-Nuclear Systems, Inc	354
71-9029	Model: 676, Technical Operations, Inc.	354	71-9096	Model, CNSI-21-300, Chem-Nuclear	355
71-9036	Model: C-1, Source Production Equipment Co.	354	71-3030	Systems, Inc.	333
71-9039	Model: 715, Technical Operations, Inc.	354	71-9105	Model Rad-Waste CR.I, Chem-Nuclear Systems, Inc.	355
71-9043	Model: NNPU, Dept. of the Navy	354	71-9111	Model CN6-80A, Chem-Nuclear Systems, Inc	355
71-9044	Model: GE-1600, General Electric Co.	354	G. 0110		255
71-9045	Model: GE-1000, General Electric Co.	354	71-9113	Model: 7-100, Chem-Nuclear Systems, Inc.	355
71-9046	Model: GE-1100, General Electric Co.	354	71-9122	Model. 18-450, Chem-Nuclear Systems, Inc.	355
71-9049	Model: GE-500, General Electric Co	354	71-9130	Model: NP-50-XXL, Nuclear Packaging, Inc.	355
71-9050	Model: GE-900, General Electric Co.	354	71.0120		
71-9067	Model: BCL-3	354	71-9132	Model. T-3, Nuclear Packaging, Inc.	355
71-9070	Model: N-55, Dept. of Energy	354	71-9135	Model: Century, Gamma Industries	355
71-9072	Model: GAHC-I, General Atomic Co.	354	71-9142	Model: 2526, Monsanto Research Corp.	355
			71-9853	Model: ORNL-BNL-NBS, Unirradiated	355
71-9073	Model: OH-142, Nuclear Packaging, Inc	354		Fuel Container, Dept. of Energy	
71-9079	Model: HN-100, Series 2, Hutman Nuclear & Development Corp.	354			

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

₹ame	Docket	Page	Name	Docket	Page
kerotest Radiography & Research Reactor	50-228	30	Browns Ferry Nuclear Power Station, Umt 2	50-260	56
Illens Creek Nuclear Station, Unit 1	50-466	289	Browns Ferry Nuclear Power Station, Unit 3	50-296	114
arkansas Nuclear One, Unit 1	50-313	135		50.225	165
rkansas Nuclear One, Unit 2	50-368	218	Brunswick Steam Electric Plant, Unit 1	50-325	165
Puane Arnold Energy Center	50-331	177	Brunswick Steam Electric Plant, Unit 2	50-324	163
abcock & Wilcox Co. Critical Facility	50-13	14	Byron Station, Unit 1	50-454	281
agnac Nuclear Power Project, Philippines	STN-50-574	333	Byron Station, Unit 2	50-455	282
ailly Generating Station	50-367	216	Calloway Plant, Unit 1	STN-50-483	292
arnwell Reprocessing Plant	50-332	179	Calloway Plant, Unit 2	STN-50-486	294
arton, Unit 1	50-524	319	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	142
arton, Unit 2	50-525	319	Calvert Cliffs Nuclear Power Plant,	50-318	145
arton, Unit 3	50-526	319	Unit 2	50.500	224
arton, Unit 4	50-527	319	Carroll Facility 1	50-599	334
eaver Valley Power Station, Unit I	50-334	181	Carroll Facility II	50-600	334
eaver Valley Power Station, Unit 2	50-412	251	Catawba Nuclear Station, Unit 1	50-413	252
ellefonte Nuclear Plant, Unit 1	50-438	260	Catawba Nuclear Station, Unit 2	50-414	252
ellefonte Nuclear Plant, Unit 2	50-439	262	CESSAR System 80	STN-50-470	290
ig Rock Point Nuclear Power Plant	50-155	18	Cherokee Nuclear Station, Unit 1	STN-50-491	297
lack Fox Station, Unit 1	STN-50-556	328	Cherokee Nuclear Station, Unit 2	STN-50-492	297
lack Fox Station, Unit 2	STN-50-557	329	Cherokee Nuclear Station, Unit 3	STN-50-493	298
lue Hills Station, Unit 1	50-510	311	Clinch River Breeder Reaction	50-537	322
lue Hills Station, Unit 2	50-511	311	Clinton Power Station, Unit 1	50-461	288
raidwood Station, Unit 1	50-456	284	Clinton Power Station, Unit 2	50-462	288
raidwood Station, Unit 2	50-457	284	Comanche Peak Steam Electric Station, Unit I	50-445	269
owns Ferry Nuclear Power Station, Unit I	50-259	54	Comanche Peak Steam Electric Station, Unit 2	50-446	275

Name	Docket	Page	Name	Docket	Page
Cooper Nuclear Station	50-298	116	Fulton Generating Station, Unit 2	50-464	289
Crystal River Nuclear Plant, Unit 3	50 302	119	General Atomic Co.	50-163	21
Crystal River Nuclear Plant, Unit 4	50-303	121	General Electric Test Reactor	50-70	16
Davis-Besse Nuclear Power Station, Unit 1	50-346	198	General Electric Nuclear Test Reactor	50-73	16
Davis-Besse Nuclear Power Station, Unit 2	50-500	310	Georgia Institute of Technology Research Reactor	50-160	21
Davis-Besse Nuclear Power Station, Unit 3	50-501	310	Georgia Tech Research Reactor GESSAR-238-BOP Interface	50-276 STN-50-550	80 325
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	77	Robert Enimet Ginna Nuclear Plant, Unit 1	50-244	33
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	161	Grand Gulf Nuclear Station, Unit 1	50-416	253
Donald C. Cook Nuclear Power Plant,	50-315	138	Grand Gulf Nuclear Station, Unit 2	50-417	255
Unit 1	30-313	130	Greene County Nuclear Power Plant	50-549	325
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	140	Greenwood Energy Center, Unit 2	50-452	281
Douglas Point Nuclear Station, Unit 1	50-448	281	Greenwood Energy Center, Unit 3	50-453	281
Douglas Point Nuclear Station, Unit 2	50-449	281	Haddam Neck Plant	50-213	25
Dow Chemical Co.	50-264	62	Shearon Harris Nuclear Power Plant, Unit 1	50-400	243
Dresden Nuclear Power Station, Unit 1	50-10	11	Shearon Harris Nuclear Power Plant,	50-401	244
Dresden Nuclear Power Station, Unit 2	50-237	30	Unit 2		
Dresden Nuclear Power Station, Unit 3	50-249	40	Shearon Harris Nuclear Power Plant, Unit 3	50-402	245
Erie Nuclear Plant, Unit 1	STN-50-580	333	Shearon Hairis Nuclear Power Plant,	50-403	246
Erie Nuclear Plant, Unit 2	STN-50-581	333	Unit 4		
Joseph M. Farley Nuclear Plant, Unit 1	50-348	200	Hartsville Nuclear Plant, Unit 1	STN-50-518	314
Joseph M. Farley Nuclear Plant, Unit 2	50-364	213	Hartsville Nuclear Plant, Unit 2	STN-50-519	315
Enrico Fermi Atomic Power Plant,	50-341	194	Hartsville Nuclear Plant, Unit 3	STN-50-520	316
Unit 2			Hartsville Nuclear Plant, Unit 4	STN-50-521	317
James A. Fitzpatrick Nuclear Power Plant	50-333	179	Edwin I. Hatch Nuclear Plant, Unit 1	50-32!	157
Floating Nuclear Plant	STN-50-437	260	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	214
Forked River Nuclear Station,	50-363	212	Haven Nuclear Plant, Unit 1	STN-50-502	310
Unit 1			Hope Creek Nuclear Station, Unit I	50-354	205
Fort Calhoun Station, Unit 2	50-548	325	Hope Creek Nuclear Station, Unit 2	50-355	206
Fort St. Vrain Nuclear Generating	50-267	66	Humboldt Bay Power Plant, Unit 3	50-133	17
Station			Indian Point Station, Unit 1	50-3	9
Fulton Generating Station, Unit 1	50-463	289	Indian Point Station, Unit 2	50-247	37

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 3	50-286	91	NEP Nuclear, Unit 2	STN-50-569	333
Indonesia Research Reactor	50-384	227	New Haven, Unit 1	50-596	334
Jamesport Nuclear Station, Unit 1	STN-50-516	313	New Haven, Unit 2	50-597	334
Jamesport Nuclear Station, Unit 2	STN-50-517	314	Nine Mile Point Nuclear Station,	50-220	29
Kewaunce Nuclear Power Plant	50-305	124	Unit I	40.410	260
Korea Research Reactor	50-351	202	Nine Mile Point Nuclear Station, Unit 2	50-410	250
La Crosse Boiling Water Reactor	50-409	248	North Anna Power Station, Unit 1	50-338	188
LaSalle County Station, Unit 1	50-373	223	North Anna Power Station, Unit 2	50-339	190
LaSalle County Station, Unit 2	50-374	225	North Anna Power Station, Unit 3	50-404	247
Limerick Generating Station, Unit 1	50-352	202	North Anna Power Station, Unit 4	50-405	248
Limerick Generating Station, Unit 2	50-353	203	North Carolina State Univ. Research	50-111	16
Maine Yankee Atomic Power Plant	50-309	128	Reactor	co 254	224
Marble Hill Nuclear Station, Unit 1	STN-50-546	322	North Coast Nuclear Plant, Puerto Rico	50-376	226
Marble Hill Nuclear Station, Unit 2	STN-50-547	323	Nuclear Fuels Recovery & Recycle Center	50-564	330
William B. McGuire Nuclear Station, Unit 1	50-369	220	Oconce Nuclear Station, Unit 1	50-269	67
William B. McGuire Nuclear Station,	50-370	222	Oconee Nuclear Station, Unit 2	50-270	70
Unit 2			Oconee Nuclear Station, Unit 3	50-287	95
Michigan State Univ Research Reactor	50-294	110	Ohio State Univ. Research Reactor	50-150	18
Midland Plant, Unit 1	50-329	174	Oregon State Univ. Research Reactor	50-243	33
Midland Plant, Unit 2	50-330	175	Oyster Creek Nuclear Power Plant	50-219	27
Midwest Fuel Recovery Plant	50-268	67	Palisades Nuclear Plant	50-255	51
Millstone Nuclear Power Station, Unit 1	50-245	34	Palo Verde Nuclear Station, Unit 1	STN-50-528	319
Millstone Nuclear Power Station.	50-336	186	Palo Verde Nuclear Station, Unit 2	STN-50-529	320
Unit 2	30-330		Palo Verde Nuclear Station, Unit 3	STN-50-530	321
Millstone Nuclear Power Station, Unit 3	50-423	257	Palo Verde Nuclear Station, Unit 4	STN-50-592	333
Montague Nuclear Power Station,	50-496	299	Palo Verde Nuclear Station, Unit 5	STN-50-593	334
Unit 1	30-490	499	Peach Bottom Atomic Power Station, Unit !	50-171	21
Montague Nuclear Power Station, Unit 2	59-497	299	Peach Bottom Atomic Power Station, Unit 2	50-277	80
Monticello Nuclear Generating Plant	50-263	60	Peach Bottom Atomic Power Station.	£0. 270	02
National Bureau of Standards Reactor	50-184	22	Unit 3	50-278	82
National Naval Medical Center	50-170	21	Pebble Springs Nuclear Plant, Unit 1	50-514	312
NEP Nuclear, Unit 1	STN-50-568	333	Pebble Springs Nuclear Plant, Unit 2	50-515	313

Name	Docket	Page	Name	Docket	Page
Perkins Nuclear Station, Unit !	STN-50-488	295	Sequoyah Nuclear Plant, Unit 2	50-328	171
Perkins Nuclear Station, Unit 2	STN-50-489	296	Shoreham Nuclear Power Station	50-322	159
Perkins Nuclear Station, Unit 3	STN-50-490	296	Skagit Nuclear Power Project, Unit 1	STN-50-522	318
Perry Nuclear Power Plant, Unit 1	50-440	264	Skagit Nuclear Power Project, Unit 2	STN-50-523	318
Perry Nuclear Power Plant, Unit 2	50-441	265	South Texas Project, Unit 1	STN-50-498	299
Phipps Bend Nuclear Plant, Unit 1	STN-50-553	325	South Texas Project, Unit 2	STN-50-499	304
Phipps Bend Nuclear Plant, Unit 2	STN-50-554	326	State Univ. of New York Research	50-57	16
Pilgrim Nuclear Power Station, Unit 1	50-293	108	Reactor	STN-50-485	293
Pilgrim Nuclear Power Station, Unit 2	50-471	290	Sterling Power Project, Nuclear, Unit 1	3111-30-403	273
Plum Brook Research Reactor Facility	50-30	15	St. Lucie Plant, Unit 1	50-335	184
Point Beach Nuclear Plant, Unit !	50-266	64	St. Lucie Plant, Unit 2	50-389	234
Point Beach Nuclear Plant, Unit 2	50-301	117	Virgil C. Summer Nuclear Station, Unit I	50-395	239
Prairie Island Nuclear Station, Unit 1	50-282	88	Sundesert, Unit 1	50-582	333
Prairie Island Nuclear Station, Unit 2	50-306	126	Sundesert, Unit 2	50-583	333
Purdue Univ. Research Reactor	50-182	22	Surry Power Station, Unit 1	50-280	84
Quad-Cities Station, Unit 1	50-254	49	Surry Power Station, Unit 2	50-281	86
Quad-Cities Station, Unit 2	50-265	62	Surry Power Station, Unit 3	50-434	260
Rancho Seco Nuclear Generating Station	50-312	132	Surry Power Station, Unit 4	50-435	260
Rhode Island & Providence Plantations AEC	50-193	22	Susquehanna Steam Electric Station, Unit 1	50-387	227
River Bend Station, Unit 1	50-458	285	Susquehanna Steam Electric Station, Unit 2	50-388	231
River Bend Station, Unit 2	50-459	286	SWESSAR-PI	STN-50-495	298
H. B. Robinson Plant, Unit 2	50-261	59	Texas A&M Univ. Research	50-128	17
RPI Critical Experiment	50-225	30	Reactor		
Salem Nuclear Generating Station, Unit 1	50-272	74	Three Mile Island Nuclear Station, Unit 1	50-289	97
Salem Nuclear Generating Station,	50-311	130	Three Mile Island Nuclear Station, Unit 2	50-320	147
Unit 2	30-311	150	TRIGA Mark II	50-585	333
San Onofre Nuclear Station, Unit 1	50-206	23	Trojan Nuclear Plant	50-344	195
San Onofre Nuclear Station, Unit 2	50-361	209	Turkey Research Reactor	50-137	18
San Onofre Nuclear Station, Unit 3	50-362	211	Turkey Point Plant, Unit 3	50-250	42
Seabrook Nuclear Station, Unit 1	50-443	266	Turkey Point Plant, Unit 4	50-251	46
Seabrook Nuclear Station, Unit 2	50-444	267	Tyrone Energy Park, Unit I	STN-50-484	293
Sequoyah Nuclear Plant, Unit I	50-327	167	UCLA Training Renctor	50-142	18

Name	Docket	Page	Name	Docket	Page
Union Carbide Research Reactor	50-54	16	Waterford Generating Station, Unit 3	50-382	226
Univ of California at Santa Barbara Research Reactor	50-433	260	Watts Bar Nuclear Plant, Unit 1	50-390	236
Univ. of California Research Reactor	50-224	30	Watts Bar Nuclear Plant, Unit 2 West Valley Reprocessing Plant	50-391 50-201	238
Univ. of Illinois LOPRA Research Reactor	50-356	207	Wolf Creek Generating Station	STN-50-482	291
Univ. of Illinois Research Reactor	50-151	18		50-534	322
Univ. of Maryland Research Reactor	50-166	21	Wolsung I, Korea		287
Univ. of Michigan Research Reactor	50-2	8	WPPSS Nuclear Project, Unit 1	50-460	
Univ. of Missouri Research Reactor	50-123	17	WPPSS Nuclear Project, Unit 2	50-397	241
University Training Reactor	50-189	22	WPPSS Nuclear Project, Unit 3	STN-50-508	310
Vallecitos Boiling Water Reactor	50-18	14	WPPSS Nuclear Project, Unit 4	50-513	311
Vallecitos Experimental Superheat Reactor	50-183	22	WPPSS Nuclear Project, Unit 5	STN-50-509	311
Vermont Yankee Nuclear Power Station	50-271	72	Yankee-Rowe Nuclear Power Station	50-29	14
Virginia Polytech Institute Training Reactor	50-124	17	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	330
Alvin W. Vogtle Nuclear Plant, Unit I	50-424	258	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	331
Alvin W, Vogtle Nuclear Plant, Unit 2	50-425	259	William H Zimmer Nuclear Station, Unit 1	50-358	207
Alvin W. Vogtle Nuclear Plant, Unit 4	50-427	260	Zion Nuclear Power Station, Unit 1	50-295	110
The state of the s	2¢,	204	Zion Nuclear Power Station, Unit 2	50-304	121

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL , NUCLEAR ENGINEERING CO

- B004010104 Forwards "Preliminary Rept on Hydrogeology of Low Level Radwaste Disposal Site Near Sheffield, IL," Open-File Rept 79-1545 TOLER, L. Q. Interior, Dept of 50/03/07 ip
- TOLER, L. G. Interior, Dept of 60/03/07 ip
- ---8004010106 "Preliminary Rapt on Hydrogeology of Low Level Radwaste Disposal Site Near Sheffiold IL." Open-File Rept 79-1545 FOSTER, J B . ERICKSON, J R Interior, Dept of, Geological Survey 79-1545 80/01/31 87pp
- 8004020132 Requests that site be inspected when thewing occurs Bignificant trench subsidence & erosion was observed in 1979 Surface deterioration admits water & leads to increased leaching of radwaster. Particularly during spring thaw SMITH, R D Low Level Waste Licensing Branch 80/03/13 1p
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations B0/04/02 34pp

DOCKET 27-047 BARNWELL, SC , CHEM-NUCLEAR SYSTEMS

- 8004040032 Forwards Haste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIS, A I Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/13 2pp
- --B004040035 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements radiation levels, removable contamination & external package features POTTER, J P. BROWN, R A Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/13 App
- H004040392 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompilance noted DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/02/13 2pp
- --B004040379 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements radiation levels, removable contamination & external packaging features POTTER, J P. BROWN, R A Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/13 App
- B004040450 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/02/13 2pp
- --8004040453 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels & marking requirements
 POTTER.J P Region 3. Chicago, Fuel Facility & Materials Bafety Branch BROWN,R A Region 3. Chicago. Office of the Director 80/02/13 4pp
- 8004070131 Forwards wasta packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/13 2pp

- 8004100518 Forwards Waste Packaging Insp Rept 79-07A on 791219 & notice of violation DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/22 2pp
- --B004100522 Notice of violation from insp on 791219
 * Region 3, Chicago, Office of the Director B0/02/22 ip
- --8004100328 Waste Packaging Insp Rept 79-07A on 791219 Noncompliance noted failure to mark package as radioactive low specific activity POTTER.J P , BRGHN,R A Region G, Chicago, Fuel Facility & Materials Safety Oranch 80/02/22 3pp
- 8004040160 Forwards Waste Packaging Insp Rept 79-07A on 791219 & notice of violation
 DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety
 Branch 80/02/23 2pp
- --8004040i44 Notice of violation from insp on 791217
 * Region 3, Chicago, Office of the Director 80/02/29 ip
- --8004040171 Waste Packaging Insp Rept 79-07A on 791219 Noncompliance noted cask shipped from facility not marked "Radioactive LBA," as required FOTTER, J P. BROWN, R A Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/23 4pp
- B0040B0135 Forwards Water Packaging Insp Rept 80-01 on B00131-0201 No noncompliance noted STORR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/25 3pp
- --8004080140 Waste Packaging Insp Rept 80-01 on 800131-0201 No noncompliance noted Major areas inspected DDT & NRC requirements including shipping paper DDT placard, radiation levels, removable contamination & labeling PDTTER, J P. PEERY, W W. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/02/21, 4pp
- 8004080145 Forwards Waste Packaging Insp Rept B0-02A on B00206-08 No noncompliance noted BTOHR: J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/26 Spp
- --8004080147 Waste Packaging Insp Rept 80-02A on 800206-08 No noncompliance noted. Major areas inspected DDT & NRC requirements including shipping paper DDT placard, radiation levels, marking & labeling. POTTER, J P. BRDWN R A Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/20 4pp
- 8004160165 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted SMITH.O H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/02/29 2pp
- --8004160172 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected radiation levels, shipping paper raquirements, removable contamination & labeling requirements for packages POTTER.J P. BROWN, R.A. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 79/12/12 7pp
- B004210027 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance hoted. BHITH O H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch B0/03/05 ip

- --8004210034 Waste Pactaging Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements.readiation levels.removable contamination & package external feature requirements POTTER.J P., PERRY.N W., MODDRUFF.R L. Region 1, Philadelphia. Fuel Facility & Materials Safety Sranch 80/01/18 7pp
- 8004210027 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted SMITH.0 H Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 80/03/05 ip
- --800421003\$ Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels, memorable contamination & package external feature requirements POTTER, J.P., BROUN, R.A. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/12/12 7pp
- 6004210074 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH, G H Region i, Philadelphia, Fuel Facility & Materials Safety Branch B0/03/05 2pp
- --8004210076 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompilance noted Hajor areas inspected shipping paper & placarding requirements radiation levels removable contamination & package external feature requirements POTTER.J P. PEERY.W W. WOODRUFF.R L. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/01/18 7pp
- 8004210079 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH.Q H Region 1. Philadelphia, Fuel Facility & Materiais Safety Branch 80/03/05 299
- --8004210082 Waste Paciaging Rept 79-07A on 791212-13 No noncompliance noted Hayor areas inspected shipping paper & placarding requirements radiation levels removable contamination & packaging external feature requirements POTTER.J P. PERRY.M W. HOODRUFF.R L. Ragion i. Philadelphia, Fuel Facility & Materials Safety Branch 80/01/18. 7pp
- B0042:01:5 Forwards Waste Packaging Insp Rept 79-06A on 79:126-28 No noncompliance noted. SMITH, O R Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- --8004210120 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels, removable contamination & package external feature requirements POTTER, JP. BROWN, RA Region i. Philadelphia, Fuel Facility & Materials Safety Branch 79/12/12 7pp
- 8004210334 Forwards Haste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted BMITH, O H Region i, Philadelphia, Fuei Facility & Materials Safety Branch 80/03/05 2pp
- --8004210339 Haste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected: shipping paper requirements. DDT placarding requirements. radiation levels, removable contamination & DDT/NRC marking & labeling PDTYER, J P., PEERY, N W . NOODRUFF, R L Region 1, Philadelphia, Fusi Facility & Materials Safety Branch 80/01/18 7pp
- 9004210349 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No oncompliance noted 4ITH, 0 H. Region i. Philadelphia. Fuel Facility & Materials Safety anch 80/03/05 2PP
 - 04210345 Waste Pactaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper requirements. DOT placarding, radiation levels, removable contamination, DOT marking & labeling & external features POTYER, J P., PEERY, W W., WOODRUFF, R L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/01/18 7pp
- 6004220379 Forwards Waste Packaging Insp Rept 79-07A No noncompliance noted SMITH.0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 60/03/05 2pp.
- --8004220402 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas impected review of shipping papers, hadiation survey of vehicles, contamination surveys & radiation level surveys of packages POTTER, J. P., PEERY, W. W. WOODRUFF, R. L. Ragion 2, Atlanta, Fuel Facility & Materials Safety Branch 80/01/18 7pp

- 8004280280 Forwards Waste Pactaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH.0 H Region i. Philadelphia, Fuel Facility & Materials Safety Dranch 80703705 2pp
- --8004280288 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper requirements. DOT placarding requirements. radiation levels & removable contamination WDDDRUFF.R L . PEERY.U W . PDITER, I P Region 1. Philadelphia. Office of the Director 80/01/18 7pp
- 8004280277 Forwards IE Insp Rept 50-293/79-23 & Waste Packaging Insp Rept 79-088 on 791227-28, 800104 & 791218, respectively GRIER.B H Region i, Philadelphia, Office of the Director 80/03/06 2pp
- --B004280310 Waste Packaging Insp Rept 79-088 on 791218 Noncompliance noted radiation levels in excess of specified limits BROWN, R A. POTTER, J.P. Region 1, Philadelphia, Office of the Director 79/12/21 3pp
- 8004070410 Forwards FR notice of availability of applicant OL application environ assessment & opportunity to request hearing
 DRAGONETTE, K S Low Level Waste Licensing Branch 80/03/13 iu
- --8004070414 Notice of availability of applicant DL application, environ assessment & opportunity to request hearing DRAGONETTE.K S Low Level Haste Licensing Branch 80/03/13 3pp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 77-07A Requests that rept sent on 800222 be destroyed DAVIS:A B Region 3: Chicago: Fuel Facility & Materials Bafety Branch 80/03/2i ip
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance noted DAVIS.A B Region 3, Chicago. Fuel Facility & Meterials Safety Branch. 80/02/22 2pp
- --8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels; removable contamination & package external features
 POTIER, JP Region 3, Chicago, Fuel Facility & Meterials Safety Branch 80/02/22 7pp.
- B004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13. No noncompliance notes DAVIS:A.B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/22. 2pp
- --8004100408 Waste Packaging 79-07A on 80791212-13 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations including shipping paper requirements, radiation is vels & DDT labeling PDTTER-J P Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22, 6pp
- DOCKET 27-048 RICHLAND, WA , NUCLEAR ENGINEERING CO
- 8004210015 Forwards Waste Packaging Insp Rept 80-06 on 800128-0201 No noncompliance noted.

 8MITH/O H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/31. 2pp
- ~-8004210020 Waste Packaging Insp Rept 80~06 on 800128-0201 No noncompliance noted Major areas inspected proper vehicle placarding package insteading backage inselecting BOOK. H E Region 5. San Francisco, Fuel Facility & Materials Safety Branch. CAIN.C L Region 4. Dalias. Office of the Director 80/02/27 App.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0215 B F. APPLIANCE: LTD

- 8003310412 Discusses IE insp of License STB-259 on 800124 & 28 & Forwards notice of violation KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/03.
- --B003310416 Notice of violation from insp on 800124 & 28 Noncompliance noted, survey data & info obtained during 1979 not available for review Burveys performed by consultant firm between Aug & Oct 1979 not documented & given to licensee & Region 3. Chicago, Office of the Director 80/03/03 App.

DOCKET 40-0261 KERR MCKEE CHEMICAL CO

- 8004100548 Forwards IE Insp Rept 40-0216/79-01 on 791220-800104 No noncompliance noted KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/02/13 200
- --8004100551 IE Insp Rept 40-0216/79-01 on 791220-800104 No noncompliance noted Major areas inspected allegations that unsurveyed, steel beam had been removed from facility & installed in residence during 1976
 PAPERIELLO,C , NOVELIUS,C E , WEIL,C H Region 3, Chicago, Office of the Director 80/02/07 9pp

DOCKET 40-0299 UNION CARBIDE CORP

- BOO4240499 "Gootechnical Investigation of Proposed Evaporation Pond, East Gas Hills, WY for Union Carbide Corp " MURDDCK,L T , NEWITON,S M Dames & Moore 79/09/10 78pp
- 8004090347 Forwards request to State of WY Dept of Environ Guality for increase in reclamation bond for projected costs of below grade tailings disposal area & evaporation pond area WDNO.T Union Carbide Corp 80/03/12 3pp.

DOCKET 40-0672 NUCLEAR METALS, INC.

- 8004210027 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 ip
- --B004210035 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, memorable contamination & package external feature requirements POTTER. J P. BROWN. R A Region i. Philadelphia, Fuel Facility & Materials Safety Branch 79/12/12 7pp

DOCKET 40-1162 WESTERN NUCLEAR, INC

- 8004070064 Forwards 800301 ravised renewal application for Source Matis License 8UA-56 W/o encl 8000EM,0 Westinghouse Electric Corp 80/03/04 ip
- 8004090250 Discusses investigation to determine if radon checks mentioned in encl EFA 730108 itr were completed Forwards Jul 1972 "Western Nuclear News," 800226 article from Riverton Ranger BOODEN,O Western Nuclear, Inc (subs of Phelps Dodge Corp) 80/03/04 App
- B004090255 Forwards B00301 revised renewal application for Source Matls License SUA-56 W/o encl BD0DEN.O Western Nuclear, Inc (subs of Phelps Dodge Corp) BD/03/04 ip
- 8004080606 Bubmits justification for deviation from operational guidelines re use of pipe-in-pipe sys as discussed w/NRC on 790926 & 27 Lists disadvantages of sys & proposes alternative BOODEN.0 Western Nuclear, Inc. (subs of Phelps Dodge Corp.) 80/03/07 3pp
- BOO4070259 Requests that review time be set aside to prepare safety evaluation for proposed tailings dam raise at U mill by BOO324 Bafety evaluation must be completed before license can be renewed Further delays will mean wasted time BCARANO,R.A. Uranium Recovery Licensing Branch 80/03/13 lp
- B0040B0607 Responds to concerns in B00131.0214.15 & iB ltrs re renewal of Bplit Rock mill license Reference to 10CFR2 206 in hearing request re renewal not applicable NRC has no direct authority over mining or haulage of ore.

 LINEHAN, J. J. Uranium Recovery Licensing Branch 80/03/15 3pp
- 8004070424 Notifies that transmittal ltrs for distribution of U mill FEB were hand carried to Document Distribution Svcs Branch on 800221 Total of 192 FEB were mailed on 800228 FIBHER.B Uranium Recovery Licensing Branch

- B0042200B3 Requests reconsideration of NRC recommendation for continued use of present tailings pond at Jeffrey City.WY Potential contamination of moving underground water endangers human & animal life BUN.B Affiliation Unknown B0/03/18 ip
- 8004210387 Forwards notice of intent to appeal final EIS re operation of Split Rock U Hill EAST.D J Wyoming Outdoor Council 80/03/21 ip
- --8004210388 Notice of intent to appeal final EIS re operation of Split
- Rock U Hill
 BOCKE B L. Wyoming Outdoor Council BODKE B L. Affiliation
 Unknown 80/03/21 ip
- B004110135 Summary of 800311 meeting w/vendor in Bilver Spring, MD rereview of updated radiation safety program incorporating generic changes since 1976 license revision & environ monitoring program contained in FEB GARCIA.P J Uranium Recovery Licensing Branch 80/03/25 3pp
- 8004280212 Reports review of 780823 & 790719-20 repts & enforcement records No noncompliance found & no license revisions recommended HOOLSEY,R T Uranium Recovery Licensing Branch 80/03/28 ip

DOCKET 40-1193 BABCOCK & WILCOX

- 8004160027 Notifies that Source Matls License BMB-502 is terminated Activities authorized under license were incorporated into Source Matls License BNN-145 PAGE,R 0 Uranium Fuel Licensing Branch 80/03/27 ip
- DOCKET 40-1341 EDGEMONT URANIUM MINE, TVA & MINES DEVELOPMENT, INC.
- 8004080207 Forwards Revision 2 to decommissioning plan environ rept. Revision replaces existing Section 4 4 re geology MILLS.L M Tennessee Valley Authority 80/02/26 ip
- --8004080210 Revision 2 to decommissioning plan environ rept, replacing existing Section 4.4 re geology # Tennessee Valley Authority 80/02/26 9pp
- 8004020j6? Requests legal opinion for U mill tailings in locations away from licensed U recovery facility sites Residents of Edgemont, BD were exposed to high radiation levels NRC role in control of offsite tailings is in question DIRCKS:N J Office of Nuclear Material Safety & Safeguards 80/02/27 2pp
- 800402004B Requests info re acquisition date for License BUA-816, whether license was transferred from Busquehanna Hestern or applied for separately & when license is up for renewal or expiration Discusses requested info re other mills BUCKB, N Black Hills Alliance 80/03/05 ip.
- 800408028B Responds to Subcommittee on Nuclear Regulation 800116 inquiry about NRC activities re health & safety of residents near facility Program to define & remove offsite tailings in progress No agency clearly responsible for remedial actions. AHEARNE, J F Commission 80/03/13 2pp.
- --8004080300 Responds to 800114 inquiry about NRC activities re health & safety of residents near facility Program to define & remove offsite tailings in progress No agency clearly responsible for remedial actions

 AHEARNE, J F Commission 80/03/19 2pp
- --B0040B0305 Responds to B00116 inquiry about NRC activities re health & safety of residents near facility Program to define & remove offsite tailings in progress Nn agency clearly responsible for remedial actions

 AHEARNEJ F Commission 80/03/13, 2pp
- --8004080307 Responds to Subcommittee on Nuclear Regulation 800116 inquiry about NRC activities re health & safety of residents near facility Program to define & remove offsite tailings in progress No agency clearly responsible for remedial actions AHEARNE, J F Commission 80/03/13 2pp
- --8004080314 Requests info on NRC activities re health & safety of residents near facility. Also requests notification of related progress & problems.

 HART, Q., SIMPBON, A. K. Senate, Environment & Public Works.

 MCCOVERN, Q. Senate 80/01/16 1p

004070428 Responds to 800206 request for clarification re info requested by NRC concerning potential for groundwater contamination at tailings disposal site Depth to unjointed unweathered low permeability shale should be determined MILLER: H J Uranium Recovery Licensing Branch 80/03/17 4

O04270070 Advises that J Jacobs will respond to future questions concerning use of Bureau of Land Mgt administered lands near Edgemont. SD for U tailings disposal site Requests lead time to review draft EIS re decommissioning plan * Interior. Dept of, Bureau of Land Management 80/03/17 ip

004280056 Forwards Revision 3 to decommissioning plan environ rept. providing reclamation info & specific discussion of surface water quality impacts
HILLB.L M Tennessee Valley Authority 80/03/25 ip

-8004280060 Facility decommissioning plan, environ rept. Revision 3 * Tennessee Valley Authority 80/03/25 126pp

ICKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEE CORP

004030303 Responds to FOIA request for info re thorium residuals in Nest Chicago, IL Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/03/27 2pp

8004030330 "Praft Environ Assessment re Kerr-McGee Chemical Corp - West Chicago Characterization of Geohydrology & Subsurface Chemistry " Argonne National Laboratory 77/05/31 190pp

O4080158 Forwards transmittal ltrs to distribution list which accompanied decommissioning & stab(lisation plan for West Chicago facility SHELLEY, W.J. Kerr-McGee Nuclear Corp. 79/08/17 3pp

8004080169 Forwards decommissioning & stabilization plan for West Chicago facility W/o enci RICE,G B Kerr-McGee Corp 79/08/15 &pp

04030147 Bubmits response to stabilization plan by Kerr-McGee Corp for decommissioning West Chicago Facility Proposed detention passin must be designed in accordance whiceal water prinances & city soil & erosion control ordinance TOSTER.J D West Chicago, IL 79/09/19 2pp

14080181 Confirms 79:101 telcon re notification from C Henk that tumerous matts used to build home were obtained from terr-McGee factory site Requests that measurements be taken other maths located & measured (ANSELL, D Illinois, State of 79/11/02 2pp

4080072 Advises that participation is welcome in 791218 meeting /public in West Chicago High School re stabilization plan or decommissioning facility
ATALAND. Q R Chicago. City of, IL 79/12/05 2pp

4080177 Requests assistance in selecting remote site for waste torage from defunct Kerr-McGee factory Based on advice from tate of IL Geological Burvey re onsite burial problems, city seeking geologically suitable site
ENNELS; A E Chicago, City of IL 80/01/07 2pp

40401B8 Requests apportunity to review EIS for plan to ecommission facility Early input from EPA could reduce slays that might arise at later date YLOR.D J. Environmental Protoction Agency 80/01/11 ip

4070151 Advises that per 791218 public meeting progosal, interested arties are requested to submit alternatives to proposed Saite burial of defunct factory waste per stabilization len for decommissioning site
NNEY, J. L. Kerr-McGee Corp. 80/01/14 3pp

\$180061 Advises of present facility security program Gloss Guard & tvestigations Svc. Inc provides 24-h coverage & regular Italia inspa conducted of perimeter fences Signs & clusures 'e made & identification cards used NNY.T.L. Kerr-McGee Corp 80/01/28 ip

040490 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 noncompliance noted VIB.A B. Region 3, Chicago, Fuel Facility & Materials Bafety anch 80/02/13 2pp

--8004040453 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Hajor areas inspected shipping paper & DOT placarding requirements, radiation levels & marking requirements
POTTER J P Region 3. Chicago. Fuel Facility & Materials Safety
Branch BROWN:R A Region 3. Chicago. Office of the Director
BO/02/13 4pp

BOO402026B Requests enci Exhibits I-IV be added to Investigative Rept 40-2061/79-01 Exhibits inadvertently omitted from rept KEPPLER, J G Region 3, Chicago, Office of the Director BO/03/04

--B004020273 Ack receipt of 791113 ltr re transfer of matl from site by M Aver Question exists about accuracy of record of transfer HANSELL.D Illinois, State of 79/11/19 ip

--8004020274 Discusses alpha survey of homes in West Chicago, IL re const mat1 from Kerr-McGre site All readings were background level RURGIN, R E Region 3, Chicago, Office of the Director 79/12/04

--B004020276 Testimony re use of matl from Kerr-McGee factory site to construct residence in West Chicago IL AVER.A A Mike Auer Construction Co 79/12/20 1p

8004210348 Submits key dates in schedule for response to comments from various agencies re West Chicago stabilization plan Vendor will edit responses on 800409-10.complete draft w/edit change on 800415 & submit revised plan by 800501 DENNY,T L Kerr-McGee Corp 80/03/17 ip

8004220066 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/04

DOCKET 40-2259 PATHFINDER MINES CORP

8004020291 Forwards radiation surveys for beta-gamma radon daughters & contamination levels of solvent extraction circuit NUCENTIE L' Pathfinder Mines Corp 80/03/03 14pp

DOCKET 40-2286 WESTINGHOUSE ELECTRIC CO

8004150079 Discusses IE insp of License 40-2285/80-01 on 800211 No noncompliance noted Major areas inspected decontamination of drains & radiation readings MCCLINTOCK,R O Region 1. Philadelphia. Office of the Director 80/02/29 2pp

DOCKET 40-3453 ATLAS MINERALS

8004080035 Forwards "Effluent Monitoring Rept, Jul-Dec 1979 " Mill no longer releases liquid effluent to unrestricted areas EDWARDS,D L Atlas Minerals 80/02/28 [p.

--B0040B0057 "Effluent Manitoring Rept.Jul-Dec 1979 " * Atlas Minerals 80/02/28 iipp

B004220099 Requests amend to License Condition 16 2 responds to questions in NRC 800219 itr re-potential flood erosion at mill tailings dam Amend requires strengthening of riprap near Section E from existing 4-inch thickness to meet specs SWANBY, G T Atlas Minerals 80/03/13 6pp

8004290449 Forwards "River Water Sample Analysis Jul-Dec 1979," not received w/priginal rept transmitted 800228 EDWARDS.D L Atlas Minerals 60/03/24 ip

~8004290452 "River Water Bample Analysis Jul-Dec 1979 " # Atlas Minerals 80/03/24 200

8004290ii0 Forwards consultant repts on tailings ratention sys const Also forwards list of specs to be used as guideline during insps at Shootering Cangon site BCARANG,R A Uranium Recovery Licensing Branch B0/04/16. 1p

~-8004270115 Summary of 771004 meeting w/United Nuclear Corp.Dames & Moore & US Army Corps of Engineers in Casper.WY rehydrologic & geotechnical engineering considerations in United Nuclear rept to be submitted late-Oct 1977. KANE.J D. Division of Site Safety & Environmental Analysis 77/10/13 Spp

DOCKETED ITEMS

- --8004290119 Forwards input to SER for Morton Ranch U mill Proposed freeboard for ultimate dam not conservative Applicant should be informed that 9 ft of freeboard will be required in event dam is reised to ultimate elevation of 5,282 ft HULMAN.L G Hydrology Meteorology Branch 79/01/11 2pp
- --8004270121 Input to SER for Morton Ranch U mill Proposed freeboard for ultimate dam not conservative Total freeboard of 9 ft should be provided # Hudrology Meteorology Branch 79/01/11 4pp
- --8004290125 Supplements 790iii input to SER re proposed freeboard not being consorvative Should be license condition to assure that applicant does not initiate tailings storage until dam is ultimate height Nime-ft freeboard still adequate HULMAN.L G Hydrology Meteorology Branch 79/05/10 2pp

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MININO)

8004070238 Comments on environ rept for expansion of U mill Species lists are too lengthy considering lack of impacts Discussion of groundwater connention between Gas Hills area & Platte river sys should be included HALL.J D Interior, Dept of 80/02/25 ip

8004070181 Discusses scoping of draft EIS on Federal American Partnurs U mill, supplementing comments transmitted previous wk Urges NRC to consider belt filtration or other techniques for producing dry tailings, if seepage to groundwater identified DANIELBON, LJ National Wildlife Federation 80/02/28 2pp

8004020053 Submits addl comments on scoping of DES for relicensing of facility NRC should obtain info from biologists w/knowledge of local conditions before drawing conclusions re migration patterns of deer & antelope in area DANIELSON, L. J. National Wildlife Federation 80/03/07 2pp

8004300043 Ack receipt of 800301 & 791113 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 40-4492/ 79-03 BROWN, G.D. Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/03/21 ip

--8004300053 Responds to NRC 800220 ltr w/addl info re violations noted in IE Insp Rept 40-4492//9-03 Micrograms per liter should be substituted for milliroentgens in Sub 1 of vendor 791113

WRIGHT, K H Federal American Partners 80/03/01 1p

--8004300059 Ack receipt of 791113 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 40-4492/79-03 Requests add1 info per 800215 telcon re Item 2 controls BROWN, 0 D. Region 4, Dallas, Fuel Facility & Materials Bafety Branch 80/02/20 ip

--8004300065 Responds to NRC 791016 ltr re violations noted in IE Insp Rept 40-4492/79-03 Corrective actions signs have been posted, bloassay programs strengthened & repts will be sent by closing date WRIGHT,K H Federal American Partners 79/11/13 3pp

--8004300068 Forwards IE Insp Rept 40-4492/79-03.on 790627-28 % notice of violation BROWN.G.D. Region 4. Dallas. Fuel Facility & Materials Safety Branch 79/10/16 2pp

--8004300075 Notice of violation from insp on 790427-28
* Region 4, Dallas, Office of the Director 79/10/11 ip

--B0043000B1 IE Insp Rept 40-4492/79-03 on 790627-28. Noncompliance noted failure to post radiation area signs to implement bloassay program & to submit effluent rept on time BROWN.0 D Region 4. Dallas. Fuel Facility & Materials Sefety Branch CAIN.0 L. HARRIBON.H C Region 4. Dallas. Office of the Director 79/10/11 10pp

DOCKET 40-6329 CATHOLIC UNIV OF AMERICA

8004070089 Ack receipt of 800226 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-00638/80-01, 40-6529/80-01 & 70-0190/80-01 MCCLINTOCK, R O Region 1, Philadelphie, Office of the Director 80/03/04 1p.

- --8004070099 Responds to NRC 800204 ltr re violations noted in IE Rept 30-00638/80-01,40-6329/80-01 & 70-0190/80-01 Corrective actions separate eating space provided for dept of biology & technicians reinstructed re mat1s rules NUESSE, C J Catholic Univ 80/02/26 2pp
- ---8004070104 Forwards IE Insp Repts 30-00638/80-01,40-6329/80-01 70-0190/80-01 on 800116 & notice of violation MCCLINTOCK,R O Region 1, Philadelphia, Office of the Direct
- --B004070107 Notice of violation from insp on B00116 Noncompliance failure to instruct technicians working in lab on procedures for handling radigactive matls Failure to wear protective gloves & having food in restricted area * Region i. Philadelphia. Office of the Director B0/02/04

DOCKET 40-6622 PATHFINDER MINES CORP

8004290444 Forwards in-vivo info for inclusion in data base for U milling facilities
HENDERBONLD M Pathfinder Mines Corp 80/03/25 14ep

DUCKET 40-6659 PETROTOMICS CO , GETTY DIL

- 8004070144 Forwards revised repts showing release amounts per star sampling test at facility from Aug-Oct 1978 & May 1979 PFAFF, B J Getty Oil Co , Petrotomics Co Div 80/02/20 1p
- --8004070185 Submits list of particulate in form of stack gases rainto unrestricted areas, including U.Ra-226.Th-230 & Rn-222 No radionuclide liquid effluents released to unrestricted areas during six months prior to 800101.
 PFAFF, S J Oetty Dil Co , Petrotomics Co Div 80/02/20 1p
- --8004070159 Bubmits list of particulate in form of stack gases reinto unrestricted press, including U.Ra-226, Th-230 & Rn-222 No radonuclide liquid effluents released to unrestricted areas during six months prior to 790101 PFAFF, S J Oetty Oil Co., Patrotomics Co. Div. B0/02/22 ip
- --8004070164 Submits list of particulate in form of stack gases re into unrestricted areas, including U,Ra-226,Th-230 & Rn-222 No radionuclide liquid effluents released to unrestricted areas during six months prior to 790701 PFAFF,S U Oetty dil Co . Petrotomics Co Div 80/02/22 ig
- --B004070169 Bubmits list of particulate in form of stack gases re into unrestricted areas including U.Ra-225.Th-230 & Rn-R22 No radionuclide liquid effluent released to unrestricted areas during six months prior to 780701 PFAFF.8 J Getty Dil Cg., Petrotomics Co Div. B0/02/22, 1p
- B004270110 Forwards consultant repts on tailings retention sys con Also forwards list of specs to be used as guideline during insps at Shootering Canyon site BCARAND,R A, Uranium Recovery Licensing Branch 80/04/16 is

DOCKET 40-7127 TOLEDO, UNIV OF

- 8004020477 Forwards notice of violation from IE insp of Licenses 34-10247-06, 8UD-815 & SNK-915 on 800219-20 DAVI9.A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/03/24 2pp
- --8004020482 Notice of violation from insp on 800219-20, Noncomplian noted food consumed in room & stored in refrigerator w/ radioactive isotopes, no neutron survey meter available for monitoring & no leak test records available for 1978 w Region 3, Chicago, Office of the Director 80/03/24 ip

DOCKET 40-7982 HONEYWELL, INC

8004220045 Forwards IE Info Notice 80-14, "Bafety Buggestions From Employees" No action required.

KEPPLER, J O Region 3, Chicago, Office of the Director. 80/04/10

DOCKET 40-8027 KERR-MCGEE CORP

8004070356 Requests add1 info in response to vendor 800129 application for 1980 fertilizer test program Matl balance & flow diagram for raffinate treatment sys starting w/raffinate from U purification circuit. is needed NIXON.W.A. Uranium Fuel Licensing Branch 80/03/13 2pp

DOCKET 40-8064 EXXON MINERALS CO USA, EXXON CORP

8004080198 Submits 1979 fourth quarter rept for U solution mine pilot operations Restoration operations at original pilot continue to be primary source of fluids from solution mining activity to tailings pond Sample analysis results & plan maps encl TRUSSELL.H H Exzon Minerals Co , USA 80/02/25 16pp

DOCKET 40-8102 EXXON MINERALS CO USA, EXXON CORP

8004070154 Forwards response to 800204 questions re License 6UA-1139 Encl Figures 1-4 placed in Contral Files ORTLOFF. O D Exxon Minerals Co , USA 80/02/28 10pp

8004280403 Responds to recent NRC request for correspondence re renewal of License 8UA-1139 W/o encl GRTLOFF, G D Exxon Minerals Co , USA 80/03/27 ip

8004290526 Forwards application submitted to State of WY Dept of Environ Quality for amend to allow commercial scale solution mining operation W/o encl.
GRTLOFF; G D Erzon Minerals Co , USA 60/03/27 ip

DOCKET 40-8135 3M CO . MINNESOTA MINING & MFO CO

8004040095 Forwards IE Insp Rept 80-01 of Licenses 22-00057-06 & 878-1127 No noncompliance noted DAVIS.A B Region 9. Chicago. Fuel Facility & Materials Safety Branch 80/02/07 2pp

--8004040102 IE Insp Rept 80-01 of Licensee 22-00057-06 & STB-1127 on 800108-11 No noncompliance noted Major areas inspected licensee action of previously identified enforcement matters, radiation protection procedures, audits & equipment PAPERIELLO.C.J., DICEY, B B, OBERG, C.T. Region 3, Chicago, Office of the Director 80/01/30 12pp

DOCKET 40-8304 WYOMING MINERAL CORP

BOO42BORB3 Amend to BOO205 renewal application for License BUA-1204 Condition 8 is amended by striking Nall, AB, Dewey & Ball Claims Conditions added re restoration of groundwater quality in aquifers & completion of amonia studies BCHENDEL, K R Hyoming Mineral Corp BO/03/18 2pp

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO

8004070196 Notifies that state engineers permit not necessary for new evaporation reservoir Ltr to be sent to Rocky Mountain Energy Co requesting termination of LE31, which authorized borehole mining project MORROW, D. Wyoming, State of 80/02/25 ip

8004080203 Forwards correspondence w/state of WV.including water sample results notices of violation & responses for NRC files NEUMANN, M R Rocky Mountain Energy Co. 80/02/29 25pp

B004250023 Forwards water sample results for 800226 & 0304 samplings Includes values for arsenic, selenium & U for 800204 NEUMANN, M R Rocky Mountain Energy Co. 80/03/11 Spp

DOCKET 40-8452 BEAR CREEK URANIUM CO

8004100249 Forwards Drawing I-2 to be included in App I & revised Drawing 174-01-C-094 to be included in App H, omitted from 800130 tailings mgt plan. Encl Drawings 174-PF-D-76 & 174-PF-D-77 w/revisions superseds those in App H HERBLOFF, L. W Rocky Mountain Energy Co 80/02/26 18pp.

--8004100257 "Lang Creek Drainage After Reclamation Water Surface Profiles." 4 Rocky Mountain Energy Co 80/02/25 10

- --8004100263 "Lang Creek Drainage After Reclamation Plan View "
 * Rocky Mountain Energy Co 80/02/28 1p
- --8004100266 "North Area After Reclamation " Figure 1-2 a Rocky Mountain Energy Co 78/08/25 ip
- --B004100272 "Probable Max Flood, Flood Plain at B-3 Pit " * Rocky Mountain Energy Co 80/02/26 1p
- --8004100276 "Cross Sections for Datermination of Probable Max Flood, Flood Plain " # Rocky Mountain Energy Co 80/02/26 ip
- BOO4070249 Recommends issuance of Amend 6 to Bource Matl License SUA-1310, authorizing mod of submittal dates for grizzly operation sampling & background radioactivity study Submittal date changed from BOO201 to BOO501 GARCIA.P J , LINEHAN.J J Uranium Recovery Licensing Branch BO/03/17 1p
- 8004070412 Advises of Amend & to License BUA-1310 authorizing changes in submittal dates for grizzly operation sampling data & background radioactivity study BCARANDIR A Uranium Recovery Licensing Branch 80/03/17 2pp

DOCKET 40-8502 IRIGARAY MINE. WYOMING MINING CORP

8004020160 Summary of 800121 meeting w/vendor in Silver Spring, MD re responses to NRC questions & clarifications concerning amond application to increase plant flow rate capacity from 800 to 2,000 gpm COOPERSTEIN, R Uranium Recovery Licensing Branch 80/02/08 2pp

8004070235 Responds to 800201 request for copy of vendor response to NRC 791220 itr re 2.000 gpm amend request Copy of vendor response was hand-delivered to MY Dept of Environ Quality on 800205 Addl copy will be sent as soon as possible WICHERS.D L Wyoming Mineral Corp 80/02/14 ip

8004070244 Notifies that WY Mineral Corp. MY Permit 478 allows max flow rate capacity for Irigaray Plant of 1600 gpm in response to 791228 request If vendor wished to increase capacity, itr of request will be submitted WIGHERS.D L. Wyoming Mineral Corp. 80/02/14 1p.

8004070195 Confirms 800212 telcon re startup of yellowcake dry-pack/calciner operation per License SU-1341 NRC given required min of 90 days advance notification on 790719
WIGHERS,D L. Wyoming Mineral Corp., 80/02/20 ip

8004040227 Bummarizes 800218 meeting re restoration of alternato lixiviant wellfields, shallow zone excursion & future mine plans Map & agenda encl HOHNE,F C Hestinghouse Electric Corp , Hyoming Mineral Corp 80/02/22 App

8004040221 Forwards groundwater restoration plan for Alternate Lixiviant Heliffield E FORD.W H Hestinghouse Electric Corp . Hypming Mineral Corp 80/02/25 12pp

8004030184 Responds to 800128 ltr re transfer of surface wastes from solution mining operations to mill tallings area View re applicability of 10CFR40 26 is correct SCARAND, R A Uranium Recovery Licensing Branch 80/02/28 ip

#004020155 Requests meeting w/NRC on 800312 to discuss cleanup of shallow tone excursion, groundwater restoration of first wellfield, conversion of plant to alternate likiviant & detailed answers to questions of concern FORD, W H Wyoming Mineral Corp 80/03/04 ip

8004080219 Forwards MY Minoral Corp 800227 ltr forwarding comments re Btate of MY insp repts for facility Soil erosion plan has been developed, Review of well field roadway sys in progress MICHERS D L. Westinghouse Electric Corp . Nyoming Mineral Corp 80/03/04 Spp

8004070070 Forwards 800306 ltr to State of WY w/weekly water quality results for shallow monitor & shallow research wells from samples taken 800213.19 & 26 Pietometric contour maps & arsenic & selenium assay valves from 800213 also encl WICHERB,D L. Wastinghouse Electric Corp. Wyoming Mineral Corp 80/03/06 12pp

800409023; Forwards shallow zone cleanup plan, in support of 790429 application to amend License SUA-1341 FORD, W.H. Myoming Mineral Corp. 80/03/07 lipp

- 8004220088 Responds to 800214 meeting request for clarification of Condition 11 of License SUA-1341 Condition 11 interpreted to refer to production flow rates from mining activities & not restoration flow rates from cleanup FORD.W H Wyoming Mineral Corp 80/03/10 ip
- 8004240178 Forwards rept, "Groundwater Restoration Plan for Production Wellfield A," provided in accordance w/NUREG-OABI Requests authorization to implement plan FORD W H Wyoming Mineral Corp 80/03/10 2pp
- --8004240209 "Oroundwater Restoration Plan for Production Wellfield A "
 * Wyoming Mineral Corp 80/03/10 12pp
- BOO411016B Summary of 800207 meeting w/WY Mineral Corp in Bilver Spring.MD re status of ongoing lixivient excursion into shallow aquifer from current operations & licensee responses to questions re amend application COOPERSTEIN.R Uranium Recovery Licensing Branch 80/03/14 3pp
- 80040703B7 Approves implementation of 800225 groundwater restoration of alternate lixiviant well field E plan Requests monthly progress 1tr be submitted re developments & possible LINEHAN, J J Uranium Recovery Licensing Branch 80/03/18 1p
- 8004220076 Advises of intent to conduct radon emissions study of alternate lixiviant process to obtain estimate of radon emissions associated u/groundwater cleanup activities at Alternate Lixiviant E Wellfield FORD, W H. Wyoming Mineral Corp 80/03/19 ip Wyoming Mineral Corp 80/03/19
- 8004290075 Advises that WY Land Quality Div presently considers shallow tone excursion uncontrolled SM-4 in Field F has been above upper control limit for chloride & conductivity for two consecutive samples MORROW,D Wyoming, State of 80/03/21 ip
- BOO4210413 Forwards 800329 itr to State of HY including weekly water quality results for shallow monitor & shallow research wells for 800307.11 & 21 Shallow monitor well SM-4 exceeded upper control limits for chloride for two consecutive samples WICHERS.D L Hyoming Mineral Corp 80/03/26 10pp
- DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO
- BOO4070262 Bubmits info re composition of mati underlying tailings cells in response to NRC request Subsurface strata is mostly poorly communted arkosic sandstone w/interbedded layers of harder siltstone Cites reference works documenting info ACOSTA, A P Union 76 Minerals Exploration Co BO/02/26 ip
- DOCKET 40-8602 UNITED NUCLEAR CORP
- 8004280423 Forwards repts & drawings prepared by CO State Univ of U Mill project ROSBBACH, L 1 79/08/15 ip Uranium Recovery Licensing Branch FIN 8-4434-9
- --8004260425 Summary of 790226 site visit to assess diversion ditch design & total drainage area of U operation Assessment rept BIMMONS, D. R. RUH-MING, L. Colorado State Univ 79/03/22 11pp
- Mill.HY "
 SIMMONS,D D , RUH-MING,L Colorado State Univ FIN 8-6436-9
- 8004070242 Notifies that foundation excavation for effluent evaporation pond & embankment is nearing completion & that placement of embankment fill will commence, weather permitting, on or after 800414 WOLFF.C E United Nuclear Corp 80/02/27 1p
- 8004290036 Requests that IE conduct insp of foundation excavations for tailings embankment & evaporation pond at Morton Ranch mill tailings pand embankment at Shootering Canyon mill. Morton Ranch license encl
 8CARANO,R A Uranium Recovery Licensing Branch, 80/04/02 1p
- --800429004: License for United Nuclear Corp for possession of byproduct matl in form of U waste tailings generated by milling operations authorized Under License 8UA-1356 BARANG, R A Uranium Recovery Licensing Branch 79/05/10 7pp

- ---8004290044 Amend to License SUA-1371 Amend 1 authorizes const of embankment for tailings impoundment SCARANO,R A Uranium Recovery Licensing Branch 79/09/28 Spp
- 8004300106 Requests that IE inspect foundation excavations for tailings pond embankment & evaporation pond at Morton Ranch & tailings pond embankment at Shootering Canyon Summary of specs encl
 SCARAND.R A Uranium Recovery Licensing Branch 80/04/02 2pp
- 8004290110 Forwards consultant rapts on tailings retention sys const Also forwards list of specs to be used as guideline during insps at Shootering Canyon site SCARANDIR A Uranium Recovery Licensing Branch 80/04/16 ip
- --B004290115 Bummary of 771004 meeting w/United Nuclear Corp.Dames & Moore & US Army Corps of Engineers in Casper.WY rehydrologic & geotechnical engineering considerations in United Nuclear rept to be submitted late-Oct 1977 KANE, J D Pivision of Site Bafety & Environmental Analysis 77/10/13 3pp
- --8004290i19 Forwards input to SER for Morton Ranch U mill Proposed freeboard for ultimate dam not conservative Applicant should be informed that 9 ft of freeboard will be required in event dam is raised to ultimate elevation of 5,282 ft HULMAN.L O Hydrology Meteorology Branch 79/01/11 2pp
- --8004290121 Input to SER for Morton Ranch U mill Proposed freeboard for ultimate dam not conservative Total freeboard of 9 ft should be provided * Hydrology Moteorology Branch 79/01/11 4pp
- --B004290125 Supplements 790111 input to SER re proposed freeboard not being conservative Should be license condition to assure that applicant does not initiate tailings storage until dam is ultimate height Nine-ft freeboard still adequate HULMAN.L G Hydrology Meteorology Branch 79/05/10 2pp
- DOCKET 40-8647 KERR-MCGEE CORP
- 8004070361 Responds to 800217 inquiry re current status of mineral development project Vendor is conducting mining operations at several locations within permit area & has applied for milling license Map of proposed ion exchange facility encl MU.O Uranium Recovery Licensing Branch 80/03/13 3pp
- DOCKET 40-8675 ENERGY FUELS NUCLEAR, INC.
- 8004020151 Forwards rept on decommissioning program for Hanksville Gre Buying Station QLASIER, Q E Affiliation Unknown 60/03/03 6pp
- DOCKET 40-8481 ENERGY FUELS NUCLEAR, INC.
- 8004020487 Forwards D'Appolonia 800214 rept re methods of calculating reclamation costs for White Mesa tailings disposal area.
 Discusses reclamation & decommissioning costs Requests that NRC review estimates & concur w/required surety GALBIER, 0 E Energy Fuels Nuclear, Inc. 80/02/18 7pp
- 8004280417 Requests that IE conduct const insp of tailings impoundment SCARANG, R A Granium Recovery Licensing Branch 80/03/31 2pp
- --8004280418 Amend 1 to License BUA-1358 authorizing first stage of const of embankments & liner sys of tailings retention sys. BCARANO.R A Uranium Recovery Licensing Branch 79/10/12 4pp
- --8004280420 Bummary of 791109 site visit to inspect const of embankments on Cells 1,2 & 3 & daily records of density & water content tests Energy Fuels Nuclear 791022 memo documenting 791018 site visit encl NELSON,J D Colorado Btate Univ 79/11/12 15pp
- 8004300087 Discusses performance of archaeological excavations & analyses, Suggests review of research proposals of prospective consultants to ensure that ancillary studies are MADSEN.D B Utah, State of 80/04/07 3pg
- 8004290110 Forwards consultant repts on tailings retention sys const Also forwards list of specs to be used as guideline during insps at Shootering Canyon site SCARANG.R A Uranium Recovery Licensing Branch 80/04/16 ip

DOCKET 40-8698 PLATEAU RESOURCES, LTD

8004280064 Confirms 800318 telcon re key trench insp Key trench expected to be ready for insp during first half of Apr 1980 Backfilling of downstream shell foundation will begin upon approval of Hoodward-Cilyde Consultants rept NEWMAN,P S Plateau Resources, Ltd 80/03/18 ip

B004290036 Requests that IE conduct insp of foundation excavations for tailings embankment & evaporation pond at Morton Ranch mill tailings pond embankment at Shootering Canyon mill Morton Ranch license ent!

BCARANO, R A Uranium Recovery Licensing Branch 80/04/02 1p

--8004290044 Amend to License SUA-1371 Amend (authorizes const of ambankment for tailings impoundment SCARAND, R A Uranium Recovery Licensing Branch 79/09/28 Bpp

8004300106 Requests that IE inspect foundation excavations for tailings pand embankment & evaporation pand at Morton Ranch & tailings pand embankment at Shootering Canyon Summary of space and Scarano, R A Uranium Recovery Licensing Branch 80/04/02 2pp

8004290110 Forwards consultant repts on tailings retention sys const Also forwards list of specs to be used as guideline during insps at Shootering Canyon site BCARANDAR A Uranium Recovery Licensing Branch 80/04/16 ip

DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

8004090209 Bubmits trip rept including 790724 scoping meeting w/
applicant, state & federal agents & general public in
Cheyenne, MY, re EIS for proposed Nine Mile Lake in-situ U
recovery project List of attendess encl
ROTHFLEISCH, J Uranium Recovery Licensing Branch 80/03/21 6pp

DOCKET 40-8722 BRUSH-WELLHAM, INC

8004300243 Advises that U recovery operations will begin on 900517 POWERS,M B Brush-Wellman, Inc. 80/03/21. Sp

DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP.

8004070361 Responds to 800217 inquiry re current status of mineral davelopment project Vendor is conducting mining operations at several locations within permit area to has applied for milling license Map of proposed ion exchange facility encl MU.O Uranium Recovery Licensing Branch 80/03/13 3pp

8004070376 Forwards proposed NRC matl license for ion exchange facility, supporting NRC environ impact assessment/sefety review & source documents used by NRC to prepare assessment Requests comments by 8000319 M/o encls HU, G Uranium Recovery Licensing Branch. 80/03/13 1p

DOCKET 40-8729 TETON EXPLORATION DRILLING CO . INC

4070038 Summarizes encl 791024 ltr from consulting geplogist,
Harner, re geology & groundwater aspects of Teton
apploration Drilling Co U in situ extraction project environ
apt M/o encl
AUFMAN, R & Uranium Recovery Licensing Branch 80/03/05 4pp

04090334 Notifies of invoice to be sent for add1 fee in connection #/review of application for License SUA-1373

MILLER.W 0 License Fee Management Branch 80/03/25 1p

KET 40-8745 DOLE PETROLEUM

14020064 Documents from State Dept of Environ Quality including memo e water quality, analysis of comments on in situ mining regulations & revised regulations & dept guidelines for reparation of RAD in situ testing Itemse HANGINI.A J. Wyoming, State of 80/01/29 9ipp

4030001 Responds to NRC 800215 request re biological assessment etermining whether proposed Hison Basin project has impact n bald eagle & black-footed ferret. Addl biological ssessment impossible due to weather conditions ATCHPOLE, Q J. Ogle Petroleum, Inc. 80/03/06 tipp

--8004030003 Comments on environ rept re Ogle Petroleum inc River Basin project WALLENSTROM.R Interior Dept of Fish & Wildlife Service BO/02/01 Boo

8004240563 Forwards response to NRC 791126 Question 25 re analytical data pertaining to barren & pregnant lixiviant streams from 25 gpm R&D test CATCHPOLE: 6 J Ggle Petroleum: Inc 80/03/2: 3pp

DOCKET 40-8740 EDLOW INTERNATIONAL CORP

80040402 FOIA request for records re Ediow Intl Co.Inc application to store radioactive matls in or near East St Louis.IL JEFFERG.T Affiliation Unknown 80/02/29 1p

8004040419 Responds to FDIA request for records re Ediow intl Co.inc application to store radioactive matls in or near East St Louis, IL Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/03/24 2pp

--BCO4040446 License SMC-1377, authorizing storage & use of 1.643,400 kgs natural U in form of U hexafiyoride & 962,300 kgs natural U in form of U ors concentrate by Edlow Intl Co BASSIN.N Licensing Namagement Branch 80/02/14 2pp

DOCKET 40-8768 KERR-MCKEE NUCLEAR CORP

8004240108 Ack receipt of 800325 application for source matl license to conduct in-situ R&D program at U site Application fee is required to process application WEISS, J D License Fee Management Branch 80/04/02 ip

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR
P Operating license stage documents & correspondence

7904110103 Responds to NRC questions repilot study on personnel dosimetry Concludes most processors have not exerted effort required to pass HPBSC std Proposes three-phase course of constructive action PLATO.P. HUDBON.G Michigan, Univ of 79/03/08 12pp

7910180103 Forwards interim position on containment purging during normal operation & proposed purge valve interim position comments Rocommends that 20-day ltr to licensees request that licensee comply w/encl position in interim ORIMES.B K Assistant Director for Systems Engineering (Pre 791030) 79/09/24 4pp

8004040385 Application to amend License R-28, changing Tech Specs, App A, Section 5.2 re-utilization of low enriched U KERR.W Michigan, Univ of 80/04/02 2pp

--8004040389 "Bafety Analysis - Utilization of Low Enrichment U Fuel," submitted in support of application to amend OL # Michigan, Univ of 79/10/31 Sipp.

4 Inspection reports, IE Gulletins & correspondence

8004090319 Forwards IE Insp Rept 50-002/80-01 on 800121-23 No noncompliance noted DAVIS:A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch, 80/02/25 2pp

--8004070327 IE Insp Rept 50-002/80-01 on 800121-23 No noncompliance noted Major areas inspected radwaste programs including qualifications.audits.facilities,training.procedures, & equipment FIBHER,N L Region 3, Chicago, Fuel Facility & Materials Safety Branch PAUL,R A . MILLER,D E Region 3, Chicago, Office of the Director 80/02/21 7pp

8004240513 Forwards IE Insp Rept 90-002/80-03 on 800304,10 & 17 No nancompliance noted Rept withheld (ref 10CFR2 770) HIND.J A Region 3: Chicago, Office of the Director 80/03/28

80043000B9 Forwards IE Insp Rept 50-002/80-04 on B00310-12 No noncompliance noted Rept withheld (ref 10CFR2 770) HIND, J A Region 3, Chicago, Bafeguards Branch 80/03/28 1p

- DOCKET 50-3 INDIAN POINT STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8004100100 Comments on proposed rule 10CFR50 10-mile emergency planning zone for plume exposure lacks technical justification NRC adopted position w/o studying validity of underlying bases WEISS.E R Sheldon, Harmon & Weiss 80/02/19 5pp
- BOO4080695 FOIA request, on behalf of UCS, for time analysis required to evacuate public from 10-mile area surrounding facilities WEISS, E.R. Sheldon, Harmon & Weiss BO/03/20 1p
- SOO4080690 Responds to FOIA request for time analysis required to evacuate public from 10-mile area surrounding facilities Forwards rept: "Evacuation Times Estimates for Areas Near Site," W/o encl FELTON, J M Division of Rules and Records 80/03/31 lp
- Q- Adjudicatory correspondence
- GOO4020091 Forwards UCS 800310 comments on director's decision under 10CFR2 206 Decision & confirmatory order do not resolve Critical issues Objects to exclusion of petitioner from meetings & correspondence solving issues
 WEISS, E. R. Sheldon, Harmon & Weiss 80/03/10 2pp

- --- EDOO4020115 "Rept on NRC Reactor Safety Review Process." Pp 8-14 & 17-19 POLLARD, R D Division of Project Management 76/02/06 11pp
- --BOO4020118 Discusses site visit & outstanding info requests Requests responses by 780718 Requests for info encl STELLO.V Division of Operating Reactors 78/08/31 18pp
- BOO 4030168 Response to NRC 800211 order to show cause re revocation of license Unit has been shut down since October 1974 Plant will retire as generating unit per util 800226 decision.but will remain as support & research ctr W/Certificate of Svc ZARAKAS.P. Gonsolidated Edison Co of New York, 80/03/12 8pp
- 8004070047 Order greating extension until 800414 for Commission to review director's 800211 decision HOYLE, J. C. Office of the Secretary of the Commission 80/03/31 1P-
- BOO 4030026 Memorandum of understanding between NRC & FEMA re-prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOBSICK.L.V. Office of the Executive Director for Operations GAMM.F Federal Emergency Management Agency 80/04/02 34pp
- 3004150073 Order granting extension until 800425 for Commission to # 1 mc t whether to review ALAB-436 & ALAB-561
 CHILK: B J. Office of the Secretary of the Commission. 80/04/04
 19-
- 004220754 Forwards petition supporting UCS petition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 GRAVES, R. S Housetonic Safe Energy Alliance, 80/04/13 ip

- ---8004220762 Supports UCS petition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 ORAVES.R S Housatonic Safe Energy Alliance 80/02/15 ip
- H General correspondence
- 8004070200 FOIA request for info re facilities & damage due to earthquakes at Indian Point BEBAS.P G Affiliation Unknown 80/02/10 ip
- 8004030016 Advises that Commission should evaluate need for power generated by Facility & take close look at safety achieved for public protection OILINSKY, V Commission 80/03/11 ip
- --800403001B Responds to 800225 ltr Forwards NY Times article re lack of need for electricity produced at facility Cites util trade association statement that reserve margin of 2% would exist if all plants in svc grid were shut down LEVINSON, J O Affiliation Unknown 60/03/02 2pp
- --B004030024 Responds to B00208 ltr supporting petition by UCB requesting decommissioning of Unit 1 & suspending operations of Units 2 & 3 Advises that Commission is reviewing comments on matter GILINSKY, V Commission B0/02/25 3pp
- --8004030025 Supports UCS 790917 potition requesting decommissioning of Unit 1 % suspension of operations at Units 2 % 3 Cites safety-related reasons for prompt action Cortificate of Svc encl LEVINSON, J O Affiliation Unknown 80/02/08 3pp
- BOD4070194 Responds to FDIA request for info re facilities & damage due to earthquakes at Indian Point Forwards Documents 1-4 listed in App A Documents 5 & 6 may be purchased by sending check in amount of \$9.50 to NRC in Mashington.D C
 FELTON.J M Division of Rules and Records 80/03/19 2pp
- --8004070205 "Semiannual Operating Rept," Jul-Dec 1973
 * Consolidated Edison Co. of New York 73/12/31 20pp
- --8004070208 "Semiennual Operating Rept." Jan-June 1974 * Consolidated Edison Co. of New York 74/06/30 21pp
- --B004070214 "Semiannual Operating Rept," Jul-Dec 1974 * Consolidated Edison Co of New York 74/12/31 21p
- --8004070224 "Annual Operating Rept." 1975 * Consolidated Edison Co of New York 75/12/31 22pp
- --8004070229 "Annual Operating Rept." 1976 * Consolidated Edison Co. of New York 76/12/31 27pp
- --8004070233 "Annual Operating Rept," 1977 THI semiannual & annual operating rept excerpts encl .

 * Consolidated Edison Co of New York 77/12/31 45pp
- 8004290054 Forwards info requested in 800218 ltr re licensing actions Matl could not be forwarded by 800225 as ltr did not arrive at NRC until 800226 W/o ancls DENTON.HR Diffice of Nuclear Reactor Regulation 80/03/25 2pp
- --8004270058 Requests info re changes affecting extension of DLs to 810101 FLEISHER, Z 8 Affiliation Unknown 80/02/18 1p
- 8004180234 Forwards NRC 800325 response to encl 800218 ltr from ZE Figisher of West Branch Conservation Association in response to 800226 request W/o encl DRCKS.H J Office of the Executive Director for Operations 80/03/28
- --8004180237 Requests info re new safety regulations FLEIGHER, Z 8 West Branch Conservation Association 80/02/18 1b
- 8004i5008B Responds to 80022B ltr re operation of nuclear power plants in high density areas NRC is investigating special measures to be taken in heavily populated areas Interim measures have already been ordered at sites.

 DENTON: HR Defice of Nuclear Reactor Regulation 80/04/01 2pp
- --8004150094 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident STERNER, J W Affiliation Unknown 80/02/28 ip

- 8004160173 Responds to B00212 ltr re continued operation of nuclear power plant Addl measures should be implemented that will further reduce probability of severe reactor accidents. Licensee has been in shutdown pending completion of actions DENTON, HR Dffice of Nuclear Reactor Regulation B0/04/01 2pp
- ~-8004160176 Requests that NRC not phase out facility or convert to monnuclear generators Ruclear power is source for power in US No nuke political arguments have no bass in reality LAVERTY, E Affiliation Unknown 80/02/12 2pp
- 8004170342 Responds to 800206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility, confirming commitment to public health & safety DENTON. H R Dffice of Nuclear Reactor Regulation 80/04/01 2pp
- 8004210088 Rosponds to 800125 request re-public hearing & determination on UCS petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or lessen consequences

 DENTON: HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- ~-8004210093 Requests scheduling of public hearing & determination of UCS petition re operation of facility prior to reactivation Concerned for health & safety of community SCIANDRA, J. New York, NY 80/01/25 ip
- 8004210193 Responds to 800207 ltr re continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants Interim measures have already been ordered at sites DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- ~-8004210201 Supports continued operation of facility Reactors supply 20% of generating capacity for New York City & Hestchester County Utils can shut off oil plant/lowering rates & dependency on foreign oil WU/U Affiliation Unknown 80/02/07 ip
- 800421020B Responds to 800204 ltr re continued operation of facility Plants reviewed to determine what addl measures or design changes can & should be implemented to further reduce probability of reactor accident or consequences
 DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- ~-8004210223 Urges NRC to decide in favor of continued operation of facility Reactors have long history of safe, clean & economic operation Concerned that fuel adjustment charges will increase if plants are shot down
 OAY R Affiliation Unknown 80/02/04 ip
- BOO4250013 Responds to BOO212 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure

 DENTON, H R Office of Nuclear Reactor Regulation BO/04/01 2pp
- --8004250030 Urges that NRC consider UCS petition re closing of facility Possibility of earthquake exists w/plant built near fault Unit 200 of erra energy generated by nuclear power Alternatives should be considered GOLDHOR.F Affiliation Unknown 80/02/12 ip
- BOO4230185 Advises that NRC held two meetings in NY re continuing operation at facility Commission presently considering form of review Public comments invited Request for another hearing in vicinity of plant uill be considered DENTON, HR Office of Nuclear Reactor Regulation BO/04/03 ip
- --B004230190 Requests that NRC hold another public hearing re continuing operation of facility to offer public chance to question plant operators & govt agencies Public should be properly notified through local news media CONNOR.R J New York, State of B0/01/08 2pp
- B004280140 Responds to B00117 ltr to DDE re B00117 incident at facilities Flent did not trip during minor earthquake tremor Epicenter of tremor was located approx seven miles from site Tremor was significantly below design capability, EISENHUT.D © Division of Operating Reactors 80/04/08 ip
- P Operating license stage documents & correspondence
- B004070094 Forwards agenda & proposed rule for NRC sponsored B00113 meeting in New York,NY re proposed rule on emergency response RYAN,R C Office of State Programs 79/12/31 12pp

- --B00407007B Requests opportunity to testify at NRC 800115 meeting in New York, NY re emergency response plans in fifty-mile zone around plant NY City Council has been holding hearings or resolution to phase out plant FRIEDLANDER. H New York, NY 79/12/21 ip
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Uperations Ctr EISENNUTID 0 Division of Operating Reactors 80/03/12 5pp
- ---B004030118 "Nuclear Data Link Specs "
 + Division of Operating Reactors 80/02/21 28pp
- 8004110045 FOIA request on behalf of UCS for Sandia Labs study re liquid effluent pathway at facility WEISS,E R Sheldon, Harmon & Waiss 80/03/18 ip
- 8004110039 Responds to FOIA request for Sandia Labs study re liquid effluent pathway at facility Rept is undergoing NRC technical review prior to publication Draft encl FELTON: J N Division of Rules and Records 80/04/02 1p
- --8004110051 Draft study of facility liquid effluent pathway
 # Bandia Laboratories 80/04/02 800pp
- 8004280197 Responds to util 790720 proposed amend to Tech Specs re radiological efficient & environ monitoring sys Forwards comments & marked-up copy of Unit 2 Tech Specs for incorporation into proposed amend SCHWENCER: A Operating Reactors Branch 1 80/04/14 7pp
- --8004280204 Marked-up version of util 790731 App A Tech Spacs re radiological effluent & environ monitoring sys # Office of Nuclear Reactor Regulation 80/04/14, 125pp
- G Inspection reports, IE Bulletins & correspondence
- B004150253 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary.
 GRIER, B H Region i, Philadelphia. Office of the Director, B0/03/3i ip
- 8004070045 Forwards IE Circular 80-05. "Emergency Diesel Oenerator Lubricating Oil Addition & Onsite Supply " No written response raquired ORIER, B H Region 1. Philadelphia. Office of the Diractor 80/04/01 ip
- GOO4110126 Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004240297 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required ORIER, BH Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180210 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil 8ys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director, 80/04/03 ip
- 8004230403 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe." Action required QRIER, B M. Region 1. Philadelphia. Office of the Director 80/04/04 ip
- BO04180125 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ORIER, B H Region i, Philadelphia, Office of the Director, 80/04/07 ip
- R Periodic operating reports & related correspondence
- 8004150599 Forwards "Environ Discharge Monitoring Rept for Mar 1980 "
 MONFI,W. A Consolidated Edison Co of New York 80/04/10 1p,
- --B004150609 "Environ Discharge Monitoring Rept for Mar 1980 "
 * Consolidated Edison Co of New York 80/04/10 15pp
- 8004210269 Forwards "Daily Counts from Intake Screens, Har 1980," refish collections Circulators were shut down for month at Unit 1 CAHILL, W J Consolidated Edison Co of New York 80/04/15 1p

- --8004210276 "Daily Counts from Intake Screens, Mar 1980." re fish collections
 - Consolidated Edison Co of New York 80/04/15 4pg

U Congressional/Executive Correspondence

- 8004080193 Responds to 791212 ltr re Rockland Mobilization for Survival ltr concerning Dec 1979 public meeting on emergency preparedness Period of public comment lasted until NRC participants had listened to all speakers DIRCKS. V Dffice of the Executive Director for Operations 80/03/05 2pp
- --8004080206 Discusses 791218 public meeting on emergency preparedness
 Plans should be arranged to allow ample time for public
 comment Viewpoints of citizens within facility vicinity
 appear to be unimportant to NRC
 STERN.L D Rockland Mobilization for Survival 79/12/05 2pp
- 8004300792 Forwards Congressman Rosenthal B00114 ltr re concerns falling within FR B00222 notice requesting public views on proceeding issues
 DIRCKS,W J Office of the Executive Director for Operations ip 80/04/11
- --8004300297 Conveys concerns re safety & health risks posed by plants & lack of adequate evacuation plan Urges NRC to respond to UCS petition
 ROSENTHAL.B S House of Rep , Foreign Affairs 80/01/14 1p
- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8004240531 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during health physics telephone network Sys designed for use during nuclear incident or AD Network may also be used for daily administrative or facsimilie traffic
 KEPPLER.J O Region 3, Chicago. Office of the Director 80/03/20
- 8004030172 Forwards Figure 2-1 to correct omission made in 800311 ltr re avacuation time estimates for facility Figure 3-1 in Section 3 should be placed in Section 2 PEDPLES D.L. Commonwealth Edison Co 80/03/26 App
- 8004150344 Forwards drawings & submits responses to NRC concerns re mods to fire protection design of fire detection sys & water suppression sys Drawings available in Central Files only JANECEKIR F Commonwealth Edison Co
- 8004230367 Forwards revised security plan Revisions.withheld (ref 10CFR2 790), PEOPLES D L Commonwealth Edison Co 80/04/21, 1P

Q Adjudicatory correspondence

- 8004250096 Responds to 800109 request for info re status of 790319 petition for preparation of EIS for chemical decontamination of facility NRC is presently reassessing environ impact of facility decontamination MENTON.H R Office of Nuclear Reactor Regulation 80/03/26 2
- --8004250062 Requests info re whether EI8 will be prepared prior to chemical decontamination of facility. There has been no public hearing, EI8 or opportunity for independent scientists to study impact of decontamination Grience article encl DREY, K. Affiliation Unknown 80/01/09 App

H General correspondence

- 8004070418 Discusses method of disposal of radwaste from facility decontamination, classification of waste & requirements util must comply with before returning facility to svc in response to 800119 itr
 VOLLMER.R H Assistant Director for Systems & Projects 80/03/13
- --8004070421 Opposes pending decontamination of facility due to possibility of migration of raduxate after burial lack of sites for burial & possibility of damage to facility STEDER, P. STEDER, T. Affiliation Unknown 80/01/19. 3pp.
- B004210282 Responds to ltr re chemical decontamination of facility Disposal of waste will not cause any new hazards not previously evaluted. Disposal is acceptable Forwards safety VOLLMER, R, H Systematic Evaluation Program Branch 80/03/15 5pp

- --8004210256 Protests proposed decontamination of facility Requests that EI8 be prepared prior to decontamination & that public hearings be held immediately to address safety MOLONE, L. Affiliation Unknown 80/04/08 ip
- 8004210260 Responds to ltr re chemical decontamination of facility Waste processing transportation & disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLLMER, R H Systematic Evaluation Program Branch 80/03/15 App
- --8004210264 Protests proposed decontamination of facility Requests that EIS be prepared prior to decontamination & that public hearings be immediately held re safety PETRIE.L Affiliation Unknown 80/04/08 ip
- 8004210272 Responds to 1tr re chemical decontamination of facility Waste disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLLMER.R N Systematic Evaluation Program Branch 80/09/15
- --8004210279 Protests proposed decontamination of facility Requests that EIS be prepared prior to decontamination & that public hearings be held immediately to address safety FERN B Affiliation Unknown 80/03/19 ip
- B004210287 Responds to ltr re chemical decontamination of facility Waste disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLLMERIR H Systematic Evaluation Program Branch B0/03/15 App
- ---9004210270 Protests proposed decontamination of facility Raquests that EIS be prepared prior to decontamination & that public hearings be hold immediately to address safety LITTLE.R Affiliation Unknown 80/03/15 ip
- 8004210298 Responds to 1tr re chemical decontamination of facility Maste disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLLMER:R H Systematic Evaluation Program Branch 80/03/15. App
- --8004210297 Protests proposed decontamination of facility Requests that
 EIB be prepared prior to decontamination & that public
 hearings be held immediately to address safety
 RODERS.L W Affiliation Unknown 80/03/15 ip
- B004210299 Responds to ltr re chemical decontemination of facility Maste disposal will not cause any new hazards not previously evaluated Disposal is acceptable forwards safety evaluation. VDLLMER.R H Systematic Evaluation Program Branch 80/03/15
- --8004210300 Protests proposed decontamination of facility Requests that EIS be prepared prior to decontamination & that public hearings be held immediately to address safety DEGEN.O. Affiliation Unknown 80/03/15 ip
- 8004210302 Responds to ltr re chemical decontemination of facility Waste disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLLMER.R.H Systematic Evaluation Program Branch. 80/03/15
- --8004210305 Protests proposed decontamination of facility. Requests that EIS be prepared prior to decontamination & that public hearings by held immediately to address safety. BRIDGES.O Affiliation Unknown 80/03/15 ip
- BOO421030B Responds to 1tr re chemical decontamination of facility. Waste disposal will not cause any new hazards not previously evaluated. Disposal is acceptable. Forwards safety evaluation & J Checker 1tr. VOLLMER:P H Systematic Evaluation Program Branch 80/03/15 App
- ---BOD4210310 Protests proposed decontamination of facility Requests that EIB be prepared prior to decontamination & that public hearings be held immediately to address safety CHECKER, J. Affiliation Unknown BO/03/15 ip
- BOO4i502ii Responds to ltr re chemical decontamination of facility Waste processing, transportation & disposal will not cause any new hazards not previously evaluated Decontamination is acceptable forwards safety evaluation
 DENTON:H R Office of Nuclear Reactor Regulation BO/03/26. Spp.
- --8004180216 Requests that complete public hearing on planned decontamination action be held that EI8 be completed & that no radioactive chamical waste be stored in IL MARTIN. @ Affiliation Unknown 80/01/08 3pp.

- 04230388 Ack receipt of ltr enclosing J Mayes ltr on decontamination Forwards response to J Mayes ltr.providing background of decontamination review & identifying actions for which EI8 is required Need for EI6 will be considered DENTON-H R Office of Nuclear Reactor Regulation 80/03/26 ip
- -8004250394 Joins IL Safe Energy Alliance petitioners in request that public hearings be held on decontamination of facility JOHNSON: T V Illinois. State of 80/03/26 ip.
- -8004250377 Requests info re public hearings & EIB concerning facility decontamination "Experiment" could have alarming effects on population & ecosys
 MAYEB, J Affiliation Unknown 80/01/14 3pp
- 004280362 Responds to 790625 ltr requesting preparation of EIS for decontamination Presently evaluating whether EIS should be prepared DENTON.H R Office of Nuclear Reactor Regulation 80/04/14 2pp
- -8004280366 Believes it imparative that EIS to prepared prior to decontamination of facility VONZELLENS B W Northern Illinois Univ 77/06/25 ip
- -8004280369 Responds to 790625 ltr requesting EIS be prepared prior to decontamination of facility Currently reviewing K Drey 790310 petition requesting preparation of EIS EISENHUT, D G Division of Operating Reactors 79/09/25 ip
- -8004280375 Ack receipt of 790319 petition requesting preparation of EIS prior to decontomination of facility Request will be treated per 2 206

 DENTIN.H R Office of Nuclear Reactor Regulation 79/04/09 ip
- --B004280379 Notice of receipt of K Drey 790319 petition requesting preparation of EIS prior to decontamination Request treated per 2 206 BDYD.R S Office of Nuclear Reactor Regulation 79/04/19 ip
 - Operating license stage documents & correspondence
- '812060303 Notification of 781207 meeting w/8EP Dwner's Oroup in Bethesda,MD to discuss plans to address seismic input for use in SEP seismic review LEVIN,H A Systematic Evaluation Programs Branch (Pre 790625) 78/11/24 2pp
- '908210548 Forwards info to present status & completion schedules for work being performed under technical assistance program Info will be updated monthly PANCIERA.V Plant Systems Branch (Fre 791030) 79/07/25 22pp
- 3004100302 Advises that responses to 74i123 ltrs re LWR assessment of enhancement of fission gas rolease at higher burnups have been reviewed No immodiate licensing action required for aperating reactors par typical fuel bundle & batch burnups ZIEMANN.D L. Operating Reactors Branch 2 80/02/27 3pp
- 3004090335 Forwards NUREO-0569. "Evaluation of Integrity of SEP Reactor Vessels." completing review of SEP Topic V-6.Wo encl ZIEMANN.D L. Operating Reactors Branch 2 B0/03/03 2pp
- 3004020010 Forwards revieu schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptably ZIEMANN, D.L. Operating Reactors Branch 2 80/03/06 5pp
- 8004030102 Forwards "Nuclear Data Link Spece," study of digital communication sys to transmit info from plants to Hethesda Operations Cir EISENNUT, D & Division of Operating Reactors 80/03/12 3pp
- --8004030118 "Nuclear Data Link Specs " # Division of Operating Reactors 80/02/21 28pp
- 9004100102 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response cir within 20 days

 KEPPLER.J & Pegion 3. Chicago, Office of the Director 60/03/20 in
- 8004090259 Notification of 800329 meeting w/SEP cwners proup in Bethesda.MD to discuss sensitivity studies re SEP sitespecific spectra project LEVIN.H A Bystematic Evaluation Program Branch. 80/03/24 ip

- 8004170279 Forwards evaluation of SEP Topic XV-20 re radiological consequences of fuel damaging accidents, inside & outside containment Review complete & evaluation will be basic input to integrated safety assessment for facility ITEMANN, D.L. Operating Reactors Branch 2 80/03/26 App
- 8004040341 Forwards response to NRC questions re potential effect of residual solvent which may be trapped beneath stainless steel cladding during layup conditions Corrosion rates are not expected to pose significant problem

 JANECEK.R F. Commonwealth Edison Co. 80/03/27 7pp
- BOO4230178 Forwards request for info re environ qualification of olectrical equipment Data is needed for NRC calculation of containment temp 2 pressure docay time Calculation should be based on current LOCA analysis

 ZIEMANN.D L Operating Reactors Branch 2 BO/03/2B 14pp
- 8004070227 Forwards util 900310 ltr to LLL transmitting drawings re containment purge sys JANECEK,R F Commonwealth Edison Co 80/03/31 2pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. OA program Revisions reflect recent organization title changes
 NAUGHTON, W F Commonwealth Edison Co 80/04/02 1p
- --8004150328 Revised pages constituting Revision 13 to QA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-1-A RI3 80/04/Q4 7pp
- BOO4180217 Forwards addl info re failure of control rods to insert fully on scram in response to NRC BOO10 & 11 ltrs Dresdon i experienced no control rod failures in 1978-79 Failure at other facilities caused by leakage past worn piston smals JANCECK RF Commonwealth Edison Co BO/04/14 10pp
- 8004220332 Bubmits list of SEP topic references in response to NRC 800214 ltr Includes info re potential hazards, severe weather flooding, tornado missiles, reactor vessel integrity & control room habitability

 JANECEK, R F Commonwealth Edison Co 80/04/14 5pp
- BOO4230072 Submits SEP topic refs. in response to NRC B00214 ltr JANECEK.R F Commonwealth Edison Co B0/04/14 3pp
- 8004290427 Forwards response to NUREO-0378 & "Dosign Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Losalie County sito-specific emergency plan PEOPLES.D L Commonwealth Edison Co 80/04/15 40pp
- --B004250428 "Dosign Criteria & Conceptual Design Description for Technical Buggert Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- O Inspection reports, IE Bulletims & correspondence
- 8004070157 Forwards IE Insp Repts 50-010/79-23,50-237/79-27 & 50-247/79-25 on 791007 & 1128 & notice of violation NAVIS.A B Region 3, Chicago. Fuel Facility & Materials Safety Branch 80/02/12 22p
- --8004070162 Notice of violation from insp on 771007 & 1128
 * Region 3. Chicago. Office of the Director 80/01/31 1
- --B004070164 IE Insp Repts 50-010/79-23.50-237/79-27.& 50-249/79-25 on 791007 & 1128 Noncompliance noted radioactive mat1 shipment record not utilized for radwaste shipments made 790101-1128 GRICGER.L R . FISHER.W L Region 3. Chicago. Office of the Director B0/01/31 7pp
- 8004040195 Forwards IE Insp Repts 50-010/80-01,50-237/80-01 & 30-247/80-01 on 800108-07 No noncompliance noted FIDRELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/16 2pp
- --8004040199 IE Insp Repts 50-010/80-01.50-237/80-01 & 50-249/80-01 on 800108-09, No noncompliance noted Major areas inspected emergency diesel generator mods & mod of electrical equipment re IEEE-279 compliance
 HAYES.D W Region 3. Chicago. Reactor Construction & Engineering Support Branch HUGHES.J J Region 3. Chicago. Office of the Director 80/02/08 Spp
- E004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted DAVIG.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch RO/02/22 2pp

- --8004100408 Waste Packages Insp Rept 79-07A on 791212-13 No noncompliance noted Major area inspected compliance w/DOT & NRC regulations including shipping paper requirements, radiation levels & DOT labeling POTTER, J P, PEERY, W W, WODDRUFF, R L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 App
- 8004100426 Forwards IE Insp Repts 50-010/80-03.50-237/80-03 & 50-249/80-03 on 800107-0201 No noncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004100432 IE Insp Repts 50-010/80-03, 50-237/80-03 & 50-249/80-03 on 800107-0201 No noncompliance noted Major areas inspected maint activities, plant appraisions, physical protection, safety-related sys survoillance insp followup & refueling BARKER, J L , TONGUE, T M , SPESSARD, R L Region 3, Chicago, Office of the Director 80/02/22 7pp
- BOD4100118 Forwards IE Info Notice 80-08. "States Co Bliding Link Electrical Terminal Black " No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/07 18
- 8004100000 Advises that IE Bulletin 80-04, "Engineered Safety Feature (CSF) Reset Controls" was sent to listed utils on 800313 CARROLL, D E Region 3, Chicago, Office of the Director 80/03/17
- 8004100119 Ack receipt of 800304 ltr informing NRC of staps taken to correct violations noted in LE Insp Repts 50-010/79-23, 50-237/79-27 & 50-249/79-25 DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/03/20 2pp
- ---8004100128 Responds to NRC 800212 ltr re violations noted in IE Insp Repts 50-010/79-23,50-237/79-27 & 50-249/79-25 Corrective actions informed personnel re cost estimate change order requirements PEDPLES,D L Commonwealth Edison Co 80/03/04 3pp
- BOO4140117 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Btd Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES,D L Commenwealth Edison Co 80/03/20 5pp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/03/21 ip
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance nated DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004040023 Corrected Waste Packaging Insp Rept 79-0/A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination & package external features POTTER, J P. PEERY, W W. WOODRUFF, R L. Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- 8004300544 Forwards IE Insp Repts 50-010/80-04,50-237/80-04 & 50-249/80-04 on 800720-22 & 26 & notice of violation DAYIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/03/21 2pp
- --8004300548 Notice of violation from insp on 800220-22 & 26 # Region 3, Chicago, Office of the Director 80/03/11 is
- --ROC4300555 IE Insp Repts 50-010/80-04, 50-237/80-04 & 50-249/80-04 on 800220-22 & 26 No noncompliance noted, Major areas inspected internal audits, licensee coordination w/offsice support agencies & review of emergency drills EBSIG.T H., OESTMANN, M.J., MATSON, E. Region 3, Chicago, Office of the Director 80/03/11 10pp
- 8004180199 Forwards IE Info Notice 80-12, "Instrument Failure Gauses Opening of PORV & Diock Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director, 80/03/31, to
- 8004080686 Forwards IE Circular 80-05, "Emergancy Diesal Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/01

- 8004150146 Advises that JE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve," was sent to listed utils on 800331 CARROLL. N E Region 3, Chicago, Office of the Director 80/04/01 3pp
- 8004080569 Advises that IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply" was sent to listed utils on 800401 CARROLL.D E Region 3. Chicago, Office of the Director 80/04/02 388
- B004150014 Forwards IE Info Notice 80-13, "GE Type BBM Control Switches Defective CAN Followers" No specific action or response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/02
- 8004180030 Forwards attachments to 1E Circular 80-03, "Protection From Toxic Oas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J O Region 3, Chicago. Office of the Director 80/04/02
- 8004220093 Forwards 1E Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02 ip
- 8004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written responso required KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/03 1p
- 8004180385 Advises that IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys" was sont to listed utils on 800403 CARROLL,D C Region 3, Chicago, Office of the Director 80/04/07
- 8004230224 Forwards IE Bulletin 79-03A. "Longitudinal Held Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/04/07
- 8004230304 Advises that IE Bulletin 77-03A. "Longitudinal Neld Defects in ASME 8A-312 Type 304 Stainless Steel Fipe." was sent to listed utils on 800404 for action CARROLL, D E Region 3. Chicago. Office of the Director 80/04/07
- 8004220067 Forwards IE Bulletin 80-08. "Exam of Containment Liner Panetration Holds " Written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director. 80/04/09
- 8004220161 Advises that IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds," was sent to listed utils on 800408 CARROLL,D C Region 3, Chicago, Office of the Director 80/04/09 350
- B004220199 Advises that IE Info Notice 80-14, "Bafety Suggestions From Employees" was sent to listed utils on 800404 CARROLL, D.E. Region 3, Chicago, Office of the Director 60/04/09
- 8004280628 Forwards revised Pages 3 & 9 & omitted Page 4 to IE Insp Repts 50-010/80-05, 50-237/80-05, 50-247/80-05, 50-254/80-05 & 50-265/80-08 F10RELI;0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/09 1p
- --G004280634 Revised Pages 3 & 5 & omitted Page 4 to 1E Inap Repta 50-010/80-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 & 50-265/80-08 * Region 2, Atlanta, Office of the Director 80/04/09 3pp
- R Periodic operating reports & related correspondence
- 8004140330 Forwards "Raduaste & Environ Monitoring Annual Rept 1979," STEPHENSON D 8 Commonwealth Edison Co. 80/03/19 ip
- ---B004140340 "Radwaste & Environ Monitoring Annual Rept 1979." KOHL, K A . CHANDRASEKARAN Eperline Instrument Corp 80/03/31 91pp
- BOO4150382 Forwards monthly operating repts for Mar 1980 BTEPHENBON B B Commonwealth Edison Co 80/04/10 1p

- --B0041503B7 Monthly operating repts for Mar 1980 C1EBZK1EWICZ.8 Commonwealth Edison Co 80/04/01 23pp
- S Reportable occurrences, LERs & related correspondence
- BOO4080541 Forwards LER 80-001/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/03/25 1p
- --B0040B0549 LER B0-001/03L-0 on B00303, capacity in Unit 1 fire pump found to be in need of updating in order to be equal to Unit 2/2 fire pump Commitment made to NRC to increase capacity New fire pump will be installed # Commonwealth Edison Co B0/03/25 ip
- BQ04220630 Forwards LER BO-002/diT-Q STEPHENSON, B B Commonwealth Edison Co BO/04/17 ip
- --B0042204B1 LER 80-002/01T-0 on 800405, while in shutdown made w/fuel removed, contaminated demineralized water was being heated & added to primary sys Tube leaks in heat exchanger were found leaking water into river Caused by unloader tube failure GATES. J Commonwealth Edison Co B0/04/17 4pp
- U Congressional/Executive Correspondence
- 8004440183 Forwards response to 800204 request for comments on IL Safe Energy Alliance statements NRC complies w/NFPA requirements Proposed decontamination under review for special circumstances which may require EIS DIRCKS, N J Office of the Executive Director for Operations 800/03/28 App
- --8004140197 Requests info on IL Safe Energy Alliance concerns re proposed decontamination of facility Also requests info on studies re reactor environ impact COLLINB.C House of Rep., Foreign Affairs 80/02/04 ip
- 8004140208 Forwards comments on IL Bafe Energy Alliance statements re proposed decontamination of facility per 800220 request NRC complies w/NEPA requirements Proposed action under review for special circumstances which may require EIS DIRCKB.W J Office of the Executive Director for Operations BO/03/28 6pp
- ~-B0D4i40215 Supports IL Safe Energy Alliance request for completion of EIS prior to facility decontamination YATES,S R House of Rep., Appropriations 80/02/20 1p
- 8004i40169 Forwards response to 800205 request for comments on itr from ER McCullough of IL Safe Energy Alliance NRC complies w/NEPA requirements Proposed decontamination under review for special circumstances which may require EIB DIRCKG.W J Office of the Executive Director for Operations 60/03/31 5pp
- --B004140180 Requests comments on encl 790123 itr from ER McCullough of IL Safe Energy Alliance Ltr proposes that EIS be required for facility decontamination BIMONJP House of Rep . Education & Labor B0/02/05 4pp
- BOO4140225 Forwards response to BOO131 request for comments on itr from ER McCullough of IL Safe Energy Alliance NRC complies w/NEPA requirements Proposed descontamination under review to 'starming if EIB is required 'RCRS,W J. Office of the Executive Director for Operations /03/31 Opp
 - JO4140230 Requests comments on encl 800122 ltr from ER McCullough of IL Safe Energy Alliance re facility decontamination STEVENSON, A. Senate 80/01/31 Spp
- 4004:40496 Forwards NRC 800328 response to Congressmen 8 Yates re status of NRC decision on need for EIS prior to plant decontamination NRC treatment of IL Energy Alliance concerns is inadequate List of concerns enc! 8HINEFLUG.M Illinois Safe Energy Alliance. 80/04/07 2pp
- --8004i40459 Responds to B00220 request for comments re IL Safe Energy Alliance statements about proposed chemical decontamination NRC will comply whrequirements of NEPA in determining whether EIS should be prepared DRRCKS.W. J. Office of Nuclear Material Safety & Bafeguards, 80/03/28 4pp

- DOCKET 50-13 BABCOCK & WILCOX CO CRITICAL FACILITY

 P Operating license stage documents & correspondence
- 8004180355 Submits add1 info re 771018 amend request Describes range of allowable nonmoderator to moderator ratio & computer codes used for front-end calculations for analysis of max credible accident

 OLSEN.A F Babcock & Wilcox Co 80/04/11 4pp
- DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

 I Financial information
- 8004070317 Forwards Annual Financial Rept 1979
 CUMNINGHAM, 0 E General Electric Co 80/03/28 ip
- --8004070321 Annual Financial Rept 1979 * General Electric Co 80/02/15 25pp
- J Insurance & indomnity information
- 8004010323 Forwards Endorsement 23 to MAELU Policy MF-95 CORREAM A Marsh & McLennan.Inc . M & M Nuclear Consultants.Inc Div 80/03/25 2pp
- R Periodic operating reports & related correspondence
- 8004080286 Forwards "1979 Annual Status Rept 15 " CUNNINGHAM, G E Ogneral Electric Co 80/02/29 ip
- --8004080289 "1979 Annual Status Rept 15 "
 * General Electric Co 80/02/29 5p
- DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- B004010446 Forwards Items 3 : 5 & 3 : 12(d) of fire protection review Proposed manually operated sprinkler sys is acceptable, contingent upon submittal of final design drawings Proposed i-h rated protection for diesel generator rooms acceptable HALL,R E Brootheven National Laboratory B0/03/24 7pp
- 8004110145 Forwards NRC position on 780822 & 790410 responses re cable fire barrier qualification testing Several deviations to NRC requirements make justification or commitment to add1 testing necessary within 30 days ZIEMANN.D L. Operating Reactors Dranch 2 80/03/24 3pp
- BOO4140172 Forwards revised safeguards contingency plan pages Encl withheld (ref 10CFR2 790) MOODY,D E Yankee Atomic Electric Co 80/04/10 1p
- 8004280534 Forwards conclusions re fire barrier qualification testing Deviations stated in NRC 800324 ltr do not significantly affect test results
 MOODY.D E Yankee Atomic Electric Co 80/04/22 4pp
- G Adjudicatory correspondence
- 8004070288 Requests that onci info be distributed to appropriate boards & parties Includes info re disc cracking in Hestinghouse turbines & Yankee Rowe turbine failure EISENMUT,D O Division of Operating Reactors 80/03/07 2pp
- 8004250266 Requests that encl documents be provided to Board notification svc lists for all cases VARQA:B A. Assistant Director for Light Water Reactors 80/03/31
- 8004280336 Forwards NRC confirmatory order BTELLD,V Office of Inspection & Enforcement, Office of the Director 80/04/04 1p
- ~-B004250337 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800701 Required info specified in Attachment A. BTELLD. V Office of Inspection & Enforcement, Office of the Director B0/04/04 6pp

H General correspondence

- 800421004B Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 10CFR20 & App 1 to 10CFR50 Environ info available in stated LPDRS BALLARD, R L Environmental Projects Branch 1 80/04/01 2pp
- --8004210060 Requests info or current repts re effects of nuclear power plants on New England marine organisms due to radiation. chemical waste disposal thermal pollution & other factors ROOERS.B J Affiliation Unknown 80/03/09 ip

I Financial information

- 8004010395 Forwards Annual Financial Rept 1979 80UCY,A R Yankee Atomic Electric Co 80/03/31 1p
- --8004010398 Annual Financial Rept 1979 * Yankes Atomic Electric Co 80/02/15 12pp

P Operating license stage documents & correspondence

- 8004100511 Advises that responses to 761123 ltrs re LWR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors per typical fuel bundle % batch burnups ZIEMANN, D L Operating Reactors Branch 2 80/02/29 2pp
- 8004230064 Advises that review & evaluation will not be completed until 800701 re loss of non-Class IE instrumentation & control power sys bus during operation KAY.J A Vankee Atomic Electric Co 80/02/29 1p
- 8004080159 Forwards NUREG-0569, "Evaluation of Integrity of SEP Reactor Vessels," completing review of SEP Topic V-6 W/a encl ZIEMANN.D L. Operating Reactors Branch 2 80/03/05 2pp
- 8004020004 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is unnecessary References or updates to info previously submitted are acceptable ZIEMANN.D L Operating Reactors Branch 2 80/03/06 5pp
- BOO4080185 Forwards evaluation of SEP Topic XV-20 comparing facility w/current licensing criteria Responses will be made if asbuilt facility differs from licensing basis ZIEMANN.D L Operating Reactors Branch 2 BO/03/07 6pp
- BO04030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT. D G Division of Operating Reactors B0/03/12 Spp
- --8004030118 "Nuclear Data Link Specs "
 # Division of Operating Reactors 80/02/21 28pp
- B00417030B Forwards request for add1 info re environ qualification of electrical equipment ZIEMANNO L. Operating Reactors Branch 2 80/03/28 29pp
- 8004110434 Forwards Revision 8 to YOGAP-I-A addressing organization changes to 8A program HEIDER:L H Yankee Atomic Electric Co 80/04/04 ip
- --8004i10444 GA program Revision 8 for facility operation VANDENBURGH, D E, HEIDER: L H , MOODY: D E Yankee Atomic Electric Co YOGAP-I-A 80/04/01 20pp.
- 8004250123 Forwards Category A Lessons Learned Task Force review items which require addl licenses action Includes info re heater capacity required & time within which capacity must be available to maintain natural circulation at hot standby ZIEMANN,D L. Operating Reactors Branch 2 80/04/05 4pp
- 8004290079 Requests payment of Class III fee for proposed Tech Spec Change 168 NRC-requested change is not exempt from fees because change enhances safe operation of facility, MILLER.W D License Fee Management Branch 80/04/08 ip
- 8004110417 Responds w/add1 info re 800402 Category A implementation and audit. Westinghouse study determined min heater requirements w/o offsite power met required heater capacity Temp inputs increased to 8 thermocouples

 KAY.J A Yankee Atomic Electric Co 80/04/07 13pp

- 8004280600 Advises of revised Step 5 to action plan re anchorage & support of safety-related electrical equipment Manpower losses delay response re investigation until 800630 All mods will be completed prior to startup KAY, J A Yankee Atomic Electric Co 80/04/23 ip
- O Inspection reports, IE Bulletins & correspondence
- 8004150310 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/31 1p
- 8004090110 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 1p
- 8004110518 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers" No written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/04/02 lp
- 8004240355 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees" No action required ORIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180255 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Oil 8ys " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/04/03 ip
- B004230516 Forwards IE Bulletin 79-03A. "Longitudinal Held Defects in ABME BA-312.Type 304 Stainless Steal Pipe " Action required ORIER, B H Region I. Philadelphia. Office of the Director B0/04/04 ip
- B004180302 Forwards IE Bulletin 80-0B, "Exam of Containment Liner Penetration Welds" Written response required ORIER,B H Region 1, Philadelphia, Office of the Director 80/04/07 1p
- R Pariodic operating reports & related correspondence
- 8004100370 Forwards "Annual Radiological Environ Surveillance Rept for 1979 " KAY, J. A. Yankee Atomic Electric Co. 80/03/31 1p
- ---B004100374 "Annual Radiological Environ Survaillance Rept for 1979 "

 * Yankee Atomic Electric Co 80/03/28 60pp
- 8004150350 Forwards monthly operating rept for Mar 1980 MODDY, D E Yankee Atomic Electric Co 80/04/11 1p
- --8004150352 Monthly operating rept for Mar 1980 BEERB.F C Yankee Atomic Electric Co 80/04/11 5pp
- S Reportable occurrences, LERs & related correspondenc
- 8004080489 Forwards LER 80-009/03L-0 AUTIO, H A Yankee Atomic Electric Co 80/04/04 ip
- --8004080494 LER 80-009/03L-0 on 800307, during maint outage in Mode 5 while performing safety injection time delay verification procedure. TDC2 setpoint found out of Tech Spec limit Caused by setpoint drift. Relay adjusted to within Tech Spec limit FRENCH. L D Yankee Atomic Electric Co 80/04/04 ip
- DOCKET 90-30 PLUM BROOK RESEARCH REACTOR FACILITY
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8004040167 Confirms recommendation re add1 subsurface investigations
 Three large diameter borings down to base & below lowest
 shear at reactor at fence uphill & at fence downhill from
 reactor should provide required info
 PHILBRICK.88 Philibrick, S8 79/12/14 1p

DOCKETED ITEMS

CKET 50-54 UNION CARBIDE RESEARCH REACTOR

Operating license stage documents & correspondence

04150082 Advises that License R-84 will expire on 800530 Renewal requires filing 30 days before expiration date demonstrating that reactor can operate safely for prolonged period REID,R W. Operating Reactors Branch 4 80/03/20 ip

Periodic operating reports & related correspondence

304080548 Forwards "Annual Operating Rept for 1979 " RUZICKA.W G Union Carbide Corp 80/03/31 ip

-8004080551 "Annual Operating Rept 1979," reporting facility mod & major maint * Union Carbide Corp 80/03/31 4pp

004070375 Forwards "Annual Operating Rept for 1979 " RUZICKA, W G Union Carbide Corp 80/03/31 1p

-8004070380 "Annual Operating Rept for 1979 "

* Union Carbide Corp 80/03/31 4pp

Operating license stage documents & correspondence

'905190094 Forwards draft of revised Tech Specs re effluent monitor aperability Requests same limits as granted to Univ of Michigan allow 24-h out of svc for monitors w/o restrictions on speration ORLOSKY, P H New York, State Univ of, Buffalo 78/12/29 3pp

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

Majudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSBICKL V Office of the Executive Director for Operations BO/04/02 34pp,

I Financial information

8004070317 Forward: Annual Financial Rept 1979 CUNNINGHAM. G E General Electric Co 80/03/29 ip

---8004070321 Annual Financial Rept 1979 * General Electric Co 80/02/15 25pp.

P Operating license stage documents & correspondence

8004040142 Bummary of B00131 meeting w/OE in Bethesda. MD to analysis proposed by vendor to support restart of GETR
NELBON.C. Operating Reactors Branch 4. 80/03/21 2pp

~-8004040153 "Probability Amalysis of Surface Rupture Offtet Beneath GETR Reactor Bldg REED,J W Jack R Benjamin & Associates, Inc. 80/03/21 10pp

8004020185 Forwards results from measurements taken to determine angle of dip in trenches at site, if surface offset to be considered in structural analyses, recommends using dip angles ranging between 10 to 30 degrees.

DARMITZEL:R W Opperal Electric Co 80/03/31 5pp

8004300052 Forwards Revision 1 to GA program CUNMINCHAM:Q E General Electric Co . Nuclear Energy Products Div 80/04/07. lp.

--8004300056 GA program # General Electric Co. GAP~1 R1. 80/03/31 33pp

B004170254 Forwards "Seismicity of Livermore Valley in Relation to GE Vallection Plant," & responses to questions & comments raised at ACRS 79:114 OETR Subcommittee meeting. Info noncontroversial & does not alter GE position.

DARMITZEL, R, W Oeneral Electric Co. SO/04/14 2pp.

--8004170257 "Seltmicity of Livermore Valley in Relation to GE Vallecitos Plant " BOLT.B A . HANSEN.R A General Electric Co 80/03/31 35pp

---B004170260 Forwards responses to questions & comments raised at ACRB 791114 GETR Bubcommittee meeting
DDRMITZEL.R W General Electric Co 80/04/14 33pp

8004280311 Forwards partial response to NRC questions re structural issues of test reactor GILLILANDID L General Electric Co 80/04/23 12pp

R Periodic operating reports & related correspondence

8004080348 Forwards "Annual Operating Rept 21 for 1979 " CUNNINGHAM, O E General Electric Co 80/03/05 1p

--80040B0359 "Annual Operating Rept 21 for 1979 "
• General Electric Co 80/03/05 5pp

8 Reportable occurrences, LERs & related correspondence

8004040030 PNO-V-80-019A ground water samples obtained from well located near underground waste tank farm & below ground fuel tank sump Analysis showed no significant activity above detectable limit
HENSLAHSKI.F. FISH.R Region 5. Ban Francisco, Office of the Director 80/03/19 19

8004040413 PND-V-80-015B.correcting PND-V-80-015A Tritium mistakonly reported as 3 O E-5, should read 3 O E-3 WENSLAWSKI,F, FISH,R Region 5, San Francisco, Office of the Director 80/03/19 1p

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

1 Financial information

B004070317 Forwards Annual Financial Rept 1979
CUNNINOHAM.0 E General Electric Co 80/03/28 1p

--8004070921 Annual Financial Rept 1979
* General Electric Co 80/02/15 95pp

P Operating license stage documents & correspondence

8004170044 Forwards proposed changes to Tech Specs, per 000320 & 21 telcons in response to NRC questions re util response to postulated swismic event application to amend Fech Specs CUNNINOHAM, O C Owners] Electric Co 80/04/03 ip

--8004i70046 Application to amend License R-33, changing Tech Epecs re postulated seismic event * General Electric Co 80/04/10 ip

~~8004170049 Proposed changes to Tech Specs 4 1(c),5 4 3,8 2 2,8 2 11 & Table I Tech Spec 8 2 5 should be deleted * General Electric Co 80/04/10 2pp

R Periodic operating reports & related correspondence

8004080308 Forwards "Annual Operating Rent 20," for 1979 CUNNINGHAM.0 E General Electric Co 80/02/29 in

--8004080313 "Annual Operating Rept 20," for 1979 OILLILAND,D L. General Electric Co. 80/02/29 Spp

DECKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR
R Periodic operating reports & related correspondence

8004220558 Forwards "Environ Radiation Surveillance Rept for Oct 1978-Mar 1979" & "Environ Radiation Surveillance Rept for Apr-Sept 1979 " ERAY: T C North Carolina State Univ 80/03/13 3pg

--8004220560 "Environ Radiation Surveillance Rept for Oct 1978-Mar 1979 " BALL-A C , DEBNAH. J North Carolina State Univ BO/03/19 7pp

--8004220565 "Environ Radiation Surveillance Rept for Apr-Sept 1979"
BALLIA C . DEBNAM. J North Carolina State Univ 80/03/13 7pp

- DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR
- O Inspection reports: IE Bulletins & correspondence
- 8004230167 Forwards IE Insp Rept 50-123/79-03 on 791105-06 & 1204-05 & notice of deviation KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/03 200
- --8004230175 Notice of violation from insp on 791105-06 & 1204-05 * Region 3, Chicago, Office of the Director 80/02/19 ip
- --8004230179 Natice of deviation from insp on 791105-06 & 1204-05
 * Region 3, Chicago, Office of the Director 80/02/19 ip
- --8004230189 IE Insp Rept 50-123/79-03 on 791105-06 & 1204-05
 Noncompliance noted failure to maintain required personnel exposure lecords & deviations in surveys, measurements & instruments
 FISHER, W L. Region 3, Chicago, Fuel Facility & Materials Safety
 Branch DUBRY, N E Region 3, Chicago, Office of the Director 80/02/19 13pp
- 8004270080 Ack receipt of 800324 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-123/79-03 KEPPLER, J Q Region 3, Chicago, Office of the Director 60/04/08
- --8004270085 Responds to NRC 800303 ltr re violations nated in IE Insp.
 Rept 50-123/79-03 Corrective actions instituted procedural change delegating routine health physics activities to reactor personnel.w/auditing by health physicist PLANJE,T J. Missouri. Univ. of, Rolla 80/03/24 9pp
- DUCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

 B Utility Preliminary Safety Analysis Report. amends
- 803310406 Forwards PSAR
 PARKINSON, T F Virginia Tech 80/03/19 ip
- --8003310411 PSAR for VA Polytechnic Inst & State Univ research training reactor CURINCR, A P . DENTON, M M . ESKIN, L D Virginia Tech 79/11/01 1070n
- --8003310415 Chapter 1 of VA Polytechnic Inst & State Univ research & training reactor PSAR, "Introduction"
 CURINGR.A P. DENTON.K M. ESKIN.L D. Virginia Tech. 79/11/01
- --8003310417 Chapter 2 of VA Polytechnic Inst & State Univ research & training reactor PSAR, "Sys Mods "
 CURTNER, A P., DENTON, M. M., ESKIN, L.D. Virginia Tech. 79/11/01
- --8003310421 Chapter 3 of VA Polytechnic Inst & State Univ research & training reactor PBAR. "Thermal-Hydraulics Analysis "
 CURTNER, A P., DENTON, M M., ESKIN, L.D. Virginia Tech. 79/11/01
- --B003310427 Chapter 4 of VA Polytechnic Inst & State Univ research & training reactor PSAR. "Reactivity Transients "
 GURTNER, A P. DENTON, M M. ESKIN, L. D. Virginia Tech. 79/11/01
 Poo.
- --8003310432 Chapter 5 of VA Polytechnic Inst & State Univ research & training reactor PBAR, "Radiation Bafety"
 CURTNER, A P., DENTON, M. M., EBKIN, L.D. Virginia Tech. 79/11/01
- --8003310439 Chapter 6 of VA Polytechnic Inst & State Univ research & training reactor PBAR, "DBA"

 CURTNER, A P., DENTON, M M., ESKIN, L. D. Virginia Tech. 79/11/01
- F Security, medical, emergency & fire protection plans
- 8004040468 Forwards Sept 1979 draft emergency plan PARKINSON, T F Virginia Tech 80/03/19 Ip

- P Operating license stage documents & correspondence
- B004150431 Application for renewal of facility License R-62 for term of 20 yrs CURTNER, A P. PARKINSON, T F. KREBS, A H. Virginia Tech. 79/10/02 200
- DUCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR
 P Operating license slage documents & correspondence
- 8003190734 Requests maps indicating low population iones for facilities EDSDN,K California, State of 80/01/07 ip
- R Periodic operating reports & related correspondence
- 8004240416 Forwards "Annual Operating Rept 1979 " KLEIN,D Texas, Univ of 80/03/31 1p
- --8004240420 "Annual Operating Rept 1979 " KLEIN,D E Texas, Univ of 80/03/31 56pp
- DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3
- 8004240340 Urges ABLB to move on hearings re facility Certificate of Svc encl DU0GING.L Affiliation Unknown 80/01/05 App
- 8004150003 Forwards rept by Woodward-Clyde Consultants re status of geologic & seismic investigations involving facility, in accordance w/ABLB 790619 order Work going forward on laddometric dating & trace olement analysis
- 8004080626 Notice of 800603 prehearing conference at Veterans Memorial Bidg, Euroka, CA Conference will address PG&E request that further praceedings be stayed & held in abeyance until 801001 re amend to OL Technical assistance requested LAZO,R M Atomic Sefety and Licensing Board Penel 80/03/24 3pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OBSICK, L V Office of the Executive Director for Operations B0/04/02 34pp
- 8004290280 Requests hearing re plant proximity to earthquake fault Certificate of Svc encl JAMES Affiliation Unknown 80/04/08 3pp
- I Financial information
- BOO4100233 Forwards Annual Financial Rept 1979 CRANE.P A Pacific Gas & Electric Co 80/04/03 ip
- ---B004100244 Annual Financial Rept 1979 * Pacific Gas & Electric Co 80/02/22 43pp
- P Operating license stage documents & correspondence
- 8004070397 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20.000 MM-day per metric ton Responses undicate that no immediate licensing action is required for operating reactors IPPOLITO,T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D G Division of Operating Reactors. 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp.

Q Inspection reports: 1E Bulletins & correspondence

- | 8004150205 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve "No specific action or response necessary | ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/03/31 ip
 - 8004i00101 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENGELKEN:R H Region 5, San Francisco, Office of the Director 80/04/01 19
 - BOO4110111 Forwards 1E Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No specific action or response regulated ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/02 to
 - BOO4220038 Forwards IE Info Notice BO-14, "Safety Suggestions From Employees" No action required ENGELKEN,R H Region 5, San Francisco, Office of the Director BO/04/02 ip
 - 8004180148 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required EMGELKEN:R H Region S. San Francisco, Office of the Director 80/04/03 ip
 - 8004230374 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ABME SA-312.Type 304 Stainless Steel Pipe" Action required ENGELKEN,R H Region 5, San Francisco. Office of the Director BO/04/04 ip
 - 8004220172 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/07 ip
 - R Periodic operating reports & related correspondence
 - 8004170233 Forwards monthly operating rept for Mar 1980 WEEKB, E.D. Pacific Gas & Electric Co. 80/04/09 ip
 - --B004170236 Monthly operating rept for Mar 1980 9ETTY,B C Pacific Oas & Electric Co 80/04/09 4pp
 - S Reportable occurrences, LERs & related correspondence
 - BOO40804B1 Forwards LER 8D-002/03L-0 GRANE.P A Pacific Oas & Electric Co BO/04/01 ip
 - ---B0040B04B7 LER B0--002/O3L-0 on B00310, while in cold shutdown for refueling & seismic mods, fossil unit trip test was not performed within allowable interval Causad by present status being unresolved Test will be performed prior to startup BIERBAUM.0 A Pacific Gas & Electric Co B0/04/01 1p
 - DOCKET 50-197 TURKEY RESEARCH REACTOR
 - P Operating license stage documents & correspondence
 - 8004100302 Advises that responses to 761123 ltrs re LHR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors per typical fuel bundle & batch burnups ZIEMANN.D L. Operating Reactors Branch 2 80/02/29 Spp
 - :KET 50-142 UCLA TRAINING REACTOR
 - Operating license stage documents & correspondence
 - 8004300278 Forwards discussion in response to Committee to Bridge the Gap 791003 petition alleging deficiencies in review procedures used in support of Amend 10 to DL Further NRC input to cover all alleged deficiencies necessary REID, R W Operating Reactors Branch 4 80/04/11. 4pp.

- U Congressional/Executive Correspondence
- BO040B0157 Responds to 791102 ltr re constituent concerns about emissions of radioactive gas from Univ of CA.Los Angeles research reactor Ar-41 emissions result in individual doses below max allowed by NRC guidelines DIRCKS,W J Office of the Executive Director for Operations BO/03/13 2pp
- --8004080164 Requests response to enc.) 6D Strum 791007 itr re emissions of radioactive gas from Univ of CA.Los Angelos research reactor
 BEILENSON, A C House of Rep. 79/11/02 Spp
- DOCKET 50-150 ONIO STATE UNIV RESEARCH REACTOR
- I Financial information
- 8004080046 Responds to FOIA request for documents re extraordinary nuclear occurrence concept, including proposed rulemaking, regulations & rules adopted by AEC Forwards documents listed in App A
 FELTON.J M Division of Rules and Records GD/03/18 Spp
- ~-8004080090 Ack receipt of 690625 ltr re Amend 2 to Indemnity Agreement E-B Amend 2 has been executed Forwards N Carlile 660120 legal opinion CARSON.0 B Dhio State Univ 69/07/10 3pp
- @ Inspection reports, IE Bullatina & correspondence
- 8004100372 Forwards IE Insp Rept 50-150/80-01 on 800204-07 No noncompilance noted DAVIS.A B Region 3, Chicago. Fuel Facility & Materials Safety Branch 80/02/29 2pp
- --8004100377 IE Insp Rept 50-150/80-01 on 800206-07 No noncompliance noted Major areas inspected radwaste mgt & radiation protection programs
 FISHER: W L. Region 3: Chicago: Fuel Facility & Materials Safoty Branch PAUL: R A : BCHUNACHER: M C. Region 3: Chicago: Office of the Director 80/02/28 7pp
- DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR
- @ Inspection reports. IE Bulletins & correspondence
- 8004110237 Forwards IE Insp Repts 90-151/80-01 & 50-356/80-01 on 800204-06 No noncompliance noted DAVIB.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/03/03 2pp
- --80041102/+ it Insp Repts 50-151/80-01 & 50-356/80-01 on 800204-06 No noncompliance noted Major areas inspected emergancy planning including support procedures; personnel interviews, review of training & drills & insp of equipment ESSIG.T H NRC Regional Offices GREER.R J Region 3: Chicago: Office of the Director 80/02/22 4pp
- DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8004100286 Forwards input to 790404 fire protection safety evaluation re need for protection of cabling & valve operators in recirculation pump room
 ZIEMANN,D L Operating Reactors Branch 2 80/03/11 2pp
- --80041002B9 Fire protection safety evaluation of acceptable supplemental item for protection of cabling in recirculation pump area # Operating Reactors Branch 2 80/03/11 ip
- 8004240540 Forwards sys description & operating instructions for NRC health physics telephone network Bys designed for use during nuclear incident or AD Network may also be used for daily administrative or facsimilis traffic KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/20 2pg
- 8004280015 Forwards now emergency plan implementing new requirements in wake of TMI accident Answers to emergency plan interrogatories will be sent shortly W/o encl QALLO.J Isham. Lincoln & Beale 80/03/24 ip

- B004280555 Forwards calculations re establishment of primary emergency planning zone radius of five miles for facility, in response to NRC B00414 request FROST, 8 R Consumers Power Co B0/04/24 1p
- --8004280557 Calculations re establishment of primary emergency planning tone radius of five miles for facility # Consumers Power Co 80/04/24 9pp

G Adjudicatory correspondence

- 8004020278 Stresses importance of compliance w/NRC regulations re svc of documents in proceeding J O'Neill 800206 motion for extension was ruled upon prior to receipt of motion by J Gallo Requests avoidance of similar inequities GALLO,J Isham, Lincoln & Beale 80/02/27 2pp
- 8004140276 Motion to extend deadline for filing in spent fuel pool expansion hearing be extended to 800310 O'NEILL, J. Affiliation Unknown 80/03/04 Ip
- 8004080191 Forwards current facility emergency plan Plan is complete except for deletion of App F.bomb threat procedures. & telephone numbers contained in App A Deletions will not adversely affect discovery rights W/ø ene!

 OALLO.J Isham, Lincoln & Beale 80/03/07 ip
- 8004030363 Requests extension until 800314 to file contentions re need for power at facility Notification of due date for filing contentions was not received until 800300 LEITHAUSER.J Charlevoix.MI 80/03/10 ip
- 8004140041 Intervenor motion to file late brief re power issue in spent fuel paul expansion hearing NRC counsel J Moore, util counsel J Oalla & Christe-Maria counsel E Heiss do not object to delay Certificate of 8vc encl
- --- 8004140044 Intervenor response to ASLB question re NEPA requirement to consider need for power in proceeding Strong precedent exists for ASLB to examine environ impact & cost-benefit & need for power issues in proposed mode Certificate of Svc O'NEILL, J. Affiliation Unknown, 80/03/10 9pp
- --B004140048 Intervenor motion for relief from burden of supplying 20 copies of all filings to NRC as required by iOCFR2 708(d) Relief is essential so that intervenor can devote energies to substantive issues of proceeding O'NEILL, J Affiliation Unknown 80/03/10 ip
- --8004140059 Intervenor motion for clarification of legal language All parties in proceeding asked to supply simple extpanations of Latin & legal terms appearing in relevant documents O'MEILL. J Affiliation Unknown 80/03/10 4pp
- 8004100570 Forwards util 800222 ltr to NRC explaining util position recertain plant mods proposed by NRC as part of SEP & post-TMI evaluations Ltr is irrelevant to proposed expansion of spent fuel pool OALLO, J Isham, Lincoln & Boale 80/03/12. 2pp
- 8004180396 Motion to be heard on need for power issue Petitioner brief was received by ASLB within max time limits Petitioner has raised issues not dealt w/in other briefs Denial of motion is denial of petitioner right to protect property LEITHAUSER.J A Affiliation Unknown 80/03/12 3pp
- ---8004180402 Brief on need for power issue Constitutional requirements of due process require ASLB to consider need for power at facility Proposed licensing amend permitting operation of unsatisfactory facility violates due process LEITHAUSER, J A. Affiliation Unknown. 80/03/10 5pp.
- B004100293 First set of interrogatories Includes questions re expert witnesses intervenor expects to call & areas of expertise GALLO.J. STEPTOE.P.P. Consumers Power Co. GALLO.J. Isham, Lincoln & Beale B0/03/13 App
- ---9004100294 Request for production of documents identified in intervenor Christa-Maria response to licensee first set of interrogatories Documents requested by 800414 OALLO, J. SEPTOE, P. P. Consumers Power Co. OALLO, J. Isham, Lincoln & Beale. 80/03/13. ip
- --8004100298 Notice of change of address for Washington, DC law ofc of Isham, Lincoln & Beale Certificate of Svc encl GALLO, J Consumers Power Co GALLO, J Isham, Lincoln & Beale 80/03/13 3ps

- BOO4090180 Forwards first set of interrogatories GALLO, J Isham, Lincoln & Beale 80/03/14 1
- ~-B0040B01B6 Licensee first set of interrogatories Includes request for identification of all documents including LERs, which serve as basis for contentions filed Cartificate of Bvc encl QALLO, J Consumers Power Co QALLO, J Isham, Lincoln & Beale B0/03/14 6pp
- 8004100451 Forwards licensed response to Interrogatories 9-32 through 9-37 % 9-39 through 9-41 Documents relied upon in preparing licensee responses have been identified OALLO.J Isham, Lincoln & Beale 80/03/19 2pp
- ---8004100455 Answers to intervenor Interrogatories 9-32 through 9-37 & 9-39 through 9-41 Includes info re failed fuel assemblies & sight placs used for observation of surge tank CL Larsen affidavit & Certificate of Svc encl GALLO, J Consumers Power Co GALLO, J Isham, Lincoln & Beale BD/03/19 17pp
- --8004100462 Forwards request for Tech Spec change to License DPR-6 Provides operability 5 surveillance requirements for modified fuel dry supping sys presently being installed at facility SEWELL.R B Consumers Power Co 75/12/18 11pp
- --8004100465 "Spent Fuel Pool Thermal Analysis "
 * NUS Corp 79/06/25 19pp
- --8004100469 Forwards evaluation of potential consequences of refueling accident inside containment in response to NRC 770429 request Containment ventilation supply & exhaust valves are of "fail-safe" design & shot automatically w/power loss BIXEL, D A Consumers Power Go 77/06/28, 20PP
- ---8004100480 Forwards evaluation of potential consequences of refueling accident inside containment in response to NRC 770117 request During single bundle drop, area monitor response times will range from one second to approx four minutes BIXEL, D A Consumers Power Go 77/03/21 8pp
- 8004210420 Errata to license 800303 brief on need for power issue, NRC published proposed regulations re consideration of alternatives in 800303 FR GALLO, J Isham, Lincoln & Beale 80/03/22 ip
- B004210401 Forwards util B00314 ltm to NRC providing further info re util response to certain NRC requirements resulting from post-TMI evaluations Info is not relevant to proposed spent fuel pool expansion OALLO, J Isham
- 8004080591 Hemorandum & order re spent fuel expansion proceeding Directs parties to address questions raised in safety assessment encl w/HR Denton 800305 itr, re valve operation & loss of feedwater event, which will be part of discovery.

 ORDESHAN, H Atomic Safety and Licensing Board Panel 80/03/27 3an
- 8004090001 Response stating no objection to J D'Neill 800310 motion for relief from twenty-copy requirement for documents filling respent fuel pool mod proceeding Certificate of Svz encl MOORE, J E Hearing Branch 2 80/03/28, 3pp
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSBICKL V Office of the Executive Director for Operations, B0/04/02 34pp
- 8004170302 Forwards HR Denton 800305 1tr w/safety assessment & 10CFR2 re Commission regulations, in response to 800331 request, re spent fuel pool mod MODRE, J E Hearing Branch 2 80/04/07 1p
- 8004230075 Order granting relief to intervenor J D'Neill from 20-copy requirement Single copies shall be served on parties & two copies on Commission, re spent fuel pool expansion proceeding ORUSSMAN. H Atomic Safety and Licensing Board Panel 80/04/15. ip
- 8004250422 Minutes of 800407 conference call participated in by all parties in spent fuel pool proceeding re addl questions contained in ASLB 800327 order Discovery on ASLB questions proper at present time MOORE. J E Hearing Branch 2 80/04/23 4pp.

DOCKETED ITEMS

General correspondence

- 004140026 Forwards Christa-Haria 791101 telegram & ltr requesting safety investigation prior to plant operation SEAL,H M President of US & Executive Offices 79/11/07 4pp
- 004140031 Opposes restart of facility due to foreign object in reactor vessel inhibiting mobility of control rods Related documentation & draft petition emcl CHRISTA-MARIA Christa-María 79/11/01 Bpp
- 4070129 Responds to 800106 petition requesting that eight issues e resolved prior to startup of facility Forwards safety saessment concluding that there is sufficient safety saurence to allow operation pending final ruling ENTON.H R Office of Nuclear Reactor Regulation 80/03/05 3pp
- 004070132 Bafety assessment re safety issues raised by J Bier & BJ Johns 791104 & 800106 ltrs Buffictent safety assurance exists to allow operation pending final ruling > Office of Nuclear Reactor Regulation 80/03/05 7pp
- 004070137 Requests action under 10CFR2 206 to require util to resolve listed safety issues prior to startup School sys should have workable evacuation plan & all diffuser pieces should be accounted for BIER, J., JOHNS. B. J. Affiliation Unknown BO/01/06 2pp
- 4230383 Forwards util 8003iB news release indicating changes in roject,engineering & const organization Hill submit evisions to GA program by 800430 to incorporate rganiiational changes OFFMAN,D P Consumers Power Co 80/04/18 79p
- Operating license stage documents & correspondence
- 4100312 Advises that responses to 761123 ltrs re LWR assessment of nhancement of fission gas release at higher burnups have sen reviewed No immediate licensing action required for perating reactors.per typical fuel bundle & batch burnups. IEMANN.D L Operating Reactors Branch 2 80/02/29 3pp
- 4180025 "Bafety Evaluation Rept.Inservice Testing Program " ENGINEER J H . ROCKHOLD, H C EG & G. Inc FIN A-6258 8004150025 80/02/27 37pp
- 4020450 Requests necessary action to refund licensee amend facs mend fees waived for certain types of fire protection mends ILLER.W D License Fee Hanagement Branch 80/03/05 ip
- 4070220 Advises that Ofc of Controller has authorized refund of hrme Class II fees submitted with 800131 & 0201 pplications License amend fees for certain Tech Spec hanges re fire protection waived ILLER.H O License Fee Management Branch 80/03/05 ip.
- 4090346 Forwards NUREO-0569, "Evaluation of Integrity of SEP eactor Vessels," completing review of SEP Topic V-6,
 - L. Operating Reactors Branch 2. 80/03/05 200
 - - " anch 2 80/03/06 6pp

- 8004100159 Notification of 800324 neeting w/util in Bethesda, MD re SEP Topic VI-9, control toon habitability O'CONNDR, P W Operating Reactors Branch 2 80/03/18 2pp
- BO040B0201 Requests forwarding of Class III fee for util 600107 application proposing Tech Specs changes re containment sphore leakage testing DIGGS.R M License Fee Management Branch 80/03/20 Ip
- 8004100076 Requests that uncontrolled set of PAIDs be placed on controlled distribution list for any future revisions Revisions should be forwarded to attention of Region 3 incident response ctr

 KEPPLER.J O Region 3. Chicago, Office of the Director 80/03/20
- 8004210125 Forwards Amend 32 to License DPR-6.safety evaluation & notice of issuance & availability ZIEMANN.D L Operating Reactors Branch 2 80/03/27 2pp
- -- 8004210127 Amend 32 to License DPR-6. increasing min size shift fire brigade from three to five ZIEMANN.D L Operating Reactors Branch 2 80/03/27 5pp
- --8004210127 Bafety evaluation supporting Amend 32 to License DPR-6 * Office of Nuclear Reactor Regulation 80/03/27 2pp
- --8004210132 Notice of Issuance & availability of Amend 32 to License ZIEMANN.D L Operating Reactors Branch 2 80/03/27 2pp
- 8004210190 Forwards request for info re containment environ conditions & sys required for accident mitigation for review of environ qualification of Class IE electrical equipment NRC will estimate time for containment temp to return to near normal ZIEMANN, D L. Operating Reactors Branch 2 80/03/28 15pp
- 8004040327 Forwards 40-day response required by NRC 800101 ltr re anchorage & support of safety-related electrical equipment Issue will be resolved by end of next refueling outage scheduled to start on 801024 ROFFMAN.D P Consumers Power Co 60/03/31 8pp
- 8004040307 Discusses 800320 meeting w/NRC re proposed overall risk assessment Compensatory measures being taken include more training for fifth operating shift 2 mods considered for emergency condenser initiation logic Guestions mod deferral DEHITTIR B Consumers Power Co 80/04/02 3pp
- --B004040311 "Technical Approach to Probabilistic Rist Assessment "
 ** Consumers Power Co 80/04/02 10pp
- 8004110308 Forwards info re RELAP input for LOCA analysis at units KUEMIN, J. L. Consumers Power Co. 80/04/02 61pp
- 8004140309 Responds to NRC 800314 request for additional clarification of action item taken as result of TMI short-term Lessons
 Learned Shift supervisor can leave control room for brief periods of time if in best interest of facility safety
 HUFFMAN.D P Consumers Power Co 80/04/10 ip
- 8004240372 Responds to NRC 800107 ltr re GA requirements for diesel generator fuel oil GA program will include diesel fuel oil by 800531 Discusses diesel fuel oil testing requirements outlined in Tech Specs 4 7 11 1 (1<) HOFFMAN.D P Consumers Power Co 80/04/21 1p
- O Inspection reports, IE Bulletins & correspondence
- BOO40805BB Forwards IE Insp Rept 50-155/B0-02 on 800206-08 No moncompilance noted HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004080594 IE Insp Rept 50-155/80-02 on 800204-08 No noncompliance noted Major areas inspected plant operations, site organization & administration.

 BAKER, R R, WRIGHT, O C Region 3, Chicago, Office of the Director 80/02/21 3pp
- 6004100132 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER.J O Region 3. Chicago. Office of the Director 60/03/07

- 8004150149 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago. Office of the Director 80/03/31
- 8004080704 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER, J. G. Region G. Chicago, Office of the Director 80/04/01
- 8004150037 Forwards IE Info Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/04/02
- 8004180040 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently amitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220123 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220365 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/03
- 8004110034 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07
- 8004230196 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07 to
- 8004220149 Forwards IC Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/09
- 8004220575 Forwards "Final Rusponse to IE Builetin 79-14," Revision 1 HOFFMAN, D P Consumers Power Co 80/04/17 ip
- --80042205Bi "Final Response to IE Bulletin 79-14," Revision i * Consumers Power Co 80/04/02 7pp
- 8004270324 Forwards response to IE Bulletin 80-02, "inadequate QA for Nuclear Bupplied Equipment " Plant feedwater spargers & thermal sleeves were not mfg by Marvin Engineering Co HUSTON.R W Consumers Power Co 80/04/25 2pp
- R Periodic operating reports & related correspondence
- 8004020285 Farwards "Environ Monitoring Rept 1979 " HUSTON,R W Cansumers Power Co 80/03/28 ip
- --8004020289 "Environ Monitoring Rept 1979 "
 * Consumers Power Co 80/03/28 7pp
- S Reportable occurrences: LERs & related correspondence
- BO040B0470 Forwards LER 80-005/03L-0 HOFFMAN, D F Consumers Power Co BO/04/02 ip
- --8004080475 LER 80-005/03L-0 on 800301, following several intermittent automatic test circuit alarms, sensor channel D of reactor depressurizing sys removed from svc Caused by estpoint drift on transmitter LT-3183 Transmitter vented & returned to svc # Consumers Power Co 80/04/02 ip
- U Cangressional/Executive Carrespondence
- 8004080284 Forwards draft ltrs to Congress re NRC response to J Bier & B Johns petitions being treated under 10CFR2 206 EMITH.H Operating Reactors Branch 2 80/03/06 App

- DOCKET 50-160 GEORGIA INST OF TECH REBEARCH REACTOR

 G Inspection reports, If Bullstins & correspondence
- 8004210204 Forwards IE Mgt Meeting Rept 90-160/80-02 on 800326 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- --B004210206 IE Mgt Meating Rept 50-140/B0-02 on 800326 Areas discussed findings of 800219-22 inspireview of provious enforcement history 5 current enforcement status LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch JULIAN, C Region 2, Atlanta, Office of the Director 80/04/04 2pp
- S Reportable occurrences, LERs & related correspondence
- 8004280486 Notifies that 30-day LER for 800305 event will be forwarded on 800411 due to continuing problem w/coolent flow anomoly KIRKLAND,R S Ocorgia Institute of Technology 80/04/04 ip
- 8004280477 RO 80-1 on 791009, during ECCS tank TD-2 monthly flow rate verification, flow rate observed to be 8 gpm Caused by loose lock nuts which fix handle-to-ball operating shaft Surveillance program will be strengthened KIRKLAND, RS Georgia Institute of Technology 80/04/11 2pp
- 8004280512 RO 80-02 on 800305, low flow ecram of flow recorder FRA-Di resulted in reactor trip & subsequent shutdown Caused by broken Teflon pasket piecos restricting flow Gasket repaired & mys refilled KIRKLAND, R B Georgia Institute of Technology 80/04/14 2pp
- DOCKET 50-169 GENERAL ATOMIC COMPANY
- Q Inspection reports, IE Bulletins & correspondence
- 8004040460 Forwards IE Insp Repts 50-163/80-01 & 50-189/80-01 on 800213-15 No noncompliance noted Encls withheld (ref 10CFR2 790) NORDERHAUGLE Region 5, San Francisco, Safeguards Branch 80/03/1R 1s
- DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR
 H General correspondence
- 7908020467 Informs NRC of administrative personnel changes DELCHER:R Maryland: Univ of 79/07/20 ip
- 8004020050 Advises of 10 appointees to membership on reactor safety committee for 1980-1981. CADMAN.T W Maryland, Univ of 80/02/27 1p
- DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER
- P Operating license stage documents & correspondence
- B004170206 Notifies that facility License R-84 will expire on 801108 Renewal of license requires application demonstrating that reactor can continue to be updated safely & that components can withstand prolonged use REID.R.W Operating Reactors Branch 4 80/04/03 ip
- DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8004010327 Forwards Items 3 1 5(2) & 3 1.7 of fire protection review Licensee submittel re fire barrier penetration seals only partly satisfactory Licensee proposal re fire doors acceptable HALL: R E Brookhaven National Laboratory 80/03/26. 4pp
- I Financial information
- 8004150267 Forwards Annual Financial Rept 1979 BRADLEY, E. J. Philadelphia Electric Co. 80/04/08 ip

- P Operating license stage documents & correspondence
- 8004220549 Responds to NRC 800228 request for info re mgt & technical resources
 COUNEY, M J Philadelphia Electric Co 80/04/11 9pp
- G. Inspection reports. IE Bulletins & correspondence
- BD04100261 Responds to IE Bulletin BO-03 No cells replaced in engineered safety feature filtration sys, however charcoal adsorber cells, will have to be removed to replaced rivits indicated in Item 1

 DALTROFF, B L Philadelphia Electric Co 80/03/19 3pp
- DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8004100380 Forwards IE Insp Rept 50-182/80-01 on 800123-24 No noncompliance noted DAVIB.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch B0/02/27 2pp.
- --8004100383 IE insp Rept 50-182/80-01 on 800123-24 No noncompliance noted Major areas inspected radwaste mgt & radiation protection program FISHER,W L. Region 3. Chicago, Fuel Facility & Materials Safety Branch PECK,C C. HUETER,L J. Region 3. Chicago, Office of the Director, 80/02/15 8pp
- DOCKET SO-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR
- I Financial information
- BOO4070317 Forwards Annual Financial Rept 1979 CUNNINGHAM, G.E. General Electric Co. 80/03/28 ip
- --8004070321 Annual Finantial Rept 1979 * General Electric Co 80/02/15 25pp
- R Periodic operating reports & related correspondence
- BOO4080217 Forwards "Annual Operating Rept 12,1979 " CUNNINGHAM.O E. General Electric Co 80/02/29 1p
- --8004080220 "Annual Operating Rept 12,1979 "
 OILLILAND, D.L. General Electric Co. 80/02/29, 3pp
- DUCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
- G Inspection reports. IE Bulletins & correspondence
- 8004040191 Notification of contract execution. Hod 2 to "Licensing Assistance/Tailings Mot Program Technical Evaluation Erxon Highland U Hill." Contractor Ofc of Sponsored Reseach. CO State Univ EDOEMORTH. P J Technical Assistance Contracts Branch FIN 8-6446-9 80/02/29 10
- 8004090194 Requests that IE Insp Rept 50-184/80-01 be withheld (ref 100FR2 790) Info contained in rept reveals amount, type & location of inventory of SMM CARTER, B Commerce, Dept of, National Sureau of Standards B0/02/15 ip
- 8004100003 Ack receipt of 800215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-184/77-05. SMITH, 0 H. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/03/05 ip
- -8004100007 Responds to NRC 800122 ltr re violations noted in IE Insp Rept 50-184/79-05 Corrective actions attention drawn to existing requirements & periodic surveys of outside areas implemented CARTER.R S Commerce, Dept of National Bureau of Standards BO/02/15 Lp
- --9004100009 Forwards IE lnsp Rept 50-184/79-05 on 770828-31,0901.04.05 & 1023-26 & notice of violation SMITH.O.H Region i. Philadelphia, Fuel Facility & Materials Sefety Branch 80/01/22 2pp

- --8004100011 Notice of violation from insp on 790828-31,0901.04.05 & 1023-26 Region I, Philadelphia, Fuel Facility & Materials Safety Branch, BO/01/22 Ip
- --8004100014 IE Insp Rept 50-184/79-05 on 790828-31.0901,04.05 & 1023-26 Nancompliance noted required cadiation surveys not performed PLUMLEE,K E Region 1, Philadelphia, Office of the Director CROCKER,H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/01/22 97pp
- 8004090191 Ack receipt of 800215 request to withhold IE Insp Rept 50-184/80-01 Encl insp rept withhold (ref 10CFR2 790) MARTIN.W 9 Region 1, Philadelphia, Safeguards Branch 80/03/10
- --8004090200 Forwards IE Insp Rept 50-184/80-01 on 800115-16 No noncompliance noted MARTIN,W O Region 1, Philadelphia, Safeguards Branch 80/03/05 1p
- --8004090211 IE Insp Rept 50-184/80-01 on 800115-14 No noncompliance noted Major areas inspected facility organization & operation, masurement & control, shipping & receiving, storage & internal control Details withheld (ref 10CFR2 790) SHAUD, ET , SUMMERSR J , MARTIN, W G Region I, Philadelphia, Bafeguards Branch 80/02/01 1p
- DOCKET 50-189 UNIV TRAINING REACTOR
- O Inspection reports, IE Bulletins & correspondence
- 8004040460 Forwards IE Insp Repts 50-163/80-01 & 50-189/80-01 on 800213-15 No noncompliance moted Encis withheld (ref 10CFR2 790) NORDERHAUO, L.R. Region 5. San Francisco, Safeguards Branch 80/03/12 in
- DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC
- I Financial information
- 8004080046 Responds to FOIA request for documents re extraordinary nuclear occurrence concept including proposed rulemaking, regulations & rules adopted by AEC Forwards documents listed in App A
 FELTON, J M Division of Rules and Records. 80/03/18 5pp
- --80040B0103 Forwards executed Amends 2 & 3 to indemnity agreement RI Atty General will comply w/NRC request for legal opinion concerning RI inability to effect waiver of immunity W/o encl DIMEQLIO: A F Atomic Energy Commission 49/07/11 1p
- DOCKET 50-201 WEST VALLEY REPROCESSING PLANT
- G Adjudicatory correspondence
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & greparedness distributed as Board notification ODSBICKL V Office of the Executive Director for Operations
- P Operating license stage documents & correspondence
- 8004140142 Summary of 800213 meeting w/NFB, DOE, EPA & NY State Energy R&D Authority in Silver Spring, MD re technical data for futute decontamination & decommissioning of facility Index of facility design data for liquid waste treatment encl HAUGHNEY, C J Advanced Fuel & Spent Fuel Licensing Branch 80/03/11 18pp
- 8004180076 "Standy Power Usage," Revision 1 PIERCE, A C , SHOKOMBKI, R T., BURN, P Nuclear Fuel Services, Inc (subs of Getty Oil Co) TOP 31-6 80/03/11 6pp
- 8004240560 Notification of 800416 meeting w/vendor in Silver Spring,MD to discuss progress of efforts to process available technical info needed to provide basis for future decontamination & decommissioning of facility, HAUGHNEY.C J Advanced Fuel & Spent Fuel Licensing Branch \$0/04/04 2pp

Q Inspection reports. IE Builetins & correspondence

- 8004090205 Ack receipt of 800226 ltr further explaining steps taken to correct violations noted in IE Insp Rept 50-201/79-03 Ltr will be withheld (ref 100FR2 790)
 MARTIN.W Q Region 1, Philadelphia, Safeguards Branch 80/03/13 to
- --8004090210 Ack receipt of 791005 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-201/79-25 Addl info needed re reply to Item I MARTIN, W O Region 1, Philadelphia, Bafeguards Branch 79/12/13 20p
- --8004090215 Forwards IE Insp Rept 50-201/79-03 & 790612-14 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 MARTIN,W O Region I, Philadelphia, Safeguards Branch 79/09/21
 200
- --8004090221 IE Insp Rept 50-201/79-03 on 790612-14 Noncompliance noted TV camera could not meet performance requirements & failure to record details of alarm responses Details withheld (ref 100FR2 790)

 DEVLIN.J W. Region 1, Philadelphia, Bafaguards Branch
 LADUN.R H, MCKEOWN.L M. Region 1, Philadelphia, Office of the Director 79/09/11 1p
- 8004100214 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-201/80-01 SMITH,0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/18 lp
- --8004100219 Responds to NRC 800207 ltr re violatins noted in IE Insp Rept 50-201/80-01 Corrective actions posted appropriate notification signs & replaced certification for compliance DUCKHORTH. J P Nuclear Fuel Services, Inc (subs of Getty Gil Go) 80/03/03 3pp
- --9004100223 Forwards IE Insp Rept 50-201/80-01 on 800108-11 & notice of violation
 SHITH 9 H Region 1. Philadelphia, Fuel Facility & Materials
 Safety Branch 80/02/07 2pp
- --8004100225 Notice of violation from insp on 800108-11
 * Region 1, Philadelphia, Office of the Director 80/02/07 2pp
- --8004100234 IE Insp Rept 50-201/80-01 on 800108-11 Noncompliance noted failure to post hardstand signs & to verify conformance of purchased filters to specs
 GROCKER.H W Region 1, Philadelphia, Fuel Facility & Materials
 Bafety Branch ROTH.J Region 1, Philadelphia, Office of the Director 80/02/07 14pp
- R Periodic operating reports & related correspondence
- 8004190062 Forwards "Fifty-fifth Quarterly Environ Monitoring Rept, for Oct-Dec 1979"

 DUCKNORTH, J P Nuclear Fuel Services, Inc (subs of Getty Dil Co)
- --B004150071 "Fifty-Fifth Quarterly Environ Monitoring Rept, for Oct-Dec 1979 "

 * Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) 80/01/22.
- 8004230053 Forwards "Environ Monitoring Rept 27,Jul-Dec 1979 DUCKWORTH, J. P Nuclear Fuel Bervices, Inc (subs of Datty Oil Co). 80/02/27 1p
- --8004230060 "Environ Monitaring Rept 27, Jul-Dec 1979."

 * Nuclear Fuel Services, Inc (subs. of Getty Oil Co.) 80/02/29, 2600
- 8004030315 Notification of 800416 meeting w/NFB in Silver Spring,MD to discuss progress of NFB efforts to provide basis for future decontamination & decommissioning of facility.

 HAUDHNEY,C J Advanced Fuel & Spent Fuel Licensing Branch 80/03/11, 3pp
- DOCKET 50-206 BAN ONOFRE NUCLEAR STATION: UNIT 1
- F Security, medical, emergency & fire protection plans
- B004:10:14B Forwards add1 comment for util to address during review of safeguards contingency plan submitted on 790323 Requests response by 800421 Enc1 withheld (ref 100FRZ 790) ZIEMANN,D L Operating Reactors Branch 2 80/03/24 2pp

- 8004080515 Forwards review summary of fire protection covering Items 3 1 6.foam suppression sys.3 1 7.gas suppression sys & 3 2 3.turbine bldg structure Items 3 1 1.3 1 2.3 1 5 are partially completed & summary will be provided accordingly HALL.R E Brookhaven National Laboratory 80/03/31 16pp
- 8004080395 Notifies that combined response to NRC 791211 & 800324 ltrs re safeguards contingency plan will be sent by 800421 HAYNES, J G Southern California Edison Co 80/04/01 1p
- 8004230320 Forwards revision to BNL 800331 ltr re Items 3 1.1(5),3 1 2 (b),3 1 5(d),3,1 6,3 1 7(a),3 1 7(b),3 1 15(b) & 3 2 3 for fire protection review MALL,R E. Brookhaven National Laboratory 80/04/16 16pp
- 8004300363 Notifies NRC that util requires addl time to revise safeguards contingency plan as described in NRC 800324 ltr Revised safeguards plan will be forwarded by 800512 BAGKIN, K P Bouthern California Edison Co 80/04/21 1p
- Q Adjudicatory correspondence
- 8004280019 Forwards NRC confirmatory order STELLO.V Office of Inspection & Enforcement. Office of the Director 80/04/04 ip
- --8004280021 Order confirming util commitment to perform review requested , by IE Bulletin 79-27 by 800515 Required info specified in Attachment A STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/04 App
- D Advisory Committee on Reactor Bafeguards reports & correspondence
- 8004040469 Discusses LER 79-017 event on 791107 involving fire & lose of 480-volt Bus 1 caused by rodents in switchgear housing Event constituted common mode failure not previously postulated Add1 info required for adequate assessment LIPINGKI, W.C. Argonne National Laboratory BO/01/15 3pp
- P Operating license stage documents & correspondence
- 8004170297 Forwards request for addl info re environ qualification of electrical equipment ZIEMANN.D L. Operating Reactors Branch 2 80/03/28 14pp.
- 8004090242 Advises that responses to 761123 ltrs re LWR assessment of enhancement of fission gas release at higher burnups has been reviewed No immediate licensing action required for operating reactors, per revised typical fuel bundle codes ZIEMANN.D.L. Operating Reactors Branch 2 80/02/29 3pp.
- 800403018B Notification of 800320 meeting w/util in Betheada.MD to discuss selsmic reassessment program O'CONNOR.P W Operating Reactors Branch 2 80/03/05 2pp
- 8004080699 Forwards NUREG-0569, "Evaluation of Integrity of BEP Reactor Vessels," completing review of BEP Topic V-6 M/o encl. ZIEMANN,D.L. Operating Reactors Branch 2 80/03/05 2pp.
- 8004020013 Forwards review schedule for environ qualification of Class IE electrical equipment per 80022/ meeting.Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable.

 ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 5pp.
- B004030102 Forwards "Nuclear Data Link Specs," study of digital compunication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D. O Division of Operating Reactors, 80/03/12 Spp.
- --8004030118 "Nuclear Data Link Specs"

 ** Division of Operating Reactors 80/02/21. 28pp.
- 8004090142 Forwards request for add1 info per 800310-11 site visit to review implementation of Category A Lessons Learned Tesk Force requirements Response required by 800318 ZIEMANN.D.L. Operating Reactors Branch 2 80/03/13. 5pp
- 8004020327 Responds to NRC 800117 request for review of draft evaluation of SEP Topic XV-20, "Radiological Consequences of Fuel Damaging Accidents, (Inside & Outside Containment), " Review confirms facts as correct HAYNES, J Q Southern California Edison Co, 80/03/28 19

- 8004030140 Forwards application for Amend 87 to License DPR-13 consisting of Proposed Change 87 to Tech Specs 3 5, "Instrumentation & Control," & 4 1, "Operational Safety Itens "Westinghouse evaluation withheld fref 10CFR2 790) DIETCH,R Southern California Edison Co 80/03/31 2pp
- --8004030141 Amend 89 to License DPR-13, modifying existing Tech Specs 3 5 & 4 1 to require limiting conditions for operation based on control rod misalignment & to specify surveillance requirements Certificate of 80× enc1

 DIETCH, R Southern California Edison Co 80/03/11 7pp
- --8004030145 Proposed Change 89 to Tech Space 3 5. "Instrumentation & Control." & 4 1. "Operational Safety Items" * Southern California Edison Co 60/03/31 11pp
- 8004300589 Provides add) info on automatic initiation of auxiliary feadwater sys flow concerning implementation of Item 2 1 7a requirements of NUREO-0578 Requests detail of safety-grade sys design Certain commitments required within 15 days EIBENHUT.D O Division of Operating Reactors 80/04/03 3pp
- 8004080491 Forwards application for Amend 90 to License DPR-13 & Proposed Changes 91 & 92 describing offsite power sources & incorporating changes necessary for implementation of fire protection mods Fee encl
 DIETCH.R Southern California Edison Co 80/04/04 2pp
- --8004080498 Application for Amend 90 to License DPR-13, describing affaite power sources & incorporating changes necessary for implementation of fire protection mods
 DIETCH.R Southern California Edison Co 80/04/04 7pp
- --8004080504 Description of Proposed Changes 91 & 92 to Tech Spece Comparison of seismic design criteria for high voltage switchyard & summary of util remarks at 791025 meeting re offsite power sources encl # Southern California Edison Co. 80/04/04 26pp
- 8004090326 Forwards response to 800214 request for refs to docketed info re sereal SEP topics HAYNES.J O Southern California Edison Co 80/04/04 3pp
- 8004240509 Discusses licensed actions re 800310 failure of saltwater cooling sys Auxiliary salt water cooling sump will not be considered in determining operability of sys Requests review of all emergency procedures & revision prior to operation ENOELKEN.R H Region 5, San Francisco, Office of the Director 80/04/04 3pp
- 8004150449 Advises that info re electrical distribution sys adequacy, requested by NRC 790508 ltr.will be submitted by 80050), instead of 800301 date indicated in 791224 response HAYNEB, J 0 Southern California Edison Co 80/04/11 lp
- 8004220503 Forwards response to upon items identified at 791114 meeting re-soismic backfit project & site specific carthquake program Results of program for evaluating earthquake anticipated in Jul 1980
 BASKIM.K P Southern California Edison Co 80/04/11 36pp
- B004220634 Confirms B00410 telcons w/regulatory gersonnel re implementation of several Category A TMI Lessons Learned Task Force requirements described in B00325 ltr BABKIN,K P Bouthern California Edison Co 80/04/11 2pp
- 8004220570 Notifies that difficulties w/proposed memorandum of agreement ro transmission project have been resolved to satisfaction of CA Ofc of Historic Preservation NRC should forward agreement to advisory council for action MELLON, K California, State of 80/04/15 1p
- 8004230494 Provides preliminary info re impact of auxiliary feedwater sys automation on main steam line broak safety analysis, in response to NRC 791221 request Revised scaping studies will be completed by 800516

 BASKIN.K P Bouthern California Edison Co 80/04/18 2pp
- BOO4220446 Notifies that evaluation of potential magnitude & effects of postulated water hammers will include development of forcing functions for classic textbook-type water hammers Evaluation will be completed by BOO930

 HAYNES, J Q Southern California Edison Co 80/04/22 ip
- BOO4240394 Forwards "Analysis of Capsule F.Reactor Vessel Radiation Burysillance Program." & Tech Bpecs 3 1 3 for cumbined heatup, cooldown & pressure limitations Proposed change to Tech Byecs will be submitted by BO1231 BABKIN.K P Southern California Edison Co. BO/04/24 2pp

- --8004240395 Yech Spec 3 i 3 for combined heatup, cooldown & pressure limitations, Figures 3 i 3a-3 i 3d & Table 3 i 3 i for reactor vessel toughness data (unirradiated) * Southern California Edison Co 80/04/24 Spp
- ---8004240397 "Analysis of Capsule F.Reactor Vessel Radiation Surveillance Program " YANICHKO, B E , ANDERSON, S L , KAISER, H T Westinghouse Electric Corp , Nuclear Energy Systems HCAP-9320 79/05/31 67pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004110532 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-204/80-01 NRRDERHAUD.L R Region 5. San Francisco. Safeguards Branch 80/03/54 in
- 8004150214 Forwards IE info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENSELKEN.R H Region 5, San Francisco, Office of the Director 80/03/31 ip
- B004100107 Forwards IE Circular B0-05, "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required ENGELKEH R H Region 5, San Francisco, Office of the Director 80/04/01 lp
- 8004110114 Forwards IE Info Natice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required ENGELMENTR H Region 5, Ban Francisco, Office of the Director 80/04/02 1p
- 8004220D48 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/02 1p
- 8004170268 Forwards IE Insp Rept 50-206/80-07 on 800318-21 No nancompliance noted Encl withhold (ref 10CFR2 790) NORDERHAUD, L R Region 5. San Francisco. Safeguards Branch 80/04/03 200
- 8004180135 Forwards IE Carcular 80~07, "Problems WHECI Turbine Oil 8ys " No written response required ENGELKEN,R H Region S, San Francisco. Office of the Director 80/04/03 1p
- 8004230364 Forwards IE Bullatin 79-03A. "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required ENOELKEN.R H Region 9. San Francisco. Office of the Director 80/04/04 1p
- 8004220195 Forwards IE Bulletin 80-08, "Exam of Containment Linor Panetration Welds " Writton response required ENGELKENIR H Region 5, San Francisco, Office of the Director BO/04/07 ip
- 8004300465 Forwards IE Insp Rept 50-206/80-08 No noncompliance nuted Rept withheld (ref 10CFR2 790) NGRDERHAUGLER Region 5. San Francisco, Safeguards Branch 80/04/11 200
- R Periodic operating reports & related correspondence
- 8004070338 Foruards info re occupational exposure & environ surveillance programs for 1979
 OTTOSON,H L. Southern California Edison Co. 80/03/31 3pp
- --80040/0342 "Annual Operating Rept for 1979 Environ Monitoring & Radiation Exposure Ropts " * Southern California Edison Co 80/03/31 41pp
- ~-8004070335 "1979 Annual Operating Rept, Vol 1, Oceanographic Data Rept "
- ---8004070348 "1979 Annual Operating Rept.Vol 2.Biological Data Rept Intertidal Infauna.Bubtidal Infaunal.Kolp.IchthyppIankton " • Harine Diological Consultants, Inc . 80/03/31 300pp
- --B004070352 "1979 Annual Operating Rept.Vol 3.Biological Data Rept Plankton.Hard Benthos Rocky Intertidal " * Lockhood Center for Marine Rosearch 80/03/31 500pp

- --8004070357 "1979 Annual Operating Rept.Vol 4.Biological Data Rept Nekton " # Brown & Caldwell 80/03/31 250pp
- 8004150345 Forwards monthly operating rept for Mar 1780 CURRAN, J M Southern California Edison Co 80/04/09 1p
- ---8004150347 Monthly operating rept for Mar 1980 WATTSON,P Southern California Edison Ca 80/04/07 5pp
- S Reportable occurrences, LERs & related correspondence
- BOO4080539 RO on BOO310 north saltwater cooling pump auto started upon indication of low discharge pressure from south pump North pump power operated relief valve could not be opened Cause under review Auxiliary pump used CURRAN, J M Southern California Edison Co 80/03/11 2pp
- 8004080477 Forwards LER 80-009/04L-0 OTTUSUN, H L Southern California Edison Co 80/04/02 2pp
- --8004080483 LER 80-009/04L-0 on 800331.during first quarter of 1980. benthic data could only be taken from six of eleven ETS benthic stations Caused by severe storm conditions interrupting data collection OTTOSON.H L Southern California Edison Co 80/04/02 ip
- 8004210270 Forwards LER 80-011/43Z-0 OTTOSON, H L Southern California Edison Co 80/04/08 2pp
- --B004210273 LER 80-011/432-0 on B00310, while purging pressurizer relief tank to remove oxygen tank, disc ruptured Caused by ovorfilling w/primory makeup water Ruptured disc replaced * Southorn California Edison Co 80/04/08 1p
- 8004180450 Forwards LER 80-008/03L-0 DTT050N,H L Southern California Edison Co 80/04/09 2pp
- --B0041B0454 LER 80-008/03L-0 on 80031B during maint of saltwater cooling pump.pips support 9-416-4 & concrete anchors found corroded Caused by vibration & corrosion induced by saltwater environ. Support refeesigned & built CURRAN, J M Southern California Edison Co 80/04/04 1p
- B004210254 Forwards LER 80-010/03L-0 OTTOSON, H L Southern California Edison Co 80/04/09 2pp
- --8004210257 LER 80-010/03L-0 on 800318 during full power operation high temp indication observed on south charging pump thrust bearing Caused by loose coupling hub on pump shaft Damaged inboard bearing shoes & coupling hub or perfaced CURRAN, J M Southern Galifornia Edison Go 80/04/09 1p
- BOO4230335 RO hydrostatic test of steam generator tubes revealed nine leaking tubus Cause unstailed Tubes will be plugged at later time during current outage CURRAN, J M Southern California Edison Co BO/04/14 lp
- 8004250418 Forwards LER 00-012/03L-0 OTTOSON, H L Southern California Edison Co 80/04/21 2pp
- --8004250420 LFR 80-012/03L-0 on 800324, during normal operations, Number 2 diesel generator fuel oil transfer pumps 0-75A & 0-79B tripped on current overload Caused by failure of sump pumps in transfer pump yoult due to high water level in vault CURRAN. J M Southern California Edison Co 80/04/20 ip
- DOCKET 50-213 HADDAM NECK PLANT
- F Security, modical, emorgency & fire protection plans
- 8004020408 Forwards "Feasibility Ropt on Evacuation of Area Around Facility " CHUNBILLY O Northeast Utilities 80/03/31 2pp
- --B004020418 "Feasibility Rept on Evacuation of Area Around Facility " One oversize drawing encl RODOERB.L M, PELL.B M Blorch Engineers MOLLOY.E J Northeast Utilities Service Co 60/03/31 58pp
- --8004020410 "Feasibility Rept on Evacuation of Area Around Facility " One oversize drawing encl RODGERS, L M Affiliation Unknown 80/03/31 58pp

- --8004020424 "Feasibility Rept on Evacuation of Area Around Facility "
 One oversize drawing enci
 RODGERS, L M , PELL, B M Storch Engineers 80/03/31 77pp
- 8004230299 Proposes to provide automatic total fluoding Halon 1301 fire suppression sys for entire switchgear room (Fire Zone S-8) Forwards Drawing D-127989, sheets 1.2. & 3 CDUNSIL N G Connecticut Yankse Atomic Power Co
- --8004230309 "Automatic Halon Fire Extinguishing Sys for Switchgear Room " Sheet 1 of 3 * Fire Equipment, Inc. 127989 80/03/10 1p
- ~~8004230313 "Automatic Halon Fire Extinguishing Bys for Switchgear Room " Sheet 2 of 3 * Fire Equipment, Inc 127987 80/03/05 Ip
- --8004230314 "Automatic Halon Fire Extinguishing Bys for Switchgear Room" Bheet 3 of 3 * Fire Equipment, Inc 127989 80/03/10 lp
- H General correspondence
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 100FR20 & App 1 to 100FR90 Environ info available in stated LPDR8
 BALLAND, R L. Environmenta; Projects Branch 1 80/04/01 2pp
- I Financial information
- 8004080292 Forwards SEC Form 10-K listing util financial statements for 1978 & 1979
 BISHOP, R W Connection Yankee Atomic Power Co 80/04/02 36pp
- J Insurance & indemnity information
- 8004150379 Forwards Endorsement 58 to MAELU Policy MF-39 IFFLAND, R R Northeast Utilities 80/04/10 2pp
- P Operating license stage documents & correspondence
- B004040066 Requests that application for route approval for round trip shipment of irradiated fuel assemblies between facility & Columbus, Oli, be approved by B00317 so that assemblies can be shipped to BMI before B00502 shutdown COUNSIL. N Q Connecticut Yankse Atomic Power Co B0/02/22 App
- 8004030365 Forwards NRC safety evaluation supporting precautions taken to minimize steem generator water hammer ZIEMANN,D L. Operating Reactors Branch 2 80/02/26 2pp
- --9004030366 Bafety evaluation supporting precautions taken to minimize steam generator water hammer.EG&O 791228 ltr to DOE encl # Division of Operating Reactors 80/02/26 10pp
- 8004100309 Advises that rusponses to 761123 ltrs re LWR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediato licensing action required for operating reactors, por typical fuel bundle & batch runps ZIEMANN. D L Operating Reactors Branch 2 GO/02/27 3pp
- HO0409033B Forwards NUREG-0969, "Evaluation of Integrity of USP Reactor Vessels," completing roview of SEP Topic V-6 W/o encl ZIEMANN,D L Operating Reactors Branch 2 H0/03/05 2pp
- BOD4020007 Forwards review schedule for environ qualification of Class IE electrical equipment per 800021 meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN, D. L. Operating Reactors Branch 2 80/03/06 Spp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Nethesda Operations Ctr EISENMUT, D O Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004030273 Responds to NRC 800214 ltrs re request for list of refs for five SEP topict Forwards topics by number, title & listing of refs for ECCS actuation typs automatic ECCS realignment & testing of reactor trip sys CQUNSIL,W Q , FCE,W F Northeast Utilities 80/03/21 3pp

- 8004100161 Notification of 800326 meeting w/util in Bethesda.MD removement of heavy loads near fuel & changes to move spent fuel cask.

 CARUSB, R Operating Reactors Branch 2 80/03/24 2pp
- BO04210411 Submits add1 info re armed escorts for BO0222 requested route approval through embargoed areas of CT Guards will be off-duty CT State Police officers Util will provide special training re security & radiological considerations CGUNSIL,N 0 FEE,N F Connecticut Yankee Atomic Power Co BO/03/24 200
- 8004020349 Submits info re safety evaluation for postulated fuel handling accident in new & spent fuel storage blog, in response to NRC 791220 request CDUNSIL.W 9 Mains Yankee Atomic Power Co 80/03/25 4pp
- 8004110528 Provides add1 info re implementation requirements set forth in Item 2 i 7a of NUREO-0378 Requests response by 800601 indicating commitment to install safety-grade sys by 810101 EISENHUT, D O Division of Operating Reactors 80/03/27. 2pp
- BOD4070265 Submits info re direct indication of PORV & safety valve positions Recent discussions w/vendor revealed difficulty w/800401 completion date Revised date of completion is Bi0401 CDUNSILLE OF Wortheast Utilities BO/03/28 2nm
- 8004210227 Forwards request for info re containment environ conditions & sys required for accident mitigation for review of environ qualifications of Class IE electrical equipment NRC will estimate time for containment temp to return near normal ZIEMANN.D L Operating Reactors Branch 2 80/03/28 14pp
- 8004070274 Discusses current intentions to submit design for providing sampling capacity for primary coolant & containment air by 800427 Utils are currently engaged in finallying design details Blight delay is required to optimize design COUNSIL.W G. Connecticut Yankee Atomic Power Co 80/04/01 2pp
- 8004150297 Confirms E00403 telcon re Hestinghouse low pressure turbine disc integraty Util & Hestinghouse concur that safety concern does not exist Turbine overspeed will be limited to 20% std speed until arguments are documented COUNBILH G., FEE.H F Connecticut Yankee Atomic Power Co 80/04/03 1p
- 8004180345 Forwards info re seismic re-evaluation requested by NRC during 790516 meeting Previous seismological determination of DBE unaffected CDUNSTL:N 0 Gonnacticut Yankee Atomic Power Co 80/04/07 2pp
- --8004180348 "NRC Info Request on Geology & Seismology "
 * Western Geophysical 80/03/31 18pp
- 8004170012 Discusses problems w/implementation of Lessons Learned Task Force recommendation to automatic initiation of auxiliary feedwaters sys Requests NRC concurrence w/plan for implementing requirement during 1980 refueling outage COUNBIL.W O Connecticut Yankse Atomic Power Co COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/ii App.
- 8004180224 Forwards info clarifying & supporting conclusion that Category A Lessons Learned Task Force requirements have been implemented Oversize drawing encl COUNBILIN O Connecticut Yankee Atomic Power Co. 80/04/11 81pp
- 8004270442 Forwards add1 info in support of 780321 proposed changes to Tech Space Revisions delete prohibition of spant fuel cask movement over spent fuel pool & substitute add1 restrictions Requests expeditious action COUNSIL.W Q. Connecticut Yankee Atomic Power Co 80/04/19 16pp
- 004280465 Responds to final questions in review of changes to Tech Specs re spent fuel cask movement Five separate shipments planned re testing & evaluation effort Return shipments not yet scheduled Requests seven movements to allow for changes GOUNBIL. H 9. Connecticut Yankee Atomic Power Co BO/04/23 2pp
- @ Inspection reports. IE Bulletins & correspondence
- 9004090i3i Forwards IE Insp Repts 50-213/79-20, 50-245/79-26 & 50-336/79-28 on 791127-30 & 1203-07, No noncompliance noted. BRUNNER:E J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/08. 2pp.

- --B004090138 IE Insp Repts S0-213/79-20.50-245/79-26 & 50-336/79-28 on 791127-30 % 1203-07 No nuncompliance noted Major areas inspected QA program implementation re QA/QC administration, design changes & mods & document control program BAUNACK, W H Region 1, Philadelphia, Reactor Operations Nyclear Support Branch NAPUDA. G Region 1, Philadelphia, Office of the Director 80/02/07 15pp
- BO04080448 Forwards IE Insp Rept 50-213/80-02 on B00122-25 No noncompliance noted BRUNNER, E.J. Region i. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/19 Zpp
- --8004080450 IE Insp Rept 90-213/80-02 on 800122-25 No noncompliance noted Major areas inspected details re establishment of onsite of for full-time resident inspector KEIKIG.R R Region 1. Philadelphia. Reactor Operations Nuclear Support Branch MCOSCAR, J J , SMITH, T H Region 1. Philadelphia. Office of the Director 80/02/15 7pp
- B004110012 Submits response to IE Bulletin 79-27 re loss of non-Class IE instrumentation & control power supply bus during operation Facility has two semivital buses w/two feeds via auto transfer & backed by two emergency generators COUNSIL.W C. FEE.W F. Connecticut Yankee Atomic Power Co 80/03/03 2pp
- 8004030261 Submits response to IE Bulletin BO-04 re analysis of PWR main steam line break w/continued feedwater addition Efforts are in progress to finallie details of control grade automatic initiation of auxiliary feedwater scheme COUNSIL. W O Northeast Utilities 80/03/05 ip
- 8004070425 Ack receipt of 791227 & 800104 ltrs informing NRC of corrective & preventive actions & check in payment of 791206 notice of proposed imposition of civil penalties Acting supervisor did not meet min qualifications STELLGLY Office of Inspection & Enforcement, Office of the Director 80/03/20 2pp
- 8004250132 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std Type 11. Two-Inch Tray, Adsorber Colls" No replacements necessary due to damage to or corresion of engineered safety feature filters COUNSIL. N 0 . FEE. W F Connecticut Yankee Atomic Power Co 80/03/24 5pp
- --8004250143 Special Maint Procedure SPL 10 7-5, "Containment Air Recirculation Fans - Installation of Addl Charcoal Air Filters" * Connecticut Yankee Atomic Power Co 79/02/07 10pp
- 8004030211 Advises that reactor coolant pump & vessel cladding exams scheduled for 1980 refueling outage are impractical Proposes alternative inservice insplexam method for Category 8-8 welds on regenerative heat exchanger Requests NRC review COUNSIL.W G Connecticut Yankee Atomic Power Co 80/03/25 3pp
- B004250051 Ack receipt of 800314 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/80-01 Util 1tr to be withheld (ref 10GFR2 790)
 MARTIN.W 0 Region 1, Philadelphia, Safeguards Branch 80/03/28
- --8004250054 Forwards IE Insp Rept 50-213/80-01 on 800108-11 MARYIN,W G Region 1. Philadelphia. Bafeguards Branch 80/02/21 2pp
- --8004280089 IE Insp Rept 50-2:3/80-01 on 800:08-11 Noncompliance noted door found unlocked & unattended in vital area Failure to meintain surveillance of protected area barriers & exterior vital area door Details withheld tref 100FR2 790) LADUN.R H . MADDEN.W Region 1. Philadelphia, Office of the Director DEVLIN.J W Region 1. Philadelphia, Bafeguards Branch 80/02/11 ip
- 8004150262 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region i, Philadelphia. Office of the Director 80/03/31 lp
- 8004090047 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER:B H Region 1, Philadelphia, Office of the Director 80/04/01 lp
- 8004110128 Forwards IE Info Notice 80-13, "GE Type SBM Control Buitches Defective CAM Followers" No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/02 1p

- 8004240298 Forwards IE Info Notice 80-14, "Safety Suggestions From 104240293 Forwards 1E Into Rotte 80-14, "Barety Suggestion Employees " No action required GRIER, B H Region 1, Philadolphia, Office of the Director 80/04/02 1p
- 8004180226 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Sys "Na writton response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/03 | 1p
- 8004230401 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 8004180131 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- 8004020372 Forwards "Personnel Exposure & Monitoring Rept for 1979 " ORAVES,R H Connecticut Yankee Atomic Power Co 80/03/14 ip
- --B004020374 "Personnel Exposure & Monitoring Rept for 1979 "

 * Connecticut Yankee Atomic Power Co B0/03/14 2pp
- 8004040331 Forwards "Annual Environ Operating Rept. 1979, " Part A nonradiological
 COUNSIL, W 9 Connecticut Yankes Atomic Power Co 80/03/30 1p
- --8004040338 "Annual Environ Operating Rept. 1979 " Part A nonradiological * Connecticut Yankee Atomic Power Co 80/03/31 48pp
- 8004150487 Forwards "Radiological Environ Monitoring Program Annual Environ Operating Rept.Part 8,1979," prepared by Northeast Utils Svc Co COUNSIL.W O Connecticut Yankee Atomic Power Co 80/03/31 1p
- ~~8004150493 "Radiological Environ Monitoring Program Annual Environ Operating Rept.Part B. 1979 " * Northeast Utilities Service Co 60/03/31 100pp
- 8004240437 Forwards "Annual Rept of Changes, Tests & Experiments 1979 "
 GRAVES, R H Connecticut Yankee Atomic Power Co 80/04/01 ip
- --8004240437 "Annual Rept of Changes, Tests & Experiments 1979 "
 GRAVES, R H Connecticut Yankee Atomic Power Co 80/04/01 44pp
- 8004290264 "Annual Operating Rept of Facility Changes, Tests & Experiments, 1979 "
 GRÁVES, R H Connecticut Yankee Atomic Power Co 80/04/01 47pp
- 8004210251 Forwards monthly operating rept for Mar 1780 GRAVES.R H Connecticut Vankes Atomic Power Co 80/0 B0/04/10 1p
- --8004210253 Monthly operating rept for Mar 1980 * Connecticut Yankee Atomic Power Co 80/04/10 Spp
- 8 Reportable occurrences, LERs & related correspondence
- 8004090027 PNO-I-80-041 on 800313 radiological surveys of site grounds uncovered three small patches of contaminated soil outside controlled area Approx three tablespoons soil removed Burvey continuing to determine if other areas contaminated BCRABIAN J. KNAPP. P., GMITH. G. Region I. Philadelphia, Office of the Director 60/03/14 1p
- 8004010362 Forwards LER 80-006/03L-0.

 ORAVES,R H Connecticut Yanke Atomic Power Co. 80/03/20
- --8004010369 LER 80-006/03L-0 on 800306, during routine monthly fan damper test, broken linkage coupling was found on CAR2 fan bypass damper, causing fan to be inoperable. Linkage coupling was replaced w/steel coupling of greater strength ORAVES, R H Connecticut Yanker Atomic Power Co 80/03/20 ip

- DOCKET 50-219 OYBTER CREEK NUCLEAR POWER PLANT
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOBSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004240532 Forwards NRC confirmatory order STELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 1p
- --B004240537 Order confirming util commitment to perform review requested by IE Bullstin 79-27 by 800425, Required info is specified in Attachment A STELLO, U Office of Inspection & Enforcement, Office of the Director 80/04/04 opp
- H General correspondence
- 8004030123 Responds to 790816. Itr re plans to reopen TMI-1, nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ No diseases resulted from TMI DENTON, HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030129 Opposes restart of TMI-1, const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety
 FDSTER,K Affiliation Unknown 79/08/16 2pp
- I Financial information
- 8004100352 Forwards JCP&L & General Public Utils Corp Annual Financial Repts 1979 ROSS,D A Jersey Central Power & Light Co 80/04/01 ip
- --8004100355 Annual Financial Rept 1979
 * Jersey Central Power & Light Co 80/03/24 24pp
- --8004100356 Annual Financial Rept 1979
 * General Public Utilities GPU Service Corp 80/04/01 44pp
- P Operating license stage documents & correspondence
- 8004i003i7 Advises that responses to 76i123 ltrs re LMR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors; per typical fuel bundle & batch burnups.

 ZIEMANN: D L Operating Reactors Branch 2 80/02/29 3pp
- B004100320 Notification of 800308 meeting w/util in Bethesda.MD recore spray sparger cracks & repairs NOWICKLS J Operating Reactors Branch 2 80/03/03 200
- 8004uzuvuv rorwards review schedule for environ qualification of Class IE electrical equipment per 80022i meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 Spp
- 8004040086 Notifies that NRC inadvertently omitted approved change to .Tech Spec 3 4.8 l.rs automatic depressurization sys.during issuance of Amend 45 to Provisional CL DPR-16 Forwards corrected Page 3 4-19 ZIEMANN.D L Operating Reactors Branch 2 80/03/07 Spp
- 8004030102 Forwards "Nuclear Data Link Bpecs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr LIBENHUT, D G Division of Operating Reactors. B0/03/12 5pp
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors, 80/02/21 28pp
- 8004230234 Forwards NRC 800128 & 0211 ltrs to GE re proposed control rod drive sys mods & optimizing pump flow to reactor vessel. Mods should not be performed until complete guidance is issued in NUREG-0619 or w/o NRC approval ZIEMANN.D L. Operating Reactors Branch 2 80/03/24 2pp

- 8004090329 Forwards "Fish Kill Associated W/800105 Outage at Facility "ROSB.D A Jersey Central Power & Light Co 80/03/26 Ip
- --8004090330 "Fish Kill Associated W/800105 Outage at Facility "
 ROCHE.M B Jersey Central Power & Light Co 80/03/31 50pp
- 8004170253 Notification of 800401 meeting w/util in Bethesda.MD to discuss core spray sparger cracks & repairs MCRWIGKI.B J Operating Reactors Branch 2 80/03/28 2pp
- 8004170285 Forwards request for add1 info re environ qualification of electrical equipment ZIEMAN,D L Operating Reactors Branch 2 80/03/28 14pp
- 8004020319 Forwards Tech Spec Change Request 83.modifying App A. Section 4 3 to provide for augmented inservice insp of core sprag sys spargers Class III Fee encl FINFROCK, I R Jersey Central Power & Light Co 80/03/31 lp
- --8004020320 Tech Spec Change Request 83, modifying App A. Section 4 3 to provide for augmented inservice insp of core apray sys spargers
 - # Jersey Central Power & Light Co 80/03/31 66pp
- BOO4160276 Forwards component list for SEP Topic III-12 re safety sysessential to mittgate postulated accidents as requested by NRC at 800310-13 meeting TIPTON, T E Jersey Central Power & Light Co 80/04/11 12pp
- 8004220508 Forwards Revision 4 to Amend 71 to application for GL Responds to several items in NRC 790814 request for add1 info re operational GA plan Remaining items will be addressed in Revision 4 to GA plan FINFROCK-1 R Jersey Central Power & Light Co 80/04/17 ip
- --B004220511 Revision 4 to Amend 71 to application for DL Revision 4 incorporates organizational changes FINFROCK, I, R Jersey Central Power & Light Co 80/04/17 7pp
- --B004220514 Operational GA plan.Revision 3 FINFROCK, I R Jersey Central Power & Light Co 79/11/09 190pp
- 8004230341 Forwards GE "Reload Fuel Application " Fee encl ROBS.D A Jursey Central Power & Light Co 80/04/21 tp
- --8004230343 "Reload Fuel Application "
 OALER.R R , ENGEL.R E General Electric Co NEDG-24195
 79/08/31 200pp
- 8004280513 Requests extension until 800531 for completion of math status rept & physical inventories inventories taken immediately would not be representative of post-outage conditions
 ROSB.D.A Jersey Central Power & Light Co 80/04/25 1p
- G Inspection reports, 1E Bullatins & correspondence
- 8004070417 Forwards JE lnsp Rept 50-219/80-01 on 800104-06.08-11 & 14 No noncompliance noted BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/14. 2pp
- --8004090422 IE Insp Rept 50-219/80-01 on 800104-06.08-11 & 14 No noncompliance noted Major areas inspected refueling preparation-refueling activities & independent insp effort KEIMIO,R R Region I, Philadelphia, Reactor Operations Nuclear Support Branch. BRIOOS,L E Region 1. Philadelphia. Office of the Director. 80/02/13 App
- 3004080421 Advises that response to IE Bulletin 79-27 re loss of nonclass IE instrumentation,will not be complete within 90 days Requests extension until 800425 ROBB,D A Jersey Central Power & Light Co 80/02/22 ig
- 8004180329 Forwards IE lnsp Rept 50-219/80-02 on 800115-18 No noncompliance noted CARLSON.R.T Region 1, Philadelphia, Reactor Construction & Engineering Bupport Branch 80/02/26. 2pp
- --8004180334 IE Insp Rept 50-219/80-02 on 800115-18 No noncompliance noted Major areas inspected; five mods & event rept followups.

 EBNETER, B, D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. FINKEL, A, E. Region 1, Philadelphia, Office of the Director 80/02/25, App

- 8004210326 Forwards IE Insp Rept 50-219/79-20 on 791127-30 No noncompliance noted MARTIN.W Q Region 1. Philadelphia, Safeguards Branch 60/02/27 2pp
- --8004210330 IE Insp Rept 50-219/79-20 on 791127-30 No noncompliance noted Major areas inspected security plansprogram audit, physical barriers in protected & vital areas.lighting & access control Details withheld (ref 10CFR2 790) DEVLIN, J W Region 1, Philadelphia, Bafeguards Branch MADDEN, W Region 1, Philadelphia, Office of the Director 80/02/20 1p
- BOO4210439 Forwards IE Insp Rept 50-219/80-05 on BO0129-0201 No noncompliance noted BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch BO/02/27 2pp
- --B004210450 IE Insp Rept 50-219/80-05 on 800129-0201 No noncompliance noted Major areas inspected refueling activities independent insp effort, IE bulletin followup, inofe LER review & periodic review KEIMIO, R R , BRIGGS, T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/24 App
- 8004090238 Ack receipt of 800222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/79-24
 BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/03/04 lp
- --8004090246 Responds to NRC 800128 ltr violations noted in IE Insp Rept 50-219/79-24 Corrective actions trates were painted w/fire retardant paint & administrative controls established ROSS,D A Jersey Central Power & Light Go 80/02/22 2pp
- --8004090249 Forwards IE Insp Rept 50-219/79-24 on 791211-14 & 18 & notice of violation BRUNNER,E J Region 1. Philadelphia, Reactor Operations Muclear Support Branch 80/01/28 2pp
- --8004090254 Notice of violation from insp on 791211-14 & 18
 * Region i, Philadelphia, Office of the Director 80/01/25 lp
- ~~8004090262 IE lnsp Rept 50~219/79~24 on 791211~14 & 18 Noncompliance noted improper storage of flammable matl KEIMIO,R R Region i, Philadelphia, Reactor Operations Nuclear Support Branch KOLTAY,P, BRIGOS,L Region i, Philadelphia, Office of the Director 80/01/25 App
- 8004100424 Responds to IE Bulletin 80-03 Charcoal adsorber cells presently utilized are acceptable & provide no indication of structural deficiencies which would affect filter performance RGSs.D. A Jersey Central Power & Light Co 80/03/13 2pp
- 8004090420 Advises that IE Bullstin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVC8) Holdup Tanks," was incorrectly sent for action No response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/17 ip
- 8004150269 Forwards IE Info Notice 80-12, "Instrument Failure Causes Dpening of PORV & Block Valve " No specific action or response necessary GRICE, B H Region 1, Philadelphia. Office of the Director 80/03/31 1p
- 8004090057 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region I, Philadelphia, Office of the Director 90/04/01 ip
- BOO4110137 Forwards IE Info Notice 80-13. "GE Type SBM Control Buitches Defective CAM Followers " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/04/02 ip
- 8004110422 Provides NRC w/immediate corrective actions in radiation protection dept in response to IE Insp Repts 80-3 & 80-11 Corrective actions involve personnel, procedures, training & work activities ROBS.D A Jersey Central Power & Light Co. 80/04/02 2pp
- 80042403ii Forwards IR Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER, B H Region 1. Philadelphia, Office of the Director. 80/04/02 lp

.

DOCKETED ITEMS

- 8004180166 Forwards IE Circular 80-07, "Problems W/MPCI Turbine Oil Sys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/03 tp 80/04/03
- 8004230478 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312.Type 304 Stainless Steel Pipe " Action required GRIER, B H Region 1. Philadelphia. Office of the Director B0/04/04 ip
- B004180149 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/04/07 ip
- R Periodic operating reports & related correspondence
- 8004020383 Forwards "1979 Annual Environ Operating Rept for ETS, App 8 " FINFROCK, I R Jersey Central Power & Light Co 80/03/28 2pp
- --8004020384 "1979 Annual Environ Operating Rept for ETS, App B " # Jersey Central Power & Light Co 80/03/31 183pp
- 8004240429 Forwards monthly operating rept for Mar 1980 ROSS,D A Jersey Central Power & Light Co 80/04/16 80/04/16
- --8004240432 Monthly operating rept for Mar 1780
 MCCLAIN.C M Jersey Central Power & Light Co 80/04/09 9pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004010480 Forwards LER 80-014/01T-0 ROSS,D A Jersey Central Power & Light Co 80/03/24 ip
- -8004010485 LER 80-014/01T-O on 800302. smergency dievel generator i ,failed to synchronize & tripped when generator 2 was tagged for mod Caused by component failure Fuse T7. found loose in holder Fuseholder repaired RDS8,D A Jersey Central Power & Light Co 80/03/24 3pp
- B004010503 Forwards LER 80-013/01T-0 ROBB,D A Jersey Central Power & Light Co B0/03/24 ip
- -8004010909 LER 80-013/01T-0 on 800309, fire suppression outhblubur LER BD-013/01T-0 on 800309, fire suppression water removed from svc to replace cracked valve.contrary to Tech Specs Fire truck pumper used as water supply backup Cause of valve body crack under investigation RDSB.D A Jersey Central Power & Light Co 80/03/24 3p
- 8004040284 Forwards LER 80-012/03L-0 ROSS,D A Jarsey Central Power & Light Co 80/03/27 1p
- --8004040288 LER 80-012/03L-0 on 800228, discovered that weekly outstanding the control of the contr
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1 Security, medical, emergency & fire protection plans
- 8004230216 Forwards criteria not adequately covered by 791228 emergency plan for revision per NUREO-0654, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparadness in Support of Nuclear Power Plants "
 ZIEMANN.D L. Operating Reactors Branch 2 80/03/24 19pp
- 8004230221 Forwards criteria not adequately covered by 800125 emergency plan for revision per NUREG-0654, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparedness in Support of Nuclear Power Plants "
 IPPOLITO.T A Operating Reactors Branch 3 80/03/27, 17pp
- 8004070269 Forwards info re 791211 security plan change Enc1 withheld (ref 100FR2 790) BARTLETT, J Niagara Mohawk Power Corp 80/03/31 1p
- 8004180345 Forwards "Functional Spec for Facility Fire Protection Mods. Fire Detection & Control." BARTLETT, J Niagara Mohawk Power Corp 80/04/14 1p
- -8004180349 "Functional Spec for Facility Fire Protection Mode. Fire Dataction & Control " SWEET,K J Niagara Mohawk Power Corp 80/03/27 50pp

- H General correspondence
- 8004280440 Notifies that position of Vice President for Electric Production abolished & future NRC correspondence should be sent to DP Dise, Vice President for Engineering Security matters should be addressed to JJ Sunser BARTLETT, J Niagara Mohawk Power Corp 80/04/22 ip
- 8004270363 Informs of changes in mgt to provide for more efficient operation Effective 800301.TE Lempges elected Vice President Nuclear Generation Correspondence is security matters should be sent to Sunser & Lempges BARTLETT, J O Niagara Mohawk Power Corp 80/04/22 ip
- P Operating license stage documents & correspondence
- 8004070402 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO,T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIBENHUT, D O Division of Operating Reactors 80/03/12 5pp
- ---8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors | 80/02/21 | 28pp
- 8004010330 Forwards info re primary coplant pressure isolation capability as per 800223 request Info demonstrates that continued operation of facility does not present undue safety hazard to public DISE, D.P. Niagara Mohawk Power Corp. 80/03/19 14pp
- 8004100032 Forwards "Evaluation of License Compliance W/Category A Thems of NRC Recommendations Resulting From YMI-2 Lessons Learned "All Category A requirements have been satisfactorily met Mods will be verified by IE IPPOLITO, TA Operating Reactors Branch 3 80/03/21 i 80/03/21 15op
- 8004180253 Forwards Amend 36 to License DPR-43, safety evaluation & notice of issuance & availability IPPOLITO, T A Operating Reactors Branch 3 80/03/28 2pp
- --9004180258 Amend 36 to License DPR-63 changing Tech Specs to modify power-to-flow curve & allowing addl operational flexibility during plant lead changes IPPOLITO,TA Operating Reactors Branch 3 80/03/28 8pp
- --B0041B0277 Bafety evaluation supporting Amend 36 to License DPR-63
 # Operating Reactors Branch 3 80/03/28 3pp
- --8004180278 Notice of issuance & availability of Amends 36 to License DPR-63 IPPOLITO,T A Operating Reactors Branch 3 80/03/28 2pp
- 8004250034 Forwards 800128 & 0211 ltrs to GE re proposed control rod drive sys mads related to elimination of cracking in return line nazzlas Mads should not be performed prior to issuance of NUREC-0619, scheduled for Apr 1980 IPPOLITO, T A Operating Reactors Branch 3 80/04/07 2pp
- 800A210407 Submits info clarifying util NUREG-0578 commitment re containment water level indication Util will install now differential pressure transmitters on torus using existing instrument taps BARTLETT. J Niagara Mohawk Power Corp 80/04/11 1p
- 8004220464 Forwards application for amend to License DPR-63 & proposed Tech Spec changes to App A
 THOMAS, E B LeBosuf, Lamb, Leiby & HacRae 80/04/21 ip
- --8004220501 Application for amend to License DPR-43, requesting that Bections 2 1 1,3 1 7,3 6 4,6 0 & bases of Tech Specs set forth in App A be revised BARTLETT, J Niagara Mohawk Power Corp 80/04/18 2pp
- --8004220504 Proposed Tech Spec App A changes to Sections 2 1 1:3 1 7. 3 6 4:6 0 % bases * Niagara Mohawk Power Corp 80/04/18 33pp

- Inspection reports, lE Bulletins & correspondence
- 004100162 Forwards IE Insp Rept 50-220/79-26 on 79;210.ii & 13 No noncompliance noted SMITH, 0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/19 2pp
- -8004100173 IE Inep Rept 50~220/79-26 on 791210.11 & 13 No noncompliance noted Major areas inspected licensee response to IE Bulletin 79-19, documents, procedures, training, audits, facility tours & records
 KNNPP,P J Region 1. Philadelphia. Fuel Facility & Materials
 Bafety Branch THOMAS.L H Region 1. Philadelphia. Office of the Director 80/02/15 4pp
- 1004080415 Advises that per 791207 ltr re IE Bulletin 79-14.ho mods are necessary to condensate demineralizer recycle loop DISE.D P Niagara Mohawk Power Corp 80/02/22 1p
- 3004090239 Forwards response to IE Bulletin 79-27 re loss of non-class IE instrumentation & control power sys buses during operation No mode nocessary after review BARLETT, J Niagara Mohawk Power Corp 80/02/29 8pp
- 8004i10055 Forwards response to IE Bulletin 79-018, re environ qualification of Class IE equipment Util is investigating equipment qualification of outstanding items Results will be reported in second response on 800417 M/o encl LEMPOES.T E Niagara Hohawk Power Corp 80/03/05 2pp
- 8004100401 Responds to IE Bulletin 79-018 Response to IE Bulletin 79-01 dtd 790712 indicated interim repts on equipment environ qualification would be provided every 60 days Repts will be discontinued & replaced by IE Bulletin 79-018 responses LEMPOEB.T E Niagara Mohawk Power Corp 80/03/07 1p
- B004090407 Advises that IE Bulletin B0~05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVCS) Holdup Tanks," was incorrectly sent for action No response required GRISER B Region 1, Philadelphia, Office of the Director 80/03/17 ip
- 8004010373 Responds to IE Bulletin 80-03, "Loss of Charcoal from 8td Type ii, Tuo-inch, Tray Adsorber Celis" No equipment abnormalities evident which would affect performance of reactor or control room emergency ventilation sus LEMPGES, T E Niagara Mohawk Power Corp 80/03/19 ip
- 8004010392 Discusses corrective action re It Insp Rept 50-220/60-01 No apparent reason found for missing chain locking device on liquid poison sys valve 41-12 Valve was checked off as locked & closed during 790522 sys valve lineup check LEMPGES.T E Niagara Mohawk Pawer Corp 80/03/19, 1p
- 8004080642 Clarifies 800319 response to IE Insp Rept 50-220/80-01 All locks which secure valves in position described by operating procedure valve check-off list will have cores changed to unique key series by end of 1981 LEMPOES, TE Niagara Mohawk Power Corp 80/03/28 ip
- 8004150282 Forwards IR Info Notice 80-12, "Instrument Failure Causes Deming of PORV & Block Valve " No specific action or response necessary GRIER.B H Region 1, Philadelphia. Office of the Director 80/03/31 1p
- 9004090080 Forwards IE Circular 80-05, "Emergency Biesel Generator ubricating Oil Addition & Onsite Bupply " No written aponse required IER.B H Region 1, Philadelphia. Office of the Director /04/01 1p
 - 110158 Forwards IE info Notice 80-13, "QE Type SBM Control Switches fective CAM Followers " No written response required AlER.B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 3004240324 Forwards IR info Notice 80-14. "Bafety Suggestions From Employees " No action required. ORIER: B.H. Region 1. Philadelphia. Office of the Director 80/04/02 ip
- 8004180262 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required ORIER.B H Region i, Philadelphia, Office of the Director 80/04/03, 1p

- 80042303B6 Forwards IE Bulletin 79-03A. "Longitudinal Wold Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required CRIER.B H Region 1. Philadelphia. Office of the Director 80/04/04 1p
- 8004180207 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds "Written response required GRIER.8 H Region 1, Philadelphia, Office of the Director. 80/04/07 1p
- R Periodic operating reports & related correspondence
- 800404040 Forwards "1979 Aquatic Ecology Studies " LEMPGES, T. C. Niagara Mohawk Power Corp. 80/03/29 ip
- --8004040408 "1979 Aquatic Ecology Studies "
 * Teras Instruments, Inc 80/03/31 100pp
- 8004140406 Forwards monthly operating rept for Mar 1980 LEMPGES, T E Niagara Mohawk Power Corp 80/04/03 3pp
- --8004140411 Monthly operating rept for Mar 1980 RDMAN, T W Niagara Mohawk Power Corp 80/04/02 3pp
- DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

 G Adjudicatory correspondence
- BOO4230340 Requests NRC intentions for planning hearings re petition to suspend all activities of TRIGA reactor Urges immodiate resolution of issues between NRC & Berkeley, CA NEWPORT, E O Berkeley, CA 80/04/17 1p
- DOCKET 50-225 RPI CRITICAL EXPERIMENT
- G Inspection reports, IE Bulletins & correspondence
- 8004300317 Ack receipt of 800328 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-225/80-01 SMITH.0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/07, ip
- ---B004300320 Responds to NRC 800310 ltr re violations noted in IE Insp Rept 50-225/80-01 Corrective actions personnel monitoring procedure revised to TLD records now computerized RYAN.R M Rensselaer Polytechnic Inst 80/03/28 ip
- --8004300322 Forwards IE Insp Rept S0-225/80-01 on 800115-17 & notice of violation SMITH.0 F Region 1. Philadelphia. Fuel Facility & Materials Safety Branch B0/03/10 2pp
- --800430324 Notice of violation from insp on 800115-17 * Region 1, Philadelphia, Office of the Director, 80/03/06 ip
- --8004300328 IE Inap Rept 80-225/80-01 on 800115-17 Noncompliance noted failure to maintain personnel dosimetry records TERC.N M , BORRB.R J Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/06 7pp
- DOCKET 50-228 AEROTEST RADIOGRAPHY & REGEARCH REACTOR
 P Operating license stage documents & correspondence
- 8004170005 Application for transfer of License R-98 from Acrotest Operations. Inc to Acrotest Operations Acquisitions, Inc Bupperting documentation and ELKUS.R J Aerotest Operations 80/04/11 11pp
- DOCKET 50-237 DREBDEN NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 800424053: Forwards sys description & operating instructions for NRC health physics telephone network Bys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimille traffic KEPPLER. J Q Region 3. Chicago. Office of the Director. 80/03/20

- 8004030172 Forwards Figure 2-1 to correct omission made in 800311 ltr re evacuation time estimates for facility Figure 3-1 in Section 3 should be placed in Section 2 PEOPLES, D L. Commonwealth Edison Co. 80/03/26 2pp
- 8004110399 Confirms & documents 800326 telcon re facility turbine bidg mezzanine area fire protection capabilities Fire provention & protection features are adequate & provide high degree of plant safety JANECEK.R F Commonwealth Edison Co 80/04/08 2pp
- 8004220299 Informs that Unit 3 refueling outage bogan 6 wks early & will end approx one month earlier than scheduled, due to failure in recirculation say jet pump Completion of some fire protection mods will not be possible prior to startup PEOPLES.D L Commonwealth Edison Co 80/04/10 1p
- 8004230367 Forwards revised security plan Revisions withheld (ref 100FR2 790)
 PEOPLES D L Commonwealth Edison Co 80/04/21 1P
- @ Adjudicatory correspondence
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSICK, L V Office of the Executive Director for Operations BO/04/02 34pp
- P Operating license stage documents & correspondence
- 8004080296 Forwards corrected Pages 68 & 93 for Licenses DPR-19 Amend 44 & DPR-25 Amend 39 & corrected Pages 3 6/4 6-2 & 3 6/4 6-9 for licenses DPR-29 Amend 53 & DPR-30 Amend 50 in response to 791002 itr | IPPOLITO,T A Operating Reactors Branch 3 80/02/20 2pp
- ---8004080310 Corrected License Pages 8B & 93 for Amends 44 & 39 to Licenses DPR-19 & DPR-25, respectively & corrected License Pages 3 6/4 6-2 & 3 6/4,6-9 for Amends 53 & 30 to Licenses DPR-29 & DPR-30, respectively # Operating Reactors Branch 3 80/02/20 8pp
- 8004030027 Bubmits info requested in 800201 ltr re seepage from plant cooling lake No dike stability or integrity concerns have been identified No effect on health & safety of public increased surveillance will provide info to evaluate change PEOPLES.D L Commonwealth Edison Co 80/02/29 2pp
- 8004090335 Forwards NUREG-0569. "Evaluation of Integrity of SEP Reactor Vessels." completing review of SEP Topic V-6 W/o encl
 ZIEMANN.D L. Operating Reactors Branch 2 80/03/05 2pp
- 8004020010 Forwards review schedule for environ qualification of Class IC electrical equipment per 800221 meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 5pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- ---B004030118 "Nuclear Data Link Specs "
 * Division of Operating Seactors 80/02/21 28pp
- BO04010397 Forwards LPCI hanger details from ring header to pumps 2A-1502 Matrix indicating hanger number, type, manufacturer, rated load & design encl
 JANECEK,R.F. Commonwealth Edison Co 80/03/17 6pp
- 8004100102 Requests controlled set of P&IDs for each plant Bubmittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER.J O. Region 3. Chicago. Office of the Director 80/03/20
- 8004230226 Forwards NRC 800128 & 0211 ltrs to GE re proposed control rod drive sys mods & optimizing pump flow to reactor vessel Mods should not be performed until complete guidance is issued in NUREO-0619 or w/o NRC approval ILEMANN, D L Operating Reactors Branch 2 80/03/24 2pp
- BOO4080235 Submits status rept for open site suitability review items per BOO304 commitment QE has extracted info re reactor vessel supports from original design files Info will be forwarded to NRC Mar 1980 Issue should be resolved JANECEK:R F Commonwealth Edison Co 80/03/27 App.

- 8004070245 Forwards OE info re imposed loads on reactor pressure vessel Nozzle reaction loads tabulated on Drawing 8850910, Revision 6 intended to include all loads that piping can impose on reactor pressure vessel JANACEK, R F Commonwealth Edison Co 80/03/28 4pp
- B004230178 Forwards request for info re environ qualification of electrical equipment Dato is needed for NRC calculation of containment temp & pressure decay time Calculation should be based on current LOCA analysis ZIEMANN.D L Operating Reactors Dranch 2 80/03/28 14pp
- B00411045B Responds to NRC 800101 itr requesting info re anchorage of safety-related electrical equipment Submits action plan & info required by Question 1

 JANACEK.R F Commonwealth Edison Co 80/04/01 App
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. AA program Revisions reflect recent organization title changes
 NAUGHTON.W F Commonwealth Edison Co 80/04/02 1p
- --8004150328 Revised pages constituting Revision 13 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-1-A R13 80/04/04 7pp
- 8004140395 Advises that replacement of spring safety valves w/safety relief valves will not be necessary due to reclassification of pressurization transient frequency & addl measures for prevention of premature valve actuation JANENCEK.R F Commonwealth Edison Co 80/04/08 2pp
- 8004180217 Forwards add1 info re failure of control rods to insert fully on screm in response to NRC 800110 & 11 ltrs Dresden 1 experienced no control rod failures in 1978-79 Failure at other facilities caused by leakage past worn piston seals JANECEK.R F Commonwealth Edison Co 80/04/14 10pp
- 800422034B Responds to NRC 800214 ltr re SEP topic references Lists references for ECCS actuation sys.engineering safety feature switch over from injection to recirculation mode & testing of reactor trip sys JANECEM.R F Commonwealth Edison Co 80/04/14 3pp
- 8004250427 Forwards response to NUREC-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lassalle County site-specific emergency plan PEOPLES,D L Commonwealth Edison Co 80/04/15 6Opp
- --8004250428 "Design Criteria & Gonceptual Design Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- G Inspection reports, IE Bulletins & correspondence
- 8004070197 Forwards IE Insp Repts 50-010/79-23,50-237/79-27 & 50-249/79-29 on 791009 & 1128 & notice of violation DAVIB.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/12 2pp
- --8004070162 * Region
- --8004070166 IE Insp Repts 30-010/79-23,50-237/79-27,& 50-249/79-25 on 791007 & 1128 Noncompliance noted radioactive mat1 shipment record not utilized for radwaste shipments made 790101-1128 GREGERL R. FISHER.W. Region 3, Chicago, Office of the Director 80/01/31. 7pp
- B004040195 Forwards IE Insp Repts 50-010/B0-01,50-237/B0-01 & 50-249/B0-01 on B0010B-09 No noncompliance noted FIORELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/02/16 Zpp
- --8004040199 IE Insp Repts 50-010/80-01,50-237/80-01 & 50-249/80-01 on 800108-09 No nencompliance noted Major areas inspected smergency diesel generator mods & mod of electrical equipment re IEEE-279 compliance HAYES,D W Region 3. Chicago, Reactor Construction & Engineering Support Branch HUGHES,J Region 3. Chicago, Office of the Director 80/02/08 5pp
- B004i00i40 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted DAVIS.A B Ragion 3. Chicago, Fuel Facility & Materials Safety Branch B0/02/22 2pp

- --B004100408 Waste Packages Insp Rept 79-07A on 791212-13 No noncompliance noted Major area inspected compliance w/DDT & NRC regulations including shipping paper requirements, radiation levels & DDT labeling POTTER.J P. PEERY.W W. WOODRUFF.R L. Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/02/22 App
- 8004100426 Forwards IE Insp Repts 50-010/80-03,50-237/80-03 & 50-249/80-03 on 800107-0201 No noncompliance noted HEISHMAN.R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004100432 IE Insp Repts 50-010/80-03.50-237/80-03 & 50-249/80-03 on 800107-0201.No noncompliance noted Major areas inspected maint activities plant operations, physical protection, safety-related sys surveillance insp followup & rafweling BARKER, J L , TONQUE, T M , SPESSARD, R L Region 3. Chicago, Diffice of the Director 80/02/22 7pp
- 8004i00ii8 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/07 ip
- 8004100119 Ack receipt of BOC304 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-010/79-23, 50-237/79-27 & 50-249/79-25 DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch BO/03/20 Zpp
- --8004100128 Responds to NRC 800212 ltr re violations noted in IE Imsp Repts 50-010/79-28.50-237/79-27 & 50-249/79-25 Corrective actions informed personnal re cost estimate change order requirements PEOPLES, D L Commonwealth Edison Co 80/03/04 3pp
- BOO4140119 Forwards response to IE Bullotin BO-O3. "Loss of Charcoal from Std Type II.Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES.D L. Commonwealth Edison Co. 80/03/20 5pp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/21 ip
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance noted DAVIG.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No moncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination & package external features
 POTTER: J P. PEERY: W W. WOODRUFF: R L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- 8004300544 Forwards IE Insp Repts 50-010/80-04.50-237/80-04 & 50-249/80-04 on 600220-22 & 26 & notice of violation DAVIS,A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/21 2pg
- --8004300548 Natice of violation from inap on 800220-22 & 26 * Region 3. Chicago. Office of the Director 80/03/11 in
- --8004300555 IE Insp Repts 50-010/80-04,50-237/80-04 & 50-249/80-04 on 800220-22 & 26 No moncompliance noted Major areas inspected internal audits, licensee coordination w/offsite support agencies & review of emergency drills EBSTO.T H. DESTMANN.M J. MATEON.E Region 3, Chicago, Office of the Director 80/03/11 10pp.
 - 130159 Forwards IE Info Notice BO-12, "Instrument Failure Causes ening of PORV & Block Valve " No specific action or seponse necessary
 KEPLER: J G Region 3: Chicago, Office of the Director 80/03/31
- 8004080686 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Qil Addition & Onsite Supply " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/01

- 8004i500i4 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Differtive CAN Followers" No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02 1s
- BO0418003D Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hezards," inadvertently omitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02 in
- 8004220093 Forwards IE Info Natice 80-i4. "Safety Buggestions From Employees" No action required KEPPLER. J G Region 3. Chicago. Office of the Director 80/04/02 ip
- 8004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbins Oil Sys " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/03 ip
- B004ii0025 Forwards IE Bulietin 80-07, "BWR Jet Pump Assembly Failure " Hritten response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/07 ip
- 8004230224 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Action required KEPPLER. J G Region 3. Chicago, Office of the Director 80/04/07 to
- B004220069 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Writton response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/04/09 1p
- 8004280628 Forwards revised Pages 3 & 5 & omitted Page 4 to 1E insp Repts 50-010/80-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 & 50-265/80-08 FIGRELLI, Q Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/09 ip
- --8004280434 Revised Pages 3 & 5 & omitted Page 4 to IE Insp Repts 50-016780-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 & 50-265/80-08 * Region 2, Atlanta, Office of the Director, 80/04/09 3pp
- R Periodic operating reports & related correspondence
- 8004140330 Forwards "Radwaste & Environ Monitoring Annual Rept 1979 " STEPHENSON.B B Commonwealth Edison Co BO/03/19 ip
- ----B004140340 "Radwaste & Environ Monitoring Annual Rept 1979 "
 KOHL, & A . CHANDRASEKARAN Eberline Instrument Corp 80/03/31
 91pp
- 80041503B2 Forwards monthly operating repts for Mar 1980. 8TEPHENSON: 8 B Commonwealth Edison Co 80/04/10 ip
- --8004180387 Monthly operating repts for Mar 1980 CleszKiewicz,8 Commonwealth Edison Co 80/04/01 23pp
- 8 Repartable occurrences, LERs & related correspondence
- 8004140423 Forwards updated LER 80-005/03X-1 STEPHENBON, B B Commonwealth Edison Co BO/03/21 ip
- ---8004140427 Updated LER 80-006/03X-01 on 800119 during normal operation:
 two successive samples of waste sample tank A showed
 radioactivity in excess of Tech Specs Caused by effluent
 release Tank A reprocessed
 BADER. 8 Commonwealth Edison Co 80/03/24 ip
- 8004150503 Forwards LER 80-011/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/04/03 ip
- --8004150513 LER 80-011/03L-0 on 800318, while performing isolation condenser condensate line hi flow calibr, DPIS 1349A tripped at 32 2 inches Caused by instrument setpoint drift, Switch readjusted to trip at 28 5 inches MAGROW, R Commonwealth Edison Co 80/04/03, 1p.

- DOCKET 50-243 DREGON STATE UNIV RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8004110543 Forwards IE Insp Rept 50-243/80-01, on 800128-30 No noncompliance noted BODK, H & Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/03/04 2pp
- --8004i10550 IE Insp Rept 50-243/80-0i on 800128-30 No noncompliance noted Major areas inspected radiation protection.including control procedures, training, area posting, radiation monitoring & personnel dosimetry

 BOOK, H E Region 5, San Francisco, Fuel Facility & Materials
 Safety Branch CURTIS, J R Region 5, San Francisco, Office of the Director 80/03/04 6pp
- B004210187 Forwards IE lnsp Rept 50-243/80-02 on 800226-27 No noncompliance noted CREMS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/03/07 2pp
- ---8004210196 IE Insp Rept 50-243/80-02 on 800226-27 No noncompliance noted Major areas inspected organization, logs & records, review & audit-requalification training, refueling, surveillance & experiments
 STERNBERG.D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch CARLSON, J P., MORRILL, P. J. Region 5, San Francisco, Office of the Director 80/03/06 5pp
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT i

 F Security, medical, emergency & fire protection plans
- 8004100448 Comments on proposed rule 10CFR50 plant should be kept open while emergency plan is upgraded for Monroe County EMITH.E J New York, State of 80/02/13 ip
- 8004170322 Notification of 800415 meeting w/util in Ontario.NY to discuss plant emergency planning review SHEA.J J Operating Reactors Branch 2 80/03/26 2pp
- 8004110195 Forwards add1 revisions to security plan, Chapter 8 (contingency plan) Encl withheld (ref 10CFR2 790) WHITE,L D Rochester Gas & Clectric Corp 80/04/03 1p
- Q Adjudicatory correspondence
- BU04030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK,L V Office of the Executive Director for Operations BO/04/02 34pp
- I Financial information
- 8004150502 Annual Financial Rept 1979 * Rochester Gas & Electric Corp 80/03/14 35pp
- P Operating license stage documents & correspondence
- 8004240222 Responds to 800208 itr re shipment of mixed oxide fuel rods Route & law enforcement contact info provided by Tri-State Motor Transit Co meets 10CFR73 requirements Data re contacts & shipment route encl Data withheld (ref 10CFR2 770) MCCORKLE, 0 W Physical Security Licensing Branch 80/02/13 1p
- 8004100316 Advises that responses to 761123 ltrs re LWR assessment of enhancement of fission gas release at higher burnups have been revisived No immediate licensing action required for operating reactors, per typical fuel bundle & batch burnups ZIEMANN.D.L. Operating Reactors Branch 2 90/02/29 3pp
- 8004100859 Forwards NUREG-0569. "Evaluation of Integrity of SEP Reactor Vessels." completing review of SEP Topic V-6 W/o encl. ZIEMANN.D L. Operating Reactors Branch 2 80/03/05 2pp
- 8004020014 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 maeting Resubmittal of info is unnecessary References or updates to info proviously submitted are acceptable ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 5pp

- 8004220110 Expresses concern re NRC failure to approve util request to use four mixed oxide fuel assemblies as reactor fuel NRC approved receipt of assemblies on 800213 Requests prompt approval due to 800329 annual refueling shutdown DRAKE.F E Rochester Gas & Electric Corp 80/03/06 3pp
- BOO4220780 Forwards request for add1 info for continued review of SEP Topic XV-16. "Radiolgical Consequences of Small Lines Carrying Primary Coolant Outside Containment "
 ZIEMANN.D L. Operating Reactors Branch 2 BO/03/11 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D 0 Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004180094 Forwards evaluation of SEP Topic VIII-4, "Electrical Penetrations of Reactor Containment" ZIEMANN.D L. Operating Reactors Branch 2 80/03/24 17pp
- B004010355 Submits deferred response to NRC 791022 ltr re long-term recommendation X 4 3 3-2 for auxiliary feedwater sys Water source capabilities will provide required flow by gravity feed to pump suction
 WHITE, L D Rochester Gas & Electric Corp 80/03/28 4pp
- 8004240003 Supplements 800306 itr re accelerated review schedule of environ qualification of electrical equipment Forwards schedule for & discussion of submittals & data necessary for NRC calculation of containment temp
 ZIEMANN,D L Operating Reactors Branch 2 80/03/28 14pp
- B004100461 Forwards responses to B00325 Lessons Learned audit questions
 WILKENS.P C Rochester Gas & Electric Corp B0/04/03 400pp
- 8004210036 Advises that 800213 proposed mods to spent fuel pool cooling sys require Class III fer category Requests prompt payment Any overpayments or addit charges will be determined at final review D1005,R M License Fee Management Branch 80/04/04 ip
- 8004150434 Forwards add1 info requested by NRC 800328 ltr re environ qualification of electrical equipment Info provided virtually identical to util 770810 ltr Roquests that analysis make use of previously supplied info WHITE, L D Rochester Gas & Electric Corp 80/04/10 19pp
- 8004150329 Forwards application for amend to License DPR-18, containing Tech 8pec change request Certificate of 8vc encl MCGRANERY, J P LeBoeuf, Lamb, Leiby & MacRae B0/04/11 4pp
- --8004180931 Application for amend to License DPR--iB to changing Tech Specs 4 2-1 & 4 2-2 re organization WHITE-L D Rochester Oas & Electric Corp 80/04/11 2pp
- ---8004150332 Tech Specs changes to Figures & 1-1 & 4 2-2 for mgt organization Safety evaluation encl * Rochester Gas & Electric Corp 80/04/11 1p
- ---8004150334 Mgt organization chart, Figure 6 2-1 * Rochester Gas & Electric Corp 80/04/11 1
- --8004150335 Facility organization chart. Figure 6 2-2
 * Rochester Gas & Electric Corp 80/04/ii 1p
- 8004150459 Submits Info in response to NRC 770529 draft evaluation of SEP Topic III-2 B, onsite meteorological measurements program Forwards "Upper Air Meteorological Study."

 WHITE, L D Rochester Oas & Electric Corp 80/04/11 3pp
- --8004150462 "Upper Air Meteorological Study "
 * York Research Corp 74/06/07 164pp
- B004230371 Forwards Class III fee for review & approval of spent fuel pool cooling sys W/o encl WHITE, L D Rochester Gas & Electric Corp 80/04/17 1p

- 8004230389 Forwards info to NRC consultant for seismic review team for seismic review of electrical equipment, in response to PJ Gallagher B00116 itr Info includes sketches of battery racks to other diagrams WJA encl WHITE,L D Rochester Gas & Electric Corp 80/04/17 lp
- 8004290378 Forwards "Environ Qualification of Electrical Equipment," Revision 2, in response to NRC 800306 & 28 requests WHITE,L D Rochester Oas & Electric Corp 80/04/25 ip
- --B004270381 "Environ Gualification of Electrical Equipment," Revision 2 * Rochester Gas & Electric Corp 80/04/25 75pp
- O Inspection reports, IE Bulletins & correspondence
- 8004210059 Forwards IE Insp Rept 50-244/80-01 on 800115-17 No BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/25 2pp
- --B004210071 IE Insp Rept 50-244/80-01 on 800115-17 No noncompliance noted Najor areas inspected tours of plant areas & plant plant status compliance w/Tech Specs, licensee action on insp findings & review of licensee action on IE circulars KISTER.H B Region i. Philadelphia. Reactor Operations Nuclear Support Branch MARKOMEKKI.R S . RAYMOND.# J Region i. Philadelphia, Office of the Director 80/02/21 10pp
- 8004090445 Submits response to IE Bulletin 79-27 re loss of non-Class IE instrumentation & control power sys bus during operation Detailed descriptions of IA, IB, IC, & 1D instrument buses given No mods required HHITE,L D Rochester Gas & Electric Corp BO/02/26 13pp
- 8004230003 Forwards response to IE Bulletin 80-03 Insp of charcoal filters completed Minor deficiencies found in two filter sys WHITE:L D. Rochester Gas & Electric Corp 80/03/21 2pp
- 8004300223 Ack receipt of 800304 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/79-18 SHITH.0 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/03/26 ip
- ---8004300227 Responds to NRC B00207 itr re violations noted in IE Insp Rept 50-244/79-18 Corrective actions isotopic analysis required of mati being shipped Higt stressed importance of timely response to audit findings A
- --8004300232 Forwards IE Imap Rept 50-244/79-18 on 791203-04 & notice of violation SMITH.O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/07 2pp.
- --8004300235 Notice of violation from insp on 791203-06 Portion withheld (ref 10CFR2 790)
 * Region i, Philadelphia, Office of the Director 80/02/01 3pp
- --8004300244 IE Insp Rept 50-244/79-18 on 791203-06 Noncompliance noted UMBIDIZER IE INSTREPT SD-244/79-IB on 791203-05 Moncompliance not feilure to respond to audit findings, to comply w/requirement of security plan, Paragraph i3 % to have written procedures for IOCFR71,App E Portion withheld (ref IOCFR2.790) CROCKER, H y YUMAS, P P. MARKONSKI, R S. Region 1, Philadelphia, Dffice of the Director BO/02/01 17pp
- 8004150303 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER.B H Region 1, Philadelphia, Office of the Director Region 1, Philadelphia, Office of the Director 80/03/31
- 8004090105 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER,8 H Region 1, Philadelphia, Office of the Director 80/04/01
- 8004110513 Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers" No written response required ORIER,B.H. Region 1. Philadelphia, Office of the Director 80/04/02 ip
- 8004240349 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees" No action required ORIER, BH Region 1. Philadelphia, Office of the Director BO/04/02 1p

- 8004180248 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 011 Sys " No written response required (RTER.) B Region 1, Philadelphia, Office of the Director 80/04/03 ip
- B004230435 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pips" Action required ORIER, B H Region 1. Philadelphia, Office of the Director B0/04/04 ip
- 8004180287 Forwards IE Bullstin 80-08, "Exam of Containment Liner Penetration Welds " Written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/04/07 ip
- B004300407 Forwards results of add1 wolds inspected during 1980 outage in accordance w/IE Bulletin 79-19.Revision 1 Seven welds inspected w/one indicating 1/32 inch cut Weld repaired WHITE.L D Rochester Gas & Electric Corp B0/04/25 2pp
- R Periodic operating reports & related correspondence
- BOO41503BO Forwards monthly operating rept for Mar 1980 SNOW.B A Rochester Oas & Electric Corp BO/04/09
- --8004150384 Monthly operating rept for Mar 1980 MCNAMARA:A E Rochester Gas & Electric Corp 80/04/10 Spp
- 5 Reportable occurrences, LERs & related correspondence
- 8004180458 Forwards LER B0-002/03L-0 WHITE,L D Rochester Gas & Electric Corp 80/04/14 1p
- --8004180471 LER 80-002/03L-0 on 800331 during review of special instructions discovered that time from previous boron concentration sample exceeded 75 days Caused by inadequate guidance for bimonthly sampling schedule Schedule changed FILKINS.D Rochester Gas & Electric Corp 80/04/14 ip
- BO04230972 RO B0~003.addy current exams conducted to detect potential tube defects Based on results.pulling initiated to remove tube w/abnormal absolute signal NOON.J C Rochester Oas & Electric Corp 80/04/14 2pp
- U Congressional/Executive Correspondence
- G004070127 Discusses recent util proposal to use four mixed oxide fuel assemblies containing approx 47 kg Pu Requests views on whether approvel would adversely affect US nonproliferation policy AHEARNE.JF Commission 80/03/04 1p
- DOCKET 50-245 HILLSTONE NUCLEAR POWER STATION, UNIT 1 F Becurity, medical, emergency & firs protection plans
- 800403026B Notifies that NRC review of util Feb 1980 revises safeguards contingency plan has been completed Forwards comments indicating need for add1 info within 30 days Comments withheld (ref 10CFR2 790)
 ZIEMANN.D L Operating Reactors Branch 2 80/03/11 2pp
- 8004080444 Advises of completed NRC review of 790411,0518 & 1009 submittals re Item 3 2 2, fire hose station evaluation Items acceptable as described ZIEMANN,D L. Operating Reactors Branch 2 80/03/13, 2pp Operating Reactors Dranch 2 80/03/13, 2pp
- BOO402040B Forwards "Feasibility Rept on Evacuation of Area Around Facility "
 COUNSIL, W. G Northeast Utilities 80/03/31 2pp
- ---800402041B "Feasibility Rept on Evacuation of Area Around Facility "
 One oversite drawing encl
 RODGERS.L M , PELL.B M Storch Engineers, MOLLOY,E J Northeast
 Utilities Service Co 80/03/31 58pp
- H General correspondence
- 800421004B Responds to 800309 htr requesting info re environ effects of New England nuclear power plants, Radiation effluent levels determined by IOCFR20 & App 1 to IOCFR50 Environ info available in stated LPDRB.

 BALLARD, R L Environmental Projects Branch 1 80/04/01 2pp

I Financial information

- BOO4080557 Responds to NRC 800305 ltr re adequacies of cash flows to meet possible retrospective premium payments & forwards 1979 annual repts for CT Light & Power Co, Hartford Electric Light Co & Western MA Electric Co O'CONNOR, L A Northeast Utilities 80/04/01 ip
- ---8004080544 Annual Financial Rept 1979 * Connecticut Light & Power Co 80/03/14 24pp
- ---8004080581 Annual Financial Rept 1979 * Hartford Electric Light Co 80/03/14 24pp
- --8004080590 Annual Financial Rept 1979
 * Western Massachusetts Electric Co 80/03/14 21pp
- BOO4150320 Forwards Annual Financial Repts 1979 BIGHOP,R W Northeast Utilities 80/04/02 1
- --8004150322 Annual Financial Rept 1979 * Connecticut Light & Power Co 80/03/14 50pp
- --8004150325 Annual Financial Rept 1979
 * Hartford Electric Light Co 80/03/14 60pp
- --8004150409 Annual Financial Rept 1979
 * Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/03/14 10pp
- BOO4150412 Annual Financial Rept 1979 * Western Massachusetts Electric Co BO/03/14 60pp
- J Insurance & indemnity information
- 8004/40254 Forwards Endorsements 57 & 58 MAELU Policy MF-52 IFFLAND,R R Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 3pp
- P Operating license stage documents & correspondence
- 8004100311 Advises that responses to 761123 ltrs re LWR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors, per typical fuel bundlo & batch burnups IIEMANN, D L. Operating Reactors Branch 2 80/02/29 3pp
- 8004080669 Confirms 800313 corporate mgt meeting in King of Prussia.PA to discuss 771219 water hammer event Proposed agenda encl ORIER.B H Region 1. Philadelphia. Office of the Director 80/03/05.
- 8004100568 Forwards NUREG-0569, "Evaluation of Integrity of SEP Reactor Vessels," completing review of SEP Topic V-6 W/o encl ZIEMANN, D. L. Operating Reactors Branch 2 80/03/05 2pp
- BOO4020015 Forwards review schedule for environ qualification of Class IE slectrical equipment per 800221 meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 5pp
- 8004090147 Forwards request for add1 info per continuing review of SEP Topic III-6 Requests response within 30 days of receiving 1tr ZIEMANN D L. Operating Reactors Branch 2 80/03/11 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D @ Division of Operating Reactors. 80/03/12 5pp
- --8004030118 "Nuclear Deta Link Specs "
 * Division of Operating Reactors 80/02/21. 28pp
- 8004030293 Responds to NRC 800214 ltrs re request for list of refs for five 8EP topics Forwards topics by number, title & listing of refs for ECCS actuation sys.automatic ECCS realignment & testing of reactor trip sys COUNSIL, W Q , FEE, W F Northeast Utilities 80/03/21 3pp

- 8004240497 Forwards NRC 800128 & 0211 ltrs to GE re proposed control rod drive sys mods & optimizing pump flow to reactor vessel Mods should not be performed until complete guidance is issued in NUREG-0619 or w/o NRC approval ZIEMANN.D L. Operating Reactors Branch 2 80/03/24 2pp
- 8004020331 Forwards aperture cards for drawings requested in NRC 791128
 1tr requesting info for review of SEP Topic VI-7 C 1 AC
 power for control valves is depicted in previously submitted
 Drawings 25202-30008 & 25202-30003 N/o encl
 COUNGIL,N G Northeast Nuclear Energy Co (subs of Northeast
 Utilities) 80/03/24 2pp
- 8004030215 Advises that GE Rept NEDD-24583, Revision 1, "Plant Unique Analysis Application Guide:" was transmitted to NRC via LJ Sobam 791227 ltr to DC Eisonhut Rept provides info re structural evaluation of Mark I containment program COUNBIL.W O Northeast Utilities 80/03/26 ip
- 8004100171 Notification of 800328 meeting w/util in Bethesda.MD repotential cracks in turbine rotors CARUSO.R Operating Reactors Branch 2 80/03/24 2pp
- 8004040306 Submits info re control rods failing to fully insert after scram & summary of other control rod drive malfunctions for 1778-1779, per NRC 800111 request COUNSIL.W Q Northeast Utilities 80/03/28 2pp
- B004070265 Submits info re direct indication of PDRV & safety valve positions Recent discussions w/vendor revealed difficulty w/B00401 completion date Revised date of completion is G10401 CDUNSIL, W O Northeast Utilities B0/03/28 2pp
- 8004170303 Forwards request for add1 info re environ qualification of olectrical equipment
 ZIEMANN, D L Operating Reactors Branch 2 80/03/28 14pp
- 8004070274 Discusses current intentions to submit design for providing sampling capacity for primary coolant & containment air by 800427 Utils are currently engaged in finalizing design details Slight delay is required to optimize design COUNSIL. W O Connecticut Yankee Atomic Power CO 80/04/01 2pp
- 8004110497 Application to amend OL by incorporating encl proposed Tech 8pec change Change would add three new curves extending max average planer linear heat generation rate limits & would delete curve for "MS" type fuel Fee encl COUNSIL. & O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80704702 3pp
- --8004110463 Proposed Tech Spec change adding three new curves which extend max average planar linear heat generation rate limits & deleting max average planar linear heat generation rate vs planar average exposure curve for "MS" type fuel # Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/30 Spp.
- 8004240373 Submits add1 info requested for NRC review of proposed Tech Spec change Existing Tech Spec for continuous leak rate monitoring via nitrogen make-up cannot be performed w/existing equipment or other instrumentation COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/14 4pp
- 8004250362 Forwards add1 info to support upgrading of isolation condenser CDUNBLLW O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/16 22pp
- 8004290651 Forwards drawings & info requested by NRC 800311 ltr re EEP.Topic IJI-6 concerning seismic re-evaluation Drawings & info available in Central Files only Info requested by NRC 800331 & 0416 ltrs will be provided later COUNSIL.W @ Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/21 400pp
- @ Inspection reports, IE Bulletins & correspondence
- B004090131 Forwards IE Insp Repts 50-213/79-20,50-245/79-26 & 50-336/79-29 an 791127-30 & 1203-07 No noncompliance noted BRUNNER, E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/08 2p
- --8004070138 IE Insp Repts 30-213/79-20, 50-245/79-26 \$ 50-336/79-28 on 791127-30 & 1203-07, No noncompliance noted Major areas inspected GA program implementation re QA/QC administration, design changes & mods & document control program BAUNACK, W H. Region I, Philadelphia, Reactor Operations Nuclear Support Branch NAPUDA, G. Region I, Philadelphia, Office of the Director 80/02/07 15pp

- 8004070213 Ack receipt of 800206 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/79-25 & 50-336/79-27 CARLSON,R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/28 Ip
- --8004070218 Responds to NRC 8001i1 ltr re violations noted in IE Insp Repts 80-245/79-25 & 80-336/79-27 Corrective actions open trash can replaced w/covered trash can & no smoking signs posted at entryways to main control boards COUNSIL.W G. FEE.W F. Northeast Utilities 80/02/06 2pp
- --8004070223 Forwards IE Insp Repts 50-245/79-25 & 50-336/79-27 on 791105-09 & notice of violation CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/11 2pp
- --8004070226 Notice of violation from 1nsp on 791109-09 * Region 1. Philadelphia, Dffice of the Director 80/01/08 ip
- --8004070231 IE Insp Repts 50-245/79-25 & 50-336/79-27 on 771105-09 Noncompliance noted failure to follow howekeeping procedura KOLTAY P S Region i, Philadelphia, Office of the Director EBNETER, S D Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/08 Spp
- 8004140129 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Sufficient alternate indications & controls plus manual operation are available w/o most COUNSIL.44 Q Northeast Utilities 80/02/29 4pp
- 8004i80i3B Forwards IE Insp Repts S0-245/79-29 & 50-336/79-30 on 79i20i-31 No noncompliance nated BRUNNER,E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --B0041B0147 IE Insp Repts 50-245/79-29 & 50-336/79-30 on 791201-31 No noncompliance noted Major areas inspected control rooms & accessible portions of Unit I containment, reactor, tyrbine, radwate, gas turbine generator & intake bldgs KEIMIG.R R Region i, Philadelphia, Reactor Operations Nuclear Support Branch ZIMMERHAN.R P, SHEDLOSKY, J T Region 1, Philadelphia, Office of the Director GO/02/29 10pp
- 8004210343 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SKITH.O H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch GD/03/05 2PP
- --B004210345 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper requirements.DOT placarding.radiation levels.removable contamination.BDT marking & labeling & external features POTTER.J P. PEERY.W W. MDDDRUFF.R L. Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/01/18 7pp
- 8004090404 Advises that IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control 8ys (CVCS) Holdup Tanks," was incorrectly sent for action No response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/17 ip
- 8004270057 Responds to IE Bulletin BO-OS. "Loss of Charcoal from Std Type II.Twd-Inch,Tray Adsorber Cells " Visual insp showed that screen on Type II cells was tightly affixed & no evidence of deformation or charcoal loss was observed COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilitles) 80/03/24 2pp
- 8004150279 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region I, Philadelphia, Office of the Director 80/03/31 ip
- 8004090074 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region i, Philadelphia. Office of the Director 80/04/01. 1p.
- 8004110156 Forwards IE Info Notice 80-13. "OE Type 88M Control Switches Defective CAM Foilowers " No written response required. ORIER, B H Region 1, Philadelphia. Office of the Director 80/04/02 ip

- 8004240319 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees "No action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180231 Forwards 1E Circular 80-07, "Problems W/HPCI Turbine 011 Sys "No written response required
 GRIER, B H Region 1, Philadelphia, Office of the Director
 80/04/03 1p
- 8004110054 Forwards IE Bulletin 80-07. "BWR Jet Pump Assembly Failure " Written response required
 GRIER.B H Region 1, Philadelphia, Office of the Director
 BO/04/04 ip
- 8004230433 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASRE GA-312, Type 304 Stainless Steel Pipe" Action required GRIER, B H. Region 1, Philadelphia, Office of the Director B0/04/04 ip
- 8004180201 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds" Writton response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/07 ip
- 6004140375 Requests relief from requirements of ASME Code Baction XI, requiring examination of Category B-L-2 reactor recirculation pump casings during each insp interval Relief would postpone examination until major maint on pump CDUNSIL.N O Northeast Nuclear Energy Co (subs of Northeast Utilities) 60/04/09 2pp
- R Periodic operating reports & related correspondence
- 8004040205 Forwards annual environ operating rept, "Monitoring Marine Environ of Long Island Sound " Requests rept be incorporated into proceedings for Unit 3 COUNSIL.W Q Northeast Utilities 80/03/30 ip
- --8004040206 "Monitoring Marine Environ of Long Island Sound," annual rept, 1979

 * Northeast Utilities 80/03/31 400gp
- 8004150327 "Annual Environ Operating Rept.1979 "
 * Northeast Utilitles Service Co 80/03/31 100pp
- 8004180383 Forwards monthly operating rept for Mar 1980 OPEKA, J. F. Northeast Nuclear Energy Co. (subs. of Northeast Utllities) 80/04/14 ip
- --8004180388 Monthly operating rept for Mar 1980
 HARRAN. O Northeast Nuclear Energy Co (subs of Northeast
 Utilitles) 80/04/03 7pp
- BO04210246 Forwards monthly operating rept for Mar 1980 OPEKA, J F Northeast Utilitles BO/04/14 ip
- --8004210249 Monthly operating rept for Mar 1980 HARRAN, 0 Northeast Utilitles 80/04/03
- B Reportable occurrences, LERs & related correspondence
- 8004090118 PND-I-80-043 on 800318, one truck full of chiorine rall tank car devailed at broken sultch on licensee property. Car presently located outside protected area; but is upright, intact, & stable Formulating plans to replace car on rail KEIMIG, R R, BRUNNER, E J Region 1, Philadelphia, Office of the Director 80/03/18 2pp
- 8004180437 Forwards updated LER 80-005/03X-1 OPEKA, J F Northeast Utilitles 80/04/10
- --8004i80440 Updated LER 80-005/03X-1 on B00220, core spray subsys declared inoperable Caused by water hammer due to seat leakage of core spray injection & check valves Pipe supports repaired & keep-fill sys modified, Valves to be reworked BIGIARELLI, M J Northeast Utilities 80/04/10 ip.
- 8004290299 Forwards LER 80-004/03L-0 OPEKA, J. F Northwest Utilities 80/04/21. 1p
- --8004290303 LER 80-006/03L-0 on 800407 during normal operation, pressure indicating switch that senses drywell pressure for automatic pressure relief sys logic initiation, found isolated Caused by personnel error Switch returned to svc BIGIARELLI, M J Northeast Utilities 80/04/21 2pp

- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8004020110 Advises of FES issuance re selection of preferred alternative closed-cycle cooling sys.NUREG-0574, Dec 1979 Future discussions re simplification of proceeding, appropriate LENTS, 8 H Hearing Branch 2 80/03/19 ip
- --B004020126 Summary of meeting w/PASNY re DES, selection of preferred closed cycle cooling sys & related issues NRC will draft stipulation for parties' comments GECKLER, R P Environmental Projects Branch 1 79/09/14 3pp
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8004180281 Addresses questions in 800214 memo on R Pollard allegations re facility SER Issue of containment isolation valves was previously addressed R Pollard input & final SER are substantially same SER excerpt encl DENTON.H R Office of Nuclear Reactor Regulation 80/04/03 9pp
- --8004180284 Responds to 770110 ltr re possibility of tornado damage & re-evaluation of containment isolation features of auxiliary steam lines Auxiliary steam supply & condensate return lines satisfy Criterion 57 of general design criteria BCHWENGER.A Operating Reactors Branch 1 78/09/27 7pp
- --8004180294 Submits questions about R Pollard allegation at 800205 commission meeting re SER inaccuracies & plants not meeting current regulations on containment isolation & environ qualification Transcript excerpt encl
 BRADFORD,P A Commission 80/02/14 9pp
- B004220462 Discusses B00326 itr re request to have UCB identify inaccuracies in plant SER in support of NRC review Requests info re purpose of request 5 findings of review Buggests procedure to identify SER discrepancies for Units 1 & 2 WEISS, E R Sheldon, Harmon & Weiss 80/04/17 2pp
- F Becurity, medical, emergency & fire protection plans
- 8004100100 Comments on proposed rule (OCFRSO 10-mile emergency planning rone for plume exposure lacks technical justification NRC adopted position w/o studying validity of underlying bases WEISB,E R Sheldon, Harmon & Weiss 60/02/17 5pp
- --B004100127 Statument before NY City Louncil, "Impact on NY City of Reactor Accidents at Indian Point," (corrected 790620)
 BEYEA, J. Princeton Univ. 19/06/20 49pp
- 8004080695 FOIA requestion behalf of UCS for time analysis required to evacuate public from 10-mile area surrounding facilities WEISBLE R Sheldon, Harmon & Weiss 80/03/20 1p
- B004080690 Responds to FOIA request for time analysis required to evacuate public from 10-mile area surrounding facilities Forwards rept. "Evacuation Times Estimates for Areas Near Bits" W/o encl FELTON.J M. Division of Rules and Records B0/03/31. Ip
- 8004220589 Forwards design details on control & turbine bldg fire walls & fires detectors for reactor coolant pumps Dasign details for reactor coolant pump oil collection sys will be provided by 800307 CAHILL.W J Consolidated Edison Co of New York 80/04/14 2pp
- O Adjudicatory correspondence
- 8004020091 Forwards UCS 800310 comments on director's decision under 10CFR2.206 Decision & confirmatory order do not resolve critical issues Objects to exclusion of petitioner from meetings & correspondence solving issues HEISS,E R Sheldon, Harmon & Weiss 80/03/10 2pp
- --B004020099 Comments on director's decision under 10CFR2 20A Decision & confirmatory order do not resolve crucial issues re site suitability & do not establish necessity schedule or stds of mods Urges disqualification of JM Hendrie W/documentation WEISB.E R Union of Concerned Scientists WEISB.E R Sheldon, Harmon & Weiss 80/03/10 43pp
- ---8004020105 Memorandum to counsel for parties disclosing previous involvement w/facility as member of ACRE & as Deputy Director for Technical Review Hill consider objections to participation if received prior to 771104 W/documentation HENDRIE, J M Commission 77/10/20 11pp

- --8004020109 Responds to 730717 ltr re siting criteria Facility site does not meet NRC regulations & criteria HENDRIE, J M Commission 73/09/10 3pp
- 8004070047 Order granting extension until 800414 for Commission to review director's 800211 decision HOYLE.J C Office of the Secretary of the Commission 80/03/31 ip
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSICK, L. V. Office of the Executive Director for Operations 80/04/02 34pp
- 8004190073 Order granting extension until 800425 for Commission to elect whether to review ALAD-436 & ALAD-561 CHILK.5 J Office of the Secretary of the Commission B0/04/04
- 8004240510 Forwards NRC confirmatory order
 STELLD,V Office of Inspection & Enforcement, Office of the
 Director 80/04/04 1p
- --8004240517 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800407 Required info specified in Attachment A BTELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 δρρ
- 8004220754 Forwards petition supporting UCS petition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 ORAVES R S Housatonic Safe Energy Alliance 80/04/13 ip
- --8004220762 Supports UCS potition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 GRAVES, R S Housatonic Safe Energy Alliance 80/02/15 ip
- BD04220030 Order granting extension until 800430 for Commission to review Director's 800211 decision
 HOVERUS C Office of the Sacretary of the Commission 80/04/14
- H General correspondence
- BOO4070200 FOIA request for info re facilities & damage due to earthquakes at Indian Point
 BEBAS:P Q Affiliation Unknown BO/02/10 1p
- 800403001A Advises that Commission should evaluate need for power generated by facility & take close look at safety achieved for public pratection GILINSKY, V Commission 80/03/11 ip
- --8004030018 Responds to 800225 ltr Forwards NY Times article re lack of need for electricity produced at facility Cites util trade association statement that reserve margin of 2% would exist if all plants in svc grid were shut down LEVINSON. J D Affiliation Unknown 80/03/02 2pp
- --8004030024 Responds to 800208 ltr supporting petition by UCS requesting decommissioning of Unit 1 & suspending operations of Units 2 & 3 Advises that Commission is reviewing comments on matter
 OILINSKY, V Commission 80/02/25 3pp
- --8004030025 Supports UCS 790917 petition requesting decommissioning of Unit 1 & suspension of operations at Units 2 & 3 Cites safety-related reasons for prompt action Certificate of Svc encl LEVINSON, J D Affiliation Unknown 80/02/08 3pp
- 800 4070174 Responds to FOIA request for info re facilities & damage due to earthquakes at Indian Point Forwards Documents 1-4 listed in App A Documents 5 & 6 may be purchased by sending check in amount of \$7 50 to NRC in Washington.D C. FELTON.J M Division of Rules and Records 80/03/17 2pp
- ---9004070205 "Bemiannual Operating Rept." Jul-Dec 1973 * Consplidated Edison Co of New York 73/12/31 20pp
- --800407020B "Semiannual Operating Rept," Jan-June 1974 * Consolidated Edison Co of New York 74/06/30 21pp
- ---8004070214 "Bemiannual Operating Rept," Jul-Dec 1974 * Consolidated Edison Co of New York 74/12/31 2ipp

- --8004070224 "Annual Operating Rept," 1975 * Consolidated Edison Co of New York 75/12/31 2200
- --8004070227 "Annual Operating Rept." 1976 * Consolidated Edison Co. of New York 76/12/31 2700
- --8004070233 "Annual Operating Rept," 1977 TMI semiannual & annual operating rept excerpts enci * Consolidated Edison Co of New York 77/12/31 45pp
- 8004270054 Forwards info requested in 800218 ltr re licensing actions Matl could not be forwarded by 800225 as ltr did not arrive at NRC until 800226 M/o arcls DENTON.H R Office of Nuclear Reactor Regulation 80/03/25 2pp
- -- B00429005B Requests info re changes affecting extension of DLs to FLEISHER, Z & Affiliation Unknown 80/02/18 1p
- 8004180234 Forwards NRC 800325 response to encl 800218 ltr from ZE Fleisher of West Branch Conservation Association, in response to 800226 request W/o encl DIRCKS, W J Office of the Executive Diroctor for Operations 80/03/28 ip
- --8004iB0237 Requests info re now safety regulations FLEISHER. Z S West Branch Conservation Association 80/02/18 ip
- 8004210336 Advises that 791106 ltr to President Carter re emergency plans has been referred to NRC Since Summer 1979, NRC has been actively pursuing program to upgrade emergency preparedness Forwards NRC/FEMA documentation W/o encl DENTON.H R D#fice of Nuclear Reactor Regulation BO/03 80/03/31 3nn
- 8004150085 Responds to 800228 itr re operation of nuclear power plants in high density areas NRC is investigating special measures to be taken in heavily populated areas Interim measures have already been ordered at sites

 DENTON, H R Office of Nuclear Reactor Regulation. 80/04/01 2pp
- ---8004150094 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident STERNER, J W Affil(ation Untrown 80/02/28 1p
- 8004160173 Responds to 800212 itr re continued operation of nuclear power plant Addi measures should be implemented that will further reduce probability of severe reactor accidents Licensee has been in shuddwin pending completion of actions DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2p
- --B004160176 Requests that NRC not phase out facility or convert to non-nuclear generators Nuclear power is source for power in US No nute political arguments have no bests in reality LAVERTY.E Affiliation Unknown B0/02/12 2pp
- 8004170342 Responds to 800206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility.confirming commitment to public health & safety DENTON.H R Office of Nuclear Reactor Regulation 80/04/01, 2pp
- 800421003B Responds to 800125 request re public hearing & determination on UCB petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or lessen consequences
 DENTON.HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210093 Requests scheduling of public hearing & determination of UCB petition re-operation of facility prior to reactivation Concerned for health & safety of community SCIANDRALJ New York.NY. 80/01/25 1p
- 8004210193 Responds to 800207 ltr re continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants interim measures have already been ordered at sites DENTON, HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210201 Supports continued operation of facility Reactors supply 20% of generating capacity for New York City & Westchester County Utils can shut off all plant, lowering rates & dependency on foreign oil.

 HU.J Affiliation Unknown 80/02/07, ip

- 800421020B Responds to 800204 ltr re continued operation of facility Plants reviewed to determine what addl measures or design changes can & should be implemented to further reduce probability of reactor accident or consequences DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- -8004210223 Urges NRC to decide in favor of continued operation of facility Reactors have long history of safe, clean & economic operation Concerned that fuel adjustment charges will increase if plants are shut down
 OAY RR Affiliation Unknown E0/02/04 ip
- 8004250013 Responds to 800212 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004250030 Urgss that NRC consider UCB petition re closing of facility Possibility of earthquake exists w/plant built near fault Only 20% of area energy generated by nuclear power Alternatives should be considered OULDHOR,F Affiliation Unknown E0/02/12 lp
- 8004290018 Responds to 800219 ltr re operation of facility NRC considering special measures to reduce probability of severe reactor accident or to lessen consequences Confirmatory orders issued as interim measure DENTON:H R Office of Nuclear Reactor Regulation, 80/04/01 2pp.
- --8004250033 Urges NRC to approve UCS petition re shutdown of facility because of proximity to New York City & impossibility of evacuation of so many people MDS.L L , MQS.H Affiliation Unknown 80/02/15 ip
- 8004230185 Advises that NRC held two meetings in NY re continuing operation at facility Commission presently considering form of review Public comments invited Request for another hearing in vicinity of plant will be considered DENTON, H R Office of Nuclear Reactor Regulation 80/04/03 ip
- --B004230190 Requests that MRC hold another public hearing re continuing operation of facility to offer public chance to question plant operators & govt agencies Public should be properly notified through local news media CONNOR.R J New York, State of B0/01/08 2pp.
- 8004280140 Responds to 800117 ltr to DOE re 800117 incident at facilities Plant did not trip during minor earthquake tremor Epicenter of tremor was located approx seven milas from sits Tremor was significantly below design capability EISENHUT.D 0 Division of Operating Reactors 80/04/08 is
- P Operating license stage documents & correspondence
- 8004070094 Forwards agenda & proposed rule for NRC eponsored 800115 meeting in New York, NY re-proposed rule on emergency response RYAN,R G Office of State Programs 79/12/31 12pp.
- --8004070098 Requests opportunity to testify at NRC 800115 meeting in New York, NY re emorgency response plans in fifty-mile zone around plant NY City Council has been holding hearings on resolution to phase out plant FRIEDLANDER, M New York, NY 79/12/21 ip.
- BOO41BO3B9 Forwards modified near-site study in response to NRC 791205 request for 40-day crash effort
 PEOPLEG.D L. Commonwealth Edison Co DAVIS.J.F Power Authority of the State of New York CAHILL.W.J Consolidated Edison Co of New York 80/02/25 ip
- --8004180375 "Near-Site Study " Viewgraphs encl.

 * Commonwealth Edison Co * Consolidated Edison Co

 * Power Authority of the State of New York. 80/02/2 of New York 80/02/25
- 8004020297 Forwards status rept on implementation of Lessons Learned Task Force short-term requirements Basis for judging acceptability of implementation of each item is requirement of NURGO-0578 4 HR Denton 791030 itr to operating plants TELFORD, J T Division of Safeguards 80/02/29 5pp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUI.D 0 Division of Operating Reactors. 80/03/12 5pp
- --8004030iiB "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/2i 28pp

- 8004140221 Summary of 800221 meeting w/representatives of all SEP plants, utils & Franklin Research Ctr re accelerated program for evaluating qualification of safety-related electrical equipment
 HILSON.R Plant Systems Branch 80/03/14 3pp
- 8004110045 FOIA request, on behalf of UCS, for Sandia Labs study re liquid effluent pathway at facility WEISS,E R Sheldon, Harmon & Weiss 80/03/18 1p
- 8004240163 Forwards add1 info & clarification re guide for evaluating environ qualification of Class IE electrical equipment in operating reactors & for identification of appropriate safety equipment of SEP reactors SCHWENCER. A Operating Reactors Branch 1 80/03/20 15pp
- --B004240175 Forwards addl info & clarification re guidelines for evaluating environ qualification of Class IE electrical equipment in operating reactors & for identification of appropriate safety equipment of SEP reactors SCHWENCER: A Operating Reactors Branch 1 80/03/20 15pp
- B004080410 Forwards answers to generic questions re turbine disc integrity in operating Mestinghouse nuclear low pressure turbines, in response to NRC B00228 ltr CAHILL:N J Consolidated Edison Co of New York B0/03/28 10pp
- 8004100167 Notification of 800403 meeting w/util in Bethesda.MD re environ qualification of electrical equipment CLSHAN.L N Operating Reactors Branch 1 80/03/31 Zpp
- B004080417 Forwards addl info re overpressure protection sys installed at facility, in response to NRC 800227 ltr
 CAHILL, W J Consolidated Edison Co of New York 80/04/02 4pp
- BOO411003B Responds to FOIA request for Sandia Labs study re liquid affluent pathway at facility Rept is undergoing NRC technical review prior to publication Draft encl FELTON.J M Division of Rules and Records SO/04/02 ip
- --8004110051 Draft study of facility liquid effluent pathway
 * Bandia Laboratories 80/04/02 B00pp
- 8004220117 Forwards request for info needed to continue NRC review of util 800311 ltr re control room habitability SCHWENCER, A Operating Reactors Branch 1 80/04/04 4pp
- 8004290158 Forwards initial request for addl info re upgraded program & procedural GA controls resulting from analysis of TMI-2 accident Response requested within 45 days after receipt of ltr SCHWENCER, A Operating Reactors Branch i 80/04/08 7pp
- BOO4240480 Forwards addl info re review of unresolved safety issues. trip rept of Lessons Learned implementation team. & task action plan in view of high population density surrounding plants.

 DENTON.H R Office of Nuclear Reactor Regulation 80/04/09 33pp
- --8004240486 Bummary of Hastinghouse Leasons Learned team 800124-25 site Visit re status of Category A implementation. Attendance & status lists encl
 TELFORD.JT Safeguards Standards Branch 80/02/20 5pp
- --8004240507 Forwards action plan developed in recognition of high population densities surrounding sites DENTON, H R. Office of Nuclear Reactor Regulation 80/02/21 80pp
- --8004240518 Discusses Event 5 probabilities Suggests continuous monitoring & readout capability of check valve position & periodic tests of leak rate measurements TAYLOR,M A Division of Reactor Safety Research 80/01/15 17pp
- 8004250232 Forwards status of unresolved safety issues at Indian Point 1 & 2, trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at facilities, task action plan & facility societal risk info DENTON, HR Office of Nuclear Reactor Regulation 80/04/09 34pp
- 8004240458 Formalizes plans re series of technology exchange meetings re facilities' accident mitigation features activity Five meetings suggested, Recommended meeting schedule & agenda items encl BCHMENCER, A Operating Reactors Branch 1 80/04/10 15pp

- 8004150433 Forwards summany of actions taken to comply w/NRC 800211 confirmatory order Detailed confirmatory documentation available at plant for review O'TOOLE, J D Consolidated Edison Co of New York 80/04/11 8pp
- 8004220627 Forwards response to NRC 800309 request for addl info re auxiliary feedwater sys reliability improvements CAHILL.W J Consolidated Edison Co of New York 80/04/14 7pp
- 8004240410 Ack receipt of NRC 800107 ltr re dissel generator fuel oil GA requirements Advises that fuel oil for standby diesel generators included in GA program CAHILL.W J Consolidated Edison Co of New York 80/04/14 ip
- BOO4280199 Responds to util 790720 proposed amend to Tech Specs re radiological effluent & environ monitoring sys Forwards comments & marked-up copy of Unit 2 Tech Specs for incorporation into proposed amend SCHWENCER.A Operating Reactors Branch 1 80/04/14 7pp
- --8004280204 Marked-up version of util 790731 App A Tech Specs re radiological effluent & environ monitoring sys * Office of Nuclear Reactor Regulation 80/04/14 125pp
- 8004300307 Forwards drawings & info re mods that provide addl assurance of safety & reliability of automatic transfer circuits & resolve concerns of UCS allegation Drawings available in Central Files only CAHILL, W J Consolidated Edison Co of New York 80/04/23 5pp
- 8004300429 Advisos that all necessary procedural revisions & operator retraining re replacement of certain Foxboro 600 transmitters will be completed on or before 800701 GAHILL N J Commonwealth Edison Co 80/04/23 2pp
- 8004300416 Forwards application for amend to License DPR-26, modifying Tech Specs to reduce min required RCS flow & revising limit for total nuclear peaking factor Certificate of Svc encl CAHILL, W J Commonwealth Edison Co 80/04/25 3pp
- --8004300419 Application for amond of License DPR-24, modifying Tech Spacs 2 1,3 10 ½ 3 3 to change min required RCS flow & to revise limit for total nuclear peaking factor CAMILL.W J Commonwealth Edison Co 80/04/25 2pp
- --8004300423 Tech Specs 2 1,3 10 & 3 3 for safety limits & limiting safety sug settings & control rod & power distribution limits Safety evaluation encl # Commonwealth Edison Co 80/04/25 66pp
- 8004300411 Forwards update to util 791016 ltr re degraded grid voltage & adequacy of station electric distribution sys voltages Computer studies, as modified by 800228 discussions w/NRC, encl CAHILL, W J Consolidated Edison Co of New York 80/04/29 19pp

- 8004090049 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 ip
- 8004110126 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 tp
- 8004240297 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180210 Forwards 1E Circular 80-07, "Problems W/MPC! Turbine Oil Sys "No written response required
 ORIER, B H Region 1. Philadelphia, Office of the Director
 BO/04/03 1p
- 8004230403 Forwards IE Bulletin 79-02A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required GRIER. B H Region 1, Philadelphia. Office of the Director 80/04/04 1p
- BOO41B0125 Forwards IE Bulletin BO-OB, "Exam of Containment Liner Penetration Welds "Written response required ORIER.B H Region 1. Philadelphia, Office of the Director BO/04/07 1p
- R Periodic operating reports & related correspondence
- 8004150599 Forwards "Environ Discharge Monitoring Rept for Mar 1980 "MONTI.W A Consolidated Edison Co of New York 80/04/10 1p
- --8004150609 "Environ Discharge Monitoring Rept for Mar 1780 "
 * Consolidated Edison Co of New York 80/04/10 15pp
- 8004210255 Forwards monthly operating rept for Mar 1980 CAHILL,W J Consolidated Edison Cg of New York 80/04/14 1p
- --8004210258 Monthly operating rept for Mar 1980 EICH,E Consolidated Edison Co of New York 80/04/04 7pp
- 8004210269 Forwards "Daily Counts from Intake Screens.Mar 1980." re fish collections Circulators were shut down for month at Unit 1 CAHILL, W. J. Consolidated Edison Co. of New York 80/04/15 ip
- --8004210276 "Daily Counts from Intake Screens, Mar 1980," re fish
- collections.
 * Consolidated Edison Co of New York 80/04/15 4pp
- S Reportable occurrences. LERs & related correspondence
- GOD4210440 PNO-77-172 on 770976 Units 2 & 3 tripped from 100 & 91% power, respectively Caused by spurious signals in reactor protection sys resulting from electrical disturbances in Buchanan substation State of Ny informed KLINGER O , NOLAN.F , SNIEZEK.J Region 1, Philadelphia, Office the Director 77/09/27 1p Region i, Philadelphia, Office of
- U. Congressional/Executive Correspondence
- 9004080193 Responds to 79:212 ltr re Rockland Mobilization for Survival ltr concerning Dec 1979 public meeting on emergency preparedness Pariod of public comment lasted until NRC participants had listened to all speakers DIRCKS, W.J. Office of the Executive Director for Operations, 80/03/05.
 - B0040B0206 Discusses 79121B public meating on emergency preparedness Plans should be arranged to allow ample time for public comment Viewpoints of citizens within facility vicinity appear to be unimportant to NRC BTERN,L D Rectland Hobilization for Survival 79/12/05 2pp
- 6004300292 Forwards Congressman Rosenthal 800114 ltr re concerns falling within FR 800222 notice requesting public views on proceeding issues DIRCKS.N.J Office of the Executive Director for Operations 80/04/11 ip

- --8004300299 Conveys concerns re safety & health risks posed by plants & lack of adequate evacuation plan Urges NRC to respond to UCB petition ROSENTHAL, B 8 House of Rep , Foreign Affairs 80/01/14 ip
- DOCKET 50-249 DREEDEN NUCLEAR POWER STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8004240531 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimilse traffic KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/03/20
- 8004030172 Forwards Figure 2-i to correct omission made in 800311 ltr re evacuation time estimates for facility Figure 3-1 in Section 3 should be placed in Section 2 PEOPLES.D L Commonwealth Edison Co 80/03/26 2pp
- 8004220299 Informs that Unit 3 refueling outage began 6 wks early S will end approx one month earlier than scheduled, due to failure in recirculation sys jet pump Completion of some fire protection mods will not be possible prior to startup PEOPLES,D L. Commonwealth Edison Co. 80/04/10 ip
- 8004230367 Forwards revised security plan Revisions withheld (ref 10CFR2 770) PEOPLES, D L Co Commonwealth Edison Co 80/04/21 1P
- 9 Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSBICKL V OFfice of the Executive Director for Operations
- P Operating license stage documents & correspondence
- 8004080296 Forwards corrected Pages 68 & 93 for Licenses DPR-19 Amend 44 & DPR-29 Amend 39 & corrected Pages 3 6/4 6-2 & 3 6/4 6-9 for licenses DPR-29 Amend 53 & DPR-30 Amend 50, in response to 791002 ltr
 IPPOLITO, T A Operating Reactors Branch 3 80/02/20 2pp
- --8004080310 Corrected License Pages 88 & 93 for Amends 44 & 39 to Licenses DPR-19 & DPR-25, respectively & corrected License Pages 3 6/4 6-2 & 3 6/4 6-9 for Amends 53 & 50 to Licenses DPR-29 & DPR-30, respectively * Operating Reactors Branch 3 80/02/20 8pp
- 8004030027 Submits info requested in 800201 ltr re seepage from plant cooling lake. No dike stability or integrity concerns have been identified No effect on health & safety of public increased surveillance will provide info to evaluate change PEOPLES.D L Commonwealth Edison Co 80/02/29 2pp
- 8004070381 Discusses NRC 761123 request that all LWR licensess assess higher fission gas release for fuel burnups above 20,000 MW-day per metric ton Responses indicate that no immediate licensing action is required for operating resctors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp.
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENNUT.D 0 Division of Operating Reactors 80/03/12. Spp.
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors, 80/02/21 28pp.
- B004i00i02 Requests controlled set of P&IDs for each plant Bubmittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER.J 0 Region 3. Chicago, Office of the Director. B0/03/20
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. GA program Revisions reflect recent organization title NAUGHTON, W.F. Commonwealth Edison Co. 80/04/02, 1p.
- --8004150328 Revised pages constituting Revision 13 to GA program. Revisions reflect recent organizational title changes # Commonwealth Edison Co CE-1-A R13 80/04/04 7pp.

- 8004290104 Forwards request for info re turbine disc cracking to be supplied on schedule that will allow review prior to startup from current refueling outage Assessment of potential for turbine missile damage should be provided IPPOLITO,T A Operating Reactors Branch 3 60/04/07 4pp
- BO04300599 Notification of 800416 meeting w/util in Bethesda.MD to discuss jet pump beam cracking HANNON,J N Operating Reactors Branch 3 80/04/07 1p
- BOO4140395 Advises that replacement of spring safety valves w/safety relief valves will not be necessary due to reclassification of pressurization transient frequency & add1 measures for prevention of premature valve actuation JANENCEK, R F Commonwealth Edison Co 80/04/08 2pp
- 8004180217 Forwards add1 info re failure of control rods to insert fully on scram in response to NRC 800110 & 11 ltrs Dresden 1 experienced no control rod failures in 1978-79 Failure at other facilities caused by leakage past worn piston seals JANECEK.R F Commonwealth Edison Co 80/04/14 10pp
- 8004180372 Forwards responses to questions raised in NRC 800407 ltr Responses include justification for startup & operation w/ultrasonic indications of water cutting in turbine disk Evaluating applicability of any turbine missile analyses PEOPLES, D L Commonwealth Edison Co 80/04/15 9pp
- 8004250427 Forwards response to NURCO-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lesaile County site-specific emergency plan PEOPLES.D L Commonwealth Edison Co 80/04/15 60pp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004290353 Outlines addl surveillance to be implemented per 800416 , meeting re recent jet pump failure Daily comparisons will be made of jet pump flow to respective recirculation pump speed & compared to expected values
 PEOPLEB.D L Commonwealth Edison Co 80/04/21 2pp
- Q Inspection reports, IE Bullatins & correspondence
- 8004070197 Forwards IE Insp Repts 50-010/79-23, 50-237/79-27 & 50-249/79-29 on 791009 & 1128 & notice of violation DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 60/02/12 2pp
- --8004070162 Notice of violation from insp on 791009 & 1128 * Region 3, Chicago, Office of the Director 80/01/31
- --8004070166 IE Insp Repts 50-010/79-23, 30-237/79-27, & 50-249/79-25 on 791009 & 1128 Noncompliance noted radioactive matl shipment record not utilized for radusate shipments made 790101-1128 QREGER, L R, FIBHER, W L. Region 3, Chicago, Office of the Director 80/01/31 7pp
- 8004040195 Forwards IE Insp Repts 50-010/80-01,50-237/80-01 & 50-249/80-01 on 800108-09 No noncompliance noted FIDRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Bupport Branch. 80/02/16 2pp
- --8004040197 IE Insp Repts 50-010/80-01,50-237/80-01 & 50-249/80-01 on 800108-09. No noncompliance noted Major areas inspected.

 emergency diesel generator mods & mod of electrical aduspment to IEEE-279 compliance HAVES,D W Region 3, Chicago, Reactor Construction & Engineering Support Brench HUOHES,J Region 3, Chicago, Office of the Director, 80/02/08 5pp
- 8004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted. DAVIB.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- ~~8004100408 Waste Packages Insp Rept 79-07A on 791212-13 No noncompliance noted Major area inspected compliance w/DOT & NRC regulations including shipping paper requirements, radiation levels & DOT labeling POTYER, J P. PEERY, K W. HOOROFF, R L. Region 3, Chicago, Fuel Facility & Materials Safety Branch, 80/02/22 opp
- 8004100426 Forwards IE Insp Repts 50-010/80-03,50-237/80-03 & 30-249/80-03 on 800107-0201 No noncompliance noted HEISHMAN,R.F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/26 2pp

- --8004100432 IE Insp Repts 50-010/80-03.50-237/80-03 & 50-249/80-03 on 800107-0201 No noncompliance noted Major areas inspected maint activities, plant operations, physical protection, eafety-related sys surveillance insp followup & refueling BARKER.JL, TUNOUE.TM, SPESSARD,RL Region 3, Chicago, Office of the Director 80/02/22 7pp
- B004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/07 is
- 8004100119 Ack receipt of 800304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-23, 50-237/79-27 & 50-249/79-25
 DAVIS, & B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/03/20 2pp
- --B004100128 Responds to NRC B00212 ltr re violations noted in IE Insp Repts 50-010/79-23.50-237/79-27 & 50-249/79-25 Corrective actions informed personnel re cost estimate change order requirements PEOPLES, D L Commonwealth Edison Co 80/03/04 3pp
- 8004140119 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II. Two-Inch Tray Adsorber Cells" Visual examination determined that contact between rasing & screen is adequate to prevent charcoal granule escape PEOPLES.D L. Commonwealth Edison Co. 80/03/20 5pp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/03/21 ip
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A, on 791212-13 No noncompliance noted DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 60/02/22 2pp
- --8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination & package external features POTTER, J P. PEERY, W W, WOODRUFF, R L. Rogion G, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- 8004300544 Forwards IE lnsp Repts 50-010/80-04,50-237/80-04 & 50-249/80-04 on 800220-22 & 26 & notice of violation DAVIG.A D Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/21 2pp
- ---8004300548 Notice of violation from insp on 800220-32 & 26 * Region 3. Chicago, Office of the Director 80/03/11 1p
- --8004300355 IE Insp Repts 50-010/80-04.50-237/80-04 & 50-249/80-04 on 800220-22 & 26 No noncompliance noted Major areas inspected internal audits, licenses coordination w/offsite support agencies & review of emergency drills ESSIO.Y H., OESTMANN.M J., MATSON.E Region 3. Chicago. Office of the Director 80/03/11 10pp
- 8004150159 Forwards IE Info Notice 80-12, 'Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/31 ip
- BOD4080696 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director B0/04/01
- 8004150014 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers" No specific action or response required KEPPLER, J. G Region G. Chicago, Office of the Director 80/04/02, in
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Qas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J. Q Region 3. Chicago, Office of the Director 80/04/02
- 8004220093 forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/02 to

- 8004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/03 Sys " No wr: KEPPLER, J Q
- 8004110025 Forwards IE Bulletin 80-07, "BNR Jet Pump Assembly Failure" Written response required
 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/07
- 8004230224 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASHE SA-312, Type 304 Stainless Steel Pipe" Action required MEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07
- 8004220069 Forwards IE Bulletin 80-08, "Eram of Containment Liner Penetration Welds " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/09
- 8004280628 Forwards revised Pages 3 & 5 & cmitted Page 4 to IE Insp Repts 50-010/80-09, 50-237/80-05, 50-249/80-05, 50-254/80-05 & 50-265/80-08 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/09 1p
- --8004280634 Revised Pages 3 & 5 & omitted Page 4 to IE Insp Repts 50-010/80-05.50-237/80-05.50-249/80-05.50-254/80-05 & 50-265/80-08 Region 2, Atlanta, Office of the Director 80/04/09 3pp
- R Periodic operating reports & related correspondence
- 8004140330 Forwards "Radwaste & Environ Monitoring Annual Rept 1979 " STEPHENSON, B B Commonwealth Edison Co 80/03/19 ip
- --8004140340 "Radwaste & Environ Monitoring Annual Rept 1979 " KOHL,K A , CHANDRASEKARAN Eberline Instrument Corp 80/0 91pp 80/03/31
- 6004150382 Forwards monthly operating repts for Mar 1 STEPHENSON, B B Commonwealth Edison Co 80/04/10
- --8004i50387 Monthly operating repts for Mar 1980 CleBZKiewicz. B Commonwealth Edison Co 80/04/01 23pp
- S Reportable occurrences. LERs & related correspondence
- 8004030110 PNG-III-80-051 on 800314, ultrasonic testing performed on D04030110 PND-111-80-051 on 800314 ultrasonic testing perfo 20 jet pump holddown beam assemblies at Unit 3 Pumps 2.5.7.11 & 20 beam indications ranged from greater than 6 mils to approx 20 mils Pump w/largest indication removed CHRISSOTIMOS, N. BARKER, J. L. SPESARD, R. L. Region 3, Chi Office of the Director 80/03/17 ipp
- 8004020309 Forwards LER 80-009/031-0 STEPHENSON.B B Commonwealth Edison Co 80/03/25
- -8004020310 LER 80-009/03L-0 on 800306, during refueling outage, while performing LPCI logic tests, injection valve MD 3-1501-22A failed to open Caused by loose wire on terminal block in MCC-38-7 due to stripped brass screw ZIRHAS,K R Commonwealth Edison Co 80/03/25 ip.
- BOO4020363 Forwards LER 90-00B/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/03/25 ip
- --B004020367 LER B0-00B/03L-0 on B00307, during refueling outage white performing temp switch calibr surveillance, three temp switches failed to trip per specs Caused by drift; excessive gap between actuator & switch plunger or dirty contacts.

 * Commonwealth Edison Co 80/03/25 2pp
- BOO4020332 Forwards LER 80-010/03L-0 STEPHENSON.B B Commonwealth Edison Co 80/03/26 Ip
- --8004020337 LER 80-010/031-0 on 800301, during shutdown, while performing SBLC relief valve setting test, relief valves RN 1105A & B actuated above Tech Specs at 1,525 psig & 1,520 psig, respectively, Caused by setpoint orift MAGROW, R. A. Commonwealth Edison Co. 80/03/26 1p.
- 8004080456 Forwards updated LER 79-030/03X-i 8TEPHENBON, B B Commonwealth Edison Co 80/03/26 ip

- ---8004080463 Updated LER 80-030/03X-; on 79:11:0, during scram testing in refuel mode, substantial loss of position indication noted for control rod draveline H-9 Caused by improperly seated socket, suggesting faulty electrical pin-socket alignment # Commonwealth Edison Co 80/03/26 ip
- 8004080552 Forwards LER 80-011/03L-0 STEPHENSON, D B Commonwealth Edison Co 80/03/28 1p
- -8004080561 LER 80-011/03L-0 on 800305, while conducting steam line area temp switch calibr surveillance, temp switch TS 3-261-178 bripped above Tech Specs Caused by dirt deposits on switch actuation plunger Switch cleaned, adjusted & tested SPERROFF, R Commonwealth Edison CO 80/03/28 lp.
- BO04210286 Forwards LER 80-012/03L-0 BTEPHENSON, B B Commonwealth Edison Co BO/04/09 1p
- --8004210288 LER 80-012/03L-O on 800313 during refueling fuel pool area radiation monitor (ARM) channels A & B & reactor bldg vent ARM channel A tripped above Tech Spec Caused by setpoints BADRAN, B Commonwealth Edison Co 80/04/09 ip
- 8004220693 Forwards LER 60-D15/01T-0 STEPHENSON, B B Commonwealth Edison Co 80/04/10 ip
- --8004220700 LER 80-015/01T-0 on B00402 during refueling reactor water cleanup mechanical snubber found fully retracted Caused by water hammer Remaining cleanup welds in weld penetrant tested Affected pipe section to be replaced before startup gPERROFF,R Commonwealth Edison Co. 80/04/14 5PP
- BOO4270422 Forwards LER 80-013/03L-0 6TEPHENSON, B B Commonwealth Edison Co BO/04/22 1p
- --8004270429 LER 80-013/03L-0 on 800328 during performance of LLRT on B feedwater outboard check valve 3-220-628 measured leakage recorded in excess of limit Caused by worn seat/disc assembly pins Assembly replaced & valve retested BUNBAR.J F Commonwealth Edison Co. 80/04/22 ip.
- DOCKET BO-250 TURKEY POINT PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- BOO4030271 Notifies that NRC review of util safeguards contingency plan complete Forwards comments indicating need for addl info Comments withheld (ref 10CFR2 790)
 SCHMENCER:A Operating Reactors Branch 1 80/03/10 2pp
- 8004070179 Summary of 800227 meeting w/util re emergency planning. OROTENHUIS:M Operating Reactors Branch 1 80/03/19 3pp
- ---8004070183 Notification of 800227 & 28 meeting w/FEMA & util in flomatead.FL re emergency planning Proposed agenda & press release enci RGE.J W Emergency Preparedness Tash Force 80/02/07. 4pp.
- BO04090275 Summary of BO0227 meeting w/util to discuss B00215 draft update of emergency plan for facilities Plan should be updated to comply w/NVREO-04554 by B00831 OROTENHUIB,M Operating Reactors Branch 1 B0/03/19, Opp
- --8004070277 Forwards proposed agenda & press release for 800227 meeting w/util to review emergency planning RDE, J W Emergency Preparedness Task Force, 80/02/07 4pp
- 8004290077 Forwards fire protection review of util design details, NRC positions re fire protection program & status table re resolution of incomplete items Response within 20 days requested

 SCHWENCER, A Operating Reactors Branch 1, 80/04/03 App
- --8004290081 "Staff Positions on Fire Protection Program." Status of resolution of incomplete items encl * Commission 80/04/03 14pp
- BOO4190519 Informs that response to NRC 800310 ltr re safeguards contingency plan will be sent by BOO618. Extension required due to complexity of matter & delays in coordinating response w/outside agency personnel.

 UHRIQ.R E Florida Power & Light Co BO/04/11 ip

G Adjudicatory correspondence

- 8004070051 Urder granting withdrawal of RA Marshall as counsel for intervenor in amends to OL proceeding re-steam generator repair
 - * Atomic Safety and Licensing Board Panel 80/03/06
- 8004080239 Mation to amend contentions re proposed amend to DL to permit steam generator repairs Questions safety of storage & other unrevisued safety matters Cartificate of Bvc & prof qualifications encl HARNAGE, H H . CHONIN, N Oncavage, Mark HARNAGE, H H Harnage, H H 80/03/11 28pp
- BOO4240086 Motion to amend Contention 1 to include Contention 18 Util application for DL amend involves mat! alteration of facility Alteration requires CP prior to issuance of amend CP requires preparation of EIS Certificate of Bvc enc! CNCAVAGE, M A Oncavage, Mark HARNAGE, H H Harnage, H H CHONIN, N Chonin, N 80/03/11 28pp
- 8004170330 Forwards util 800318 ltr re steam generator repair, in response to NRC 791119 ltr to intervenor Certificate of Svc encl COLLIN A Steel, Hector & Davis 80/03/21 4pp
- 8004240484 Response to intervenor motion to amend contentions Intervenor proposes to amend Contention is solely related to preparation of EIS, rather than add independent contention Contention i rendered moot W/Certificate of Svc REIS, HF Florida Power & Light Co REIS, HF Lowenstein, Newman, Reis, Axelrad & Toll 80/03/26 12pp
- 8004080656 Response in opposition to intervener 800311 motion sesking amend of admitted contentions EIS rs steam generator repair amend is being prepared Factors re nontimely fillings are not addressed in motion Certificate of Svc encl QOLDBERO, S C Hearing Branch 2 80/04/01 3pp
- BOD4110529 Forwards Mar 1980 "Bteam Generator Repair Rept." Revision 7 & util BO0328 transmittal ltr to DO Eisenhut re proposed amend to DLs to germit steam generator repairs by pipe cut approach Centificate of Svc encl REIB.H F. Lowenstein, Newman, Reis, Axelrad & Toll BO/04/01 3pp
- --8004110533 Forwards Mar 1980 "Bteam Generator Repair Rept," Revision 7 Major changes cover lower assembly removal, dose calculations, steam generator disposal & return to svc testing Affidavit encl UHRIG,R E Florida Power & Light Co 80/03/28 3pp
- --B004110536 "Steam Generator Repair Rept," Revision 7 * Florida Power & Light Co B0/03/31 111pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004080550 Requests temporary suspension of 800301 patition for leave to intervene, pending informal resolution of safety issues re time extensions between steam generator insps Provides list of terms & questions for NRC review GNCAVAGE, M.P. Oncavage, Mark 80/04/02 5pp
- 8004210128 Order dissmissing intervenor M Oncavage 800311 motion to amend contentions; as moot.NRC will issue EIS, re proposed steam generator repair, in compliance w/Commission 800304 order & as fulfilment of relief sought by intervenor.

 BOWERS, E. B. Atomic Sefety and Licensing Board Panel 80/04/09

H General correspondence

- 8004070423 Requests info re public meeting originally scheduled for 800108. Reiterates 790820 request to make statement re radioactive leeks Requests placement on meiling list 80HERA:L Affiliation Unknown. 80/03/17 ip
- I Financial information
- BOC4150406 Forwards Annual Financial Rept 1779
 UHRIO,R E Florida Fower & Light Co 80/04/08 ip
- --8004150411 Annual Financial Rept 1979 * Florida Power & Light Co. 80/02/09 72pp

J Insurance & indemnity information

- B004080281 Forwards Endorsement 43 to MAELU Policy MF-55 FIELDER.J Marsh & McLennan.Inc , M & M Nuclear Consultants.Inc Div 80/03/31 3pp
- 8004280449 Forwards Endorsement 52 to NELIA Policy NF-185 FIELDER: J. Marsh & McLennan. Inc., M & M Nuclear Consultants, Inc Div 80/04/21 ip
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Link Spets," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- --8004030i18 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- BOO4090166 Forwards Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability SCHWENGER, A Operating Reactors Granch 1 80/03/12 2pp
- --8004090169 Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively, increasing min low-low generator water level reactor trip point from 5% to 15% of narrow range instrument scale SCHMENCER.A Operating Reactors Branch 1 80/03/12 App
- --8004090170 Bafety evaluation supporting Amends 53 & 45 to Licenses
 DPR-31 & DPR-41, respectively
 # Office of Nuclear Reactor Regulation 80/03/12 2pp
- ---BO04070174 Notice of issuance & availability of Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively SCHWENCER, A Operating Reactors Branch 1 80/03/12 2pp
- 8004040179 Forwards Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively, safety evaluation & notice of issuance & availability BCHWENCER, A Operating Reactors Branch 2 80/03/13 2pp
- ---B0040401B3 Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively, incorporating results of revised ECCS analysis for steam generator tube plugging level of 22% SCHMENCER, A Operating Reactors Branch 2 80/03/13 9pp
- --8004040187 Safety evaluation supporting Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively * Office of Nuclear Reactor Regulation 80/03/13 6pp
- ---8004040170 Notice of issuance & availability of Amends 54 & 44 to Licenses DPR-31 & DPR-41 respectively SCHWENCER.A Operating Reactors Branch 1 80/03/13 2pp
- 8004110093 Bummary of 800304 meetings w/util & Westinghouse in Bethesda.MD re steam generator insp & plugging program GROTENHUI8.M Operating Reactors Branch 1 80/03/13 17pp
- 8004140120 Summary of 800304 meeting w/util % Westinghouse re steam generator insp & plugging program Util presented scheduling considerations & technical basis for operation until 800501 GROTENHUIG.M Operating Reactors Branch 1 80/03/13 20pp
- 8004240251 Forwards Amends 55 & 47 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availabilty SCHMENGER, A Operating Reactors Branch 1 80/03/14 2pp
- --8004240263 Amends 55 & 47 to Licenses DPR-31 & DPR-41, respectively, incorporating new limiting conditions for operation & murveillance requirements re low temp reactor vossel overpressure protection sys installed in both units SCHWENGER.A Operating Reactors Branch 1 80/03/14 14pp
- --8004240276 Bafety evaluation supporting Amends 55 & 47 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation 80/03/14 14pp
- --8004240283 Notice of issuance & availability of Amends 55 & 47 to Licenses DPR-31 & DPR-41, respectively BCHWENCER, A Operating Reactors Branch 1 80/03/14 2pp

- 8004100269 Forwards Amends 36 to 48 to Licenses DPR-31 & DPR-41 respectively safety evaluation & notice of issuance & availability SCHWENCER.A Operating Reactors Branch 1 80/03/21 2pp
- --8004100275 Amends 55 & 48 to Licenses DPR-31 & DPR-41 respectively, revising reactor coolant pressure-temp limits to account for neutron irradiation induced increases in reactor vessel mil ductility temp
 SCHWENCER.A Operating Reactors Dranch 1 80/03/21 9pp
- ---8004100281 Safety evaluation supporting Amends 55 & 48 to Licenses

 OPR-31 & DPR-41 respectively

 * Office of Nuclear Reactor Regulation 80/03/21 3pp
- --8004100284 Notice of issuance & availability of Amends 56 & 48 to Licenses DPR-31 & DPR-41 respectively BCHHENCER.A Operating Reactors Branch I 80/03/21 2pp
- 8004010210 Forwards "Steam Generator Repair Rept," Revision 7 re lower assembly removal dose calculations, steam generator disposal & return to svc testing UHRIO.R E Fiorida Power & Light Co 80/03/28 Jpp
- --8004010214 "Steam Generator Repair Rept," Revision 7 * Florida Power & Light Co 80/03/31 150pp
- 8004030289 Responds to NRC 800320 ltr re implementation of short-term Lessons Learned requirements Bupplemental info re direct indication of valve position.subcooling meter.containment isolation & plant shielding review encl UHR10.R E Florida Power & Light Co 80/03/28 jipp
- 8004080452 Provides response to NUREC-0578, short-term requirements re subcooled margin, plant shielding review & technical support ctr data display Detailed info on ability of digital data processing sys to supply subcooling data encl UHRIO.R E Florida Power & Light Co 80/04/04 6pp
- 8004280062 Forwards evaluation of licensee compliance w/Category A of NRC recommendations resulting from TMI-2 Lessons Learned Util has satisfied all Category A requirements Attendee list for NRC 800117-18 site visit enci SCHWENCER, A Operating Reactors Branch 1 80/04/07 15pp
- 8004280177 Approves one-month extension of 1979-80 licensed operator requalification program

 COLLINS.P F Operator Licensing Branch 80/04/08 1p
- 8004280247 Responds to NRC 800410 itr requesting that info re use of NUKEM 750 be provided by 800530 Technical basis for use of NUKEM 750 as qualified caulk requested from Ameron Info will not be available by 800530 Submittal expected 800730 UHRIGAR E Florida Power & Light Co 80/04/22 ip
- Q Inspection reports. IE Bulletins & correspondence
- 8004090344 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/04
- BO04040003 Responds to NRC ltr re violations noted in IE lnsp Repts 50-250/79-37 & 50-251/79-37 Corrective actions testing will be incorporated into security plan w/security supervisor taking responsibility UHRIGAR E Florida Power & Light Co 80/02/19 ip
- 8004100195 Forwards IE Insp Repts 50-250/80-02 & 50-251/80-02 on 800118-21 No noncompliance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/20 2pp
- --8004100202 IE Insp Repts 50-250/80-02 & 50-251/80-02 on 800118-21 No noncompliance noted Major areas inspected.engineered safeguards & emergency power sys integrated testing UPRIGHT, C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch BROUKS,E H Region 2. Atlanta, Office of the Director 80/02/18 Gpp
- 8004230009 Forwards IE lasp Repts 50-250/80-05 & 90-251/80-05 on 800205-07. No noncompliance noted . BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/22 2pp.

- ---8004230026 IE Insp Repts 50-250/80-05 & 50-251/80-05 on 800205-07 No 104250026 IE Insp Repts 50-250740-05 & 20-251740-05 on Bould of Montroppliance noted Major areas inspected pipe support baseplates & safety-related piping sys per IE Bulletins 79-02 & 79-14, respectively HERDI.A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch ANO.W P Region 2, Atlanta, Office of the Director BO/02/20 App
- 8004230026 IE Insp Repts 50-250/80-05 & 50-251/80-05 on 800205-07 No noncompliance noted Major areas inspected pipe support baseplates & safety-related piping sys per IE Bulletins 79-02 & 79-14, respectively MERDIA R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/20 4pp
- BO04020279 Summary of telcon w/Westinghouse & Fi. Power & Light returbine rotor insp Insp revealed one crack in low pressure rotors Data is in part proprietary & will be transmitted separately Insp still in progress GROTENHUIS. M Operating Reactors Branch 1 80/03/12. 3pp
- 8004280115 Forwards 1E Insp Repts 50-250/80-06 & 50-251/80-06 on 800204-07 No noncompliance noted LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branth 80/03/12 2pp
- --8004280125 IE Insp Repts 50-250/80-06 & 50-251/80-06 on 800204-07 No 104280125 lt Insp Rapts 30-230700-02 & 30-231700-06 bn 200204-07 No noncompliance noted Mayor areas inspected areas an areas of small breat loss of coolant procedures & training MARTIN.R D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch JOHNSON,A H, WEDSTER,E H. Region 2, Atlanta, Office of the Director 80/03/12 7pp
- 8004040328 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-39 & 50-251/79-39 7-37 P. Region 2, Atlanta, Fuel Facility & Materials Bafety 80/03/13 ip
- ---8004040347 Responds to NRC 800128 ltr re violations noted in IE Insp Repts 50-250/79-39 & 50-251/79-39 Corrective actions new procedures & revisions implementing subsections will be reviewed & approved prior to issuance for use UHRIO,R E Florida Power & Light Co 80/02/19 2pp
- --8004040351 Forwards IE Insp Repts 50-250/79-39 & 50-251/79-39 on 791219-21 & notice of violation STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 60/01/28 2pp
- --8004040340 Notice of violation from insp on 791219-21 * Region 2, Atlanta, Office of the Director 80/0
- --8004040365 IE Insp Repts 50-280/79-37 & 50-251/79-39 on 791219-21 Noncompliance noted deficiency in approval of procedures re implementation of ETS CUNNINOHAM.A L. Region 2. Atlanta. Office of the Director JENKINS.O R. Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/01/25 4pp
- 8004100187 Summary of 780304 meeting w/util & Westinghouse in Bethesda, MD rs steam generator insp & plugging program GROTENHUIS,M Operating Reactors Branch 1 80/03/13 17pp
- 8004080010 Ack receipt of 800307 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-250/79-40 & 50-251/79-40 STCHR.J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/03/19 ip
- ---8004080015 Responds to NRC 800201 ltr re violations noted in IE Insp Repts 30-250/79-40 & 50-251/79-40 Corrective actions.marking procedures for steam generator heads have been changed to require monitoring UHRIO.R E Florida Power & Light Co 80/03/07 App
- --8004080023 Advises that response to 800201 ltr requesting corrective actions to violations noted in IE Insp Repts 50-250/79-40 & 50-251/79-40 will be complete by 800307 UHRIO,R E Fiorida Power & Light Co. 80/02/27 ip
- --B004080027 Forwards IE Insp Repts 50-250/79-40 & 50-251/79-40 on 791217-20 & notice of violation STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/01 2pp
- --8004080030 Notice of violation from insp on 791217-20
 * Region 2, Atlanta, Office of the Director 80/02/01 ip

- --8004080038 IE Insp Repts 50-250/79-40 & 50-251/79-40 on 791217-20 Noncompliance noted failure to follow procedures re marking defective steam generator tubes & failure to have adequate procedures for marking defective tubes OIDSON.A F. WRAY.J R Region 2. Atlanta. Office of the Director 80/02/01 7pp
- 8004240030 Forwards response to IE Bulletin 80-03. "Luss of Charcoal from 8td Type II. Two-Inch,Tray Adsorber Cells " Adsorber cells used in affected sys do not employ screen rivets Possibility of charcoal loss as described does not exist UHRIG.R E Florida Power & Light Co 80/03/26 2pp
- B004150517 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 2pp
- 8004080619 Forwards IE Circular 80-05, "Emorgancy Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01 2pp
- 8004150001 Farwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/04/02 20n
- 8004240260 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/02 2pp
- 8004240371 Ack receipt of 800321 ltr informing NRC of steps taken to correct violation noted in IE lnsp Repts 50-250/80-03 & 50-251/80-03 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip
- --8004240378 Responds to NRC 800225 ltr re violation noted in IE Insp Repts 50-250/80-03 & 50-251/80-03 Corrective actions fire protection QA program will be implemented by 800731 UHRIO,R E Florida Power & Light Co 80/03/21 2pp
- --8004240383 Forwards IE Insp Repts 50-250/80-03 & 50-251/80-03 on 800107-11 & notice of deviation LEMIS.R C Region D. Atlanta, Reactor Operations Nuclear Support Branch 80/02/25 2pp
- --8004240387 Notice of deviation from insp on 800107-11 * Region 2, Atlanta, Office of the Director 80/02/20 1p
- --8004240390 [E Insp Repts 50-250/80-03 & 50-251/80-03 on 800107-11.

 Noncompliance noted failure to implement fire protection QA program.

 MARTIN,R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch ELROD, B A Region 2. Atlanta, Office of the Director 80/02/20. App
- 8004180321 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Oil Bys." No written response réquired O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 200
- 8004230165 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04 ip
- 8004180417 Forwards IE Bulistin 80-08. "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, UP Region 2. Atlanta, Office of the Director 80/04/07 2pp
- 8004300583 Updates 800304 response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Info re Item 7 a will be forwarded by 800401 Info re Item 7 b will be forwarded by 800701
 UHRIO,R.E Fiorida Power & Light Co 80/04/08 ip
- R Periodic operating reports & related correspondence
- 8004240348 Forwards monthly operating repts for Mar 1978 SCHMIDT, A D. Florida Power & Light Co 78/04/07 ip

- --8004240374 Monthly operating repts for Mar 1978
 CHILBON, V T Florida Power & Light Co 78/04/06 13pt
- 8004240448 Forwards monthly operating repts for Apr 1978 8CHMIDT, A D Florida Power & Light Co 78/05/06 ip
- --B004240452 Monthly operating repts for Apr 1978 CHILSON,V T Florida Power & Light Co 78/05/06 9pp
- 8004240350 Forwards monthly operating repts for May 1978 8CHMIDT, A D Florida Power & Light Co 78/06/03 1p
- --8004240356 Monthly operating repts for May 1978
 CHILBON, V T Florida Power & Light Co 78/06/03 13pp
- 8004240470 Forwards monthly operating repts for June 1778 SCHMIDT, A D Florida Power & Light Co 78/07/01 ip
- --8004240474 Monthly operating repts for June 1978 CHILBON, V T Florida Power & Light Co : 78/07/01 14pp
- 8004240455 Forwards monthly operating repts for Jul 1978 8CMMIDT, A D Florida Power & Light Co 78/08/10 1p
- --8004240459 Monthly operating repts for Jul 1978, CHILSON, V T Florida Power & Light Co 78/08/10 12pp
- 8004240359 Forwards monthly operating repts for Aug 1978 6CHMIDT, A D Florida Power & Light Co 78/09/04 ip
- --8004240363 Monthly operating repts for Aug 1978 CHILBON, V T Florida Power & Light Co 78/09/04 13pp
- 8004240443 Forwards monthly operating repts for Sept 1978 SCHMIDT, A D Florida Power & Light Co 78/10/07 1p
- --8004240444 Monthly operating repts for Sept 1978
 CHILBON, V T Florida Power & Light Co 78/10/07 13pp
- 8004240463 Forwards monthly operating repts for Oct 1978 8CHMIDT, A D Florida Power & Light Co 78/11/04 1p
- --8004240464 Monthly operating repls for Oct 1978 CHILSON, V T Florida Power & Light Co 78/11/04 15pp
- 8004240436 Ferwards monthly operating rapts for Nov 1970 BCHMIDT, A D Florida Power & Light Co 78/12/06 ip
- --8004240440 Monthly operating repts for Nov 1978 CHIL80N,V T Florida Power & Light Co 78/12/06 14pp
- 800424041B Forwards monthly operating repts for Dec 1978 8CHMIDT, A D Florida Power & Light Co 79/01/06 ip
- --8004240422 Monthly operating repts for Dec 1978 CHILSON, V T Florida Power & Light Co 79/01/06 15
- CHILSON, V T Florida Power & Light Co 79/01/06 15pp
- 8004230330 Forwards monthly operating repts for May 1977 SCHMIDT, A D Florida Power & Light Co 79/06/09 1p
- --8004230332 Monthly operating repts for May 1979 CHILBON, V T. Florida Power & Light Co 79/06/09 12pp
- 8004230484 Forwards monthly operating repts for June 1979 SCHMIDT, A D Florida Power & Light Co 79/07/07 1p
- --8004230490 Monthly operating repts for June 1979 CHILSON, V T Florida Power & Light Co 79/07/07 11pp
- BOO4230321 Forwards monthly operating repts for Jul 1979 BCHMIDT, A D Florida Power & Light Co 79/08/04 1p
- --8004230326 Monthly operating repts for Jul 1979 CHILBON, V T Florida Power & Light Co 79/08/04 13pp
- 8004180524 Forwards monthly operating rapts for Jan 1980 8CHMIDT A D Florida Power & Light Co 80/02/09 1p
- --8004180528 Monthly operating repts for Jan 1980 CHILBON, V T Florida Power & Light Co 80/02/09 3pp

- 8004180527 Forwards monthly operating repts for Feb 1780 SCHMIDT, A D Florida Power & Light Co 80/03/08 1p
- ~-8004180530 Monthly operating repts for Feb 1980 CHILBON.V T Florida Power & Light Co. 80/03/08 3pp
- 8004040380 Forwards "Semiannual Groundwater Monitoring Program Summary Rept" & "Annual Nonradiological Environ Monitoring Rept. 1979 " UHRIG.R E Floride Power & Light Co 80/03/31 1p
- ---B0040403B7 "Semiannual Groundwater Monitoring Program Summary Rept."
 for period ending Jul 1979 Twenty-one oversize drawings &
 graphs encl
 * Dames & Moore 79/07/31 140no Dames & Moore 79/07/31 14000
- --8004040397 "Annual Nonradiological Environ Monitoring Rept.1979 "
 Florida Power & Light Co 79/12/31 &000pp
- BOO4180373 Forwards monthly operating repts for Mar 1780 SCHMIDT. A D Florida Power & Light Co 60/04/05 tp
- --B004180374 Monthly operating repts for Mar 1980 CHILGON, V T Fiorida Power & Light Co 80/04/05 9pp.
- 8 Reportable occurrences, LERs & releted correspondence
- 8004030249 Forwards LER 80-004/03L-0 SCHMIDT, A D Florida Power & Light Co 80/03/26 ip
- --9004030256 LER 80-004/03L-0 on B00225, operator detected radiator tube leak on emergency diesel generator A Probably caused by foreign object being forced into radiator by cooling fame Leak repaired w/epoxy patch & new radiator cores ordered BCKOPPMANN, M A Florida Power & Light Co £00/03/26 2pp
- 8004080601 Forwards LER 90-005/03L-0 80HMIDT.A D Florida Power & Light Co 80/03/31 1p
- --8004080408 LER 80-009/03L-0 on 800229 during review of Maint Procedure 15937 2, fire hose station found not fully operable Caused by misunderstanding of what constitutes operability & failure of administrative controls Procedure will be revised SCHOPPMANN M A Florida Power & Light Co 80/03/31 2pp
- B004240309 Forwards LER 80-004/03L-0 BCHMIDT: A D Florida Power & Light Co B0/04/15 ip.
- --8004240317 LER 80-006/03L-0 on 800316.during review of MF 19537 2.four post indicator valves in fire protection water sys found not inspected within time interval limit Caused by misunderstanding of responsibility SCHOPPMANN.M A Florida Power & Light Co 80/04/15 2pp
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4
- F. Security, medical, emergency & fire protection plans
- 8004030271 Notifies that NRC review of util safeguards contingency plan complete Forwards comments indicating need for addl info Comments withheld (ref 10CFR2 770) SCHWENCER.A Operating Reactors Branch 1 80/03/10 2pp
- 04070179 Summary of 800227 meeting w/util re emergency planning PROTENHUIS: M Operating Reactors Stanch 1 80/09/19, 300
- -8004070183 Notification of 800227 & 28 meeting u/FEHA & util in Homestead/FC re emergency planning. Proposed agenda & prass release enci ROE-J W Emergency Preparedness Task Force 80/02/07 4pp Emergency Preparedness Task Force 80/02/07 4pp
- 8004090275 Summary of 800227 meeting w/util to discuss 800215 draft update of emergency plan for facilities Plan should be updated to compig w/NUREG-0654 by 80053: GROTENHUIS.M Operating Reactors Branch t 80/03/19 3pp
- ~~8004090277 Forwards proposed agenda & press release for 800227 meeting w/util to review emergency planning.

 RDE: J W Emergency Preparedness Task Force 80/02/07 4pp
- 8004290077 Forwards fire protection review of util design details, NRC positions re fire protection program & status table re resolution of incomplete items Response within 20 days

requested
SCHMENCER: A Operating Reactors Branch 1. 80/04/03 6pp

- ---B004290081 "Staff Positions on Fire Protection Program " Status of resolution of incomplete items and the Commission 80/04/03 14pp
- B004150919 Informs that response to NRC B00310 ltr re safeguards contingency plan will be sent by 800618 Extension required due to complexity of matter & delays in coordinating response w/outside agency personnel UHRIG.R E Florida Power & Light Co 80/04/11 ip
- G Adjudicatory correspondence
- 8004070051 Order granting withdrawal of RA Harshall as counsel for intervenor in amends to OL proceeding re steam generator Atomic Safetu and Licensing Board Panel 80/03/06 ip
- 8004080239 Motion to amend contentions re proposed amend to DL to permit steam generator repairs Questions safety of storage & other unreviewed safety matters Certificate of Evc & prof qualifications encl HARNAGE: H H. CHONIN, N Oncavage, Mark HARNAGE: H H Harnage, H H 80/03/11 28pp
- 8004240086 Motion to amend Contention 1 to include Contention 18 Util application for QL amend involves math alteration of factifity Alteration requires CP prior to issuance of amend CP requires preparation of EIS Certificate of Svc encl ONCAVADE.M A Oncavape.Mark HARNAGE.H H Harnage,H H CHONIN,N Chomin,N 60/03/11 28pp
- 8004170330 Forwards util 800318 ltr re steam generator repair in response to NRC 791119 ltr to intervenor Certificate of Byc encl CDLL, N A Steel, Hector & Davis 80/03/21 4pp
- 8004240484 Response to intervenor motion to amend contentions intervenor proposes to amend Contention 1, solely related to preparation of EIS rather than add independent contention Contention 1 rendered most W/Certificate of Svc REIS.H F Florida Power & Light Co REIS.H F Lowenstein, Newman, Reis. Azelrad & Toll 80/03/26 12pp
- B004080696 Response in opposition to intervenor B00311 motion seaking amend of admitted contentions EIB re-steam generator repair amend, is being prepared Factors re-nontimely filings are not addressed in motion Certificate of Buc entl QULDBERG,8 C Hearing Branch 2 80/04/01 3pp
- BOO4110529 Forwards Mar 1980 "Steam Generator Repair Rept." Revision 7 & util 800328 transmittal ltr to DO Eisenhut re proposed amend to DLs to permit steam generator repairs by pipe cut approach Certificate of Svc encl
- --8004110533 Forwards Har 1980 "Steam Generator Repair Rept," Revision 7
 Major changes cover lower assembly removal, dose
 calculations, steam generator disposal & return to svc
 testing Affidavit encl
 UHRIO,R E Florida Power & Light Co 80/03/28 3pp.
- --8004110536 "Btoam Generator Repair Rept." Revision 7 # Floride Power & Light Co 80/03/31, 111pp
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSBICKI, V Office of the Executive Director for Operations, 80/04/02 34pp
- 8004080390 Requests temporary suspension of 800301 petition for leave to intervene, pending informal resolution of safety issues retime extensions between steam generator insps. Provides list of terms & questions for NRC review.

 ONCAVAGE, H.P. Oncavage, Mark 80/04/02 3pp
- 8004210128 Order dissmissing intervenor M Oncavage 800311 motion to amend contentions, as most NRC will issue EIB, re proposed steam generator repair, in compliance w/Commission 800304 order & as fulfilment of relief sought by intervenor BDWERB, E 8 Atomic Bafety and Licensing Board Panel. 80/04/07
- H. Osneval correspondence
- 8004070423 Requests info re public meeting originally scheduled for B00108 Reiterates 790820 request to make statement re radioactive leaks Requests placement on mailing list BCHERAL Affiliation Unknown B0/03/17 ip.

I Financial information

- 8004150406 Forwards Annual Financial Rept 1979
 UHRIG.R E Florida Power & Light Co 80/04/08 ip
- --8004i5041i Annual Financial Rept 1979 * Florida Power & Light Co 80/02/08 72pp

J Insurance & indemnity information

- 800408028: Forwards Endorsement 43 to MAELU Policy MF-55 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/03/31 3pp
- 8004280449 Forwards Endorsement 52 to NELIA Policy NF-185 FIELDER.J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/04/21 1p
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D O Division of Operating Reactors 80/03/12 3pp
- --8004030i18 "Nuclear Data Link Specs"
 * Division of Operating Reactors 80/02/21 28pp
- 8004090166 Forwards Amends S3 & 45 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability SCHMENCER, A Operating Reactors Branch 1 80/03/12 2pp
- --9004090169 Amends 53 & 45 to Licenses DPR-31 & DPR-41.respectively, increasing min low-low generator water level reactor trip point from 5% to 15% of narrow range instrument scale SCHWENCER.A Operating Reactors Branch 1 80/03/12 App
- --8004090170 Bafety evaluation supporting Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation 80/03/12 2pp
- --8004090174 Notice of issuance & availability of Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively GCHWENCER, A Operating Reactors Branch 1 80/03/12 2pp
- 8004040179 Forwards Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively, safety evaluation & notice of issuance & availability SCHMENGER, A Operating Reactors Branch 2 80/03/13 2pp
- SCHWENCER, A Operating Reactors Branch 2 80/03/13 2pp
- ---8004040183 Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively, incorporating results of revised ECC8 analysis for steam generator tube plugging level of 22% BCHWENGER.A Decreting Reactors Branch 2 80/03/13 9pp
- --8004040187 Bafety evaluation supporting Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively * Office of Nuclear Reactor Regulation 80/03/13 épp
- --B004040190 Notice of issuance & availability of Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively BCHNENCER: A Operating Reactors Branch 1 80/03/13 2pp
- B004ii0093 Summary of B00304 meetings w/util & Westinghouse in Bethesda.MD re steam generator insp & plugging program GROTENHUIS:M Operating Reactors Branch i 80/03/13. 17pp
- BO04240251 Forwards Amends 55 & 47 to Licenses DPR-31 & DPR-41. respectively safety evaluation & notice of issuance & availability BCHWENGER.A Operating Reactors Branch 1 80/03/14 2pp
- --8004240263 Amends 55 & 47 to Licenses DPR-91 & DPR-41, respectively, incorporating new limiting conditions for operation & surveillance requirements re low temp reactor vessel overpressure protection sys installed in both units SCHHENCER.A Operating Reactors Branch 1 80/03/14 14pp
- --8004240276 Bafsty evaluation supporting Amends 55 & 47 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation 80/03/14, 14pp

- --8004240283 Notice of issuance & availabilty of Amends 55 & 47 to Licenses DPR-01 & DPR-41.respectively SCHMENCER.A Operating Reactors Branch 1 80/03/14 2pp
- 8004100268 Forwards Amends 56 & 48 to Licenses DPR-31 & DPR-41 respectively, safety evaluation & notice of issuance b availability SCHWENCER. A Operating Reactors Branch 1 80/03/21 2pp
- --8004100275 Amends 56 & 48 to Licenses DPR-31 & DPR-41 respectively, revising reactor coolant pressure-temp limits to account for neutron irradiation induced increases in reactor vessel nil ductility temp

 8CHWENCER.A Operating Reactors Branch 1 80/03/21 9pp
- ---80041002B1 Safety evaluation supporting Amends 56 & 48 to Licenses DPR-31 & DPR-41 respectively * Office of Nuclear Reactor Regulation 80/03/21 3pp
- --8004100284 Notice of issuance t availability of Amends 56 & 48 to Licenses DPR-31 t DPR-41 respectively SCHWENCER. A Operating Reactors Branch 1 60/03/21 2pp
- 8004100498 Forwards Amend 49 to License DPR-41, safety evaluation & notice of issuance & availability
 SCHWENCER, A Operating Reactors Branch 1 80/03/21 3pp
- --8004100467 Amend 49 to License DPR-41, revising Tech Specs to permit continued operation for one month more than authorized by Amend 44

 BCHMENCER, A Operating Reactors Branch 1 80/03/21 Spp
- --8004100473 Safety evaluation supporting Amend 49 to License DPR-41 * Office of Nuclear Reactor Regulation 80/03/21 3pp
- ---B004100475 Notice of issuance & availability of Amend 49 to License DPR-41 SCHMENCER, A Operating Reactors Branch 1 B0/03/21 2pp
- 8004010210 Forwards "Steam Generator Repair Rept," Revision 7 re lower assembly removal dose calculations, steam generator disposal & return to svc testing UHRIG:R E Florida Power & Light Co 80/03/28 3pp
- --8004010214 "Steam Generator Repair Rept," Revision 7
 * Florida Power & Light Co 80/03/31 150pp
- 8004030289 Responds to NRC 800320 ltr rs implementation of short-term Lessons Learned requirements Supplemental info re direct indication of valve position, subcooling meter, containment isolation & plant shielding review encl
 UHRIO.R E Florida Power & Light Co 80/03/28 lipp
- BOO4080452 Provides response to NUREG-0578, short-term requirements re subcooled margin, plant shielding review & technical support ctr data display Detailed info on ability of digital data processing sys to supply subcooling data encl UHRIG.R E Florida Power & Light Co BO/04/04 App
- B004280042 Forwards evaluation of licensee compliance w/Category A of NRC recommendations resulting from TMI-2 Lessons Learned Util has satisfied all Category A requirements Attendee list for NRC 800117-18 site visit encl
- BOO42B0177 Approves one-month extension of 1979-BO licensed operator requalification program
 COLLING.P F Operator Licensing Branch BO/04/08 1p
- 8004280267 Responds to NRC 800410 ltr requesting that info re use of NUKEM 750 be provided by 800530 Technical basis for use of NUKEM 750 as qualified caulk requested from Ameron Info will not be available by 800530 Gubmittal expected 800730 UHRIG.R E Florida Power & Light Co 80/04/22 ip
- G Inspection reports, IE Bulletins & correspondence
- 9004070344 Forwards IE Bulletin 80-03, "Loss of Charcoal From Btd Type II.7wo-Inch.Tray Adsorber Culls " Action required D'REILLY, J P Region 2, Atlanta, Office of the Director 90/02/06
- 8004040003 Responds to NRC ltr re violations noted in IE Insp Repts 50-250/79-37 & 50-251/79-37 Corrective actions testing will be incorporated into security plan w/security supervisor taking responsibility UHRIO:RE Florida Power & Light Co 80/02/19 lp

- B004100195 Forwards IE Insp Repts 50-250/80-02 & 50-251/80-02 on B00118-21 No moncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/02/20 2pp
- --8004100202 IE lnsp Repts SO-250/80-02 & 50-251/80-02 on 800118-21 No noncompliance noted Major areas inspected engineered safeguards & emergency power sys integrated testing UPRIGHT, C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch BROOKS, E H Region 2, Atlanta, Office of the Director 80/02/15
- 8004230007 Forwards IE Insp Repts 50-230/80-05 & 50-251/80-05 on 800205-07 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/22 2pp
- --8004230026 IE Insp Repts 50-250/80-05 & 50-251/80-05 on 800205-07 No noncompliance noted Major areas inspected pipe support baseplates & eafty-related piping sys per IE Bulletins 77-02 & 79-14, respectively HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ANG.W P Region 2, Atlanta, Office of the Director 80/02/20 4pp
- 8004280115 Forwards IE lnsp Repts 50-250/80-06 % 50-251/80-06 on 800204-07 No noncompliance noted LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/12 2pp
- --8004280125 IE Insp Repts \$0-250/80-06 & 50-251/80-06 on 800204-07 No noncompliance noted Major areas inspected areas of small break loss of coulant procedures & training MARTIGE D Region 2: Atlanta, Reactor Operations Nuclear Support Branch JOHNSON, A H., WEBSTER, E H Region 2: Atlanta, Office of the Director 80/03/12 7pp
- 8004040328 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-39 & 50-251/79-39 STOHR.J P Region 2. Ablanta. Fuel Facility & Materials Safety Branch 80/03/13 1p
- --R004040347 Responds to NRC 800128 ltr re violations noted in IE Insp Repts 50-250/79-39 & 90-251/79-39 Corrective actions new procedures & revisions implementing subsections will be reviewed & approved prior to Issuance for use UHRIG.R E Florida Power & Light Co 80/02/19 2pp
- --800404035; Forwards IE Into Repts 50-250/79-39 & 50-251/79-39 on 791219-21 & notice of violation SIOHR.J P Region 2: Atlanta, Fuel Facility & Materials Safety Branch 80/01/28 2pp
- --8004040360 Notice of violation from insp on 791219-21 * Region 2. Atlanta, Office of the Director 80/01/25 ip
- --8004040365 IE Insp Repts 50-250/79-39 & 50-251/79-39 on 791219-21
 Noncompliance noted deficiency in approval of procedures re
 implementation of ETS
 CUNNINGHAM.A L. Region 2, Atlanta, Office of the Director
 JENKINS, G.R. Region 2, Atlanta, Fuel Facility & Haterials Safety
 Branch 80/01/25 4pp
- 8004100187 Summary of 780304 meeting w/util & Hestinghouse in Bathesda, MD re steam generator insp & plugging program GROTENHUIS,M Operating Reactors Branch 1 80/03/13 17pp
- B004080010 Art receipt of B00307 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-40 & 50-251/79-40
 BTOHR-J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/19 19
- -8004080015 Responds to NRC 600201 itr re violations noted in IE Insp., Repts 50-250/79-40 & 50-251/79-40 Corrective actions marking procedures for steam generator heads have been changed to require monitoring UHRIG.R E Florida Power & Light Co 80/03/07 4pp
- --8004080023 Advises that response to 800201 Itr requesting corrective actions to violations noted in IE Insp Repts 50-250/79-40 & 50-251/79-40 will be complete by 800307 UHRIG.R E Florida Power & Light Co 80/02/27 ip
- --8004080027 Forwards IE Insp Repts 50-250/79-40 & 50-251/79-40 on 791217-20 & notice of violation STOHRJ.P Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 80/02/01 2pp

- --8004080030 Notice of violation from insp on 791217-20
 * Region 2. Atlanta, Office of the Director 80/02/01 ip
- --8004080038 IE Insp Repts 50-250/79-40 & 50-251/79-40 on 791217-20 Noncompliance noted failure to follow procedures re marking defective steam generator tubes & failure to have adequate procedures for marking defective tubes OIBSON.A F. WRAY.J R. Region 2. Atlanta, Office of the Director 80/02/01 7pp
- 8004240030 Forwards response to IE Bulletin 80-03, "Loss of Chercoal from Std Type II, Two-Inch, Tray Adsorber Cells "Adsorber cells used in affected sys do not employ screen rivets Possibility of charcoal loss as described does not exist UHRIG.R E Florida Power & Light Co 80/03/24 2pp
- 8004190517 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080619 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Dil Addition & Unsite Supply " No written response required D'REILLY. J P Region 2, Atlanta, Office of the Director 80/04/01
- 800415008: Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers" No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240260 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/02 200
- 8004240371 Ack receipt of 800321 ltr informing NRC of steps taken to correct violation noted in IE lasp Repts 50-250/80-03 & 50-251/80-03 LEMIB:R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip
- --8004240378 Responds to NRC 800225 ltr re violation noted in IE Insp Repts 50-250/80-03 & 50-251/80-03 Corrective actions fire protection QA program will be implemented by 800731 UHRIO,R E Florida Power & Light Cn 80/03/21 2pp
- --8004240383 Forwards IE Insp Repts 50-250/80-03 & 50-251/80-03 on 800107-11 & notice of deviation LEMIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/23 2pp
- --8004240387 Notice of deviation from insp on 800107-11 * Region 2. Atlanta, Office of the Director. 80/02/20 ip
- --8004240390 IE Insp Repts 50-250/80-03 & 50-251/80-03 on 800107-11 Noncompliance noted failure to implement fire protection GA program MARTIN.R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch ELROD.8 A Region 2, Atlanta, Office of the Director 80/02/20 6pp
- B004180321 Forwards IE Circular 80~07: "Problems W/HPCI Turbine Dil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/04/03.
- 8004230145 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASHE 8A-312,Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004i804i7 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds" Written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 200.
- B004300583 Updates 800304 response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Info re Item 7. a will be forwarded by 800601. Info re Item 7. b will be forwarded by 800701
 UHR10.R.E. Florida Power & Light Co 80/04/08 ip

- R Periodic operating reports & related correspondence
- 8004240368 Farwards monthly operating repts for Mar 1978 SCHMIDT, A.D. Florida Power & Light Co. 78/04/07 1p
- --8004240374 Monthly operating repts for Mar 1978 CHILBON, V T Florida Power & Light Co 78/04/06 1300
- 8004240448 Forwards monthly operating repts for Apr 1978 SCHMIDT.A D Florida Power & Light Co 78/05/06 ip
- --B004240452 Monthly operating repts for Apr 1978 CHILBON,V T Fiorida Power & Light Co 78/05/04
- 8004240350 Forwards monthly operating repts for May 1978 BCHMIDT, A D Florida Power & Light Co 78/06/03 tp
- -8004240356 Monthly operating repts for May 1978 CHILSON,V T Florida Power & Light Co 78/06/03 1300
- 8004240470 Forwards monthly operating repts for June 1978 SCHMIDT, A D Florida Power & Light Co 78/07/01 ip
- --BO04240474 Monthly operating repts for June 1978 CHILSON, V T Florida Power & Light Co 78/07/01
- 8004240455 Forwards monthly operating repts for Jul 1978 SCHMIDT, A D Florida Power & Light Co 78/08/10 ip
- --8004240459 Monthly operating repts for Jul 1978 CHILBON,V T Florida Power & Light Co 78/08/10
- 8004240359 Forwards monthly operating repts for Aug 1978 8CHMIDT A D Florida Power & Light Co 78/09/04 ip
- --8004240363 Monthly operating repts for Aug 1978 CHILEON, V T Florida Power & Light Co 78/09/04 1300
- 8004240443 Forwards monthly operating ropts for Sept 1978 8CHMIDT, A D Florida Power & Light Cd 78/10/07 ip
- --8004240444 Monthly operating repts for Sept 1978 CHILBON, V T Florida Power & Light Co 78/10/07
- 8004240466 Monthly operating rapts for Oct 1978 CHILBON, V T Florida Power & Light Co 78/11/04
- BOO4240436 Forwards monthly operating repts for Nov 1978 BCHMIDT, A.D. Florida Power & Light Co. 78/12/06 ip
- --B004240440 Monthly operating repts for Nov 1978 CHILBON, V T Florida Power & Light Co 78/1 78/12/06
- BOO4240418 Forwards monthly operating rapts for Dec 1979 BCHMIDT, A D Florida Power & Light Co 79/01/06 ip
- --8004240422 Monthly operating tepts for Dec 1978 CHILSON, V T Florida Power & Light Co 79/01/06 15pp
- BOO4230330 Forwards monthly operating repts for May 1979 SCHMIDT.A D Florida Power & Light Co 79/06/09 1p
- --8004230332 Monthly operating repts for May 1979
 CHILBUN, V T Florida Power & Light Co 79/06/09
- 8004230484 Forwards monthly operating repts for June 1979 8CHMIDT, A D Florida Power & Light Co 79/07/07 ip
- ---BO04230490 Monthly operating repts for June 1979 CHILBON,V T Florida Power & Light Co 79/07/07 lipp
- 8004230321 Forwards monthly operating repts for Jul 1979. 8CHMIDT, A D Florida Power & Light Co 79/08/04 ip.
- --8004230326 Monthly operating repts for Jul 1979 CHILBON, V T Florida Power & Light Co 79/08/04 13pp
- 8004240463 Forwards monthly operating repts for Oct 1978 SCHMIDT, A D Florida Power & Light Co 78/11/04 1p

- 8004180524 Forwards monthly operating repts for Jan 1980 SCHMIDT.A D Florida Power & Light Co 80/02/09 ip
- --8004180528 Monthly operating repts for Jan 1980 CHILSON, V T Florida Power & Light Co 80/02/09 3pp
- 8004180529 Forwards monthly operating tepts for Feb 1980 SCHMIDT.A D Florida Power & Light Co 80/03/08 ip
- ---8004180930 Monthly operating repts for Feb 1980 CHILSON, V T Florida Power & Light Co 80/03/08
- B0040403B0 Forwards "Semiannual Groundwater Monitoring Program Summary Rept" & "Annual Nonradiological Environ Monitoring Rept, 1979 "
 - UHRIG.R E Florida Power & Light Co 80/03/31 1p
- ---80040403B7 "Semiannual Groundwater Monitoring Program Summary Rept," for period ending Jul 1979 Twenty-one oversize drawings & graphs encl * Dames & Moore 79/07/31 140pg Dames % Moore 79/07/31 140pp
- --8004040397 "Annual Nonradiological Environ Monitoring Rept.1979 " * Florida Power & Light Co 79/12/31 600pp
- BOO4180373 Forwards monthly operating repts for Mar 1980 SCHMIDT, A D Florida Power & Light Co 80/04/05 ip
- ---80041803/4 Monthly operating repts for Mar 1980 CHILSON, V T Florida Power & Light Co 80/04/05
- S Reportable occurrences, LERs & related correspondence
- 8004020377 Forwards LER 80-003/03L-0 8CHMIDT, A D Florida Power & Light Co 80/03/17 ip
- --8004020391 LER 80-003/03L-0 on 800215, while testing 4C steam generator feedwater control valve rapid change in steam generator level resulted in lifting RV-1410 which did not fully reseat Caused by binding between gear & nut Valve tested SCHOPPMAN.M A Florida Power & Light Co 80/03/17 ip

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8004240531 Forwards sys description & operating instructions for NRC health physics telephone natwork Bys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsintlie tra
- 80040702/2 Forwards input to facility fire protection review for fire detection systwator suppression sys & foam suppression sys Info completes items for which adequate licenses input exists
 HALL,R E Brookhaven National Laboratory 80/03/31 Spp
- BOO4070273 Forwards Pages C-26 & C-27 of Revision 5 to security plans, amitted from BOO324 submittal Encl withheld (ref 10CFR2 790)
 PEOPLES, D L. Commonwealth Edison Co. BO/04/02 1p
- 8004230524 Forwards revisions to 800331 ltr re fire protection review, Item 3 1 1.fire detection sys. Item 3 1 5.water suppression sys, & Item 3 1 6.foam suppression sys MALL,R E Brookhaven National Laboratory 80/04/16 Spp
- B004230367 Forwards revised security plan Revisions withheld (ref 100FR2 770)
 PEOPLES,D L Commonwealth Edison Co 80/04/21 IP Commonwealth Edison Co 80/04/21 iP
- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification, OOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp

P Operating license stage documents & correspondence

- 8004080296 Forwards corrected Pages 88 % 93 for Licenses DPR-19 Amend 44 % DPR-25 Amend 39 % corrected Pages 3 6/4 6-2 % 3 6/4 6-9 for licenses DPR-29 Amend 53 % DPR-30 Amend 50 in response IPPOLITO, T A Operating Reactors Branch 3 80/02/20
- --B0040BD310 Carrected License Pages 88 & 73 for Amends 44 & 37 to Licenses DPR-19 & DPR-25, respectively & corrected License Pages 3 6/46-2 & 3 6/46-9 for Amends 53 & 50 to Licenses DPR-27 & DPR-30, respectively Operating Reactors Branch 3 80/02/20 8pp
- 8004070381 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPDLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D O Division of Operating Reactors 80/03/12 5pe
- Division of Operating Reactors 80/03/12 500
- --B004030118 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28pp
- 8004i00102 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/20
- 8004190316 Forwards revised pages constituting Revision 13 to CE-1-A, QA program Revisions reflect recent organization title NAVGHTON, W F Commonwealth Edison Co 80/04/02 1p
- --8004150328 Revised pages constituting Revision i3 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-I-A RI3 80/04/04 7pp
- 8004180217 Forwards add1 info re failure of control rods to insert fully on scram in response to NRC 8006160 & 11 ltrs Bresden 1 experienced no control rod failures in 1978-79 Failure at other facilities caused by leakage past worm pistom seals JANECEK,R F Commonwealth Edison Co 80/04/14 10pp
- 8004290427 Forwards response to NUREO-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Factlities" for review Util emergency plan will be submitted w/Lasalle County site-specific emergency plan PEOPLES,D L Commonwealth Edison Co 90/04/15 & 60pp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities "

 * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- G Inspection reports, IE Bulletins & correspondence
- 8004040029 Forwards IE Insp Repts 50-254/79-30 & 50-265/79-28 on 791211-14. No noncompliance noted DAVIB.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/12 Zpp
- --8004040034 IE Insp Repts 50-254/79-30 & 50-265/79-28 on 791211-14 No noncompliance noted Major areas inspected licensess data, repts & experience in meeting design objective gaseous release rate for radioiodine & radiactive matl.

 HUETER: L J Region 3. Chicago. Office of the Director FISHER: L Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/02/06 Spp.
- 8004100140 Forwards Haste Packaging Insp Rept 79-07A on 791212-13.No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/02/22 2pp
- --8004100408 Waste Packaging 79-07A on 80791212-13 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations including shipping paper requirements, radiation levels & DDT labeling PDTFER.J P. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/02/22 App

- 8004100518 Forwards Waste Packaging Insp Rept 79-07A on 791219 & notice of violation

 DAVIS,A B Region 3. Chicago, Fuel Facility & Materials Safety
 Branch 80/02/22 2pp
- --8004100522 Notice of violation from insp on 79121? * Region 3. Chicago, Office of the Director B BO/02/22 1p
- --8004100528 Waste Packaging Insp Rept 79-07A on 791219 Noncompliance noted failure to mark package as radioactive low specific activity POTTER, J.P., BROKN,R.A. Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/22 3pp
- 6004100192 Forwards IE Insp Repts 50-254/80-03 & 50-265/80-05 on B00115-16 & 0211 No noncompliance noted FIDRELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch B0/02/28 2pp
- --8004100207 IE Insp Repts 50-254/80-03 & 50-255/80-05 on 800115-16 & 0211 No noncompliance noted Major areas inspected torus support GA/GC program.procedures.wprk activities & feedwater
 - sys welds DANIELBON.D H Region 3, Chicago: Reactor Construction & Engineering Bupport Branch WARD.K D Region 3, Chicago: Office of the Director 80/02/28 9pp
- 8004080617 Forwards IE Insp Repts 50-254/80-01 & 50-265/80-02 on BO0102-0201 No noncompliance noted HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/29 2pp
- --8004080625 IE Insp Repts 50-254/80-01 & 50-245/80-02 on 800102-0201 No noncompliance noted Major areas inspected maint plant operations, physical protection & followups SPESGABLR L . CHRISBOTINOS.N Region 3, Chicago, Office of the Director 80/02/25 7pp
- 8004i00ii8 Forwards 1E Info Notice 80-0B. "States Co Bliding Link Electrical Terminal Block " No specific action or response KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07
- BOO4i40i19 Forwards response to IE Builetin BO-03, "Loss of Charcoal from Std Type II, Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is edequate to prevent charcoal granule escape PEOPLES, D L Commonwealth Edison Co BO/03/20 Spp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/21 1p
- --B004040019 Forwards corrected Waste Packaging Insp Rept 79-07A, on DAVIS:A D Region 3. Chicago, Fuel Facility & Materials Bafety Branch GO/02/22 2pp
- ---B004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No honcompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, ramovable contamination & package external features POTTER, J.P. Region G. Chicago, Fuel Facility & Materials Bafsty Branch 80/02/22 7pp
- 8004080494 Forwards final technical evaluation rept re feedwater nozzle cracking Insp program for feedwater nozzles & control rod driveline return line nozzle acceptable CASFA0NO,8 P. Franklin Institute/Franklin Research Center, NRC-03-79-118 80/03/28 6pp
- 8004150139 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or REPPLERIU O Region 3, Chicago, Diffice of the Director 80/03/31
- 8004080686 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required KEPPLERIJ 0 Region 3, Chicago, Office of the Director 80/04/: Region 3. Chicago. Office of the Director 80/04/01.
- 8004i300i4 Forwards IE Info Notice 80-i3, "GE Type 98H Control Buitches Defective CAM Followers " No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02.

- B004180030 Forwards attachments to IE Circular 80-03. "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal
- KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/02 tp
- 8004220093 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees " No action required KEPPLER,J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/03
- 8004220067 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/04/09
- B004110025 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Written response required XEPPLER,J O Region 3, Chicago, Office of the Director 80/04/07
- 8004230224 Forwards IE Bulletin 79-03A: "Longitudinal Weld Defects in ABME SA-312.Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3: Chicago, Office of the Director 80/04/07 19
- 8004280628 Forwards revised Pages 3 % 5 % omitted Page 4 to IE Insp Repts 50-010/80-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 % 50-265/80-08 FIGRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/04/09 ip
- --B004280634 Revised Pages 3 & 5 & omitted Page 4 to IE Insp Repts 50-010/80-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 & 50-265/80-08
 - * Region 2, Atlanta, Office of the Director 80/04/09 3pp
- R Periodic operating reports & related correspondence
- E004150004 Forwards "Radioactive Waste & Environ Monitoring, Annual Rept. 1979" Rept constitutes Part 3 of facility operating rept
 KALIVIANAKIG, N Commonwealth Edison Co 80/03/06 ip
- --8004150007 "Radioactive Wasts & Environ Monitoring Annual Rept.1979 "
 * Eberline Instrument Corp 80/03/31 91pp
- 8004220333 Forwards listing of changes, tests & experiments performed in Mar 1980 KALIVIANAKIS, N. Commonwealth Edison Co. 80/04/14 5pp
- B Reportable occurrences: LERs & related correspondence
- BO04020422 Forwards LER 80~004/03L-0 KALIVIANAKIS,N, Commonwealth Edison Co 80/03/14 1p
- --8004020427 LER 80-006/03L-0 on 800222; while doing routine panel checks, reactor core isolation cooling supply valves MO 1-1301-16 & 17 were found in closed position Caused by procedural inadequacy & personnel performance Procedures revised VAHRENWALD, J Commonwealth Edison Co 80/03/14, ip
- 8004020350 Forwards LER 80-005/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 80/03/20 1p
- --B004020357 LER B0-005/03L-0 on B00224, while performing MIBV closure timing, valva AD 1-203-1B failed to close when control switch was operated. Caused by blockage of exhaust restrictor on on pilot valve Exhaust restrictor cleaned B0DEN, R Commonwealth Edison Co 80/03/20 2pp
- BOO4190463 Forwards LER 80-007/03L-0 KALIVIANAKIB, N Commonwealth Edison Co 80/03/25 1p
- --8004150467 LER 80-007/03L-0 on 800308, while performing control room insp & panel check, B main steam line radiation monitor found reading low Caused by logarithmic radiation monitor chassis electronically drifting out of callipr Chassis recallibr WYKOFF, D Commonwealth Edison Co 80/03/25 2pp
- 8004150457 Forwards LER 80-008/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 80/03/27 ip

- --8004150468 LER 80-008/03L-0 on 800308, after performing proventive maint, 1/2 diesel generator would not start from control room Caused by poor electrical contact between fuse & clip Fuse clip adjusted
 LEECH, K. Commonwealth Edison Co. 80/03/27 2pp
- DOCKET 50-255 PALIBADES NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8004080426 Advises that designs for fire protection, sprinklers, cable penetration seals & cable firestops described in util 800222 ltr are acceptable for protection intended in NRC safety evaluation ZIEMANN, D. L. Operating Reactors Branch 2 80/03/11 2pp
- 8004110022 Forwards suppl to 780701 fire protection safety evaluation in response to 780715 & 27 ltrs providing addl info Items 3 2 f & 3 2 5 are resolved IEMANN.D L. Operating Reactors Branch 2 80/03/19 2pp
- --8004110026 Suppl 1 to file protection safety evaluation, resolving Items 3 2 1 & 3 2 9 * Office of Nuclear Reactor Regulation 80/03/19 1p
- 8004240540 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimilis traffic KEPPLER.J O Region 3. Chicago, Office of the Director 80/03/20 20a
- 8004280614 Forwards drawings indicating fire protection mods to Item 3 ! 5. "Fire Darriers " FROST.8 R Consumers Power Co 80/04/24 3pp
- --8004280624 "Curtain-Type Fire Doors Heating & Ventilation Sys, Fire Areas 1.2,3 & 4., Mod 10 " Sheet 1 of 1 * Nuclear Services Corp 79/11/29 ip
- --8004280417 "Heating & Ventilation Auxiliary & Containment Plan at Elevation 607 Ft 6 inches & 611 Ft " * Bechtel Corp 79/11/29 ip
- --8004280421 "Heating & Ventilation Auxiliary & Containment Bidg Plan Elevation, 625 Ft " * Bechtel Corp 5935 79/11/29 ip
- ---B004280625 "Heating & Ventilation Auxiliary & Containment Plan at Elevation 639 Ft & 649 Ft "

 * Bechtel Corp 79/07/03 ip
- --8004280627 "Mod 8,Fire Doors 81,119,184,185 Fire Area Numbers 1,2,5,9 "
 Sheet 1 of 1
 * Nuclear Services Corp 79/01/03 ip
- O Adjudicatory correspondence
- 8004100310 Forwards Revision 4 of "Stram Generator Repair Rept," which is being served on parties to proceeding W/o encl
 OIBBS.M E Isham, Lincoln & Beale 80/03/03 ip
- BO04090442 Responds to B00221 ltr enclosing CPC first round of interrogatories & request for production of documents Answers will be accomposed informally, to extent of relevancy to civil penalty issues.w/o waiving objections MURRAY, J P Rulemaking & Enforcement Division 80/03/06 3pp
- 8004080062 Response to CPC 800221 first set of interrogatories & request for production of documents re-civil penalty Itoms 12,13,14 & 17 will be supplemented by 800411 Forwards objections & responsive answers Certificate of Syc encl BURNS,5 A Rulemaking & Enforcement Division 80/03/31 2pp
- --B004080067 Response in opposition to certain of CPC B00221 first set of interrogatories & request for documents re civil penalty Employees home addresses & personal handwritten notes are not discoverable per case law re invasion of privacy BURNS:8 O Rulemaking & Enforcement Division 80/03/31 iipp
- --BO040B0074 Response to CPC B00221 first set of interrogatories & request for production of documents recivil penalty Includes facts supporting IE notice of violation & name of persons who have knowledge of stated facts W/affidavit MOSELEY,N C Division of Reactor Operations Inspections B0/03/31 27pp

- 8004080006 Discovery rept for Mar 1980 re civil penalty proceeding Responded to CPCC first round of interiogatories Received GPC 800317 request, per FDIA, repeating requests for documents under CPC 80021 discovery filling Certificate of Svc ent BURNS, S G Rulemaking & Enforcement Division 80/04/01 3pp
- B004030026 Memorandum of understanding between MRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOBSICK, L. V. Office of the Executive Director for Operations B0/04/02 34pp
- 8004170295 Supplemental responses to CPC 800221 first set of interrogatories & request for documents re civil penalty proceeding Regulations do not require performance of research or compilation of data not readily known BURNS, S G Rulemaking & Enforcement Division 80/04/14 B0/04/14 3pp
- --8004170258 Supplemental answers to CPC first interrogatories & request for documents re civil penalty proceeding Includes statements re identified noncompliances & actions taken after discovery of violation BURNS.S G Rulemaking & Enforcement Division 80/04/14 35pp
- ---B004170262 Recommends civil penalty be assessed against CPC due to violation discovered in Sept 1979 re manual isolation valves in locked open condition Bases genalty on prior violations re containment integrity W/affidavit & Certificate of Svc KEPPLER.J G Region 3. Chicago. Office of the Director 79/10/2
- B004210232 Interrogatories & request for documents directed to CPC recivil penalty proceeding Requests description of investigations re 791911 discovery of two locked-open manual containment isolation valves Certificate of Svc enci LIBERMAN.J. BURNS.8 0 Rulemaking & Enforcement Division 80/04/18 Bpp

H General correspondence

- 8004230303 Forwards util 800318 news release indicating changes in project, engineering & const organization Will submit revisions to GA program by 800430 to incorporate organizational changes HOFFMAN.D P Consumers Power Co 80/04/18 7pp
- P Operating license stage documents & correspondence
- 8004180135 Discusses fission gas release rate from LWR fuel pellets Data re C-E & Exxon PWR fuel bundles demonstrated no adverse effect on ECCS evaluations nor did internal fuel rod pressure exceed sys pressure ZIEMANN.D L Operating Reactors Branch 2 80/02/27 2pp
- B004020450 Requests necessary action to refund licensee amend fees Amend fees waived for certain types of fire protection amends MILLER, W C License Fee Management Branch 80/03/05 Ip
- 8004070220 Advises that Ofc of Controller has authorized refund of three Class II fees submitted with 800131 & 0201 applications License amend fees for certain Tech Spec changes re fire protection waived MILLER.W D License Foe Management Branch 80/03/05 ip
- 8004090346 Forwards NUREG-0569, "Evaluation of Integrity of SEP Reactor Vessels." completing review of SEP Topic V-6 H/q encl ZIEMANN,D L. Operating Reactors Branch 2 80/03/05 2pp
- 8004020001 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN.D L. Operating Reactors Brench 2 80/03/06 6pp
- 8004080402 Forwards Amend 55 to License DPR~20, safety evaluation & notice of issuance & availability
 ZIEMANN, D. L. Operating Reactors Branch 2, 80/03/06 2pp
- --8004080405 Amend 55, to License DPR-20, revising Tech Specs contained in App A.changing Tech Specs to conform w/aperating limits of 10CFR50, App O, "Fracture Toughness Requirements"
 ZIEMANN, D.L. Operating Reactors Branch 2 80/03/04 13pp
- --8004080408 Safety evaluation supporting Amend 55 to License DPR-20 & Office of Nuclear Reactor Regulation 80/03/06 3pp

- --- BCO4080412 Notice of issuance & availability of Amend 55 to License WAMBACH, T V Operating Reactors Branch 2 80/03/06
- 8004030102 Forwards "Nutlear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIEENHUIT.D Q Division of Operating Reactors 80/03/12 5pp
- ---8004030118 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28pp
- 8004100159 Notification of 800326 meeting w/util in Bethesda,MD re BEP Topic VI-B, control room habitability O'CONNOR,P W Operating Reactors Branch 2 80/03/18 2pp
- 8004100154 Requests that future revisions to P&IDs be forwarded to Region 3 incident response ctr Also requests removel of HL Azekson from distribution list KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/20
- 8004010289 Submits ref list for SEP Topics VI-7 A 3.VI-7 B.VI-10 A.VII-1 A & VII-2.in response to NRC 800214 request HOFFRANN.D P Consumers Power Co. 80/03/26 3pp
- B004100166 Notification of 800331 meeting w/util in Bethesda.MD re automatic initation of auxiliary feedwater SILVER.R D Operating Reactors Branch 2 B0/03/26 2pp
- 8004020166 Responds to NRC 800327 request for add1 info re facility pressurizer pressure transmitters Rosemont Model 1151 transmitters are being used When plant is taken to cold shutdown, higher selsmic quality Model 1153 will be used HUSTON: R W Consumers Power Co 80/03/28 1p
- 8004210190 Forwards request for info re containment environ conditions \$\forall \text{ sys required for accident mitigation for review of environ qualification of Class IE electrical equipment NRC will estimate time for containment temp to return to near normal ZIEMANN,D t. Operating Reactors Branch 2 80/03/28 15pp
- 8004070320 Forwards "Environ Assessment, Steam Generator Replacement" addressing effects of proposed new barge slip HOFFMAN, D.P. Consumers Power Co. 80/03/31 2pp
- --8004070322 "Environ Assessment, Steam Generator Replacement "
 * Consumers Power Co 79/12/31 50pp
- 8004070305 Forwards sys design description re proposed containment hydrogon monitoring sys as committed to under NURE9-0578 HOFFMAN, D P Consumers Power Go 80/04/01 21pp
- 6004080202 Notifies that 800401 C-E owners group rept is applicable to facility & constitutes util response to short-term analysis & emergency procedure guideline requirements of Section 2: 9(c) of NURE-0578
 HOFFMAN, D P Consumers Power Co 80/04/01 1p
- 8004090389 Forwards "Beismic Consultation for Befety-Related Electrical Equipment, Interim Rept 1, Equipment Checklist, " providing results of investigation of positive anchorage for certain electrical equipment HOFFMAN, D P Consumers Power Co 80/04/02 ip
- ---8004090394 "Geismic Consultation for Bafety-Related Electrical Equipment, Interim Rept i. Equipment Checklist " 4 John A Blume & Associates. Engineers (subs. URB Corp.) 80/03/20 35pp
- 8004110308 Forwards info re RELAP input for LOCA analysis at Units KUEMIN.J.L. Consumers Power Co. 80/04/02 61pp
- 8004300055 Provides addl info on automatic initiation of auxiliary feedwater sys flow concerning implementation of Item 2 1 7a requirements of NUREO-0578 Requests detail of sefety-grade sys design Certain commitments required within 15 days EISENHUT, D 0 Division of Operating Reactors 80/04/03 3pp
- 8004150215 Advises that facility has not experienced turbine overspeed trip to date per 800321 commitment re cracking in low pressure turbine discs HDFFMAN.D P Consumers Power Co 80/04/10 ip

- 8004i50398 Responds to NRC 79ii09 order modifying license Controlled review to upgrade plant drawings, checklists & procedures associated w/engineered safeguards sys initiated Revisions resulting from review will be completed prior to startup DEWITT, R B Consumers Power Co 80/04/10 3pp
- 8004150474 Requests amend change to License DPR-20 to allow plant personnel to conduct feedwater line water hammer test Forwards Special Tost Procedure T-30, "Feedwater Line Water Hammer Test"

 DEWITT, R D Consumers Power Co 80/04/11 2pp
- --8004150479 "Feedwater Line Nater Hammer Test " * Consumers Power Co 80/04/11 15pp
- BO04150627 Notifies that current main steam line break analysis requested in NRC 791221 itr cannot be completed until containment spray problem identified in LER 80-002, is resolved NOFFMAN.D P Consumers Power Co 80/04/11 io
- 8004210159 Submits add1 info requested by NRC re amend to OL to conduct feedline water hammer test
 NOFFMAN,D P Consumers Power Co 80/04/16 3pp
- BOD4240450 Responds to NRC 800107 request to review aspects of GA program re diesel fuel for facility Diesel fuel oil is included in GA program Sample of main storage tank diesel fuel is tested every three months.per ASTM-D270-65 HOFFMAN.D P Consumers Power Co 80/04/21 ip
- 8004250425 Forwards add1 info in response to NRC 800331 recommendations re automatic initiation of auxiliary feedwater sys Believes that auxiliary feedwater flow of 300 gpm adequate to recover from loss of main feedwater, HUBTON.R W Consumers Power Co 80/04/22 5pp
- 8004250426 Submits add1 info ro auxiliary feedwater sys in response to NRC 800403 request Short-term Lessons Learned Task Force requirements will be implemented w/o prior NRC approval Sys will be Upgraded to safety-grade sys by 810101 HOFFMAN,D P Consumers Power Ca 80/04/23 2pp
- BOO4280519 Forwards request for exemptions to ARME BV & PC Code.Section XI re inservice pump testing Request will remain in effect after code update & is in addition to 780613 submittal HOFFMAN.D P Consumers Power Co 80/04/25 3pp
- G Inspection reports, IE Bulletins & correspondence
- B004040032 Forwards Waste Packaging Insp Rept 79-06A on 791126-28. No noncompliance noted DAVIB.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/13 2pp
- --8004040035 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements; radiation levels, removable contamination & external package features POTTER, J P. BROWN, R. A. Region S. Chicago, Fuel Facility & Materials Safety Branch 80/02/13 4pp
- 8004100132 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J & Region 3, Chicago, Office of the Director 80/03/07 in
- 8004090379 Ack receipt of 800208 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-259/79-20 KEPPLER.J O. Region 3. Chicago, Office of the Director 80/03/20 2pp.
- --B00409083 Responds to NRC 800102 ltr re violations noted in IE Insp Rept 50-285/79-20 Corrective actions submitted revised LER 79-044, marked test gauge w/serial number & resolved all discrepancies in valve stroke times HOFFMAN.DP Consumers Power Co 80/02/08 7pp
- B004030325 Ack receipt of B00305 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept Util ltr withheld (ref 10CFR2 790)
 HINDLY A Region 3, Chicago, Bafeguards Branch 80/03/21 ip
- 8004150169 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J Q. Region 3, Chicago, Office of the Director 80/03/31 1p

- 8004080704 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required KEPPLER, J O Region O. Chicago, Office of the Director 80/04/01
- 8004150037 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response regulred KEPPLER, J G Region 3, Chicago, Office of the Director 60/04/02
- 8004180040 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J.O. Region 3. Chicago, Office of the Director 80/04/02
- 8004220123 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220365 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Bys "No writted respon≤e required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03 to
- 8004280402 Notifies that response to Item 2 of IE Dulletin 79-27 "Loss of Nonclass IE Instrumentation & Control Power Sys Bus During Operation" will be submitted upon completion of emergency procedures review HOFFMAN, D P Consumers Power Co 80/04/03 1p
- B004230196 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe" Action required KEPPLER. J G Region 3. Chicago, Office of the Director 80/04/07 to
- 8004140334 Responds to NRC 800306 ltr re violation noted in IE Insp Rept 50-255/80-02 Corrective actions containment pressure instrument lines will be modified prior to startup HOFFMAN.D P Consumers Power Co 80/04/08 4pp
- B004220149 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Wolds " Written response required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/04/09
- 80041804B7 Responds to NRC telcon request for addl info re "stubbed-in" joints at facility Mods requiring addition of pipe saddles on some joints made so that FSAR or interim acceptance criteria for allowable stress limits in piping are met HOFFMAN, D P Consumers Power Co 80/04/14 1p
- 8004220588 Submits addl info re IE Bulletin 79-27. "Loss of Nonclass IE Instrumentation & Control Power Sys Bus During Operation." per 800417 & IB teleon requests Estimates 320 man-hours will be expended on bulletin to complete action HOFFMAN.D P Consumers Power Co 80/04/18 2pp
- B004250313 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in AGME SA-312, Type 304 Statisless Steel Pipe "Bulletin is not applicable to plant safety-related sys HUSTON:R W Consumers Power Co 80/04/22 2pp
- R Pariodic operating reports & related correspondence
- 8004030217 Forwards "1979 Radiological Environ Monitoring Rept " HOFFMAN, D.P. Carolina Power & Light Co 80/03/31 1p
- ---8004030220 "1979 Radiological Environ Monitoring Rept "
 * Consumers Power Co 80/03/31 9pp
- BOD4040371 Forwards "1977 Environ Monitoring Rept " Analysis of rept data demonstrates no detectable increase in radioactivity levels of environ media attributable to facility effluents HOFFKAN.D P Consumers Power Co 80/03/31 1p
- ---8004040374 "1979 Environ Monitoring Rept "
 # Consumers Power Co 80/03/31 9pp
- 8004080436 Forwards monthly operating rept for Mar 1980 ADAMS, W E Consumers Power Co 80/04/01 lp
- --8004080438 Monthly operating rept for Mar 1980 BODTKE.P J Consumers Power Co 80/04/01 4pp

- S Reportable occurrences. LERs & related correspondence
- 8004180520 PND-IJI-78-177 factlity was shut down on 781128 to correct excessive control rod drive mechanism seal leakage Cause may be metallurgy problem associated w/seal math Most seals installed during refueling outage have been replaced KLINGER. 0 . NOLAN.F Region 3. Chicago, Office of the Director 78/11/30 ip
- 8004100396 Forwards LER 80-002/03L-0 HOFFMAN, D P Consumers Power Co 80/04/03 1p
- --8004100359 LER 80-002/03L-0 on 791023, during routine testing of hydraulic snubbers, snubber 8-6, located on main steam line, failed to meet test acceptance criteria Caused by loose accumulator oil fill fitting Snubber replaced * Consumers Power Co 80/04/03 lp
- 6004100403 Forwards LER 60-003/01T-0 HOFFMAN, D P Consumers Power Co 60/04/03 1p
- --8004100404 LER 80-003/01T-0 on 600304, during evaluation of 8EP Topic VI-3 discovered total activation time for containment spray sys in excess of FSAR institution times Caused by personnel error during initial accident analyses * Consumers Power Co 80/04/03 2pp
- 8004100413 Forwards updated LER 79-044/01X-1 HOFFMAN, D P Consumers Power Co 80/04/03 ip
- --B004100415 Updated LER 79-044/01X-1 on 790729, after surveillance test A0-0, valves 3363 ES & 3364 ES left in closed position, resulting in sodium hydroxide addition sys not being returned to svc Caused by inadequate procedure requirements * Consumers Pawer Co. B0/04/03 ip
- 8004150012 Forwards NPBES noncompliance notification HOFFMAN, D P Consumers Power Co 80/04/08 12
- --8004150019 NPDES noncompliance notification on 800310 dissel fuel spill detected in dissel generator room Caused by fuel tank high level shutoff switch failing to stop transfer pump while filling fuel tank Crew assigned to clean up turbine sump FORBES,R L Consumers Power Co 80/03/26 3pp.
- 8004150530 Forwards LER 88-004/01T-0 HDFFMAN: D ? Consumers Power Co 80/04/10 ip
- --B004150537 LER 80-004/01T-0 on 800327.during review of fach Spec surveillance procedures, discovered procedure MO-19 requiring isolation of both containment spray headers during test violated Cause not stated Procedure rewritten * Consumers Fower Co 80/04/10 1P
- 8004150544 Forwards LER 80-005/01T-0 HDFFMAN-D P Consumers Power Co. 80/04/10 1p
- --8004150556 LER 80-005/017-0 on 800327, during review of Tech Spec surveillance procedures, discovered that procedures GO-2 & MD-23 require stroking SIRW tank autlet valves Amend to DL or clarification of Tech Spec requirements will be sought * Consumers Power Co 80/04/10 IP
- 8004250350 Forwards LER 80-007/01T-0 FROST, S R Consumers Power Co 80/04/21 1p
- --B004250358 LER 80-007/01T-0 on 800407, during maint on control room ventilation sys, discovered leakage defects through shaft of fan V-36. Fresh air damper D-1 would not close Caused by inadequate pre-operational testing of ventilation sys * Consumers Power Co B0/04/21 ip
- 8004250354 Forwards LER 80-006/03L-0 HOFFMAN, D. P. Consumers Pawer Co 80/04/21. Lp
- --8004250359 LER 80~006/03L-0 on 791110, during routing surveillance of containment purge valves, redundant T-ring air supplies for 12-inch & 48-inch valves leaked beyond accepted criteria Cause not stated Leaks were primarily at fittings & packing * Consumers Power Co. 80/04/21. ip

- DOCKET 50-259 BROWNS FERRY MUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8004130105 Forwards comments on 790301 safeguards contingency plan & 790901 Revision 1 Requests revisions & addl info Encl withheld (ref 10CFR2 790) | PROLITOLYA Operating Reactors Branch 3 80/03/27 2pp
- O Adjudicatory correspondence
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification QUSSICK,L V Office of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- 8004300404 Requests that public hearing & EI8 be required for proposed low level waste compaction & incineration facility at site JURENKO,R C Affiliation Unknown 80/04/22 1p
- P Operating license stage documents & correspondence
- 8004020178 Forwards request for addl info on proposed Tech Spec changes re control & wiring diagrams LAINAS.O Plant Systems Branch 80/02/11 3pp
- 8004070384 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO,T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT,D 0 Division of Operating Reactors 80/03/12 5pp
- --8004030ii8 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- GO04040127 Forwards Corrected Pages 159 & 160 to Amend 59 & Pages 157 & 158 to Amend 35 for Licenses DPR-33 & DPR-52 IPPOLITO,T A Operating Reactors Branch 3 BO/03/14 4pp.
- 8004110519 Forwards Amends 60.55 & 32 to Licenses DPR-33.DPR-52 & DPR-68 respectively, safety evaluation & notice of issuance & availability IPPOLITO, T A Operating Reactors Branch 3 80/03/17 2pp
- --8004110525 Amends 60.55 & 32 to Licenses DPR-33, DPR-52 & DPR-68, respectively, authorizing temporary storage of low level radwaste in existing covered pavilion, outside security fence but inside site exclusion area IPPOLITO, T A Operating Reactors Branch 3 80/03/17 App
- --8004110525 Amends 40,55 & 32 to Licenses DPR-33, DPR-92 & DPR-46, respectively, authorizing temporary storage of low level radwaste in existing covered pavilion, outside security fence but inside site exclusion area IPPOLITO.TA Operating Reactors Branch 3 80/03/17 4pp
- --8004110527 Bafety evaluation supporting Amends 60,55 & 32 to Licenses DPR-33,DPR-52 & DPR-68, respectively * Office of Nuclear Reactor Regulation. 80/03/17 7pp
- --8004110331 Notice of issuance & availability of Amends 60,55 & 32 to Licenses DPR-33,DPR-52 & DPR-68,respectively IPPOLITO,T A Operating Reactors Branch 3, 80/03/17, 3pp
- 8004150423 Advises that add1 time will be needed to develop coordinated response to NRC request of 800215 Response will be submitted by \$60501 MILLS, L H Tennessee Valley Authority. 80/04/07 1p
- 8004150557 Forwards add1 info re containment purge & venting sys.in response to NRC 800226 ltr.Key lock switches are provided on control switches to allow overriding primary containment isolation signal
 MILLS-L N Tennessee Valley Authority 80/04/07 3pp

- 8004290020 Forwards 800128 & 0211 ltrs to GE re proposed control rod drive sys mods related to elimination of cracking in return line nozzles Ouidelines for mods will be discussed in NUREG-O619, to be issued in "For Comment" form in Apr 1980 JPPOLITO T A Operating Reactors Branch 3 80/04/07 2pp
- 8004230283 Forwards request for add1 info re degraded grid voltage Also requests revised schedule for submission of design of long-term mods re adequacies of station electric distribution sys voltages IPPOLITUIT A Operating Reactors Branch 3 80/04/08 3pp
- 8004230506 Forwards into re control drive malfunctions during CY78 & 79, in response to NRC 800110 request
 MILLS.L M Tennessee Valley Authority 80/04/11 2pp
- 8004220340 Application to amend Licenses DPR-33,DPR-52 & DPR-68 changing Teck Specs to allow conduct of short containment integrated leak rate test Fee enci MILLS.L M Tunnessee Valley Authority 80/04/15 2pp
- --8004220349 Proposed Tech Spec revisions, allowing conduct of short containment integrated leak rate test
 * Tennessee Valley Authority 80/04/15 13pp
- ---BOO4220358 "Nuclear Containment Testing for TVA Nuclear Power Plants," presented at ANS 79:11:1-16 winter meeting CLARK,K H , WHITE,T J Tennessee Valley Authority 79/11/16
- BO04220523 Responds to NRC 800212 request for info needed to compare RETRAN code results w/simulator results & EG&O 800317 request for info re LOCA calculational models Singer Co could more adequately address NRC request
 MILLS.L M Tennessee Valley Authority 80/04/15 2pp
- --8004220331 Requests assistance in comparing RETRAN & simulator results for BWR plant transients/incidents re loss of feedwater & loss of load BML should be provided w/related info EG&G BOO317 request for info encl FABIC.8 Analysis Development Branch 80/02/12 App
- BOO4220533 Advises that Section 316 documents re NNPDES Permit ALO022080 are being sent to JW Warr, H Zeller & LB Tebp, in accordance w/util 800331 ltr EL-ASHRY, M T Tennesses Vailey Authority 80/04/17 2pp
- G Inspection reports, IE Bulletine & correspondence
- 8004040174 Ack receipt of 800124 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-42. 50-260/79-42 & 50-276/79-42 BRYANT.J.C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/04 Epp
- --8004040181 Responds to NRC 800102 ltr re violations noted in IE Insp Repts 50-259/79-42,50-260/79-42 & 50-296/79-42 Corrective actions, review of all previous insp data records was made to verify notification to DES engineer MILLS,L M Tennessee Valley Authority 80/01/24 3pp
- --8004040185 Forwards IE Insp Repts 50-289/79-42,50-260/79-42 & 50-286/79-42 on 791126-27 & notice of violation MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/02 2pp
- --8004040189 Notice of violation from insp on 791126-27
 * Region 2, Atlanta, Office of the Director 79/12/14. 1p.
- --8004040176 IE Insp Repts 50-259/79-42,50-260/79-42 & 50-296/79-42 on 791126-27 Noncompliance noted failure to report discrepancies to DES engineer HERDT.A Region 2, Atlanta, Reactor Construction & Engineering Support Branch MODENOB.L. Region 2, Atlanta, Office of the Director 79/12/14 4pp
- 8004070352 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06, 2pp.
- 8004090245 Forwards IE Insp Repts 50-259/80-03,50-260/80-03 & 50-296/80-07 on 800129-31.No noncompliance noted LENIS.R.C Region 2. Atlants, Reactor Operations Nuclear Support Branch 80/02/19 2pp

- --8004070252 IE Insp Repts 50-259/80-03,50-260/80-03 & 50-296/80-09 on 800129-31 No noncompliance noted Major areas inspected refueling activities
 KELLOGO.P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/15 Spp
- 8004110503 Forwards IE Insp Repts 50-259/80-07,50-240/80-07 & 50-294/80-07 on 800205-07 No noncompliance noted BRYANT,J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004110314 IE Insp Repts 30-259/80-07, 50-260/80-07 & 50-296/80-07 on 800203-07 No noncompliance noted Major areas inspected video observation of core spray sys sparger & review of proposed actions for LER HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Dranch VANDORN.P K Region 2. Atlanta, Office of the Director 80/02/25 3pp
- 8004280194 Forwards IE Insp Repts 50-259/80-05,50-260/80-05 & 50-296/80-05 on 800206-08 No noncompliance noted BRYANT,J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/07 2pp
- --8004280202 IE Insp Repts 50-259/80-05, 50-260/80-05 & 50-296/80-05 on 800206-08 No noncompliance noted Major areas inspected areas of seismic analysis for as-built safety-related piping sys (IE Bullatin 79-14)
 HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Support Branch HODENOS, L. Region 2. Atlanta, Office of the Director 80/03/04 4pp
- 8004020242 Ack receipt of 800204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-38, 50-250/79-38 \$ 50-276/79-38 LEWIS:R C Region 2. Atlanta, Reactor Operations Nuclear Support Br
- --8004020249 Responds to NRC 800110 ltr re violations noted in IE Insp Repts 50-259/79-38, 50-240/79-38 & 50-296/79-38 Corrective actions local leak rate test performed on normal hatch cover & control rod drive added to CILRT results MILLB.L M Tennessee Valley Authority 80/02/04 3pp
- --8004020252 Forwards IE linsp Repts 50-259/79-38,50-260/79-38 & 50-276/79-38 on 791119-23 & notice of violation LENIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 60/01/10 2pp
- --8004020258 Notice of violation from insp on 791119-23 # Region 2. Atlanta. Office of the Director 80/01/08 1
- --8004020263 IE Insp Repts 50-289/79-38.50-260/79-38.8.50-296/79-38 on 791119-23 Noncompliance noted use of temporary control rod driveline hatch cover during integrated leak rate test UPRIGHT; C M. Region Z: Atlanta, Reactor Operations Nuclear Support Branch 80/01/08 &pp
- --8004020263 IE Insp Repts 50-259/79-38.50-260/79-38 & 50-296/79-38 on 791119-23 Noncompliance noted use of temporary control rod driveline hatch cover during integrated leak rate test UPRIGHT.C H Region 2. Atlanta. Reactor Operations Nuclear Support Branch BROOKS.E H., WHITENER.H L Region 2. Atlants. Office of the Director 80/01/08 App
- 8004100364 Responds to 1E Bulletin 79-23 Conducted sustained full-load operational test on Emergency Diesel Generator 3A Test demonstrated ability of diesel generators to function properly over 24-h period at specified loads MILLS, L M Tennessee Valley Authority 80/03/21, ip
- 8004210178 Forwards response to IE Bulletin 80-03, "Loss of Charcost from 8td Type II. Two-Inch. Tray Adsorber Ceits " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS, L M Tennesse Vailey Authority 80/03/21 4pp
- 8004280001 Supplements 800212 response to IE Bulletin 79-19 Forwards info re procedural controls necessary until completion of sys mods for upgrading public address & evacuation alarm sys as required by bulletin MILLS.L M Tennessee Valley Authority 80/03/25 2pp
- 8004130527 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31

- 8004080636 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01
- 8004150097 Forwards IE Info Notice 80~13, "QE Type 88M Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J P Region 2, Atlanta, Defice of the Director 80/04/02
- 8004240274 Forwards IE info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 3hs
- 8004180275 Forwards IE Circular 80-07. "Problems W/HPCI Turbine 011 Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/03
- 6004110021 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Hritten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Wald Defects in ASME 6A-312.Type 304 Stainless Steel Pipe" Action required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004180445 Forwards IE Sulletin 80-08, "Exam of Containment Liner Penetration Helds " Hritten response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/07 Son
- 8004280170 Forwards monthly progress rept for Mar 1980 in response to IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys " Includes insp of drawings, pipe supports & floor & wall penetrations MILLS.L K Tennessee Valley Authority 80/04/07 20pp
- 8004270170 Forwards IE Insp Repts 50-259/80-12,50-260/80-10 & 50-276/80-11 on 800311-14 No noncompliance noted KENNA: W B Region 2: Atlanta: Saleguards Branch 80/04/09 2pp
- --B004290177 lE Insp Repts 80-289/80-12, 50-260/80-10 & 50-296/80-11 on B00311-14 No noncompliance noted Major areas inspected review of security plan.organization.access controls & barriers Details withheld (ref 10CFR2 790) GILLESPIE.F Region 2, Atlanta, Safeguards Branch TILLHAN, A Region 2, Atlanta, Office of the Director B0/04/07 1p
- 8004270377 Requests approval of ABME Code Cases N-234 & N-235 for use on reactor pressure vessols Expeditious approval is necessary for use of code cases in forthcoming preservice insp
 MILLS.L M Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- 8004240411 Forwards monthly operating rapts for Mar 1980 ABERCROMBLE, H.L. Tennessee Valley Authority 80/04/10 19
- --8004240415 Monthly operating repts for Mar 1980 THOW,T Tennessee Valley Authority 80/04/02 32pp
- S Reportable occurrences, LERs & related correspondence
- 8004180518 PNO-11-78-147 on 780818 one of six air compressors suffered massive failure resulting in rapid loss of control air pressure to all three units Caused by large hole in cylinder head of failed compressor Compressor was isolated KLINOER. G. NOLAN, F. SNIEZEK, J. Region 2, Atlanta, Office of the Director 78/08/18 ip
- 8004D10451 Forwards LER 80-020/03L-0 CALHOUN, J R Tennessee Valley Authority 80/03/28 1p
- --8004010458 LER BO-020/03L-0. on 800301, during normal operation, w/high winds & freezing raim. Trinity offsite 161-kV power source was lost intermittently Caused by ice loading & high winds requiring operation of line protective relay # Tennessee Valley Authority 80/03/28 2pp
- 8004010487 Forwards LER 80-021/03i-0 CALHOUN: J R Tennessee Valley Authority 80/03/28 ip

- --8004010491 LER 80-021/03L-0 on 800301 during severe ice storm, wind speed instrumentation on meteorology tower failed to indicate true wind speed. Caused by ice formation on instrument No action planned
 * Tennessee Valley Authority 80/03/28 2pp
- 8004150573 Forwards LER 80-023/03L-0 CALHOUN, J R Tennessee Vailey Authority 80/04/08 ip
- --8004150585 LER 80-023/03L-0 on 800312, during refueling outage, relay 23A-442 found wared incorrectly, eliminating HPCI reactor high water level trip Cause undetermined * Tennessee Valley Authority 80/04/08 2pp
- 8004130525 Forwards LER 80-024/03L-0 CALHOUN, J.R. Tennessee Valley Authority 80/04/10 t
- --8004150536 LER 80-024/03L-0 on 800312, during refueling outage w/Units 2 & 3 under normal operation, nut came off bracket holding insulated communications ground wire above Athens 161-K line.causing fault resulting in trip of breakers * Tennessee Valloy Authority 80/04/10 2pp
- 8004150523 Forwards LER 80-025/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/11 ip
- --B004150535 LER BD-025/03L-0 on 800313, primary containment isolation testing revealed failure of RHR injection valve 74-67 to close upon isolation signal Caused by limit switch on FCV-74-48 not making good contact Contact cloamed & adjusted Tonnessee Valley Authority 80/04/11 2pp
- 8004220696 Forward's supplemental LER 80-001/01T-1 CALHOUN'S R Tennessee Valley Authority 80/04/18 ip
- --8004220699 Bupplemental LER 80-001/01T-1 on 800107, during performance of STER 7902 per IE Bulletin 79-23, diesel generator 3A lost speed control Caused by deteriorated elastomer spider coupling Spider coupling replaced

 * Tennessee Valley Authority 80/04/18 2pp
- 8004220742 Forwards LER 80-027/03L-0 CALHOUN: J.R. Tennessee Valley Authority 80/04/18 ip
- --8004220750 LER 80-027/03L-0 on 800322, while performing 81 4 2, B-14, RHR6W pump D3 timer found 3-8 less than min requirement Cause unknown Timer adjusted & verified within Tech Spec tolerance 7 Tennessee Valley Authority 80/04/18 2pp
- 8004250376 Forwards upgated LER 80-011/01T-1 CALHGUNJ R Tennessee Valley Authority 80/04/18 ip
- --8004250408 Updated LER 60-011/01T-1 on 800214 analysis indicated potential loss of secondary containment should primary containment purging be conducted during hot standby concurrent w/LDCA. No cause stated Purging will be limited a Tennessee Valley Authority 80/04/18 2pp
- 8004280593 Forwards LER 80-026/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/18 1p
- ---BOD4280598 LER 80-026/03L-0 on 800322; HPCI stop valve would not open completely Caused by worn mechanical overspeed trip piston.
 Hydraulic sys adjusted & stop valve tested
 * Tennessee Valley Authority BO/04/18 2pp
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2
 F Security, medical, emergency & fire protection plans
- 8004150185 Forwards comments on 790301 safeguards contingency plan & 790901 Revision i Raquests revisions & add1 info.Enc1 withheld (ref 100FR2 790) IPPOLITO.T A Operating Reactors Branch 3 80/03/27 2pg
- Q Adjudicatory correspondence
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparadness distributed as Board notification GDSBICKL V Office of the Executive Director for Operations. 80/04/02 34pp

- H General correspondence
- 8004300404 Requests that public hearing & EIS be required for proposed law level waste compaction & incineration facility at site JURENKO:R C Affiliation Unknown 80/04/22 ip
- P Operating license stage documents & correspondence
- 8004020178 Forwards request for addl info on proposed Tech Spec changes re control & witing diagrams LAINAS.O Plant Systems Branch 80/02/11 3pp
- BOO40703B4 Discusses NRC 761123 request that all LWR licenboes assess higher fission gas release for fuel burnups above 20,000 MW-day par metric ton Rosponses indicate that no immediate licensing action is required for operating reactors IPPOLITO,T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIBENHUT.D O Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs"
 * Division of Operating Reactors 80/02/21 28pp
- 8004040127 Forwards Corrected Pages 159 & 160 to Amend 59 & Pages 157 & 158 to Amend 35 for Licenses DPR-33 & DPR-52 IPPCLITO.T A Operating Reactors Branch 3 80/03/14 4pp
- 8004110517 Forwards Amends 60,55 & 32 to Licenses DPR-33,DPR-52 & DPR-68,respectively,safety evaluation & notice of issuance & availability | PPDLITG,T A Operating Reactors Branch 3 80/03/17 2pp
- --8004110525 Amends 40,55 % 32 to Licenses DPR-33, DPR-52 & DPR-48, respectively, authorizing temporary storage of low level radwaste in existing covered pavilion, outside security fonce but inside site exclusion area IPPOLITO,T A Operating Reactors Branch 3 80/03/17 6pp
- --8004110527 Safety evaluation supporting Amends 60.55 & 32 to Licenses DPR-33,DPR-52 & DPR-68, respectively * Office of Nuclear Reactor Regulation 80/03/17 7pp
- --8004110531 Notice of issuance & availability of Amends 60,55 & 32 to Licenses DPR-33,DPR-52 & DPR-60 respectively IPPOLITO,T A Operating Reactors Branch 3 80/03/17 3pp
- BOO4150429 Advises that addl time will be needed to develop coordinated pasponse to NRC request of 800215 Response will be submitted by 800501 MILLS.L M Tennessee Valley Authority 80/04/07 ip
- 8004150557 Forwards add1 info re containment purge & venting sys, in response to NRC 800226 Itr Key lock switches are provided on control switches to allow overriding primary containment isolation signal HILLGIL M Tennessee Valley Authority 80/04/07 3pp
- 8004270028 Forwards 800120 & 0211 ltrs to GE re proposed control rod drive sys mods related to elimination of cracking in return line notices Obidelines for mods will be discussed in NUREO-O619, to be issued in "For Comment" form in Apr 1980 IPPOLITO.T.A Operating Reactors Branch 3 80/04/07 2pp
- 8004230283 Forwards request for add1 info re degraded grid voltage Also requests revised schedule for submission of design of long-term mods re adequacies of station electric distribution sys voltages IPPQLITO.T A Operating Reactors Branch 3 80/04/08 3pp
- 8004230506 Forwards info re control drive malfunctions during CY78 & 79.in response to NRC 800110 request MILLB.L M Tennessee Vailey Authority 80/04/ii, 2pp
- 8004220340 Application to amend Licenses DPR-33, DPR-52 & DPR-68 changing Tech Spers to allow conduct of short containment integrated leak rate test Fee encl.

 MILLS, L.M. Tennessee Valley Authority 80/04/15 2pp
- --8004220347 Proposed Tech Spec revisions, allowing conduct of short containment integrated leak rate test
 * Tennessee Valley Authority 80/04/15, 13pp

- --8004220358 "Nuclear Containment Testing for TVA Nuclear Power Plants," presented at ANS 791111-16 winter meeting CLARK, K H, WHITE, T J Tennessee Valley Authority 79/11/16 40pp
- BOO4220523 Responds to NRC BOO212 request for info needed to compare RETRAN code results w/simulator results & E0&0 B00317 request for info re LOCA calculational models Singer Co could more adequately address NRC request MILLS,L M Tennessee Valley Authority B0/04/15 2pp
- --B004220531 Requests assistance in comparing RETRAN & simulator results for BWR plant transients/incidents re loss of feedwater & loss of food BNL should be provided w/related info EO&G B00317 request for info encl FABIC.B Analysis Development Branch 80/02/12 4pp
- Q Inspection reports. IE Bulletins & correspondence
- 8004040174 Ack receipt of 800124 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-42, 50-260/79-42 & 50-296/79-42 & 50-296/79-42 BTYANTJ C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8004040181 Responds to NRC 800102 ltr re violations noted in IE Insp Repts 90-259/77-42,30-260/79-42 & 50-296/79-42 Corrective actions review of all previous insp data records was made to verify notification to BES engineer MILLS.L M Tonnessee Valley Authority 80/01/24 3pp
- --8004040185 Forwards IE Insp Repts 50-259/79-42,50-260/79-42 & 50-296/79-42 on 791126-27 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/02 2pp
- --8004040189 Notice of violation from insp on 791126-27
 * Region 2, Atlanta, Office of the Director 79/12/14 1p
- --B004040196 lE Insp Repts 50-269/79-42.50-260/79-42 & 50-296/79-42 on 791126-27 Noncompliance noted failure to report discrepancies to BES engineer HERDT, A Region 2. Atlanta, Reactor Construction & Engineering Support Branch MCIDENOS, L. Region 2. Atlanta, Office of the Director 79/12/14 4pp
- 8004090382 Forwards IE Bulletin BO-03, "Loss of Charcoal From Std Type II. Two-Inch. Tray Adsorber Colls " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06 2pp
- 8004090245 Forwards IE lnsp Repts 50-259/80-03,50-260/80-03 & 50-296/80-09 on 800127-31 No noncompliance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/19 2pp
- --8004090252 IE Insp Repts 50-289/80-03.50-260/80-03 & 50-296/80-09 on 800129-31 No noncompliance noted Major areas inspected refueling activities KELLOGO,P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/15 3pp
- 8004110503 Forwards IE Insp Repts 50-259/80-07, 50-260/80-07 & 50-276/80-07 on 800203-07 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004ii0514 IE Insp Repts 50-257/80-07.50-260/80-07 & 50-296/80-07 on 800205-07 No noncompliance noted Major areas inspected video observation of core spray sys sparger & review of proposed actions for LER HERDT. A Region 2. Atlanta. Reactor Construction & Engineering Support Branch VANDOURN.P K Region 2. Atlanta. Office of the Director 80/02/25 3pp
- 8004280194 Forwards IE Insp Repts 50-299/80-05,50-260/80-05 & 50-296/80-05 on 800206-08 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/07 2pp
- --8004280202 IE Insp Repts 30-259/80-05.50-260/80-05 & 90-296/80-09 on 800206-08 No noncompliance noted Major areas inspected areas of seismic analysis for as-built safety-related piping sys (IE Bulletin 79-14)
 HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENOS, L. Region 2. Atlanta. Office of the Director 80/03/04 4pp

- B004020242 Ack receipt of E00204 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-259/79-38, 50-260/79-38 & 50-296/79-38 Region 2, Atlanta, Reactor Operations Nuclear Support
- G Region 2, Atlanta, Reactor Operations Nuclear Support BO/03/11 ip
- --8004020249 Responds to NRC 800110 itr re violations noted in IE Insp Repts 50-259/79-38.50-260/79-38 & 50-296/79-38 Corrective actions local leak rate test personned on normal hatch cover & control rod drive added to CILRT results HILLS,L H Tennessee Valley Authority 80/02/04 3pp
- --8004020252 Forwards IE Insp Repts 50-259/79-38.50-260/79-38 & 50-296/79-38 on 791119-23 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/10 2pp
- --8004020259 Notice of violation from insp on 791119-23
 4 Region 2. Atlanta, Office of the Director 80/0 B0/01/08 1p
- -8004020263 IE Insp Repts 50-259/79-38.50-260/79-38 & 50-296/79-38 on 791119-23 Noncompliance noted use of temporary control rod draveline hatch cover during integrated leak rate test UPRIGHT.C M Region 2. Atlanta. Reactor Operations Nuclear Support Branch BROOKS.E H. WHITENER.H L Region 2. Atlanta. Office of the Director 80/01/08 6pp
- BOO4100344 Responds to IE Bulletin 79-23 Conducted sustained full-load operational test on Emergency Diesel Generator 3A Test demonstrated ability of diesel generators to function properly over 24-h period at specified loads HILLS.L M Tennessee Valley Authority 80/03/21 19
- 800421017B Forwards response to IE Bullstin BO-03, "Loss of Charcoal from Btd Tupe II, Two~Inch, Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority BO/03/21 App
- 800A2B0001 Supplements 800212 response to 1E Bulletin 79-18 Forwards info re procedural controls necessary until completion of ays mods for upgrading public address & evacuation alarm sys as regulared by bulletin MILLS.L M Tennessee Valley Authority 80/03/25 2pp
- 8004150527 Forwards IE Info Notice 80-12, "Instrument Failure Gauses Opening of PORV & Block Valve " No specific action or response mecessary U'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080636 Forwards IE Circular 80-05, "Emargency Diesel Cenerator Lubricating Dil Addition & Dosite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/ Region 2. Atlanta, Office of the Director 80/04/01
- BOO4:50097 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2. Atlanta, Office of the Director BO/04/02
- 8004240274 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required D'REILLY.J P Region 2: Atlanta. Office of the Director 80/04/02
- BQ04180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Bys " No written response required O'RELLLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004110021 Forwards IE Bulletin 80-07, "BMR Jet Pump Assembly Failure." Written response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04.
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Held Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/04/04 B0/04/04
- 8004180445 Forwards IE Bulletin 80-08, "Eram of Containment Liner Penetration Welds," Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/04/07

- 8004280170 Forwards monthly progress rapt for Har 1980 in response to IE Bulletin 79-14, "Seismic Analysis for As-Built Bafety-Related Piping Bys "Includes insp of drawings, pipe supports & floor & wall penetrations
 HILLS-L M Yennessee Valley Authority 80/04/07 20pp
- 8004290170 Forwards IE Insp Repts 50-259/80-12,50-260/80-10 & 50-296/80-11 on 800311-14 No noncompliance noted KENNA, H B Region 2: Atlanta, Bafeguards Branch 80/04/07 200
- --8004290177 IE Insp Repts 50-259/80-12.50-260/80-10 & 50-296/80-11 nn 004290177 It inspires 30-257/80-12.50-260/80-10 & 50-297/80-1 BOO311-14 No noncompliance noted Major areas inspected review of security plan.organization.access controls & barriers Details withhold (ref 10CFR2 790) GILLEBRIE,F Region 2. Atlanta, Bafeguards Branch TILLMAN, A Region 2. Atlanta, Office of the Director BD/04/07 Ip
- 8004270379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice MILLB, L M Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- 8004240411 Forwards monthly operating repts for Mar 1980 ABERCROMBLE, H. L. Tennesses Valley Authority 80/04/10 80/04/10
- --B004240415 Monthly operating rapts for Mar 1980 THOM.T Tennessee Valley Authority 80/04/02 32pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004180518 PNO-II-78-147 on 780818, one of six air compressors suffered massive failure resulting in rapid loss of control air pressure to all three units Caused by large hole in cylinder head of failed compressor Compressor was isolated KLINGER, O Region 2, Atlanta, Office of the Director 78/08/18
- 8004019460 Forwards LER 80~013/03L-0 GALHOUN, J R Tennessee Valley Authority 80/03/28 ip
- --8004010466 LER 80-013/03L-0 on B00301 during preparations for startup after outage for maint, offsite 161-kV power source intermittently lost power Caused by winter storm Icing & wind effects under investigation # Tennessee Valley Authority 80/03/28 ip
- 8004070288 Forwards LER 80-014/031-0 CALHOUN, J R Tennessee Valley Authority 80/03/31, ip
- --8004070289 LER 80-014/03L-0 on 800216, intent of special instruction 4 2 i3-44 not met because RHR pump C in operation in torus cooling mode when special instruction performed Caused by procedural inadequecy for experienced plant configuration # Tennessee Valley Authority 80/03/31. 2pp
- 8004150515 Forwards LER 80-015/03L-0 CALHOUN, J.R. Tennessee Valley Authority, 80/04/07, 1p.
- --8004150522 LER 80-015/03L-0 on 800307 during startup rod block monitor A was bypassed for more than 24-hrs in 30-day period Caused by need for calibr & maint Channel recalibr tested & returned to sve Tennessee Valley Authority 80/04/07 2pp
- 8004140433 Forwards LER 80~017/03L-D. CALHOUN,J.R. Tennessee Valley Authority 80/04/08, ip
- ~~8004i40436 LER 80-0i7/03L-0 on 8003i0, while performing surveillance instruction 4 5.E i.HPCI turbine tripped Caused by failed rupture disc in turbine exhaust line Rupture disc replaced * Tennesses Valley Authority 80/04/08 2pp.
- 8004190451 Forwards LER 80-016/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/08 1p
- ~~8004180497 LER 80~016/03L~0: on 800310, after startup, discovered roof valve failure after being closed during short outage to allow repair on instrument panel Caused by blocked sensing line & slow beak Valve mechanically cleared * Tennesses Valley Authority 80/04/08 2PP
- 8004220649 Forwards LER 80-018/03L-0.
 CALHOUN, J.R. Tennessee Valley Authority 80/04/18 1p.

- ~-8004220680 LER 80-018/03L-0 on 800321, during normal operation, 2A reactor recirculation motor generator set tripped Caused by generator stator temp high relay actuation * Tennessee Valley Authority 80/04/18 2pp
- DOCKET 90-261 H B ROBINSON PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8004070313 Forwards response to NRC 800207 questions re fire protection Add1 responses will be submitted no later than 800401 Mods necessary to provide adequate fire protection will be completed by 801031
 UTLEY.E E Carolina Power & Light Co 80/04/01 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification gospicki, L V Office of the Executive Director for Operations 80/04/02 34pp
- I Financial information
- 8004010405 Forwards Annual Financial Report 1979 Also forwards info re cash flow projection, to guarantee retrospective premium liability to nuclear liability insurance carriers GRAHAM.W E Carolina Power & Light Co 60/03/27 App
- --8004010409 Annual Financial Rept 1979 * Carolina Power & Light Co 80/03/01 36pp
- J Insurance & indemnity information
- BOC4180344 Forwards Endorsement 43 to NELIA Policy NF-180 GRAHAM.W E Carolina Power & Light Co 80/04/11 2pp
- BD04240379 Forwards Endorsement 51 to MAELU Policy MF-49 QRAHAM.W E Carolina Power 8 Light Co 80/04/17 2p
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT, D O Division of Operating Reactors 80/03/12 3pp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004280148 Forwards Amend 46 to License DPR-23 & notice of issuance & availability
 BCHWENCER, A Operating Reactors Branch 1 80/03/13 3pp
- --8004280151 Amend 46 to License DPR-23, revising Tech Spacs to reflect corporate & plant organizational changes BCHWENCER.A Operating Reactors Branch 1 80/03/13 16pp
- --B004280156 Notice of issuance & availability of Amend 46 to License DPR-23. SCHWENCER, A Operating Reactors Branch 1 80/03/13 2pp
- 8004010324 Informs of addition of onsite diesel generator for auxiliary shutdown sys, to be installed & operational by 801031 Forwards Figures 1-15 to be substituted for Figures 1-14 of 800201 submittal UTLEY, E E Carolina Power & Light Co. 80/03/21 14pp
- 8004020076 Forwards request for add1 info re electricial & instrumentation aspects of containment purging Advises that 791207 commitment meets NRC interim position re purge & vent valve operation pending resolution of isolation operability SCHWENGER.A. Operating Reactors Branch 1. 80/03/21 4pp
- 8004020307 Supplements 800225 ltr re-preliminary results of Zircaloy guide tube wear measurement Subsequent analysis assures no safety concern re-assembly integrity & control rod scram capability

 OWBLEY, OF Exxon Nuclear Co., Inc. (subs of Exxon Corp.). 80/03/29 1p

- 8004040273 Forwards suppl to 74i218 application for amend to License DPR-23 Revision commisses of rewording of proposed changes to Items B through EDF Paragraph 2 & description of health physics program UTLEY,E E Carolina Power & Light Co 80/03/31
- --8004040297 Suppl to 741218 application to amend License DPR-23 Revision consists of rewording of proposed changes to Items B through E of Paragraph 2 & description of health physics program # Carolina Power & Light Co 80/03/31 4pp
- 8004080648 Forwards suppl to 791231 response to Lessons Learned Task Force short-term requirements Describes pressurizer level 5 mods to control switches UTLEY, E E Caralina Power & Light Co 80/03/31 50pp
- 8004250029 Forwards list of addl info needed to complete review of auxiliary feedwater sys.containing NRC positions on certain recommendations Requests response within 30 days from itr receipt Revised version of endurance test requirements encl 8CHWENCER, A Operating Reactors Dranch 1 80/03/31 11pp
- 8004140413 Submits addl info re implementation of Task Force shortterm Lessons Learned requirements Discusses replacement of switch for radiation monitors R-11 & R-12 circuits & mod to power operated relief valve position indication UTLEY.E E Carolina Power & Light Co 80/04/04 3pp
- 8004300443 Confirms 791231 plans, reviewed w/ NRC, re interim implementation of shift technical advisor program SROs will be substituted for shift technical advisors undergoing planned training
 UTLEY.E E Carolina Power & Light Co 80/04/25 ip
- Q Inspection reports. IE Bulletins & correspondence
- 8004070134 Forwards 45-day response to IE Bulletin 79-01 W/o encl FURR:B J Caroline Power & Light Co 80/03/10 1p
- 8004280099 Forwards IE Insp Rept 50-261/80-05 on 800220-21 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/14 2pp
- --8004280109 IE Insp Rept 50-261/80-05 on 800220-21 No noncompliance JOARDOOM IE Insp Rept 50-26/20-03 on 800220-21 No moncompitance noted Major areas inspected areas of seismic analysis for as-built safety-related piping sys (IE Bulletin 79-14) HERDIAR Region 2, Atlanta, Reactor Construction & Engineering Support Branch MODENOSI. Region 2, Atlanta, Office of the Director 80/03/13 4pp
- 8004100343 Responds to IE Bulletin 80-03 No charcoal colls of ref type are used at facility FURR.B J Carolina Power & Light Co 80/03/21 6pp
- 8004;50497 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary response necessary
 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/31
- 8004080598 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gli Addition & Onsite Supply " No written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/04. Region 2. Atlanta, Office of the Director 80/04/01
- 8004140462 Ack receipt of 800314 ltr informing NRC of steps taken to correct violation moted in IE Insp Ropt 80-261/80-01 8TOHR. J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/01 1p
- --8004140468 Responds to NRC 800225 itr re violation noted in IE Insp Rept 50-261/80-01 Corrective actions written procedures re gamma rays are being developed STARKEY/R B Carolina Power & Light Co 80/03/14 2pp
- --8004140473 Forwards IE Insp Rept 50-261/80-01 on 800204-07 & notice of violation STOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Bafoty Branch 80/02/25 2pp
- --BOO4140477 Notice of Violation from insp on BOO204-07 * Region 2, Atlanta, Office of the Director BO/0 80/02/22 1o

- --80041404B) IE Insp Rept 50-261/80-01 on 800204-07 Noncompliance noted failure to have & foilou uritten approved procedures for radiochemical measurements
 JENAINS, G R Region 2. Atlanta, Fuel Facility & Materials Safety Branch MONTODMERV, D M Region 2. Atlanta, Office of the Director 80/02/22 Bpp
- B004i500A7 Forwards IE Info Notice 80-13. "GE Type SBM Control Suitches Defective CAM Followers ' No specific action or response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/02
- E304240245 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required D'REILLY, J P Region 2 Atlanta, Office of the Director 80/04/02 Zoo
- E3004180378 Forwards IE Circular 80-07, "Problems W/MPCI Turbine Dil Sys " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03 200
- GIO04230117 Forwards IE Bulletin 79-03A 'Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY. J P Region 2. Atlanta. Office of the Director BO/04/04 ip
- E004180340 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds" Hritten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 2pp
- E3004250251 Act receipt of 800320 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/80-03 STOHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/04/09 ip
- ---8004250261 Responds to PRC 800227 ltr re violations noted in IE Insp Rept 50-261/80-03 Corrective actions acid & battery removed Shipping container reinspected & resealed for shipment Labeled containers of radioactive mat1 STARKEY.R B Carolina Power & Light Co 80/03/20 3pp
- ---8004250275 Forwards IE Insp Rept 50-261/80-03 on 800204-06 & notice of violation
 STORR.JP Region 2. Atlanta. Fuel Facility & Materials Safety
 Branch 80/02/27 2pp
- --8004250282 Notice of violation from insp on 800204-06 * Region 2, Atlanta, Office of the Director 80/02/26 ip
- --B00425027i IE Insp Rept 50-261/80-03 on B00204-06 Noncompliance noted failure to properly label containers of radioactive matl & to follow procedures
 OIBSDN:A F Region 2: Atlanta, Fuel Facility & Materials Safety
 Branch PUCKETT, J M. WRAY, J R Region 2: Atlanta, Office of the Director B0/02/26 6pp
- R Periodic operating reports & related correspondence
- S1004040305 Forwards "Annual Environ Surveillance Rept,1979 " STARKEY R B Carolina Power & Light Co 80/03/31 ip
- BOO4150374 Forwards monthly operating rept for Har 1980 STARKEY,R B Carolina Power & Light Co 80/04/09 1
 - 3004150376 Monthly operating rept for Har 1980 WATFORD, M L Carolina Power & Light Co 80/04/01 3pp
 - Reportable occurrences, LERs & related correspondence
- E-004080361 PNG-II-80-044 on 800314, reactor shut down for regair of primary-to-secondary steam generator leat During outage, 480-volt power transfer switch operated, causing loss of power to half of ECCS valves Cause under investigation HARDIN, A K , KELLGOO, P J Region 2, Atlanta, Office of the Director 80/03/17 1p
- BOO4030171 RO on 800324, determined that potential generic problem could exist in Westinghouse relay Model NBFD-315 Three relays have exhibited coil failures due to shorting of lead-in wires Westinghouse is investigating problem STARKEY, R B Carolina Power & Light Co 60/03/24 ip

- 8004100340 Forwards LER 80-006/01T-0 BTARKEY, R B Carolina Power & Light Co B0/04/04 ip
- --8004100345 LER 80-006/017-0 on 800324, w/plant at cold shutdown for steam generator maint, three relay coils in B train found failed & one coil found contacting ground in B battery bus Caused by shorting of outer layer of coil windings STARKEY, R B Carolina Power & Light Co 80/04/04 2pp
- 8004180418 Forwards LER 80-004/03L-0 STARKEY, R B Carolina Power & Light Co 80/04/14 1p
- --8004180425 LER 80-004/03L-0 on 800316.w/facility shut down w/primary sys at 350 psig & 250F in RHR recirculation mode.loss of power to all MCC-5 & 10 loads occurred Caused by overcurrent trip of MCC-5 main power transfer switch Settings reset STARKEY.R B Carolina Power & Light Co 80/04/14 4PP
- 9004230520 Forwards LER 80-005/03L-0 STARKEY,R B Carolina Power & Light Co 80/04/19 ip
- --B004230525 LER B0-005/03L-0 on B00320 during cold shutdown while performing PT 42 0, valve CCW-626.RCP thermal barrier outlet containment isolation valve failed to close Caused by loose locknut Nut tightend & staked STARKEY.R B Carolina Power & Light Co B0/04/19 2pp
- 8004240342 Forwards LER 80-007/03L-0 STARKEY, R B Carolina Power & Light Co 80/04/21 ip.
- --8004240366 LER 80-007/03L-0 on 800326, data from previous instrument calibr identified that first stage pressure transmitters PT-446 & PT-447 on turbine were found out of calibr nonconservatively Caused by instruments drifting high STARKEY, R B Carolina Power & Light Co 80/04/21 2pp
- DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

 F Becurity, medical, emergency & fire protection plans
- 8004090223 Submits results of drywell safe shutdown analysis required by NRC 790829 fire protection safety evaluation No add1 fire protection provisions needed During normal operation drywell inerted w/nitrogen/reducing oxygen & combustion possibility MAYER/L O Northern States Power Co 80/03/31, 2pp
- 8004080508 Submits design info for installation of sprinkler curtain to cool hot gases entering cable tray area in water treatment & engineered safety feature motor control ctrarea, as discussed in fire protection safety evaluation MAYER.L O Northern States Power Co 80/04/01 3pp
- 8004080368 Forwards design info re mod to cable spreading room, standby gas treatment sys room, switchgear areas, intake structures & motor generator set room, as required by NRC 790827 fire protection SER MAYER, L O Northern States Power Co. 80/04/02 ip
- HOO4080479 Forwards security plan, Revision 9 pages Encl withheld (ref 10CFR2 790) MAYER, L.O. Northern States Power Co. 80/04/03 1p
- 8004180357 Forwards "Evacuation Time Estimates" in response to NRC 791129 1tr MAYER, L.O. Northern States Power Co. 80/04/10 1p
- --8004180360 "Evacuation Time Estimates "
 * Northern States Power Co. 80/04/30 18pp.
- 8004230387 Forwards input for fire protection review. Items 3 i. 8(5 & 6) & 3 2 2(1), fire barriers/penetration seals & Item 3 i 12(2), yard loop Recommends approval of licenses submittals recriteria & test procedures & proposed mods HALL, R E Brootheven National Laboratory 80/04/14 3pp.
- O Adjudicatory correspondence
- 8004030026 Memorandum of understanding butween NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp

- P Operating license stage documents & consespondence
- OOOAO70717 Discusses NRC 76112) request that all LVR licensess assess higher Pission gas release for fuel burnups above 40,000 MM day per metric ton Responses indicate that no immediate litensing action is required IPPOCITAL TA Operating Reactors Branch J DO703710 Spp
- UOOAGGOTO-Forwards "Musican Data Link Opers." study of digital communication sys to transmit info from plants to Dethesda Operations (tr (IGCNMUT.D O Division of Operating Reactors (DOOG)/12 Spp
 - 00040 10110 "Nuclear Data Link Upers "
 # Division of Operating Reactors 180702721 2Upp
- 0004070.1/f) forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is trainessed in the beatty physics info doring the ident or abnormal occurrence at facility RIPPIIR JO Region O Chicago Uffice of the Disector 00/03/19 Opp
- HOO4100100 Requests controlled set of PSIDs for each plant Dubmittal should be forwarded to attention of Region i incident response ctr within 20 days. HipPrint J. Beginn i. Chicago, Hiffice of the Director. 80709720
- BOOM1000TF Intwards "Evaluation of Licensee Compliance McCategory A Items of NHC Recommendations Resolting IIII & Lessons Learned " All Category A requirements satisfactority met Mode will be verified by II IPPOLITHET A. Operating Resitus Branch J. 80/01/21 Lipp.
- HOO4040'119 Advises that mod of reactor protection sys supply protective circuitry will be parformed when qualified equipment is available from QI MAYCELL () Northern Blates Power Co. 19970 1736 1p.
- BUCADIDATO Notifies that piping supports between automatic pressurs tells valve accomplator (herk valves & valve operators will be upgraded to correct lessen: Class 1 criticals prine to startup following current refueling outsign (LIABRALR R. Northern litates flows) (b. 1070/1720 tp.
- 110040(B)),?/J Notifies of revised schedule for installing containment penetrations for recombines in igthal Feb 1910 schedule not met due to problems developed w/containment contains valves Addl design & fabrication work required MAYUN, I O Morthern States Fower to IBP/04/01 Ip
- BOUGESOORI Forwards HENRY & ORIF Itys to G. is proposed control rod drive spa mads related to elimination of a 18 proposed of the graph of the installation of transling in 1 line untales Outdellines for mode will be distinsted in Midfl Colfo. to be a several in the Comment form in Apr 1 IPPO 116.7 A Operating Resitur distinct 1 (0204207) 1.9610
- it Inspection reports. It hollettes & correspondence
- 0004040405 forwards If Insp Rept 50 25'1/00 03 on 000114 No TORCLLIO Region A Chicago, Reactor Construction & Engineering Upport Branch 80/03/16 Jpp
 - H004040410 to the Rept 30 JAJ/H0 Ot on Whill4 No nuncompliance noted Hajor erass inspected actions of thitistin 79 14 general discussion of NRC requirements procedure rasses & review OF atrees calculations
 DANHIGORD H. YIM. I T. Region J. (Nikago, Office of the Director 180702711 Spp.
- H004100143 Forwards II. Info Hotics 80 OH. "Nighter Co Sittling Link Clastrical Yerminal Block" Hn specific artion or response required REPPLEATING Region 7. Chicago: Office of the Director - 00/03/07
- HOOAOBOAD? Forwards If Insp Rept 80 264/8d Bl no 800204 OB & notice of Violation Motice of Violation withheld fraf 100/82 7901 HIND-J A. Region D. Chicago. Bafeguards Branch. 00/03/18 2pp
- HIND, J.A. Region G. Chicago, Bafeguards Branch USTICK. CHRISTOPESS.O. Region J. Chicago, Defice of the Director 80/03/08 Rep USTICK. N .

- 8004150184 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLERIJ © Region 3, Chicago, Office of the Director 80/03/31
 - Region 3. Chicago, Office of the Director 80/03/31
- 0004000/19 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/01
- 0004150092 Forwards IC Info Notice 80-13, "GE Type SBM Contro) Switches Defective CAM Collowers " No specific action or response 10061104 KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 1004180055 Forwards attachments to IE Circular 80-03, "Protection From Toxic Qas Haiards," inadvertently emitted from 800306
- Total variation in independently united from 55555 transmittal KCPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220148 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 80042203/8 Forwards IC Circular 80-07, "Problems W/HPCI Turbine Oil 10420370 Forwards it treests and an all of the Director BO/04/03 KEPPLER. J O Region 3. Chicago, Office of the Director BO/04/03
- 800411004/ Forwards IE Bulletin 80-07, "BHR Jet Pump Assembly Failure " Written response required Milton response required MLPPLER.J O Region 3. Chicago, Office of the Director 80/04/07
- 8004230297 Forwards IE Bullotin 79-03A. "Longitudinal Weld Defects in ASHE BA-312. Type 304 Stainless Steel Pipe " Action required KEPPLER, J. O. Region 3. Chicago, Office of the Director 80/04/07
- 6004220047 Forwards II Bulletin BO-OB, "Exam of Containment Liner Penetration Helds" Written response required KEPPLFR.J G Region 3. Chicago. Office of the Director BO/04/09
- R Periodic operating suports & related correspondence
- 6004150401 Forwards monthly operating rept for Mar 1980 MAYLR.t () Northern States Power Co 80/04/10 ip
- HOQ4150405 Monthly operating rept for Mar 1980
 HYRABDIA L Northern States Power Co 80/04/04 4pp
- B Reportable accurrences. LERs & related correspondence
- 0004220247 PND-77-033 on 770223, during reactor startup, period of less than 5-s was obtained before reactor tripped on lowest level intermediate range Caused by combination of temp & high renon concentration
 OCWER.O C . RUY.O W THO
 Director 77/02/25 2pp THOMPSON.D Region 3. Chicago, Office of the
- 0004010492 Forwards LER 80-015/01T-0 MAYER, L D Northern States Power Co 80/03/27 ip
- ---B004010485 LER E0-015/01T-0 on B00317 during refueling outage & insprequence by IE Bulletin 79-01B, unqualified splices found in power cables for imboard MBIV solenoid valves Gause not stated Eplices replaced w/qualified matls HAMMER.M F Northern States Power Co B0/03/27 ip
- 8004130843 Farwards LERs 80~002/01T-0,80~003/01T-0,80~004/01T-0, 80~005/01T-0,80~008/01T-0,80~009/01T-0,80~010/01T-0, 80 012/01T-0 & 80~014/01T-0 HAYER,L 0 Northern States Power Co 80/04/08 ip
- --B004150555 LER 80-002/017-0 on B00225, during refueling outage, local leak rate for A0-2-B6A outboard MSIV exceeded Tech Spec acceptance criteria Caused by poppet not seating properly Poppet machined & stem replaced OVERLID.T H Northern States Power Co B0/04/08 19

- --5004150554 LER 80-003/017-0 on 800225.during refueling outage.local trait rate for A0-2-05D outboard MSIV.exceeded Tech Spec acceptance criteria Caused by lapping of main seat so that poppet did not seat properly Poppet rachined OVERLID T W Northern States Power Co 80/04/08 Ip
- --8004150571 LER 80-004/01T-0 on 800223, during local leak rate testing.

 HPCI-9 turbing enhaust line check valve found leaking in
 excess of Toch Spec acceptance criteria Caused by leakage
 past body-to-seat ring threaded joint
 SHURTS.S J Northern States Power Co 80/04/08 1p
- --B0041505B0 LER B0-005/01T-0 on 800303, during local leak rate testing, AP-6 standby liquid control outboard isolation valve, found leaking in excess of Tech Specs Caused by accumulation of scale on seat Replaced valve SHURTS, S J Northorn States Power Co B0/04/08 ip
- ---B004150559 LER 80-003/01T-O on B00303.during local leak rate testing.
 A0-2876 torus vent isolation valve found leaking in excess
 of Tech Spec acceptance criteria Cause undetermined Valve
 disasse-bled, inspected, cleaned & reassembled
 SHURTS, S J Northern States Power Co B0/04/08 ip
- --800415059B LER 80-009/01T-0 on 800304.during refueling outage.local leak rate for RCIC-9 turbine exhaust check valve, exceeded Fach Spec acceptance criteria Probably caused by downstream check valve jacked shut for test Valves lapped & retested SHURTS,S J Northern States Power Co 80/04/08 ip
- --B004150610 LER B0-010/01T-0 on B00324, during local leak rate testing. CV-7956 torus instrument air isolation valve found leaking in excess of Tech Spec acceptance criteria Apparently caused by dirt on seat Valve cleaned & reassembled IVERSON.O N Northern States Power Co 80/04/08 1p
- ---B004150617 LER B0-012/01T-0 on B00307, during local leak rate testing, AD-2561A drywell equipment drain sump isolation valve found leaking in excess of Tech Specs Caused by packing leak Packing tightened HINDSCHILL, J E Northern States Power Co 80/04/08 1p
- --8004150623 LER 80-014/01T-O on 800314, during refueling outage, local leak rate for A0-2-80A inboard MSIV exceeded Tech Spec acceptance criteria Caused by poppet not seating properly New poppet & stem installed OVERLID.T W Northern States Power Co 80/04/08 ip
- B004140370 Responds to NRC B00110 ltr requesting update of control rod drive sys malfunctions through 1979 Two drives stopped at position 02 during 1978 & 1979 Caused by stop piston seal leakage Drives removed & rebuilt during fuel outages MAYER.L O Northern States Power Co 80/04/09 2pp
- 8004140431 Forwards LER 60-016/01T-0 MAYER.L O Northern States Power Co 80/04/10 1p
- --8004140437 LER 80-014/01T-0 on 800327, during refueling, supports for SRV pneumatic supply sys would not meet seismic Class I requirements Caused by inadequate design & installation of sys Sys was upgraded to satisfy requirements

 OVERLID.T W Northern States Power Co 80/04/10 ip
- 8004180468 Forwards LER 80-017/01T-0 MAYER, L O Northern States Power Co 80/04/11 10
- --8004180472 LER 80-017/01T-0 on 800328, Bechtel Power Corp notified util that control rod driveline hydraulic piping frame supports would not meet OBE stress limits Caused by EDS computer code error Supports modified DAY.8 D Northern States Power Co 80/04/11 ip

DOCKET SO-264 DOH CHEMICAL CO

- P Operating license stage documents & correspondence
- B004220533 Advises that Section 316 documents re NNPDES Permit AL0022080 are being sent to JW Warr.H Zeller & LB Tebo,in accordance w/util 800331 ltr EL-ASHRY.M T Tennessee Valley Authority 80/04/17 2pp

- DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- BOO4240531 Forwards sys description & operating instructions for NRC health physics telephone network Bys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimile traffic KEPPLER, J O Region 3. Chicago, Office of the Director 80/03/20 200
- 8004070272 Forwards input to facility fire protection review for fire detection systwater suppression sys & foam suppression sys Info completes items for which adequate licensee input exists
 HALL, R E Brookhaven National Laboratory 80/03/31 5pp
- 8004070273 Forwards Pages C-26 & C-27 of Revision 5 to security plans, omitted from 800324 submittal Encl withheld (ref iOCFR2 790)
 PEOPLES D C Commonwealth Edison Co 80/04/02 ip
- 8004230524 Forwards revisions to 800331 ltr re fire protection review, Item 3 1 l.fire detection sys.ltem 3 1 5.water suppression sys. & Item 3 1 6.foam suppression sys. & Item 3 1 6.foam suppression sys. HALL, R E Brookhaven National Laboratory 80/04/16 5pp
- BOO4230367 Forwards revised security plan Revisions withheld (ref 10CFR2 790) PEDPLES, D L Commonwealth Edison Co 80/04/21 1P
- P Operating license stage documents & correspondence
- 8004080276 Forwards corrected Pages 88 % 93 for Licenses DPR-19 Amend 44 % DPR-25 Amend 39 % corrected Pages 3 6/4 6-2 % 3 6/4 6-9 for Licenses DPR-29 Amend 53 % DPR-30 Amend 50 in response to 791002 ltr
 IPPDLITG.T A Operating Reactors Branch 3 80/02/20 2pp
- --8004080310 Corrected License Pages 88 % 93 for Amends 44 % 39 to Licenses DPR-19 % DPR-25, respectively & corrected License Pages 3 6/4 6-2 % 3 6/4 6-9 for Amends 53 % 50 to Licenses DPR-29 % DPR-30, respectively * Operating Reactors Branch 3 80/02/20 8pp
- 80040703B1 Discusses NRC 76i123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MH-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- BOO4030102 Forwards "Nuclear Data Link Spocs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENMUT, D O Division of Operating Reactors BO/03/12 Spp
- ---8004030i18 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28ee
- 8004i00i02 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days

 KEPPLER. J G Region 3. Chicago. Office of the Director 90/03/20 lp
- 8004100313 Natification of 800325 meeting w/util & OE to discuss demonstration bundles
 8EVAN,R Operating Reactors Branch 3 80/03/21 2pp
- 8004i503i6 Forwards revised pages constituting Revision i3 to CE-i-A, GA program Revisions reflect recent organization title changes
 NAUGHTON:W F Commonwealth Edison Co 80/04/02 ip
- ---800419032B Revised pages constituting Revision 13 to QA program Revisions reflect recent organizational title changes.

 ** Commonwealth Edison Co CE-i-A RI3 B0/04/04 7pp.
- 8004180217 Forwards addi info re failure of control rods to insert fully on scram in response to NRC 800110 & 11 ltrs. Dresden 1 experienced no control rod failures in 1978-79 Failure at other facilities caused by leakage past worn piston seals. JANECEK.R F Commonwealth Edison Co 80/04/14. 10pp

- 8004250427 Forwards response to NUREO-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util energency plan will be submitted w/Lasaile County site-specific energency plan PEOPLES.D L Commonwealth Edison Co 80/04/15 60pp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Fac(littes " * Bechtel Power Carp (subs of Bechtel Corp) 79/12/26 32pp
- 8004240412 Advises of review & plans re reload core Forwards Table 1 providing summary of key parameters W/approvel of Amend 51 to DPR-30, util concludes that addl Tech Spec changes not required Reload core design will be verified by std tests PEOPLES, D. L. Commonwealth Edison Co. 80/04/17 4pp
- G Inspection reports, IE Bulletins & correspondence
- 8004040029 Forwards IE Insp Repts 50-284/79-30 & 50-265/79-28 on 791211-14 No noncompliance noted DAVIS, A B Region 3, Chicage, Fuel Facility & Materials Bafety Branch 60/02/12 2pp
- --8004040034 IE Insp Repts 50-254/79-30 & 50-265/79-28 on 791211-14 No noncompliance noted Major areas inspected licensees data, repts & experience in meeting design objective gaseous release rate for radioiodine & radiactive matl HUETER, L J Region 3, Chicago, Office of the Director FIBHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/06 Spp
- 8004100140 Forwards Waste Packaging Insp Ropt 79-07A on 791212-13 No noncompliance noted DAVIS.A D Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- ---8004100408 Waste Packaging 79-07A on 80791212-13 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations including shipping paper requirements, radiation levels & DOT labeling POTTER, J P Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 App
- B004100192 Forwards IE Insp Repts 50-254/80-03 & 50-265/80-03 on B00119-16 & 0211 No noncompliance noted FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Bupport Branch B0/02/28 2pp
- --8004100207 IE Insp Repts 50-254/80-03 & 50-265/80-05 on 800115-16 & 0211 No noncompliance noted Major areas inspected torus support GA/GC program, procedures, work activities & feedwater sys welds
 DANIELBUND H Region 3. Chicago, Reactor Construction & Engineering Support Branch WARD, K D Region 3. Chicago, Office of the Director 60/02/25 9pp
- 8004080617 Forwards IE Insp Repts 50-254/80-01 & 50-265/80-02 on 800102-0201 No noncompliance noted.

 HEISHMAN R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/27 2pp
- ---B0040B0625 IE Insp Repts 50-254/B0-01 & 50-265/B0-02 on B00102-0201 No noncompliance noted Major areas inspected maint plant operations, physical protection & followups BPESBARD, R L., CHRISBOTIMOS, N. Region 3, Chicago, Office of the Director B0/02/25 7pp
- B004280020 Forwards IE Insp Rept 50-265/80-07 on 800130-31 No noncompliance noted FIGRELLI, G Region G, Chicago, Reactor Construction & Engineering Bupport Branch 80/03/06 2pp
- --8004280025 IE Insp Rept 50-265/80-07 on 800130-31 No noncompliance noted Major areas inspected IE Bulletin 80-02, inadequate QA for nuclear supplied equipment & examination of QE replacement feedwater sparages BANIELSON.D H Region S. Chicago, Reactor Construction & Engineering Support Branch KEY, W. J Region 3, Chicago, Office of the Director 80/02/27 3pp
- 8004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required.

 KEPPLER, J G. Region 3, Chicago. Office of the Director 80/03/07 in
- BOO4140119 Forwards response to IE Bulletin BO-03, "Loss of Charcoal from Btd Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES, D L. Commonwealth Edison Co 80/03/20. Spp.

- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.A Il Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/03/21 tp
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A, on 791212-13 No noncompliance noted DAVIS A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- ~~8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placanding requirements radiation levels, removable contamination & package external features POTTER, J P Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- 8004150159 Forwards IE info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary XEPPLER.J G Region 3. Chicago, Office of the Director 80/03/31
- 8004080686 Forwards IE Carcular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Bupply " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/01
- 8004150014 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02 to
- 8004180030 Forwards attachments to IE Circular B0-03, "Protection From Toxic Oas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220093 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/02
- 8004220324 Forwards IC Circular 80-07, "Problems W/HPCI Turbine 0:1 Bys " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/04/03
- B004220069 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director B0/04/09
- 8004110025 Forwards 1E Bulletin 80-07, "BWR Jet Pump Assembly Failure "
 Written response required
 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/07
- 8004230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME 8A-312.Type 304 Stainless Steel Pipe " Action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/07
- 8004280628 Forwards revised Pages 3 & 5 % omitted Page 4 to IE Insp Repts 50-010/80-05, 50-237/80-05, 50-247/80-05, 50-254/80-05 & 50-265/80-08 FIGRELI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 60/04/09 ip
- --8004280634 Revised Pages 3 & 5 & omitted Page 4 to 1E Insp Repts 50-010/80-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 & 50-265/80-08 * Region 2, Atlanta, Office of the Director 80/04/09 3pp
- R Periodic operating reports & related correspondence
- B004150004 Forwards "Radioactive Waste & Environ Monitoring.Annual Rept.1979 " Rept constitutes Part 3 of facility operating rept KALIVIANAKIS.N Commonwealth Edison Co 80/03/06 1p
- --B004150007 "Radioactive Waste & Environ Monitoring Annual Rept.1979, "
 * Eberline Instrument Corp 80/03/31 91pp

- 220333 Forwards listing of changes, tests & experiments performed in r 1980 LIVIANAKIS,R Commonwealth Edison Co BO/04/14 Spp
- eportable occurrences. LERs & related correspondence
- 080573 Updated PND-111-80-045B licensee ultrasonic examination of respray piping in A & B loops located in drywell mpleted Puping will be replaced w/low carbon stepl pipe in in 187590TIMOS.N. SPESSARD.R.L. Region 3. Chicago. Office of the rector 80/03/14 2pp
- 020435 Forwards supplemental LER 79-009/03L-1 LIVIANAKIS,N Commonwealth Eduson Co E0/03/17 ip
- 104020443 Supplemental LER 79-009/03L-0 on 790429, while measuring MSIV limit switchtrip position.13 of 16 switches were sot at greater than 10% of MSIV closure Caused by failure to field calibre react limit switch trip point Switches adjusted VAHRENHALD.J Commonwealth Edison Co 80/03/17 2pp
- (030110 PND-111-80-051 on 800314, ultrasonic testing performed on) jet pump holddown beam assemblies at Unit 3 Pumps 5,9,11 8 20 beam indications ranged from greater than 6 ls to approx 20 mils Pump w/largest indication removed RISBUTINOS, N., BARKER, J. L., SPESSARD, R. L. Region 3, Chicago, fice of the Director 80/03/17 1pp
- 020352 Forwards LER B0-006/01T-0 LIVIANAKIS, N Commonwealth Edison Co 80/03/22 ip
- 104020399 LER 80-005/017-0 on 800308, while performing reactor vessel pressure test, several crack indications were discovered in pipe to elbow welds Cause not determined Affected pipe sections will be replaced w/carbon steel piping CLARK, D Commonwealth Edison Co 80/03/22 7pp
- 020430 Forwards LER 80-005/03L-0
 «LIVIANAXIB.N Commonwealth Editor Co 80/03/24 ip
- 104020445 LER E0-005/03L-0 on 800303.while performing LPCI & containment cooling modes of RHR9 logic test.5-s delay timer 10A-M2A for 10228 RHR pump failed to actuate relay K21A Relay failed to energise Caused by Microswitch drift HAFERA.T Commonwealth Edison Co 80/03/24 2pp
- 150402 Forwards LER 80-008/03L-0 LIVIANAKAB, N Commonwealth Edison Co 80/03/26 1p
- 004150498 LER 80-008/03L-0 on 800305, while performing LPC1 & containment cooling modes, two 5-8 delay timers for starting 10020 RNR pump failed to actuate timer contacts Caused by microswitch arm being out of alignment HOELLER, J. Commonwealth Edison Co. 80/03/26 2PP
- IZZO613 Forwards LER 80-007/03L-0 LIVIANAKAS,N Commonwealth Edison Co 80/04/09 1p
- 204220623 LER BO-007/03L-O on BO0316. while ultrasonically inspecting jet pump fixture beam assemblies one through RO, width-wise cract indication discovered along upper surface of pump 16 near bolt Gaused by intergranular stress corrosion MURRAY.R. Commonwealth Edison Co BO/04/09 3pp
- 1270380 Forwards LER 80-009/03L-0 LIVIANAKIB,N Commonwealth Edison Co 80/04/21 1g
- 104290407 LER BO-009/03L-O on B00322, while performing PCI simulated automatic closure initiation test, procedure GOS 1600-13, transient in-core probe 2. failed to respond to Group 2 isolation signal Caused by dirty contacts on relay K21 REED, M Commonwealth Edison Co BO/04/21 ip
- (ET 50-264 POINT BEACH NUCLEAR PLANT, UNIT 1 Jecurity, medical, emergency & fire protection plans
- 108022) Forwards operating instructions & characteristics of NRC salth physics telephone network Purpose of metwork is ansmission of health physics info during incident or inormal occurrence
 PPLER, J. G. Region 3: Chicago

- 8004010336 Forwards fire protection review Items 3 1 17.3 1 25.3 2 2 & 3 2 6 Licensee proposed mods to hydrogen sys & reactor coolant pump oil collection sys are only partly acceptable NRC should request drawings re mods proposed in Item 3 2 2 HALL.R E Brookhaven National Laboratory 80/03/26 5pp
- 8004020410 Forwards estimates of evacuation times for area surrounding plant, per NRC 791129 ltr request FAY. C W Wisconsin Electric Power Co 80/03/26 9pp
- 8004290428 Responds to 800305 ltr re status of NRC review of plant firs protection program List re status of resolution of incomplete items encl BURSTEIN.S Wisconsin Electric Power Co 60/04/21 2pp
- G Adjudicatory correspondence
- 8004010389 Protests licensees failure to serve filings re steam generator tube degradation Reiterates request for relief as stated in 800226 ltr & requests NRC to direct licensee to serve documents
 FALK.K M Wisconsin's Environmental Decade 80/03/27 2pp
- B004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification COSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004230010 Forwards Ofc of Nuclear Reactor Regulation 800404 order requiring that testing be performed within 90 effective full power days Health & safety will not be endangered by continued operation 8CHNENCER. A Operating Reactors Branch 1 80/04/04 2pp
- --8004230014 Mod of 791130 order deleting & replacing Condition 1 of Section IV Testing must be performed within 70 effective full power days Health & safety will not be endangered by order remaining in effect Safety evaluation encl
 CASE,E G Office of Nuclear Reactor Regulation 80/04/04 5pp
- --8004230017 Safety evaluation re-steam generator tube degradation due to deep crevice corrosion Continued safe operation may be permitted within confirmatory order terms * Office of Nuclear Reactor Regulation 80/04/04 17pp
- I Financial information
- B0042904iB Forwards Annual Financial Rept 1979 & certified financial statements
 ORTECH.J H Wisconsin Electric Power Co B0/04/22 19pp
- --8004290425 Annual Financial Rept 1979 MCNEER.C Wisconsin Electric Power Co 80/03/14 33pp
- P Operating license stage documents & correspondence
- 8004040123 Notifies that description of QA program is App H to final description & SAR FAY. CH Wisconsin Electric Power Co 80/02/25 2pp
- B004140087 Finds actions taken to repair inspect & test cracking found in Peedwater sys piping adequate until recommendations of owners group & NRC Pipe Crack Study Group have been evaluated Safety analysis encl.

 8CHWENCER: A Operating Reactors Branch 1 80/02/25 6pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENNUT.D O Division of Operating Reactors 80/03/12 Spp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- B004300276 Forwards Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability SCHWENCER, A Operating Reactors Branch i 80/03/19 2pp
- --8004300280 Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively, modifying Tech Spec qualification requirements for radiation protection manager SCHMENCER. A Operating Reactors Branch 1 80/03/19 7pp

- --8004300285 Bafety evaluation supporting Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation 80/03/19 2pp
- --80043002B7 Notice of issuance & availability of Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively SCHWENCER, A Operating Reactors Branch 1 80/03/17 2pp
- 8004100172 Requests controlled set of P&IDs Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/03/20
- B004020326 Discusses Event 5 valve configurations at facilities in response to NRC 800223 request Valves will be verified properly closed by combination of periodic testing & observation Sketch showing valve configurations encl FAY, C W Wisconsin Electric Power Co 80/03/21 3pp
- 8004010317 Responds to 800107 ltr re QA requirements for diesel generator fuel oil Adequate controls to assure quality of fuel oil are being implemented FAY.C W Wisconsin Electric Power Co 80/03/24 2pp
- B004240096 Provides info to clarify further NRC position re containment isolation (Section 2 i 4 of NUREO-0578) All plants required to have double isolation barriers w/o need for operator action Plant does not meet position on two penetrations SCHWENCER, A Operating Reactors Branch i B0/04/03 3pp
- 8004280273 Forwards Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability SCHMENCER. A Operating Reactors Branch 1 80/04/03 2pp
- -8004280299 Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively, making minor changes to Tech Specs & approving revised organizational structure

 8CHMENCER; A Operating Reactors Branch 1 80/04/03 3ipp
- --8004280301 Bafety evaluation supporting Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation 80/04/03 2pp
- --8004280304 Notice of issuance & availability of Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively 8CHMENCER, A Operating Reactors Branch 1 80/04/03 2pp
- 8004300497 Confirms schedule arranged by NC Choules re 800408 meeting at site to discuss regulatory performance of facility KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/07 ip.
- B004220475 Notifies of changes to undervoltage relaying for protection against degraded grid voltage on 4140 volt safeguard busses Action responds to NRC request to upgrade circuitry upon review of facility 79084 & 1012 & B00117 ltrs
 FAY, C. W Wisconsin Electric Power Co B0/04/17 2pp

Q Inspection reports, IE Bulletins & correspondence

- 8004ii0230 Forwards IE Insp Repts 50-266/80-02 & 50-301/80-01 on 800122-24 No noncompliance noted HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/05 2pp
- --8004110245 IE Insp Repts 50-266/80-02 & 50-301/80-01 on 800122-24 No noncompliance noted Major areas inspected plant operations organization & administration, GA review audits & records WARNICK, R F. NRC Regional Offices HAOVE, R L . SMITH, J D Region 3, Chicago. Office of the Director 80/03/04 5pp
- B004070206 Bubmits status rept of stress analysis & pipe support review as of B00227.in response to IE Bulletin 79-14 Analysis has been completed for 52 drawings & pipe supports evaluated for 26 pipe lines.

 FAY: C W Wisconsin Electric Power Co 80/03/07 6pp.
- 8004100149 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block "No specific action or response required.

 KEPPLER.J Q Region G, Chicago, Office of the Director 80/03/07.

- 8004030353 Responds to IE Bulletin 79-01 re environ qualification of Class IE equipment Master list enci compiling all sys required to function under postulated LOCA or high energy line break accident FAY.C W Wisconsin Electric Power Co 80/03/12 12pp
- B004240449 Ack receipt of NRC B00310 ltr transmitting IE Info Notice B0-10 re Crystal River Unit 3 incident Notice will be reviewed by util nuclear projects ofc personnel & by plant supervisory personnel Results will determine further action FAY.C W Wisconsin Electric Power Co B0/03/24 1p
- 8004240419 Responds to IE Bulletin 80-03. "Loss of Charcoal from Std Type 11. Two-Inch. Tray Adsorbet Cells " Lists number, sys & manufacturer Containment purge sys cell had loose strip securing screen to frame Next insp scheduled for Apr FAY.C M Wisconsin Electric Power Co 80/03/26 2pp
- 8004010223 Submits results of steam generator inspirequested in 791130 order Requests written concurrence that tests are acceptable so that unit may be returned to syc List of tubes plugged & description of QA program encl
 BURSTEIN.S Wisconsin Electric Power Co 80/03/28 8pp
- 8004180194 Forwards IE info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/31
- 8004080727 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/01 in
- 8004150059 Forwards IE Info Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004180065 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J G Region 3. Chicago, Dffice of the Director 80/04/02 in
- 8004220198 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02 to
- 8004220392 Forwards IE Circular 80~07. "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 8004230288 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07
- 8004220053 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/09
- 8 Reportable occurrences, LERs & related correspondence
- 8004020333 Forwards LER 80-002/017-0 FAY,C W Wisconsin Electric Power Co 80/03/25 Ip
- ---B004020344 LER B0-002/01T-0 on B00311.during shutdown.B00 psi secondary-to-primary hydrostatic leak test of B steam generator revealed tube R23644 leaking.tube RBC37 wet & plug end R23650 wet Tube holes will be weld plugged FAY.C W Hisconsin Electric Power Co 80/03/25 5pp
- BOO4290307 Forwards LER BO-003/03T-0 FAY,C W Wisconsin Electric Power Co BO/04/16, 1p
- --8004290310 LER 80-003/03T-0 on 800318 during post-mod testing of containment spray sys, relay 1CSB would not latch. Caused by latching mechanism misalignment Latch adjusted & proper operation verified on 800318 Similar relay bench tested FAY.C W Wisconsin Electric Power Co 80/04/16 Zpp

4290298 Forwards updated LER 80~002/017-1 AY,C W Hisconsin Electric Power Co 80/04/17 1p

004290306 Updated LER 80-002/017-01 on 800311 during 800 pst secondary to primary hydrostatic leak test, tubes 823044 & 88037 & plug end 823030 found leaking Eddy current insp performed Tube holes & leaking explosive plugs were plug welded FAY,C W Wisconsin Electric Power Co 80/04/17 9pp

Congressional/Executive Correspondence

4140374 Responds to M Charlier B00107 ltr requesting facility hutdown until completion of needed repairs Inspitests & to assure public health & safety of the problems wistening generator tube degradation problems in the problems by the problems of the pr

304140379 Forwards M Charlier B00107 Itr requesting that facility be shot down until needed repairs are completed PROXMIRE, W Benate BD/O1/17 2pp

1140294 Forwards NRC 800104 1tr to J Estas, in response to 791213 iquest If requested, Lakeshore Citizens for Safe Energy will included in future meetings se steam generator condition RCKG.4 J diffice of the Executive Director for Operations 1/03/29 1p

ET 90-26/ FORT ST VRAIN NUCLEAR GENERATING STATION lecurity, modical, emergency & fire protection plans

OBOG99 Forwards evaluation of emergency planning rone distances per IREG-O396 guidelines Requests emergency planning ne kingestion pathway be established at 5 % 30 miles, apoctively REMBOURO, D Public Service Co of Colorado BO/D4/01 27pp

djudicatory correspondence

240512 Forwards NRC confirmatory order ELLO, V Defice of Inspection & Enforcement, Office of the rector \$00/04/04 19

04240514 Drder confirming util commitment to perform review requested by IE Bulletin 79-27 by 800425 Required info specified in Attachment & Office of Inspection & Enforcement, Office of the Director 80/04/04 App

inancial information

R20775 Forwards Annual Financial Rept 1979
REMBOURG: D Public Service Co of Colorada 80/04/14 19

14220778 Annual Financial Rept 1979 Public Service Co of Colorado 80/02/07 43pp

parating license stage documents & correspondence

170286 Represents that util motification to NRC refuel particles C microperoxity was timely. Bases opinion on info ginally presented to util by GA Co & in-reactor formace of fuel to date LER.J K Public Service Co. of Golerado 80/03/04 2pp

10490 Advises that GA program implementation differs slightly from codures stated in FBAR I terms are not safety significant on us represent unreviewed safety question GA program rite will be included in upplanted FSAR Y:HL Public Service Co. of Colorado 80/03/24 ip

spection reports: IE builetins & correspondence

40128 Forwards IE Insp Rept 50-267/80-01 on 791231-800131.notice violation & notice of deviation SEN.Q.L. Region 4, Dallas, Reactor Operations Nuclear Support nch 80/02/19 2pp

4040133 Notice of violation from insp on 791231-800131 Region 4: Dalies, Office of the Director 80/02/15 ip

4040136 Notice of deviation from insp on 791231-800131 Region 4. Dallas, Office of the Director. 80/02/15 is --8004040140 IE insp Rept 50-267/80-01 on 791231-800131 Noncompliance noted failure to meet diesel fuel tank Tech Spec capacity linits & deficiency re electronic surveillance testing procedures HESTERMAN, T.F., COLLINS, R.E., EMITH, R. Region 4, ballas, Office of the Director 80/02/15 9pg

8004080600 Farwards IE Insp Rept 50-267/80-04 on 800211-12 No noncompliance noted MADEEN,O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/25 2pp.

~~8004080602 IE Insp Rept 50-267/80-04 on 800211-12 No noncompliance noted Major areas inspected review of licensee performance history & meeting w/licensee mgt HESTERMAN, T F, DICKERSON, M W Region 4, Dallas, Office of the Director MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/02/25 2pp

8004240469 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation "Review & analysis of four instrument buses progressing No violations of basic design criteria found SWART.F E Public Service Co of Colorado 80/02/27 ip

Q004210354 ADvises that util will not be able to keep commitment made per 800227 telcon re partia; response to IE Bulletin 79-01B Communication problems have made info inaccessible Submittal will be pade within next 14 days

SHART.F E Public Service Co of Colorado 80/03/04 ip

8004030(30 Forwards Category I inservice insp & testing program submittais re helium circulator & secondary coolant sys FULLER, J K Public Service Co of Colorado 80/03/31 3pp

~-8004030:31 Inservice insp & testing program, "Proposed Tech Spec Survaillance Regultements for Primary Coolant Sys Helium Circulators," draft.Revision 2 * Public Service Co of Colorado 80/03/25 5pp

--8004030132 "Burveillance Requirements Review for Primary Coolant Bys Helium Circulators." Revision 1 * Public Bervice Co of Colorado EE-21-0004 80/03/25 17pp

--8004030133 "Proposed Tech Bpec Surveillance Requirements for Becondary Coolant Sus," draft, Revision 2 + Public Service Co of Colorado B0/03/25 7pp

---8004030134 "Surveiltance Requiraments Review for Secondary Coolant Sys." Revision : * Public Bervice Co of Colorado EE-22-0002 80/03/25 28pp

--8004030136 "ASHE Code Equipment & Related Insps & Testing "
+ Public Service Co of Colorado 80/03/25 9pp

8004150237 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve "No specific action or response necessary.

SEYFRIT, K V Region 4. Dallas. Office of the Director. 80/03/31

8004080673 Forwards IE Circular 80-05. "Emergency Dissel Generator Lubricating Oil Addition & Onsite Supply " No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/01 in.

G004110104 Forwards IE Info Notice 80-13, "GE Type 8BM Control Ewitches Defective CAM Followers" No specific action or response required SEYFRIT.K V Region 4, Dalias, Office of the Director 60/04/02

8004180499 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees" No action required. EEYFRIT.K V Region 4. Dallas. Office of the Director. 80/04/02

B004180162 Forwards IE Circular 80-07, "Problems W/HPGI Turbine Oil Sys " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director, 80/04/03 in

8004230350 Forwards & Builetin 79-03A. "Longitudinal Weld Defects in ABME BA-312, Type 304 Stainless Steel Pipe" Action required EEYFRIT, K V Pagion 4, Dallat, Office of the Director. 80/04/04 in

- 8004210163 Ack receipt of 800317 ltr informing NRC of 4teps taken to correct violations noted in IE Insp Rept 50-267/80-01 HADSEN:O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/04/07 lp
- --8004210166 Responds to NRC ltr re violations noted in IE Insp Rept 50-267/80-01 Corrective actions graduated gallon scale was installed adjacent to sight glass for quick inventory LEE, UR Public Service Co of Colorado 80/03/17 ip
- 8004290390 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Pawer Sys Bus During Operation "Loss of instrument bus voltage is alarmed in control room Voltmeters are provided for addl verification
 FULLER, J K Public Service Co of Colorado 80/04/25 App
- R Periodic operating reports & related correspondence
- BOO4130333 Forwards monthly operating rept for Jan 1980
 WAREMBOURG,D Public Bervice Co of Colorado BO/04/07 ip
- --8004150336 Monthly operating rept for Jan 1980
 OAHN, J W Public Service Co of Colorado 80/04/07 9pp
- 8004150338 Forwards monthly operating rept for Feb 1980 WAREMBOURG, D Public Service Co of Colorado 80/04/07 ip
- 8004210268 Forwards monthly operating ropt for Mar 1980 WAREMBOURG, D Public Service Co of Colorado 80/04/14 ip
- --8004210271 Monthly operating rept for Mar 1980 GAHM, J W Public Service Co of Colorado 80/04/02 App
- B. Reportable occurrences, LERs & related correspondence
- 8004080422 Forwards LER 80-010/03L-0 WAREMBBURG, D Public Service Co of Colorado 80/04/02 4pp
- --B004080427 LER 80-010/03L-0 on B00303, at 10% thermal power. A emergency diesel generator would not load as required for weekly 50% load test surveillance Caused by diesel generator governor problem which reduced speed control response GAHM. J W Public Service Co of Colorado B0/04/02 1p
- 8004090503 Forwards LER 80-011/03L-0 WAREMBGURG, D Public Service Co of Colorado 80/04/02 9pp
- --8004080512 LER 80-011/03L-0 on 800306-21, reactor deepoint limiting conditions for operation were exceeded on one occasion & operation in degraded mode occurred on three occasions Gaused by problems wholfer hellum sys GAHM, J W Public Service Co of Colorado 80/04/02 1p
- BOO4150432 Forwards LER 80-016/03L-0 WAREMBOURG,D Public Service Co of Colorado BO/04/09, 5pp
- --8004180438 LER 80-016/03L-0 on 800322, during testing, four of twelve helium circulator seal malfunction pressure differential switch units tripped outside specs Caused by dirt accumulation in electrical switches Readjusted switches # Public Service Co of Colorado 80/04/07 ip
- 8004150542 Forwards LER 80-013/03L-0
 WAREMBOURG, D Public Service Co of Colorado 80/04/09 5pp
- --8004150552 LER 80-013/03L-0 on 800310 during 58% thermal power operation, indicated flow for two low level primary coolant dawpoint moisture monitors discovered less than requirements Caused by inaccurate flow elements OAHM, J W Public Service Co of Colorado 80/04/09. 1p
- 8004150382 Forwards LER 79-002/03X-1 WAREMBOURD, D Public Service Co of Colorado 80/04/09 4pg
- --8004150411 Supplemental LER 79-002/03X-1 on 791207, during repairs to buffer helium purge valve, operation in degraded mode occurred Caused by bypass of buffer helium dryer for repair of valve GAMM, J W Public Service Co. of Colorado 80/04/09. ip
- 8004150626 Forwards LER 80-014/03L-0. WAREMBOURG, D. Public Service Co of Colorado 80/04/09 4pg

- --B004150634 LER 80-014/03L-0 on B00311.during reactor shutdown, emergence feedwater snubber BFS-228E observed to be missing pin at piston rod eye & rendered inoperable No cause stated for missing pin New pin Fabricated & installed OAHM.J W Public Service Co of Colorado B0/04/09 1p
- 8004210294 Forwards LER 80-017/03L-0 WAREMBOURG,D Public Service Co of Colorado 80/04/09 3pp
- --8004210276 LER 80-017/03L-0 on 800311.w/plant shut down due to loss of main cooling water return line, plant liquid effluent sample required by SR NR 1 i not taken Caused by preempted time due to plant upset Sampling resumed on next shift GAHM.J W Public Service Co of Colorado 80/04/07 ip
- 8004240323 Forwards LER 80-015/03L-0
 WAREMBDURG, D Public Service Co of Colorado 80/04/18 4pp
- --8004240328 LER 80-015/03L-0 on 800320, during operation at approx 60% power, emergency feedwater header supply to loop 2 helium circulation water turbine drives was isolated to repair jeaking pressure control valve Gaused by loose block bolt GAHM, J W Public Service Co of Colorado 80/04/18 ip
- DOCKET 50-268 MIDWEST FUEL RECOVERY PLANT
- P Operating license stage documents & correspondence
- 8004190031 Appeals denial of FOIA request for all records re sabotoge analyses for spent fuel storage at Morris Operation in Morris.IL GUIGO.C Pollution Environmental Problems GD/02/19 5pp
- 8004010163 Responds to FOIA request for seven documents related to earlier request under FOIA-79-520 Forwards documents listed in App A Safeguards manual NEDO-14502, withheld (ref FOIA Exemption 4)
 FELTON, J M Division of Rules and Records 80/03/18 3pp
- ~-8004010101 Informs that NRC 720602 ltr containing 720517 issue of proposed license conditions for facility has been reviewed Mods can be made to clarify & strengthen matls mgt components Forwards proposed mods & evaluation of mods VANHOOMISSEN, J General Electric Co 72/07/05 16pp
- DOCKET 50-269 OCONEE NUCLEAR BYATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8004010235 Forwards list of revisions & additions that should be incorporated in 790803 revised safeguards contingency plan Revised plan incorporating revisions & additions should be submitted within 30 days Info withheld (ref 10CFR2 790) REID.R W Operating Reactors Branch 4 80/03/14 2pp
- 8004030157 Forwards info in support of standby shutdown facility Encl withheld (ref 10CFR2, 790) PARKER, W O Duke Power Co 80/03/28 2pp.
- BOO4170164 Forwards Revision 4 of security plan Plan withheld (ref 10CFR2 790) PARKER, W O Duke Power Co BO/04/09 1p
- 8004220443 Advises that revised pages to safeguards contingency plan will be provided by 800430 in response to NRC 800314 request PARKER: N O Duke Power Co 80/04/11 ip
- Q Adjudicatory correspondence
- BOO4230078 Forwards BOO328 SECY-BO-166 requesting amend to irradiated reactor fuel in-transit physical protection requirements If amend approved effect on NRC case re spent fuel transportation & storage will be provided HDEFLINO,R K Hearing Branch 4 80/04/01 1p
- BOO4180432 Forwards NRC 800403 ltr w/encl commercial newspaper advertisement re resumption of evidentiary hearings NRC wishes to notify public officials of counties in which proposed alternate routes are located KETCHEN,

- -8004180441 Notifies of resumption of evidentiary hearings relamend of License SNM-1773 Proposed action is to transport up to 300 spent fuel assemblies from Oconee nuclear facility to McG0:re nuclear facility to McG0:re nuclear facility Commercial newspaper notice encl ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 80/04/03
- 004160197 Forwards BS Spitalny, JN Donohow, CR Maretta & E Lantz prefiled testimonies re amend to License SMM-1773 for Oconee spent fuel transportation & storage at McGuire KETCHEN. G G Hearing Dranch 4 BO/04/11 2pp
- -8004160199 Profiled testimony re 800428 hearing Updates license amend record re spent fuel handling & storage alternatives, status of NRC spent fuel cask review & pin compaction application SPITALNY.II S Advanced Fuel & Spent Fuel Licensing Branch 80/04/11 Spp
- -8004160210 Supplemental NRC rept "Spent Fuel Storage of Oconee Spent Fuel at McGuire Nuclear Station - Unit i" * Commission 80/04/11 Zpp
- ~8004160219 Prefiled testimony re-doses caused by Oconee spent fuel assembly rupture while stored at McGuire spent fuel pool Converts NRC 800208 affidavits to question & answer format Prof qualifications encl
 DONOHEN.J N Environmental Evaluation Branch 80/04/11 13pp
- -8004160221 Testimony re ASLB questions at Transcript 4027 & 4432-47 concerning whether fuel stored in McGuire spont fuel pool would remain subcritical if cask falls onto pool Converts NRC 80020B affidavits to question & answer format MARCITA.C R Office of Nuclear Material Safety & Safeguards 80/04/11 2pp
- -8004160224 "NRC Criticality Analysis of McQuire Spent Fuel Pool Containing Oconee Spent Fuel for Cask-Drop Accident " Prof qualifications encl MAROTTA.C R Office of Nuclear Material Safety & Safeguards 80/04/11 10pp
- -8004160227 Testimony re ASLB questions at Transcript 4027 & 4432-47 concerning whether fuel stored in McQuire spent fuel pool would remain subcritical if cask falls onto pool Converts NRC 800208 afficavits to question & answer format LANTZ.E Division of Operating Reactors 80/04/11 2pp
- -8004160230 "Supplemental Criticality Analysis for Proposed Transfer of Spent Fuel From Oconee to McGuire "Prof qualifications encl LANTZ, E Division of Operating Reactors 80/04/11 Spp
- -8004160235 Affidavit re occupational doses caused by Oconee spent fuel assembly rupture, at 270 days in age, when stored in McGuire spent fuel pool Completes NRC response to ASLB 791031 urder Supporting documentation sncl
 DONOHEW.J N Environmental Evaluation Branch 80/04/10 8pp
- -8004160240 Affidavit re occupational doses caused by Ocenee spent fuel assembly rupture, at 40 days in age, when stored in McGuire spent fuel pool Completes NRC response to ABLB 791031 order Supporting documentation encl
 DONDHEW.J N Environmental Evaluation Branch 80/04/10 8pp
 - offidavit modifying JN Donohew 80D111 affidavit.Table 2.Page 3.Page 11 N Environmental Evaluation Branch 80/04/11 3pp
 - ponse requesting deferral of ASLB consideration of 10405 motion proposing primary route of spent its Urges ASLB to hold motion in absyance pending ction re security issue M/Certificate of Svc Hearing Branch 4 80/04/11 7pp

respondence

punds to 800009 Itr requesting info re environ effects of nuclear power plants Radiation effluent levels y 100FR20 & App 1 to 100FR30 Environ info stated LPDRS Environmental Projects Branch 1 80/04/01 2pp

nformation

wards Annual Financial Rept for 1979, annual certified atements, financial forecast for 1980-82 & available sources of funds to satisfy liability

Duke Power Co 80/03/28 App

- --8004020338 Annual Financial Rept 1979
- P Operating license stage documents & correspondence
- E0040400005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800206 reactor trip at Crystal River Sequence of events & planned corrective actions also encl DENTON: H.R. Office of Nuclear Reactor Regulation 80/03/04 26pp
- B004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENMUT.D G Division of Operating Reactors B0/03/12 5pp
- --8004030f18 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- B004030230 Notification of 800318 measting w/all operating B&W reactor licensees in Bethesdar,MD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID,R W Operating Reactors Branch 4 80/03/14 2pp
- 8004170327 "TMI-Plus One Toward a Bafer Nuclear Power Program " * Dute Power Co 80/03/26 13pp
- BO04010470 Supplements B00324 ltr Confirms conversations w/NRC ratesting of loss of non-nuclear instrumentation, integrated control sys power on Unit i Test will be completed within 90 days up order if required PARKER, N O Duke Power Co 80/03/28 1p
- 8004030199 Forwards proposed amend to facility Tech Specs Table 4 1-3, Section 6 6 4 4(2)(a) & Table 6 6-1 re monitoring waste disposal programs PARKER, W O Duke Power Co 80/03/28 2pp
- --8004030202 Proposed amend to facility Tech Specs Table 4 1-3, Section 6 6 1 4(2)(a) & Table 6 6-1 re waste disposal monitoring programs

 * Dute Power Co. 80/03/31 7pp
- B004210321 Requests followup rept to 791030 ltr re method used to demonstrate conformance w/provisions of 40CFR190 rept required by Tech Specs REID,R W Operating Reactors Branch 4 80/03/28 2pp
- BOO4160001 Responds to 791116 Tech Spac change application re operation of Unit 2 at full rated power during Cycle 5 Review has determined that proposed reload requires Class IV amend fae instead of Class III Requests add | fee DIOGS.R M License Fee Management Branch 80/03/31 ip
- BOO40B0595 Forwards info re indications & controls requiring mods to maintain plant at hot shutdown independent of ICS/NNI power supplies PARKER, H O Duke Power Co 80/04/01 2pp
- BOO4080614 Supplements 800102 ltr & confirms discussions w/NRC re reactor vessel head vent required by NUREO-0578 Remotely aperable reactor vessel head vent will be installed Design will be similar to that of hot leg vents per 800102 ltr PARKER, W O Duke Power Co 80/04/02 lp.
- B004210328 Summary of B00222 meeting w/B&W owners group in Bethesda. Md re abnormal transient operational guidelines BEIGEL, B. L. Reactor Bystems Branch 80/04/02 4pp
- 8004140430 Forwards comparison of draft ST8 w/snubber functional test sampling plan COLLINOS.D M Duke Power Co 80/04/03 11pp.
- 8004250368 Summary of 800403 meeting w/utils, B&W. NUS Corp & McGraw-Hill in Bethesda. MD re draft NUREG-0667. "Transient Response of B&W-Designed Reactors"
 CAPRAR A Standardization Branch 80/04/04 7pp
- BOO4180490 Notification of 800423 meeting w/utils & B&W in Bathesda, MD to discuss implementation of recommendations by B&W Reactor Transient Response Task Force CAPRA, R. A. Blandardization Branch 80/04/05 2pp.
- 8004280105 Forwards evaluation of implementation of Lessons Learned Task Force Category A items All items satisfactorily implemented at Unit 1 Three remaining items at Units 2 % 3 will be met prior to restart from Mar 1980 shutdown REID,R W. Operating Reactors Branch 4 80/04/07, 15pp

- 8004300137 Concurs w/800321 ltr describing safety of fuel pool operation w/o addl cooling capacity due to delay of addl cooler by pump installation Requests process estimate for procurement & installation by 800601
 REID.R W Operating Reactors Branch 4 80/04/09 3pp
- 8004150469 Forwards supplemental response to NRC 800223 request for info re primary coplant sys pressure isolation valves
 Neither continuous surveillance nor periodic testing is now being purformed Check valves display no lack of integrity PARKER.W D Duke Power Co 80/04/11 4pp
- B004220502 Advises that detailed analysis of thermal-mechanical conditions of reactor vessel during recovery from small breaks will be submitted B00715 PARKER, W O Duke Power Co B0/04/14 ip
- 8004220640 Supplements util 790925,1019 & 1219 ltrs re design & use of containment purge sys Requests NRC concurrence in scape of mods to parmit purging during operations above cold shutdown
 PARKER;W O Duke Power Co 60/04/15 2pp
- 8004180356 Submits add1 info to supplement 800324 ltr Describes parameters needed by operator to place plant in safe hot shutdown condition & testing for loss of power PARKER, N O Duke Power Co 80/04/18 2pp
- G Inspection reports, IE Bulletins & correspondence
- BOO4070362 Responds to NRC request made during 800109-11 insp for add1 info re assumptions made for support/restraint calculations performed in compliance w/IE Bulletin 79-02 Add1 & original calculations for Support SR 134 enc1
 PARKER.W 0 Duke Power Co 80/01/31 19pp
- 8004040358 Ack receipt of IE lnsp Repts 50-267/80-04.50-270/80-03 & 50-267/80-03 on GOD121-25 & 20 & 0201 No proprietary info PARKER, W O Duke Power Co 80/03/10 1p
- --8004040383 Forwards IE Insp Repts 50-269/80-04.50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted STOHR, J P Region 2. Atlanta, Fue) Facility & Materials Safety Branch 80/02/14 & 2po
- --8004040402 IE Insp Repts 50-269/80-04,50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted Major areas inspected emergency facilities, equipment & procedures, means for determining rolease & emergency training JENKING, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch PERROTTI, D J Region 2, Atlanta, Office of the Director 80/02/14 11pp
- 8004040402 IE Insp Repts 30-269/80-04, 90-270/80-03 & 90-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted Major areas inspected emergency facilities, equipment & procedures, means for determining release & emergency training JENKINB, 0 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/14 119p
- 8004080253 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Completion of Items 1, 2 & 3 documented W/o encl
 PARKER, W O Duke Power Co 80/03/13 2pp
- 8004100351 Responds to IE Bulletin 79-13 Results of radiographic examinations of feedwater noizle welds was provided in 800225 ltr w/s encl rept by H Thielsch documenting metallurgical evaluation PARKER: H O Duke Power Co 80/03/19 1p
- 8004240035 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells " No evidence of filter degradation as described in bulletin was observed at facilities PARKER.W D Duke Power Co 80/03/21 2pp
- 8004230202 Ack receipt of 800204 ltr informing NRC of steps taten to correct violation noted in IE lnsp Repts 50-269/79-41, 50-270/79-39 & 50-287/79-41 LEWIS R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/26 1p
- --8004230234 Responds to NRC 800114 itr re violations noted in IE Insp Repts 50-269/77-41,50-270/79-39 & 50-287/79-41 Corrective actions technician involved given written warning & independent verification being developed PARKER.W. D Duke Power Co 80/02/04. 2pp

- --8004230249 Forwards JE Insp Repts 50-269/79-41.50-270/79-39 & 50-287/79-41 on 791203-10 % notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/01/14 2pp
- --800423026/ Notice of violation from insp on 791203-10
 * Region 2, Atlanta, Office of the Director 80/01/11 ip
- --8004230277 IE Insp Repts 50-269/79-41.50-270/79-39 & 50-287/79-41 on 791203-10 Noncompliance noted failure to follow maint procedures resulting in noncompliance w/Tech Specs MARTINIR D. JAPELF Region 2. Atlanta. Reactor Operations Nucle Support Branch 80/01/11 épp
- 8004210191 Ack receipt of IE Insp Repts 50-269/80-03,50-270/80-02 & 50-267/80-02 on 800114-24 No proprietary 18fo PARKER, W O Duke Power Co 80/03/28 1p
- ~-8004210195 Forwards [E Insp Repts 50-269/80-03.50-270/80-02 ; 50-28 80-02 on B00114-24 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineerin Support Branch 80/03/04 2pp
- --B004210199 IE Insp Repts 50-269/80-03,50-270/80-02 & 50-287/80-02 or B00114-24 No noncompliance noted Major areas inspected IE Bulletins 79-13 & 79-17, auxiliary feedwater notals thermal sleeve insp & crack repair HERDT, A R Region 2, Atlanta, Reactor Construction & Engineer ing Support Branch ECONOMOS. N Region 2, Atlanta, Office of the Director B0/02/25 7pp
- B004190511 Forwards 1E Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004220188 Forwards IE Insp Repts 50-269/80-08,50-270/80-06 & 50-287/80-06 on 800225-29 No noncompliance noted KENNA.W B Region 2, Atlanta, Safeguards Branch 80/03/31 2pp
- --8004220204 IE Insp Repts 50-269/80-08,50-270/80-06 & 50-287/80-04 or 800225-29 No noncompliance noted Major areas inspected security plan. security program t physical security Details withheld (ref 10GFR2 790)
 TOBIN.W J Region 2: Atlanta, Bafeguards Branch 80/03/25 1p
- 8004080áil Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required CIREILLY, J P Region 2, Atlanta. Office of the Director 80/04/01
- 8004150070 Forwards IE Info Notice 80-13, "GE Type SBM Control Switche Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02.
- 8004250330 Ack receipt of 800314 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-26/80-05, 50-270/80-04 & 50-287/80-04 LEWIG.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip
- --B004250334 Responds to NRC B00220 ltr re violation noted in IE Insp Repts B0-267/80-05,50-270/80-04 & 50-287/80-04 Corrective actions areas cited were cleaned & maint practices & procedures changed to include housekeeping practices PARKER, W O Duke Power Co 80/03/14 2pp
- --8004250340 Forwards IE Insp Repts 50-269/80-05.50-270/80-04 & 50-287/80-04 on 800107-31 & notice of deviation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 60/02/20 2pp
- --8004250346 Notice of deviation from insp on 800107-31 * Region 2, Atlanta, Office of the Director 80/02/20 ip
- --B004250357 IE Insp Repts 50-269/80-05.50-270/80-04 & 50-287/80-04 or B00107-31 Noncompliance noted failure to adhere to stated housekeeping practices in areas occupied by safety-related equipment MARTINE D Region 2. Atlanta. Reactor Operations Nuclear Support Branch B0/02/20 Spp

- 8004180326 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004250357 IE Insp Repts 50-269/80-05.50-270/80-04 & 50-287/80-04 on 800107-31 Noncompliance noted failure to adhere to stated housekeeping practices in areas occupied by safety-related
 - equipment
 MARTIN R D Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch JAPE, F Region 2, Atlanta, Office of the Director
 80/02/20 Spp
- 8004230132 Forwards IE Bulletin 77-03A "Longitudinal Weld Defects in ASHE SA-312 Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004180358 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004300205 Ack receipt of 800303 itr informing NRC of steps taken to correct violations & deviations noted in IE Insp Repts 50-269/79-37,50-270/79-34 & 50-267/79-37
 O'RETILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- --8004300214 Responds to NRC 800206 ltr re violations & deviations in IE Insp Repts 50-269/79-37.50-27D/79-34 & 50-287/79-37 Corrective actions shift operating personnel instructed on manual transfer intercommunication sys & alarm procedures PARKER.W O Duke Power Co 80/03/03 4pp
- --8004300230 Forwards IE Insp Repts 50-269/79-37,50-270/79-34 & 50-287/79-37 on 791111,15 & 16 & notices of violation & deviation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/06 25p
- --8004300237 Notice of violation from insp on 791111.15 & 16 * Region 2, Atlanta, Office of the Director 80/01/16 ip
- --8004300245 Notice of deviation from imap on 791111,15 & 16 * Region 2, Atlanta, Office of the Director 80/01/18
- -8004300260 IE Inst Repts 50-269/79-37.50-270/79-34 & 50-267/79-37 on 004300260 IE Insp Repts 50-267/79-37.50-270/79-34 & 30-28//79-17.79fill; 15 & 16 Noncompliance noted inadequate procedures to correct potential malfunctions, excessive RCS cooldown rate & failure to notify of RO within 1-h GUICK, DR, MARTIN,R Region 2, Atlanta, Diffice of the Director 80/01/18 dpp
- 1004240296 Forwards add1 response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Revised master sys/components list & sys component evaluation work sheets encl Add1 equipment info will be sent by 800701 THIES: A C. Duke Power Co 80/04/21, 1200pp
- Reportable occurrences: LERs & related correspondence
- 004070327 Forwards LER 80-005/03L-0 PARKER, W O. Duke Power Co 80/03. 80/03/28. 3pp
- -8004070330 LER 80-005/03L-0 on 800229, during annual calibr check, reactor protection sys channel B reactor coolant pressure transmitter found out of calibr Cause undetermined Transmitter recalibr & will be checked at next outage LEWIS, S.R. Duke Power Co. 80/03/28 ip
- D04080471 Forwards LER 80-006/03L-0 PARKER, W O Duke Fower Co 80/04/04 1p
- -8004080476 LER 80-006/03L-0 on 800305, during decay heat removal test, heat removal cooler 18 outlet valve 1LP-4 failed to open manually Caused by limit switch being out of adjustment Switch readjusted LEMIS,S R. Duke Power Co 80/04/04 2pp
- 304170203 Forwards LER 80-008/13T-1 PARKER, W Q Duke Power Co 80/04/10 3pp
- -8004170208 LER 80-008/13T-1 on 900327.motor operator on valve ILP-105 determined unqualified for in-containment use Caused by erroneous provision during transfer to site for installation as part of NSM-507 Valve operator will be replaced.
 WILBON, K.R. Duke Power Co. 80/04/11 ip

- B004220692 Forwards LER 80-007/03L-0 PARKER, 44 0 Duke Power Co 80/04 B0/04/14 205
- -8004220690 LER 80-007/03L-0 on 800315, during installation of cable between cable rooms, void botween two layers of firestop mat1 was discovered Caused by large number of cable trays deflecting layer of mat1 Add1 layer of firestop mat1 added LEWIS, S R Duke Power Co 80/04/14 1p
- DOCKET 50-270 OCCINEE NUCLEAR STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8004010255 Forwards list of revisions & additions that should be incorporated in 790803 revised safeguards contingency plan Revised plan incorporating revisions & additions should be submitted uithin 30 days Info withheld (ref 10CFR2 790) REID, R W Operating Reactors Branch 4 80/03/14 2pp
- 8004030157 Forwards info in support of standby shutdown facility Encl withheld (ref 100FR2 790) PARKER,W O Duke Power Co 80/03/28 2pp
- 8004170164 Forwards Revision 4 of security plan Plan withheld (ref 10CFR2 790) PARKER, W O Duke Power Co E0/04/09 to
- 8004220443 Advises that revised pages to safeguards contingency plan will be provided by 800430 in response to NRC 800314 request
 PARKER, W O Duke Power Co 80/04/11 1p
- Q Adjudicatory correspondence
- 8004230078 Forwards 800328 BECY-80-166 requesting amend to irradiated reactor fuel in-transit physical protection requirements If amend approved, offset on NRC case re spent fuel transportation & storage will be provided HOEFLING.R K Hearing Branch 4 80/04/01 ip
- 1 Financial information
- 8004020334 Forwards Annual Financial Rept for 1979, annual certified financial statements, financial forecast for 1980-82 & statement re available sources of funds to satisfy liability requirements THIES, A C Duke Power Co 80/03/28, 4pp
- --8004020338 Annual Financial Rept 1979. * Duke Power Co 80/02/11 44pp
- P Operating license stage documents & correspondency
- 8004080641 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valva Isolation & Other Safety Feature Signals. Oconee Nuclear Station," informal rept UDY. A C EO & O. Inc FIN A-6285 8004080641 80/02/29 12pp
- BO04040005 Forwards outline of plant-specific questions to be address in addition to info required by IE Bulletin 79-27 re B00204 reactor trip at Crystal River Sequence of events & planned corrective actions also encl
 DENTON, H R Office of Nuclear Reactor Regulation 80/03/06 26pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr FISENMUT, D 9 Division of Operating Reactors 80/03/12 5pp.
- --8004030118 "Nuclear Data Link Specs " # Division of Operating Reactors 80/02/21 28pp.
- BOO4030230 Notification of B00318 meesting w/all operating B&W reactor licensees in BethesdarMD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID:R W Operating Reactors Branch 4 B0/03/14 2pp
- 8004170327 "TMI-Plus One Toward a Safer Nuclear Power Program" # Duke Power Co 80/03/26 13pp
- 8004010470 Supplements 800324 ltr Confirms conversations w/NRC retesting of loss of non-nuclear instrumentation, integrated control sys gower on Unit 1 Test will be completed within 90 days of order, if required PARKER, 40 D Duke Power Co 80/03/28 tp

- 8004030199 Forwards proposed amend to facility Tech Specs Table 4 1-3. Section 6 6 4 4(2)(a) ? Table 6 6-1 re monitoring waste disposal programs PARKER,W 0 Duke Power Co 80/03/20 2pp
- --8004030202 Proposed amend to facility Tech Specs Table 4 1-3, Section 6 6 1 4(2)(a) % Table 6 6-1 re waste disposal monitoring programs * Duke Power Co 80/03/31 7pp
- 8004210321 Requests followup ropt to 791030 ltr re method used to demonstrate conformance w/provisions of 40CFR190 rept required by Tech Specs
 REID,R W Operating Reactors Branch 4 80/03/28 2pp
- 8004160001 Responds to 791116 Tech Spec change application re operation of Unit 2 at full rated power during Cycle 5 Review has determined that proposed reload requires Class IV amend fee instead of Class III Requests add | fee DIGOS,R M License Fee Management Branch 80/03/31 ip
- 8004080595 Forwards info re indications & controls requiring mods to maintain plant at hot shutdown independent of ICS/NNI power supplies
 PARKER: M O Duke Power Co 80/04/01 2pp
- BOO4080614 Supplements BOO102 ltr & confirms discussions w/NRC re reactor vessel head vent required by NUREO-0578 Remotely operable reactor vessel head vent will be installed Design will be similar to that of hot leg vents per BO0102 ltr PARKER, W Q Duke Power Co BO/04/02 ip
- 8004210328 Summary of 800222 meeting w/B&W owners group in Bethesda. Md re abnormal transient operational guidelines SEIGEL, B L Reactor Systems Branch 80/04/02 4pp
- BO04140430 Forwards comparison of draft STB w/snubber functional test sampling plan COLLINGS,D M Duke Power Cn BO/04/03 11pp.
- 800425036B Summary of 800403 meeting w/utils.B&W.NUB Corp & McGraw-Hill in Bethesda.MD re draft NUREO-0467, "Transient Response of B&W-Designed Reactors " GAPRA,R A Standardization Branch 80/04/04 7pp
- 8004180490 Notification of 800423 meeting w/utils & 11kH in Bethesda, MD to discuss implementation of recommendations by 11kH Reactor Transfent Response Task Force CAPRA, R A Standardization Branch 80/04/05 2pp
- 8004280105 Forwards evaluation of implementation of Lessons Learned Task Force Category A items All items satisfactorily implemented at Unit i Three remaining items at Units 2 & 3 will be met prior to restart from Mar 1980 shutdowns REID.R W Operating Reactors Branch 4 80/04/07 15pp.
- BO04300137 Concurs w/B00321 ltr describing safety of fuel pool operation w/o addl cooling capacity due to delay of addl cooler & pump installation Requests precise estimate for procurement & installation by B00601
 REID,R W Operating Reactors Branch 4 80/04/09 3pp
- 8004150465 Forwards supplemental response to NRC 800223 request for info re primary coolant sys pressure isolation valves Neither continuous surveillance nor periodic testing is now being performed Check valves display no lack of integrity PARKER, W O Duke Power Co 80/04/11 App
- 8004220502 Advises that detailed analysis of thermal-mechanical conditions of reactor vessel during recovery from small breaks will be submitted 800715 PARKER, M. O. Duke Power Co. 80/04/14 ip
- 8004220640 Supplements util 790925, 1019 & 1219 ltrs re design & use of containment purge sys Requests NRC concurrence in scope of mods to permit purging during operations above cold shutdown PARKER, W D Duke Fower Co. 80/04/15. 20p
- 8004220649 Forwards fee to supplement license fee submitted on 791116 PARKER, W C Duke Power Co 80/04/15 ip
- BOO4180336 Gubmits addi info to supplement BO0324 ltr Describes parameters needed by operator to place plant in safe hot shutdown condition & testing for loss of power PARKER, W. D. Duke Power Co. 80/04/18 2pp

- G Inspection reports, IE Bulletins & correspondence
- 8004070362 Responds to NRC request made during 800107-11 insp for add1 info re assumptions made for support/restraint calculations performed in compliance w/IE Bulletin 79-02 Add1 & original calculations for Support SR 134 enc1 PARKER. W O Duke Power Co 80/01/31 19pp
- G004040358 Ack receipt of IE Insp Repts 50-269/80-04.50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No proprietary info PARKER, W Ω Duke Power Co 60/03/10 Ip
- --8004040383 Forwards IE Insp Repts 50-269/80-04.50-270/80-03 & 50-287/80-03 on 800121-25 \$ 28 & 0201 No noncompliance noted STOHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Brench 80/02/14 2pp
- --8004040402 IE Insp Repts 50-249/80-04,50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted Major areas inspected emergency facilities, equipment & procedures, means for determining release & emergency training JENKINS, 9 R Region 2, Atlanta, Fuel Facility & Matorials Safety Branch PERROTTI.D J Region 2, Atlanta, Office of the Director 80/02/14 11pp
- 8004080253 Forwards response to IE Bulletin 79~018 re environ qualification of Class IE equipment Completion of Items 1, 2 & 3 documented W/o encl PARKER, W D Duke Power Co 80/03/13 2pp
- 8004240039 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II. Two-Inch, Tray Adsorber Cells" No evidence of filter degradation as described in bulletin was observed at facilities
 PARKER. W D Duke Power Co. 80/03/21 2pp
- 8004230202 Ack receipt of 800204 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-269/79-41, 30-270/79-39 & 50-287/79-41
 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 60/03/26 ip
- --8004230236 Responds to NRC 800114 ltr re violations noted in [E Insp Repts 50-269/79-41.50-270/79-39 & 50-287/79-41 Corrective actions technician involved given written warning & independent verification being developed PARKER.W O Duke Pawer Co 80/02/04 2pp
- --B004230249 Forwards IR Insp Repts 50-269/79-41,50-270/79-39 & 50-287/79-41 on 791203-10 & notice of violation LEWIS.R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/14 2pp
- ---B004230267 Natice of violation from insp on 791203-10 * Region 2, Atlanta, Office of the Director 80/01/11 ip
- ---B004230277 IE Insp Repts 50-269/79-41.50-270/79-39 & 50-287/79-41 on 791203-10 Noncompliance noted failure to foilum maint procedures resulting in noncompliance w/Tech Spacs MARTIN.R D. JAPE.F. Rogion 2. Atlanta. Reactor Operations Nuclear Support Branch 80/01/11 &pp
- 8004210191 Ack receipt of IE Insp Repts 50-269/80-03,50-270/80-02 & 50-287/80-02 on 800114-24 No proprietary info PARKER, N O Duke Power Co 80/03/28 ip
- --8004210195 Forwards IE Insp Repts 50-269/80-03.50-270/80-02 & 50-2817/80-02 on 800114-24 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004210199 IE Insp Repts 50-249/80-03,50-2/0/80-02 & 50-287/80-02 on 800114-24 No noncompliance noted Major areas inspected IE Builetins 79-13 & 79-17,auxiliary feedwater nozzle thermal sleeve insp & crack repair HERDT.A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS,N Region 2, Atlanta, Office of the Director 80/02/25 7pp
- 80041505i1 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary OffEILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31 2pp.
- 8004220188 Forwards IE Insp Repts 50-269/80-08,50-270/80-06 & 50-287/80-06 on 800225-29 No noncompliance noted KENNA,W B Region 2. Atlanta, Safeguards Branch 80/03/31 2pp

- -9004220204 IE Insp Repts 30-249/80-08.50-270/80-04 & 50-287/80-06 on 600225-29 No noncompliance noted Major areas inspected security planssecurity program & physical security Details withheld (ref 10CFR2 790)
 TOBIN.W J Region 2, Atlanta, Sareguards Branch 80/03/25 ip
- 8004080611 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 200
- B004150070 Forwards IE Info Notice 80-13, "GE Type SBK Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required G'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/02
- 8004250330 Ack receipt of 800314 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-269/80-05, 50-270/80-04 & 50-287/80-04 LENIS, C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip
- --8004250334 Responds to NRC 800220 ltr re violation noted in IE Insp Repts 50-269/80-05,50-270/80-04 & 50-287/80-04 Corrective actions areas cited were cleaned & maint practices & procedures changed to snclude housekeping practices PARKER.W O Buto Power Co 80/03/14 2pp
- --B004250340 Forwards IE Insp Repts 50-269/80-05,50-270/80-04 & 50-287/80-04 on B00107-31 & notice of deviation LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. B0/02/20 2pp
- --8004250346 Notice of deviation from Insp on 800107-31
 * Region 2, Atlanta, Office of the Director 80/02/20 ip
- 8004180326 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 200.
- 8004250357 IE Insp Repts 50-269/80-05,50-270/80-04 & 50-287/80-04 on B00107-31 Noncompliance noted failure to adhere to stated housekeeping practices in areas occupied by safety-related equipment MARTIN.R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch JAPE.F Region 2, Atlanta, Office of the Director B0/02/20 Bpp
- 8004230132 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pips" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180358 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004300205 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Repts 50-269/79-37,50-270/79-34 & 50-287/79-37 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 2nn.
- -8004300214 Responds to NRC 800206 ltr re violations & deviations in IE Insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 Corrective actions shift operating personnel instructed on menual transfer intercommunication sys & alarm procedures PARKER, W D Duke Power Co. 80/03/03 4pp
- 8004300230 Forwards IE insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 on 7911fi.15 & 16 & notices of violation & deviation.

 LEWIS.R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/02/06 2pp.
- 8004300237 Notice of violation from insp on 791111,15 & 16 * Region 2, Atlanta, Office of the Director 80/01/18 ip
- 8004300245 Notice of deviation from insp on 791111,15 & 16 * Region 2, Atlanta, Office of the Director 80/01/18 2pp

- ---8004300260 IE Insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 on 7911i1.15 & 16 Noncompliance noted inadequate procedures to correct potential malfonctions, excessive RCS cooldown rate & failure to notify of RO within 1-h GUICK, D R: MARTIN, R Region 2, Atlanta, Office of the Lifector BO/01/IB 600
- B004240276 Forwards addl response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Revised master sys/components list & sys component evaluation work sheets encl Addl equipment info will be sent by 800701
 THIES, A C Dute Power Co 80/04/21 1200pp
- DUCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- 8004110465 Confirms provision of self-contained breathing apparatus for ready access by control room personnel, as discussed in fire protection safety evaluation CDNMAY, W.F. Vermont Yankee Nuclear Power Corp. 80/04/07 ip
- 8004140403 Forwards assessment of fire protection review re Item 3 : [3.portable ventilation equipment Licenses input has not been received Recommends that ventilation equipment be installed HALL.R E Brookhaven National Laboratory 80/04/08 2pp
- 8004230510 Forwards results of fire protection review, Item 3 1 8, fire barrier penetations Recommends NRC consider design & const of penetration seals as conditionally acceptable Typical H penetration requires addl test data HALL.R E Brookhaven National Laboratory 80/04/14 2pp
- 9 Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OUSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- B0040B0374 Notifies of change in address on "list of copies" to read LH Heiden.Vice President.23 Research Drive, Westboro, MA & WP Murghy, Plant Superintendent, PO Box 157, Vernon, VT BMITH, R L Vermont Yankee Nuclear Power Corp B0/04/01 ip
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 100FR20 & App 1 to 100FR50 Environ info available in stated LPDR8

 BALLARD
- P Operating license stage documents & correspondence
- B00415003B "Safety Evaluation Rept. Inservice Testing Program"
 FEHRINGER J M . ROCKHOLD H C E0 & Q. Inc FIN A-4238 800415003B 80/02/27 40pp
- 8004070408 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20:000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIBERHUT,D O Division of Operating Reactors B0/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28pp.
- 8004110084 Forwards requests for add1 info needed to complete evaluation of electrical/bupass assets of containment purps sys IPPOLITO.T A Operating Reactors Branch 3 80/03/12 App
- 8004110040 Forwards info on 800402 meeting w/util in Bethesda,MD re analysis of accidents & transients & preparation of emergency procedure guidelines ROSS,D F Division of Project Management 80/03/17 App

- 8004070040 Summary of 800129 meeting w/util in Sethesda, MD re App J requirements ROONEY,V L Operating Reactors Branch 3 80/03/21 ip
- ---8004070042 Forwards notes of 800129 meeting w/util CARFAGNO.8 P Franklin Institute/Franklin Research Center 80/01/31 6pp
- 8004010237 Forwards inadvertently deleted page of "Cycle VII Startup Test Rept " SMITH.R L Vermont Yankes Nuclear Power Corp 80/03/24 ip
- --8004010243 Inadvertently deleted page of "Cycle VII Startup Test Rept "
 * Vermont Yankee Nuclear Power Corp E0/03/24 ip
- 8004010256 Responds to NRC telcon request for add1 info & clarification re NUREG-0578. Item 2 1 3a concerning direct position indication of safety & relief valvas Position indication sys consists of pressure switches in valve discharge piping CONHAY.W F Vermont Yankee Nuclear Power Corp 80/03/24 2pp.
- 8004080238 Forwards hydrogen monitoring sys description Util has investigated requirements of Recommendation 2 1 9 of NUREO-0578 Present sys meets virtually all monitoring requirements Replacement would be expensive & unnecessary CONWAY,W F Vermont Yankee Nuclear Power Corp 80/04/01 7p 80/04/01 700
- 8004080490 Forwards nonproprietary version of NRC 791211 presentation rept, "Eight by Eight Fuel Failure Investigation "
 SMITH,R L Vermont Yankes Nuclear Fower Corp 80/04/03 1p
- 8004110170 Responds to NRC 800110 ltr requesting info re failure of control rods to insert fully since Sept 1978 No failures observed On 781101. Control Rod 26-31 failed to latch after scram & settled to position 02 Rod retested satisfactority CONWAY, W F Vermont Yankee Nuclear Power Corp 80/04/04 ip
- 8004110434 Forwards Revision 8 to YOGAP-I-A addressing organization changes to GA program
 HEIDER, L H Yankee Atomic Electric Co GO/O4/O4 ip
- --8004110444 GA program Revision 8 for facility operation VANDENBURGH,D E, HCIDER.L H , MODDY,D E Yankee Atomic Electric Co YOGAP-1-A 80/04/01 20pp
- 8004210043 Requests that licensee remit add1 sum per 100FR170 requirements for Class III fee category to 800125 Tech Spec amend Fee should be submitted within 15 days after receipt of itr. MILLER, W O License Fee Management Branch 80/04/04 ip
- 8004250017 Forwards 800128 & 0211 ltrs to QE re proposed control rod drive sys mods related to elimination of cracking in return line notates Quidelines for mods will be discussed in NOREO-0619. to be issued in "For Comment" form in Apr 1980 IPPOLITO.T A Operating Reactors Branch 3 80/04/07 2pp
- HO04220307 Requests that Proposed Change 68 to Tech Space be withdrawn HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 80/04/15 ip
- BOO4290415 Requests mod to App A of OL reflecting change in organizational structure of util Deletes position of technical svcs supervisor & updates position titles & membership responsibilities of prof techniciens
 HEIDER, L H Vermont Yankes Nuclear Power Corp. BO/04/23 6pp
- 8004280506 Responds to NRC 800417 request Provides add1 info remonitoring to complete NRC review of 800401 response to NUREO-0578.TMI Lesseons Learned short-term requirements No flooding danger to hydrogen analyzers BMITH,R L. Vermont Yankee Nuclear Power Corp. 80/04/24 4pp.
- G Inspection reports, IE Bulletins & correspondence
- 8004080423 Advises that per telcon, anchor bolts associated w/two hangers on two 8-inch RHR lines which crossconnect RHR systo spent fuel pool cooling systell not be inspected or replaced as previously agreed upon for safety reasons MDDDY, D.E. Vermont Yankee Nuclear Power Corp. 80/02/28 Ip
- 8004080384 Submits schedule for response to IE Bulletin 79-018 re environ qualification of Class IE equipment Certain data for submittal not yet available JOHNSON,W P Vermont Vankse Nuclear Power Corp 80/03/04. 2pp

- 80040B0433 Requests confirmation of NRC understanding that 79-018 missing Item I info will be submitted by 800314 & Items 2 & 3 qualification work sheets submitted by 800314 per util 800304 telegopy GRIER B H Region 1, Philadelphia, Office of the Director
- 8004080261 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Util evaluating need for alarm in control room to indicate loss of power & revising instrument power bus procedures SMITH.R L Vermont Yankes Nuclear Power Corp 80/03/10 8pp
- 8004080269 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Revised data re I tem 1 & updated response to Items 2 & 3 attached Missing info will be submitted within 90-day period W/o encl
 JOHNSON, W P Vermont Yankas Nuclear Power Corp 80/03/14 2pp
- GO04090410 Advises that IE Bulletin GO-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," was incorrectly sent for action No response required ORIER, B H Region 1, Philadelphia, Office of the Director GO/03/17 ip
- 8004150307 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- B004090107 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oll Addition & Onsite Supply " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 ip
- 8004110515 Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004240393 Forwards IE Info Notice 80-14, "Eafety Suggestions From Employees" No action required CRIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004180251 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Bys " No written response required ORIER,8 H Region 1, Philadelphia, Office of the Director 80/04/03 1p
- 8004110072 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure "Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004230397 Forwards IE Builetin 79-03A, "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pipe" Action required GRIER, B H Region I, Philadelphia, Office of the Director 80/04/04 ip
- B004180293 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Wolds" Written response required ORIER, B M. Region i, Philadelphia, Office of the Director B0/04/07 ip
- R Periodic operating reports & related correspondence
- 8004150360 Forwards monthly operating rept for Mar 1980 MODDY, D.F. Vermont Yankee Nuclear Power Corp. 80/04/11 1p
- --8004150361 Monthly operating rept for Mar 1980
 BEERS:F C Vermont Yankee Nuclear Power Gorp 80/04/11 App
- 8004i80368 Notifies that meeting of Environ Technical Advisory Committee will be held 800509 in White River Junction VT Forwards annual, "Ecological Studies of CT River, Vernon/VT, Rept IX, 1979" Vermont Yankee Nuclear Power Corp 80/04/15 ip MARX.D J
- --- 8004180371 Annual "Ecological Studies of CT River, Vernon/VT, Rept IX, 1979." # Aquatic, Inc 80/04/15 203pp
- 8004220301 Forwards "Ecological Monitoring Rapt 1979" BMITH,R L. Vermont Yankes Nuclear Power Corp. 80/0 80/04/17 1p

- --8004220304 "Ecological Monitoring Rept 1979"
 * Vermont Yankee Nuclear Power Corp 80/04/17 203pp
- S Reportable occurrences. LERs & related correspondence
- 8004010489 Forwards LER 80-011/01T-0 HURPHY.W P Vermont Yankee Nuclear Power Corp 80/03/26 1p
- ---B004010479 LER 80-011/01T-0 on B00312, investigation of onsite power distribution sys revealed voltage of some 480-volt loads below min allowable w/min grid voltage & worse case loading Caused by incomplete analysis when transformers replaced MURPHY, W P Vermont Yankee Nuclear Power Corp 80/03/26 ip
- BOO4020356 Forwards LER BO-012/01P-0.
 MURPHY,W P Vermont Yankee Nuclear Power Corp B0/03/28 1p
- --8004020362 LER 80-012/01P-0 on 80032B, during seismic analysis, pipe supports RHR-H-83 & RSM-H-16B discovered possibly inadequate to support seismic load Caused by deviations from hanger design details Mods to sys will be performed MURPHY, & P Vermont Yankee Nuclear Power Corp 80/03/20 ip
- 8004040329 Forwards LER 80-010/03L-0 MURPHY,N P Vermont Yankee Nuclear Power Corp 80/03/31 1p
- --8004040332 LER 80-010/03L-O on B00307,50-millisecond value used in GE transient analysis for reactor protection sys delay time in violation of Tech Specs Tech Spec 3 1 A will be revised MURPHY.W P Vermont Yankee Nuclear Power Corp GO/03/31 ip
- 8004150506 Forwards LER 80-012/01T-0 MURPHY.H P Vermont Yankee Nuclear Power Corp 80/04/11 1p
- --8004150514 LER 80-012/017-0 on 800328, during seismic analysis required by IE Bulletin 79-14, discovered that pipe supports RHR-H-83 & RSM-H-168 may be inacequate to support seismic loads Caused by deviations from hanger design details.

 MURPHY, M P Vermont Yankee Nuclear Power Corp 80/04/11 1p
- 8004180410 Forwards LER 80~013/03L~0 MURPHY,W P. Vermont Yankee Nuclear Power Corp 80/04/14 ip
- --8004180413 LER 80-013/03L-O on 800326, while performing surveitlance test on HPCI, turbine speed would not increase above 800 rpm Caused by failure of flow controller Flow controller was replaced.

 MURPHY, W P Vermont Yankee Nuclear Power Corp 80/04/14. ip
- DUCKET 50-272 SALEH NUCLEAR GENERATING STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8004140037 Notifies that util 800125 proposed emergency plan must be revised Forwards specific criteria for compliance w/NUREO-0554 Proposed plan should be resubmitted SCHMENCER.A Operating Reactors Branch 1. 80/03/28 20pp,
- 9 Adjudicatory correspondence
- 8004040207 Comments on irresponsible way intervenors are being treated Sites case of ruling to allow Salem Unit 1 to operate despite no evidence that licensee could protect endangered shortnese sturgeon COLEMAN, E. G., COLEMAN, A. C. Affiliation Unknown 80/03/05 3pp
- 8004080633 Notices of KA Onsdorff withdrawl & RE Makul appearance on behalf of intervenors Colemans in proceeding. DNBDORFF,K A New Jersey, State of 80/03/10 2pp
- B004070005 Forwards intervenor Coleman B00317 motion for extension of time to file testimony & for postponement of B00422 hearing AYRES,S T New Jersey, State of B0/03/19 ip
- 8004i50027 Forwards licensee supplemental brief re motion for directed certification & for stay Pendency of Class 9 issue before Commission noted in Licensee motion for directed certification & for stay Discussed on Pages 7-10 METTERHAHN, M J Conner, Moore & Corber 80/03/24 2pg

- --8004150030 Supplemental brief re motion for directed certification & for stay Commission 800321 memorandum & order re Black Fox leaves no doubt that ASLAB proposed consideration of Question 5 is contrary to directive of Commission NETTERHANNIM J Public Service Electric & Qas Co of New Jersey WETTERHANNIM J Conner, Moore & Corber 80/03/24 App
- --8004150043 Memorandum & order varating portion of ALAB 973 captioned "Consideration of Class 9 Accidents" & remanding to ASLAB for further consideration Certificate of 8vc encl CHILK.B J Office of the Secretary of the Commission 80/03/21
- 8004100253 Memurandum & order denying licensee motion for certification.stay & other relief, reconsideration of Class Y accident environ consequences. In spent fuel pool storage expansion proceeding
 BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/04/01 1000
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification QOSBICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004240483 Forwards NRC confirmatory orders STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/04 ip
- --8004240490 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800701 Required info specified in Attachment A STELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 6pp
- --8004240495 Order confirming util commitment to perform review requested by IE Bulletin 79-27 Info required is specified in Attachment A STELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 App.
- 800A210291 Forwards response to Public Svc Electric & Cas Co of NJ comments re request of Lower Alloways Creek Township for suspension of monatorium of issuance of OL OL should not be issued until conclusion of ASLD hearing VALORE, C J Valore, C 80/04/15, 5pp
- 8004300585 Responds to 791018 petitions requesting that Commission issue show cause order to suspend or revoke OL for Balem 1 & CPs for Balem 2 & Hope Creek 1 & 2. & stay issuance of OL for Balem 2 Request denied W/Director's decision DENTON.H R Office of Nuclear Reactor Regulation 80/04/18 1p.
- ---B004300598 Notice of issuance & availability of Director's decision under 10CFR2 206 on A & E Coleman patition requesting that Commission issue show cause order re facilities OL & CP issuances DENTON, H R Office of Nuclear Reactor Regulation, 80/04/18 2pp
- --8004300400 "Assessment of Impacts of Facilities on Shorthose Sturgeon, Acipenser Brevirostrum Lesuer " MABNIK,M Y , WILBON, J, H Office of Nuclear Reactor Regulation 80/03/31 ip
- 8004220674 Response in opposition to Township of Lower Alloys Creek proposed testimony RE Wabb & DB Fankhauser testimonies should not be admitted in entirety, due to total concern w/Class 9 accident Certificate of Byc encl MORE, J. E Hearing Branch 2. PATON, W D Hearing Branch 4. 80/04/21 iJpp
- 8004270233 Notice of appearance in proceeding Certificate of Svc encl SCINTG.J. Regulations Division. 80/04/25 3pp
- H General correspondence
- 8004030123 Responds to 790816, itr re plans to reopen TMI-1, nuclear plant const in NJ & nuclear accidents. Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ No diseases resulted from TMI DENTON, HR Office of Nuclear Reactor Regulation 80/03/03 2pp.

- --8004030129 Opposes restart of TMI-1, const of nuclear plants in NJ to nuclear accidents due to health hazards & risks to public safety FOSTER:X Affiliation Unknown 79/08/16 2pp

I Financial information

- 8004070225 Confirms extension of date for submittal of annual certified financial statements from 800415 to 800515 Extension requested so that current cash flow projection can be furnished for 1980 SCHNEIDER.F.W. Public Service Electric & Gas Co. of New Jorsey 80/04/01
- P Operating license stage documents & correspondence
- 8004020460 Forwards NRC safety analysis of cracking discovered in feadwater sys Util repair program, nondestructive insps & laakage testing are adequate to insule that integrity of feedwater piping will be maintained SCHMENCER, A Operating Reactors Branch 1 80/02/25 App
- 8004020433 Summarizes 791210 audit of implementation of small break LOCA guidelines into plant procedures Forwards audit, list of meeting attendees & specific comments ROSS.W J Operating Reactors Branch 1 80/02/29 11pp
- G004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D O Division of Operating Reactors G0/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28pp
- 8004020184 Forwards add1 info re shortnose sturgeon in Delaware River Concludes that continued operation of Unit 1. future operation of Unit 2 & const completion of Hope Creek Units will not jeopardize existence of shortnose sturgeon REGAN.W H Assistant Director for Environmental Projects 80/03/14
- --8004020163 "Assessment of Impacts of Balem & Hope Creek Stations on Shortnose Sturgoon, Acipensor Brevinostrum Losuer " MASNIK, M T , WILSON, J H Office of Nuclear Reactor Regulation 80/03/05 110pp
- 8004150227 Notification of 800408 & 09 meeting w/util in Hancocks Bridge.NJ.re implementation of Lessons Learned Task Force short-term recommendations RUBB.W J Operating Reactors Branch i 80/03/20 2pp
- 8004080390 Forwards "Reactor Containment Integrated Leak Rate Test. First Retest Aug 1979 " LIBRIZZI.F P Public Service Electric & Gas Co. of New Jersey 80/03/31 ip
- --8004080394 "Reactor Containment Integrated Leak Rate Test,First Retest Aug 1979 " * PSE & G Research Corp. 79/08/31 200pp
- 8004210032 Forwards evaluation of info re auxiliary feedwater sys Open items must be resolved in acceptable manner prior to completion of safety evaluation Requests notification of further actions that will be taken to meet NRC position SCHMENGER.A Operating Reactors Branch 1 80/04/04 Bpp
- B004170060 Describes plans to staff licensed operator positions on both units, following QL issuance for Unit 2, per 800328 discussion w/NRG MITTLER L. Public Service Electric & Oas Co. of New Jersey MITTL.R L Pu 80/04/09, 3pp
- 8004170062 Forwards revised pages to 800102 response to TMI Lessons Learned Task Force short-term requirements, incorporating addl info in response to NRC 800608 request Also forwards revised pages previously submitted for Unit 2 by 8000328 itr LIBRIZZI.F.P. Public Service Electric & Gas Co of New Jersey. 80/04/11, 20pp
- 8004170250 Responds to NRC 800314 biological assessment of impact of continued operation or const of facilities Forwards biological opinion & summary of informal consultation w/NRC re Balem Unit i Shortness sturgeon are not in jeopardy LEITZELL,T L Commerce. Dept of. National Marine Fisheries Bervice 80/04/15 20pp

- 8004250366 Responds to 800107 ltr re QA requirements for diesel foel oil Fuel is supplied from day tanks which are fed from 20,000 gailon storage tanks Lists Tech Spec requirements re surveillance of fuel LIBRIZZI,F P Public Service Electric & Gas, Co of New Jersey 60,00421 10 80/04/21 10
- Q Inspection reports, IE Bulletins & correspondence
- 8004080318 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Failure analysis on circuit-by-circuit basis to check bus loads & alarms 40% complete Submittal by 801001 SCHNEIDER,F W Public Service Electric & Gas Co of New Jersey 80/02/24 2pp
- 8004170288 Forwards IE Insp Repts 50-272/79-32 & 50-311/79-37 on 791118-1215 No noncompliance nated BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/24 2pp
- --8004170293 IE Insp Repts 50-272/79-32 & 50-311/79-37 on 791118-1215 N noncompliance noted Major areas inspected plant operations, including tours of facility, log & record review, review of licensee events: IE circulars & bulletins & followup items KEMIGAR R Region 1, Philadelphia, Reactor Derations Nuclear Support Branch JOHNSON, D F , NORHOLM, L J Region 1, Philadelphia, Office of the Director 80/02/20 20pp
- 8004220416 Ferwards IE Insp Repts 50-272/79-32 & 50-311/79-37 on 791118-1215 & 800109 GRIER, B H Region t, Philadelphia, Office of the Director 80/02/26 2pp
- --B004220429 IE Insp Repts 50-272/79-32 & 50-311/79-37 on 791118-1215 & B00109 Noncompliance noted unauthorized individual approved tagging request w/o knowledge of responsible shift Supervisor JOHNBON, D F Region 1. Philadelphia, Reactor Operations Nuclear Support Branch NORRHOLML J Region 1. Philadelphia, Office of the Director 80/02/20 21pp
- 8004100256 Requests extension of response dates re IE Bulletin 77-01 Extension required due to numerous changes & respective scape of work SCHNCIDER, F. W. Public Bervice Electric & Gas Co. of New Jersey 80/02/29
- 8004210074 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance moted BHITH, OH Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- --8004210076 Haste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels, removable contamination & package external feature requirements POTIER J P. PEENY, W W. WOUDRUFF, R L. Region 1. Philadelphia, Fuel Facility & Materials Safety Dranch SO/01/18 7pp
- 8004100247 Forwards response to IE Bulletin 79-018 "Environ Qualification of Class IE Equipment " Partial response addresses Items 1,2 & 3 Submittal made por 800229 Itr W/o encl BCHNEIDER.F W Public Service Electric & Gas Co of New Jersey 80/03/07
- 8004300488 Advises that audibility survey requested by IE Bulletin 79-18 has been hampered by recent reactor outage Burvey still in progress Final rept will be forwarded by 800404 BCHNEIDER:FM Public Service Electric & Oas Co of New Jersey 80/03/18
- 8004240494 Responds to IE Bulletin 80-03 Interim findings of visual insp indicate adsorber cells are adequate w/few exceptions Investigation & evaluation are continuing Final rept expected by 800331
 SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey
- 8004160004 Forwards notice of violation from TE Insp on 790820-30 & 0930, notice of proposed imposition of civil penaties, enforcement history & order modifying license Notice of violation & enforcement history withhold (ref 100FR2 790) DEYQUNO,R C Office of Inspection & Enforcement, Office of the Director 80/03/20 2pp

- --8004i60007 Notice of proposed imposition of civil penalties Civil penalty must be paid or written answer protesting imposition of civil penalties submitted within 20 days of receipt of notice

 * Office of Inspection & Enforcement, Office of the Director 80/03/20 10
- --B004i40019 Order immediately modifying license to adopt & implement written security procedures requiring continuous surveillance of doors leading to vital areas & review to prevent security breach by maint activities DEYDUNG:R C Office of Inspection & Enforcement, Office of the Director B0/03/20 Spp
- BC04280207 Forwards second partial response to IE Bulletin 79-01B addressing Items 1.2 & 3 W/o encl SCHNEIDER.F W Public Service Electric & Qas Cn of New Jersey 80/03/21 2pp
- ©O04210016 Forwards IE Insp Rept 50-272/79-26 on 790828-30 GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/26 2pp
- --B004210024 IE Insp Rept 50-272/79-26 on 790828-30 Moncompliance noted physical barriers. Vital Doors B & 9, floor plate openings at 100.84 & 64 ft elevations, physical barrier patrols & access control Details withheld (ref 1005R2 790)
 DEVLIN. J W Region 1. Philadelphia, Safeguards Dranch
 BAILEY. R J Region 1. Philadelphia, Office of the Director 79/12/10
- BO04280111 Ack receipt of 800319 itr informing NRC of steps taten to correct violations noted in IE Insp Rept 50-272/80-01 BRUNNER, E J Region I, Philadelphia, Reactor Operations Nuclear Support Branch 60/03/26 ip
- --8004280124 Responds to NRC 800227 ltr re violations noted in IE (nsp Rept 50-272/80-01 Corrective actions personnel error re calibr procedures was torrected & supervisors have been reinstructed SCHNEIDER,F W Public Service Electric & Qas Co of New Jersey 80/03/19 2pp
- ---8004280130 Forwards IE Insp Rept 50-272/80-01 on 800122-25 & notice of violation BRUNNERSE J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/29 2pp
- ---B004280135 Notice of violation from insp on 800122-25
 * Region 1, Philadelphia, Office of the Director 80/02/27 19
- --8004280147 IE Insp Rept 50-272/80-01 on 800122-25 Noncompliance noted failure to properly review calibr data BAUNACK. W Region 1. Philadelphia, Reactor Operations Nuclear Support Branch BLUMBERG.N J Region 1. Philadelphia, Office of the Director 80/02/27 12pp
- BO04150296 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/31. 1p
- BOO4070101 Forwards IE Circular BO-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/04/01 1p
- RO04i1QSOA Forwards IE Info Notice 90-13. "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/02 ip
- ED04240342 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- BO04110497 Forwards "Computer Program Verification," using PIPDYN 11 stress analysis for NRC Benchwork Problems 1,2,323A & 803, in response to NRC 790724 request & IE Bulletin 79-07 LIBRIZI.F P. Public Bervice Electric & Oas Co of New Jersey. 80/04/03 Ip.
- ---8004110500 "Computer Program Verification "
 NANJAPPAM Public Service Electric & Gas Co of New Jersey
 LIN, 1. Franklin Institute/Franklin Research Center 80/04/03
 205pp

- B0041B0246 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Oil Sys " No written response required ORIEN.B H Region i. Philadelphia, Office of the Director B0/04/03 ip
- 8004230442 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required GRIER B H Region 1. Philadelphia, Office of the Director 80/04/04 ip
- 8004180280 Forwards IE Bullotin 80-08, "Exam of Containment Liner Penetration Welds " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/07 1p
- 8004160249 Revises 770520 response to item of noncompliance noted in IE insp Rept 50-272/77-13 re starting reactor coolant pump Operating instruction prohibiting starting while reactor is critical has been deleted SCHMEIDER, F N Public Service Electric & Gas Co of New Jersey 80/04/08 2aa
- 8004140246 Responds to item of noncompliance noted in IE Insp Rept 50-272/80-05 Work order initiated to investigate inoperable boron injection tank host trace channel & conduct necessary repair action Surveillance procedure will be revised SCHNEIDER, E.J. Public Service Electric & Oas Co. of New Jersey 80/04/10 2pp
- R Periodic operating reports & related correspondence
- B004010331 Forwards "First Interim Rept,316(b) Studies," for Mar-Nov 1979 LIBRIZZI,F P Public Service Electric & Qas Co of New Jersey 80/03/18 10
- --8004010337 "First Interim Rept,316(b) Studies," for Mar-Nov 1979 * Fublic Service Electric & Gas Co of Naw Jersey 80/02/27 150pp
- 8004150384 Forwards monthly operating rept for Mar 1980 MIDURA. H J Public Service Electric & Oas Co of New Jersey 80/04/10 ip
- --8004150389 Monthly operating rept for Mar 1980 MILLER,L K Public Service Electric & Gas Co of New Jersey 80/04/10 19pp
- 8004290489 Forwards "NPDES Discharge Monitoring Repts for Jan-Har 1980 " MIDURA, H J Public Service Electric & Oas Co of New Jersey
- --8004290497 "NPDES Discharge Monitoring Repts for Jan-Mar 1980 "
 * Public Service Electric & Gas Co of New Jersey 80/04/21, 54pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004220226 PND-77-002 on 770103.RC8 was leaking Caused by broken vent iins in letdown line to chemical vol control sys No personnel overexposures or radioactive releases occurred Licensee plans cleanup operations & repair of broken line DREMER, F. ROY, O. W. Region 1. Philadelphia, Office of the Director, THOMPSON, D. Region 3. Chicago, Office of the Director 77/01/04, 2pp
- B0042200B4 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770B12
 WHITT.K W , NOLAN,F Region 2, Atlanta, Office of the Director 77/08/12 ip
- --8004010348 LER 60-013/03L-0 on 800227, during routine surveillance, temp maintained by heat trace circuit 403 found to be 142 F instead of 145 F Caused by pipe insulation erosion Heat tracing repaired & piping reinsulated MURPHY, M J Public Service Electric & Oas Co of New Jersey 80/03/27 19
- 8004010386 Forwards LER 79-089/03L-0 LIBRIZZI,F P Public Service Electric & Oas Co of New Jersey 80/03/27 3pp

- --B004010370 LER 79-059/03L-0 on 790424 & 0508, during refueling outage, Public Svc Relay Dept was performing relay tests & de-energized vital bus supplying operating RHR pump Caused by inadequate work procedures Low level limit raised KAPPLE,A W Public Service Electric & Gas Co of New Jersey B0/03/27 ip
- 8004040317 Forwards LER 80-014/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/03/31 3pp
- --800403034 LER 80-014/03L-0 on 800303, ground developed on power supply line to Unit 3, resulting in loss of station power transformer 12 Power supply line replaced & transformer re-energized MURPHY.H J Public Service Electric & Qas Co of New Jersey 80/03/31 ip
- 8004110472 Forwards supplemental LER 79-053/01X-1 LIBRIYZI,F P Public Service Electric & Gas Co of New Jersey 80/03/31 3pp
- --8004i10494 Supplemental LER 79-053/01X-1 on 7908i0, during refueling outage, stress calculations for safety-related pipe support found unacceptable Gaused by using computer code which calculated piping response by algebraic summation method KAPPLE, A W Public Servico Electric & Gas Co of New Jersey 80/03/31 1p
- 8004280225 RO 80-17/01P on 800228.during review of environ qualification documentation for accident mitigation/shutdown equipment.RCS wide pressure transmitters found located below max containment flood level following major LOCA MIDURA.H J Public Service Electric & Gas Co of New Jersey 80/03/31 3pp
- 8004080525 Forwards LER 80-015/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/04/01 ip
- --8004080933 LER 80-019/03L-0 on 800304, during normal operation, auxiliary annunciator typewriter began printing meaningless messages Caused by fatled solid state component circuit board in typewriter logic control cabinet Circuit board replaced MURPHY, M J Public Service Electric & Oas Co of New Jersey 80/04/01 Spp
- 8004140320 Forwards LER 80-016/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co. of New Jersey 80/04/09 3pp
- --8004140323 LER 80-016/03L-0 on 800319, while taking voltage readings in RMB rack, power supply inadvertently grounded by instrument probe resulting in 115 volts ac breaker trip Caused by personnel error Instrument reset MURPHY. M J Public Bervice Electric & Gas Co of New Jersey 80/04/09 ip
- 8004140409 Forwards LER 79-081/04L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jarsey 80/04/09 2pp
- --B004140412 LER 79-0B1/04L-0 on 790B23 during normal river trawling survey of DE River.Atlantic loggerhoad sea turtle was captured Turtle is listed as threatened & endangered Turtle was released unharmed MURPHY, M J Public Service Electric & Qas Co of New Jersey B0/04/09. ip.
- 8004300495 Ack receipt of 800306 ltr.in response to NRC 800211 ltr re RD 79-71 Corrective actions will be examined during subsequent insp
 MDSELEY.N C Division of Reactor Operations Inspections. 80/04/09
- 8004190593 Forwards LER 80-017/01T-0 LIBRIZZI,F P Public Service Electric & Gas Co. of New Jersey 80/04/11 4pp
- --8004150558 LER 80-017/01T-0 on 800328, during review of environ qualification documentation required by IE Bulletin 79-01B, RC8 wide range pressure transmitters were found below max flood level Caused by imposition of new requirements MURPHY.M J Public Service Electric & Gas Co of New Jersey 80/04/11 1p

- T Hearing transcripts on non-antitrust matters
- 8004180405 Forwards NRC direct testimeny re ASLB Question 5 & prof qualifications of NRC witness, MF Pasedag Also forwards piofessional qualifications of AS Benjamin, Gandia Labs MCORE, J E Hearing Branch 2 80/04/10 ip
- --8004180416 Direct testimony of WF Pasedag in response to ASLB Question 5 Pp 1-5 WF Pasedag prof qualifications encl PASEDAG.W F Commission 80/04/10 7pp
- V Operator Examinations
- 8004030257 Provides add1 info per 800125 request Operator licensed for one unit of two-unit facility must take oral & written eiamination when applying for license on second unit Applicant must scare min 80% overall to receive license COLLINS.P F Operator Licensing Branch 80/03/20 2pp
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS DF Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re auxiliary foodwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of OL W/encl ROSS, D F Division of Project Management 80/03/10 53pp
- 8004010436 Forwards addl info re refueling water storage tank capacity in response to 790720 request FSAR commitments & Tech Spec limit is 350,000 gallons Possibility for 27 error exists in indication of tank level CRANE.P A Pacific Qas & Electric Co 80/03/20 6pp
- 8004010437 Forwards Draft 2.Revision 2 of proposed ET8 for facility. in response to NRC request TIDRICK, G A Pacific Gas & Electric Co 80/03/21 1p
- --8004010441 Draft 2.Revision 2 of proposed ETS for facility * Pacific Gas & Electric Co 80/03/31 21pp
- 8004080466 Forwards nonproprietary version of response to NRC 790912 ltr re tube wear Application for withholding proprietary info & Westinghouse supporting ltrs encl CRANE,P A Pacific Oas & Electric Co 80/03/25 34pp
- BOO4020283 Advises that work of R Lesley re offshore faults does not impact conclusions contained in Suppl 4 of safety evaluation concerning possible connection between Ban Simeon & Hosgrifault tones
 DEVINE, JF Interior, Dect of, Geological Survey 80/03/31 10
- 8004040281 Forwards response to short-term Lessons Learned Task Force requirements Five oversize drawings encl CRANE.P A Pacific Gas & Electric Co 80/03/31 35pp
- BOO4140016 Notification of 800404 meeting w/utils in Bethesda, MD to discuss applicants' progress & status in design review re plant shielding & environ qualification of equipment for spaces/sys used in post-accident operations
 BUCKLEY. B C Light Water Reactors Branch 1 DROMERICK, A W , LICITRALE A Light Water Reactors Branch 3. 80/03/31 7pp
- 8004240248 Responds to 791115 telegram to F Press science advisor to President Kemeny Commission rept on TMI accident is being incorporated into NRC Action Plan Applicants will need to implement recommendations prior to CL issuance ROSS, D F Division of Project Management 80/04/01 5pp
- 8004240520 Discusses potential design deficiencies in hypass. override & reset circuits of engineered safety features Cites specific examples, safety significance & criteria to be satisfied Protection sys design conformance response due by 800405 STOLZ. J F Light Water Reactors Branch 1 80/04/01 Spp

- BOO4080443 Forwards press clippings purporting to state NRC position re Chumash Indians' access to facility Util is willing to meet & discuss issue Access question derived from possible application of Native American Religious Freedom Act PETERS,R J Pacific Qas & Electric Co 80/04/03 4pp
- B004150435 Forwards draft "Archaeological Resources Mgt Plan " Plan covers area north of plant in area designated 5LO-2 PETERS,R J Pacific Gas & Electric Co 80/04/07 2pp
- --8004150441 Draft "Archaeological Resources Mgt Plan"
 Pacific Gas & Electric Co 80/04/30 45pp
- 8004150337 Forwards comparison of NUREO-Odil recommendations for auxiliary feedwater sys to design &/or operation of facility sys CRANE.P A Pacific Gas & Electric Co 80/04/08 8pp
- 8004160253 Responds to NRC request for add1 info re secondary water chemistry control & forwards administrative operating & chemical analysis procedures Procedures include schematic diagrams indicating sampling point locations
 CRANE,P A Pacific Oas & Electric Co 80/04/08 2pp
- --8004160296 Operating Procedure F-5.Revision 1. "Chemical Control Limits "
 - * Pacific Gas & Electric Co 80/02/01 42pp
- --8004i60259 Chemical Analysis Procedure A-2,Revision 2, "Secondary Cycle Sampling Schedule" + Pacific Oas & Electric Co 79/12/04 Spp
- --8004160260 Chemical Analysis Procedure E-6. "Secondary Sys Sampling "
 Pacific Gas & Electric Co 80/01/08 5pp
- ---8004160264 Administrative Procedure C-12, Revision 2, "Resolution & Reporting of Plant Problems "

 * Pacific Gas & Electric Co 78/03/06 12pp
- --8004160267 Administrative Procedure C-201, Revision 1. "General Requirements for Chemical & Radiochemical Control Programs " * Pacific Gas & Electric Co 75/11/24 3pp
- --8004160271 Suppl to Administrative Procedure C-20, "Chemistry Data Review & Record Mgt " Descriptions of secondary water chemistry control program encl * Pacific Oas & Electric Co 75/11/24 12pp
- 8004170074 Forwards Revision 3 to response to NUREO-0978 re short-term Lessons Learned Task Force recommendations CRANE.P A Pacific Gas & Electric Co 80/04/09 29pp
- 3004150343 Forwards Revision 4 to facility response to short-term Lessons Learned Task Force requirements CRANE.P A Pacific Gas & Elactric Co 80/04/11 21pp
- 3004220406 Responds to NRC 800228 ltr requesting add1 info required to evaluate mpt & technical resources available at POSE facilities Advises that 800221 telcon w/J Powers of Teknekron relayed requested info CRANE.P A Pacific Gas & Electric Co 80/04/15, 1p
- 3004220692 Reissues Revision 2 to response to NUREC-0578 Also forwards modified instructions for Revision 2 insertion into manual & eight administrative procedures previously sent to review group Oversize drawings encl
 CRANE.P A Pacific Oas & Electric Co 80/04/18 33pp
- -8004220697 "General Authorities & Responsibilities of Shift Foremen " # Pacific Qae & Electric Co 80/03/27 2pp
- ~8004220704 "Plant Staff Organization & Responsibilities for Normal Operations," Revision 2 * Pacific Gas & Electric Co 80/03/27 3pp
- -8004220716 "Caneral Authorities & Responsibilities of Nuclear Plant

7 3p

hift Tachnical Advisor (Bhift

200

f Off-duty Personnel."

200

- ---8004220744 "Relieving Watch (Shift Turnover)," Revision 3 * Pacific Gas & Electric Co 80/03/27 2pp

- 8004280373 Forwards Revision 5 to response to NUREO-0578 Changes result from questions by NRC reviewers preparing BER CRANE.P A Pacific Oas & Electric Co 80/04/22 Bpp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr, has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004240384 Forwards diaft rapt, "Evacuation Times Assessment Study," in response to NRC 791226 request Rept will be raissued w/possible minor changes by 800523 LOCKER F Pacific Oas & Electric Co 80/04/11 ip
- --B004240389 "Evacuation Times Assessment Study "
 PRC Systems Services Co 80/04/30 102pp
- O Adjudicatory correspondence
- 8004020133 Request by joint intervenors for Commission early intercession or reconstitution of ABLB.re seismic issues Urges disqualification of JH Buck due to prior involvement Requests oral argument on issue Certificate of Svc encl FLEISCHAKER.D Fleischaker, D B PHILLIPB.J R Center for Law in the Public Interest 80/03/13 23pp
- 8004090038 Request by joint intervenors, to stay 800403 oral argument re seismic issues Adequate time should be given to Commission to evaluate joint intervenors' request for early intercession or reconstitution of ASLAB PFLEISCHAKER, D B Fleischaker, D B PHILLIPS, J R Center for Law in the Public Interest 80/03/i3 4pp
- 8004080712 Notifies of appearance on behalf of applicant at oral argument re intervenors exceptions concerning earthquake issues.per ASLAB 800225 order Cartificate of Svc encl NORTON.B Bruce Norton 80/03/14 3pp
- 8004030015 Opposes operation of facility CA is not safe place to build power plants due to saismic activity SNAPP.C Affiliation Unknown 80/03/15 ip
- 8004090033 Advises of appearance on behalf of Govenor of State of CA, at 800403 hearing Certificate of Svc ancl BROWN, H H Hill Christopher & Phillips 80/03/17 4pp
- 8004220001 Forwards notice of appearance of author,PC Valentine & A Baldwin on behalf of San Luis Obispo Mothers for Peace Intervenor JP Taylor prof qualifications encl JONES,Y I James. Brown & Clifford 80/03/17. 13pp
- B004020086 Response in opposition to joint intervenors B00313 request to stay oral argument re seismic issues Urges denial of joint intervenors B00319 request for Commission early intercession or ASLAB reconstitution H/Certificate of Svc. KETCHEN.E 9 Hearing Branch 4 B0/03/21. 20pp
- 8004080681 Order re Joint Intervenors' 800313 motions. Commission shall not interceds in seismic proceeding JH Buck should publish decision by 800403 Dral argument denied CHILK.S.J. Office of the Secretary of the Commission 80/03/21
- 8004020020 Forwards affidavit of nondisclosure & protective order drafts.per ASLAB 800225 first prehearing conference order Advises that parties were unable to agree on certain provisions Encloses list of NRC witnesses re security issue STAENBURO, M.R. Regulations Division 80/03/24 17pp
- 8004090132 Response by joint intervenors in opposition to Commissioner Hendrie decision to hear proceeding. Ex parte communication is sufficient for withdrawaliper case law regardless of bias against or in favor of party Decision should be retracted. FLEISCHAKER, D. Fleischaker, D. S. PHILLIPS, J. R. Center for Law in the Public Interest. 80/03/26 11pp

- --8004090137 Response by joint intervenors in opposition to Commissioner Kennedy decision to hear proceeding Ex parte communication is sufficient for withdrawal, per case law, regardless of bias against or in favor of party Certificate of Svc encl FLEISCHAKER,D Fleischaker, D S PHILLIPS,JR Center for Law in the Public Interest 80/03/26 14pp
- 8004230107 Forwards USGS Circular 795 containing conclusions re adjudicated issues.per ASLAB directive to provide new info if relevant t mat! FLETSCHAKER,D Fletschaker, D S 80/03/26 51pp
- 8004080556 Petition by Joint Intervenors for review of JH Buck decision to remain member of ABLAB re seismic appeal Prior involvement in facility solamic concerns may jeopardize ability to maintain total impartiality W/Certificate of Svc FLEISCHAKER, D Fleischakor, D S PHILLIPS, J R Center for Law in the Public Interest 80/03/28 8pp
- 8004210322 Motion by Joint Intervenors to reppen record re seismic issues & environ qualification of safety-related equipment
 New info invalidates ASLB evaluation of Hosgri seismic fault W/Certificate of Svc & supporting documentation
 FLEISCHAKER,D Fleischaker, D S PHILLIPS,J Center for Law in the Public Interest FLEISCHAKER,D San Luis Obispo Mothers for Peace 80/03/28 18pp
- ~-8004210325 Affidavit indicating that facility design accelerations, velocities & displacements are not established as conservative values for M-7 5 design earthquake Bupporting documentation encl
 BRUNE, J N California, Univ of San Diego 80/02/29 43pp
- ---B004210327 Affidavit advising of recent investigations indicating that Hosgri & San Simeon rones represent continuous & throughgoing fault sys Chart encl LEBLIE:R B California, Univ of, Banta Cruz 80/02/28 7pp
- --8004210393 Affidavit demonstrating that independent review of safety related equipment qualification program should be conducted prior to OL issuance HUBBARD.R B. MHD Technical Associates 80/02/20 13pp
- ~-8004210375 "Preliminary Rept on Strong-Motion Records from Imperial County Svcs Bldg." KOJAHN.C , RAGSDALE.J D Affiliation Unknown 80/02/28. 18pp
- 8004070454 Order denying Joint Intervenors 800328 petition for review of JH Buck 800324 memorandum stating intention not to disqualify from participation JH Buck prior involvement at CP stage does not require disqualification CHILK.B J Office of the Secretary of the Commission 80/04/01 300
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OCSSICK, L V Office of the Executive Director for Operations 80/04/02. 34pp
- 8004210100 Hemorandum to counsels re Joint Intervenors 791024 motion requesting Commissioner Hendrie's disqualification Intervenors have presented no new info proving bias or appearance of bias Self-disqualification not required HENDRIE, J Commission 80/04/07 2pp
- 8004230081 Advises that applicant response to joint intervenors 800328 motion to reopen evidentiary hearings is due on 800424 & NRC response on 800505, per 800403 stipulation approved by ABLAB KETCHEN, E O Hearing Branch 4 80/04/07 2pp
- 8004240541 Ack receipt of Anson 800325 ltr distributed to all parties for consideration BIBHOP:C J Atomic Safety and Licensing Appeal Panel 80/04/09
- --8004240545 Forwards map indicating inner evacuation area Expresses concerns re escape routes during meltdown event ANBON: # B Affiliation Unknown 80/03/25 App
- 8004210168 Order granting extension, until 800415, for Commission to act to review ALAB-583 CHILK, S. J. Office of the Sacretary of the Commission. 80/04/10 in.

- B004230098 Order reporting 800402 second prehearing conference re procedures & schedules for receiving security plan evidence Licensee physical security plan is entitled to confidential treatment per encl protective order & affidavit BISHOP.C J Atomic Safety and Licensing Appeal Panel B0/04/10
- --B004230103 Protoctive order re licensee security plan, restricting San Luis Obispo Mothers for Peace access to protected info per enci affidavit of nondisclosure to be executed by counsel & experts BALZMAN, R S Atomic Safety and Licensing Appeal Panel 80/04/03
- 8004220371 Response in opposition to POLE 800414 application for stay of ASLAB 800411 order re disclosure of sanitized version of security plan Applicant failed to show that util will be irreparably harmed from disclosure W/Certificate of 8vc DAVIS,L D Hearing Branch 4 80/04/18 12pp

H General correspondence

- 7706290854 Responds to 770411 ltr on reactor safety, clarifying concerns re Davis-Besse shutdown & geologic faults near Diablo Canyon EISEN/UT, D G Division of Operating Reactors 79/05/22 2pp
- BO04040346 Forwards articles from Los Angeles Times re analysis of util financial problems apgravated by commitment to large coal 8 nuclear power plants RGE,D Environmental Derense Fund 80/02/27 7pp
- 8004030010 Requests permanent denial of OL ANSHUTZ, T L Affiliation Unknown 80/03/08 ip
- 8004030008 Urges ticensing of power plants ready or near ready for operation Reliable power reserves at stake in CA TERRELL.O D Affiliation Unknown 80/03/10 1p
- B004030180 Urges release of hold on licensing plant for operation Area may suffer brownouts & blackouts if plant not licensed within one or iwo months
 MCRRIS.E W Affiliation Unknown 80/03/10 ip
- 8004020250 Responds to 800207 mailgram to President Carter re validity of rumor concerning 800531 issuance of OL to facility NRC has no knowledge of rumor & no such decision has been made NRC is preparing action plan to complete licensing reviews DENTON, H R Office of Nuclear Reactor Regulation 80/03/17 2pp
- 8004110303 Opposes nuclear power plants due to extreme danger to population resulting from meltdown Winds in area of facility would quickly spread radiation over 35-mile radius NRC should expand evacuation area accordingly ANSON.N B Affiliation Unknown 80/03/25 5pp

I Financial information

- BOO4100233 Forwards Annual Financial Rept 1979
 GRANE, P. A. Pacific Gas & Electric Co. BO/04/03 ip
- --8004100244 Annual Financial Rept 1979 * Pacific Oas & Electric Co 80/02/22 43pp
- G Inspection reports. IE Bulletins & correspondence
- 8004070175 Forwards IE Insp Rept 50-275/80-01 on 800101-25 No noncompliance noted CREMS.J L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/02/20 2pp
- --8004070178 IE Insp Rept 50-275/80-01 on 800101-25 No noncompliance noted Major areas inspected preoperational testing, plant tour, fire protection/prevention.operator training & witnessing of testing in progress
 BTERNBERG, D M Region 5. San Francisco. Reactor Operations Nuclear Support Granch YOUNG, T Region 5. San Francisco, Office of the Director 80/02/06 3pp
- 8004280016 Forwards IE lnsp Repts 50-275/80-02 & 50-323/80-01 on 800211-14 & 20 No noncompliance noted SPENCER.0 & Region 5. San Francisco: Reactor Construction & Engineering Support Branch 80/03/04 2pp

- --B004280022 IE Insp Rapts S0-275/80-02 & S0-323/80-01 on 800211-14 & 20 No noncompliance noted Major areas inspected const & mod activities, including licensee actions on previous findings, deficiency repts item, IE bulletins & circulars HAYNES:R C Region S. San Francisco, Reactor Construction & Engineering Support Branch MORRILL, J . KIRSCH, D F Region S. San Francisco, Orfice of the Director 80/03/04 7pp
- 8004150205 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary EMGELKEN: R H Region 5, San Francisco, Office of the Director 80/03/31 ip
- BOO4100101 Forwards 1E Circular 80-05, "Emergancy Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required ENGELKEN H Region 5, San Francisco, Office of the Director 80/04/01 ip
- 8004110111 Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN'R H Region 5, San Francisco, Office of the Director 80/04/02 1p
- 800422003B Forwards IE Info Notice 80-14, "Safety Suggestions From Enployees" No action required ENGELKEN: R H Region 5. San Francisco, Office of the Director 80/04/02 ip
- 8004180148 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required ENSELKEN.R H Region 5, San Francisco, Office of the Director 80/04/03 ip
- 8004230379 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ASME SA-312-Type 304 Stainless Steel Pipe." Action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/04/04 1p
- 8004220176 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ENGELKEN, R H Region 5, San Francisco. Office of the Director 80/04/07 ip
- S Reportable occurrences, LERs & related correspondence
- 8004220084 PNG-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of interior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT,K W Region 2, Atlanta, Office of the Director 77/08/12
- 8004040131 Preliminary deficiency rept re possible equipment defact Un 800118, licensee reported that plastic castings used to hold auxiliary electrical contacts in safety-related 4-kV circuit breakers contained cracks Vendor will replace CRANE, P A Pacific Oas & Electric Co 80/03/10 2pp

- POCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8004010329 Forwards Items 3 1 5(2) & 3 1 7 of fire protection review Licensee submittal re fire barrier penetration seals only partly satisfactory Licensee proposal re fire doors acceptable

 MALL.R E Brookhaven National Laboratory 80/03/26 4pp
- 8004280252 Forwards comments on 800114 emergency plan, per review against criteria set forth in NUREG-0654 IPPOLITO, T A Operating Reactors Branch 3 80/04/01 14pp
- G Adjudicatory correspondence
- BOO4090192 Explains circumstances involving BOO222 svc of BNWL draft rept re measurements of underground mining radon releases & NRC testimony of RM Wilde re same rept Hissing Page & enci BORDENICK.B M Hearing Branch 4 80/03/05 4pp
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations BO/04/02 34pp
- I Financial information
- 8004190246 Forwards Annual Financial Repts 1979 for Philadelphia Electric Co, Public Svc Electric & Oas Co. Atlantic City Electric Co & Delmarva Power & light Co BRADLEY.E J Philadelphia Electric Co 80/04/08 1P
- --8004150250 Annual Financial Rept 1979
 * Philadelphia Electric Co 80/02/25 32pp
- --8004150252 Annual Financial Rept 1979 * Public Service Electric & Gas Co of New Jersey, 80/02/15
- --8004150260 Annual Financial Rept 1979
 # Delmarva Power & Light Co 80/02/15 32pp
- 8004190470 Requests that date for filing certified financial statements & cash flow statements be delayed until 800515, due to pending rate proceedings involving Public Svc Electric & Gas Co & Philadelphia Electric Co BRADLEY, E J Philadelphia Electric Co 80/04/10 2pp
- P Operating license stage documents & correspondence
- 8004080194 Discusses NRC 76i123 request that all LHR licensees assess higher fission gas release for fuel burnups above 20,000 MW-day per metric ton Responses indicate that no immediate licensing is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIBENHUT.D 9 Division of Operating Reactors 80/03/12 Spp.
- --8004030118 "Nuclear Data Link Specs"
 * Division of Operating Reactors 80/02/21 28pp
- 8004230409 Forwards Amends 65 & 64 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability IPPOLITO.T.A Operating Reactors Branch 3 80/03/26. 2pp
- --8004230414 Amends 65 & 64 to Licenses DPR-44 & DPR-56, respectively, revising Tech Spacs re core monitoring.core floading & sysoperability requirements TPPOLITO: TA Operating Reactors Branch 3 80/03/26 28pp
- --B004230419 Safety evaluation supporting Amends 65 & 64 to Licenses DPR-44 & DPR-56 respectively * Office of Nuclear Reactor Regulation 80/03/26 7pp

- -8004230441 Notice of issuance & availability of Amends 65 & 64 to Licenses DPR-44 & DPR-56, respectively IPPOLITO, T A Operating Reactors Branch 3 80/03/26 2pp
- 8004010406 Provides add1 info re proposed installation of analog transmitters & trip units addressed in 790827 amend request Amend is necessary to allow removal of 24 safety-related switches in soveral facility sys DALTROFF, 8 L Philadelphia Electric Co 80/03/27 2pp
- 8004080538 Responds to NRC 800110 request for tabulation of instances of control rods failing to insert on scram & summary of other control rod drive malfunctions for 1978 & 1979 Facility experienced 15 scrams w/successful rod insertion GALLAGHER, J H Philadelphia Electric Co 80/03/31 200
- BOO4080543 Discusses implementation of ATMS mitigation Alternative 3A Prefors prevention of event rather than mitigation Util will install Alternative 3A in facilities if ACRS subcommittee believes ATMS is not extremely remote event DOYER.V 8 Philadeiphia Electric Co 80/03/31 2pp
- 8004080349 Forwards revisions & additions to info originally submitted 791116 to Bulletins & Orders Task Force re process signals QALLAGHER, J W Philadelphia Electric Co 80/04/02 13pp
- 8004140273 Notifies NRC of intent to modify containment suppression chamber Analysis indicates need for torus mods to mitigate effects of hydrodynamic loads Util will install load mitigation devices during current refueling outage XEMPER, J 8 Philadelphia Electric Co 80704/03 ip
- BO04240299 Forwards Amends 46 & 65 to Licenses DPR-44 & DPR-56, respectively safety evaluation & notice of issuance & availability

 IPFOLITO, T A Operating Reactors Branch 3 80/04/03 2pp
- ---B004240307 Amends 66 & 65 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs to permit purging of primary containment through reactor bldg ventilation exhaust FPPCLITG. 7 A Operating Reactors Branch 3 B0/04/03 IOpp
- --8004240320 Safety evaluation supporting Amends 66 & 65 to Licenses DPR-44 & DPR-96, respectively * Operating Reactors Branch 3 80/04/03 4pp
- --8004240327 Notice of issuance & availabilty of Amenda 66 \$ 65 to Licenses DPR-44 & DPR-56, respectively IPPOLITO, T A Operating Reactors Branch 3 80/04/03 2pp
- 8004250007 Forwards 800128 & 0211 ltrs to 0E re proposed control rod drive sys mods related to elimination of cracking in return line notices Outdelines for mods will be discussed in NUREO-0619, to be issued in "For Comment" form in Apr 1980 IPFOLITO, T A Operating Reactors Branch 3 80/04/07 2pp
- 8004220549 Responds to NRC 800228 request for info re mgt & technical resources. COONEY.M J Philadelphia Electric Co 80/04/11 9pp
- 8004240402 Responds to NRC 800414 ltr re QA of diesel generator fuel oil QA program mod underway to conform w/Reg Ouide I 137 Revision I, "Fuel Oil Gys for Standby Diesel Generators " Requires mods of storage tanks & procurement of equipment DALTROFF, S L Philadelphia Electric Co 80/04/14 App
- 8004170246 Forwards application for amend of Licenses DPR-44 & DPR-54 Fee encl BRADLEY.E J Philadelphia Electric Co 80/04/15 ip
- -8004170252 Application for amend of Licenses DPR-44 & DPR-96 changing Toch Specs re station fire hose hydrostatic test pressure & flexibility in min shift crew composition Certificate of Svc BAUER, E G . BRADLEY, E J Philadelphia Electric Co 80/04/13
- --B0041/0256 Revised pages to Tech Specs re station fire hose hydrostatic test pressure & flexibility in min shift crew composition * Philadelphia Electric Co B0/04/15 10pp
- BOO4290423 Notifies NRC that util has been informed by QE that Unit 1 Reload 4 & Unit 3 Reload 3 safety analyses were performed using 50 millisecond scram circuit delay time Tech Spec specifies delay not to acceed 100 milliseconds COONEY, M J Philadelphia Electric Co BO/04/23 3pp.

- G Inspection reports, IE Bulletins & correspondence
- 8004100211 Responds to IE Bulletin 79-27 re loss of Non-Class IE instrumentation Submits actions requested & responses Design mods pending completion of review DALTROFF.S.L. Philadelphia Electric Co. 80/02/29 5pp
- 8004160165 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted BMITH, G H Region I, Philadelphia, Fuel Facility & Materials Saf Branch 80/02/29 2pp
- --B004160172 Waste Perkaging Insp Rept 79-06A on 771126-28 No noncompliance noted Major areas inspected radiation levels, shipping paper requirements removable contamination & labeling requirements for packages POTTER, J.P., JRONN, R.A., Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/12/12 7pp
- 8004140064 Forwards response to IE Bulietin 79-018 re environ qualification of Class IE equipment Master list of engineered safety feature sys 8 environ qualification evidonce attached HELB analysis due by 800410 W/o encl DALTROFF, 8 L Philadelphia Electric Co 80/03/03 3pp
- B004210079 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH, G H Region 1. Philadelphia. Fuel Facility & Materials Bafe Branch B0/03/05 2pp
- --B0042100B2 Waste Packaging Rept 79-07A on 791212-13 No noncomplien noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contemination & packaging external feature requirements POTTER, JP. PERRY, W. HODDRUFF, R. L. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch HO/01/18 7pp
- GOO4090416 Advisor that IE Bulletin GO-OS, "Vacuum Condition Resulti in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," was incorrectly sent for action No response requised GRIER. B H Region i. Philadelphia, Office of the Director ORIER B H R
- GCO4100261 Responds to IE Buildtin BO-03 No cells replaced in engineered safety feature filtration systhomover charcoal adsorber cells will have to be removed to replaced rivits indicated in Item 1 DALTROFF, S.L. Philadelphia Electric Co. 80/03/18 3pp
- 8004140183 Ack receipt of 800228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-29 & 50-279/79-32 BRUNNER/E J Region 1. Philadelphia, Reactor Operations Nuclear Buppert Branch 80/03/21
- --8004160187 Responds to NRC 800208 1tr re violations noted in IE Inc.
 Repts S0-277/79-29 & 50-278/79-32 Corrective actions review
 of provision allowing entry w/o filling out radiation work
 permit will be made w/revisions to procedures
 DALTROFF, 8 L. Philadelphia Flacture Co. 80/03/28 200
- --F
- --B004i40174 IE Insp Repts 30-277/79-29 & 30-278/79-32 on 79i101-30 Noncompliance noted failure to adhere to radiation work permit & maintain fire & penetration seal barrier MCCABE.E C Region 1. Philadelphia. Reactor Operations Nuclear Support Branch GREENMAN.E 9 Region 1. Philadelphia. Office of the Director 80/02/04 13pp
- 8004150291 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region I, Philadelphia, Office of the Director 80/03/31 ip
- BOO4250045 Updates BOO22? response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation " Lists mods being designed to provide redundant instruments in control room GALLAGHER, J W Philadelphia Electric Co BO/03/31 :11pp

- 8004070075 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply " No written response required GRIER, B H Region L. Philadelphia, Office of the Director 80/04/01 1p
- E004110501 Forwards IE Info Notice 80-13, "OE Type 80M Control Switches Defective CAM Followers " No written response required ORIER, B M Region), Philadelphia, Office of the Director 80/04/02 10
- B004240339 Forwards IE Info Notice 80-14. "Safety Buggestions From Employees" No action required GRIER, B H Region I. Philadelphia, Office of the Director B0/04/02 ip
- 8004180263 Forwards JE Circular 80-07, "Problems W/HPCI Turbine 0:1 Sys " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/03 1p
- 8004110066 Forwards IE Bulletsh 80-07, "BMR Jet Pump Assembly Failure "Written response required GRIER.B H Region i, Philadelphia, Office of the Director 80/04/04 1p
- 8004230512 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe " Action required GRIER.D H Region 1. Philadelphia, Office of the Director 80/04/04 1p
- 8004180252 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ORIER, D H Region 1, Philadelphia, Office of the Director 80/06/07 1p
- 6004240391 Forwards second response to IE Bulletin 79-018 re environ qualification of Class IE equipment ALDEN.W M Philadelphia Electric Co 80/04/16 1p
- --8004240392 Provides second response to IE Bulletin 79-018 re environ qualification of Class IE equipment Detailed repts w/sys master lists & equipment qualification forms and Repts revise & supersede 800303 submittal re licensee actions DALTROFF, S.L. Philadelphia Electric Co. 80/04/15 1300pp
- R Periodic operating reports & related correspondence
- 8004070270 Forwards "Thermal Hamitoring Rept 78 for Dec 1979 " WILLSEY.W B Philadelphia Electric Co 80/03/26 ip
- --8004070271 "Thermal Monitoring Rept 78 for Dec 1979 "
 * Philadelphia Electric Co 80/03/26 27pp
- BOO4170228 Forwards monthly operating repts for Mar 1980 CDDNEY.M J Philadelphia Electric Co 80/04/10 ip
- --8004170230 Monthly operating repts for Mar 1980 ALDEN:W M Philadelphia Electric Co 80/04/10 9pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004150560 LER 80-006/03L-0 on 800305, w/both units at full power, one of two offsite power sources tripped due to loss of transformer cooling fans Exact cause unknown Cooling fans restored, blown fuse replaced & transformer tested COONEY, M J Philadelphia Electric Co 80/04/03 ip
- 8004270439 RO 2-80-8/IP on 800417, development of environ spectrums associated w/high energy line areaks indicated guillotine failure of steam supply piping to HPCI turbine Caused by engineering deficiency ULLRICH,W T Philadelphia Electric Co 80/04/18 2pp
- 8004290443 RO 2-80-8-1P updates info re pressure profile within Unit 3 valve following guillotine failure of HPCI steam supply piping Analysis indicates higher pack pressure than riginally reported Caused by engineering error LRICH. W T. Philadelphia Electric Co 80/04/28 2gp.

- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- BO04010329 Forwards Items 3 i 5(2) & 3 i 7 of fire protection review Licensee submittal re fire barrier penetration seals only partly satisfactory Licensee proposal re fire doors acceptable HALL, R E Brookhavan National Laboratory 80/03/26 4pp
- 8004280252 Forwards comments on 800114 emergency plan, per review against criteria set forth in NUREG-0654 IPPOLITO, T A Operating Reactors Branch 3 80/04/01 14pp
- Q Adjudicatory correspondence
- 8004090192 Explains circumstances involving 800222 svc of BNWL draft rept to measurements of underground mining radon releases & NRC testimony of RN Wilde re same rept Missing Page 6 encl BORDENICK, B.M. Hearing Branch 4
- 6004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board natification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 1 Financial information
- 8004150246 Forwards Annual Financial Repts 1979 for Philadelphia Electric Co.Public Svc Electric & Gas Co.Atlantic City Electric Cn & Delmarva Power & light Co BRADLEV.E J Philadelphia Electric Co 80/04/08 IP
- --8004150250 Annual Financial Rept 1979
 * Philadelphia Electric Co 80/02/25 32pp
- --8004150255 Annual Financial Rept 1979
 * Atlantic Electric of New Jersey 80/04/08 32pp
- --8004150260 Annual Financial Rept 1979
 * Delmarva Power & Light Co 80/02/15 32pp
- 8004150470 Requests that date for filing certified financial statements & cash flow statements be delayed until 800515, due to pending rate proceedings involving Public Svc Electric & Gas Co & Philadelphia Electric Co BRADLEY, E J Philadelphia Electric Co 80/04/10 2pp
- P Operating license stage documents & correspondence
- 8004080194 Discusses NRC 761123 request that all LNR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing is required for operating reactors IPPOLITO T A Operating Reactors Branch 3 80/03/10 3pp
- B004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT, D O Division of Operating Reactors 80/03/12 Spp
- --8004030118 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28pp
- 8004230409 Forwards Amends 55 & 64 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability IPPOLITO, T A Operating Reactors Branch 3 80/03/26, 2pp
- --8009230414 Amends 65 & 64 to Licensus DPR-44 & DPR-56, respectively, revising Tech Specs re core monitoring, core flooding & sys operability requirements IPPOLITO, 7 A Operating Reactors Branch 3 80/03/26 28pp
- ---8004230419 Safety evaluation supporting Amends 65 & 64 to Licenses DPR-44 & DPR-56, respectively * Office of Nuclear Reactor Regulation 80/03/26 7pp
- --8004230441 Notice of issuance & availability of Amends 65 & 64 to Licenses DPR-44 & DPR-56, respectively IPPGLITO, T A Operating Reactors Branch 3 80/03/26 2pp

- 8004010406 Provides addl info re proposed installation of analog transmitters & trip units addressed in 790827 amend request Amend is nacessary to allow removal of 24 safety-related soutches in several facility sys

 DALTROFF, S L Philadelphia Electric Co 80/03/27 2pp
- 8004080538 Responds to NRC 800110 request for tabulation of instances of control rods failing to insert on scram & summary of other control rod drive malfunctions for 1978 & 1979 Facility experienced 15 scrams w/successful rod insertion GALLAOHER, J W Philadelphia Electric Co 80/03/31 2pp
- BOOA080543 Discusses implementation of ATWS mitigation Alternative 3A Prefers prevention of event rather than mitigation Util will install Alternative 3A in facilities if ACRB subcommittee believes ATWS is not extremely remote event BOYER, V & Philadelphia Electric Co 80/03/31 2pp
- 8004080349 Forwards revisions & additions to info originally submitted 791116 to Bulletins & Orders Task Force re process signals GALLAGHER, J W Philadelphia Electric Co 80/04/02 13pp
- 8004240299 Forwards Amends 66 & 45 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availabilty IPPOLITO, TA Operating Reactors Branch 3 80/04/03 2pp
- --8004240307 Amends 66 & 65 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs to pormit purging of primary containment through reactor bldg ventilation exhaust IPPOLITO, T A Operating Reactors Brench 3 80/04/03 10pp
- --8004240320 Safety evaluation supporting Amenda 66 & 65 to Licenses DPR-44 & DPR-56, respectively * Operating Reactors Branch 3 80/04/03 App
- --8004240329 Notice of issuance & availabilty of Amends 66 & 65 to Licenses DPR-44 & DPR-56, respectively IPPOLITO, T A Operating Reactors Branch 3 80/04/03 2pp
- BOO4250007 Forwards BOO128 & O211 litrs to GE re proposed control red drive sys mods related to elimination of cracking in return line nozzles Ouidelines for mods will be discussed in NUREG-0619, to be issued in "For Comment" form in Apr 1980 IPPOLITO.T A Operating Reactors Branch 3 80/04/07 2pp
- 8004240402 Responds to NRC 800414 ltr re GA of diesel generator fuel oil, GA program mod underway to conform w/Reg Guide i 137 Revision I, "Fuel Oil Bys for Standby Diesel Generators" Requires muds of storage tanks & procurement of equipment, DALTROFF, BL. Philadelphia Electric Co 80/04/14 App
- BOO4170246 Forwards application for amend of Licenses DPR-44 & DPR-56 Fee encl
 BRADLETYE J Philadelphia Clastric Co 80/04/15 ip
- --BOO4170252 Application for amend of Licenses DPR-44 & DPR-56 changing Tech Space re station fire hose hydrostatic test pressure & flexibility in min shift crew composition Certificate of Svc encl.
 BAUER, E Ø, BRADLEY, E J Philadalphia Electric CO 80/04/15 7pp
- --B004170296 Revised pages to Tech Specs re station fire hose hydrostatic test pressure & fleribility in min shift crew composition * Philadelphia Electric Co B0/04/15 10pp
- E3004290423 Notifies NRC that util has been informed by GE that Unit 1 Reload 4 & Unit 3 Reload 3 safety analyses were performed using 50 millisecond scram circuit delay time Tech Spec specifies delay not to exceed 100 milliseconds COUNEY.M J Philadelphia Electric Co. 80/04/23 3pp
- EMOA220549 Responds to NRC 800228 request for info re mpt & technical resources COUNEY.M J. Philadelphia Electric Co 80/04/11 9pp
- G Inspection reports, IE Bulletins & correspondence
- EICO4100211 Responds to IE Bulletin 79-27 re loss of Non-Class IE instrumentation. Submits actions requested & responses Design mods pending completion of review. DALTROFF, B L. Philadelphia Electric Co. 60/02/29 Spp.

- 8004140064 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Haster list of engineered safety feature sys & environ qualification evidence attached HELB analysis due by 800410 M/o encl DALTROFF, S.L. Philadolphia Electric Co. 80/03/03. 3pp
- B004210079 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH, O H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- --B004210082 Wasto Packaging Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, rediation levels, removable contamination & packaging external feature requirements POTYER, J.P., PERRY, N.W., WDODRUFF, R.L. Region 1, Philadelphia, Fuel Facility & Naterials Safety Branch B0/01/18 7pp
- 8004090416 Advises that IE Bulletin 60~05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVC8) Holdup Tanks." was incorrectly sent for action No response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/17 ip
- 8004100261 Responds to IE Bulletin 80-03 No cells replaced in engineered safety feature filtration sys,however charcoal adsorber cells,will have to be removed to replaced rivits indicated in Item 1 DALTROFF.S L Philadeiphia Electric Co 60/03/18 3pp
- 8004140183 Ack receipt of 800228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-29 & 50-278/79-38
 BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch
- --8004160187 Responds to NRC 800208 ltr re violations noted in IE Insp Repts 50-277/79-29 % 50-278/79-32 Corrective actions review of provision allowing entry w/o filling out radiation work permit will be made w/revisions to procedures DALTROFF, 8 L Philadelphia Electric Co 80/02/28 3pp
- --B004160189 Fowards IE Insp Repts 50-277/79-29 & 50-278/79-32 on 791101-30 & notice of violation BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch 80/02/08 2pp
- --8004160171 Notice of violation from insp on 791101-30
 * Region 1. Philadelphia. Office of the Director 80/02/06 1p
- --8004160194 IE Insp Repts 50-277/79-29 & 50-278/79-32 on 791101-30 Noncompilance noted failure to adhere to radiation work permit & maintain fire & penetration seal barrier MCCABE.E C Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch GREENMAN.E G Region 1. Philadelphia, Office of the Director 80/02/06 13pp
- 8004130271 Forwards IE Info Notice 80-12, "Instrument Failura Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 1p
- 8004250065 Updates 800R29 response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Lists mods being designed to provide redundant instruments in control room GALLAGHER, J. H. Philadelphia Electric Co. 80/03/31 11pp
- 8004090095 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadolphia, Office of the Director 80/04/01 ip.
- 8004110801 Forwards IE Info Natice 80-13, "GE Type 88H Control Switches Defective CAM Followers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 lp
- 8004240339 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees " No action required ORIER, B H Region 1. Philadelphia, Office of the Director 80/04/02 1p
- 8004180263 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required GRIER, B H Region 1, Philadolphia, Office of the Director 80/04/03 tp

- B004110066 Forwards IE Bulletin B0-07, "BWR Jet Pump Assembly Failure " Written response required GRIER.D H Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004230512 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required CRIER.B H. Region 1. Philadelphia, Office of the Director 80/04/04 p
- 8004180252 Forwards IE Bulletin BO-OB. "Exam of Containment Liner Penetration Welds" Hritten response required CRIER.B H. Region 1. Philadelphia. Office of the Director 80/04/07 1p
- 800424039: Forwards second response to IE Bulletin 79-018 re environ qualification of Class IE equipment ALDEN.W M Philadelphia Electric Co 80/04/16 lp
- --8004240392 Provides second response to IE Bulletin 79-018 re environ qualification of Class IE equipment Detailed repts b/sys master lists & equipment qualification forms encl Repts revise & supersed 800303 submittal re licensee actions DALTROFF,S L. Philadelphia Electric Co. B0/04/15 1300pp
- R Periodic operating reports & related correspondence
- 8004070270 Forwards "Thermal Monitoring Rept 78 for Dec 1979 " WILLSEY.W B Philadelphia Electric Co 80/03/26 1p
- --8004070271 "Thermal Monitoring Rept 78 for Dec 1979 "
 * Philadelphia Electric Co 80/03/26 27pp
- BOO4170228 Forwards monthly operating repts for Mar 1980 COONEY,M J Philadelphia Electric Co 80/04/10 ip
- --8004170230 Monthly operating repts for Mar 1980 ALDEN:W M Philadelphia Electric Co 80/04/10 9pp
- S Reportable occurrences, LERs & related correspondence
- 8004220432 RO 3-80-7/iP on 800221, during routine insp of plant equipment seismic air supply to five containment ventilation valves valved out of svc Causad by procedural & operation error Investigation continuing Procedural mods considered ULLRICH.W T Philadelphia Electric Co 80/02/22 2pp
- B004070311 LER 80-003/03L-0 on 800303, while performing surveillance tests, MO-3-10-25A LPCI on A, loop failed to open & RHR pump would not start Caused by galled Halworth 24-inch gate, pressure seal bonnet Valve repaired & leak tested COONEY, M J Philadelphia Electric Co 80/04/02 ip
- GOO4150560 LER 80-004/03L-0 on GOO305, w/both units at full power, one of two offsite power sources tripped due to loss of transformer cooling fans Exact cause unknown Cooling fans restored, blown fuse replaced & transformer tested CODNEY, M J Philadelphia Electric Co 80/04/03 ip
- 8004290439 RO 2-80-8/IP on 800417, development of environ spectrums associated w/high energy line breaks indicated guillatine faiture of steam supply piping to HPCI turbine Caused by engineering deficiency
 ULLRICH.N T Philadelphia Electric Co 80/04/18 2pp
- 8004290443 RO 2-80-8-1P updates info re pressure profile within Unit 3 valve following guillotine failure of HPCI steam supply piping Analysis indicates higher peak pressure than originally reported Caused by engineering error ULLRICH, W Y Philadelphia Electric Co 80/04/28 2pp
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- D, NRC Draft/Final Environmental Statements, suppls & correspondence
- BOO4150427 Comments on DEB re steam generator repair Proposed recommended action has no effect on transportation sys, except in event transport of hazardous matl is required. COOPER.S Transportation.Dept of BO/04/08 Ip
- F Security, medical, emergency & fire protection plans
- 8004150041 Requests add1 info identified in enclosure, for review of revised contingency plan Requests response within 60 days Encl withheld (ref 10CFR2 790)

 BCHWENCER, A Operating Reactors Branch 1 80/02/29 2pp

- 8004:40258 Responds to NRC request at 800326 & 27 meeting for emergency plans revised in accordance w/NUREQ-0454 North Anna emergency plan will be submitted on 800501 Surry plan will be submitted on 800402 Burry plan will BAUM, E.A. Virginia Electric & Power Co. 80/04/08 1p
- BOO4300072 Forwards summary of roview by element number for upgraded emergency plan per requirements of NURED-0554 Plan should be reviewed per new elements & revisions provided by BOO616 BCHMENCER.A Operating Reactors Dranch (80/04/11 10pp
- BOO4220311 Forwards fire protection project status summary for OL Amends 53 & 54 mods SYLVIA.B R Virginia Electric & Power Co BO/04/18 2pp
- H General correspondence
- 8004020400 Forwards resumes of persons holding revised employment positions resulting from 800401 mgt reorganization, to assist in review of proposed Tech Bpec changes Also forwards job descriptions of positions Info withheld (ref Privacy Act) STALLINOS, C.M. Virginia Electric & Power Co. 80/03/31 1p
- 1 Financial information
- 8004010269 Forwards Annual Rept 1979 BAUM.E A Virginia Electric & Power Co 80/03/27 lp
- --8004010275 Annual Rept 1979
 * Virginia Electric & Power Co 79/12/31 32pp
- J Insurance & indomnity information
- 8004300436 Confirms 800425 telcon granting extension until 800915 to file info per guarantee requirements set forth in Alternative 5 of NRC 770615 Itr re implementation of certain provisions of 1975 amends to Price Anderson Act JOHNSON. B D Virginia Electric & Power Co 80/04/25 ip
- P Operating license stage documents & correspondence
- 8004150249 Notification of ACRS Subcommittee on Surry Nuclear Station 800123 meeting in Washington DC to continue review of steam generator replacement program HOVLE, J C ACRS Advisory Committee on Reactor Safeguards 79
- 8004440481 Responds to util 790914 answel to NRC request for info on reactor coolant pump supports info does not resolve concern re integrity components made of high strength maraging steel Requests insp of all maraging components SCHMENCER. A Operating Reactors Branch 1 80/02/28 2pp
- BOD4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUY, D O Division of Operating Reactors BO/03/12 Spp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004080320 Forwards corrected Amend 55 to License DPR-32, safety evaluation & notice of issuance & availability, Date of issuance not affixed to original SCHWENGER. A Operating Reactors Branch 1 80/03/17 2pp
- --8004080325 Corrected Amend 95 to License DPR-32 requiring next steam generator tube insps be conducted within 6 months of equivalent operation from 791025
 6CHMENCER.A Operating Reactors Branch 1 80/02/05 2pp
- --8004080327 Safety evaluation supporting Amend 55 to License DPR-32 # Office of Nuclear Reactor Regulation 80/02/05 5pp
- --8004080330 Notice of issuance & availability of Amend 55 to License DPR-32 SCHMENCER,A Operating Reactors Branch 1 80/02/05. 2pp
- BOO4230178 Forwards Amends 58 & 57 to Licenses DPR-32 & DPR-37, respectively safety evaluation & notice of issuance & availability SCHWENCER, A Departing Reactors Branch 1 80/03/21, 2pp

- --8004250193 Amends 58 & 57 to Licenses DPR-32 & DPR-37, respectively changing Tech Specs re condition which required use of temporary containment & ventilation sys for all cutting & grinding operations

 ECHWENCER, A Operating Reactors Branch 1 80/03/21 4pp
- --8004250204 Safety evaluation supporting Amends 58 & 57 to Licenses DPR-32 & DPR-37, respectively * Office of Nuclear Reactor Regulation 80/03/21 2pp
- --B004250212 Notice of issuance & availabilty of Amends 5B & 57 to Licenses DPR-32 & DPR-37 respectively BCHWENCER.A Operating Reactors Branch 1 60/03/21 2pp
- B0040103B4 Forwards corrections to B00115 "Revised Rept on Reanalysis of Bafety-Related Piping Sys " No impact on previous ltrs indicating that analysis & installation of show cause mode is complete

 SPENCER, W C Virginia Electric & Power Co 80/03/28 ip
- --8004010387 Corrections to "Revised Ropt on Reanalysis of Safety-Related Piping Sys" * Virginia Electric & Power Co 80/01/31 Spp
- 8004030126 Forwards corrected pages to revised. "Reanalysis of Bafety-Related Piping Bys" SPENCER.W C Virginia Electric & Power Co 80/03/28 ip
- 8004010231 Application for amend to DPR-32 & DPR-37 Encl proposed Tech Spec Change 84 reflects changes to Section 6 O. administrative controls re organization of nuclear operations & maint dept & nuclear technical svcs dept STALLINGS.C M Virginia Electric & Power Co 80/03/31 3pp
- --8004010236 Proposed Tech Spec Change 84 reflecting changes to Section 6 O-administrative controls re organization of nuclear operations & maint dept & nuclear technical sucs dept * Virginia Electric & Power Co 80/03/31 iSpp
- B004030234 Forwards addi info re implementation of TMT-2 Lessons Learned Task Force short-term Category A requirements, based on NRC onsite review SYLVIA, B R Virginia Electric & Power Co 80/04/01 78pp
- 8004210010 Forwards request for addl info re bupass & reset of engineered safety features for review of containment purging & venting Commitment re performance of containment venting operations meets 791022 position SCHWENCER: A Operating Reactors Branch i 80/04/02 4pp
- BOO4140246 Informs NRC that ERL-Marragansett declines to review Mar 1980 DES Task is outside area of expertise PRAGER, J C Environmental Protection Agency 80/04/08 ip
- B00422031B Discusses options for disposal of reactor coolant pipe from Unit 1 steam generator replacement Preferred option is onsite storage SYLVIA:B R Virginia Electric & Power Co 80/04/18 2pp
- 8004300472 Forwards info re implementation of TMI short-term Category A Lessons Learned Requirements Remaining info will be forwarded at later date, SYLVIA:BR Virginia Electric & Power Co 80/04/28 4pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004170079 Forwards response to IE Bulletin 79-17. Item 1.re cracking in stagnant borated water sys Review identified sys which potentially contain stagnant oxygenated borated water BTALLINGS.C M Virginia Electric & Power Co 79/08/30 22pp
- B004040232 Ack receipt of B00125 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-65 & 50-281/79-65 LEWIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/05 ip
- --8004040242 Responds to NRC 791231 itr re violations noted in IE Insp Repts 50-280/79-65 & 50-281/79-85 Corrective actions periodic test steps are now signed in ink & reviewed by supervisor Correct review procedures were stressed BTALLINGS.C M Virginia Electric & Power Co 80/01/25 Spp

- --8004040250 Forwards IE Insp Repts 50-280/79-65 % 50-281/79-85 on 791126-30 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/12/31 2pp
- --8004040259 Notice of violation from insp on 791126-30
 * Region 2. Atlanta. Office of the Director 79/12/27 ip
- --B004040289 IE Insp Repts 50-280/79-65 & 50-281/79-85 on 791126-30
 Noncompliance noted failure to follow surveillance test
 procedure & review & retain instrument calibr procedures
 UPRIGHT,C M Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch MODN,B T Region 2, Atlanta, Office of the Director
 79/12/27 7pp
- 8004090358 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/06 200
- 8004090366 Forwards IE Insp Repts 50-280/80-02 & 50-281/80-04 on 800129-0201 No noncompliance noted BRYANT,J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/21 2pp
- --8004070374 IE Insp Repts 50-280/80-02 & 50-281/80-04 on 800129-0201 No noncompliance noted Major areas inspected previous insp findings.const testing.review of quality records.primary & secondary hydrostatic test & const status
 HUNTIM D Region 2. Atlanta. Reactor Construction & Engineering Support Branch. WILCOX.J D Region 2. Atlanta. Defice of the Director BD/02/20 4pp
- 8004010401 Responds to IE Bulletin 79-17. Revision i. "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No adverse plant conditions re intergranular stress corrosion cracking were detected No mods to plant or operating procedures planned STALLINOS.C M Virginia Electric & Power Co 80/02/27 2pp
- 8004240408 Forwards IE Insp Repts 50-280/80-03 & 50-281/80-05 on 800213-15 No noncompliance noted LEWIB:R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --B004240413 IE Insp Repts 50-280/80-03 & 50-281/80-05 on B00213-15 No moncompliance noted Major area inspected surveillance testing program
 UPRIOHT, C M Region 2, Atlanta, Reactor Operations Nuclear Support Dranch MESBITT-B R Region 2, Atlanta, Office of the Director B0/02/28 App
- 8004080270 Submits interim response to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Operator can be alerted to loss of power by combination of alarms or indications from equipment STALLINGS.C M Virginia Electric & Power Co 60/03/07 4pp
- B004020027 Requests extention until end of May to respond to IE
 Bulletin 79-14 Two long-term items re sv. water sys outside
 containment will require addl analysis
 FEROUSON, J H Virginia Electric & Power Co 80/03/18 2pp
- 8004080356 Submits response to IE Bulletin 79-01B re environ qualification of Class IE equipment Requested Master list will be ready by 800415 Equipment test repts in progress Review of Facility svc conditions ready by 800
- 8004150164 Forwards response to IE Bulletin 80-03 re charcoal adsorbor cells North Anna charcoal adsorber cells in use do not have potential for loss of charcoal No evidence of degraded cells has been noted during rockarging at Surry STALLINGS, CM Virginia Electric & Power Co 80/03/21 7pp
- 8004240509 Responds to IE Bulletin 79~17. Revision 1. "Pipe Cracks in Stagnant Borated Water Bys at PWR Plants " No adverse plant conditions re intergranular stress corrosion cracking were detected during required evaluations
 STALLINGS.C M Virginia Electric & Power Co 80/03/27 2pp
- 8004150540 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta, Office of the Director B0/03/31
- 8004080652 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01 2pp

- B004150105 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/04/02
- 8004240284 Forwards IE info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY-J P Region 2, Atlanta, Office of the Director 80/04/02 2co
- 6004180299 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004230108 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainloss Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004250036 Responds to 800226 ltr re status of insp on low pressure turbines NRC issued draft EIS re proposed repair Final EIS will be issued soon after required comment period ends on 800505 DENTON, H R Dffice of Nuclear Reactor Regulation 80/04/04 2pp
- ---8004250041 Advises that turbine insp oraginally scheduled for May, is now underway due to vibrations experienced prior to shutdown Completion expected by 800310 Requests that preparation of EIS not interfere u/generator replacement FERGUSON.J H Virginia Electric & Power Co 80/02/26 ip
- 8004i10478 Responds to NRC 800314 ltr re violations noted in IE Insp Repts 50-280/80-0: & 50-281/80-03 Corrective actions personnel instructed to utilize only manufacturer recommended replacement parts & proper gaskets SYLVIA,8 R Virginia Electric & Power Co 80/04/07 ip
- 8004180401 Forwards IE Bulletin 80-08, "Exam of Containment Liner Panetration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 2pp
- 8004180289 Forwards results of steam generator insp & preventive plugging program Approx 25 12 tubes plugged Existing analysis by Amend 55 to License DFR-52 applicable Approval will be requested to allow addl six months power operation SYLVIA.B R Virginia Electric & Power Co E0/04/15 15pp
- 8004290334 Responds to IE Bulletin 79-13, Revision 2, "Cracking in Feedwater Piping Sys " No nonconformances identified in visual exam of feedwater pipe supports Welds will be inspected during refueling outage Supersedes 800408 ltr SYLVIA.B R Virginia Electric & Power Co 80/04/24 2pp
- R Periodic operating reports & related correspondence
- 8004170241 Forwards monthly operating rapts for Mar 1980 SYLVIA.R B Virginia Electric & Power Co 80/04/14 ip
- --8004170244 Honthly operating repts for Mar 1980 COSTELLO.G J Virginia Electric & Power Co 80/04/02 42pp
- S Reportable occurrences, LERs & related correspondence
- 8004030266 Forwards LER 80-019/03L-0 STALLINGS.C.H Virginia Electric & Power Co 80/03/28 ip
 - O4030270 LER 80-019/03L-0 on 800304, during evaluation of vols of ontaminated drain tanks for increasing tankage vailability, error was discovered in vols being used Caused y level indication during plant const
 TEWART. W L Virginia Electric & Power Co 80/03/26 2pp
 -)80474 Forwards LERs 80-014/01T-0 & 80-002/01T-0 80N.J W Virginia Electric & Power Co 80/04/02 1p
 - 14080482 LER 40-002/017-0 on 800320, insp of containment following upe A leak rate revealed eight 1/4 inch holders drilled frough containment liner Caused by improper interpretation f procedure during Design Change 78-48 Repair planned ILSCN, J L Virginia Electric & Power Co 80/04/02 2pp

- ~-8004080486 LER 80-014/017-0 on 800320, informed by Westinghouse that incident of stress corrosion cracking in control rod sypport pins & flexures noted in foreign plant Vendor testing & assessment program in progress Appropriate action planned WILBON, J L Virginia Electric & Power Co 80/04/02 2pp
- 8004250371 RO while conducting PY 25 12. jump 1-FP-P2 in fire protection sys failed to meet acceptance criteria of 250 ft at 2500 gallons per minute Cause not determined Vendor will partitipate in insp Local fire depts will supply assistance SYLVIA.B R Virginia Electric & Power Co 80/04/22 1p
- 8004280612 Forwards LERs 80-021/03L-0 & 80-022/03L-0 WIL50N,J L Virginia Electric & Power Co 80/04/24 is
- --8004280616 i.ER 80-021/03L-0 on 800327, during performance of 1-PT-398-1, enubber 1-WAPD-HSS-148 discovered w/low fluid level in reservoir Caused by fluid leaking out through reservoir to block tube fitting Bnubber declared Inoperable WILSON, J L Virginia Electric & Power Co 80/04/24 2pp
- --8004280626 LER 80-022/03L-O on 800327, during performance of 1-PT-39B-1, stubbers 1-RC-H5B-116 & 1-RC-H5S-117 discovered installed 90 degrees out of position Caused by corrective work performed per 1E Bulletin 79-14 WILSON, J L Virginla Electric & Power Co 80/04/24 2pp
- DOCKET 50-281 SURRY POWER STATION, UNIT 2
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- BOD4150429 Comments on DES re steam generator repair Proposed recommended action has no effect on transportation system except in event transport of hazardous mati is required CDOPER:S Transportation Dept of 80/04/08 ip
- F Security, medical, emergency & fire protection plans
- 8004150041 Requests add1 info identified in enclosure, for review of revised contingency plan Requests response within 60 days Encl withheld (ref 10CFR2 790)

 8CHMENCER.A Operating Reactors Branch 1 80/02/24 2pp
- B004140258 Responds to NRC request at 800326 & 27 maeting for emergency plans revised in accordance w/NUREG-0454 North Anna emergency plan will be submitted on 800501 Surry plan will be submitted on 800402

 BAUM, E.A. Virginia Electric & Power Co. 80/04/08 ip
- B004300072 Forwards summary of review by element number for upgraded amergency plan per requirements of NUREC-054. Plan should be reviewed per new elements & revisions provided by 800616 SCHMENCER, A depending Reactors Branch 1 80/04/11. 10pp
- 8004220311 Forwards fire protection project status summary for QL Amends 53 & 54 mods SYLVIA.B R Virginia Electric & Power Co 80/04/18 2pp
- O Adjudicatory correspondence
- 8004070056 Forwards order lifting suspension of facility operation required by 790313 order to show cause DENTON, If R Office of Nuclear Reactor Regulation 80/03/26 Zpp.
- ---8004070063 Order lifting suspension of facility operation required by 790313 order to show cause, effective immediately Ail mods to correct piping sys overstress shall be completed prior to startup CABE.E O Office of Nuclear Reactor Regulation 80/03/26 Spp.
- --B004070066 Bafety evaluation stating that conditions of 790313 order to show cause have been met # Office of Nuclear Reactor Regulation B0/03/21 7pp.
- H General correspondence
- 8004020400 Forwards resumes of persons holding revised employment positions resulting from 800401 mgt reorganization, to assist in review of proposed Tech Spec changes Also forwards job descriptions of positions info withheld (ref Privacy Act) STALLINOS, CM Virginia Riectric & Power Co. 80/03/31 ip
- 1. Financial information
- 8004010267 Forwards Annual Rept 1979
 8AUM.E A Virginia Electric & Power Co 80/03/27 lp

- --8004010275 Annual Rept 1979
 * Virginia Electric & Power Co 79/12/31 32pp
- J. Insurance & indemnity information
- 8004300436 Confirms 800425 telcon granting extension until 800515 to file info per guarantee requirements set forth in Alternative 5 of NRC 770615 ltr re implementation of certain provisions of 1975 amends to Price Anderson Act JOHNSON, B D Virginia Electric & Power Co 80/04/25 1p
- P Operating license stage documents & correspondence
- B004150249 Notification of ACRS Bubcommittee on Surry Nuclear Station 800123 meeting in Washington.DC to continue review of steam generator replacement program MOYLE,J C ACRS Advisory Committee on Reactor Safeguards 79/12/20 3pp
- B004140481 Responds to util 790914 answer to NRC request for info on reactor coolent pump supports Info does not resolve concern re integrity components made of high strength maraging steel Requests insp of all maraging components

 SCHWENCER, A Operating Reactors Branch 1 80/02/28 2pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D Q Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- B004250178 Forwards Amends 58 & 57 to Licenses DPR-32 & DPR-37, respectively safety evaluation & notice of issuance & availability SCHMENCER. A Operating Reactors Branch 1 80/03/21 2pp
- ---8004250193 Amends 58 & 57 to Licenses DPR-32 & DPR-37, respectively changing Tech Bpecs re condition which required use of temporary containment & ventilation sys for all cutting & grinding operations,
 BCHWENCER, A Operating Reactors Branch 1 80/03/21 4pp
- --8004250204 Bafety evaluation supporting Amends 50 & 97 to Licenses DPR-32 & DPR-37, respectively * Office of Nuclear Reactor Regulation 80/03/21 2pp
- --8004250212 Notice of issuance & availability of Amends 58 & 57 to Licenses DPR-32 & DPR-37 respectively BCHWENCER.A Operating Reactors Branch 1 80/03/21 2pp.
- 8004010231 Application for amend to DPR-32 & DPR-37 Encl proposed Tech Spec Change 84 reflects changes to Section 6 0, administrative controls re organization of nuclear operations & maint dept & nuclear technical svcs dept BTALLINGB, C. M. Virginia Electric & Power Co. 80/03/31 Gpp
- ~-8004010236 Proposed Tach Spec Change 84 reflecting changes to Section 6 O, administrative controls re organization of nuclear operations & maint dept & nuclear technical svcs dept * Virginia Electric & Power Co 80/03/31 15pp
- 8004030234 Forwards add1 info re implementation of TMI-2 Lessons Learned Task Force short-term Category A requirements, based on NRC onsite review, SYLVIA:B.R Virginia Electric & Power Co 80/04/01. 78pp,
- 8004210010 Forwards request for additinfoirs bypass & reset of engineered safety features for review of containment purging & venting. Commitment re performance of containment venting operations meets 791022 position.

 BCHWENCER, A. Operating Reactors Branch 1 80/04/02 4pp.
- BOO4140219 Forwards "Rept on Reanalysis of Bafety-Related Piping Sys." Revision i re 800222 request for startup of facility. Incorporates 800321 commitment to complete installation of mods re-order to show cause prior to startup, SPENCER.W C Virginia Electric & Power Co. 80/04/11, ip.
- ---8004140224 "Rept on Reanalysis of Safety-Related Piping Sys." Revision

 1
 * Ebasco Bervices, Inc. (subs. of Enserch Corp.) 80/04/11.

- BOO4220318 Discusses options for disposal of reactor coplant pipe from Unit i steam generator replacement Preferred option is onsite storage
 BYLVIA.B R Virginia Electric & Power Co 80/04/18 2pp
- BOO4300472 Forwards info re implementation of TMI short-term Category A Lessons Learned Requirements Remaining (nfo will be forwarded at later date SYLVIA:B R Virginia Electric & Power Co BO/04/28 4pp
- G Inspection reports. IE Bulletins & correspondence
- 8004170079 Forwards response to IE Bulletin 79-17, Item i, re cracking in stagnant borated water sys Review identified sys which potentially contain stagnant oxygenated borated water STALLINOS.C M Virginia Electric & Power Co 79/08/30 22pp
- 7909280009 Responds to IE Bulletin 79-13, "Cracking in Feedwater Piping Sys " Unit 2 weld insps are approx 25% complete STEMART,W L Virginia Electric & Power Co 79/09/05 ip
- 8004040232 Ack receipt of 800125 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~280/79-65 & 50~281/79-85 LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/05 ip
- --8004040242 Responde to NRC 791231 ltr re violations noted in IE Insp Repts 50-280/79-65 & 50-281/79-85 Corrective actions pariodic test steps are now signed in ink & reviewed by supervisor Correct review procedures were stressed BTALLINOS.C M. Virginia Electric & Power Co. 80/01/25 3pp
- --8004040250 Forwards IE Insp Rapts 50-280/79-65 & 50-281/79-85 on 791126-30 & notice of violation LENIS.R C. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/12/31 2pp
- --8004040257 Notice of violation from insp on 791124-30
 * Region 2, Atlanta, Office of the Director 79/12/27 in
- --80040402B9 IE insp Rapts 50-280/79-65 & 50-281/79-85 on 791126-30
 Noncompliance noted failure to follow surveillance test
 procedure & review & retain instrument calibr procedures
 UPRIGHT.C M Region 2. Atlanta. Reactor Operations Nuclear Support
 Branch MIDM.B T Region 2. Atlanta. Office of the Director
 79/12/27 7ap
- 8004090358 Forwards IE Bulletin 80-03. "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/02/06
- 8004090366 Forwards IE Insp Repts 30-280/80-02 & 50-281/80-04 on 800129-0201 No noncompliance noted BRYANT, J_C Region 2. Atlanta, Reactor Construction & Engineering

- 8004080356 Submits response to IE Bulletin 79-018 re environ qualification of Class IE equipment Requested Master list will be ready by 800415 Equipment test repts in progress Review of facility syc conditions ready by 800905 STALLINGS, C.M. Virginia Electric & Power Co. 80/03/18 3pp
- 8004150164 Forwards response to IE Builetin 80-03 re charcoal adsorber cells North Anna charcoal adsorber cells in use do not have potential for loss of charcoal No evidence of degraded cells has been noted during recharging at Burry STALLINGS, C. M. Virginia Electric & Power Co. 80/03/21 7pp
- 8004240509 Responds to IE Bulletin 79-17, Revision 1, "Pipe Cracks in Stagnant Borated Hater Sys at PMR Plants." No adverse glant conditions re intergranular stress corrosion cracking were detected during required evaluations STALLINGS, C.M. Virginia Electric & Power Co. 80/03/27 2pp
- 8004150540 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080652 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01 200
- 8004150105 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240284 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required C'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004110339 Notification of 800415-17 meeting w/util in Surry, VA to discuss inservice lnsp & pump & valve testing NEIOHBORS, D Operating Reactors Branch 1 80/04/03 2pp
- B004180299 Forwards IE Circular 80-07, "Problems W/HPCI Turbine dil Sys " No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director B0/04/03 2pp
- 8004230108 Forwards IE Builetin 79-03A "Longitudinal Weld Defects in ASHE SA-312, Type 304 Stainless Stast Pips " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04.
- 8004110478 Responds to NRC 800314 ltr re violations noted in IE Insp Repts 50-280/80-01 & 50-281/80-03 Corrective actions personnel instructed to utilize only manufacturer recommended replacement parts & proper gaskets SYLVIA.B R Virginia Electric & Power Co 80/04/07 1p.
- 8004180401 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J. P Region 2, Atlanta, Office of the Director 80/04/07, 2pp
- 8004290334 Responds to IE Bulletin 79-13. Revision 2. "Cracking in Feedwater Piping Sys " No nonconformances identified in visual exam of feedwater pipe supports Helds will be inspected during refueling outage Supersedes 800408 ltr SYLVIA.B R Virginia Electric & Power Co 80/04/24 2pp
 - Periodic operating reports & related correspondence
 - 04170241 Forwards monthly operating repts for Mar 1980 BYLVIA:R. B Virginia Electric & Power Co 80/04/14 Ip
- --8004170244 Monthly operating repts for Mar 1980. CDSTELLO.O J Virginia Electric & Power Ca 80/04/02 42pp
 - 108
 - ... ginte Electric & Power Co 80/04/02 1p.

- --8004080492 LER 80-002/01T-O on 800320, insp of containment following Type A leak rate revealed eight i/4 inch holders drilled through containment liner Caused by improper interpretation of procedure during Design Change 78-48 Repair planned WILSON, J L Virginia Electric & Power Co 80/04/02 2pp
- 8004250371 RD while conducting PT 25 12.pump 1-FP-P2 in fire protection sys failed to meet acceptance criteria of 250 ft at 2500 gallons per minute Cause not determined Vendor will participate in insp. Local fire depts will supply assistance SYLVIA.B R Virginia Electric & Power Co 80/04/22 1p
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- BOO4080225 Bubmits revised achedule for implementing fire protection mods MAYER, L D Northern States Power Co 80/03/31 2pp
- 8004170056 Forwards "Evacuation Time Estimates," from areas near nuclear generating plant in response to NRC 791129 request MAYER, L Q Northern States Power Co 80/04/10 ip
- --8004170059 "Evacuation Time Estimates"

 * Northern States Power Co 80/04/30 18pp
- G Adjudicatory correspondence
- 8004230088 Request for hearing and petition to intervene re spent fuel pool mod License smend should not be issued until State of MN administrative proceedings are completed re licensee application for certificate of need & environ evaluation SENECHAL, M E . OLSON, J F Minnesota, State of 80/03/31 5pp
- 8004230100 Notice of appearance in proceeding SENECHALIM E , OLSON, J F Minnesota, State of 80/03/31 2pp
- H Caneral correspondence
- 8004280037 Discusses NRC intervenor funding in response to 800305 ltr.
 Commission decided not to initiate program to provide
 funding in 1976 Intervenor funding is being studied again &
 funds for pilot program have been requested for FY81
 CHRISTENBURY, E Mearings Division 80/04/08 ip
- --BOD42BOD43 Requests info on availability of govt financial aid for intervenors in facility spent fuel storage license amend proceeding FIELDSETH. H. Affiliation Unknown. BO/03/05 ip
- P. Operating license stage documents & correspondence
- 8004110320 Forwards FR notice of proposed issuance of amend to Licenses DPR-42 & DPR-60 re spent fuel storage capacity 8CHMENGER.A. Operating Reactors Branch 1, 80/02/28 2pp
- --8004110524 Notice of proposed issuance of amend to Licenses DPR-42 & DPR-40 re spent fuel storage capacity BCHMENCER.A Operating Reactors Branch 1 80/02/28 4pp
- B004020070 Forwards Amends 41 & 35 to Licenses DPR-42 & DPR-40, respectively & notice of issuance & availability , BCHMENCER,A, Operating Reactors Branch i 80/02/29 4pp
- --8004020073 Amend 41 to License DPR-42 revising App B Tech Specs by changing requirement re blowdown flow over 150 cfs to annual & fish impingement sampling frequency to once every two wks

 BCHMENCER, A Operating Reactors Branch 1 80/02/29 2pp
- --BOO4020075 Amend 35 to License DPR-60 changing App B Tech Specs by revising requested requirement re blowdown flow over 150 cfs to annual 8 fish impingement sampling frequency to once every two wks Tech Spec replacement pages encl.

 BCHWENCER, A Operating Reactors Branch 1 80/02/29 8pp
- --8004020079 Notice of issuance & availability of Amends 41 & 35 to License DPR-42 & DPR-60, respectively. BCHMENGER, A Operating Reactors Branch 1 80/02/29 2pp.
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr. EISENHUT, D Q. Division of Operating Reactors 80/03/12 5pp.

- --8004030(18 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/2(28pp
- 8004070378 Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics info during incident or abnormal occurrence at facility
 KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/17
- BOO41001B3 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days

 KEPPLER, J G Region 3. Chicago, Office of the Director BO/03/20 to
- 8004100486 Summary of 800221 telcon w/util re status of NURED-0578 implementation ltems requiring addl clarification subcooling meter & backup procedures used to determine subcooling & use of CRTs not having seismic qualifications OROTENHUIS.M Operating Reactors Branch 1 80/03/21 5pp
- 8004140099 Summary of 800321 meeting w/util in Bethesda, MD re fuel pool expansion proposed by util on 800131 Addl info re unresolved questions will be transmitted by util encl list of attendees

 OROTENHUIS.M Operating Reactors Branch 1 80/03/21 3pp
- 8004210023 Advises that 781122 application to amend Licenses DPR-42 & DPR-60 is pro forms & administrative in nature placing Unit 1 in Class II fee category Refund for Class II1 overpayment will be processed MILLER.W O License Fee Management Branch 80/04/03 1p
- B004150339 Forwards add1 info re implementation of short-term Lessons Learned Task Force recommendations MAYER, L O Northern States Power Co 80/04/11 17pp
- BOO4180464 Forwards proprietary & nonproprietary versions of "Structural Analysis of RCS for Postulated LUCA," preliminary issue Applications for withholding encl Proprietary version withhold (ref 10CFR2 770) ANDERSON
- --8004180475 Nonproprietary version of "Structural Analysis of RCS for Postulated LCCA," preliminary issue # Westinghouse Electric Corp . Nuclear Energy Systems 80/02/29 100pp
- 8004180341 Forwards Offsite Dose Calculation Manual, Revision 1 MAYER, L O Northern States Power Co 80/04/15 ip
- --5004180342 Offsite Dose Calculation Manual, Revision 1
 * Northern States Power Co 80/04/30 150pp
- 8004280947 Requests NRC review of proposed implementation of short-term Lessons Learned Task Force recommendations re Item 2 1 6 b; "Plant Shielding Review;" Item 2 1 7; "Reactor Vessel Head Vent;" & Item 2 2 26; "Onsite Technical Bupport Ctr " MAYER, L O Northern States Power Co 80/04/25 1p
- @ Inspection reports. IE Bulletine & correspondence
- B004100267 Forwards IE Insp Repts 30-282/80-01 & 50-306/80-01 on 800102-31 & notice of violation HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --8004100283 Natice of violation from inap on 800102-31 * Region 3, Chicago, Office of the Director 80/02/22 2pp
- --8004i00270 lE Insp Repts 50-282/80-01 & 50-304/80-01 on 800i02-3i Noncompliance noted containment spray additive tank isolated from containment spray sys & failure to follow operating procedure. FEIERABEND, C. D. BOYD, D. C. Region 3. Chicago, Office of the Director 80/02/22 7pp
- B00407005B Responds to IE Bulletin 79-17. Revision i, "Pipe Cracks in Stagnant Borated Water Bys at PWR Plants " Required visual insp completed on Unit i in Feb 1980 No corrective actions nacessary.

 OLBERTS.D E Northern States Power Co 80/03/07 ip
- 8004070210 Responds to 1E Bulletin 79-27 outlining conclusions from investigation of instrument buses Design change initiated to replace instrument inverters w/inverters capable of automatic transfer to alternate ac GILBERTS, D E Northern States Power Co 80/03/07 2pp

- 8004100143 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/07
- 8004040456 Responds to LE Bulletin 79-01B. "Environ Qualification of Class IE Equipment " Delay until 800314 approved by J Hughes in 800229 teiron Evaluates components & sys qualification for expected operational conditions OILBERTS, D E Northern States Power Co 80/03/13 4pp
- 8004100067 Ack receipt of 800229 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-282/79-32 & 50-306/79-26
 DAVIS.A B Region 3. Chicago, fuel Facility & Materials Safety Branch 80/03/20 ip
- --8004100070 Responds to NRC 800207 ltr re violations noted in IE Insp Repts 50-202/79-32 % 50-306/79-26 Discusses collection of Xe-133 gas samples wiow level gas headers GILDERTS, D E Northern States Power Co 80/02/29 2pp
- 8004160013 Responds to IE Bulletin 80-03 re loss of charcoal from std adsorber cells Visual insp of charcoal filters installed revealed no degradation or sagging Datailed visual insp of each filter performed annually OILDERTS, D E Northern States Power Co 80/03/24 2pp
- 8004150184 Forwards IE Info Notice 80-12, "Instrument Failure Causes Deening of PORV & Block Valve " No specific action or response necessary KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/31
- 8004080719 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/01
- GOO4150052 Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- B004180055 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800304 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220148 Forwards IE Info Notice 80-14. "Bafety Buggestians From Employees" No action required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/02 in
- 800422037B Forwards 1E Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/03
- 8004230297 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME BA-312, Type 304 Stainless Steel Pips " Action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/07
- 8004220047 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER.J O Region 3. Chicago, Office of the Director, BO/04/09 ip
- 80042304B0 Forwards Revision 4 to "ABME Code XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ABME Code Section XI Requirements"

 MAYER.L G Northern States Power Co B0/04/17 2pp
- R Periodic operating reports & related correspondence
- 8004140339 Forwards monthly operating rept for Mar 1980 MAYER, L. O. Northern States Power Co. 80/04/10 1p

- ~~8004140344 Monthly operating rept for Mar 1980 HUNSTAD, A A Northern States Power Co 80/04/01 8pp
- S Reportable occurrences, LERs & related correspondence
- 8004080478 Forwards updated LER 79-030/03X-3 MAYER.L O Northern States Power Co 80/04/03 1p
- --8004080484 Updated LER 79-030/03X-3 on 791121 during insp per IE Bulletins 79-14 & 79-02, two snubbers in cooling water sys found installed incorrectly & five hangers found damaged or in violation of safety requirements Insp ongoing HUNSTAD, A A Northern States Power Co 80/04/03 ip
- B0Q4140435 Forwards LER 80-009/03L-0 MAYER.L D Northern States Power Co 80/04/09 1p
- ~-8004140440 LER 80-009/03L-0 on 800310, during normal operation, nuclear power range channel 1N44 was inoperable for several minutes Caused by latch-up of high voltage power supply due to spike on yellow instrument bus Fuses were removed & roset HUNSTAD, A A Northern States Power Co 80/04/09 1p
- 8004150587 Forwards LER 80-010/03L-0 MAYER.C O . Northern States Power Co 80/04/10 1p
- --8004150403 LER 80-010/03L-0 on 80031; during surveillance test, containment isolation valve 11 opened at 0 57 psi Caused by apparent drift in Barton Model 188A differential pressure switch Setpoint adjusted & valve retested satisfactorily HUNBTAD, A A Northern States Power Co 80/04/10 lp
- 8004230358 Forwards updated LER 80-010/03L-1 MAYER.L D Northern States Power Co 80/04/17 1p
- --8004230359 Updated LER 80-010/03L-1 "cause code" & "component manufacturer" corrected HUNSTAD, A A Northern States Fower Co 80/04/17 1P
- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1
 P Operating license stage documents & correspondence
- B004030275 Discusses NRC B00307 site visit to review implementation of Category A Lessons Learned requirements Addl licensee action/discussion is necessary by 800314 Request for addl info enci REID.R W Operating Reactors Branch 4 80/03/10 1p
- GOD4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D Q Division of Operating Reactors 80/03/12 Spp

- 8004220561 Responds to NRC 800327 request by providing info regarding implementation of Lessons Learned Task Force item re automatic initiation of auxiliary feeduater sys Control grade sys complying w/requirements has been installed JONES.W C Omaha Public Power District 80/04/08 3pp
- 8004240536 Ack receipt of 800211 ltr by forwarding response to J Weber 800211 questions re power rating REID;R W Operating Reactors Branch 4 80/04/09 8pp
- BOO4280040 Forwards Amend 47 to License DPR-40, safety evaluation & notice of issuance & availability
 REID,R W Operating Roactors Branch 4 BO/04/11 2pp
- --8004280046 Bafety evaluation supporting Amend 47 to License DPR-40 * Operating Reactors Branch 4 80/04/11 28pp
- ---8004280047 Notice of Issuance & availability of Amend 47 to License DPR-40 REID.R W Operating Reactors Branch 4 80/04/11 2pp
- @ Inspection reports, IE Bulletins & correspondence
- 8004040252 Forwards IE Insp Rept 50-285/80-01 on 800114-17 No noncompliance noted MADBEN.O L Region 4. Dallas, Reactor Operations Nuclear Bupport Branch 80/02/05 2pp
- --8004040262 IE Insp Rept 50-285/80-01 on 800114-17 No noncompliance noted Major areas inspected plant operations & prerefueling activities

 KELLEV.O L . WESTERMAN.Y F Region 4. Dallas, Office of the Director 80/02/04 App
- 8004080591 Forwards IE Insp Rept 50-285/B0-02 on 800128-0201 No noncompliance noted MADBEN, Q L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/14 2p
- ~-BOO4080696 IE Insp Rept 50-285/80-02 on 800128-0201 No noncompliance noted Major areas inspected second periodic containment integrated leak rate test HEBIERMAN, T F, KELLEY, D L, HALL, R E Region 4, Dallas, Office of the Director 80/02/13 4pp
- 8004250086 Forwards response to IE Builetin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation " Dased on util review, adequate indication & annunciation available to identify bus failure JONES,H C Omaha Public Power District 80/02/21 App
- 8004140021 Forwards response to Items 1.2.3 % 5 of IE Bulistin 79-018 Chart of svc condition profiles & master list of Class IE components required to function under accident conditions encl
 JONES.W C Omaha Public Power District. 80/03/03. 200pp
- 6004070033 Forwards IE Insp Rept 50-285/80-05 on 600212-15.No noncompliance noted MADSEN.0 L Region 4. Dallas. Reactor Operations Nuclear Support Branch. 60/03/19 2pp
- --8004070036 IE Insp Rept 50-285/80-05 on 800212-15 No noncompliance noted Major areas inspected review of security plan, physical barriers, lighting & alarm stations, Datails withheld (10CFR2 790) GALDMELL, R A , EVANS, C A Region 4, Dallas, Office of the Director MADBEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/03/17 2pp.
- 8004110489 Forwards IE Insp Rept 50-285/80-04 on 800305-07. No noncompliance noted Details withheld (ref 100FR2 790), HIND, J A Region 3, Chicago, Safeguards Branch 80/03/27, 2pp
- --B004110498 IE Insp Rept 80-285/80-06 on B00305-07. No noncompliance mated Major areas inspected, facility organization & controls, inventory & verification; shipping & receiving; storage & controls Details withheld (ref 10CFR2, 790) HIND, J.A. Region 3, Chicago, Bafeguards Branch, PATTERSON, J.P., FINLEY, A.G. Region 3, Chicago, Diffice of the Director, B0/03/25 ip.

- BOO4190234 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV A Block Valve " No specific action or response necessary SEYFRIT,K V Region 4. Dallas, Office of the Director 80/03/31
- BOD4080670 Forwards IE Clicular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required
- Region 4. Dallas, Office of the Director 80/04/01
- 8004110102 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/02
- 8004180496 Forwards IE Info Notice 80-14, "Gafety Suggestions From Employees" No action required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/02
- 8004180158 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil 8ys " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/03
- 8004230354 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required BEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/04
- R Periodic operating reports & related correspondence
- HOC4150391 Forwards monthly operating rept for Mar 1980 JDNES,W C Dmaha Public Power District HO/04/02
- ---8004150375 Monthly operating rept for Mar 1980 HICKLE, B J | Omaha Public Power District | 80 80/04/02 17pp
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8004020110 Advises of FEB issuance re selection of preferred alternative closed-cycle cooling sys.NUREG-0574, Dec 1979 Future discussions re simplification of proceeding. appropriate LEWIS.8 H Hearing Branch 2 80/03/19 ip
- --B004020126 Bummary of mesting w/PASNY re DES. selection of preferred closed cycle cooling sys & related issues NRC will draft stipulation for parties' comments GECKLER, R P Environmental Projects Branch 1, 79/09/14 3pp
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8004180281 Addresses questions in 800214 memo on R Pollard allegations refacility SER lesue of containment isolation valves was previously addressed R Pollard Input & final SER are substantially same SER excerpt encl DENTON, H R. Office of Nuclear Reactor Regulation. 80/04/03 9pp
- --B004180286 Responds to 770110 ltr re possibility of tornado damage & re-evaluation of containment isolation features of auxiliary steam lines. Auxiliary steam supply & condensate return lines satisfy Criterion 57 of general design criteria BCHWENCER.A. Operating Reactors Branch 1 78/09/27 7pp
- --B0041B0294 Submits questions about R Pollard allegation at B00205 commission meeting re BER inaccuracies & plants not meeting current regulations on containment isolation & environ qualification, Transcript excerpt encl.

 BRADFORD, P. A. Commission 80/02/14 9pp
- B004220462 Discusses B00926 ltr re request to have UCS identify inaccuracies in plant BER in support of NRC review, Requests info re purpose of request & Pindings of review, Buggests procedure to identify BER discrepancies for Units 1 & 2 WEISS, E R Sheldon, Harmon & Weiss B0/04/17 2pp

- F Security, medical, emergency * fire protection plans
- 8004;00100 Comments on proposed rule 10CFR50 10-mile emergency planning ione for plume exposure lacks technical justification NRC adopted position w/o studying validity of underlying bases WEISB.E R Sheldon Harmon & Weiss 80/02/19 5pp
- --8004100127 Statement before NY City Council, "Impact on NY City of Reactor Accidents at Indian Point," (corrected 790620) BEYEA, J Princeton Univ 79/06/20 49pp
- 8004080695 FOIA request, on behalf of UCS, for time analysis required to evacuate public from 10-mile area surrounding facilities WEISS, E.R. Sheldon, Harmon & Weiss 80/03/20 1p
- BOD4080690 Responds to FOIA request for time analysis required to revacuate public from 10-mile area surrounding facilities
 Forwards rept. "Evacuation Times Estimates for Areas Near
 Site " W/o encl
 FELTON, J M Division of Rules and Records 80/03/31 1p
- 8004250382 Forwards input to fire protection review for Items 3 1 8(2), Seprinkler sys. Item 3 2 4, cable spreading nom & Item 3 2 1. separation of instrumentation in containment HALL.R C Brookhaven National Laboratory 80/04/17 3pp
- G Adjudicatory correspondence
- 8004020091 Forwards UCB 800310 comments on director's decision under 10CFR2 206 Decision & confirmatory order do not resolve critical issues Objects to exclusion of petitioner from meetings & correspondence solving issues
 WEISS.E R Sheldon, Harmon & Weiss 80/03/10 2pp
- -8004020099 Comments on director's decision under 10CFR2 204 Decision & confirmatory order do not resolve crucial issues re site suitability X do not establish necessity schedule or stds of mode Urges disqualification of JM Handrie W/documentation WEISS, E R Union of Concerned Scientists NEISS, E R Sheldon, Harmon & Weiss 80/03/10 43pp 43рр
- --8004020109 Responds to /30717 ltr re siting criteria Facility site does not meet NRC regulations & criteria HENDRIE, J II Commission 73/09/10 3pp
- B004070047 Order granting extension until 800414 for Commission to review director's 800211 decision HOYLE,J C Office of the Secretary of the Commission 80/03/31
- BOD4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSBICK.L V Office of the Executive Director for Operations 00881CK,L V 0
- 8004190073 Order granting extension until 800425 for Commission to elect whether to review ALAB-436 & ALAB-561
 CHILK, B. J. Office of the Secretary of the Commission 80/04/04
- 8004270002 Forwards NRC confirmatory order STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/04 ip
- --8004290006 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800530 Required info specified in Attachment A BTELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/04 6pp
- 8004220754 Forwards potition supporting UCS potition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 GRAVES, R 8 Housatonic Safe Energy Alliance 80/04/13 ip
- --8004220762 Supports UCS potition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 GRAYES,R 8 Housatonic Safe Energy Alliance 80/02/15 ip
- B004220030 Order granting extension.until B00430.for Commission to review Director's B00211 decision HOYLE.J C Office of the Secretary of the Commission 80/04/14

H General correspondence

- BO02290456 Comments on util 800201 ltr from 9 Berry re design safety & operating procedures Possible human failure & lack of adequate info about equipment performance (llustrates inherent danger Licensing should not continue FLEISHER.W L Affiliation Unknown 80/02/25 2pp
- ECO4030016 Advises that Commission should evaluate need for power generated by facility & take close look at safety achieved for public protection GILINSXY.V Commission 80/03/11 ip
- --8004030018 Responds to 800225 ltr Forwards NY Times article re lack of need for electricity produced at facility Cites util trade association statement that reserve margin of 2% would exist if all plants in svc grid were shut down LEVINSON. J O Affiliation Unknown BO/03/02 2pp
- --8004030024 Responds to 80020B ltr supporting petition by UCS requesting decommissioning of Unit 1 & suspending operations of Units 2 & 3 Advises that Commission is reviewing comments on matter OILINSKY,V Commission 80/02/25 3pp
- ~-8004030025 Supports UCS 790917 petition requesting decommissioning of Unit 1 & suspension of operations at Units 2 & 3 Cites safety-related reasons for prompt action Certificate of Svc encl LEVINSON, J O Affiliation Unknown 80/02/08 3pp
- BOO4070194 Responds to FOIA request for info re facilities & damage due to barthquakes at Indian Point Forwards Documents 1-4 listed in App A Documents 5 & 6 may be purchased by sending check in amount of \$9.50 to NRC in Washington, D C FELTON/J M Division of Rules and Records 80/03/19 2pp
- --8004070229 "Annual Operating Rept." 1976
 * Consolidated Edison Co. of New York 76/12/31 27em
- --8004C70233 "Annual Operating Rept," 1977 TMI semiannual & annual operating rept excepts encl

 * Consolidated Edison Co of New York 77/12/3t 45pp
- BOOA290054 Forwards info requested in 800218 ltr re licensing actions Matl could not be forwarded by 800229 as ltr did not arrive at NRC until 800226 M/o encls
 DENTON.H R Office of Nuclear Reactor Regulation 80/03/25 App
- --8004290058 Requests info re changes affecting estension of OLs to Bloloi FLEISHER, Z S Affiliation Unknown 80/02/19 ip
- BOO4180234 Forwards NRC 800325 response to encl 800218 ltr from ZE Fleisher of West Branch Conservation Association in response to 800226 request W/o encl BIRCKS, W J Office of the Executive Director for Operations 80/03/28 lp
- --B004180237 Requests info re new safety regulations FLEISHER, 2 S West Branch Conservation Association 80/02/18
- SDO4210336 Advises that 791106 ltr to President Carter re emergency plans has been referred to NRC Since Summer 1979, NRC has been actively pursuing program to upgrade emergency preparedness Forwards NRC/FEMA documentation N/O encl. DENTON-H R Office of Nuclear Reactor Regulation 80/03/31 Spp
- BO041500B5 Responds to B0022B ltr re operation of nuclear power plants in high density areas NRC is investigating special measures to be taken in beavily populated areas Interim magsures have already been ordered at sites DENTON: H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --B004150094 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident STERNER.J W Affiliation Unknown 80/02/28 ip
- BOO4160173 Responds to B00212 ltr re continued operation of nuclear power plant Add1 measures should be implemented that will further reduce probability of severe reactor accidents. Licensee has been in shutdown pending completion of actions DENTON, H R. Office of Nuclear Reactor Regulation 80/04/01 2pp
- ---BOO4160176 Requests that NRC not phase out facility or convert to nonnuclear generators Nuclear power is source for power in US, No nuke political arguments have no basis in reality LAVERTY.E. Affiliation Unknown 80/02/12 2pp

- 8004170342 Responds to 800206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility, confirming commitment to public health & safety DENTON H R Dffice of Nuclear Reactor Regulation 80/04/01 2pp
- 8004210088 Responds to 800125 request re public hearing & determination on UCB petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or iessen consequences
 DENTON, HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --B004210093 Requests scheduling of public hearing & determination of VCB petition re operation of facility prior to reactivation Concerned for health & safety of community BCIANDRA, J. New York, NY 80/01/25 ip
- 8004210193 Responds to 800207 ltm re continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants Interim measures have already been ordered at sites DENTON, HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210201 Supports continued operation of facility Reactors supply 20% of generating capacity for New York City & Westchester County Utils can shut off oil plant, lowering rates & dependency on foreign oil WU,J Affiliation Unknown 80/02/07 1p
- 8004210208 Responds to 800204 itr re continued operation of facility Plants reviewed to determine what addi measures or design changes can & should be implemented to further reduce probability of reactor accident or consequences DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210%23 Urges NRC to decide in favor of continued operation of facility Reactors have long history of saferclean & economic operation Concerned that fuel adjustment charges will increase if plants are shut down

 GAY R Affiliation Unknown 80/02/04 ip
- 8004250013 Responds to 800212 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure probability of the confirmatory orders and the confirmatory of the confir
- --8004250030 Urges that NRC consider UCS petition re closing of facility Possibility of earthquake exists w/plant built near fault, Only 20% of area energy generated by fluctear power Alternatives should be considered OOLDHOR.F Affiliation Unknown 80/02/12, 1p
- 8004290018 Responds to 800215 itr re operation of facility NRC considering special measures to reduce probability of severe reactor accident or to lassen consequences Confirmatory orders issued as interim measure
 DENTON, H R Office of Nuclear Reactor Regulation, 80/04/01 2pp
- --8004250033 Urges NRC to approve UCB petition re shutdown of facility Because of proximity to New York City & impossibility of evacuation of so many people MOB.L., MOB.M. Affiliation Unknown 80/02/18 ip.
- 8004230185 Advises that NRC held two meetings in NY re continuing operation at facility. Commission presently considering form of review Public comments invited Request for another hearing in vicinity of plant will be considered.

 DENTON: HR Diffice of Nuclear Reactor Regulation 80/04/03. ip
- --8004230190 Requests that NRC hold another public hearing re continuing operation of facility to offer public chance to question , plant operators & govt agencies Public should be properly notified through local news media CONNOR.R J New York, State of 80/01/08 2pp
- 8004280287 Responds to 800225 ltr re facility safety Shutdown not ordered due to interim measures imposed by encl confirmatory order M/o encl EISENHUT, D 0. Division of Operating Reactors 80/04/07 1p
- 8004280140 Responds to 800117 ltr to DDE re 800117 incident at facilities Plant did not trip during minor earthquake tremor Epicenter of tremor was located approx seven miles from site. Tremor was significantly below design capability EISENHUT, D O Division of Operating Reactors 80/04/08 1p

- P Operating license stage documents & correspondence
- 8004070094 Forwards agenda & proposed rule for NRC sponsored 800115 meeting in New York, NY re proposed rule on emergency response RYAN, R © Office of State Programs 79/12/31 12pp
- --8004070098 Requests opportunity to testify at NRC 800115 meeting in New York:NY re emergency response plans in fifty-mile zone around plant NY City Council has been holding hearings on resolution to phase out plant FRIEDLANDER:N New York:NY 79/12/21 ip
- 800403030? Summary of B00123,24 & 30 site visits to facility to identify problems to determine extent of compliance w/ outstanding items Facility meets all short-term Lessons Learned Task Force requirements TELFORD, J T NRC Three Mile Island Task Force B0/02/19 Spp
- 800418038? Forwards modified near-site study in response to NRC 791205 request for 60-day crash effort
 PEOPLES:D L Commonwealth Edison Co DAVIS, J.F. Power Authority of the State of New York CAHILL. W.J. Consolidated Edison Co of New York 80/02/25 ip
- --8004180375 "Near-Site Study" Viewgraphs encl
 # Commonwealth Edison Co * Consolidated Edison Co of New York
 # Power Authority of the State of New York 80/02/25 95pp
- B004040260 Forwards response to 791221 ltr addressing NRC requirements for auxiliary feedwater sys at facility NRC review & addl info required for completing review encl Urges reply no later than 30 days from receipt of ltr BCHHENGER.A Operating Reactors Branch 1 B0/03/05 6pp
- BOO4040423 Forwards response to 791219 ltr addressing NRC requirements for auxiliary feedwater sys at facility, NRC review & addinequired info for completing roview encl Urges reply no later than 30 days from roceipt of itr SCHWENGER, A Operating Reactors Branch 1 80/03/05 7pp
- BOO4280223 Forwards SEP schedule & content requirements for environ qualification of electrical equipment Previously submitted info should be incorporated by spacific ref Unit exempt from IE Bulletin 79-018
 BCHWENCER, A Operating Reactors Branch 1 BO/03/05 4pp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D. G Division of Operating Reactors 80/03/12 9pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004140221 Summary of 800221 meeting w/representatives of all SEP plants.utils & Franklin Research Ctr re accelerated program for evaluating qualification of safety-related electrical equipment WILSON,R Plant Systems Dranch 80/03/14 3pp
- B004110045 FOIA request, on behalf of VCB, for Sandia Labs study re liquid effluent pathway at facility WEISB, E R Sheldon, Harmon & Weiss 80/03/18 ip
- 8004240163 Forwards addl info & clarification re guide for evaluating environ qualification of Class IE electrical equipment in operating reactors & for identification of appropriate safety equipment of SEP reactors SCHWENCER, A Operating Reactors Branch 1 80/03/20 15pp
- B004110001 Forwards corrected attachment to Amend 29 to License DPR-64 forwarded in NRC 800221 ltr Attachment lists page numbers of revised pages to be removed & inserted SCHWENGER.A Operating Reactors Branch 1 B0/03/21 3pp
- 8004140014 Responds to statement during 800225 meeting re many significant discrepancies between inputs to SER & published public version Identification would be helpful so appropriate action can be taken SCHENCER.A Operating Reactors Branch 1 80/03/26 ip
- B004100169 Notification of B00403 meeting w/util in Bethesda.MD re snyiron qualification of electrical equipment OLBHAN.L N Operating Reactors Branch 1 80/03/31 2pp

- 8004080381 Forwards response to L Dishan 800219 verbal request for summary of original evaluations of RCS includes tables providing seismic loads for RCS piping & supports EARLY.P J Power Authority of the State of New York 80/04/01
- 9004210112 Advises that 780831 amend application re secondary water chemistry monitoring falls in Class II fee category Refund will be forwarded for Class III overpayment MILLER, W O License Fee Management Branch 80/04/01 ip
- 8004110038 Responds to FOIA request for Sandia Labs study re liquid effluent pathway at facility Rept is undergoing NRC technical review prior to publication Draft encl FELTON.J M Division of Rules and Records 80/04/02 lp
- --8004110051 Draft study of facility liquid effluent pathway
 * Sandia Laboraturies 80/04/02 800op
- 8004170061 Submits info requested at 800111 meeting w/NRC recontainment bldg basemat X-ray defraction test performed to determine crystalline % noncrystalline calcium compounds & silicon dioxide Results listod EARLY.P J Power Authority of the State of New York 80/04/08
- 8004290167 Forwards request for info as part of NRC upgrade review of QA program includes info re requirements & methodology for determining how & to what estent QA program will be applied to specific items & activities

 SCHWENCER, A Operating Reactors Branch 1 80/04/08 7pp
- 8004240480 Forwards addl info re review of unresolved safety issues, trip rept of Lessons Learned implementation team, & task action plan in view of high population density surrounding plants
 DENTON. H R Office of Nuclear Reactor Regulation 80/04/09 33pp
- --8004240483 Summary of Westinghouse Lessons Learned team 800121-22 site visit to determine status of Category A implementation Attendance & status lists encl TELFDRD, J T Safeguards Standards Branch 80/02/18 Spp
- --8004240486 Summary of Westinghouse Leasons Learned team 800124-25 site visit re status of Category A implementation Attendance & status lists encl TELFORD, J T Bafeguards Standards Branch 80/02/20 Spp
- ---8004240489 Summary of Westinghouse implementation team 800123-24 & 30 site visit re short-term Lessons Learned requirements TELFORD, J T Sefeguards Standards Branch 80/02/15 8pp
- --8004240492 Forwards evaluation of util actions taken to satisfy
 Lessons Learned Category A requirements Concludes all
 requirements satisfied Attendance list for 800121-22 site
 visit encl
 SHCWENCER.A Operating Reactors Branch 1 (Pre 791030) 80/02/29
 27pp
- ---8004240504 Forwards evaluation of util compliance w/Category A Lessons Learned requirements Concludes all requirements satisfied IE followup & attendance lists encl SCHMENCER, A Operating Reactors Branch 1 (Pre 791030) 80/02/21 14pp
- --8004240507 Forwards action plan developed in recognition of high population densities surrounding sites DENTON,H R Office of Nuclear Reactor Regulation 80/02/21 80on
- ---B004240518 Discusses Event 5 probabilities Suggests continuous monitoring & readout capability of check valve position & periodic tests of leak rate measurements
 TAYLOR.M A Division of Reactor Safety Research B0/01/15 17pp
- BOO4250232 Forwards status of unresolved safety issues at Indian Point 1 & 2.trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at facilities, task action plan & facility societal risk info DENTON.H R Office of Nuclear Reactor Regulation BO/04/09, 34pp
- 8004280054 Forwards status of unresolved safety issues at Indian Point 2 & 3, trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at facilities, task action plan & facility societal risk info DENTON, HR Office of Nuclear Reactor Regulation 80/04/09 34pp

- 8004280113 Forwards safety evaluation re util 800129 t 0227 LOCA reanalyses All assumptions in analyses are conservative Analyses provide acceptable basis for operation within limitation of Tech Specs SCHWENCER, A Operating Reactors Branch 1 80/04/09 2pp
- --8004280120 Safety evaluation concluding that assumptions made in util 800127 & 0227 LOCA reanalyses are conservative Analyses provide acceptable basis for operation within limitation of Yoch Specs

 9 Office of Nuclear Reactor Regulation 80/04/09 2pp
- 8004240458 Formalizes plans re series of technology exchange meetings re facilities' accident mitigation features activity Five meetings suggested Recommended meeting schedule & agenda items encl
 80MWENCER.A. Operating Reactors Branch 1 80/04/10 15pp
- BO04180343 Responds to NRC 800305 ltr re auxiliary faedwater sys Forwards commitment dates &/or responses re level indication & alarm control room & results of endurance test on steam driven auxiliary feed pump EARLY.P J Power Authority of the State of New York 80/04/11 70p
- 8004180350 Forwards responses to 60-day action items of NRC 800211 confirmatory order (interim actions) Steady state generator operating level was chosen on basis of analyses & set point-type studies Level optimized w/Class I transients EARLY.P J Power Authority of the State of Neu York 80/04/11 1000
- G Inspection reports, IF Bulletins & correspondence
- B004080632 Forwards response to IE Circular 78-08 & IE Bulletin 79-01 re environ qualification of safety-related electrical squipment Basic requirements of FSAR have been met Transmitters environmentally qualified BAYNE. J P Power Authority of the State of New York 79/06/13 78pp.
- 8004220787 Responds to IE Bulletin 79-17 Examination of stagnant borated water sys detected no visible leaking on normally accessible welds
 BAYNErJP Power Authority of the State of New York 80/02/06
- BO04090354 Forwards response to IE Bullotin 79-14 Complete listing of static span table analyzed lines entl Representative sample of bldgs & components investigated for seismic input to design specs

 SCHMIEDER, J. R. Power Authority of the State of New York 80/02/25
- #3004080328 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Review requires addi procedure guidance to be submitted within 60 days Site design differs from bulletin sys PAYNE, J P Power Authority of the State of New York 80/02/28 2ap
- EOO4030267 Submits response to IE Dulletin 79-18 re audibility problems encountered on evacuation of personnel from high noise areas Performed survey to determine adequacy of notification sys Resoults indicated sys needs upgrading BAYNE, J P Power Authority of the State of New York 80/03/03 ip
- BO04220004 Forwards interim safety evaluation rept of piping reanalysis in response to IE Bulletin 79-07 Total reanalysis package should be submitted by 800411 & supports should be modified by 800420
 BGHWENCER, A Operating Reactors Branch 1 80/03/24 2pp
- ---B004220007 Safety evaluation supporting review of piping reanalysis in response to IE Bulletin 79-07 * Operating Reactors Branch 1 80/03/24 2pp
- BOO4210056 Ack receipt of 800103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/79-24 SMITH.O H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/26 ip
- ---8004210061 Responds to NRC 791211 ltr re violations noted in IE Insp Rept 50-286/79-24 Corrective actions evaluation performed to determine monitoring & protective clothing requirements for specific job BAYME.J P Power Authority of the State of New York 80/01/03 200

- --8004210064 Forwards 1E Insp Rept 50-286/79-24 on 791030-31 & notice of violation SMITM, GH Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/12/11 200
- --800421006B Notice of violation from insp on 791030-31
 * Region 1, Philadelphia, Office of the Director 79/12/10 ipp
- --8004210070 IE Insp Rept 50-286/79-24 on 791030-31 Noncompliance noted failure to maintain results of surveys re personnel monitoring requirements for individuals entering steam generators
 STOMR, J.P. Region 1, Philadelphia, Fuel Facility & Materials
 Safety Branch SERABIAN, J.A. Region 1, Philadelphia, Office of the Director 79/12/10 Spp
- BO04150280 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director BO/03/31 ip
- 8004090092 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/04/01 ig
- 8004110163 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No written response required ORIER.B H Regian 1, Philadelphia, Office of the Director 80/04/02 ip
- BO04240333 Forwards IE Info Notice BO-14, "Safety Suggestions From Employees" No action required GRIER.B H Region I, Philadelphia, Office of the Director BO/04/02 1p
- 8004180241 Forwards IE Circular 80~07, "Problems W/HPCI Turbine Oil Sys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/03 ip
- 8004230452 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Stopl Pipe" Action required ORIER. B H Region 1. Philadelphia, Office of the Director 80/04/04 ip
- 8004180212 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required ORIER, B H. Region 1, Philadelphia, Office of the Director 80/04/07 ip
- 8004300041 Responds to IE Bulletin 79-14 Forwards SPT-V14, Revision 3, "As-Built Verification of Seismic Class I & II Pipe Supports."

 EARLY, P J Power Authority of the State of New York 80/04/09 2nn
- --8004300044 "Ax-Built Verification of Seismic Class I & If Pipe Supports " * Power Authority of the State of New York 79/09/29 4pp
- BOO4150458 Submits final rept of work performed under IE Bulletin 79-07 Safety sys re-evaluated "As-built" verification of piping sys performed per field check plan Plant may continue operation W/o risk to public safety ERRLY.P J Power Authority of the State of New York 80/04/10
- R Periodic operating reports & related correspondence
- 8004150599 Forwards "Environ Discharge Monitoring Rept for Mar 1980 "
 MONTI, W A Consolidated Edison Co of New York 80/04/10 1p
- --B004150609 "Environ Discharge Monitoring Rept for Mar 1980 "
 Consolidated Edison Co of New York 80/04/10 15pp
- 8004180426 Forwards monthly operating rept for Mar 1980 BAYNE, J.P. Power Authority of the State of New York 80/04/15 ip
- --8004180434 Monthly operating rept for Mar 1980 CONNELL.C Power Authority of the State of New York. 80/04/03

- 8004210267 Forwards "Daily Counts from Intake Screens, Mar 1980," re fish collections Circulators were shut down for month at Unit 1
 - CAHILL, U J Consolidated Edison Co of New York 80/04/15 1p
- --8004210276 "Daily Counts from Intake Screens, Har 1980." re fish collections
 * Consolidated Edison Co. of New York 80/04/15 App
- S Reportable occurrences, LERs & related correspondence
- 8004210440 PNO-77-172 on 770926. Units 2 & 3 tripped from 100 & 91% power, respectively Caused by spurious signals in reactor protection sys resulting from electrical disturbances in Buchanan substation State of NY informed KLINGER. G. Region i, Philadelphia, Office of the Director 77/09/27 ip
- 8004110437 Forwards LER 80-002/03L-0 BAYNE, J P Power Authority of the State of New York 80/04/03 1p
- --8004110442 LER 80-002/03L-O on 800309, at hot shutdown, during routine check of heat trace circuitry, borse and heat trace circuitry borse and trace circuit 7 was found not continuous Cause not stated Circuit fault repaired GUMBLE, FW Power Authority of the State of New York 80/04/03 is
- 8004140416 Forwards LER 80-003/03L-0 BAYNE,J P Power Authority of the State of New York 80/04/10 1p
- ---8004140422 LER 80-003/03L-0 on 800311.during hot shutdown body of valve CF-43 was leaking causing piping associated w/boiler feed pumps to become inoperable Caused by pinhole leak in valve body Valve was replaced & returned to svc GUMBLE.F W Power Authority of the State of New York 80/04/10
- 8004180448 Forwards LER 80-004/03L-0 BAYNC,J P Power Authority of the State of New York 80/04/14 1p
- --8004180461 LER 80-004/03L-O on 800319, upon completion of containment spray pump test operator attempted to open VC isolation valve 8698 W/o success Cause by key failure induced by mechanical fatigue Key & keyway repaired OVMBLE.F W Power Authority of the State of New York 80/04/14 in
- 8004220741 Forwards LER 80-005/03L-0 BAYNE,J P Power Authority of the State of New York 80/04/17 1p
- ---8004220749 LER 80-005/03L-0 on 800326, while operating at 75% power, signs of outboard pump bearing overheating were indicated from visual observance of auxiliary boiler feed pump Caused by thrust bearing failure which created shaft scoring, GUNBLE, F. W. Power Authority of the State of New York, 80/04/17

U Congressional/Executive Correspondence

- 8004080193 Responds to 791212 ltr re Rockland Mobilization for Survival ltr concerning Dec 1979 public meeting on emergency preparedness Period of public comment lasted until NRC participants had listened to all speakers DIRCKS.N J Office of the Executive Director for Operations 80/03/05 2pp
- --8004080206 Discusses 791218 public meeting on emergency preparedness Plans should be arranged to allow ample time for public comment Viewpoints of citizens within facility vicinity appear to be unimportant to NRC STERN.L D Rockland Mobilization for Burvival 79/12/09 2pp.
- 8004300272 Forwards Congressman Rosenthal B00114 ltr re concerns falling within FR 800222 notice requesting public views on proceeding issues DIRCKB, y Office of the Executive Director for Operations 80/04/11 ip
- --8004300299 Conveys concerns re safety & health risks posed by plants & lack of adequate evacuation plan Urges NRC to respond to UCB petition RDBENTHAL.B B House of Rep , Foreign Affairs. 80/01/14 1p

- DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8004010255 Forwards list of revisions 2 additions that should be incorporated (a 790803 revised safeguards contingency plan Revised plan incorporating revisions 3 additions should be submitted within 30 days [nfo withheld (ref [OCFR2 790] REID;R W Operating Reactors Branch 4 80/03/14 2pp
- 8004030197 Forwards info in support of standby shutdown facility Encl withhold (ref 10CFR2 790) PARKER,W D Duke Power Co 80/03/28 2pp
- 8004170164 Forwards Revision 4 of security plan Plan withheld (ref 10CFR2 790) PARKER,N D Duke Power Co 80/04/09 1p
- 8004220443 Advises that revised pages to safeguards contingency plan will be provided by 800430 in response to NRC 800314 request PARKER, U. D. Duke Power Co. 80/04/11 | 15

G Adjudicatory correspondence

- 8004230078 Forwards 800328 SECY-80-166 requesting amend to irradiated reactor fuel in-transit physical protection requirements If amend approved, effect on NRC case re spent fuel transportation & storage will be provided HDEFLING.R K Hearing Branch 4 80/04/01 1p
- 6004240544 Opposes licensee motion to compel discovery upon intervenor Motion constitutes part of continuing pattern of harrassment by licensee attys Certificate of Soc encl
 KEPFORD.C Environmental Coalition on Nuclear Power 60/04/03

I Financial information

- BOO4020334 Forwards Annual Financial Rept for 1979, annual certified financial statements, financial forecast for 1980-82 & statement re available sources of funds to satisfy liability requirements
 THIES.A C. Duke Power Co. 80/03/28 600

P Operating license stage documents & correspondence

- 80040B0641 "Electrical, Instrumentation & Control Aspects of Override of Containment Purga Valve Isolation & Other Safety Feature Signals, Oconee Nuclear Station," informal rept UDY, A C EO & 6, Inc FIN A-6256 80040B0641 80/02/29 12pp
- 8004040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bullotin 79-27 re 800206 roactor trip at Crystal River Bequence of events & planned corrective actions also encl
 DENTON, HR Office of Nuclear Reactor Regulation 80/03/04 26pp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT.D 9 Division of Operating Reactors 60/03/12 5pp
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors 80/02/21 28pp
- B004030230 Notification of 80031B meesting w/all operating B&W reactor licensees in Betheada.MD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID.R W Operating Reactors Branch 4 80/03/14 2pp
- 8004170327 "TMI-Plus One Toward a Safer Nuclear Power Program" * Duke Power Co 80/03/26 1300
- 8004010470 Supplements 800324 ltr Confirms conversations w/NRC retesting of loss of non-nuclear instrumentation, integrated control sys power on Unit 1 Test will be completed within 90 days of order, if required PARKER, NO Duke Power Co 80/03/28 1p

- _004030179 Forwards proposed arend to facility Tech Specs Fable 4 1-3, Section 6 6 4 4(2)(a) 2 Table 6 6-1 re nonitoring waste disposal programs
 PARKER H O Dute Power Co 60/03/28 2pp
- --8004030202 Proposed amend to facility Tech Specs Table 4 1-3, Section 6 5 1 4(2)(a) 8 Table 6 6-1 re waste disposel monitoring
- programs

 Dute Power Co 80/03/31 7pp
- B304210321 Requests followup rept to 791030 ltr re method used to demanstrate conformance exprovisions of 400FR190 rept required by Tech Specs
 FEID.R W Operating Reactors Branch 4 80/03/28 2pp
- BOO4160001 Responds to 791116 Tech Spec change application re operation of Unit 2 at full rated power during Cycle 3 Review has determined that proposed reload requires Class IV amend fee instead of Class III Requests add) fee DIGOS R M License Fee Management Branch 80/03/31 ip
- 8004080555 Forwards info re indications & controls requiring mods to maintain plant at hot shutdown independent of ECS/NNI power supplies PARKER.H O Dure Power Co 80/04/01 2pp
- E004080614 Supplements B00102 ltr & confirms discussions w/NRC re reactor vessel head vent required by NUREO-0578 Remotely operable reactor vessel head vent uill be installed Design uill be similar to that of hot leg vents per B00102 ltr PARKER, N D Duie Power Co B0/04/02 lp
- 8004210328 Summary of 800222 meeting u/BbW owners group in Bathasda, Hd re abnormal transient operational guidelines SEIGEL, B L Reactor Systems Branch 80/04/02 4pp
- 8004140430 Forwards comparison of draft STS w/snubber functional test sampling plan COLLINGS,D M Dute Power Co 80/04/03 11pp
- 8004250368 Summary of 800403 meeting w/utils. B&H, NUS Corp & McGraw-Hill in Bethesda, MD re draft NUREC-0667, "Transient Response of B&H-Designed Reactors" CAPRA, R A Standardization Branch 80/04/04 7pp
- 8004180490 Notification of 800423 mesting w/utils & B&W in Bethesda, HD to discuss implementation of recommendations by B&W Reactor Transient Response Tast Force CAPRA, R A Standardization Branch 80/04/05 2pp
- 8004280105 Forwards evaluation of implementation of Lessons Learned Tast Force Category A items All items satisfactorily implemented at Unit 1 Three remaining items at Units 2 & 3 will be met prior to restart from Mar 1980 shutdowns REID.R U Operating Reactors Branch 4 80/04/07 15pp
- BOO4300137 Concurs w/B00321 ltr describing safety of fuel pool operation w/o add1 cooling capacity due to delay of add1 cooler & pump installation Requests precise estimate for procurement & installation by B00601 REID.R W Operating Reactors Branch 4 B0/04/09 3pp
- BOO4150465 Forwards supplemental response to NRC BOO223 request for info re primary coolant sys pressure isolation valves. Neither continuous surveillance nor periodic testing is now being performed Check valves display no lack of integrity PARKER, W.O. Dute Power Co. 80/04/11 4pp
- B004220502 Advises that detailed analysis of thermal-mechanical conditions of reactor vessel during recovery from small breaks will be submitted 800715

 FARKER, W. O. Duke Power Co. 80/04/14 ip
- B00422040 Supplements util 770725,1017 & 1219 ltrs re design & use of containment purge sys Requests NRC concurrence in scope of mods to permit purging during operations above cold shutdown PARKER, H O Duke Power Co B0/04/15 2pp
- BOO4180356 Bubmits addl info to supplement BOO324 ltr Describes parameters needed by operator to place plant in safe hot shutdown condition & testing for loss of power PARKER, H O Dute Power Co BO/04/18 2pp

- G Inspection reports. IE Bulletins & correspondence
- 8004220227 Discusses investigation of scram breaker failures at facility Adjustment mechanisms can potentially fail both ac & dc breakers IE headquarters is pursuing concerns & preparing circular on affected breakers SATIERFIELD, R Electric. Instrumentation & Control Bystems Branch 79/06/21 3pp
- 8004070362 Responds to NRC request made during 800107-11 insp for addl info re assumptions made for support/restraint calculations performed in compliance w/IE Bulletin 77-02 Addl & original calculations for Support SR 134 encl PARKER.W D Dute Power Co 80/01/31 19pp
- 8004040358 Ack receipt of IE Insp Repts 50-267/80-04,50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No proprietary info PARKER, W O Duke Power Co 80/03/10 ip
- --8004040383 Forwards IE lnsp Repts 50-269/80-04,50-270/00-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/14 2pp
- --8004040402 IE Insp Repts 50-269/80-04,50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No nancompliance noted Major areas inspected emergency facilities, equipment & procedures, means for determining release & emergency training JENKINS,0 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch PERROTTI.D J Region 2, Atlanta, Office of the Director 80/02/14 lipp
- 8004080283 Forwards response to IE Bulletin 79-018 re environ quelification of Class IE equipment Completion of Items 1, 2 % 3 documented M/o encl PARKER, W 0 Duke Power Co 80/03/13 2pp
- 8004240035 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II. Two-Inch. Tray Adsorber Cells" No evidence of filter degradation as described in bulletin was observed at facilities
 PARKER, W O Duke Power Co 80/03/21 2pp
- 8004230202 Ack receipt of 800204 ltr informing NRC of steps taken to correct violation noted in IE Thep Repts 50-269/79-41, 50-270/79-39 & 50-287/79-41

 LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/26 ip
- --800423023A Responds to NRC 800114 ltr re violations noted in IE Insp Repts 50-269/79-41,50-270/79-39 % 50-287/79-41 Corrective actions technician involved given written warning & independent verification bying developed PARKER. N O Duke Power Co 80/02/04 2pp
- --8004230249 Forwards IE Insp Repts 50-269/79-41.50-270/79-39 & 50-287/79-41 on 791203-10 & notice of violation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/01/14 2pp
- --8004230267 Notice of violation from into an 791203-10, * Region 2, Atlanta, Office of the Director 80/01/11. 1p
- --B004230277 IE Insp Repts 50-269/79-41.30-270/79-39 & 50-287/79-41 on 791203-10 Noncompliance noted failure to follow maint procedures resulting in noncompliance w/Tech Specs MARTIN,R D , JAPE,F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/11 6pp
- B004210191 Ack receipt of IE Insp Repts 50-249/80-03, 50-270/80-02 & 50-287/80-02 on 800114-24 No proprietary info PARKER, N O Duke Power Co B0/03/28 ip
- --8004210195 Forwards IE Insp Repts 50-269/80-03,50-270/80-02 & 50-287/80-02 on 800114-24 No honcompliance noted BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004210199 IE Insp Repts 50-269/80-03,50-270/80-02 & 50-287/80-02 on 800114-24 No noncompliance noted Major areas inspected IE Bulletins 79-13 & 79-17, auxiliary faedwater noise thermal sleeve insp & crack repair HERDT. A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS, N Region 2. Atlanta, Office of the Director 80/02/25 7pp

- 8004190811 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PCRV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 800422018B Forwards IE Insp Repts 50-249/80-08,50-270/80-06 & 50-287/80-06 on 800225-29 No noncompliance noted KENNA,W B Region 2, Atlanta, Bafeguards Branch 80/03/31 2pp
- --8004220204 IE Insp Repts 50-249/80-08.50-270/80-06 & 50-287/80-06 on 800225-29 No noncompliance noted Major areas inspected security plan, security program & physical security Details withheld (ref 10CFR2 790)
 TOBIN, H J Region 2. Atlanta, Bafeguards Branch 80/03/25 lp
- 8004080611 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required g'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/01
- 8004150070 Forwards IE Info Notice 80~13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required Q'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004250330 Ack receipt of 800314 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-269/80-05, 50-270/80-04 t 50-287/80-04 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip
- --8004250334 Responds to NRC 800220 ltr re violation noted in IE Insp Repts 50-269/80-05.50-270/80-04 & 50-287/80-04 Corrective actions areas cited were cleaned & maint practices & procedures changed to include housekeeping practices PARKER.W D Duke Power Co 80/03/14 2pp
- --8004230340 Forwards IE Insp Repts 50-249/80-05,50-270/80-04 & 50-287/80-04 on 800107-31 & notice of deviation LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/20 2pp
- --8004250346 Notice of deviation from Insp on 800107-31.
 * Region 2. Atlanta. Office of the Director 80/03 80/02/20 1p
- 8004080432 Forwards steam generating operating history updating info in util 781128 ltr through 1979 refueling outage inservice PARKER, W D Duke Power Co 80/04/03 12pp.
- 8004180326 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Bys "No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/03
- 8004250357 IE Insp Repts 50-269/80-05, 50-270/80-04 & 50-287/80-04 on B00107-31 Noncompliance noted failure to adhere to stated housekeeping practices in areas occupied by safety-related equipment

 MARTINER D. Region 2, Atlanta, Reactor Operations Nuclear Support

 Branch JAPE.F. Region 2, Atlanta, Office of the Director

 80/02/20 Spp
- B004230132 Forwards IE Bulletin 79-03A "Longitudinal Held Defects in ABME BA-312.Type 304 Stainless Steel Pipe" Action required O'REILLY.J.P. Region 2. Atlanta. Office of the Director 80/04/04
- 8004180358 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P. Region 2, Atlanta. Office of the Director 80/04/07
- B004300205 Ack receipt of B00303 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 G'REILLY, J P Region 2. Atlanta. Office of the Director, 80/04/07

- --8004300214 Responds to NRC 800206 ltr re violations & deviations in IE Insp Repts 50-269/79-37,50-270/79-34 & 50-287/79-37 Corrective actions shift operating personnel instructed on manual transfer intercommunication sys & alarm procedures PARKER.W O Duke Power Co 80/03/03 4pp
- --8004300230 Forwards IE Insp Repts 50-269//9-37,50-270/79-34 & 50-287/79-37 on 791111.15 & 16 & notices of violation & deviation LEMIB:R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/06 2pp
- --BD04300237 Notice of violation from insp on 771111,15 & 16 * Region 2. Atlanta, Office of the Director 80/01/18
- --8004300245 Notice of deviation from insp on 791111,15 & 16
 * Region 2. Atlanta, Office of the Director B0/01/18 2pp
- --8004300260 IE Insp Repts 50-269/79-37,50-270/79-34 \$ 50-287/79-37 on 79111. 15 & 16 Noncompliance noted inadequate procedures to correct potential maleunctions, excessive RCS cooldown rate & failure to notify of RO within 1-h GUICK, DR, MRTIN, R Region 2, Atlanta, Office of the Director 80/01/18 dpp
- 8004240276 Forwards add1 response to IE Bulletin 77-018, "Environ Gualification of Class IE Equipment " Revised master sys/ components list & sys component evaluation work sheets encl Add1 equipment info will be sent by 800701 THIE8, A C Duke Power Co 80/04/21 1200pp
- S Reportable occurrences, LERs & related correspondence
- 8004160272 RO 287/80-4 rept re breach of fire barrier in cable room should have been submitted by 800327 Anticipates that rept will be submitted no later than 800411 PARKER.W O Duke Power CO 80/03/27 p
- 8004030223 Forwards LER 80-005/03L-0 PARKER,W 0 Duke Power Co 80/03/31 3pp
- --- 8004030224 LER 80-005/03L-0 on 800302, borated water storage tank level Channel i failed high when beliows froze Caused by removal of transmitter box cover Transmitter thawed & calibr LEWIS, S.R. Duke Power Co. 80/03/31 1p
- B004160229 Forwards LER 80-004/03L-0 PARKER, W O Duke Power Co B0/04 B0/04/11 3pp
- --8004160232 LER 80-004/03L-0 on 800226.breach in final barrier penetrations discovered in two places Cause for missing matl in one sleeve & hole in plate of other undetermined Hourly firm watch established until firestop matl was installed LEHIS.8 R Duke Power Co 80/04/11 ip
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8004100350 Forwards Revision AB to modified amended physical security plan Plan withheld (ref 10CFR2 790)
 HERBEIN, J O Metropolitan Edison Co 80/04/02 1p
- BOO4210263 Notification of 800415 meeting u/util in Behtesda re open items on fire protection per NRC 800207 ltr DIIANNI,D C Operating Reactors Branch 4 80/04/04 lp
- 8004300409 Advises that std market weather alert monitor is sufficient for use in notifying public, regardless of on-off switch HERBEIN, J O Metropolitan Edison Co 80/04/25 ip
- G Adjudicatory correspondence
- 8004100136 First set of interrogatories directed to licensee in restart proceeding re UBDA fixed nuclear facility incident plan Gentificate of Svc enci AAMODT,M M Affiliation Unknown 80/02/16 Spp
- --BOO4100142 Second set of interrogatories directed to State of PA in restart proceeding re relation between hypothyroidism & radioactive emissions AAMODT/M M Affiliation Unknown 80/02/22 2pp

- -CTD4(1)145 Serind set of interrogatories directed to licensee in restart professing re-Contention 8 concerning radiation enterior data AAM-071,00 Affiliation Unknown 80/02/22 Lp
- -20041v0150 Third set of interrogatories directed to licensee in restart proceeding re-Contention 11 Licencerning projected & present capitalizes cost & related data
 ARMODINO Affiliation Uninon 80/02/22 ip
- FIC4100155 Fourth set of interrogatories directed to licensee in restart proceeding re amended Contention 4-concerning data record 4 transmission in control room Supporting documentation & Certificate of Svc ent!
 AAMODT N Q Affiliation Unknown 80/02/22 Spp
- ECO4633137 Notice of taking of depositions Submits names of add1 licensee employees to be added to list provided in inter-enom ECO120 notice of taking of depositions Centificate of Svcs encl HICCF, HP Three Hile Island Alert WIDCFF, HP Widoff, Reager, Seltciti & Adder ECO/02/22 Zpp
- --BO040E0145 Notice of intent to take depositions of individuals listed, all of whom served as staff or consultants to President's Commission on IMI Certificate of Svc & related correspondence encil
 HIDDEF, H P Intee Mile Island Alert WIDDEF, H P Hidoff, Reager, Seltouitz & Adier 80/02/22 4pp
- --BJ04080150 Further amend to 800128 notice of depositions & 800214 amend to notice, adding following dates 800212 & 17 Centificate of Suc enci NUDOFF, M P Three Mile Island Alert WIDOFF, M P Widoff, Reager, Seltowitz & Adler 80/02/22 3pp
- --8004080167 Seventh set of interrogatories Includes questions re past b present util personnellinsp & maint log & administrative procedures explaining use & meaning of job ticket form Certificate of Svcs encl HIDOFF, M P Three Hile Island Alert HIDOFF, M P Hidoff, Reager, Selkouitz & Adler 80/02/22 7pp
- --B0040B017A Notice of taking of depositions Submits names of NRC personnel to be added to list provided in intervenor B0020A notice of depositions Certificate of Svc encl WICOFF.H P Three Mile Island Alert WICOFF.H P Hidoff. Reager. Seltowitz & Adler 80/02/22 2pp
- BO04220350 Certification to Commission re psychological distress issues Unges consideration of issue under NEPA for purpose of mitigating effects of THI—I licensing activities Intervenors contentions enci JOADAN.H H , LITTLE, L H , SMITH, I H Atomic Safety and Licensing Board Panel B0/02/22 31pp
- BOO4010064 Third set of interrogatories, re Contention 4 Includes questions re NRC monitoring of data from licensee & NRC role in restricting nath news programming in Harrisburg area during THI-2 accident AAMODI, N O Affiliation Uninown 80/02/23 1p
- --B004010070 Fourth set of interrogatories re Contentions 4 & 5 Includes questions re potential for foodstuff poisoning due to radioactive iddine emissions

 AAMODT.M M. Affiliation Unknown B0/02/25 2pp
- --8004010072 First set of interrogatories re Contention 8 Includes questions re methods of measuring emissions during routine radioactive plant releases

 AAMODT.N 0 Affiliation Unknown 80/02/23 1p
- --- B004010076 Third set of interrogatories re Contentions 4 & 5 Includes questions re effects of radioactive loding emissions on feodatuffs

 AAMODI, M H Affiliation Unknown B0/02/25 2pp
- ---B004010078 Third set of interrogatories re Contention 4 Includes questions re emergency evacuation plan
 AAMODT.H H Affiliation Unknown 80/02/25. 3pp
- --- 8004010082 Fifth set of interrogatories re Contention 4 Includes questions re NRC news release policies & radioactive sefisions estimates Certificate of Svc encl AAHODT: H Affiliation Unknown 80/02/25 4pp

- --8004010089 Fourth set of interrogatories re Contention 2 Includes questions re operator & senior operator basic engineering & physics training in thermal hydraulics AAMDDT.M M Affiliation Unknown 80/02/25 Bpp
- --8004010093 Sixth set of interrogatories re Contention 2 Includes questions re tests used for licensing operators before & after TMI-2 accident Certificate of Svc encl AAMODT, M M Affiliation Unknown B0/02/25 6pp
- 8004010036 First of set of interrogatories Interrogatories limited to Contention B re emergency planning & preparedness Certificate of Svc encl SHOLLY.8 C Affiliation Unknown 80/02/25 App
- --8004010040 First set of interrogatories & document requests Includes questions re communications links between state agencies & licensee emergency event classification scheme Certificate of Svc encl
 SHOULY, S.C. Affiliation Unknown 80/02/25 7pp
- ~-8004010042 Second set of interrogatories & document requests includes questions re NRC assessment of adequacy of licensee proposed high radiation containment isolation signal Certificate of Svc encl
 SHOLLY.S C Affiliation Unknown 80/02/25 15pp
- --8004010044 Fourth set of interrogatories & document requests Includes questions re former amployees who served on THJ security force & attempted acts of sabotage & theft Certificate of Svc encl
 SHOLLY,S C Affiliation Unknown 80/02/25 36pp
- 8004090190 Notice of address change for intervenor Chesapeake Energy Alliance Mail should be sent to representative in Baltimore, MD Certificate of Svc encl POLLARD, R O Chesapeake Energy Alliance 80/02/27 3pp
- 8004020202 Response in opposition to SC Sholly Interrogatories 5.6.18, 22 & 29-34 of third set of interrogatories re Contention 16. Guestions bear on security planning but do not relate to alleged threat posed by Unit 2 Certificate of Svc encl BLAXE.E L. Hetropolitan Edison Co. BLAXE.E L. Shaw, Pittman, Potts & Troubridge 80/02/28 7pp
- 8004090096 Motion seeking extension until 800331 to respond to intervenors' interrogatories, due to large vol & last-minute filing, re restart proceeding Certificate of 8vc encl.
 TROMBRIDGE, 0 F Metropolitan Edison Co TROMBRIDGE, 0 F Bhaw, Pittman, Potts & Trowbridge 80/03/03 6pp
- S004(1054) Notice of intervenor 800307 entry upon premises of TMI-1 for purpose of inspineesuring & photographing control room storage location for radiation monitoring instruments & hydrogen recombiner Certificate of Svc encl SHOLLY-S C Affiliation Unknown 80/03/03 4pp.
- --8004i10546 Intervenor motion to compel licensee response to second set of interrugatories, Licensee filed objections to two intervenor interrugatories on 800225 Intervenor finds objectives w/o merit SHOLLY/8 C Affiliation Unknown 80/03/07 10pp
- 80040B0375 Advises of late receipt of NRC B00219 notice announcing 800226 meeting between Met Ed. General Public Utils & NRC to discuss restart open issues Urges timely transmittal of info in future
 WEISS, E.R. Sheldon, Harmon & Weiss, 80/03/04 ip
- 8004110212 Correction to initial objections to second set of interrogatories from intervenor SC Sholly Explanation of objection to Interrogatory 16-004 supplied W/Certificate of Svc ZAHLER, R E Metropolitan Edison Co 80/03/04 4pp
- 8004030320 Suppl to intervenor 800213 omnibus motion, in response to denial of oral argument re restart proceeding. Alleges little justification for funding one class of intervenors over another Budget request & Certificate of Svc encl POLLARD, R G Chesapeake Energy Alliance. 80/03/06 7pp
- 8004020018 Response in opposition to certain of intervenor MI Lewis third & fourth sets of interrogatories Questions 23-25,27-31 & 36-37 irrelevant & do not lead to admissible evidence Remaining questions will be answered W/Certificate of Syc EWARTZ, L. L. Antitrust Division 80/03/07 12pp

- 8004030322 Response in opposition to fourth special prehearing conference order disposing restart Contentions II(C), III(A) (a) & III(A)(b) Urges revision of order due to improper determination of merits Certificate of Svc enc.]

 BOWERS.J Anti-Nuclear Group Representing York 80/03/10 4pp
- BOD4110155 Forwards licensee response to TMI Alert third set of interrogatories ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 80/03/10 ip
- --8004110162 Response to third set of interrogatories Includes info re radiation releases into atmosphere & into Susquebanna River during first quarter of 1979 Affidavits & Certificate of Svc enci ZAHLER.R E Metropolitan Edison Co ZAHLER.R E Shaw, Pittman, Potts & Trowbridge 80/03/10 16pp
- 8004210235 Forwards licensee supplemental response to TMI Alert second set of interrogatories Responses to Interrogatories 17.21.22 & 33 have been treated as document requests ZAHLER.R C. Shaw Fittman, Potts & Trowbridge 80/03/10 2pp
- --B004210250 Supplemental response to second set of interrogatories
 Includes info re util mgt audit,TMI-1 operating & emergency
 procedures & names of all health physicists employed at
 TMI-1 Affidavit & Certificate of Svc encl
 ZAHLER,R E Metropolitan Edison Co ZAHLER,R E Shaw Pittman,
 Potts & Trowbridge 80/03/10 9pp
- 8004040229 Motion for extension until 800324 for depositions noticed on 800128 & until 800331 for depositions noticed on 800222 re restart proceeding License does not appose extension Certificate of 8vc encl ADLER, T A Three Mile Island Alert ADLER, T A Widoff, Reager, Belkowitz & Adler 80/03/11 3pp
- 8004080022 Memorandum & order re Chesapeake Energy Alliance 800213 omnibus motion filed in restart proceeding Certification to Commission will not be entertained absent extraordinary circumstances Funding denied Labeling sys granted partially SMITH, I W Atomic Bafety and Licensing Board Panel 80/03/ii 4pp
- 8004080425 Mution to compel UCS answer to Interrogatory 8-1 of licensee 800118 first set of interrogatories ra facility restart Licenses is ontitled to identification of alleged inadequacy re UCS Contention 8 W/supporting itr & Certificate of 8vc TROMBRIDGE.0 F Metropolitan Edison Co TROMBRIDGE.0 F Shaw, Pittman, Potts & Trombridge 80/03/11 8pp
- B0040B0720 Objections to intervenor BC Gholly fourth set of interrogatories & document requests Intervenor requests info not within scope of Contentions 15 & 16 Certificate of Bvc encl TROMBRIDGE.O F Metropolitan Edison Co TROMBRIDGE.O F, Shaw, Pittman, Potts & Trowbridge B0/03/11 12pp
- 8004110029 Objections to Interrogatory 179 of intervenor UCS second set of interrogatories Request for info re licensee hearing preparations is irrelevant to ultimate disposition of issues Certificate of Svc encl TROWBRIDGE, OF Metropolitan Edison Co TROWBRIDGE, OF Shaw, Pittman, Potts & Trowbridge 80/03/11 5pp
- 8004020044 First set of interrogatories directed to NRC Supplements SC Sholly 800117 interrogatories re restart proceeding Includes questions re quantity of radiation, adequacy of emergency plan & ingestion exposure Certificate of Svc encl SHOLLY.8 C Affiliation Unknown 80/03/13 7pp.
- 8004030170 Motion for emergency funding to continue depositions re restart proceeding Funding approved by Comptroller General Jan 1980 opinion Requests immediate certification to Commission Certificate of Svc Encl. ADLER.T A Three Mile Island Alert ABLER.T A Widoff, Reager, Belkowitt & Adler 80/03/19 3pp
- 8004100308 Objects to interrogatories included in intervenor Aamodt Contention 2 interrogatories, fourth set. Info requested is either beyond scope of Contention 2 or irrelevant to Contention 2. Certificate of Svc encl TROMBRIDGE, 0 F Metropolitan Edison Co TROMBRIDGE, 0 F Shaw, Pittman, Potts & Trombridge 80/03/13 8pp
- 8004100435 Objections to intervenor Aamodt Family 800222 second set of interrogatories Interrogatories 1-6 do not relate to Aamodt Contention 8 or any other contention accepted by ASLB ZAHLER, R E Metropolitar Edison Co. ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/03/13 Rep

- --8004100436 Objections to intervenor Aamodt Family 800222 third set of interrogatories Interrogatories [-7 relate to Aamodt Contention II I.rejected by ASLB ZAHLER,R E Metropolitan Edison Co ZAHLER,R E Shaw, Pittman, Potts & Troubridge 80/03/13 ip
- --8004100437 Objections to intervenor Aamodt 800225 sixth set of interrogatories Interrogatories 4-10 are unrelated to Aamodt Contention 10 or any other contention accepted by ASLB Certificate of Svc encl
 ZAHLER,R E Metropolitan Edison Co ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 80/03/13 App
- 8004080064 Forwards Reg Guides 1 134 & 1 145 in further response to document requests portion of intervenor second suppl to interrogatories to NRC staff Copy of MASH 1400 is on order & will be forwarded as soon as received W/o encl SOUDER, J L. Division of Rules and Records 80/03/14 1g
- 8004080678 Notice rescheduling licensee B00318 deposition to 800326 at OF Trowbridge ofc, Washington, DC, re restart proceeding Certificate of Bvc encl WEISS, E.R. Union of Concerned Scientists WEISS, E.R. Sheldon, Harmon & Weiss 80/03/14 3pp
- 8004100479 Objections to Chesapeake Energy Alliance first set of interrogatories Intervenor requests are irrelevant to ultimate disposition of issues Certificate of Svc encl TROMBRIDGE.0 F Metropolitan Edison Co TROMBRIDGE.0 F Shaw, Pittman, Potts & Trowbridge 80/03/14 14pp
- B004100563 Amend to notice of deposition Depositions of O Honderson, H Dougherty & T Gerusky, officials of Commonwealth of PA.will be taken on B00324 L Jackson will not be deposed BDMERG, J Anti-Nuclear Group Representing York B0/03/14 ip
- --8004100545 Intervenor response to first set of interrogatories Includes info re intervenor witnesses who will testify as to adequacy of licensee & govt emergency plans
 BOWERS.J Anti-Nuclear Group Representing York 80/03/14 ip
- --8004100567 Followsh interrogatories Includes info re 20-mile evacuation radius discussed by Chairman Hendrie on 790330 Certificate of Svc encl BOWERS.J Anti-Nuclear Group Representing York 80/03/14 2pp
- 8004080179 Forwards licensee responses to MI Lewis 800130 second set of interrogatories Affidavits for responses will be forwarded shortly ZAHLERRE Shaw, Pittman, Potts & Trowbridge 80/03/17 ip
- ~~8004080200 Response to second set of interrogatories includes info re history of incident Message Form R-72 entry in radiological data log book ZAMLER,R E Metropolitan Edison Co ZAMLER,R E Shaw, Pittman, Potts & Trowbridge 80/03/17 Spp
- 8004090281 Forwards licenses responses to intervener 800121 first set of interrogatories Affidavits will be forwarded shortly ZAHLER,R E Shaw, Pittman, Potts & Troubridge 80/03/17 ip
- --8004090283 Response to first set of interrogatories Includes info re gaseous & liquid effluent filtration devices & measures taken in response to NUREO-0560 reactor control room design criticisms ZAHLER.R E Hetropolitan Edison Co 80/03/17 13pp
- B004090289 Forwards licenses further response to BC Sholly 800104 first set of interrogatories Affidavits will be forwarded shortly ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/03/17 ip
- ---8004070275 Further response to first set of interrogatories Includes info re hydrogen control.ECCS flow rate use of radiation monitoring devices & health physics procedures ZAHLER,R E Metropolitan Edison Co ZAHLER,R E Bhaw, Pittman. Potts & Trowbridge 80/03/17 22pp
- 8004100279 Forwards licensee response to Sholly 800206 second set of interrogatories Afficavits for responses will be forwarded shortly ZAMLER,R E Shaw, Pittman, Potts & Trowbridge 80/03/17 ip
- ---8004100285 Response to second set of interrogatories Includes info re persons who contributed to licensee emergency plan & emergency plan accident classification sys ZAHLER:R E Hetropolitan Edison Co ZAHLER:R E Shaw, Pittman, Potts & Trowbridge 80/03/17 13pp

- 8004100476 Ack receipt of 800229 request to be informed when TMI refurns to operation ASLB will hold hearings re TMI-1 restart Hearings may commence during Summer 1980, but date of Commission final decision is not known SMITH.I W Atomic Safety and Licensing Board Panel 80/03/17
- --B004100478 Requests info as to when TMI will become operational again Author is General Public Utils stockholder SEKULA:P Affiliation Unknown 80/02/29 ip
- B004100539 Commonwealth of PA response to second set of interrogatories includes info me federal state & local emergency response plans Certificate of Svc encl CARTER.K W Pennsylvania. State of B0/03/17 33pp
- 8004100549 Response to third set of interrogatories includes info repersons responsible for internal security, security contracts & incident repts Certificate of Svc & RA Rice affidavit encl
 BLAKE, E.L. Metropolitan Edison Co BLAKE, E.L. Shaw, Pittman, Potts & Trowbridge 80/03/17 15pp
- 8004100562 Response to first set of interrogatories includes info re alleged inadequacy of natural circulation to remove decay heat Certificate of Svc encl HEISS, E.R. Union of Concerned Scientists WEISS, E.R. Sheldon, Harmon & Heiss 80/03/17 28pp
- 8004100566 Objections to Interrogatories 1.5 % 6 re intervenor TMI Alert.Inc seventh set of interrogatories Bocial security numbers of former employees deemed irrelevant Certificate of Svc encl BLAKE, E. L. Shaw. Pittman, Potts & Troubridge 80/03/17 5pp
- B004ii0175 Response to first set of interrogatories Includes info re potential for accidents at TMI-1 resulting from TMI-2 accident Centificate of Byc encl FOLLARDER O Chesapeake Energy Alliance B0/03/17 4pp
- 8004110516 Responds to PA Public Util Commission first set of interrogatories includes info re witnesses who will be called to testify by I(censee Certificate of Byc & attachment w/addl response encl TROWBRIDGE.0 F Metropolitan Edison Co TROWBRIDGE.0 F Shaw, Pittman, Potts & Trowbridge 80/03/17 27pp
- 8004110561 Forwards licensee response to TMI Alert Inc 800128 fifth set of interrogatories Affidavits for responses will be forwarded shortly BLAKE,E L Shaw, Pittman, Potts & Trowbridge 80/03/17 lpp
- --B004110567 Responds to fifth set of interrogatories includes info re independent contractors to perform maint repair & QA functions at TMI Certificate of Svc encl BLAKE.E.L. Metropolitan Edison Co BLAKE.E.L. Shaw, Pittman, Potts & Trowbridge 80/03/17 18pp
- 9004140074 Forwards Commonwealth of PA responses to intervenor interrogatories & document requests Objects to Interrogatory O8-009 & suggests redrafting Interrogatory O8-002 interpreted very narrowly CARTER, K # Pennsylvania, State of 80/03/17 2pp
- ---B004140077 Response to first set of interrogatories Includes info re communications links between state agencies, control room & omergency planning tone Affidavit of MA Reilly encl CARTER.K W Pennsylvania. State of B0/03/17 Spp
- --8004140080 Response to Aamodt second set of interrogatories Includes info re connection between incidence of hypothyroidism in PA & THI-2 accident ES Boudin, GK Tokuhata & MA Reilly draft affidavity encl CARTER, K W. Pennsylvania, State of 80/03/17 9pp
- --8004i40084 Becond response to first set of interrogatories Includes info re persons employed by Commonwealth of PA who were notified by licenses of TMI-2 accident Affidavit of JI Everly & Certificate of Svc encl
 CARTER
- 8004080676 Memorandum & order rejecting Chesapeake Energy Alliance 800213 late Contentions 14 & 15 NUREG/CR-1270 upon which contentions are based does not deal w/newly discovered info re human factors in control room design BMITH, I W Atomic Safety and Licensing Board Panel 80/03/18 5pp

- 8004080026 Memorandum & order shortening time for answering motions to compel discovery re restart proceedings to five days after svc of motion Requests for extension will be entertained. Time to answer motions served prior to order, shortened SHITH, I W Atomic Safety and Licensing Board Panel 80/03/19 3pp
- 8004090189 Motion to compel responses by licensee to fourth set of interrogatories & document requests Licensee 800311 objections attempt to carvo out scope of restart contentions Certificate of Evc enci
 SHOLLY, 8 C Affiliation Unknown 80/03/19 17pp
- 8004210403 Responses to Asmodt first set of interrogatories Includes info re agricultural emergency plans Affidavits & Certificate of Bov encil CARTER. K W Pennsylvania. State of 80/03/19 23pp
- 8004110077 Forwards licensee answer to SC Sholly Interrogatory 08-006, re restart proceeding ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/03/20 ip
- --B0041iOO81 Response to BC Sholly Interrogatory OB-OOA of first wet of interrogatories, re restart proceeding Sept 1979 accident classification sys,NUREO-OA10, has been adopted by licensee in emergency plan
 * Metropolitan Edison Co B0/03/20 5pp
- 8004110085 Response in opposition to 8C Sholly 800303 motion to compel answers to second set of interrogatories Theoretical assumptions underlying emergency plan impossible to document ove to reliance on thoughts rather than facts ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittmah, Potts & Trowbridge 80/03/20 9pp
- 800411010Q Responds to ASLB 800123 third special prehearing conference order requesting extent to which emergency plan has incorporated NUREO-037& Class 7 accident considerations Response to Sholly Interrogatory 08-006 provides info ZAHLER, R E Hatropolitan Edison Co ZAHLER, R E Bhaw, Pittman, Potts & Trowbridge 80/03/20 2pp
- 8004250069 Response in apposition to licensee objections to Aamodt 800225 third set of interrogatories Asserts that appropriate relationship exists between interrogatories & Contention 4 re restart proceeding AAMODT.N D Affiliation Unknown 80/03/20 2pp
- --B0042500Bl Response in apposition to licensee objections to Aamodt second set of interrogatories Challenges licensee assessment of radioactive matl quantities & licensee capability under projected waste mgt mechanisms

 AAMODT, N O Affiliation Unknown B0/03/20 ip
- --B004250075 Response in opposition to licensee objections to Aamndt interrogatories re Contention 4 Questions licensee refusal to disclose tests prior to Apr-May 1980 Requests permission to question employees re training W/Certificate of 8vc AAMODT,M M Affiliation Unknown 80/03/20 5pp
- B004020104 Suppl to NRC position on med to consider Class 9 events previously submitted in response to ABLB 791218 first special prehearing conference order SINCER.L N Hearing Branch 2 TOURTELLOTTE.J Hearing Branch 4. B0/03/21 ip
- --8004020107 Buppl to NRC 800131 position on need to consider Class 9 avents Bummarizes & discusses action plans & accident scenarios & measures Plans & recommendations for rulemaking will be placed before Commission W/Certificate of Svc SINGER.L N Hearing Branch 2 TOURTELLOTTE, J Hearing Branch 4 80/03/21 18pp
- B004090397 Advises of TMI Alert lack of financial resources to participate in restart proceeding Urges ABLB to use power & good ausgices in order to help provide funding permitting intervenor continued activity in discovery. Mysvc list.

 ADLER.T A Widoff Reager Belkowitz & Adler 80/03/21 3pp
- B004010287 Forwards Commission 800321 memorandum & order vacating part of ABLAB 791207 memorandum & order.ALAB-573.re consideration of Class 9 accidents' consequences W/o encl SINGER.L. N Hearing Branch 2 80/03/24 3pp.
- B004010315 Response in opposition to MI Lewis 800304 request to compel discovery Urges issuance of protective order re Interrogatories 14 & 18 Response to Interrogatory 15 re leak reduction will be prepared Certificate of Svc encl. SWARTZ.L.L Antitrust Division 80/03/24 6pp

- 8004010514 Response in opposition to UCS 800311 motion to compe) NRC answer Renews & confirms objections to Interrogatory 210 due to irrelevancy & under protection of Privacy Act NRC will proceed willtherrogatory 211 Certificate of Svc encl SWARTZ, L L Antitrust Division 80/03/24 App
- 8004100010 Motion to compel intervenor Environ Coalition on Nuclear Power to respond to licensee first set of interrogatories Although ASLB granted extension until 800317. Intervenor neither responded nor objected to interrogatories ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge 80/03/24 1p
- --B004100015 Mation to compel intervenor TMI Alert to respond to licensee 800114 first set of interrogatories Although ABLD granted extension until 800317 intervenor neither responded nor objected to interrogatories Cartificate of Bvc encl ZAHLER.R E Hetropolitan Edison Ca ZAHLER.R E Bhaw. Pittman. Potts & Trowbridge 80/03/24 4pp
- 8004100464 Forwards notarized, signed affidavits for "Licensee Response to Interrogatories (Fifth Set) of TMI Alert, Inc "
 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/03/24 13pp
- 8004230037 Clarification of intervenor 800304 suppl to umnibus motion Urges ASLB to grant financial assistance due to intervenor lack of resources to contribute effectively to psychological distress issue Certificate of Svc oncl
 POLLARD, R Q Chesapeaks Energy Alliance 80/03/24 4pp
- B004080630 Memorandum & order advising licensee that intervenor Aamodt B00321 pleadings should be treated as mations to compel discovery ra restart proceeding BMITH.I W Atomic Bafety and Licensing Board Panel B0/03/25 2pp
- 8004110157 Interrogatories directed to NRC re psychological distress issue.Contention 4 in restart proceeding Requests specification of NRC position.controversial aspect of contention & credibility of licensee POLLARD.R Q Chesapeake Energy Alliance 80/03/26 3pp
- --8004i10164 Interrogatories directed to licensee re psychological distress contention in restart proceeding Requests adoption of enci 800326 interrogatories directed to NRC POLLARD,R Q Chesapeake Energy Alliance 80/03/26 ip
- --8004110166 Interrogatories directed to State of PA re psychological distress contention in restart proceeding Requests adoption of encl 800326 interrogatories directed to NRC Certificate of Svc enci
 PULLARD, R Q Chesepeake Energy Alliance 80/03/26 2pp
- 8004080347 Discusses MI Lewis request for documents contained in 800215 further discovery & interrogatories Request for documents authored by RE Webb should be directed to author. CUTCHIN-J M Hearing Branch 3 80/03/27 2pp
- G004100492 Forwards FR notice of proposed rule, "Physical Protection of Plants & Matle:Access Controls to Nuclear Powerplant Vital Areas," & SECY 80-131, "Accident Considerations Under NEPA" BINDER:L. N. Hearing Branch 2. 80/03/27 Spp
- 8004i10095 Followon interrogatory directed to State of PA re restart proceeding Requests identification of all repts studies & documentation relied upon in State of PA response to Interrogary 23(b) Centificate of Svc ent
- 8004070011 Confirms that ASLB has granted extension until 800410 for NRC to respond to SC Sholly, UCB, Chesapeake Energy Alliance & other intervenors' interrogatories, Majority of answers will be filed on 800331 CUTCHIN. J M Hearing Branch 3 80/03/28 3pp
- 8004090403 Memorandum & order inviting parties to move for relief consistent w/Commission 800314 order & ASLB present interpretation of same order Correctness of Interpretation may be argued Motions must be filed within 5 days SMITH.I W Atomic Sefety and Licensing Soard Panel, 80/03/28 6pp
- 8004160131 Forwards People Against Nuclear Energy interrogatories to licensee Requests that interrogatories be served on those on eve list
 JORRANN B Sheldon, Harmon & Weiss 80/03/28 ip
- --8004i60138 Interrogatories to licensee Includes questions re intervenor Contentions 1 & 2,documents that licensee expects to introduce into evidence & licensee position on possible psychological distress caused by TMI-2 accident JORDAN, W S , SHELDON, K P People Against Nuclear Energy JURDAN, W S Sheldon, Harmon & Weiss. 80/03/28 9pp

- 8004230001 Response in apposition to intervenor Aamodt motions to compel Questions do not bear on Contention B Disclosure of tests re Contention 2 delayed W/util 800124 ltr & Certificate of Svc ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/03/28 iópp
- 8004230030 Response in opposition to UCS motion to compel licensee to answer Interrogatory 179 Elements of UCS contentions, re licensee position to be provided per motion, should be identified if ASLB grants motion Certificate of Svc encl TROMBRIDGE, 0 F Metropolitan Edison Co TROMBRIDGE, 0 F Shaw, Fittman, Potts & Troubridge 80/03/29 8pp
- 8004230097 Forwards affidavits re licensee further response to SC Sholly first set of interrogatories, response to Sholly Interrogatory 08-006 of first set & response to Sholly second set of interrogatories WCertificate of Svc ZAHLER, R C Shaw, Pittman, Fotts & Trowbridge 80/03/28 11pp
- 8004230127 Forwards RW Keaton affidavit re licensee response to MI Lewis second set of interrogatories ZAHLER, R E Shaw, Pittman, Potts & Troubridge 80/03/28 2pp
- 8004230131 Forwards RW Keaten & RL Long affidavits re licensee response to intervenor Anti-Nuclear Group Representing York first set of (Interrogatories ZAHLER: R E Shaw. Pittman, Potts & Troubridge 80/03/28 3pp
- 8004080004 Partial response to intervenor SC Sholly second set of interrogatories Addresses Interrogatories 01-005,07-003, OB-010 through 08-016,10-002 & 15-005 through 15-013 Affidavits, prof qualifications & Certificate of Svc encl CUTCHIN.J M Hearing Branch 3 80/03/31 47pp
- BOO4080045 Response to Chesapoake Energy Alliance Interrogatory 12-16 re BW analysis of integrated control sys Area of concern remultiple failure is relatively insignificant Affidavit & Centificate of Syc encl
 SINOER.L N Hearing Branch 2 BO/03/31 7pp
- ---B0040B0051 Response to intervenor Aamodt first & third through sixth sets of interrogatories Includes info re-monitoring programs; operator performance & incidents attributed to human errors Affidevits & Certificate of Bvc enci SHANBON, D T Hearing Branch 1 80/03/31 49pp
- 8004080056 Response to UCS first & second sets of interrogatories Includes bibliography of Class 9 accident studies & NRC position on UCS contentions Prof qualifications & affidavits encl
 SWARTZ,L L Hearing Branch | 80/03/31 99pp
- 8004100222 Memorandum & order directing NRC to specify & descibe encl accident sequences of NRC 800331 response to ABLB inquiry re Class 9 accident, in relation to restart proceeding Satisfactory answer should be filed within 15 days from svc LITTLE, L. W., JORDAN, R. H., BMITH, I. W. Atomic Safety and Licensing Board Panel 80/03/31 7pp
- 8004140004 Response to TMI Alert seventh set of interrogatories re restart proceeding Includes names & functions of maint & operations personnel OF Troubridge 800331 forwarding ltr to TA Adler encl BLAKE, E. Metropolitan Edison Co BLAKE, E. L. Shaw, Pittman, Potts & Troubridge 80703731 28pp
- --B004140007 Response to Asmodt family B00222 fourth set of interrogatories re restart proceeding Includes info re primary & backup communication sys in emergency plan GF Troubsridge B00331 forwarding ltr to MM Asmodt encl TRDWBRIDDC.G F , ZAMLER.R E Metropolitan Edison Co TROWBRIDDC.G F Shaw, Pittman, Potts & Troubsridge B0/03/31 Sps
- --B004140013 Response to Aamodt family 800225 sixth set of interrogatories re restart proceeding Includes into re routine & planned radioactive raleases per Tech Specs GF Trouberidge 800331 forwarding ltr to MM Aamodt encl TROUBERIDGE OF, ZAHLER.R E Metropolitan Edizon Co TROUBERIDGE, OF Shaw. Pittman. Potts & Troubridge 80/03/31 3pp
- --B004140017 Response to Newberry Township TMI Steering Committee 80021:
 first set of interrogatories re restart proceeding Includes
 info re selection of witnesses & licensee studies re
 emergency plan OF Trowbridge 800331 forwarding ltr ancl
 TROWBRIDGE, OF , ZAMLER, R E. Metropolitan Edison Co
 TROWBRIDGE, OF Shaw, Pittman, Potts & Trowbridge 80/03/31

- --B004140019 Response to UCS second set of interrogatories re-restart protecting includes info re-prevention of void formation & reduction of natural circulation loss GF Trowbridge B00331 forwarding itr to ER Weiss enci
- --8004140023 Response to Anti-Nuclear Group Responsenting York second set of interrogatories re restart proceeding Includes info re offsite emergency operations of a lactrical svc OF Troubridge 800331 forwarding 1tr encl TROMBRIDGE, G F , ZAMLEGAR E Matropolitan Edison Co TROMBRIDGE, G F , SAMLEGAR E Matropolitan Edison Co
- --800414002B Response in opposition to SC Shally 800321 motion to compet answers to certain of fourth set of interrogatories re restart proceeding Certificate of Svc encl RROWRIDGE, OF Metropolitan Edison Co TROWBRIDGE, OF Shaw, Pittman, Potts & Troubridge 80/03/31 20pp
- --8004140032 Motion to compel Chasapeake Energy Alliance answer to licensee 800118 first set of interrogatories he restart proceeding Intervenor 800317 responses are insufficient & incomplete Certificate of Svc encl
 TROWBRIDGE, 0 F Metropolitan Edison Co TROWBRIDGE, Q F Shaw Pittman, Potts & Trowbridge 80/03/31 23pp TROUBRIDGE, Q.F. Shaw,
- --8004140038 Response to MI Lewis third set of interrogatories re restart proceeding Includes info re selection of witnesses & background of MI Lewis & B Barley GF Troubridge 800331 forwarding ltr to MI Lewis encl TROUBRIDGE.0 F. ZAHLER,R E. Metropolitan Edison Co TROUBRIDGE.0 F. Shaw, Pittman, Potts & Troubridge 80/03/31
- --B004140045 Response to Aamodt family 800216 first set of interrogatories re restart proceeding Includes info re agricultural emergency plan & other related agricultural issues RE Zahler 800331 forwarding itr to MM Aamodt encl TROMBRIDGE OF F. ZAHLER R E. Metropolitan Edison Co TROMBRIDGE OF F. Shaw, Pittman, Potts & Trowbridge 80/0 80/03/31
- --8004140051 Response to MI Lewis fourth set of interrogatories re restart proceeding Includes info re pathway analyses & radwaste gas sys drawings OF Trowbridge 800331 forwarding ltr to MI Lewis encl TROWBRIDGE, OF, ZAHLER, RE Metropolitan Edison Co TROWBRIDGE, OF, Shaw, Pittman, Potts & Trowbridge 80/03/31
- ---8004140057 Response to AA Aamodt 900225 fourth set of interrogatories re restart proceeding Includes info re training in basic heat transfer, fluid flow & thermodynamics Supporting documentation & GF Trowbridge 800331 ltr encl TROWBRIDGE, GF F Shaw, Pittman, Potts & Trowbridge 80/03/31 3App
- ---B004140062 Response to Chesepeake Energy Alliance first set of interrogatories Includes info re description of present radicactive water storage & methods of decontamination OF Trowbridge B0033i forwarding ltr to RG Pollard enc! TROWBRIDGE, O F. Metropolitan Edison Co. TROWBRIDGE, O F. Shaw, Pittman, Potts & Trowbridge 80/03/31 30pp.
- --8004140065 Supplemental response to PA Public Util Commission first set of interrogatories re restart proceeding Includes into re decontemination & restoring during operation Affidavits, GF Troubridge 800931 Forwarding itr & Certificate of Svc encl TROMBRIDGE, 0 F Metropolitan Edison Co. TROMBRIDGE, 0 F Shaw, Troubridge 80703731 179p.

- 8004080019 Response to intervener SC Sholly first set of Outpourly response to intervenor at anothy first set or interrogatories includes info re radioactive release as result of containment isolation failure & other related matters Affidavits & prof qualifications encl CUTCHIN.J M Hearing Branch 3 80/04/01 16pp
- --8004080025 Response to intervenor Anti-Nuclear Orgus Representing York NHOBOUSES RESPONSE to Intervenic Anti-Notizer Group Represent follow-on interrogatories filed as result of NRC answer to Interrogatory 4 Addresses evacuation radius stated by Chairnan Hendrie Affidavit & Certificate of Svc encl SINGER, L N Hearing Branch 2 80/04/01 5pp
- 8004080579 Hemorandum advising that ASLB is in process of selecting map & overlays depicting TMI vicinity, to be presented as exhibit in restart proceeding ASLB member LW Little & NRC employee Q LaRoche will select appropriate map features SMITH.1 N Atomic Safety and Licensing Board Panel 80/04/01 4pp
- 8004080586 Hemorandum & order compelling UCS to answer licensee 800118 Interrogatory 8-1 re UCS Contention 8 challenging analysis required for ECCS performance Grants 20-day extension after svc of present order; for UCS to comply w/ASLB directive SMITH, I W Atomic Safety and Licensing Board Panel 80/04/01 7pp
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICKL V Office of the Executive Director for Operations З4рр
- 8004100018 Memorandum & order denying UCS 800324 motion to compel licensee answer to Interrogatory 179 re restart proceeding Interrogatory is broad & premature SMITH.I W Atomic Safety and Licensing Doard Panel 80/04/02 3pp
- 8004100021 Memorandum & order directing NRC to delete confidential info from original record & to provide rest of info in response to UCS Interrogatory 210 re restart proceeding Recommends that NRC & UCS confer re Interrogatory 211 SHITH.I W Atomic Safety and Licensing Board Panel 80/04/02 7pp
- 8004100024 Memorandum & order re SC Sholly 800303 motion to compel licenses answers Response to Interrogatory 08-006 is responsive to Interrogatory 08-019 Enforcement of SC Sholly Interrogatory 08-024 is declined BHITH.IW Atomic Safety and Licensing Board Panel 80/04/02 2pp
- 8004100304 Memorandom & order re Lewis 800304 motion to compel NRC answers to Interrogatories 14.15 & 18 Denies motion re Interrogatory 18 NRC 800324 answers sufficient re Interrogatory 14 Interrogatory 15 is not answerable SMITH, I W Atomic Safety and Licensing Board Panel 80/04/02 80/04/02 2nn
- 8004220011 Response to ASLB 800325 memorandum & order, stating objective of intervenor discovery & deposition program Prospected info will spotlight licensee internal weakness Participation in future depositions uncertain Certificate of Svc encl ADLER, T A Three Mile Island Alert 80/04/02 3pp
- 8004300001 Discusses preparation for 800410 meeting w/USQS re charting of amergency planning maps for TMI-1 restart hearings Forwards lists of relevant items in emergency planning assessment of area LITTLE: L W Atomic Safety and Licensing Board Panel 80/04/02
- ~-8004300005 Confirms 800331 notification of 800410 meeting w/USGS in Reston.VA re USGS production of maps for TMI-1 hearings in June or Jul 1980 USGS land use list encl LAROCHE.Q Environmental Specialists Branch 80/04/01 2pp
- 8004100589 Response to ASLB 800325 memorandum & order ASLB does not have authority to order NRC to take depositions on behalf of ASLB & intervenor TMI Alert ASLB proposed action is impractical & intervenor deposition program repetitive SNANSON,D T Hearing Branch 1 SINGER,L N Hearing Branch 2 SNANSON,D T Hearing Branch 2 13pp 80/04/03
- 8004210114 Hemorandum & order re Lewis 800319 motion to compel NRC to answer interrogatories Declines to enforce Interrogatories 23,24,25,29,30 & 37 Interrogatories 27 & 28 will be answered by NRC May submit substituted Interrogatory 31 SMITH, I W Atomic Safety and Licensing Board Panel 80/04/03 4pp.
- 8004210421 Comments on ASLB 800325 order re adoption of TMI Alert DMEZUMEL Comments on ASLB 800325 order re adoption or deposition program concerning util mgt & financial compatence Question re whether depositions have been productive should not be addressed by licensee TROMBRIDGE.OF Metropolitan Edison Co TROMBRIDGE. Pittman, Potts & Trowbridge 80/04/03. App TROWERIDGE, OF Shaw.

- 8004250053 Petition for addition of new contention Hany sys have had to operate unattended at THI-2 for over a yr Same sys must be qualified at THI-1 to operate unattended for similar period Svc list encl LEMIS,M I Affiliation Unknown 80/04/03 2pp
- 8004150176 Interim memorandum & order directing licenses to answer Interrogatory 16 of Aamodt 800225 fourth set of interrogatories, re Contention 2 in restart proceeding SHITM, I W Atomic Safety and Licensing Board Panel 80/04/04 lp
- 8004240176 Memorandum stating practicality of issuing no ruling re Aamodt family request to depose State of PA officers, due to PA offer of continued voluntary responses Informal ASLB 800229 fourth special probearing order not changed SMITH, I W Atomic Safety and Licensing Board Panel 80/04/08 2pp
- B004210094 Hemorandum A order re Aamedt Family 800320 motions to compel licensee response to discovery requests Licensee not required to answer Contention 8 re raduaste SMITH, I V Alomic Safety and Licensing Board Panel 80/04/09 9pp
- 8004150273 Add1 response to SC Shaily second set of interrogatories Answers interrogatories 14-003.14-004.14-005 & 16-004 Includes statements re NUREO-0616 Affidavits.profqualifications & Centificate of Svc encl CUTCHIN.J M Hearing Branch 3 80/04/11 11pp
- 8004150499 Forwards adjudicatory hearing stipulation of settlement document re NPDES Permit 0009720 HERBEIN, J G Metropolitan Edison Co B0/04/11 App
- 8004230115 Memorandum A order directing TM1 Alert to respond to licensee 800114 first set of interrogatories within 10 days from svc Answers are essential for licensee litigation of intervenar contentions SMITH, I W Atomic Safety and Licensing Board Panel 80/04/11 3pp
- B004170055 Response in opposition to Lewis B00403 petition for addition of new contention No new allegation advocated due to coverage by UCS Contention 12 Certificate of Svc encl CUTCHIN.J M. Hearing Branch 3. 80/04/14. 4pp
- 8004170058 Motion for extension until 800401 to respond to ASLB 800331 memorandum % order requesting further supplementation re Class 9 accidents involvement in safety evaluation publication will dolay answer Certificate of Svc encl SINDER.L N Hearing Branch 2 80/04/15 Spp
- BOO42B0356 Ack receipt of BOO326 interragatories Until ASLB rules on whether psychological stress issues will be heard in praceeding, NRC is rejuctant to initiate review or analysis SWARTZ, L. Hearing Branch 1 BO/04/15 ip
- BOO4280398 Ack receipt of People Against Nuclear Energy 800331 interrogatories Since ASLB has not rolled on psychological distress issue.NRC is reluctant to initiate review or analysis of issue at this time BWARTZ.L L Hearing Branch 1 80/04/15 ip
- 8004220291 Reminds of B Pollard commitment during 800411 deposition to inform NRC if discussion in NUREG-0640, Draft 3. Yask IID, satisfies UCB Contention 6
 SHANSON, D T Hearing Branch 1 80/04/18 ip
- 8004250373 Requests review & reconsideration of 800407 Director's decision under 10CFR2 206 denying 800225 petition Interests of public health demand that cleanup be started at facility GARY.R Affiliation Unknown 80/04/18 2pp
- 8004280249 Advises of intention not to respond to Aamodt 800407 request for further extension of time re State of PA deposition, unless advised to contrary ASLB 800229 memorandum disposes of matter SWANSON,D T Hearing Branch I 80/04/24, 1p.
- H General correspondence
- 8004020227 Responds to 790919 ltr expressing concern re NRC participation in decision to place reactor in operation & NRC monitoring activities of reactor const Beyond licensing requirements, commercial operation is corporate decision VOLLMER.R H TMI-2 Operations/Support 80/02/05 2pp
- --B004020234 Expresses concern re NRC participation in decision to place reactor in operation & NRC monitoring activities of reactor const. Ltr of 791024 to Met Ed expressing concern re Unit 1 restart encl EDMONSON, L. D. Affiliation Unknown 79/09/19 6pp

- 8004030123 Responds to 790816. Lit is plans to reopen TMI-1, nuclear plant const in NJ % nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info replants in NJ No diseases resulted from TMI DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030129 Opposes restait of TMI-1.const of nuclear plants in NJ & nuclear accidents due to health hazards & 1187s to public safety
 FOSTER,K Affiliation Unknown 79/08/16 2pp
- 8004180109 Responds to encl ltr to President Carter re restart of THI-1 Util lequest to restart TMI-1 is sobj of public hearing, not expected before early part of 1981 INGRAM, F Office of Public Affairs 80/03/05 2pp
- 8004210108 Responds to 800108 ltr re boron dilution errors % spent fuel cask drop evaluation Provisions to protect against accidental boron dilution are acceptable Fuel shipment not anticipated for at least one yr after startup REID,R W Operating Reactors Branch 4 80/03/12 ip
- 8004220019 Forwards ST Ament 800219 ltr urging restart of facility Requests NRC findings 5 views STONE.R Senate 80/03/14 2pp
- 8004020112 Responds to 800227 itr re util financial situation NRC does not regulate electrical util rates Licensing board hearing will determine whether Unit 1 can safely resume operation during Unit 2 cleanup GILINSKY, V Commission 80/03/19 2pp
- --8004020114 Discusses concerns re util financial situation Development of nuclear power should not be blocked GUISENBERRY.G F Affiliation Unknown 80/02/27 2pp
- 8004040002 Responds to General Public Utils stockholder re financial concern for restart of plant site NRC is conducting hearing before Licensing Board to determine whether Unit 1 can restart while cleanup begins at Unit 2 OILINSKY, V Commission 80/03/19 lp
- ---8004040004 Requests restart of unit because dividends are needed & nuclear power is needed until some other source of power is found if util goes bankrupt.NRC is to blame BAKER.R G Affiliation Unknown 80/03/12 ip
- 8004180113 Ack receipt of 800312 ltr concerning financial situation of util NRC does not regulate rates charged by utils Main concern of NRC is regulation of safety of nuclear reactors OILINSKY, V Commission 80/03/19 ip
- --8004180120 Requests assistance of NRC in restoring financial integrity to util Util presently close to bankruptcy because of financial burden of TMI accident LAMBON.J D Affiliation Unknown 80/03/12 2pp
- BOO42103Bi Responds to ltr re permanent shutdown of facility, cleanup of waste & payment of expenses concerning accident Dry wastes are packed in steel drows & shipped to burial sites Util customers do not pay for facility restoration DENTON, H R Office of Nuclear Reactor Regulation 80/03/19 200
- BOO-mazured responses to //ooi/ its seconts severy errors being made to protect public health % safety at all nuclear power plants currently operating or planned for operation Restart hearing has not yet begun
 DENTON, HR Office of Nuclear Reactor Regulation 80/03/19 ip
- --8004220171 Requests adherence to regulatory directives
 FH1LL[P8,L B , PH1LL[P8,V Affiliation Unknown 79/06/17 ip
- 8004240441 Responds to 790815 ltr expressing concern re pollution of environ by use of EPICOR-II sys Bys will clean water in auxiliary bldg to extent that no further risk will be posed Environ assessment will be issued prior to disposal DENTON.H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- --8004240447 Expresses concern re plans for disposal of contaminated water at TMI-2 Use of EPICOR-II sys will pollute environ & expose workers to radiation GILBERTIR S Affiliation Unknown 79/08/15 ip

- Table 11 People's to the tree trees and the leading of reduce to the party to the trees of the t
- in 12701A4 Neap nds to 7% involte to INV re facility occident in Hay 1477 NC atrotted resident inspector program inspectors are presently assigned to approx TO sites Nuclear plants are equipped unincerous alarms to automatic shutdown equipment CENTON HAR Universe of Nurlear Reactor Regulation BO/03/19 Spp.
- r 04290076 Responds to life re disposal of radioactive water from TMI-2 Release of unitarinated water into Susquehanna River is not currently permitted except for liquids containing low or randetectable levels of radioactivity

 CENTCY H P Office of Nuclear Reactor Regulation 80/09/19 2pp
- E./J4270CBB Opposes releases of ladicactive water from THI-2 into Eurquehanna River NRC is tiging to sale nuclear industry w/o regard to inferests of public ERGULE, M. Affiliation Unixoln 80/03/19 lp
- COJO20117 Hesponds to 800_03 ltr requesting info re application of THI-2 Lessons Learned Task Force to facility & certain other plants under const NTIS should be contacted for SER info ASLB proceedings announced in FP VARCA S A Assistant Director for Light Water Reactors 80/03/22 2pp
- GOO4250332 Ad ises that response to inquiry re plants under const will be provided in SERs which will include TMI-2 Lessons Learned Task Force findings Forwards Commission order defining TMI-2 review parameters & MAC ltr to all BNN reactors. W/o encis VARDA S.A. Assistant Director for Light Water Reactors. GO/03/22 2pp
- 8004210356 Responds to 750904 ltr re release of Kr-851 from facility Util 'Safety Analysis '2 Environ Rept' states that optimum choice for release of Kr-851 is atmospheric dispersion through controlled purging or reactor bidg atmosphere DENION: H R Office of Nuclear Reactor Regulation 80/03/24 2pp
- --8004210360 Opposes reopening of facility & release of Kr-85 into atmosphere Requests plans for disposal of waste LEONARD, J. Affiliation Unknown 79/09/04 ip
- 6004210363 Responds to ltm re holding of public hearings on facilities Commission has ordered that public hearing be conducted to determine whether Unit I should be operated Hill conduct review or technical info on restart DENTON HR Office of Nuclear Reactor Regulation 80/03/24 2pp
- --8004210373 Expresses conviction that public hearings must be held in communities within 25-mile radius of facility site LYON5.E Affiliation Unknown 79/07/23 2pp
- BOO4280342 Responds to 791630 ltr to NRC re IMI NRC has ordered public hearing to determine whether TMI-1 should be restarted Licensee authority to operate Unit 2 was suspended by NRC 790720 order DENTON.H R Office of Nuclear Reactor Regulation 80/03/24 2pp
- --8004280350 Oppuses reoponing of TMI due to health hazard posed to area residents Requests info re plans to dispose of radioactive water which flooded reactor Hater may freeze in winter & burst containment walls

 GAMBING.M Affiliation Unknown 79/06/30 4pp
- 8004100047 Forwards Commission 790809 order & notice of hearing for restart of facility in response to 800317 telcon VOLLMER,R H TM1-2 Operations/Support 80/03/25 1p
- B004110571 Forwards MASH-1400 "Reactor Safety Study, Assessment of Accident Risks in US Commercial Nuclear Power Plants," & listed appendices to rept All dacuments identified in second suppl to interrogatories to PRC have now been sent SAUDER. J L Division of Rules and Records B0/03/26 2pp
- B004100574 Responds to 790615 ltr restart up of reactor Both Units 1 & 2 shut down Unit 2 where accident occurred will be shut down for some time NRC hearings to ascertain safety of Unit 1 will be conducted before startup DENTON: H R Office of Nuclear Reactor Regulation 80/03/27 1p

- --B004100578 Requests into re-stailing of Unit 1 NRC should be investigating competence of util to have reactor license Presidential Commission rept should be studied Questions NRC concern for safety HOSTETTER. J.J. Affiliation Unknown 19/06/15 (p.
- BOOA090357 Urges NRC to provide educational matis in effort to educate public on nuclear energy Educated public is only way for fair decision re future of nuclear energy, restart of TMI-1 & cleanup of TMI-2 SNYDER,M O Affiliation Unknown 80/03/31 2pp
- GOO4180114 Responds to GOO228 itr regarding entl A & D Thompson ltr of concern re delay in restart Commission /90809 ander identifies items that must be resolved prior to restart Timb needed to resolve items will Jelay restart until late 1900 pIRCKS, N J Office of the Executive Director for Operations 80/03/31 5pp
- BO04220173 Ack receipt of ltr re financial situation of Ogneral Public
 Utils NRC does not requiate rates charged by electrical
 utils NRC is conducting hearing to determine whether THI-1
 can be restarted while TMI-2 cleanup proceeds
 QILINSKY,V Commission BO/04/02 ip
- --8004220181 Urges NRC to expedite rate relief requested by General Public Utils & return TMI-1 to svc Unfair treatment accorded to General Public Utils has encouraged demonstrators LESH.L Affiliation Unknown 80/03/24 2pp
- BOO4290049 Responds to 790823 itr re nuclear fission & biological effects of radiation FPA.Occupational Safety & Health Administration & NRC are responsible for regulating exposure to radiation or radioactive mat!

 DENTON.H R Office of Nuclear Reactor Regulation BO/04/03 2pp
- 8004100504 Opposition to TMI-I restart People who live in vicinity of TMI live in constant dread NRC personnel do not have to share danger of living close to plant Chances of nuclear accident greatly underestimated by util & NRC KAUFMANN-D H Affiliation Unknown 80/04/09 3pp
- 8004150478 Forwards updated svc copy distribution list for facilities Notifies that GK Hovey has replaced RF Wilson as director of Unit 2 ARMIDLD R G Hetropolitan Edison Co 80/04/10 5pp
- 8004280384 Ac) receipt of 800308 ltr expressing concern re delay in placing TMI-1 back in svc Based on 790809 shutdown order 8 current status of proceedings, restart not possible until searly 1991
 DENTON, H R Office of Nuclear Reactor Regulation 80/04/14 ip
- ~-8004280389 Requests immediate restart of unit Delay could cause serious economic dislocations & creats political imbalance Draft Ofc of General Counsel reply encl YOUNG,D W Affiliation Unknown 80/03/08 Epp
- ! Financial information
- B004030241 Forwards update to util B00219 ltr re projected 1980 cash flow forecast reflecting recent rate relief Company is able to meet max retrospective premium HERBEIN.J G Metropolitan Edison Co B0/03/31 3pp
- 8004090477 Forwards supplementary financial info in support of TMI-1 restart proceedings
 HAFER, F. D. General Public Utilities GPU Service Corp. 80/04/03 140pp
- --8004090478 Transcript of PA Public Util Commission 800213 hearing in Harrisburg.PA Pp 1, 7463-2, 149 SHANAMAN.S Pennsylvania, State of Ryan. Russell & McConaghy 80/04/03 182pp
- --8004090479 Transcript of PA Public Util Commission 800227 hearing in Harrisburg,PA Pp 2, 494-2,527A SHANAMAN,S Pennsylvania, State of Ryan: Russell & McConaghy 80/04/03 37pp
- ---8004090480 Transcript of PA Public Util Commission 800228 hearing in Harrisburg,PA Pp 2: 528-2:682 SHANAMAN, & Pennsylvania. State of Ryan, Russell & McConaghy 80/04/03 RUSSELL. & B , SELTZER. A M 156p
- --800407048: Transcript of PA Public Util Commission 800318 hearing in Harrisburg, PA Pp 3. 217-3, 419 SHANAMAN, S Pennsylvania, State of Ryan, Russell & McConaghy 80/04/03 204pp

- --8004090482 Annual Financial Rept 1979

 * General Public Utilities GPU Service Corp * Jersey Central
 Power & Light Co * Metropolitan Edison Co 80/04/03 44pp
- --8004090483 "Proposel to Conduct Analysis of Strategic Options for JCP&L" * Arthur Young & Co. 80/02/29 125pp
- --B004090484 "TM]-2 Coal Burning Plant Summary of Study of Converting TMI-2 to Fossil-Fueled Plant "
 Gilbert/Commonwealth Cos B0/02/25 13pp
- 8004280630 Forwards Met Ed certified Annual Financial Rept 1979 & General Public Utils Corp certified Annual Financial Rept 1979 & certified "Uniform Statistical Rept.1979" HERBEIN.J G Metropolitan Edison Co 80/04/22 1p
- --8004280633 Certified Annual Financial Rept 1979 * Metropolitan Edison Co 80/03/07 27pp
- ---8004280638 Certified Annual Financial Rept 1979 Certified "Uniform Statistical Ropt.1979" encl * General Public Utilities - OPU Service Corp 80/04/22 7ipp
- P Operating license stage documents & correspondence
- 800404005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800206 reactor trip at Crystal River Sequence of events & planned corrective actions also enci DENTON: H R Office of Nuclear Reactor Regulation 80/03/06 26pp
- BOO4080121 Forwards NRC/TMI weekly status rept Liquid effluents from TMI-1 released to Susquehanna Rivor, after processing were within limits specified in Tech Specs No liquid effluents were discharged from TMI-2 COLLINGIJ T TMI-2 Operations/Support 80/03/11 4pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENNUT.D O Division of Operating Reactors 80/03/12 5pp
- --B004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors \$0/02/21 28pp
- BOO4070141 Notification of BOO321 meeting w/util & NRC consultant, R Mittelstaedt, in Bethesda, MD to discuss TMI-1 restart SILVER, H NRC Three Milo Island Task Force 80/03/13 ip
- 8004030230 Notification of 800318 meeeting w/all operating 85W reactor licenses in BothesdarMD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID: R W Operating Reactors Branch 4 80/03/14 2pp
- 8004020067 Confirms 800305 teleon re regulatory requirements for portable radiation survey meter calibr recall sys. Proposed radiation protection plans will specify min frequencies for portable survey meter calibr COLLING.D M Division of Site Bafety & Environmental Analysis 80/03/17 1p
- 8004170294 Forwards suppl to safety evaluation re Amend 46 to License DPR-50 REID:R W Operating Reactors Branch 4 80/03/23 4pp
- --8004170300 Buppl to safety evaluation supporting Amend 46 to License DPR-50. increasing frequency for performing heat balance checks of out-of-core detectors
 * Operating Reactors Branch 4 80/03/26 4pp.
- 8004010412 Advises that Met Ed response to Item 3 of NRC 790814 ltr will be included in revised study on degraded grid, to be submitted on 800415 HERBEIN J. G Metropolitan Edison Co 80/03/28 ip
- 8004070284 Responds to NRC 791030 ltr & 800306 telcon inquiry re IOSCC investigation Forwards item-by-item response to NRC 791030 ltr.describing changes to investigation & repair program MERBEIN-J O "Metropolitan Edison Co 80/03/31 4pp
- --B004070285 Revision 2 to "Qas Tungsten Arc Shielded Metal Arc Welding of Stainless Steel in Borated Water Piping Sys" re ID weld clad procedure * Metropolitan Edison Co 79/12/04 5pp

- 8004070290 Forwards Tech bpec Change Request 618 to App A of License DPR-50 HERBEIN, J G Metropolitan Edison Co 80/03/31 ip
- --8004070291 Application to amend App A of License DPR-50 per Tech Sper Change Request 61B HERBEIN J G Metropolitan Edison Co 80/03/31 1p
- --8004070306 Tech Spøc Change Request 618 to App A of License DPR-50 re mods to high pressure injection sys to ensure min acceptable flow through each leg should one pump fail # Metropolitan Edison Co 80/03/31 4pp
- 8004070318 Advises that capacity of approx 160,000 gallons of Unit 2 water will be maintained by one reactor coolant bleed holdup tank in each unit Tanks will remain empty.per NRC requirements
 WILSON.R F Metropolitan Edison Co 80/03/31 ip
- 8004070319 Forwards Tech Spec Change Request 77A to App A of DPR-50 HERBEIN, J G Metropolitan Edison Co 80/03/31 ip
- --8004070323 Application to amend App A of DPR-50 per Tech Spec Change Request 77A HERBEIN J O Metropolitan Edison Co 80/03/31 1p
- --8004070325 Tech Spec Change Request 77A to App A of DPR-50 re revision of tendon surveillance to reflect Reg Guide 1 35.Revision 3 requirements & to delete ring girder surveillance program # Metropolitan Edison Co 80/03/31 10pp
- B004080560 Responds to NRC 800223 ltr re overpressurization & rupture of low pressure injection sys low pressure piping due to failure of redundant check valves to act as pressure isolation barrier

 MERBEIN-J G Hetropolitan Edison Co 80/03/31 2pp
- 8004080703 Forwards Tech Spec Change Request 90 to temporarily amend License DPR-50 Cortificate of Svc encl HERBEIN, J O Metropolitan Edison Co 80/03/31 1p
- --8004080707 Application to temporarily amend License DPR-50 per Tech Boec Change Request 90 HERBEIN J G Metropolitan Edison Co 80/03/31 2pp
- --8004080716 Tech Spec Change Request 70 reported for Cycle & refueling Page 4-59 Change would be deleted upon completion of Cycle 5 * Metropolitan Edison Co 80/03/31 2pp
- 8004110471 Notifies NRC that as of 800326, approx 160,000 gallons of shielded storage capacity for TMI-2 water will be maintained by reactor coolant bleed holder tank IA of Unit 1 & IA of Unit 2 Util 800328 memo re TMI-1 bleed tanks encl WILSON,R F Metropolitan Edison Co 80/03/31 2pp
- 8004110395 Responds to 800307 ltr re reactor bldg spray sys Evaluation determined that by eliminating sodium thiosulfate tank & adjusting sodium hydroxide tank concentration & level, sys can maintain spray ph between 8 5 & 11 O
 HERBEIN, J G Metropolitan Edison Co. 80/04/07 in

- 9904150749 Forwalls when 114 to Restart Rept " HERBEIN, J.G. Metropolitan Edison Co. 80/04/11 1p
- --6004150351 "Arend to to hestart Rept, providing add1 info re plant ◆ Metropolilan Edison to 60/04/11 54pp
- 8004150446 Forwards nods to encl pernits / certificates for environ protection in response to NRC 800125 request HERBEIN J.G. Metropolitan Edison Co. 80/04/11 122pp
- 8004220223 Forwards Tech Specs Change Request 92 Certificate of Svc 5 fee encl HERBEIN, J G Metropolitan Edison Co 80/04/11 2pp
- --BC04220224 Terh Specs change Pequest /2 revising Page 3-80 re location of temp detectors in reactor bldg
 HERBEIN J G Hetropolitan Edison Co 80/04/11 3pp
- 8004220542 Forwards application to amend License DPR-50.App A, consisting of Tech Spec Change Request 9! Fee encl HERBEIN, J.G. Metropolitan Edison Co. 80/04/11 2pp
- --8004220545 Application to arend License DPR 50, App A, consisting of Tech Spec Change Pequest 91 # Metropolitan Edison Co 80/04/11 ip
- ~~8004220552 Tech Spec Change Pequest 91 replacing Pages 4~11,12,13,13a & 27a re RCS inservice insp to provide interim measures for irradiation of one reactor vessel matl survesilance capsule in Crystal River Unit 3 reactor

 * Metropolitan Edison Co 80/04/11 6pp
- HCCC4150281 Forwards corrected Page 2 1-45, Amend 13, to restart rept. describing short-term mods

 * Metropolitan Edison Co 80/04/14 1p
- --BOO4150287 Corrected Page 2 1-45, Amend 13, to restart rept. describing short-term mods

 → Metropolitan Edison Co 80/04/14 1p
- 4004170104 Forwards Amend 17to Restart Rept." App 7A Revision 2 to radiation protection plan
 HERBEIN.J G Metropolitam Edison Co 80/04/14 1p
- --BOD4170106 Amend 17 to 'Restart Rept.' App 7A.Revision 2 to radiation protection plan
 MERBEIN, J G , POTTS, W E Metropolitan Edison Co 80/04/03 24pp
- 8004210335 Forwards Susquehamna River data in response to NRC 800407 SKINNER.W F Pennsylvania Power % Light Co 80/04/15 ip
- --8004210344 "Potential Effects of Brunner Island Steam Electric Station on Future Migrations of American Shad in Susquehanna River " # EC / G. Inc 77/08/13 23pp
- --8004210347 "Probabilities of Normal & Worst Case Conditions in Susquebanna River during Critical Periods for Muskellunge Spauning & Smallmouth Bass Egg Survival & Development " * EO & G, Inc 77/09/15 lápp
- --8004210349 "Assessment of Thermal Effects from Brunner Island Steam Electric Station Based on Newly Derived Max Weekly Average Temps " * EQ & G, Inc 79/05/31 33pp
- -~8004210355 "Ecological Study of Effects of Brunner Island Steam Electric Station Cooling Water Intakes" JOHNSON.T D Roy F Weston.Inc 77/11/19 78pp
- --8004210358 "Biological Survey of Susquehanna River in Vicinity of York Haven,PA 1978 Terminal Rept ' WURTZ,C B Charles B Wurtz 79/06/29 33pp
- --8004210366 "Ichthyafauna) & Creel Census/Fishing Pressure Surveys in Vicinity of Brunner Island Steam Electric Station "
 DENONCOURT, R F R F Benoncourt 78/05/34 16ipp

- 8004220654 Forwards list of outstanding Tech Spec change requests % respective submittal dates Requests review of list % status rept for each item HERBEIM J G Metropolitan Edison Co 80/04/15 3pp
- 8004250367 Requests withdrawal of Tech Spec Change Request 88 for potential effects of atquical weld wire temp limits to reflect potential effects of atquical weld wire possibly used in vessel fabrication Existing pressure-temp limits acceptable HERBEIN, J G | Hetropolitan Edison Co | 80/04/18 | 19
- Q Inspection reports, IF Bulletins & correspondence
- 800421G097 Forwards IE Insp Repts 50-320/79-30 & 50-289/79-24 pm 791128-B00104 No noncompliance noted GRIER.B H Region 1: Philadelphia. Office of the Director B0/02/28 2pp
- --8004210102 JE Insp Repts 50-320/79-30 % 50-289/79-24 on 791128-800104 Major areas inspected licensee action on previous inspected licensee action on previous inspected from the findings, new & revised recovery procedures, plant operations, plant tours & status meetings MARTIN.T T. PLUMEE, N E. YUHAS, O P. Region 1, Philadelphia, Office of the Director 80/02/26 7pp
- 8004070013 Responds to IE Builetin 77-27 to loss of non-Class IE instrumentation % control power sys bus during operation Mod to intercommunication sys is being made to ensure prompt action Kanual transfer contractors will be provided HERDEIN. J G Metropolitan Edison Co 80/02/27 2pp
- 8004210115 Forwards Waste Packaging Insp Rept 79-06A on 791126-20 No noncompliance noted sance noise H. Region 1, Philadelphia, Fuel Facility & Materials Bofsty 80/03/05 2pp
- --B004210120 Waste Packaging insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & placarding requirements rediation levels removable contamination & package oxternal feature requirements POTTER.JP. BROWN.R A Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 79/12/12 7pp
- 8004070409 Ack receipt of 800118 % 791211 Itrs informing NRC of steps taken to correct violations noted in IF Insp Rept GRIER, B H Region i, Philadelphia, Office of the Director 80/03/07 ip
- --8004070416 Responds to NRC 791115 ltr re violations noted in IE linep Rept 50-289/78-18 Corrective actions evaluation of extremity dose to whole body dose ratios in progress Extension until 791231 requested HERBEIN, J 0 11e Netropolitan Edison Co 79/12/11
- --8004070420 Ack review of corrective action & advises that corrected termination itrs sent to affected individuals
 ARNOLD,R C Metropolitan Edison Co 80/01/18 1p
- 8004020054 Forwards response to IE Bulletin /9-01B re environ qualification of Class IE equipment Provides master list of abettrical components Will submit qualification data within 45 days after master list submitted HERBEIN.J 0 Metropolitan Edison Co BO/03/11 33pp
- 8004070219 Responds to IE Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Buriai " Personnel training requirements will be completed by Apr 1980 Requests that Unit 1 radwaste be released for shipment WILSON.R F Metropolitan Edison Co 80/03/31 7pp
- 8004110298 Responds to NRC 800223 ltr requesting status of actions All IE Bulletin 79-19 items essentially complete Personnel training requirements near completion & approval of three radvaste shipments was gained Add status info encl WILBON, R F Metropolitan Edison Co 80/03/31 7pp
- 8004150276 Forwards IE Info Notice 80~12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- 8004090065 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 1p

- 8004110149 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/04/02 lp
- 8004240315 Forwards IE Info Notice BO-14. "Safety Suggestions From Employees" No action required GRIER.B H Region 1. Philadelphia, Office of the Director BD/04/02 ip
- 8004180260 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required CRIER, B H Region I. Philadelphia, Office of the Director 80/04/03 ip
- 800423046B Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312,Type 304 Stainless Steel Pipe " Action required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004180171 Forwards IE Bulletin 80~08, "Exam of Containment Lines Penetration Welds " Written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/04/07 1p
- 8004i5062i Forwards 79082i & 22 itrs from B&W to B&W owners group as partial response to IE Bulletin 79-05C Includes technical analysis of smail breaks & impact assessment of RCP trip on non-LOCA events
 THORPE.J R General Public Utilities GPU Bervice Corp 80/04/09 i35pp
- 8004300580 Ack receipt of 800220 itr informing NRC of steps taken to correct violations noted in IF Investigation Rept 50-289/779-10
 * Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/04/10 ip
- --8004300586 Responds to NRC 790906 ltm re violations noted in JE Investigation Rept 50-289779-10 Corrective actions researchmenton of items not completed during 1979 inservice inspectaments been scheduled for wk of 600218

 HERBEIN.J O Metropolitan Edison Co 80702720 1p
- B0041B0473 Discusses inservice insp program submitted 791026 Clarifies position re upprade of ultrasonic nondestructive examination techniques & procedures Upgrade completed w/o replacing calibr stds
 HERBEIN, J O Metropolitan Edison Co B0/04/ii ip
- R Periodic operating reports & related correspondence
- 8004010444 Bubmits "EPA Freliminary Data Rept 800312,14,17 & 21," prepared by Environ Monitoring Sys Lab SMITH.A E Environmental Protection Agency 80/03/24 1p
- 8004010490 Submits "NRC Air Sample Results for 800305,12 & 19," prepared by Environ Monitoring Sys Lab. EPA SMITH, A E Environmental Protection Agency 80/03/26 1p
- 8004070222 Submits preliminary air & water sampling data for 600319-24 BMITH.A E Environmental Protection Agency 80/03/27 ip
- 8004140420 Forwards weekly status rept for wk ending 800328 re offsite emergency radiological environ monitoring program Surface & drinking water samples had normal tritium & gross beta activities

 OERTZ.8 M Porter-Gertz Consultants, Inc. 80/03/28 22pp
- 8004070335 Forwards "Radiological Environ Monitoring Program Annual Rept,1979," "Hydraulic Survey" & "1979 Menitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of Facility"

 HERBEIN, J. O. Metropolitan Edison Co. 80/03/31 2pp
- --8004070339 "Radiological Environ Monitoring Program Annual Rept for 1979 "
 - * Metropolitan Edison Co 80/04/30 98pp
- --8004070343 "Hydraulic Survey," for Jul 1979 Three oversize drawings enc!
 4 Cilbert/Commonwealth Cos. 79/07/31 20pp
 - 7004070517 #107D W.-.... A A.-... T.... B...... I
- --8004070347 "1979 Monitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of Facility " PELLEK.R R , FRIDAY.G P , JOHNSON.R R NUS Corp 80/02/29 32pp

- 8004250395 Forwards preliminary data from offsite emergency radiological environ monitoring program consisting of program summary & status for w/ of 800328-0403 GERTZIS M Porter-Gertz Consultants, Inc. 80/04/01 14pp
- 8004070332 Submits average daily readings of radiation levels as measured by gamma rate recorder installed at Goldsboro fire hall for 800322-29 BAST. J. Environmental Protection Agency 80/04/07 [p.
- 8004230493 Forwards monthly operating rept for Mar 1780 HERBEIN, J G Metropolitan Edison Co 80/04/15 Lp
- --B004230495 Nonthly operating rept for Mar 1980 MITCHELL, D. G. Metropolitan Edison Co. B0/04/15 Spp
- BOO4230375 Preliminary data rept of air % water sampling CORKERN, W D Environmental Protection Agency BO/04/16 ip
- S Reportable occurrences, LERs & related correspondence
- 8004010338 RO BO-06/1P on 800325, during refueling frequency reactor bldg local leak rate tost of valve RB-V7.updated total leakage exceeded Tech Specs Testing is continuing w/approx 1/4 of test program complete TOOLE,R J Netropolitan Edison Co 80/03/26 lp
- 8004040336 Forwards LERs 80-005/99Y-0 th 80-011/99X-0 HERBEIN J Q Metropolitan Edison Co 80/03/27 1
- --8004040344 LER 80-005/99%-0 on 800321/Rosemount 1152 pressure transmitter in limited cases eshibited output between 4 & 20 ma w/input pressure over or under callibr range Caused by long-term degradation from submergence in water CHAPLIN/S D Metropolitan Edison Co 80/03/27 ip
- --8004040349 LER 80-011/99X-0 on 800321. Rosemount 1152 pressure transmitter in limited cases exhibited output between 4 & 20 ma w/input pressure over or under calibr range Caused by long-term degradation from submergence in water CHAPLIN.S D Metropolitan Edison Co 80/03/27 4pp
- 8004280632 PNS-I-80-004 on 800327, two bomb threats were received both stating that bomb was set for 800328 Search conducted No bombs found MADDEN, W., DEVLIN, J., MARTIN, W. Region 1, Philadelphia, Office of the Director
- 8004230406 Forwards LER 80-004/01T-0 HERBEIN, J G Matropolitan Edison Co 80/04/08 1p
- --8004230411 LER 80-006/017-0 on 800325 during periodic reactor bldg local leak rate testing containment isolation Valve RB-V7 had excessive leakage Cause suspected to be seat damage Improved valve placed on order MITCHELL.D Q Metropolitan Edison Co 80/04/08 2pp
- U Congressional/Executive Correspondence
- 8004080137 Responds to 800220 ltr referring to 0 Bogardus concerns refacility restart Hearing could not be expected before June 1980, due to scope of proceeding, magnitude of intervention & late licensee submittal of technical matl DIRCKS.W J Office of the Executive Director for Operations 80/03/07 ip
- --8004080141 Requests response to encl GBV Hogardus 800209 ltr supporting plant restart MATHIAS, C M Senate 80/02/20 2pp
- V Operator Examinations
- 8004100420 Discusses reasons for postponement of re-examination of licensed personnel at facility Startup date has been indefinitely postponed making testing premature Util will probably contest decision COLLINS.P.F. Operator Licensing Branch 80/03/27 2pp

- * F T * , Fritigian to lead a war Staffey UHT 1

 F errit, residual traiger, frire tratection plans
- in 15 list bases in 17 tel or ne ambeins for emergency readiness and a Fill using act. In discrete defore resumption of systetic feedby for interest reasure? protect Parists is listed act to be for the Parists of the Director and Film Interest in a state of the Director of the Director
- T 1929 1924 F tuards revised sameguards contingency plan Plan withheld thef luffed (19)
 ARD File Suc. Dustin Edison Co. 90/04/22 In
- Aliu*ica*uFy correspondence
- * JACAURS/ Mutiries that lain has been filed by E Brooks? A Brooks dialinst little in connection of operation of facility extrans and compliaint encl. ANEXISTANT OF BOSTON CO. BOYON/17 App.
- of General currespondence
- of ACCOSES Responds to BINGAR lit requesting into re environ effects of New England nuclear journ plants Radiation effluent levels determined by ICCFREO * Map 1 to ICCFREO Environ info available in stated IPING BALLARD R L. Environmental Projects Branch 1 80/04/01 2pp
- M Antitrust rorrespondence
- EU04090471 Response recommending that State of MA Municipals 791011 withdraudi of intervention as most be granted Antitrust teating no longer necessary per entl 000 800317 ltr & due to settlement between municipals & util GOLDBERG J R Antitrust Division 80/03/31 2pp
- -- 6004050475 Responds to 791024 itr requesting DDJ advice per Atomic Energy Act Antitrust hearing no longer neressary due to settlement between State of MA numeripels & util Certificate of Sec encl LITVACK. S M Justice. Dept of 80/03/17 4pp
- P Operating license stage tocuments & correspondence
- COURCEOUTS Sur-ally of SURER neeting u/GE & licensee in Bethesda, MD resiste core spray spaiger cracks associated analysis & plans for resuming power associated unlarge MANNOS, J. 4. Operating Reactors Branch 3 80/03/07 16pp
- C304070405 Discusses ARC Toll23 request that ail LHR licensees assess Aigher vission gas telease for fuel burnups above 20,000 MH-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IRPDL 170,7 A Operating Reactors Branch 3 90/03/10 3pp
- 6004030102 Forwards "Nuclear Dara Link Specs." study of digital communication sys to transmit info rrom plants to Bethesda Operations Ctr EISEWHUT D G Division or Operating Reactors 80/03/12 3pp
- -- J004030118 'Nuclear Data Lint Specs "

 Division of Operating Reactors 80/02/21 28pp
- 5004030322 Summary of 800313 meeting u/util.MPR Associates.lnc.0A Power Co. 1. NUS Corp in Bethesda.hD re util plans to operate facility during Cycle 5 w/visually identified cracks in core spray sparger
 HANNON.J N Operating Reactors Branch 3 80/03/20 6pp
- BC04070304 Submits electrical power sys info re new voltage trip actorints, surveillance testing for timers on shutdown transformer. It installation of undervoltage trip devices for auxiliary & shutdown transformer breaters.

 ANDOGNINI.G C Boston Edison Co 80/03/28 5pg
- BO04280167 Forwards video tape of fuel assemblies in fuel pool provided by util on 800321 for NRC review Wip enc! GRIER,B H Region 1. Philadelphia. Office of the Director BO703/31 1p
- EGOAGGO39B Responds to NRC BOO327 telcon request for info re unscheduled entries of drywell from 750101 to present Submits info for pariag covering 770801 to present ANDOGNINI, C C Boston Edison Co BO/04/Q1 2pp

- 8004090470 Forwards proposed changes to App A of Tech Spots & Bupp) i to "Supplemental Reload Cicensing Submittal for Reload 4" HOWARN, J E Boston Edison Co 80/04/03 Spp
- --8004090472 Proposed changes to Tech Space App Activising operating limit may average planar linear heat-peneration rate to ensure LOCA limits will not be exceeded

 * Boston Edison Co 80/01/03 Bpp
- ~-8004040476 Cuppl 1 to "Supplemental Reload Licensing Bubmittal for Reload 4' ' GRANDON,R J , KISS,E' , GRIDLLY,R L. General Electric Co NEDO-24224-1 80/03/27 10/pp
- 8004100414 Forwards methods of implementation for Category A items re 791030 discussions of Lessons Learned Task force short-term requirements Conformance necessary prior to next operating cycle

 ANDGONINIC C Boston Edison Co B0/04/04 35pp
- --8004100389 Proposed App A Tech Spec changes re care spray spangar àceat detection sethoint hydraulic snubbers, electrical power sys surveillance requirements, mods to safety relief valyes & containment isolation valve logic * Boston Edison Co 80/04/07 3bpp
- 8004140310 Discusses secondary containment leak rate test Test demonstrated that standby gas treatment sys could maintain 1/4 inch of water vacuum in secondary containment Test data enci MCGUIRE, P. J. Boston Edison Co. 80/04/07 1p
- --800414031) "Secondary Containment Leak Rate Test Data " s Boston Edison Co 80/03/20 lp
- 8004250037 Forwards 800128 % 0211 ltrs to GE re proposed control rod drive sys mode related to elimination of crecking in return line horizes Guidelines for mode will be discussed in NUREO-0617, to de issued in "For Comment" form in Apr 1980
 IPFOLITO.T A Operating Reactors Branch 3 80/04/07 2pp
- 8004280027 Forwards request for info returbine disc cracking to be supplied an schedule that will allow review prior to startup from turrent refueling outage Assessment of patential for turbine missile damage should be provided 1970LITCH T A Operating Reactors Branch 3 80/04/07 App
- 8004180363 Forwards addl info in response to NRC 791211 itr requesting clarification of adequacy of breakwater to pesign safety function Results of survey 5 insp of breakwater encl ANDOGNINI, G C Boston Edison Ca 80704/15 25rp
- 8004220580 Forwards info re control rods failing to fully insert for 1978-79, per 800110 request ANDONINI.G C Boston Edison Co 80/04/16 App
- 8004230469 Advises of typographical error in NEBB-24224 re Relead 4 licensing Info on Page 2 should be -D 228/O 217 Calculations not affected ANDOONING.G C Boston Edison Co 80/04/17 1p
- G Inspection reports, IE Bulletins & correspondence
- 8004070334 Forwards IE Insp Rept 50-293/80-02 on 800117-18 No noncompliance noted MITH, 0 H Region 1. Philadelphia, Fuel Facility & Materials Safetty Branch 80/02/09 2pp
- ~-8004070358 IE Insp Rept 50~293/80~02 on 800117~18 No noncompliance noted Major areas inspected radwaste shipment to Barnwell, SC including procedure, shipment record & regulatory requirement clerknes, P. CROCKER, H. W. Region 1, Philadelphia, Office of the Director 80/01/31 Jpp
- 8004040407 Forwards IE Insp Rept 50-293/80-01 on 800108-11 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/08 ip

- --B0040404ii IE Insp Rept 50-293/80-01 on 800108-11 No noncompliance noted Major areas inspected administrative controls for safety-related mainth activities, technician qualifications & preparation for refueling KEHOE.D., BAUNACK.W. Region I, Philadelphia, Office of the Director MARTIN.T T Region I, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/06 Spp
- 8004090395 Forwards IE Insp Rept 50-293/80-03 on 800122-24 No noncompilance noted CARLGON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/12 2pp
- --8004070401 IE Insp Rept 50-273/80-03 on 800122-24 No noncompliance nated Major areas inspected torus mod & inservice insp
 TRIPP.L E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MALTONG A Region 1, Philadelphia, Office of the Director 80/02/07 App
- BCO4160145 Farwards IE Insp Rept 50-293/80-04 on 800128-31 No noncompliance noted BRUNNER: E J NRC Regional Offices 80/02/28 2pp
- --8004i60153 lE Insp Rept 50-293/80-04 on 800128-31 No noncompliance noted Major areas inspected inservice insp implementation, snubber program, containment integrated leak rate test procedure & plant tours

 MARTIN.T T Region 1. Philadelphia. Reactor Operations Nuclear Support Branch KEHOE.D. HIGGINS.J Region 1. Philadelphia. Office of the Director 80/02/25 14pp
- BO04210169 Forwards IE Insp Rept 50-293/79-07 on 791009-10 No noncompliance noted BMITH, O H Region I. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/28 2pp
- --8004210173 IE Insp Rept 50-293/79-07 on 791009-10 No noncompliance noted Major areas inspected radiation protection program, including training, surveys, posting & control & facility tours
 KNAPP,P J Region 1, Philadelphia, Fuel Facility & Materials
 Safety Branch GALLINA,C D , THONUS,L H Region 1, Philadelphia,
 Office of the Director 80/02/27 Spp
- 8004110079 Requests 10-day extension of 45-day response period for Itams 1.2 & 3 of IE Bulletin /7-018
 ANDOONINI.0 C Boston Edison Co 80/03/04 ip
- 8004090469 Forwards IE Mgt Meeting Rapt 50-293/80-06 on 800207 BRUNNER,E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/03/06 1p
- --8004070473 IE Mgt Meeting Rept 50-273/80-06 on 800207 Areas discussed actablishment of ansite ofc for two full-time resident inspectors All parties concurred on adminstrative & operational considerations needed to establish ofc MARTIN,T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch MCGAUGHY,R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch KEHOE,D V Region 1, Philadelphia, Office of the Director 80/03/04 2pp
- BOO4280297 Forwards IE Insp Rept 50-293/79-23 & Waste Packaging Insp Rept 79-08B on 791227-28.600104 & 791216.respectively GRIER.B H Region i, Philadelphia. Office of the Director BO/03/06 2pp
- --B0042B0300 IE Insp Rept 50-293//9-23 nn 791227-28 & 800104 Noncompliance noted failure to comply w/DOT regulations CLEMONS.P , GALLINA.C , CROCKER.H W Region 1, Philadelphia. Office of the Director B0/01/10 Spp
- --8004280310 Waste Packaging Insp Rept 79-088 on 791218 Noncompliance noted radiation levels in excess of specified limits BROWN,R A , POTTER, J.P. Region i, Philadelphia, Office of the Director 79/12/21 Jap
- 8004010013 Forwards response to 800215 notice of violation & \$5,000 check for resulting civil penalty imposed Responsible personnel reinstructed on proper methods of radiation surveying, packaging & shielding ANDQONINI.0 C Boston Edison Co 80/03/10 3pp
- 8004250156 Forwards response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Environ capability of electrical equipment received adequate consideration during design & const of facility W/o encl ANDOGNINI.0 C Boston Edison Co 80/03/12 5pp

- 8004110008 Ack receipt or 800304 lir requesting extension of IE Bulletin 79-018 data submittal date Requests 24-h notification of any deviation from understanding that response to Items 1,2, 5 3 will be submitted by 800317 GRIER, B H Region 1. Philadelphia. Office of the Director 80/03/14 ip
- BOO4240552 Advises that IE Bulletin BO-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," was incorrectly sent for action No response required ORIER, 8 H. Region 1, Philadelphia, Office of the Director BO/03/17 in
- 8004300602 Forwards IE Insp Rept 50-293/80-07 on 800220-22 No noncompliance noted CARLSON,R T Region 1, Philadelphia, Reactor Construction 3 Engineering Support Branch 80/03/17 2pp
- --B004300607 IE Insp Rept 50-293/80-07 on 800220-22 No noncompliance noted Major areas inspected activities re torus mod & inservice insp WALYDN,Q A Region 1, Philadelphia, Office of the Director 80/03/13 5pp
- 8004160125 Ack receipt of 800227 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 30-27377-21
 BRUNNER.E J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch 80/03/24 ip
- --8004160133 Responds to IRC 800121 ltr re violation noted in IE Insp Rept 50-293/79-21 Corrective actions fire protection operating procedures will be revised to implement requirements re Tech Specs 6 8 0.3 12 2 4 12 AND
- --8004160137 Forwards lE Insp Rept 50-293/79-21 on 791210-14 & notice of violation BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/01/21 2pp
- --8004160141 Notice of violation from insp on 771210-14
 * Region 1, Philadelphia, Office of the Director 80/01/14 ip
- --8004160146 IE Insp Rept 50-293/79-21 on 791210-14 Noncompliance noted failure to adequately implement fire protection operating procedures

 BAUNACK, W. Region I. Philadelphia, Reactor Operations Nuclear Support Branch CHUNG, J. BLUMBERG, N. Region I. Philadelphia, Office of the Director 80/01/14 14pp
- 8004150242 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 1p
- 8004090037 Forwards IE Circular 80-05, 'Emergency Diesel Generator Lubricating Oil Addition 2 Onsite Supply "No written response required Region i, Philadelphia, Office of the Director 80/04/01 ip
- 8004110122 Forwards IE Info Notice 80-13, "9E Type SBM Control Switches Defective CAM Followers" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004240290 Forwards 1E Info Notice 80~14, "Gafety Suggestions From Employees" No action required ORIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004180227 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required ORIER,B H Region I. Philadelphia, Office of the Director 80/04/03 ip
- 8004110050 Forwards IE Bulletin 80-07, "BMR Jet Pump Assembly Failure " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004230463 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME 8A-3i2, Type 304 Stainless Steel Pipe " Action required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 1p

- Fundiquith Forumers If Bulletin to up. Even or Containment Liner Penetration Wells United response required GRIER BH Region I Prolatelphia, Office of the Director 80/04/r² lp
- 13 #04233177 Dibmits response to 1E Bulletin 80-02 Replacement feedwater spargers / treinal size on usine purchased through GE-San Unse CA / fabricated by Mar in Engineering during Feb 1980 Ho adverse effects on quality were observed AMODSMIMI G C Boston Edison CD 80/04/17 2pp
- & Periodic operating reports / related correspondence
- 6004080511 Forwards Environ Radiological Monitoring Rept 12, 1979 ANDOGMINE G.C. Boston Edison Co. 80/04/01 1p
- --8004050524 Environ Radiological Monitoring Rept 12," 1979 SOWDON T L . MOSCLESMO.F J Boston Edison Co BO/04/30 131pp
- BCC4230497 Forwards monthly operating rept for Mar 1980 MCCUIRE.P J. Boston Edison to 60/04/09 1p
- ---B004230479 Monthly operating rept for Mar 1980 WHITNEY, G G Boston Edison Co 80/04/03 6pp
- 5 Reportable occurrences &ERs & related correspondence
- B00425033B Requests 24-h norification of deviation from understanding per 800311 telcon re recent incident that fuel handling operation will not resume until certain conditions are met, including concurrence from IE GRIER.B H Region 1, Philadelphia, Office of the Director 80/03/11 1p
- 8004150576 Forwards revised LER 80-007/04T-1 MCGUIRE, P J Boston Edison Co 80/04/02 ip
- --8004150588 Revised LER 80-009/04T-1 on 800310.util received analysis rept from fankee Atomic Electric Lab indicating reportable Cr-51 concentrations were found in mussel samples from discharge canal Cause not stated MCLOUGHLIN.M T Boston Edison Co 80/03/18 1p
- BOO4300552 PNS-I-80-005 on 800404, bomb threat was received Sparch was conducted No bomb found MCHEOWILL DEVLIN.J. MARTIN N Region 1, Philadelphia, Office of the Director BO/01/07 ip
- 8004140337 Forwards LER 80-010/03L-0 MCGUIRE, P. J. Boston Edison Co. 80/04/09 1p
- --8004140342 LER 80-010/03L-O on 800310 hydrant hose house 5 damaged when hit by truck House wrapped around hydrant preventing access Cause not stated House rebuilt & returned to svc MCLGUGHLIN:M T Boston Edison Co 80/04/09 1p
- 8004170184 Forwards LER 80-011/017-0 HCGUIRE.P J Boston Edison Co 80/04/09 Lp
- --B004170191 LER B0-011/011-0 on B00326, utilizing approved station procedure TFB0-37. PNPS jet pumps examined & jet pump beams 1.3 ½ 15 found to have discontinuities Caused not stated Flaued beams & beam bolt assemblies replaced MCI NUMBLIN.M T Boston Eduson Co B0/04/09 1p

- V Operator Examinations
- 8004150158 Approves 770828 revision to requalification program ru simulator retaining Add1 changes may be required after review of other operator training programs COLL NRS.P F Operator Licensing Branch 80/03/27 1p
- DOCKET 50-294 HICHIGAN STATE UNIV RESEARCH REACTOR
 P Operating license stage documents & correspondence
- 8004010227 Forwards Tech Specs, amended to comply w/new format requirements, for renewal of License R-114 WILKINSON.R., CARRICK, J., TERRY, S.H. Michigan State Univ BO/03/11
- --8004010227 Tech Specs, amended to comply w/new format requirements * Michigan State Univ 80/03/11 52pp
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B0041100B9 Forwards request for add1 info re 790323 contingency plan & 791026 Revision 1 Request withheld (ref 10CFR2 790) SCHWENCER, A Operating Reactors Branch 1 80/02/27 1p
- 8004240531 Forwards sys description b operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimile traffic KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/20
- 8004010357 Forwards fire protection review Items 3 1 3.3 1 4 % 3 1 5 Review is duplicate of 800307 review w/minor paragraph change in Item 3 1 3 % clarification of Item 3 1 5 HALL, R E Brookhaven National Laboratory 80/03/21 4pp
- 8004230125 Forwards evaluation of facility fire protection program & status of incomplete items identified in 780310 & 790413 safety evaluations Position on safe shutdown capability also enc:
 SCHMENCER, A Operating Reactors Branch 1 80/03/24 22pp
- 8004290039 Discusses arrangements for 800411 meeting w/util in Glen Ellym.IL re noncompliance & program weaknesses identified in recent health physics program appraisal insp KEEPLER, J G Region 3, Chicago, Diffice of the Director 80/04/07 lp
- 8004300588 Notification of 800417 meeting w/util in Bethesda,MD to discuss meteorological acceptance criteria for emergency preparedness at site REEVES,E Operating Reactors Branch 1 80/04/08 2pp
- B004220356 Submits info in response to NRC question re characteristics of fire suppression sys for grouped cable trays in stairwell between Unit 1 & 2 cable spreading rooms NAUOHTON, W F Commonwealth Edison Co B0/04/14 2pp
- 8004230318 Forwards add1 info re Item 3 1 3,gas suppression sys.for fire protection review Bys acceptable MALL.R E Brookhaven National Laboratory 80/04/14 2pp
- 8004230367 Forwards revised security plan Revisions withheld (ref 10CFR2 790) PEOPLES.D.L. Commonwealth Edison Co. 80/04/21 1P
- G Adjudicatory correspondence
- BC04070139 Forwards 800229 confirmatory order amending facility QLs by incorporating commitments to implement add1 procedural measures b design changes made in util 800222 ltr Actions necessary fur continued assurance of public health & safety DENTON, HR Office of Nuclear Reactor Regulation 80/02/29 2pp
- --8004070142 Confirmatory order amending facility DLs by incopprating commitments to implement addl procedural measures & design changes agreed to in util 800222 ltr & discussed in encl. DENTON, H R Office of Nuclear Reactor Regulation 80/02/29 21pp

- 8004080078 Forwards FR notice & director's decision under IOCFR2 206 denying request for preparation of EIS re Amends 44 & 41 to facility OLs

 BENTON, H R Office of Nuclear Reactor Regulation 80/03/13 1p
- --BOO40B00B3 Director's decision under 10CFR2 206 denying C Quigg 790427 request that Director of Nuclear Reactor Repulations order full EIS for Amends 44 % 41 to OLs Amends will not significantly affect quality of human environ DENTGN.H R Office of Nuclear Reactor Regulation 80/03/13 6pp
- --BOO40B00BB Notice of issuance of Director's decision under 10CFR2 206 denying C Guigg 790427 request that Director of Nuclear Reactor Regulation order full EIS for Amends 44 % 41 to CLs No basis for issuing EIS exists DENTON.H R Office of Nuclear Reactor Regulation 80/03/13 1p
- 8004080568 Order granting extension until 800409 for Commission to elect whether to review 800319 denial of enforcement action CHILK,S J Office of the Secretary of the Commission 80/03/31
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GDSSICKL, V Office of the Executive Director for Operations BO/04/02 34pp
- BOO4280590 Requests immediate suspension of license issued by NRC to Comm Ed to rerack & compact spent fuel pool to 2.112 spent fuel assemblies GUIGG.C Pollution Environmental Problems 80/04/17 2pp
- H General correspondence
- BOD4210336 Advises that 791106 ltr to President Carter re emergency plans has been referred to NRC Bince Summer 1979, NRC has been actively pursuing program to upgrade omergency preparedness Forwards NRC/FEMA documentation W/o encl DENTON, H R Office of Nuclear Reactor Regulation BO/03/31 3pg B0/03/31 3pp
- 8004150085 Responds to 800228 ltr re operation of nuclear power plants in high density areas NRC is invostigating special measures to be taken in heavily populated areas Interim measures have already been ordered at sites

 DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --B004190094 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident BTERNER, J W Affiliation Unknown 80/02/28 ip
- 8004i60173 Responds to 800212 ltr re continued operation of nuclear power plant Add1 measures should be implemented that will further reduce probability of severe reactor accidents Licensee has been in shutdown pending completion of actions DENTON:H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --B004i60i76 Requests that NRC not phase out facility or convert to non-nuclear generators Nuclear power is source for power in UB No nuke political arguments have no basis in reality LAVERTY, E Affiliation Unknown B0/02/12 2pp
- 8004170342 Responds to 800206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility.confirming commitment to public health & safety DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 29p
- 800421008B Responds to 800125 request re-public hearing & determination on UCS petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or lessen consequences
 DENTON, HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210093 Requests scheduling of public hearing & determination of UCB petition re operation of facility prior to reactivation. Concerned for health & safety of community SCIANDRA. J New York NY 80/01/25 ip.
- 8004210193 Responds to 800207 ltr re continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants Interim measures have already been ordered at sites DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210201 Bupports continued operation of facility Reactors supply 20% of generating capacity for New York City & Westchester County Utils can shut off oil plant, lowering rates & dependency on foreign oil WU, J Affiliation Unknown 80/02/07 ip •

- 8004210208 Responds to 800204 ltr re continued operation of facility Plants reviewed to determine what addl measures or design changes can & should be implemented to further reduce probability of reactor accident or consequences
 DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- 8004250013 Responds to 800212 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure DENTON, HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004250030 Urges that NRC consider UCS petition re closing of facility Possibility of earthquake crists u/plant built near fault Only 20% of area energy generated by nuclear power Alternatives should be considered GOLDHOR,F Affiliation Unknown 80/02/12 1p
- 8004250018 Responds to 800215 1tr re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident or to lessen consequences Confirmatory orders issued as interim measure DENTON-HR Office of Nuclear Reactor Regulation 60/04/01
- P Operating license stage documents & correspondence
- B004040031 Advises of issuance of NUREC-0588. "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D F Division of Project Management B0/02/05 7pp
- B0040B0377 Summary of Westinghouse Lossons Learned team B00121-22 site visit to determine implementation status of Category A Lessons Learned requirements Status of each item & attendance list encl
 TELFGRD.J T NRC Three Mile Island Task Force 80/02/15 App
- 8004110569 Forwards Lessons Learned Task Force status relimplementation of Category A requirements following 800121-22 visit by Westinghouse Util has signed confirmatory itr specifying that NRC will be notified of noncompliance TELFORD FT TMI-2 Lessons Learned Task Force 50/02/15 App
- 8004020463 Forwards NRC safety analysis of cracking discovered in feedwater sys Util repair program, nondestructive insps & leakage tosting are adequate to insure that integrity of feedwater piping will be maintained SCHMENCER: A Operating Reactors Branch 1 80/02/25 App
- QOO4180387 Forwards modified near-site study in response to NRC 791205 request for 60-day crash effort PEOPLES.D L Commonwealth Edison Co DAVIS, J.F. Power Authority of the State of New York CAHILL, W.J. Consolidated Edison Co of New York QO/02/25 ip
- 8004020257 Forwards Amends 52 & 49 to Licenses DPR-39 & DPR-48, respectively Amends consist of changes to license & appended Tech Specs permitting mod of spent fuel pool increasing storage capacity from 848 to 2.112 fuel assemblies SCHWENCER, A Derating Reactors Branch 1 80/02/28 2pp
- --8004020262 Amend 52 to License DPR-07.changing license & appended Tech Specs to permit mod of spent fuel pool to increase storage capacity from 868 to 2,112 fuel assemble 80/02/28 3pp
- --8004020266 Amend 49 to License DPR-48, changing license & appended Tech Specs to permit mod of spent fuel pool to increase storage capacity from 868 to 2.112 fuel assemblies Replacement pages of App A Tech Specs encl SCHMENCER, A Operating Reactors Branch 1 80/02/28 6pp
- --8004020270 Notice of issuance of Amends 52 & 49 to Licenses DPR-39 & DPR-48, respectively & negative declaration SCHKENCER.A Operating Reactors Branch i 80/02/28 3pp
- 8004220192 Requests add1 info me dimension of upper vessel head surrounding control rod penetrations Info needed to complete work being conducted by Los Alamos Labs me vessel strengthening Drawing encl
 SCHWENCER. A Operating Reactors Branch 1 80/02/28 2pp
- 8004010004 Forwards "Evaluation of Licenses Compliance w/Category A Items of NRC Recommendations Resulting From TMI-2 Lessons Learned "All Category A requirements satisfied BCHWENCER, A Operating Reactors Branch i 80/02/27 2pp

- ---8004010006 Evaluation of Licenses Compliance U/Category A Items of NRC Recommendations Resulting From TMI-2 Lessons Learned " # Division of Operating Reactors 80/02/28 11pp
- 8004280217 Forwards SFP schedule 5 content requirements for environ qualification of electrical equipment Previously submitted info should be incorporated by specific ref Facilities exempt from 1E Bulletin 79-01B SCHWENCER, A Operating Reactors Branch 1 80/03/05 5pp
- 8004030102 Forwards "Nurlear Data Link Specs." study of digital tommunication sys to transmit into from plants to Bethesda Communication sys to transmit into from plants to operations Ctr
 EISENIUT, D G Division of Operating Reactors 80/03/12 5pp
- --8004030il8 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/21 28pp
- 8004080003 Forwards Amends 53 % 50 to Licenses DPR-37 % DPR-48, respectively, safety evaluations & notice of issuance & availability SCHHENCER A Operating Reactors Branch 1 80/03/13 2pp
- --8004080005 Amends 53 b 50 to Licenses DPR-39 & DPR-49, respectively, changing, Tech Specs, App Auto increase allowable LOCA peaking factor from 1 86 to 1 93, based on FCCS reanalysis GAMMILL, N P Division of Operating Reactors 80/03/13 7pp
- --800408000B Sarety evaluation supporting Amends 53 & 50 to Licenses DPR-39 & DPR-48 respectively

 Office of Nuclear Reactor Regulation 80/03/13 4pp
- --8004080011 "Safety Evaluation of Request for Removal of Conservatism In Westinghouse PAD Computer Code." prepared in response to util request for OL amend Core Performance Branch 80/03/31 32pp
- --8004080013 Notice of issuance & availability or Amends 93 & 50 to Licenses DPR-39 & DPR-48, respectively SCHMENGER.A Operating Reactors Branch 1 80/03/13 2pp
- 8004140221 Summary of BOO221 meeting w/representatives of all SEP plants, utils 5 Franklin Research Ctr re accelerated program for evaluating qualitication of safety-related elactrical equipment HILSON, R Plant Systems Branch 80/03/14 3pp
- 8004100102 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response cir within 20 days

 KEPPLER J G Region 3. Chicago, Office of the Director 80/03/20
- 8004210194 Forwards request for info re containment environ conditions & sys required fo; accident mitigation for review of environ qualification of Class IE electrica) equipment NRC will estimate time for containment temp to return to near normal BCHMENCER A Operating Reactors Branch 1 80/03/20 15pp
- 8004020189 Forwards response to ARC 800229 confirmatory order to perform actions within 30 days Hestinghouse representative stationed onsite/ventilation intakes re-examined/emergency action levels revised by reactor operators training underway NAUCHTON, W.F. Commonwealth Edison Co. 80/03/28 7pp
- 8004080214 Forwards response to immediate action items of NRC 800229 confirmatory order No immediate action required In-plant wall-throughs will be completed prior to next reactor startup Simulator training is in progress
 NAUGHTON. N F Commonwealth Edison Co 80/03/28 4pp
- 8004250364 "Safety Evaluation of Inservice Testing Program for Pumps & Valves." 780117-790916 FEHRINGER, J H : ROCKHOLD, H C EG & Q, Inc FIN A-6258 8004250364 80/03/31 46pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. GA program Revisions reflect recent organization title NAUGHTON.W F Commonwealth Edison Co 80/04/02 lp
- ~~8004150328 Revised pages constituting Revision 13 to QA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-1~A RIO 80/04/04 7pp

- 800410033B Responds to NRC 800-28 ltr re Drawing 686J374 Apparent increased thickness of upper vessel head surrounding control ind penetrations does not exist Actual thickness uniform & 6-5/B inches + 1/B inches-0 inches t/o clad NAUGHTDN:W F Commonwealth Edison Co 80/04/03 ip
- 8004240480 Forwards addl info re review of unresolved safety issues, trip rept of Lessons Learned implementation team & task action plan in view of high population density surrounding plants
 DENTON, H R Office of Nuclear Reactor Regulation BO/04/09 33pp
- -8004240483 Summary of Westinghouse Lessons Learned team B00121-22 site visit to determine status of Category A implementation Attendance & status lists encl FELFORD. J T Safeguards Standards Branch BO/OZ/15 5pp
- --8004240486 Summary of Westinghouse Lessons Learned team 800124-25 site visit re status of Category A implementation Attendance & status lists encl TELFORD, J T Safeguards Standards Branch 80/02/20 5pp
- --- 8004240489 Summary of Westinghouse implementation team 800123-24 & 30 site visit re short-term Lessons Loained requirements TELFORD, J T Safeguards Standards Branch 80/02/15 8pp
- -8004240492 Forwards evaluation of util actions taken to satisfy Lessons Learned Category A requirements Concludes all requirements satisfied Attendance list for 800121-22 site Visit enc)
 SHCWENCER, A Operating Reactors Branch 1 (Pre 791030) 80/02/29 27pp
- ---B004240504 Forwards evaluation of util compliance w/Catagory A Lessons Learned requirements Concludes all requirements satisfied IE followup & attendance lists encl SCHWENCER:A Operating Reactors Branch 1 (Pre 791030) 80/02/21
- ---R004240507 Forwards action plan developed in recognition of high population densities surrounding sites DENTON.H R Office of Nuclear Reactor Regulation 80/02/21
- --8004240518 Discusses Event 5 probabilities Suggests continuous monitoring & readout capability of check valve position & periodic tests of leak rate measurements TAYLOR:M A Division of Reactor Safety Resoarch 80/01/15 17pp
- 8004250232 Forwards status of unresolved safety issues at Indian Point 1 & 2. trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at facilities, task action plan & facility societal risk info DENTON, H R Office of Nuclear Reactor Regulation 80/04/09 34pp
- 9004240498 Formalizes plaus re series of technology exchange meetings re facilities' accident mitigation features activity Five meetings suggested Recommended meeting schedule 2 agenda items encl SCHWENCER.A Operating Reactors Branch 1 80/04/10 15pp
- B004250427 Forwards response to NUREO-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctra for Facilities" for review Util amargency plan will be submitted w/Lasalle County Site-specific emergency plan PEOPLES.D L. Commonwealth Edison Co. 80/04/15 60pp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities," * Buchtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004280509 Forwards revised Page 37 to DL Peoples 800101 ltr concerning commitments re TMI-2 Lessons Learned Task Force short-term commitments : requirements *EOPLEB.B L Commonwealth Edison Co 80/04/18 2pp
- 8004290502 Application for amend to Licenses DPR-39 & DPR-49, App A Tech Space eliminating refs to part length rods & atmospheric relief valves & revising reactor protection sys permissive testing Table 4 1-1 PECPLES, D L Commonwealth & dison Co 80/04/22 4pp
- --8004270506 Revised pages to Tech Specs eliminating refs to part length rods & atmospheric relief valves & revising reactor protection sys permissive testing Table 4 1-1 * Commonwealth Edison Co 80/04/22 43pp

- G inspection reports, IE Bulletins & correspondence
- 8004040316 Forwards IE Insp Repts 50-295/79-22 & 50-304/79-24 on 790910-800204 No noncompliance noted FIORELLIG Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004040339 IE Insp Repts 50-295/79-22 \$ 50-304/79-24 on 790910-800204
 No noncompliance noted Major areas inspected review of inservice insp program % review of licensee activities re [E Bulletin 79-13 & 79-17
 DANIELSON.D H , KEY.W J Region 3, Chicago, Office of the Director 80/02/14 19pp
- 8004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004100408 Waste Packaging 79-07A on 80791212-13 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations including shipping paper requirements, radiation levels & DDT labeling POTTER, J P Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/22 6pp
- 8004220157 Forwards IE Insp Repts 50-295/80-01 & 50-304/80-01 on BD0103-0206 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/03/04 Zpp
- --B004220165 Notice of violation from insp on B00103-0206
 * Region 3, Chicago, Office of the Director B0/03/03 ip
- --8004220175 IC Insp Repts 50-295/80-01 & 50-304/80-01 on 800103-0206 Noncompliance noted facture to follow procedures during shift turnover LITTLE,W S . KCHLER,J C Region 3, Chicago, Office of the Director 80/03/03 11pp
- 8004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07 1g
- 8004140ii9 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 9td Type II. Two-inch Tray Adsarbor Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLEG.D L Commonwealth Cdison Co 80/03/20 5pp
- BOO4040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.AB Region 3. Chicago, Fuel Facility & Materials Bafety Branch B0/03/21 Ip
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --B004040023 Corrected Maste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shapping paper & placarding requirements, radiation levels, removable contamination & package external features POTTER.J P Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- 8004110555 Summary of 800118 meeting w/util & Westinghouse in Bethesda, MD re Unit 1 turbine disc insp results repairs made & plans for inspecting Unit 2 low pressure turbine rotor discs List of attendees & supporting mati
- BOO4150159 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/31 1a
- 8004090686 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/04/01 ip

- 8004150014 Forwards IE Into Notice 80-13, 'GF Type SBM Control Switches Defective CAM Followers ' No specific action of response required KEPPLER, J.G. Region 3 Chicago, Office of the Director 80/04/02 lp
- 8004180030 Forwards atlachments to IF Circulal 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLERJ G Region 3, Chicago, Office of the Director 80/04/02
- 8004220093 Forwards [E Inro Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J.G. Region 3, Chicago, Orfice of the Director 80/04/02 is
- B004220324 Forwards IF Circular 80-07, "Problems W/HPCI Turbine Dil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 8004230224 Forwards JE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/04/07
- 8004220069 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written tesponse required KEPPLER, J.G. Region 3, Chicago, Office of the Director 60/04/09
- R Periodic operating reports & related correspondence
- BOO4140306 Forwards "Radwaste & Environ Monitoring Annual Rept. 1979 " WANDKE,N E Commonwealth Edison Co 80/03/18 1p
- --8004140322 "Radwaste & Environ Monitoring Annual Rept,1979 " KOHL, K A Eberline Instrument Co:p 80/03/18 60pp
- 5 Reportable occurrences, LERs & related correspondence
- 8004220094 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps and using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT.K W Region 2. Atlanta, Office of the Director 77/08/12
- 8004020311 Forwards LER 80-010/03L-0 WANDKE, N Commonwealth Edison Co 80/03/17 1p
- --8004020313 LER 80-010/03L-O on 800219 during normal operation component cooling liquid rad monitor IRE-0017 read high alarm intermittently Caused by correded detector contact pins due to condensation Pin replaced & more insulation installed Q8T.F Commanwealth Edison Co. 80/03/17 1p
- BDO4020369 Forwards LER BO-011/03L-0 WANDKE,N E Commonwealth Edison Co 50/03/17 1p
- --8004020376 LER 80-011/CJL-O on B00224, while performing daily radiation monitor operability check. PTO App N. Unit 1 passive gas failure radiation monitor, HTPRIS failed low 2 could not be reset Caused by defective transistor ZN3638 TRZYNA. G Commonwealth Edison Co 80/03/1/ 1p
- 8004280644 PNO-III-80-063 on 800331, unplanned gaseous radiation release occurred because of operator error in operating valves Preltainary analysis indicates release rates did not exceed Tech Spec limits
 BOYD, D C , KOMLER, J C Region 3, Chicago, Office of the Director BO/04/01 2pp
- 6004280654 PND-111-80-063A 800402.1tr from Mayor of Waukegan, IL. demanded actions as result of 800331 unplanned gaseous release Region 3 is continuing investigation & evaluation STRABAR.R J. HEISHHAN.R F. Region 3. Chicago. Office of the Director 80/04/03 2pp
- BD04220586 Forwards LCR 80-012/03L-0
 HANDKEIN E Commonwealth Edison Co 80/04/11 tp
- --8004220574 LCR 80-012/03L-0 on 800312, during normal gower w/18 diesel generator in standby, 6c control breaker tripped Caused by use of 5-amp slow blow fuses in annunciator inverter Slow blow fuses replaced w/fast blowing fuses CLARK, 8 Commonwealth Edison Co 80/04/11 ip

- 8004220660 Forwards LER GC 013 07L-0 WANDKE N F Commonwealth Edison Co 80/04/14 ip
- --BOO42_OneB LER Po-013/(12)-A on GCD314, while performing periodic radiation surveillance of administry bldg area monitor ORT-ARO), nonitor cas have by factor greater than tive Caused by instrument state by normal variation or accordental reset OST.F. Commonwealth Eduson Co. BO/04/14 lp
- 8004290486 Forwards LER 80 014/03L-0 WANDRE,N E. Commonwealth Edison to 80/01/18 ip
- --8004290496 [ER 80-014/Hs] -D on 800320.during normal operation, blower of containment tent rad monstor IRE-0011 tripped repeatedly Caused by monstor vibration Replaced relays which trip blower on high or low flow OST.F Commonwealth Esison Co. 80/04/18 IP
- 8004290473 Forwards LER 80-015/03L-0
 WANDKE, N E Commonwealth Edison Co 80/04/22 1p
- --8004270483 LER 80-015/0JL-0 on 800401 during normal operation, autiliary bldg exhaust sys particulate Lodine rad monitor QRT-PRIZABB instrument failed 'alarms activated Caused by natural endor-filte of P/N 2000 nagnahelic (sendor-duyer)

 AKER.R E commonwealth Edison Co 80/04/22 IP
- DOCKET 50 276 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

 F. Security, medical, emergency & fire protection plans
- 8004150185 Forwards comments on 790301 safeguards contingency plan & 790901 Revision 1 Requests resisions & addl info Encl withheld (ref. 10LFR2 790) IPPOLITO,T A. Operating Reactors Branch 3 60/03/27 2pp
- H General correspondence
- 8004210208 Responds to 800704 ltm re continued operation of facility Plants reviewed to determine what addl measures or design changes can A should be implemented to further reduce probability of reactor accident or consequences
 DENTON-H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- ~-8004210223 Urges NRC to decide in Pavor of continued operation of facility Reactors have long history of safe, clean & economic operation Concerned that fuel adjustment charges will increase if plants are shot down

 GAY R Affiliation Unknown 80/02/04 1p
- 8004300404 Requests that public hearing 5 EIS be required for proposed low level waste compaction 5 inclineration facility at site JUREIMO.R C Affiliation Uninown 80/04/22 ip
- P Operating license stage documents & correspondence
- 8004020178 Forwards request for addl info on proposed. Tech Spec changes re control & wiring diagrams LAINAS. © Plant Systems Branch 80/02/11 3pp
- 8004240505 "Confirmation of Original Qualification Test for Electrical Connectors Used at Facility," suppl BONZON,L L, BUCKALEH,M H, DUGAN,D M Sandia Laboratories NUREG/CR-1191 80/02/29 200p Available at NTIS
- 8004070384 Discusses NRC 761123 request that all LMR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per motric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bothesda Operations Ctr EISENHUT,D G Division of Operating Reactors B0/03/12 5pp
- --8004030118 "Nuclear Data Lin' Specs " * Division of Operating Reactors | 60/02/21 | 28pp
- 80041105(9 Farwards Amends 40.55 & 32 to Licenses DPR-33, DPR-52 & DPR-68; respectively, sarety evaluation & notice of issuance & availability if availability Reactors Granch 3 80/03/17 2pp

- -8004110525 Amenda 60:55 % 32 to Licenses DPR-33, DPR-52 & DPR-68, respectively, authorizing temporary storage of low level raduaste in existing covered pavilion outside security fence but inside site exclusion area 1PPOLITO, TA Operating Reactors Branch 3 80/03/17 6pp
- --8004110527 Safety e.alvation supporting Amends 60.55 & 32 to Licenses DPR-33 DPR-52 * DPR-68. respectively * Office of Nuclear Reactor Regulation 80/03/17 7pp
- --8004110531 Notice of issuance % availability or Amends 60.95 % 32 to Licenses DPR-33.DPR-52 % DPR-68 respectively IPPOLITO.T A Operating Reactors Branch 3 80/03/17 3pp
- 8004150423 Advises that additime will be needed to develop coordinated response to NRC request of 800215 Response will be submitted by 800501 MILLS, L.K. Tennessee Valley Authority 80/04/07 ip
- 8004150557 Forwards add1 info re containment purge & venting sys.in response to NRC 800226 ltr Key lock switches are provided on control switches to allow overriding primary containment isolation signal NILLS.L M Tennessee Valley Authority 80/04/07 3pp
- 8004290028 Forwards 800128 & O211 ltrs to GE re proposed control rod drive sys mods related to elimination of cracking in return line noisles Guidelines for mods will be discussed in NUREO-0619, to be issued in "For Comment" form in Apr 1980 IPPOLETO,T A Operating Reactors Branch 3 80/04/07 2pp
- 8004230283 Forwards request for additinfo re degraded grid voltage Also requests revised schedule for submission of design of long-term mods re adequacles of station electric distribution sys voltages
 [FPOLITO.T A Operating Reactors Branch 3 80/04/08 3pp
- 8004230506 Forwards info re control drive malfunctions during CY78 & 79.in response to NRC 800110 request MILLS.L.M. Tennassee Valley Authority 80/04/11 2pp
- 8004220340 Application to amend Licenses DPR-33, DPR-52 & DPR-68 changing Tech Specs to allow conduct of short containment integrated leaf rate test Fee encl
 MiLLS, L.M. Tennessee Valley Authority 80/04/15 2pp
- --8004220349 Proposed Tech Spec revisions, allowing conduct of short containment integrated leak rate test
 # Tennessee Valley Authority 80/04/15 13pp
- --8004220359 "Nuclear Containment Testing for TVA Nuclear Power Plants," presented at ANS 791111-16 winter meeting CLARK, K H , WHITE, T J Tennessee Valley Authority 79/11/16 Abox
- 8004220523 Responds to NRC 800212 request for info needed to compare RETRAN code results w/simulator results & EG&O 800317 request for info re LOCA calculational models Singer Co could more adequately address NRC request MILLS:L II Tennessee Valley Authority 80/04/15 2pp
- --8004220531 Requests assistance in comparing RETRAN & simulator results for BUR plant transients/incidents re loss of feedwater & loss of load BNL should be provided w/related info EG&O BOO317 request for info ancl FABIC.6 Analysis Development Branch 80/02/12 4pp
- 8004220533 Advises that Section 316 documents re NNPDES Permit ALO022080 are being sent to JW Warr,H Zeller & LB Tebo.in accordance w/util 800331 itr EL-ASHRY,M T Tennessee Valley Authority 80/04/17 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004040174 Ack receipt or 800124 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-42, 50-260/79-42 t 50-296/79-42 Region 2. Atlanta, Reactor Construction & Engineering Support Branch
- --8004040181 Responds to NRC 800102 ltr re violations noted in IE Imap Repts 50-259/79-42, 50-260/79-42 & 50-276/79-42 Corrective actions review of all previous insp data records was made to verify notification to DES engineer MILLS.L M Tennessee Valley Authority 80/01/24 3pp

- --B004040185 Forwards IE Insp Repts 50-259/79-42.50-260/79-42 & 50-276/79-42 on 791126-27 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/02 2pp
- ~~8004040189 Notice of violation from insp on 791124-27

 * Region 2. Atlanta. Office of the Director 79/12/14 ip
- --8004040196 IE Insp Repts 50-259/79-42,50-260/79-42 & 50-296/79-42 on 791126-27 Noncompliance noted failure to report discrepancies to DES engineer HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENOS, L Region 2. Atlanta. Office of the Director 79/12/14 App
- 8004090352 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Tupe II, Two-Inch, Tray Adsorber Cells " Action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06
- 8004090245 Forwards IE Insp Repts 50-259/80-03,50-260/80-03 & 30-296/80-09 on 800129-31 No noncompliance noted LEWIS:R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/17 2pp
- --8004070252 IE Insp Repts 50-259/80-03.50-260/80-03 & 50-296/80-09 on 800129-31 No noncompliance noted Najor areas inspected refueling activities KELL030,F J Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/15 Spp
- B004110503 Forwards IE Insp Repts 50-259/80-07.50-260/80-07 & 90-296/80-07 on B00205-07 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/02/27 2pp
- --8004110514 IE Insp Repts 50-259/80-07,50-260/80-07 & 30-296/80-07 on 800205-07 No noncompliance noted Hayor areas inspected video observation of core spray sys sparger & review of proposed actions for LER HERDIAR Region 2, Atlanta, Reactor Construction & Engineering Support Branch VANDORNAP & Region 2, Atlanta, Office of the Director 80/02/25 3pp
- 8004280194 Forwards IE Insp Repts 50-259/80-05.50-240/80-05 & 50-296/80-05 on 800206-08 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/07 2pp
- --8004280202 IE Insp Repts 50-259/80-05, 50-260/80-05 & 50-296/80-05 on 800206-08 No noncompliance noted Major areas inspected areas of seismic analysis for as-built safety-related piping sys (IE Bulletin 79-14)
 HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENDS, L. Region 2. Atlanta, Office of the Director 80/03/04 App
- 8004020242 Ack receipt of 800204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-38, 50-260/79-38 & 50-296/79-38 LEHIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/ii ip
- ---8004020249 Responds to NRC 800110 ltr re violations noted in IE Insp Repts 50-259/79-38.50-260/79-38 & 50-296/79-38 Corrective actions local leak rate test performed on normal hatch cover & control rod drive added to CILRT results MILLS,L M Tennessee Valley Authority 80/02/04 3pp
- --8004020252 Forwards IE Insp Repts 50-259/79-38,90-260/79-38 & 50-296/79-38 on 791119-23 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/10 2pp
- --8004020263 IE Insp Repts 50-259/79-38,50-260/79-38 & 50-296/79-38 on 791119-23 Noncompliance noted use of temporary control rod driveline hatch cover during integrated leak rate test UPRIGHT.C.M. Region 2, Atlanta, Reactor Operations Nuclear Support Dranch BROOKS, EH, WHITENER, HL Region 2, Atlanta, Office of the Director 80/01/08 6pp
- 8004100364 Responds to IE Bulletin 79-23 Conducted sustained full-load operational test on Emergency Diesel Generator 3A Test demonstrated ability of diesel generators to function properly over 24-h period at specified loads MILLB, L M. Tennessee Valley Authority 80/03/21 ip

- BO042101/B Forwards response to IE Bulletin BO-OG. "Loss of Charcoal from Gtd Type 11.Two-Inch.Tray Adsorber Cells " Encl lists rosults of insps at facilities to determine if potential for loss of charcoal incidental to h
- 8004280001 Supplements 800212 response to 1E Bulletin 79-18 Forwards info re procedural controls necessary until completion of sys mods for upgrading public address & evacuation alarm sys as required by bulletin MILLS, L M Tennesses Vailey Authority 80/03/25 2pp
- 8004190527 Forwards IE Info Notice 80~12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 200
- 8004080636 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition 3 Onsite Supply 'No written response required U'REILLY.J P Region 2. Atlanta, Office of the Director 80/04/01 2pp
- 8004150097 Forwards IC Info Notice 80-13, "QE Type 88M Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 20p
- 8004240274 Farwards IC Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 3pp
- 8004180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03 200
- 8004110021 Forwards IE Bulletin 80~07, "BWR Jet Pump Assembly Failure " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004230142 Forwards JE Bulletin 77-03A "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04 ip
- 8004180445 Forwards IE Bulletin 80-08, "Cxam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/07 Jpp
- 8004280170 Forwards monthly progress rept for Har 1780 in response to IE Bulletin 77-14. "Seismic Analysis for As-Built Safety-Related Piping Sys" Includes insp of drawings.pipe supports & floor & wall penetrations
 MILLS.L M Tennessee Valley Authority 80/04/07 20pp
- B004290170 Forwards IE Insp Repts 50-259/80-12.50-260/80-10 & 50-296/80-11 on 800311-14 No noncompliance noted KENNA,W B Region 2, Atlanta, Safeguards Branch 80/04/09 2pp
- --8004270177 IE Insp Repts 50-259/80-12.50-260/80-10 & 50-296/80-11 on 800311-14 No noncompliance noted Major areas inspected review of security plan.organization.access controls & barriers Details withheld (ref 10CFR2 770) GILLESPIE.F Region 2. Atlanta. Safeguards Branch TILLMAN.A Region 2. Atlanta. Office of the Director 80/04/07 1p
- 8004270377 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp
 MILLB.L M Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- 8004240411 Forwards monthly operating repts for Mar 1980 ABERCROMBLE.H L Tennessee Valley Authority 80/04/10 ip
- --8004240415 Monthly operating repts for Mar 1980 THOM: T Tennessee Valley Authority 80/04/02 32pp

S Reportable occurrences, LERs 3 related correspondence

- 8004180518 PNO-II-70-147 on 780818, one of six air compressors suffered massive failure resulting in rapid loss of control air pressure to all three units Caused by large hole in cylinder head of failed compressor Compressor was isolated KLINGER.G. Region 2. Atlanta, Office of the Director 78/08/18
- 8004010393 Forwards LER 80-007/03L-0 CALHOUN,J R Tonnessee Valle, Authority 80/03/28 lp
- --8004010402 LER 80-007/03L-0 on 800301, after offsite power was restored to 4-kV bus tie board, short period of time elapsed before reclosure of bus tie boarde: feeder bleaker Apparent disagreement in time is still being investigated * Tennessee Valley Authority 80/03/28 2pp
- 8004180452 Forwards LER 78-008/01/-1 CALHOUN, J R Tennessee Valley Authority 80/04/08 lp
- --8004180456 LER 78-008/01X-1 on 780415 during reactor scram relief valve 1-31 failed to reseat until reactor pressure reached 280 osig Moderator cooldown late exceeded 100 F allowed by Tech Specs Caused by excessive pilot leakage * Tennessee Valley Authority 80/04/08 ip

DOCKET 50-298 COOPER NUCLEAR STATION

- F Security, medical, emergency & fire protection plans
- 8004250391 Forwards change to physical security plan, Revision 9 Encl withheld (ref 10CFR2 770) PILANT, J M Rebraska Public Power District 80/03/26 ip
- P Operating license stage documents & correspondence
- B004070390 Discusses NRC 741123 request that all LNR licensees assess higher fission gas release for fuel burnups above 20,000 MH-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO,T A Operating Reactors Branch 3 B0/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digitat communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs " + Division of Operating Reactors 80/02/21 28pp
- 8004300610 Forwards NRC 800128 & 0211 ltrs to GE re mods to BHR control rod drive sys RUREQ-0619 will provide requirements for facilities where mods to operating reactors have elready been performed under code requirements 1PPOLITO.T A Operating Reactors Branch 3 80/04/07 2pp
- 8004230457 Discusses 800317 ltr re request for change in Tech Spec 3 7 E i value for drywell suppression chamber differential pressure from 1 47 psid to 1 l psid Requests another change to Tech Spec to value of 1 0 psi PILANT, J M Nebraséa Public Power District 80/04/18 2pp
- @ Inspection reports. IE Bulletins & correspondence
- 8004230192 Responds to IE Bulletin BO-01 re operability of automatic depressuritation sys valve pneumatic supply Automatic depressuritation accumulator sys uses soft-seat design lift check valves and by Dragon Valves.Inc
 PILANT.J M Nebraska Public Power District 80/01/16 2pp
- 80041D0093 Forwards IE info Notice 80-02. "BXOR Water Rod Lower End Plug Wear " No specific action or response required SEYFRIT.K V Rugion 4. Dallas, Office of the Director 80/01/25 ip
- B004140479 Responds to IE Bulletin 79-02 "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Boits " Torque vertfication of all expansion anchors on supports for 2 5-inch diameter t larger piping completed actisfactorily PILANT, J M Nebraska Public Power District 80/02/05 4pp
- 8004030246 Forwards 1E lnsp Rept 50-298/79-19 on 791203-14 No noncompitance noted MADSEN/8 L Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/02/28 2pp

- --800403024/ IE lnsp Rept 50-298/79-19 on 791203-14 No noncompilance noted Major areas inspected low level waste shipments & packaging ZURAKONSKI,P R Region 4. Dailas. Office of the Director BODK.H E Region 4. Dallas. Fuel Facility & Materials Bafety Branch 80/01/31 9pp
- 8004250077 Responds to IC Bulletin 79~27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Review identified two instrument panels lacking direct loss of power alarms Direct alarms added PiLANT.J M Nebrasia Public Power District 80/02/28 2pp
- 8004210211 Forwards IE Insp Rept 50-298/80-01 on 800129-0201.05-07 & 13-14 ½ notice of violation MADSEN.0 L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/03/10 2pp
- ---8004210215 Notice of violation from insp on 800129-0201,05-07 & 13-14 * Region 4. Dallas. Office of the Director 80/02/06 ip
- --B0042i02i9 IE Insp Rept 50-298/B0-01 on B00129-0201.05-07 % id-t4
 Noncompliance noted failure to adhere to surveillance
 procedure % to wear required protective clothing
 HESTERMAN.T F. YANDELL.L A. SPANGLER.R G. Region 4. Dallas,
 Office of the Director B0/02/06 13pp
- B004280:84 Forwards response to IF Bulletin 80-20, "Inadequate QA for Nuclear Supplied Equipment " Rept was omitted from 8003:8 response PILANT, J M Nebraska Public Power District 80/03/17 ip
- 8004030349 Forwards 1E Insp Rept 50-278/80-02 on 800303-05 No noncompliance noted HIND, J.A. Region 3: Chicago: Bafeguards Branch 80/03/24 2pp
- --8004030350 IE Insp Rept 50-298/80-02 on 800303-05 No noncompliance noted Major areas inspected facility organization & openation measurements & control & inventory verification Details withheld (ref 10CFR2 790)
 HIND.J A Region 3. Chicago. Safeguards Branch FINLEY.A G Region 3. Chicago. Office of the Director 80/03/19 ip
- 5004150233 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary SEYPRIT, K V Region 4, Dallas, Office of the Director 00/03/31
- 6004080668 Forwards IE (ircular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/01
- 8004ii0101 Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective GAM Followers " No specific action or response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/02
- 8004180494 Forwards IE Info Notice BO-14, "Bafety Buggestions From Employees " No action required SEYFRIT,K V Region 4, Dallas, Office of the Director BO/04/02 to
- 8004180165 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/03
- 8004ii0006 Forwards IE Bulletin 80-07, 'BWR Jet Pump Assembly Failure "Written response required
 SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/04
- 6004230327 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312. Type 304 Stainless Steel Pipe " Action required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/04 in
- 8004290009 Forwards IE Insp Rept 50-278/80-03 on 800317-20 No moncompliance noted MADSEN.Q L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/04/07 2pp

- --8004270011 IE Insp Rept 50-278/80-03 on 800317-20 No noncompliance noted Major areas inspected security plan, physical barriers, protected & vital areas, access control & alarm station Details withheld (ref 10CFR2 770)
 CALDWELL(R A , EVANS, C A Region 4, Dallas, Office of the Director MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/04/07 2pp
- R Periodic operating reports & related correspondence
- 8004010454 Forwards "Semiannual Operating Rept.Radioactive Effluents. Jul-Dec 1979 " FILANT, J M Nebraska Public Power District 80/03/21 2pp
- --8004010457 "Gemiannual Operating Rept.Radioactive Effluents.Jul-Dec
 - * Nebraska Public Power District 80/03/21 25pp
- 8004040396 Forwards "Annual Environ Operating Rept.1979," Vol 2 radiological PILANT.J M Nebraska Public Power District 80/03/28 1p
- --8004040406 "Annual Environ Operating Rept 1979," Vol 2 radiological * Teledyne Isotopes 80/03/28 86pp
- 8004090303 Forwards monthly operating rept for Mar 1980 LEBBOR, L. C. Nebraska Public Power District 80/04/03 1p
- --B004090304 Monthly operating rept for Mar 1980
 BALLINGER, P. L. Nebraska Public Power District 80/04/03 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004040025 PND-IV-80-013 Wastinghouse inspectors found two cracks in rotor disc of low pressure turbine i Largest crack is approx 2 9 inches deep & extending over length of keyway Licensee plans to remove cracked disc at next outage CONSTABLE, 0 L , WESTERMAN, T F Region 4, Dellas, Office of the Director 80/03/17 2pp
- 8004280574 Forwards LER 80-007/03L-0 LEBSGR.L C Nebraska Public Power District 80/03/25 2pp
- --B0042B0579 LER B0-007/O3L-0 on B00310.during surveillance testing of standby liquid control pumps.standby liquid control pump 10 would pump only 36 5 gpm at 1,215 psig Caused by wear & pitting to seating surface BALLINGER.P L. Nebraska Public Power District 80/03/25 lp
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2
- F Security, medical, emergency & fire protection plans
- 80040B0Z24 Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics info during incident or abnormal occurrence KEPPLER, J G Region 3. Chicago, Office of the Director BO/03/19 Bpp
- 8004010336 Forwards fire protection review Items 3 i 17.3 i 25.3 2 2 & 3 2 4 Licensee proposed mods to hydrogen sys & reactor coolant pump oil collection sys are only partly acceptable NRC should request drawings re mods proposed in Item 3 2 2 HAEL, R E Brockhaven National Laboratory 80/03/26 Spp
- 8004020410 Forwards estimates of evacuation times for area surrounding plant, per NRC 791129 ltr request FAY, C W Wisconsin Electric Power Co. 80/03/26 9pp
- BOO4290428 Responds to BUU305 ltr re status of NRC review of plant fire protection program List re status of resolution of incomplete items encl BURBIEIN. B Wisconsin Electric Power Co BO/04/21 2pp
- G Adjudicatory correspondence
- 8004010389 Protests licensees failure to serve filings re steam generator tube degradation Reiterates request for relief as stated in 800226 ltr & requests NRC to direct licensee to serve documents FALK, K M Wisconsin's Environmental Decade 80/03/27 2pp

- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 80041B0122 Ack receipt of B00312 petition requesting that NRC issue order to show cause 0 order enjoining util from returning facility to operation due to steam generator tube degradation Petition will be acted upon within 45 days DENTON: HR Office of Nuclear Reactor Regulation 80/04/02 ip
- ----8004180126 Notice of WI Environ Decade 800312 request that NRC issue order to show cause & order enjoining operation of facility because of steam generator tube degradation Petition will be acted upon within 45 days
 DENTON.H R Office of Nuclear Reactor Regulation 80/04/02 ip
- --B004180130 Requests that NRC issue order to show cause & order enjoining operation of facility because of steam generator tube degradation FALK M Wisconsin's Environmental Decade 80/03/12 in
- I Financial information
- 8004290418 Forwards Annual Financial Rept 1979 & certified financial statements GDRTSCH.J H Wisconsin Electric Power Co 80/04/22 19pp
- --8004270425 Annual Financial Rept 1979 MCNEER.C Wisconsin Electric Power Co 80/03/14 33pp
- P Operating license stage documents & correspondence
- B004040123 Notifies that description of GA program is App H to final description & SAR FAY. C W Wisconsin Electric Power Co 80/02/25 2pp
- B004140087 Finds actions taken to repair, inspect & test cracking found in feedwater sys piping adequate until recommendations of owners group & NRC Pipe Crack Study Group have been evaluated Safety analysis encl SCHHENCER. A Operating Reactors Branch i 80/02/25 6pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- --8004030ii8 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- BOO4300276 Forwards Amends 42 % 47 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability SCHMENGER.A Operating Reactors Branch 1 B0/03/19 2pp
- ---8004300280 Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively, modifying Tech Spec qualification requirements for radiation protection manager SCHMENCER: A Operating Reactors Branch 1 80/03/19 7pp
- ---B0043002B5 Bafsty evaluation supporting Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation 80/03/17 2pp
- --8004300287 Notice of issuance & availability of Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively SCHWENCER.A Operating Reactors Branch 1 80/03/19 2pp
- 8004i00172 Requests controlled set of P&IDs Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/20 in
- 8004020326 Discusses Event 5 valve configurations at facilities in response to NRC 800223 request Valves will be verified properly closed by combination of periodic testing & observation 8tech showing valve configurations encl FAY, C W Wisconsin Electric Power Co 80/03/21 3pp
- 8004010319 Responds to 800107 itr re QA requirements for diesel generator fuel oil Adequate controls to assure quality of fuel oil are being implemented FAY.C W Wisconsin Electric Power Co 80/03/24 2pp

- 8004240096 Provides into to clarify further NRC position re-containment isolation (Section 2 : 4 of NUREG-0578) All plants required to have double isolation barriers w/o need for operator action Plant does not meet position on two penetrations SCHWENCER.A. Operating Reactors Branch 1 80/04/03 3pp
- 8004280293 Forwards Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance % availability SCHMENCER. A Operating Reactors Branch & 80/04/03 2pp
- --8004280299 Amends 43 & 48 to Licenses DPR-24 % DPR-27, respectively, making minor changes to Yech Specs & approving revised organizational structure SCHMENGER, A Operating Reactors Branch 1 80/04/03 31pp
- --8004280301 Safety evaluation supporting Amends 43 & 48 to Licenses DPR-24 b DPR-27, respectively * Office of Nuclear Reactor Regulation 80/04/03 2pp
- --8004280304 Notice of issuance & availability of Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively SCHWENCER, A Operating Reactors Branch i 80/04/03 2pp
- 8004300499 Confirms schedule arranged by NC Choules re 800408 meeting at site to discuss regulatory performance of facility KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/09
- 8004220278 Forwards "Analysis of Capsule R From Util Facility Reactor Vessel Radiation Surveillance Program " FAY.C W Hisconsin Electric Power Co 80/04/16 4pp
- --8004220284 "Analysis of Capsule R From Ut;1 Facility Reactor Vessel Radiation Surveillance Program " MAGAR, T R Westinghouse Electric Corp WCAP-9435 79/12/31
- 8004220475 Notifies of changes to undervoltage relaying for protection against degraded grid voltage on 4160 volt safeguard busses Action responds to NRC request to upgrade circuitry upon review of facility 770824 % 1012 & 800117 ltrs
 FAY.C W Hisconsin Electric Power Co 80/04/17 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004110230 Forwards IE Insp Repts 50-266/80-02 & 50-301/80-01 on 800122-24 No noncompliance noted HEISHMAN,R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/03/05 2pp
- --B004110245 IE Insp Repts 50-266/B0-02 & 50-301/B0-01 on B00122-24 No noncompliance noted Major areas inspected plant operations organization & administration; @A review audite & records WARNICK, R F NRC Regional Offices HAQUE.R L, SMITH, J D Region 3. Chicago, Office of the Director 80/03/04 3pp
- 8004070206 Submits status rept of stress analysis & pipe support review as of 800229; in response to IE Bulletin 79-14 Analysis has been completed for 52 drawings & pipe supports evaluated for 26 pipe lines
 FAY.C W Wisconsin Electric Power Co 80/03/07 6pp
- 8004100149 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07
- B004030353 Responds to IE Bulletin 79-01 re environ qualification of Class IE equipment Master list enci compiling all sys required to function under postulated LOCA or high energy line broak accident FAY,C W Wisconsin Electric Power Co B0/03/12 12pp
- 8004240449 Ack receipt of NRC 800310 ltr transmitting IE Info Notice 80-10 re Crystal River Unit 3 incident Notice will be reviewed by util nuclear projects of personnel & by plant supervisory personnel Results will determine further action FAY.C W Wisconsin Electric Power Co 80/03/24 ip.
- 8004240419 Responds to 1E Bulletin BO-03, "Loss of Charcoal from 8td Type II, Two-Inch, Tray Adsorber Cells " Lists number, sys & manufacturer Containment purge sys cell had loose strip securing screen to frame Next insp scheduled for Apr FAY.C M Wisconsin Electric Power Co 80/03/26 2pp

- 8004150194 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/31 ip
- BOD4080727 Forwards 1E Circular BO-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER, J.G. Region 3, Chicago, Office of the Director BO/04/01
- 8004150059 Forwards IE lnfo Notice 80~13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required XEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 8004180065 Forwards attachments to IE Circular BO-03, "Protection From Toxic Qas Hazards," inadvertently omitted from 800306 transmittal KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004220158 Forwards IE Info Notice 80~14. "Safety Suggestions From Employees " No action required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/02
- B004220392 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Oil Bys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 8004230288 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainloss Steel Pipe" Action required KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/04/07
- 8004220053 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/09
- S Reportable occurrences, LERs & related correspondence
- 8004270464 Forwards updated LER 80-002/01T-1 FAY, C W Wisconsin Electric Power Co 80/04/16 ip
- --8004270469 Updated LER 80-002/017-1 on 800227.during normal operations indication of increasing primary-to-secondary leak in A steam generator noted Caused by leaking tube in A steam generator position R18037
 FAY.C W Wisconsin Electric Power Co 80/04/16 4PP
- 8004290470 Forwards LER 80-003/01T-0 FAY, C W Wisconsin Electric Power Co 80/04/17 1p
- --8004290479 LER 80-003/017-0 on 800408, while testing pressurizer logic channels, pressurizer level channel 427 was momentarily failed low by instrumentation & control technicians Gaused by personnel error Event discussed w/personnel FAY.C W Wisconsin Electric Power Co 80/04/17 2pp
- U Congressional/Executive Correspondence
- BO04140374 Responds to M Charlier B00107 itr requesting facility shutdown until completion of needed repairs Inspectests & operating limits increased to assure public health & safety following problems w/steam generator tube degradation DIRCKS, N J Office of the Executive Director for Operations B0/03/21 | Jp
- ~~8004i40379 Forwards M Charlier 800107 ltr requesting that facility be shut down until needed repairs are completed PRDXMIRE,W Senate 80/01/17 20p
- 8004140294 Forwards NRC 800104 ltr to J Estes, in response to 791213 request If requested, Lakeshore Citizens for Bafe Energy will be included in future meetings re steam generator condition DIRCKS, M J Office of the Executive Director for Operations 80/03/25 1p

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

H General correspondence

- BO04250332 Advises that response to inquiry re plants under const will be provided in BERs which will include TMI-2 Lessons Learned Task Force findings Forwards Commission order defining TMI-2 review parameters & NRC itr to all BWW reactors W/m encis VAROA,S A Assistant Director for Light Water Reactors 80/03/22
- B004180510 Forwards annotated sequence of 800226 events & simplified spectrical circuitry schematics per 800227 request DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 21pp

f Financial information

- BOO4180462 Forwards Annual Financial Repts 1978 & 1979 & Repts of Examinations & Audits BRIGHTR M Florida Power Corp BO/04/15 3pp
- ---8004180469 Annual Financial Rept 1978 * Seminole Electric Cooperative, Inc 80/04/15 46pp
- ---8004180474 Annual Financial Rept for yr ending Sept 1979 * Orlando,FL 79/12/07 15pp
- --8004t60478 Annual Financial Rept 1979 * Orlando,FL 80/02/01 30pp
- --8004180484 Annual Financial Rept 1978 * Florida Power Corp 79/02/06 31pp
- --8004180491 Annual Financial Rept for yr ending Sept 1978 * Leesburg:FL 79/01/26 92pp
- --8004180500 Annual Financial Rept for yr ending Sept 1978 * Sebring, FL 78/12/06 147pp
- --B004180503 Annual Financial Rept for yr ending Sopt 1978 Sebring Util Commission financial statements encl * Tallahasse.FL 79/04/15 129pp
- D Advisory Committee on Reactor Safeguards reports & correspondence
- B004100508 Forwards certified minutes of ACRS Ad Hoc Subcommittee meeting re TMI-2 accident implications HAJDR.R K ACRS Advisory Committee on Reactor Bafeguards 80/03/04 ip
- --B004100321 Discusses development of general framework for conduct of limited risk assessment of B&W reactor simed at identifying unique risk-impacting sequences re reactor safety study MMRPHY, J A. TAYLOR, M A. Probabilistic Analysis Branch (Pre 791030) 79/10/04 12pp
- P Operating license stage documents & correspondence
- BOO4040005 Forwards putline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800206 reactor trip at Crystal River Sequence of events & planned corrective actions also encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/06 26pp
- 8004030102 Forwards "Nutlear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIBENHUT,D G Division of Operating Reactors 80/03/12 5pp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004080002 Summary of 800304 meeting w/util,88W licensees re facility 800226 nonnuclear instrumentation power supply failura resulting in 43.000 gallons of coolant escaping primary coolant sys into reactor bldg Supporting documentation encl REID.R W Operating Reactors Branch 4 80/03/13 57pp
- 8004030230 Notification of 800318 meseting w/all operating B&W reactor licensees in Bethesda.MD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID.R W Operating Reactors Dranch 4 80/03/14 2pp

- 8004100365 Forwards proposed changes to Tech Specs.App A BRIGHT.R II Florida Power Corp 80/03/24 10
- --8004100367 Proposed changes to Tech Specs.App A re reactivity control sys * Floride Power Corp 80/03/24 12pp
- 8004210328 Summary of 800222 meeting w/B&W owners group in Bethesda. Nd re abnormal transient operational guidelines SEIGEL.B L Reactor Systems Branch 80/04/02 4pp
- 8004080374 Forwards "Electrical Distribution Sys Review Summary "BRIGHT, R M Florida Power Corp 80/04/03 4pp
- ---8004080380 "Electrical Distribution Sys Review Summary " * Florida Power Corp 80/04/03 ip
- 8004080613 Advises that response to NRC 800227 request for add1 info re containment purge & vent sys will not be completed until 800515 Delay caused by need for plant-specific analysis BRIOHT, R M Florida Power Corp 80704703 2pp
- 8004250006 Forwards Amend 29 to License DPR-72.safety evaluation \$ notice of issuance \$\mathcal{t}\$ availability

 REID,R W Operating Reactors Dranch \$\dagger\$ 80/04/03 3pp
- --8004250008 Amend 29 to License DPR-72, revising Tech Specs re containment structural integrity, to incorporate guidance on selecting number of tendons for insp & detensioning requirements Revised pages encl REID, R W Operating Reactors Branch 4 80/04/03 7pp
- --8004250012 Safety evaluation supporting Amend 29 to License DPR-72 * Office of Nuclear Reactor Regulation 80/04/03 2pp
- --B004250015 Notice of issuance of Amend 29 to License DPR-72 REID:R W Operating Reactors Branch 4 80/04/03 2pp
- 8004250368 Summary of 800403 meeting w/utils.82M,NUS Corp & McGraw-H;ll in Bethesda.HD re draft NUREG-0667, "Transient Response of B&M-Designed Reactors" CAPRA,R A Standard:ization Branch 80/04/04 7pp
- 8004180490 Notification of 800423 meeting w/utils & B&W in Bothesda, MD to discuss implementation of recommendations by B&W Reactor Transient Response Task Force CAPRA: R A Standardization Granch 80/04/05 2pp
- 8004180307 Supplements util 800111 ltr re implementation of TMI-2 Lessons Learned Task Force recommendations In addition to hot leg vents, remotely operable reator vessel head vent will be installed at CR-3 MODRC, C C Florida Power Corp 80/04/11 2pp
- 8004280351 Forwards BAW-1607, Revision 1, "Cycle 3 Reload Rept," Justifying operation of Cycle 3 at rated thermal power of 2544 MN Formal Tech Spec change request will be filed under separate cover BRIGHT,R M Florida Power Corp 80/04/14 3pp
- ---8004280354 "Cycle 3.Reload Rept." Revision 1 * Babcock & Wilcox Co BAW-1607 80/04/14 90pp
- B004180239 Responds to NRC 800215 ltr re NUREC-0578 requirements Forwards reviews of over-low/overpressure protection for tanks & sys containing radioactive fluids & miscellaneous waste storage tank design
 BRIGHT.R M Florida Power Corp 80/04/15 26pp
- 8004240467 Forwards add1 info re implementation of NUREO-0978,TMI short-term Lessons Learned recommendations in response to NRC request BAYMARD, P Y Florida Power Corp 80/04/20 4pp
- B0042B0567 Application for amend to App A of License DPR-72, consisting of Tech Spec Change Request 51. Revision 1 Certificate of Svc encl
 BRIGHT,R H Florida Power Corp B0/04/23 App
- --B004280569 Yech Spec Change Request 51:Revision 1 (App A) re organizational changes to GA program * Florida Power Corp 80/04/23 1p
- --8004280571 Tech Spec Figure & 2-2, "Facility Organization"
 * Florida Power Corp 80/04/23 1p

- Q. Inspection reports, 1E Bulletins & correspondence
- 8004090337 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Tun-Inth.Tray Adsorber Cells " Action required O'REILLY.J P Region 2 Atlanta, Orfice of the Director 80/02/06 20p
- 8004090351 Forwards IE lnsp Rept 50-302/80-02 on 800116-18 % 24-25 No noncompliance noted BR/ANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/02/21 2pp
- --8004090355 IE insp Rept 50-302/80-02 on 800116-18 & 24-25 No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys per IE Builetin 79-14
 HERDTAR Region 2, Atlanta, Reactor Construction & Engineering Support Bianch MODENUS.L. Region 2, Atlanta, Office of the Director 80/02/20 Spp
- 8003240555 Requests notarized statements re util insp of turbine discs for possible crack formation Statements will enable NRC to decide whether OL should be modified suspended or revoked IE Info Notice 79-37 wereats sheet binfo request encl EISERHUT, D.G. Division of Operating Reactors 80/02/25 5pp
- 8004090133 Forwards IE Insp Rept 50-302/80-05 on 800205-09 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004070163 IE Insp Rept 50-302/80-05 on 800205-08 No noncompliance noted Major areas inspected plant operations & review of previously identified items
 MARTIN,R D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch DYERJ A. Region 2, Atlanta, Office of the Director 80/02/25 4pp
- 8004210105 Forwards IE lnsp Rept 50-302/80-06 on 800211-15 No noncompliance noted LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/03/04 2pp
- --8004210113 IE Insp Rept 50-302/80-06 on 800211-15 No noncompliance noted Major areas inspected licensee action on previous inspector identified items infractions & unresolved items & review of plant operations
 UPRIGHT.C M Region 2. Atlanta. Reactor Operations Nuclear Support Branch BELISLE.G A Region 2. Atlanta, Office of the Director 80/03/03 6pp
- 8004040010 Forwards response to 1E Bulletin 80-03. "Loss of Charcoal from Std Type II.2-Inch.Tray Adsorbers " No deficiencies or degradation found CR-3 filter cells slightly different Screens fastened to frame by spot welds w/l-inch spacing BRIGHT.R M Florida Power Corp 80/03/17 2pp
- 8004040437 Ack receipt of 800307 ltr informing NRC of steps taken to correct violations moted in IE Imap Rept 50-302/80-07 LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/18 ip
- --8004040445 Responds to NRC 800215 ltr re violations noted in 1E lnsp Rept 50-302/80-07 Corrective actions stainless steel piping capped plugged or sealed Storing racks have wooden stripping installed to prevent contact of stainless & carbon steel HANCOCK.J A Florida Power Corp 80/03/07 2pp
- --8004040447 Forwards IE lnsp Rept 50-302/60-07 on 800128-0201 & nutice of violation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/15 2pp
- ~~800404049 Notice of violation from insp on 800128~0201 * Region 2, Atlanta, Office of the Director 80/02/14 tp
- --8004040452 IE insp Rept 50-302/80-07 on 800128-0201 Noncompliance noted several lengths of pipe stored in warehouse were not capped or plugged & open ends unprotected MESSITT.8 R. UPRIONT.C II Region 2. Atlanta, Office of the Director 80/02/14 4pp
- 8004110562 Forwards LE Insp Rept 50-302/80-11 on 800225-28 No noncompliance noted KENNA-W B Region 2. Atlanta, Safeguards Branch 80/03/25 2pp

- --8004110566 IE Insp Rept 50-302/80-11 on 800225-28 No noncompliance noted Major areas inspected vital area access, communications, alarm stations, detection aids & security organization Debails withheld (ref 10CFR2 790) TOBIN, N J Region 2, Atlanta, Bařeguards Branch BESECKER, K H Region 2, Atlanta, Office of the Director 80/03/25 ip
- 8004210111 Updates 800227 response to IE Bulletin 79-27 Util will complete review? evaluation of Non-Class IE instrumentation & control sys as required by bulletin Rept will be submitted by 800426 BRICHIR BY Florida Power Corp. 80/03/26 20p
- 8004150315 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director BO/03/31
- 8004080575 Forwards IE Circular 80-05, "Emergency Diesol Generator Lubricating Oil Addition & Chaite Supply " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01
- B004150080 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAN Followers" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004240259 Forwards IC info Notice 80-14. "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02 2pp
- 8004180274 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004230169 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 9A-312. Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/04/04
- 8004180317 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds " Nritten response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 2pp
- 8004300143 Ack receipt of 791107 1tr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-302/79-24 LEMIB.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/04/11 1p
- --8004300151 Responds to NRC 790924 ltr re violations noted in IE lnsp Rept 50-302/79-24 Corrective actions inso scheduled for all accessible.posted.high radiation areas once per shift MANCOCK.J A Florida Power Corp 79/11/07 ip
- --8004300158 Ack receipt of 791018 ltr informing NRC of steps taken to correct violations in IE Insp Rept 50-302/79-24 Addl info requested re Item A LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/10/24 ip
- --8004300164 Responds to NRC 790924 ltr re violations noted in IE Insp. Rept 50-302/79-24 Corrective actions supervisors instructed not to sign clearances unless clearance log is properly filled out STEWART.W P Florida Power Corp 79/10/18 2pp
- ~-8004300171 Forwards IE Insp Rept 50~302/79~24 on 790702-0803 & notice of violation LEWIB.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/09/24 2pp
- --8004300177 Notice of violation from insp on 790702-0803 * Region 2, Atlanta, Office of the Director 79/09/19 ip
- --8004300187 JE Insp Rept 50-302/79-24 on 790702-0803 Noncompliance noted failure to control high radiation area & failure to properly control equipment clearance MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch GUICK,D. BRADFORD,W Region 2, Atlanta, Office of the Director 79/09/19 13pp

- 8004220526 Responds to IE Bulletin 79-018 Actions required by Items 4 % 5 can be completed by 800630 Responsor required by Items 1,2 % 3 will be submitted by 800421 BRIGHT,R M Florida Power Corp 80/04/17 2pp
- 800430033i Forwards response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation" Equipment necessary for cold shutdown available BRIOHT.R M Florida Power Corp 80/04/29 7pp
- R Periodic operating reports & related correspondence
- 8004010469 Forwards "Post-Operational Ecological Monitoring Program, Annual Rept 1979;" Vol I,Parts 1 & 2 & Vol II MODRE, G C Florida Power Corp 80/03/25 1p
- --8004010473 "Post-Operational Ecological Monitoring Program, Annual Rept 1979, " Vol I.Part 1 * Florida Power.Corp 80/03/31 300pp
- --8004010479 "Post-Operational Ecological Monitoring Program, Annual Rept Vol I. Part 2
 - Florida Power Corp 80/03/31 300pp
- --8004010483 "Post-Operational Ecological Monitoring Program, Annual Rept 1979," Vol II * Florida Power Corp 80/03/31 300pp
- 800401048B Forwards "Annual Environ Operating Rept 1979." Vols 1 5 2 HANCOCK, J A Florida Power Corp 80/03/31 3pp
- --8004010474 "Annual Environ Operating Rept 1979," Vol 1, nonradiological * Florida Power Corp 80/03/31 450pp
- --8004010497 "Annual Environ Operating Rept 1979." Vol 2.radiological * Florida Power & Light Co 60/03/31 95pp
- BOO4210238 Forwards monthly operating rept for Mar 1980 BRIGHT.R M Florida Power Corp 80/04/11 1p
- --8004210240 Monthly operating rept for Mar 1980 CULVER, M W Florida Power Corp 80/04/01
- S Reportable occurrences, LERs & related correspondence
- 8004020318 Forwards LER 80-013/04L-0 HANCOCK, J A Florida Power Corp 80/03/11 4pp
- --8004020323 LER 80-013/04L-0 on 800304, more than two std deviations were discovered between propperational study & operational study in metabolic function of discharge salt marshes Possibly caused by natural or seasonal variations LANCASTER,K F Florida Power Corp BO/03/11 1p
- 8004090313 Forwards LER 80-015/03L-0 HANCOCK, J A Florida Power Corp 80/04/03 1p
- --8004070315 LER 80-015/03L-0 on 800306, while performing engineered safeguards functional test, decay heat suction isolation valve began to close inadvertently No apparent cause for event investigation underway LANCASTER, K F Florida Power Corp 80/03/31 2pp
- 8004290480 Forwards LER 80-016/01T-0 HANCOCK, J A Florida Power Corp 80/04/16 ip
- --GOD4290488 LER BO-016/01T-O on 800401, inadvertent actuation of fire svc deluge sys resulted in damage to auxiliary bldg ventilation exhaust filter AHFL-2A Caused by personnel error during reset of fire svc panel alarm AHFL-2A media replaced LANCASTER, K F Florida Power Corp BO/04/08 2pp
- DOCKET 50-303 CRYSTAL RIVER NUCLEAR PLANT, UNIT 4 H General correspondence
- 8004250332 Advises that response to inquiry re plants under const will be provided in BERs which will include TMI-2 Lessons Learned Task Force findings Forwards Commission order defining TMI-2 review parameters & NRC itr to all B&W reactors W/o encls VARGA.8 A Assistant Director for Light Water Reactors 80/03/22

- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2 F. Security, medical, emergency & rice protection plans
- BOO4110089 Forwards request for add1 into re 790323 contingency plan & 791026 Revision 1 Request withheld (ref 100FR2 790) SCHWENCER A Operating Reactors Branch 1 B0/02/27 1p
- 8004240531 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimalise traffic KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/20
- 8004010357 Forwards fire protection review Items 3 1 3,3 1 4 % 3 1 5 Review is duplicate of 800307 review w/minor paragraph change in Item 3 1 3 & claiification of Item 3 1 5 HALL,R E Brookhaven National Laboratory 80/03/21 4pp
- 8004230125 Forwards evaluation of facility fire protection program & status of incomplete items identified in 780310 & 790413 safety evaluations Position on safe shutdown capability also enc1 SCHWENCER. A Operating Reactors Branch 1 80/03/24 22pp
- 8004290039 Discusses arrangements for 800411 meeting w/util in Clen Ellyn, IL re noncompliance & program weaknesses identified in recent health physics program appraisal insp KEEPLER, J G Region 3. Chicago. Office of the Director 60/04/07
- 8004300588 Notification of 900417 meeting w/util in Bethesda,MD to discuss meteorological acceptance criteria for emergency preparedness at site REEVES.E Operating Reactors Branch 1 80/04/08 2pp
- 8004220356 Submits info in response to NRC question re characteristics of fire suppression sys for grouped cable trays in stairwell between Unit 1 % 2 cable spreading rooms NAUOHTON,W C Commonwealth Edison Co 80/04/14
- B00423031B Forwards addl info re Item 3 i 3.gas suppression systfor fire protection review Sys acceptable HALL.R E Brookhayen National Laboratory 80/04/14 2pp
- 8004230367 Forwards revised security plan Revisions withheld (ref 10CFR2 790) PEOPLES, D L Cor Commonwealth Edison Co 60/04/21 1P
- Q Adjudicatory correspondence
- 8004070139 Forwards 800229 confirmatory order amending facility OLs by incorporating commitments to implement addl procedural measures & design changes made in util 800222 ltr Actions necessary for continued assurance of public health & safety DENTON, HR Office of Nuclear Reactor Regulation 90/02/29 2pp
- --8004070142 Confirmatory order amending facility OLs by incoporating commitments to implement addl procedural measures & design changes agreed to in util 800222 ltr & discussed in encl DENTON.H R Office of Nuclear Reactor Regulation 80/02/29
- 8004080078 Forwards FR notice & director's decision under 10CFR2 206 denying request for preparation of E18 re Amends 44 & 41 to facility OLs
 DENTON:H R Uffice of Nuclear Reactor Regulation 80/03/13 ip
- --8004080083 Director's decision under 10CFR2 206 denuina C Guioa 790427 request that Director of Nuclear Reactor Regulations order full EIS for Amends 44 % 41 to OLs Amends will not significantly affect quality of human environ DENTON, H R Office of Nuclear Reactor Regulation 80/03/13 6pp
- --- BOO4000088 Notice of issuance of Director's decision under 10CFR2 206 denying C Guigg 790427 request that Director of Nuclear Reactor Regulation order full EIS for Amends 44 & 41 to OLs No basis for Issuing EIS exists DENTON. HR Office of Nuclear Reactor Regulation 80/03/13 ip
- 8004080548 Order granting extension, until 800409, for Commission to elect whether to review 800319 denial of enforcement action CHILK.S J Office of the Secretary of the Commission 80/03/31

- 8004030026 Nemotandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparadness distributed as Board nottrication 005510K.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004280590 Requests immediate suspension of license issued by NRC to Comm Ed to reract b compact spent fuel pool to 2,112 spent fuel assemblies OUIGG.C Pollution Environmental Problems 80/04/17 2pp

- 8004210336 Advises that 791106 ltr to President Carter re emergency plans has been referred to NRC Since Summer 1979.NRC has been actively pursuing program to upgrade emergency preparedness Forwards INC-FEMA documentation M/o enci DENTON, HR Office of Nuclear Reactor Regulation 80/03/31 Spp
- 8004150085 Responds to 800228 lti re operation of nuclear power plants in high density areas NRC is investigating special measures to be taken in heavily populated areas Interim measures have already been ordered at sites

 DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004150074 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident STERNER, J W Affiliation Unknown 80/02/28 ip
- 8004160173 Responds to 800212 itr re continued operation of nuclear power plant Addl measures should be implemented that will further reduce probability or severe reactor accidents Licensee has been in shutdown pending completion of actions DENTON:H R Office of Nuclear Reactor Regulation 80/04/01 2p
- --8004160176 Requests that NRC not phase out facility or convert to nonnuclear generators Nuclear power is source for power in US No noke political arguments have no basis in reality LAVERTY.F Affiliation Unknown BO/02/12 2pp
- 8004170342 Responds to G00206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility.confirming commitment to public health & safety DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- 8004210088 Responds to 800125 request re-public hearing & determination on UCS petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or lessen consequences

 DENION.H R Office of fluctear Reactor Regulation 80/04/01 2pp
- --8004210093 Requests scheduling of public hearing & determination of UCS potation we operation of facility prior to rectivation Concerned for health & safety of community SCIANDRA. J. Rew York, NY 80/01/25 19
- 8004210193 Responds to 800207 ltr re continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants Interim measures have already been ordered at sites DENTON:H R Office of Nuclear Reactor Regulation 80/04/0: 2pp
- --8004210201 Supports continued operation of facility Reactors supply 20% of generating capacity for New York City & Westchester County Utils can shut off oil plant.lowering rates & dependency on foreign oil NU.J Affiliation Unknown 80/02/0/ 1p
- BO0421020B Responds to B00204 itr re continued operation of facility Plants reviewed to determine what add1 measures or design changes can & should be implemented to further reduce probability of reactol accident or consequences

 DENTON: R Office of Nuclear Reactor Regulation B0/04/01 2pp
- --8004210223 Urges NRC to decide in favor of continued operation of facility Reactors have long history of safe, clean & economic operation Concerned that fuel adjustment charges will increase if plants are shut down GAY R R Affiliation Uninown 80/02/04 19
- BO04250013 Responds to BO0217 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure

 DENTON.H R Driice of Nuclear Reactor Regulation BD/04/01 2pp

- --8004250030 Urges that NRC consider UCS petition re closing of facility Possibility of earthquake exists u/plant built near fault Only 20/ of area energy generated by nuclear power Alternatives should be considered GOLDHOR.F Affiliation Unknown 80/02/12 ip
- 8004250018 Responds to 800215 ltm re operation of facility NRC considering what special measures should be taken to roduce probability of severe leactor accident or to leasen consequences Confirmationy orders issued as interim measure DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2p
- P Operating license stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RGSS.D F Division of Project Hanagement 80/02/05 7pp
- 80040B0377 Summary of Westinghouse Lessons Learned team B00121-22 site visit to determine implementation status of Category A Lessons Learned requirements Status of each item & attendance list enc!

 TELFORD. J T NRC Three M:le Island Task Force B0/02/15 App
- 8004110569 Forwards lessons Learned Task Force status re implementation of Category A requirements following 800121-22 visit by Westinghouse Util has signed confirmatory It specifying that MRC will be notified of noncompliance TELFORD.FT TMI-2 Lessons Learned Task Force 50/02/15 App
- 8004020463 Forwards NRC safety analysis of cracking discovered in feedwater sys Util ropair program, nondestructive insps & leakage testing are adequate to insure that integrity of faedwater piping will be maintained SCHNENCER. A Operating Reactors Branch (80/02/25 App
- 8004180389 Forwards modified near-site study in response to NRC 791205 request for 60-day crash effort PEOPLES.D.L. Commonwealth Edison Co. 80/02/25 1p
- --8004180375 "Near-Site Study " Viewgraphs encl * Commonwealth Edison Co 80/02/25 75pp
- 8004020257 Forwards Amends 52 & 49 to Licenses DPR-39 & DPR-48, respectively Amends consist of changes to license & appended Tack Specs permitting mod of spent fuel pool increasing storage capacity from 868 to 2.112 fuel assemblies SCHWENCER.A Operating Reactors Branch 1 80/02/28 2pp
- --8004020266 Amend 49 to License DPR-48, changing license & appended Tech Specs to permit mod of spent fuel pool to increase storage capacity from 868 to 2,112 fuel assemblies Replacement pages of App A Tech Specs encl SCHWENCER, A Operating Reactors Branch 1 80/02/28 6pp
- --8004020270 Notice of issuance of Amends 52 & 49 to Licenses DPR-39 & DPR-48-respectively & negative declaration SCHWENCER.A Operating Reactors Branch 1 80/02/28 3pp
- 8004220192 Requests add1 info re dimension of upper vessel head surrounding control rod penetrations Info needed to complete work being conducted by Los Alamos Labs re vessel strengthening Drawing enci SCHWENCER.A Operating Reactors Branch 1 80/02/28 2pp
- 8004010004 Forwards "Evaluation of Licenses Compliance w/Category A Items of NRC Recommendations Resulting From TMI-2 Lessons Learned " All Category A requirements satisfied SCHWENCER,A Operating Reactors Branch 1 80/02/29 2pp
- --8004010006 "Evaluation of Licensee Compliance u/Category A Items of NRC Recommendations Resulting From TMI-2 Lessons Learned " * Division of Operating Reactors 80/02/28 lipp
- 8004280217 Forwards SEP schedule & content requirements for environ qualification of electrical equipment Previously submitted info should be incorporated by specific ref Facilities exempt from IE Bulletin 79-018
 SCHWENCER.A Operating Reactors Branch 1 80/03/05 Spp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT,D 9 Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp

- 8004090003 Forwards Amends 93 % 50 to Licenses DPR-39 % DPR-48, respectively, safety evaluations % notice of issuance & availability
 SCHWENCER, A Operating Reactors Branch 1 80/03/13 2pp
- --8004080005 Amends S3 % 50 to Licenses DPR-39 & DPR-48, respectively, changing, Tech Specs, App A, to increase allowable LOCA peaking factor from 1 86 to 1 93, based on ECCS reanalysis GAMMILL, WP Division of Operating Reactors 80/03/13 7pp
- ---8004080008 Safety evaluation supporting Amends 53 % 50 to Licenses DPR-39 % DPR-48, respectively * Office of Nuclear Reactor Regulation 80/03/13 4pp
- ~-8004080011 "Safety Evaluation of Request for Removal of Conservatism In Westinghouse PAD Computer Code," prepared in response to util request for OL amend * Core Performance Branch 80/03/31 32pp
- --8004080013 Notice of issuance & availability of Amends 53 & 50 to Licenses DPR-39 & DPR-48, respectively SCHWENCER, A Operating Reactors Branch 1 80/03/13 2pp
- 8004140221 Summary of 800221 meeting w/representatives of all EEP plants, utils & Franklin Research Ctr re accelerated program for evaluating qualification of safety-related ejectrical equipment WIESUN,R Plant Systems Dranch 80/03/14 3pp
- 8004100102 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLERJ Q Region 3. Chicago, Office of the Director 80/03/20
- 8004210194 Forwards request for info re containment environ conditions & sys required for accident mitigation for review of environ qualification of Class IE electrical equipment NRC will estimate time for containment temp to return to near normal SCHWENCER.A Operating Reactors Branch 1 80/03/20 15pp
- 8004020189 Forwards response to NRC 800229 confirmatory order to perform actions within 30 days Westinghouse representative stationed ensite ventilation intakes re-examined emergency action levels revised & reactor operators training underway NAUGHTON.W F Commonwealth Edison Co 80/03/28 9pp
- 8004080214 Forwards response to immediate action items of NRC 800229 confirmatory order No immediate action required In-plant walk-throughs will be completed prior to next reactor startup Simulator training is in progress NAUGHTON.W F Commonwealth Edison Co 80/03/28 4pp
- BOO4250364 "Bafety Evaluation of Inservice Testing Program for Pumps & Valves." 780117-790916 FEHRINGER.J M , ROCKHOLD.H C EQ & O, Inc FIN A-6298 8004250364 80/03/31 46pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A: QA program Revisions reflect recent organization title NAUGHTON, W.F. Commonwealth Edison Co. 80/04/02 1p
- --B004150328 Revised pages constituting Revision 13 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CC-1-A R13 80/04/04 7pp
- 8004100338 Responds to NRC 800228 ltr re Drawing 686J374 Apparent increased thickness of upper vessel head surrounding control rod penetrations does not exist Actual thickness uniform & 6-5/8 inches + 1/8 inches-0 inches w/o clad NAUGHTON W F Commonwealth Edison Co 80/04/03 ip
- 8004240480 Forwards add1 info re raview of unresolved safety issues, trip rept of Lessons Learned implementation team,& task action plan in view of high population density surrounding plants
 DENTON, H R Office of Nuclear Reactor Regulation 80/04/09 33pp
- --8004240483 Summary of Westinghouse Lessons Learned team 800121-22 site visit to determine status of Category A implementation Attendance & status lists encl TELFORD, J. T. Safeguards Standards Branch 80/02/15 5pp
- --8004240492 Forwards evaluation of util actions taken to satisfy Lessons Learned Category A requirements Concludes all requirements satisfied Attendance list for 800121-22 site visit encl BHCWENCER, A Operating Reactors Branch 1 (Pre 791030) 80/02/29

- -8004240507 Forwards action plan developed in recognition of high population densities surrounding sites DENTON, HR Office of Nuclear Reactor Regulation 80/02/21
- --8004240518 Discusses E.ent 5 probabilities Suggests continuous monitoring & readout capability of check valve position & periodic tests of leak rate measurements TAYLOR.M A Division of Reactor Safety Research 80/01/15 17pp
- 8004250232 Forwards status of unresolved safety issues at Indian Point 1 % 2.trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at facilities, task action plan & facility societal risk info DENTON, HR Office of Nuclear Reactor Regulation 80/04/09 34pp
- 8004240458 Formalizes plans re series of technology exchange meetings re facilities' accident mitigation features activity Five meetings suggested Recommended meeting schedule & agenda items encl SCHWENCER, A Operating Reactors Branch 1 80/04/10 15pp
- BOO4250427 Forwards response to NUREO-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Leasalle County site-specific emergency plan PEOPLES.D L Commonwealth Edison Co 80/04/15 4Opp
- --8004250428 "Dosign Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" * Dechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004280507 Forwards revised Page 37 to DL Peoples 800101 ltr concerning commitments re TMJ-2 Lessons Learned Task Force short-term requirements
 PEOPLEGID L. Commonwealth Edison Co. 80/04/18 2pp
- 8004290502 Application for amend to Licenses DPR-39 & DPR-48, App A Tech Specs eliminating refs to part length rods & atmospheric relief values & revising reactor protection sys permissive testing Table 4 1-1 PEOPLES, D L Commonwealth Edison Co 80/04/22 4pp
- --8004290504 Revised pages to Tech Specs eliminating refs to part length rods & atmospheric relief valves & revising reactor protection sys permissive testing Table 4 1-1 * Commonwealth Edison Co 80/04/22 45pp
- G Inspection reports. IE Bulletins & correspondence
- 8004040316 Forwards IE Insp Repts 50-295/79-22 & 50-304/79-24 on 790910-800204 No noncompliance noted FIORELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004040339 IE Insp Repts 50-295/79-22 & 50-304/79-24 on 790910-800904 No noncompliance noted Major ereas inspected review of inservice insp program b review of liconses activities re IE Bulletin 79-13 & 79-17 DOTTESTIN 79-13 & 79-17

 DANIELBON, D. H. KEY, W. J. Region 3, Chicago, Office of the Director 80/02/14 19pp
- 8004100140 Forwards Wasto Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted DAVISIA B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004100408 Waste Packaging 79-07A on 80791212-13 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations including shipping paper requirements, radiation levels & DDT labeling POTTER, J P Region 3, Chicago, Fuel Facility & Materials Safety Branch G0/02/22 App
- 8004220157 Forwards IE Insp Repts 50-295/80-01 % 50-304/80-01 on 800103-0206 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/04 2pp
- --8004220165 Notice of violation from insp on 800103-0206 * Region 3, Chicago, Office of the Director BO/03/
- -8004220175 IE Insp Repts 50-295/80-01 % 50-304/80-01 on 800103-0206 Nancampliance noted failure to follow procedures during shift turnover LITTLE, W S , KOMLER, J E Region 3, Chicago, Office of the Director 80/03/03 lipp

- 8004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block' No specific action or response required XEPPLER, J.G. Region 3, Chicago, Office of the Director 80/03/07
- 8004110087 Notifies that facility will be performing inservice inspactivities during refueling outage Insps will include volumetric surface 8 visual insps of class (& 2 components Insps scheduled for 800512 will extend through 800613 WANDKE:N E Commonwealth Edison Co 800/03/13 (p
- 8004140119 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES: D. L. Commonwealth Edison Co. 80/03/20 Spp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/21 tp
- --80040400)9 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-19 No honcompliance noted DAVIS.A B. Region 3. Chicago. Fuel Facility & Materials Bafety Branch 80/02/22 2pt
- --8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels, removable contamination & package external features
 POTTER. J P. Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- B004110555 Summary of B00118 meeting w/otil & Westinghouse in Bethesda, MD re Unit 1 turbine disc inspiresults repairs made & plans for inspecting Unit 2 low pressure turbine rotor discs List of attendees & supporting mat1 enc1 REEVES.E A Operating Reactors Branch 1 B0/03/26 14pp
- BO04190159 Forwards It Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J G Region 3. Chicago. Office of the Director B0/03/31 to
- 8004080686 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Gil Addition 5 Onsite Supply "No written rasponse required KEPPLER, J G Region G. Chicago, Office of the Director 80/04/01 ip
- 8004150014 Forwards IE info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hajards," inadvertently omitted from 800304 transmittal KEPPLER. J Q Region 3, Chicago. Office of the Director 80/04/02
- 6004220093 Forwards IC Info Notice 80-14. "Safety Suggestions From Employees." No action required KEPPLER. J. C. Region 3. Chicago. Office of the Director 80/04/02

- -8004140322 "Radwaste & Environ Monitoring Annual Rept.1979 "
 KOHLIK A Ebesline Instrument Corp 80/03/18 60pp
- S Reportable occurrences, LERs & related correspondence
- 8004210433 PNC~77-131A on 770/12.during routing testing w/facility in hot shutdown safety sys circuits were temporarily disabled Caused by inadequate mgt attention & procedural controls Program of Corrective action instituted KLINGER.O . NOLAN.F . SNIEZEW.J Region 3. Chicago. Office of the Director 77/07/28 ip
- 8004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior mat1 Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT,K & Region 2, Atlanta, Office of the Director 77/08/12
- 800402040/ Forwards LER 80-012/03L-0 WANDKE,N E Commonwealth Edison Co 80/03/25 1p
- --8004020412 LER 80-012/03L-0 on 800224,while increasing power to 80%, control rod bank D rod position indicators were slightly greater than 12 steps above bank demand position Caused by instrument drift Recalibr performed
 T'NIEMI,W D Commonwealth Edison Co 80/03/25 lp
- 8004190472 Forwards LER 80-013/031-0 WANDME,N E Commonwealth Edison Co 80/03/28 1p
- --8004150477 LER 80-013/03L-0 on 800227.during normal operation, maint personnel found steam generator pressure comparator 2PC-336A-U shifted high by 1 5% Caused by defective unit Defective unit replaced w/spare unit JEMKINS.R V Commonwealth Edison Co 80/03/28 ip
- 8004280641 PHO-SII-80-063 on 80033; unplanned gaseous radiation release occurred because of operator error in operating valves. Preliminary analysis indicates release rates did not exceed. Tech Spor limits.

 BOYD.D.C., KUHLER.J.E. Region 3, Chicago, Office of the Director. 80/04/01 | 2pp
- 8004150518 Forwards LER 80-014/03L-0 WANDKE,N E Commonwealth Edison Co GO/04/02 1p
- --8004150526 LER 90-014/031-O on 800303 during normal operation, maint personnel found steam generator pressure transmitter 2-PI-316 had shifted low by 2% Defective Fisher Porter Model 50EP1041 BCXA replaced & channel returned to svc JENKINS.R V Commonwealth Edison Co 80/04/02 ip
- 8004280654 PND-111-80-063A BO0402.1tr from Mayor of Waukegan, IL, demanded actions as result of 800331 unplanned gasebus release Region 3 is continuing investigation & evaluation STRASMAR J. HEISHMAN, F. Region 3. Chicago. Office of the Director 80/04/03 2pp
- 8004220694 Forwards updated LER 80-002/03X-1 WANDXE.N E Commonwealth Edison Co 80/04/14 ip
- --8004220/02 Updated LER 80-002/03X-1 on 800126, during steady state operation, pressure transmitters 2PT-926 for steam generator 2B & 2PT-946 for steam generator 2C failed high Caused by cold drafts freezing instrument root lines KURTH.N R Commonwealth Edison Co 80/04/14 2pp
- DUCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- B004140490 Forwards into on emergency broadcast sys including Dept of Commerce pamphlet entitled, NDAA's Ubiquitous Radio & "Defense Civil Preparedness Agency pamphlet entitled, Emergency Broadcast Bys "
 SCKWENCER, A Operating Reactors Branch 1 B0/02/28 24pp
- 8004080187 Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics info during incident or abnormal occurrence at facility KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/19 Boo

- 8004140086 Confirms 800319 tolcon re arrangements for 800423 & 24 meetings in Kewaunoe, WI rg licensee emergency preparedness procedure & capability of public agencies Public is invited SCHWENCER, A Operating Reactors Branch 1 80/03/26 2pp
- 8004300502 Informs that certain areas of industrial security manual do not meet requirements of IOCFR73 55 Requests that proposed amonds to industrial security manual be submitted for review within 30 days Encl guidance withheld (ref IOCFR2 790) SCHWENCER, A Operating Reactors Branch 1 80/04/03 2pp
- P Operating license stage documents & correspondence
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIBENHUT.D G Division of Operating Reactors BO/03/12 5pp
- BOO4100186 Requests controlled set of PAIDs Submittal should be forwarded to attention of incident response ctr within 20 days KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/20
- 8004010492 Forwards info re qualification of certain equipment.control room indications of bypassed or inoporable safety-related equipment.Page TS6-17 of Tech Specs & listing of current Tech Spec pages, in response to NRC request SCHRUCK.C A Wisconsin Public Service Corp 80/03/27 14pp
- --8004010495 Page TB6-17 of Tech Specs re safety-related equipment & listing of current Tech Spec pages * Wisconsin Public Service Corp 78/01/25 14pp
- 8004080337 Forwards addl info requested at 800305 meeting w/NRC re implementation of short-term Lessons Learned Task Force requirements Info involves Tech Specs 2 1 3.2 1 & & 2 1 8 MATHEWS,E R Wisconsin Public Service Corp 80/04/03 15pp
- 8004170018 Discusses proposed installation of restraints near reactor vessel nozzles to limit break size of LOCA event & limit asymmetric loads to reactor vessel Restraints will improve safety margin while not prosenting hazard MATHEWB.E R Wisconsin Public Service Corp 80/04/10 3pp
- 8004180464 Forwards proprietary & nonproprietary versions of "Structural Analysis of RCS for Postulated LGCA," preliminary issue Applications for withholding encl Proprietary version withhold (ref 10CFRZ 790) ANDERSON, T M Westinghouse Electric Corp 80/04/11 11pp
- --8004180475 Nonproprietary version of "Structural Analysis of RCS for Postulated LOCA," proliminary issue + Westinghouse Electric Corp , Nuclear Energy Systems 80/02/29
- 8004180428 Forwards "Reload Safety Evaluation, Cycle VI. Mar 1780 " MATHEWS, E R Wisconsin Public Service Corp 80/04/14 1p
- --8004180433 "Reload Bafety Evaluation, Cycle VI, Mar 1980"
 HDLLY, J T Wisconsin Public Service Corp 80/03/27 65pp
- 8004180479 Forwards revised pages of reactor test program Revisions reflect results of conversations w/M Chatterton Program was successful during Cycle V startup MATHEWS.E R Wisconsin Public Service Corp 80/04/14 2pp
- 8004220756 Responds to NRC 800411 request for add1 info re RCS vent design & radiation qualification of ECCS Will install reactor vessel head vent sys of C-E design Mill define dose criteria for items w/o acceptable dose qualification MATHEMB.E R Wisconsin Public Service Corp 80/04/14 2pp
- 8004210327 Forwards proposed Amend 40a to Tech Specs, Sections 3 15, 4 15 & 6-2 Proposed Amend 40a supersedes proposed Amend 40 & adds appropriate requirements concerning fire protection sys MATHEMBLE R Wisconsin Public Service Corp 80/04/16 2pp

- --8004210331 Proposed Amend 40a to Tech Specs. Sections 3 15.4 15 & 6-2, superseding proposed Amend 40 Adds requirement for five-man fire response team, corrects wording inconsistencies & deletes fire protection mod requirements wellsconsin Public Service Corp. 80/04/14 9pp
- O Inspection reports, [E Bulletins ≥ correspondence
- 8004100122 Forwards lE Insp Rept 50-305/80-04 on 800204-05 No noncompliance noted FlORELLI. G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/21 2pp
- --B004100130 IE Insp Rept 50-305/80-04 on B00204-05 No noncompliance noted Major areas inspected actions re IC Bulletins 79-14 & 79-04.uark procedure teview & records

 DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch YIN, I T Region 3, Chicago, Office of the Diractor 80/02/21 6pp
- 8004100153 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/07 in
- 8004100405 Responds to IE Bulletin 79-01B Consistent w/intent of IE Circular /8-08, IE Bulletin 79-01 % 79-01A, review of Class IE instrumentation comparing qualifications w/design specs or FSAR requirements shows add1 requirements were met MATHEWB, E.R. Wisconsin Public Service Corp. 80/03/ii 1p
- 8004090428 Forwards 1E Insp Rept 50-305/80-05 on 800217-22 No noncompliance noted Details withheld (ref 10CFR2 790) HIND. J A Region 3, Chicago, Safeguards Branch 80/03/18 2pp
- --800409043(IE Insp Rept 50-305/80-05 on 800219-22 No noncompliance noted Major areas inspected facility organization to operations, previously identified items touclear matlicentrol Details withheld (lef 10CFR2 790)
 HIND, J. A. Region 3, Chicago, Safeguards Branch PATIERSON, J.P., FINLEY, A.C. Region 3, Chicago, Office of the Director 80/03/07
- 8004150176 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/31
- 8004080728 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/01
- 8004i50061 Forwards IE Info Notice 80-13. "GE Type SDM Control Switches Defective GAM Followers" No specific action or response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/04/02 in
- BO04180057 Forwards attachments to IE Circulas BO-03. "Protection From Toxic Qas Hazards," inadvertently omitted from 800306 transmittal KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/02
- BOO4220140 Forwards IE Info Natice BO-14, "Safety Suggestions From Employees " No action required KEPPLER, J G Region 3, Chicago, Office of the Director BO/04/02
- 8004220395 Forwards IC Cyrcular 80-07. "Problems W/HPCI Turbine Oil Bys " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/03
- 8004230291 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME BA-312. Type 304 Stainless Steel Pipe " Action required KEPPLER. J O Region 3. Chicago. Office of the Director 80/04/07
- BO04220060 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director B0/04/09

- R Periodic operating reports 5 related correspondence
- BCC4150354 Forwards nonthly operating rept to: Mar 1980 MATHEWS, E.R. Wisconsin Public Service Corp. BC/04/09 1
- --8004150355 Nonthly operating rept for Mar 1980 RUITER, G. H. Wisconsin Public Service Corp. 80/04/09 5pp
- S Reportable occurrences, LERs ' related correspondence
- 8004080457 Forwards LERs 60-015/03L-0 % 80-016/03L-0 MATHEWS, E R Wisconsin Public Service Corp 80/04/01 16
- --8004080462 LER 80-015/03L-0 on 800303, while performing SP34-099, valve SI-351A would not open Caused by setting of 2 1/2 close 1 1/2 open on torque switch Open torque switch raised to 2 1/2 Tested satisfactorily NALEPKA,D S Wisconsin Public Service Colp 80/04/01 1p
- --BO040B0467 LER BO-016/03L-O on BO0305, while testing 10 diesel generator operability for ICPs on 1A diesel generator. 18 generator failed to start Caused by primary air start motors not rotating engine Motors replaced Manufacturers investigating NALEPKA.D 5 Wisconsin Public Service Corp BO/04/01 ip
- 8004150524 Forwards revised LER 79-028/03X-2 MATHEWS.E R Wisconsin Public Service Corp 80/04/09 ip
- --8004;50532 Revised LER 79-028/03%-2 on 791207, during inspithree horizontal paper restraints discovered missing on 16-inch see water header Caused by oversight between seismic analysis h hanger design teams
 SAVER,D W. Wisconsin Public Service Corp. 80/04/09 2pp
- 8004150581 Forwards supplemental LER 79-017/03L-0 MATHEWS, E.R. Wisconsin Public Service Corp. 80/04/09 [p.
- --8004150596 LER 80-017/03L-0 on 800310, during surveillance testing, turbine driven auxiliary feedwater pump discharge cross—connect valve AFM 10B would not close from control room When imagected, valve operated properly NALEPMA, D.S. Wisconsin Public Service Corp. 80/04/09 ip
- 8004220642 Forwards LER 80-014/04L-0 MATHEWS,E R Wisconsin Public Service Corp 80/04/16 1p
- --8004220648 LER 80-014/04L-0 on 800318, when circulation water inlet temp rose above limit due to circulating water discharge drifting over intake after wind shift, second circulating water pump failed to start Caused by clogged bearing cooler flow line MARCHI,M L. Wisconsin Public Service Corp. 80/04/17 ip
- 8004230504 Forwards LER 80-018/03L-0 MATHEWS, E.R. Wisconsin Public Service Corp. 80/04/18 1p
- --8004230555 LER 60-018/031-0 on 800320 during normal steady state operation.unfamiliar udor noted in diesel generator room 18 While looking for source. Bus 1-6 potential transformer disconnect cubicle door opened causing loss of voltage NALEPKA. D. Misconsin Public Service Corp. 80/03/19 ip
- 8004270321 Forwards LERs 80-019/03L-0 & 80-020/03L-0
 MAYHEWB, E.R. Wisconsin Public Service Corp. 80/04/23 1p
- --8004290327 LER 80-019/031-0 on 800326, during shield bldg ventilation sys surveillance testing, check damper SBV-10A failed to open fully-resulting in Inability to draw vacuum in annulus Caused by controller setpoint drift Setpoint adjusted NAPLEPKA, D & Wisconsin Public Service Corp 80/04/18 1p
- --B004290336 LER 80-020/03L-0 on 800326, control valve SH 1061A failed to open upon removal of heat detector during charcoal filter heat detector test SP 08-195 Caused by dirty valve Valve internals cleaned & diaphragm replaced NALEPKA.D S Wisconsin Public Service Corp 80/04/25 ip
- DOCKET 90-304 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8004080225 Submits revised schedule for implementing fire protection mods MAYER, L.O. Northern States Power Co. 80/03/31 2pp

- 8004170056 Forwards "Evacuation Time Estimates," from areas near nuclear generating plant, in response to NRC 791129 request MAYER,L D Northern States Power Co B0/04/10 ip
- --8004170059 "Evacuation Time Estimates"
 * Northern States Power Co 80/04/30 18pp
- G Adjudicatory correspondence
- 8004230088 Request for hearing and petition to intervene re spent fuel pool mod License amend should not be issued until State of MN administrative proceedings are completed re licensee application for certificate or need & environ evaluation SENCCHAL.M E. DLSON.J F Minnesota, State of 80/03/31 Spp
- 8004230100 Notice of appearance in proceeding SEMECHAL, M.E., DESON, J.F. Minnesota, State of 80/03/31 App
- H General correspondence
- 8004280037 Discusses NRC intervenor funding in response to 800305 ltr Commission decided not to initiate program to provide funding in 1976 Intervenor funding is being studied again & funds for pilot program have been requested for FYB1 CHRISTENBURY.E Heatings Division 80/04/08 1p
- --8004280043 Requests info on availability of govt financial aid for intervenors in racility spent fuel storage license amend proceeding FIELDSETH.H Affiliation Unknown 80/03/05 1p
- P Operating license stage documents 4 correspondence
- 8004110520 Forwards FR notice of proposed issuance of amend to Licenses DPR-42 & DPR-60 re spent fuel storage capacity SCHWENCER.A Operating Reactors Branch 1 80/02/28 2pp
- ---8004110524 Notice of proposed issuance of amend to Licenses DPR-42 to DPR-60 re spent fuel storage capacity SCHHENCER.A Operating Reactors Branch 1 80/02/28 4pp
- 8004020070 Forwards Amends 41 & 35 to Licenses DPR-42 & DPR-60, respectively & notice of issuance & availability SCHHENGER.A Operating Reactors Branch 1 80/02/29 4pp
- --8004020075 Amend 35 to License BPR-60 changing App B Tech Specs by revising requested requirement re blowdown flow over 150 cfs to annual & fish impingement sampling frequency to once every two wks Tech Sper replacement pages encl
 SCHMENCER, A Operating Reactors Branch 1 80/02/29 Spp
- --8004020079 Notice of issuance & availability of Amends 41 & 35 to Licanse BPR-42 & DPR-60, respectively SCHMENCER. A Operating Reactors Branch 1 80/02/29 2pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D G Division of Operating Reactors 80/03/12 Spp
- --8004030110 "Nuclear Data Link Specs"
 * Division of Operating Reactors 80/02/21 28pp
- 800407037B Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics info during incident or abnormal occurrence at facility KEPPLER.J O Region 3. Chicago, Office of the Director 80/03/19
- 8004100183 Requests controlled set of PbIDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/20
- 8004100486 Summary of 800221 telcon w/util re status of NUREG-0578 implementation Items requiring addl clarification subcooling moter & backup procedures used to determine subcooling & use of CRTs not having seismic qualifications GROTENHUIS.M Operating Reactors Branch ! 80/03/21 5pp
- 8004140079 Summary of 800321 meeting w/util in Bethesda, MD re fuel pool expansion proposed by util on 800131 Addl info re unresolved questions will be transmitted by util encl list of attendees GROTENHUIS, M. Operating Reactors Branch 1 80/03/21 3pp

- 8004210023 Advises that 781122 application to amend Licenses DPR-42 & DPR-60 is pro forma & administrative in nature placing Unit 1 in Class II fee category Refund for Class III overpayment will be processed MILLER, W O License Fee Hanagement Branch 80/04/03 ip
- 8004150339 Forwards addl info to implementation of short-term Lessons Learned Task Force recommendations MAYER.L O Northern Status Power Co 80/04/11 17pp
- 8004180464 Forwards proprietary A nonproprietary versions of "Structural Analysis of RCS for Postvolated LOCA," preliminary issue Applications rol withholding encl Proprietary version withheld (ref 10CFR2 790) ANDERSON.T M Westinghouse Electric Corp 80/04/11 lipp
- --B004180475 Nonproprietary version of "Structural Analysis of RCS for Postulated LUCA," preliminary issue # Westinghouse Electric Corp , Nuclear Energy Systems 80/02/29
- 8004180341 Forwards Offsite Dose Calculation Manual Revision 1 MAYER, L.O. Northern States Power Co. 80/04/15 1p
- --B0041B0342 Offsite Dose Calculation Manual Revision 1 * Northern States Power Co B0/04/30 150pp
- 8004280547 Requests NRC review of proposed implementation of short-term Lessons Learned Task Force recommendations re Item 2 1 6 b. "Plant Shielding Review," Item 2 1 9, "Reactor Vessel Head Vent." & Item 2 2 26, "Onsite Technical Support Ctr "MAYER, LO Northern States Power Co 80/04/25 ip
- Q Inspection reports, If Bulletins & correspondence
- BOO4010151 Further responds to NRC 790123 Itr re violations in IE Insp Rept 50-306/78-24 Corrective actions Anker Holt snubber delivery scheduled for Apr 1980 & installation will be completed one month after delivery WACHTER, L J Northern States Power Co 79/12/18 1p
- 8004030251 Forwards IE Insp Rept 50-306/80-03 on 800115-18 & notice of violation FIGRELI.0 Region 3. Chicago: Reactor Construction & Engineering Support Branch 80/02/16 2pp
- --8004030252 Notice of violation from insp on 800115-18
 * Region 3. Chicago. Office of the Director 80/02/13 ip
- --8004030255 IE insp Rept 50-306/80-03 on 800115-19 Noncompliance noted failure to follow nondestructive examination procedures KEY,H J, DANIELSON,D H Region 3, Chicago, Office of the Director 80/02/13 9pp
- 8004100269 Forwards IE Insp Repts 50-282/80-01 & 50-306/80-01 on B00102-31 & notice of violation HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --8004100283 Natice of violation from 1989 on 800102-31 * Region 3, Chicago, Office of the Director 80/02/22 2pp
- --8004100290 IE Insp Repts S0-282/80-01 & 50-306/80-01 on 800102-3i Noncompliance noted containment spray additive tank isolated from containment spray sys & failure to follow operating procedure FEIERABEND.C D . BOYD,D C Region 3. Chicago. Office of the Director. 80/02/22 9pp
- 8004070038 Responds to IE Bulletin 79-17. Revision i, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " Required visual insp completed on Unit 1 in Feb 1980 No corrective actions necessary OILBERTS, D E Northern States Power Co 80/03/07 ip
- 8004070210 Responds to IE Bulletin 79-27 outlining conclusions from investigation of instrument buses Design change initiated to replace instrument inverters w/inverters capable of automatic transfer to alternate ac Oll
- 8004100143 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block "No specific action or response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/03/07

- B004040456 Responds to IL Bulletin 79 OIB, 'Environ Gualitication of Class IE Equipment' Delay until B00311 approved by J Hughes in B00279 telon Foaluates Components' sys qualification for expected operational conditions
 GILBERTS, D.E. Northern States Power Co. B0/03/13 4pp
- 8004100067 Ack receipt of 800229 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50 282/79-32 % 50-306/79-26 DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/20 1p
- --8004100070 Responds to NRC 800207 ltr .e violations noted in IE Insp Repts 50-282/79-32 > 50-306/79-26 Discusses collection of Xe-133 gas samples w/low level gas headers GLUBERTS: D E Northern States Power Co 80/02/29 2pp
- 8004140199 Summary of 800212 meeting w/util \(\hbegin{align*} \text{Hestinghouse at Forest} \\ \text{Hills Lab re results of facility steam generator insp Insp \(\hbegin{align*} \phi \text{plugging of steam generators was acceptable \(\text{\$\chi}\) supports resumption of power operation Supporting matis encl \(\text{grants}\) ORATENHUIS.NI Operating Reactors Branch 1 \(\text{80/03/20}\) 17pp
- --8004140210 STS Pages 3/4 4-1/.3/4 4-10.3/4 4-3 3 3/44 4-4 re steam generator insp * Westinghouse Electric Corp 79/0//15 4pp
- BOO4160013 Responds to IE Bulletin 80-03 ie loss of charcoal from std adsorber colls Visual jusp of charcoal filters installed revealed no degradation or sagging Detailed visual imap of each filter performed annually GILBERTS.D E Northern States Power Co BO/03/24 2pp
- B004150184 forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action of response necessary KEPPLER. J O Region 3, Chicago. Office of the Director 80/03/31
- 8004080719 Forwards 1E Circulat 80-05, "Emergency Diosol Generator Lubricating Dil Addition & Onsite Supply " Na written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/01
- 8004150052 Forwards IF Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/02
- 8004180055 Forwards attachments to IC Circular 80-03, "Protection From Toxic Oas Hazards," inadvertently omitted from 800306 transmittal KEPPLER.J Q Region 3, Chicago, Office of the Director 80/04/02
- 8004220148 Forwards IC Info Notice 80-14. "Safety Suggestions From Employees " No action required KEPPLER, J G Region 3. Chicago. Office of the Director 80/04/02 to
- 8004220378 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Sys " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/03 ip
- 8004230297 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/07 ip
- 8004300334 Ack receipt of 800312 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-306/80-03 FIORELLI, @ Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/08 2pp
- ---8004300337 Responds to NRC 800216 ltr re violations noted in JE Insp Rept 50-306/80-03 Corrective actions liquid penetrant examinations conducted during fuel outage Helds buffed smooth OTLBERTS.D E Northern States Power Co 80/03/12 2pp
- 8004220047 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Helds" Written response required KEPPLER, J O Region 3. Chicago. Office of the Director 80/04/09 ip

- 8004180296 Forwards inservice inspiesam summary for refueling outage Number 4 on 800102-0204 MAYER.L O Northern States Power Co 80/04/16 Jp
- --8004180307 Inservice imsp rept/exam summary for refueling outage Number 4 on 800102-0204 HAUSEN D B , DAHLMAN, L C , MRUMPOS, P J Northern States Power Co 80/04/01 150pp
- 8004230480 Forwards Revision 4 to "ASME Code VI Inservice Insp / Testing Program / Info Requised for NRC Review of Requests for Reliet from ASME Code Section XI Requirements " MAYER, L O Northern States Forer Co 80/04/17 2pp
- --8004230487 Revision 4 to 'ASME Code XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section 4I Requirements "

 Northern States Power Co 80/04/17 35pp
- A Periodic operating reports ? related correspondence
- 8004140339 Forwards monthly operating rept for Nar 1980 MAYER, L. O. Northern States Power Co. 80/04/10 ip
- --8004140344 Monthly operating rept for Mar 1980 HUNSTAD, A.A. Northern States Power Co. 80/04/01 Spp
- S Reportable occurrences, LERs & related correspondence
- 8004;80360 Forwards LER 80-01;/031-0 MAYER, L. O. Northern States Power Co. 80/04/11 lp
- --8004180386 LER 80-011/03L-0 on 800312 motor breaker of charging pump 22 would not stay closed Pump stopped Caused by failed TFK breaker Breaker replaced HWHSTAD, A A Northern States Power Co 80/04/11 1p
- DOCKET 50-309 MAINE YANKEF ATOMIC POWER PLANT
- H General correspondence
- 8004240435 Forwards 800229 ltr from Sensible MC Power legal counsel S Tupper Counsel takes issue w/NRC stated purpose for meeting to discuss group role in util request to expand spent fuel storage facility Requests comment on Tupper ltr CDHEN.44 8 Senate 80/03/07 App
- 8004080644 Discusses 800225 teleon w/AF Stevens of ME Voice of Energy re concerns expressed in 800108 ltr Teleon assured that NRC is receptive to info from all parties concerned in action involving energy FAIRTILE.M D. Operating Reactors Branch 4 80/03/11 ip
- --8004080653 Expresses concern that NRC may be giving too much weight to positions of Sonsible MF Power Group does not represent all cititens of ME STEVENS,AF Maine Voice of Energy 80/01/18 ip
- 8004030112 Responds to 800116 ltr re racility concerns Forwards detailed outline info addressing concerns including info re asymmetric LOCA loads, operator training & licensing & Mar 1979 radiocative gas release DENTON-H R Office of Nuclear Reactor Regulation 80/03/17 3pp
- 8004080339 Notifies NRC that util concurs w/C=E owners group request that future correspondence re regulatory matters be directed to individual licensees MGGDY.D E Maine Yankee Alomic Power Co 80/03/27 2pp
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England huclear power plants Radiation effluent levels determined by 100FR20 & App 1 to 100FR50 Environ info available in stated LPDPS BALLARD,R t Environmental Projects Branch (80/04/01 2pp
- t Financial information
- 8004150290 Forwards Form 10-K.util 1979 annual financial rept HOWE.R B Maine Yankee Atomic Power Co 80/04/10 37pp

- P Operating license stage documents & correspondence
- B004280065 Responds to 80012B request for info re testimony before Public Utils Commission & forwards LER 78-53/01T-0.781206 backup rept & list of documents on dockets for Dct 1978-Mar 1979 & Mar 1979-May 1979 Request list encl RUSSELL.N T Technical & Administrative Support Branch 80/02/05
- --8004280090 Reques*s encl chronology of safety injection piping stress analysis to reviews be forwarded to Engineering Branch for review Refs AITS-F14/4H2, document record for dockets for Oct 1978-Mar 1979 to her-May 1979, respectively, encl KEIMIG.R R Region 1. Philadelphia, Office of the Director 79/01/18 95pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISERHUT,D G Division of Operating Reactors 80/03/12 5pp
- -8004030118 "Nuclear Data Link Specs"

 # Division of Operating Reactors 80/02/21 28pp
- 8004080047 Responds to 800229 memo re deletion of NRC water quality requirements from facility UL Commission approval was not sought since action involved implementation of ASLAP decisions Comparison of requirements of EIS & NPDES encl EHAPAR, H.K. Office of the Erecutive Legal Director DENTON, H.R. Office of Nuclear Reactor Regulation 80/03/21 7pp
- --8004080053 Submits questions re deletion of water quality requirements from facility OL Response should be completed before further deletions are made to other OLs
 BRADFORD, P.A. Commission 80/02/29 1p
- 8004110570 Provides add1 info re implementation of requirements set forth in Item 2 i 7a of NUREG-0578 Commitment to install safety-grade sys prior to 810101 required no later than 15 days after receipt of Itr EISENHUT.D 0 Division of Operating Reactors 80/03/27 2pp
- 8004080634 Notifies that info requested in NRC 800312 ltr.re bypass & reset of engineered safety features, will be submitted by 800319 GROCE.A H Maine Yankee Atomic Power Co 80/03/28 2pp
- 8004110434 Forwards Revision 8 to YOGAP-I-A addressing organization changes to GA program
 HEIDER, L H Yankee Atomic Electric Co 80/04/04 ip
- --BO04110444 GA program Revision 8 for facility operation VANDENBURGH.D C, HEIDER.L H , MODDY.D E Yankee Atomic Electric Co YOQAP-1-A 80/04/01 20pp
- 8004140308 Notifies that CEN-128, "Response of C-E NBSS to Transients & Accidents" constitutes response to short-term analysis & emergency procedure guideline requirements of NUREO-0578. Section 2 1 9 (C) CROCE,8 H Maine Yankee Atomic Power Co 80/04/10 1p
- 8004180438 Provides status of response to NRC 800327 request for commitment to installation of auxiliary freedwater sys & safety-grade sys for automatic initiation Development of safety-grade sys underway GROCE, R H Maine Yankee Atomic Power Co 80/04/14 ip
- 8004220522 Forwards revised Section 5 4 1 of "Cycle 5. Core Performance Analysis "
 VANDENBURCH, D. Maine Yankee Atomic Power Co. 80/04/17 ip
- --8004220530 Revised Section 5 4 1. of "Cycle 5. Core Performance Analysis " * Maine Yankee Atomic Power Co 80/04/17 35pp
- O inspection reports. IF Bulletins & correspondence
- 8004180508 Forwards IE Insp Rept 50-309/80-03 on 800122-25 No noncompliance noted CARLSON,R T Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/26 2pp
- --8004180512 IE Insp Rept 50-309/80-03 on 800122-25 No noncompliance noted Major areas inspected quality related activities associated w/inservice insp program TRIPP.L E Region 2. Atlanta. Reactor Construction & Engineering Support Branch SANDERS.W F Region 2. Atlanta. Office of the Director 80/02/21 5pp

- 8004230120 Forwards IE Insp Rept 50-309/79-20 on 791217-20 No noncompliance noted MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/03/03 200
- --8004230128 IE Insp Rept 50-309/79-20 on 791217-20 No noncompliance noted Major areas inspected approved physical security plan, auditorganization, barriers, lighting, access controls & alarm stations Details withheld (ref 10CFR2 790)
 DEVLINJ W. Region I. Philadelphia. Safeguards Branch JONES. E
 Region I. Philadelphia, Office of the Director 80/02/21 lp
- 8004090458 Forwards addl response to IE Bulletin 79-01 re environ qualification of Class IE equipment Mastor list & electrical component list encl Qualification work sheets & other missing info will be submitted by 800314 W/o encl JQHNSQN,W P Maine Yankee Atomic Powor Co 80/03/04 2pp
- 8004100422 Responds to IE Rulletin 79-14 Field verification of valve weights, existing pipe geometry, seismic support locations, functions & all details completed Review of field work vs design shows differences at rate of approx 30% MDODY, DE Maine Yankee Atomic Power Co 80/03/04 2pp
- BOO40B0430 Requests confirmation of NRC understanding that 79-01B missing Item 1 info will be submitted BOO314 & Items 2 & 3 qualification work sheets by BOO314 per util BOO304 telecopy GRIER. BH Region 1, Philadelphia, Office of the Director BO/03/06 ip
- BD04020016 Responds to IE Bulletin 79-19 & NRC B00213 ltr Training program required by bulletin presently underway & will be fully implemented by Jul 1980
 MGDDY,D E Maine Yankee Atomic Power Co 80/03/07 1p
- 8004100404 Responds to IE Bulletin 79-14 Submits mod to Paragraph 4 of 800304 ltr to NRC.per 800304 telcon All seismic support monconformance will be restricted prior to restart MODPy D E Maine Yankee Atomic Power Co 80/03/07 lp
- 8004080263 Submits response to IE Bulletin 77-27 ro loss of instrument control power & effect on ability to achieve cold shutdown Redundancy of info & controls sufficient to achieve cold shutdown in event of single bus failure No mods nocessary GROCE, R H Maine Yankoe Atomic Power Co 80/03/10 8pp
- 8004080351 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Revised data re Item 1 & updated work sheets & profiles attached hissing info to be submitted within 90-day response period W/o encl JOHNSON,W P Maine Yankee Atomic Power Co 80/03/14 2pp
- BCO4230005 Responds to IE Bulletin 80-03 Investigation completed & charcoal adsorber cells found adequate
 MODDY, D E Maine Yankee Atomic Power Co 80/03/18 Rpp
- BOO4210039 Ack receipt of BOO317 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Rept 50-309/80-01 ORIER.B H Region 1. Philadelphia, Office of the Director BO/03/24 1p
- --B004210044 Responds to NRC B00225 itr re violations noted in IE Insp. Rept 50-309/80-01 Corrective actions refueling machine operators reminded to wear protective cotton gloves unless special health physics surveys performed MOODY, D.E. Maine Yankee Abomic Power Co. 80/03/17 2pp
- --8004210045 Forwards 1E Insp Rept 50-309/80-01 on 800121-25 & notice of violation BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/02/25 2pp
- --8004210049 Notice of violation from insp on 800121-25 * Region i, Philadelphia. Office of the Director B0/02/21 ip
- --8004210053 IE Insp Rept 50-309/80-01 on 800121-25 Noncompliance noted failure to comply w/radiation work permit requirements
 Audible count rate monitor not operating in refueling cavity area
 MARTIN,T T Region 1, Philadelphia, Reactor Operations Nuclear
 Support Branch, SHETLAND,P D, LAZARUS,W J, Region 1,
 Philadelphia, Office of the Director 80/02/21 lp
- 8004i50277 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER: B H Region 1, Philadelphia, Office of the Director 80/03/31 ip

- 8004090069 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 in
- 8004110154 Forwards IE Info Notice 80-13, "GE Type SHM Control Switches Defective CAM Followers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/04/02 ip
- 8004240318 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER.B H Region 1. Philadelphia. Office of the Director 80/04/02 ip
- 8004180174 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 0:1 Sys " No written response lequired CRIER.8 H Region 1. Philadelphia. Office of the Director 80/04/03 1p
- 8004230459 Forwards [E Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required ORIER, II H. Rogion i, Philadelphia, Dffice of the Director 80/04/04 ip
- 8004180194 Forwards TE Bulletin 80-08, 'Exam of Containment Liner Penetration Welds "Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/07 1p
- R Periodic operating reports & related correspondence
- 8004080406 Forwards "Radiological Environ Surveillance Rept.1979" GROCE, R H Maine Yankee Atomic Power Co 80/03/31 1p
- ---8004080411 "Radiological Environ Surveillance Rept.1979 "

 * Maine Yankee Abomic Power Co 80/03/23 55pp
- BO04140154 Forwards "Discharge Monitoring Rept for Feb 1980" Background info also encl re mixing zone temps recorded during summer of 1979 & status of discharge license renewal QARRITY, J H Maine Yankee Atomic Power Co 80/04/04 3pp
- ---B004140157 "Discharge Monitoring Rept for Feb 1980" * Maine Yankee Atomic Power Co 80/02/12 16pp
- HOO4150367 Forwards monthly operating rept for Mar 1980
 MODDY, D E Maine Yankee Atomic Power Co 80/04/11 2p
- --B004150370 Monthly operating rept for Mar 1980 BEERS F C Maine Yankee Atomic Power Co B0/04/11 5pp
- BO042B0562 Forwards "Discharge Monitoring Rept for Mar 1980," submitted to ME Dept of Environ Protection Rept sent to NRC per 800307 commitment Transmittal ltr encl OARRITY, J H Maine Yankee Atomic Power Co 80/04/23 2pp
- --8004280564 "Discharge Monitoring Rept for Mar 1980 "
 # Maine, State of 80/03/07 6pp
- S Reportable occurrences, LERs & related correspondence
- 8004180489 Forwards LER 80-007/03L-0 WODD, E C Maine Yankee Atomic Power Co 80/04/10 1p
- --8004180492 LER 80-007/03L-0 on 800319, during routine power escalation following refueling shutdown RHR valves RH-B & 10 found open & unlocked Six addi valves found unlocked Causad by personnel error Operators rethistructed on procedures BRINKLER, J & Haine Yankee Atomic Power Co 80/04/10 2pp
- 8004210277 Forwards LER 80-008/03L-0 WOOD, E C Maine Yankee Atomic Power Co 80/04/14 1p
- --8004210278 LER 80-008/03L-0 on 800321, during special testing of trip matrix pointion of reactor protective sys, found one set of relay contacts on one matrix relay would not open reliably upon de-energization Cause not stated BRINKLER, J E Maine Yankee Atomic Power Co 80/04/14 2pp

- U Congressional/Executive Correspondence
- 8004)40299 Responds to 800131 request Forwards NRC 800317 response to M Dwinell 800116 inquity re-racility safety BIRCKS.R J German of the Elecutive Director for Operations 80703/21 ip
- --8004140303 Forwards response to 800116 ltr to Senator Cohen re facility safety Handware necessary to resolve asymmetric LOCA load issue installed prior to restait Operator training program improved as illustrated by 1007 success on Oct 1979 test DENTOLOHR Office of Nuclear Reactor Regulation 80/03/17 3pp
- --B004140304 Forwards N Numell B00116 inquiry ltr ie facility safety SNONE.O J House of Rep 80/01/31 3pp
- DOCKET 50-311 SALEN NUCLEAR GENERATION STATION: UNIT 2

 A Application/construction stage documents & correspondence
- H004040631 Advises or issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment." providing guidance re methods for compliance ROSS, D.F. Division of Project Hanagement 80/02/09 7pp
- 8004040017 Submits addl guidance to NVREC-0588. "Interim Staff Position on Environ Qualification of Serety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSB.D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re auxiliary feedwator sys par Bulletins & Orders Task Force review of IMI-2 accident Info should be provided as amend to application Submittal schedule should include RRC approval prior to issuance of DL 4/Anni ROSS.D F Division of Project Management 80/03/10 53pp
- 8004040472 Summary of 800727 meeting w/applicant at site re near-term OL requirements LICITRA,E A Light Water Reactors Branch 3 90/03/11 3pp
- BOO4020256 Requests review of protection sys design for potential deficiencies in bypass.override & reset circuits & conformance w/listed critoria Use or noneafety grade monitor could degrade reliability of isolation sys
- 8004020154 Forwards add1 info re shorthose sturgeon in Delaware River Concludes that continued operation of Unit 1. future operation of Unit 2 & const completion of Hope Creek units will not jeopardize existence of shorthose sturgeon REGANLW H Assistant Director for Environmental Projects 80/03/14 2pp
- --8004070163 "Assessment of Impacts of Salem & Hope Creek Stations on Shortnose Sturgeon, Acipenser Brevirostrum Lesuer " MASNIP,M T , WILEON, J H Office of Nuclear Reactor Regulation 80/03/05 110pp
- 8004070101 Cunfirms points made during 800313 teleon w/util Te test that simulates loss of all ac power using RCS pump heat to simulate decay heat Preparation of detailed test procedures requested PARR.O D Light Water Reactors Branch 3 80/03/17 3pp
- 8004100526 Notification of 800319-21,24 & 25 site visit in Salem County,NJ to discuss control room LICITRA,F A Light Water Reactors Branch 3 80/03/18 3pp
- 8004140486 Notification of 800328 meeting w/util in Bethesda.MD to discuss staffing of facility LICITRA.E A Light Water Reactors Branch 3 80/03/27 2pp
- BOO4240149 Approves secondary water chemistry control program for steam generator tube integrity Requires addl measures reinstallation of inspiports & plugging of Row 1 tubes prior to startup
 PARR.O D Light Water Reactors Branch 3 80/03/27 3pp
- BD0401043B Forwards updated info re implementation of THI Task Force short-term Lessons Learned requirements Onsite technical support cir operational, w/communications installed as described in B00104 submittal MITTL.R L. Public Service Electric & Oas Co. of New Jersey 80/03/28 iipp

- 8064010443 Forwards add1 info requested to containment purge & pressure-vacuum relief circuitry Containment ventilation isolation circuitry modified to include add1 safety injection input aignal MITTLER L. Public Service Electric & Gas Co. of New Jersey 80/03/28 8pp
- 8004010449 Advises of new low level alaim on refueling water storage tank Alarms to be installed prior to low power testing MITTL:R L. Public Service Electric & Gas Co. of New Jersey 80/03/28 2pp
- B004010453 Notifies of review per NRC request of Tables I-2 & 3, II-1, III-1, IV-1 & VI-1 from NUREG-0611. "Generic Evaluation of Feedwater Transients & Small Break COCA in Hestinghouse-Designed Operating Plants " Lists corrections for tables MITTL.R L Public Service Electric & Gas Co or New Jersey 80/03/28 2pp
- 8004070250 Requests extension of CPPR-53 until 801101, due to delay in NRC issuance of OLs caused by TMI accident MITTL.R L Public Service Electric & Gas Co of New Jersey 80/03/28 2pp
- 8004040313 Submits supplement to low power test program described in 800208 itr includes two additests re establishment of natural circulation from stagnant conditions & boron mixing & cooldown Test summarios encl MITTL.R I Public Service Electric & Gas Co of New Jersey 80/03/31 4pp
- BOO4140014 Notification of BOO404 meeting w/utils in Bethesda.MD to discuss applicants' progress & status in design review re plant shielding & environ qualification of equipment for spaces/sys used in post-accident operations BUCKLEY.B C Light Water Reactors Branch i DROMERICK.A W .
 LICITRA.E A Light Water Reactors Branch BO/03/31 7pp
- 8004040282 Notifies that util plans to develop training program re use of installed plant sys to control or mitigate accident involving severe tore damage Licensed operators will be trained prior to full power operation MITTLER L. Public Bervice Electric & Gas Co of New Jersey 80/04/01 3pp
- 8004i10305 Informs that mod planned to ECCS to provide automatic sysfor changeover from injection to recirculation phase Mad will provide backup for normal manual changeover operation Design description will be provided prior to implementation MITTL,R I Public Service Electric & Oas Co of New Jersey 80/04/03 ip
- B004110431 Forwards updated info re implementation of short-term Lessons Learned Task Force requirements Evaluation will be performed of expected radiation levels prior to initiation of special low power test program HITTL.R. L. Public Bervice Electric & Gas Co of New Jersey B0/04/03 app
- 8004110468 Notifies that util will establish onsite safety review group, independent of station staffits perform independent reviews of plant operational activities Training program for offsite technical personnel will be instituted by Aug 1980 HITTL, R L Public Service Electric & Oas Co of New Jersey 80/04/03 2pp
- 8004110474 Forwards "Refueling Water Storage Tank Vortex Test," yerifulng no vortex formation MITTL, R L. Public Service Electric & Gas Co. of New Jersey 80/04/03 ip
- ~-8004110475 "Refueling Water Storage Tank Vortex Test "

 * Public Service Electric & Gas Co of New Jersey 80/04/03
 4pe
- 8004110426 Submits info re RWST low level alarm setpoints, in response to BQ0401 & 02 teleons Setpoints will be set at 150,000 gallons to insure that sufficient vol will be available in RWST to allow changeover from injection to recirculation MITTL,R L. Public Service Electric & Gas Co. of New Jersey 80/04/07 3pp
- 8004170060 Describes plans to staff licensed operator positions on both units, following OL issuance for Unit 2.per 800328 discussion w/NRC MITTLAR L. Public Service Electric & Oas Co. of New Jersey 80/04/09. 3pp
- Q004280139 Notifies of completion of review of util application for OL Forwards proposed license
 DENTON, H.R. Office of Nuclear Reactor Regulation 80/04/09 18pp

- --8004280162 Draft safety evaluation re CL application

 # Office of Nuclear Reactor Regulation NUREQ-0317 S4 80/04/08
 400pp
- BOO4170250 Responds to NRC BOO314 biological assessment of impact of continued operation or const of facilities Forwards biological opinion b summary of informal consultation w/NRC re Salem Unit i Bhortnose sturgeon are not in jeopardy LETTZELL,T L Commerce, Dopt of, National Marine Fisheries Service BO/04/15 20pp
- 8004250393 Responds to NRC 800327 request that Row 1 tubes in steam generators be plugged prior to start of operation Util considers mod unnecessary Plugging Row 1 tubes would remove capability for early detection of onset of deating MITTL.R L. Public Service Electric & Gas Co. of New Jersey 80/04/15 2pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.hem been postponed pending GAU clearance under Foderal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004240377 Responds to 800411 telcon requesting info re availability & adequacy of procedural guidance for supervisor of unaffected reactor when companion unit is involved in emergency Procedures to be approved prior to Unit 2 criticality MITTL.R L. Public Service Electric & Gas Co. of New Jersey 80/04/14 ip
- 8004240365 Notifies that procedures for corporate mgt & technical support are being prepared for revised emergency plan implementation procedures manual & will be incorporated prior to inital fuel loading MITTL, R L Public Service Electric & Gas Co of New Jersey BO/04/15 1p

O Adjudicatory correspondence

- B004040207 Comments on irresponsible way intervonors are being treated Sites case of ruling to allow Salom Unit 1 to operate despite no evidence that licensee could protect endangered shortnose sturgeon COLEMAN. C Affiliation Unknown B0/03/05 3pp
- 8004100466 Notice that CJ Valore appears as attorney of record for petitioner SE Donelson.Mayor of Lower Alloways Township, Salem County, KJ VALORE, C. J. Lower Alloways Creek, NJ VALORE, C. J. Valore, C. 80/03/25 lp
- 8004100583 Intervenor request for suspension or moratorium on issuance of CL Issuance would permit same enlarged spent fuel pool that is subject of ongoing hearing DONEL8GN:6 E Lower Alloways Creek, NJ 80/03/25 4pp
- 8004240485 Forwards NRC confirmatory orders STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/04 1p
- --8004240475 Order confirming util commitment to perform review requested by IE Bulletin 79-27 Info required is specified in Attachment A STELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 Opp
- 8004150456 Forwards comments in opposition to Township of Lower Alloways Creek 800325 request for suspension of issuance of OL per 10CFR2 206 Delay not warranted WETTERHAHN.M.J Conner Moore & Corber 80/04/11 ip
- --8004150469 Comments in opposition to Township of Lower Alloways Creek 800325 request for suspension of issuence of OL per 100FR2 206. Unges denial due to untimeliness of petition & inadequacy of allegations re noncompliance ω/ΝΕΡΑ rules * Public Bervice Electric & Gas Co of New Jersoy * Conner. Moore & Corber 80/04/11 Spp
- 8004210291 Forwards response to Public Svc Electric & Gas Co of NJ comments re request of Lower Alloways Creek Township for suspension of moratorium of issuance of OL OL should not be issued until conclusion of ASLB hearing VALORE.C J Valore. C 80/04/15 5pp
- 8004280190 Forwards Director's decision under 10CFR2 206 denying 790803 & 31 petitions re issuance of OL Related FR notice encl
 DENTON, H R Office of Nuclear Reactor Regulation 80/04/16 1p

- --B0042B0195 Notice of issuance of Director's decision under 10CFR2 206 denying intervenors Coleman 790B03 & 31 petitions reissuance of OL.

 DENTON: HR Office of Nuclear Reactor Regulation B0/04/16 ip
- ~-8004280196 Director's decision under 10CFR2 206 denying interveners Coleman 790803 & 31 petitions re issuance of OL Operation of facility would result in substantial production cost savings to ratepayers DENTON.H R Office of Nuclear Reactor Regulation 80/04/16 40pp
- 8004300585 Responds to 791018 petitions requesting that Commission issue show cause order to suspend or revoke DL for Salem 1 & CPs for Salem 2 & Hope Creek 1 & 2 & stay issuance of DL for Salem 2 Request denied W/Director's decision

 DENTON: H R Office of Nuclear Reactor Regulation 80/04/18 ip
- ~~8004300590 Director's decision under 10CFR2 206 on E 2 A Coleman petition requesting that Commission issue show cause older re facilities OL 2 CP issuances Request denied DENTON.H R Office of Nuclear Reactor Regulation 80/04/18 6pp
- --8004300598 Notice of issuance 3 availability of Director's decision under 100FR2 206 on A & E Coloman petition requesting that Commission issue show cause order re facilities OL & CP issuances
 DENTO(), H R Office of Nuclear Reactor Regulation 80/04/18 2pp
- --8004300600 "Assessment of Impacts of Facilities on Shortnose Sturgeon, Acipenser Brevirostrum Lesuer " MASNIK, N T , WILSON, J H Orrice of Nuclear Reactor Regulation 80/03/31 ip

- BOO4030123 Responds to 790816, itr re plans to reopen THI-1.nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ No diseases resulted from THI DENTON. HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030129 Opposes rostant of TMI-1, const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety
 FOSTER, K. Affiliation Uninous /9/08/16 2pp
- P. Operating license stage documents $\ell \epsilon$ correspondence
- 8004230338 Confirms 800417 discussion w/DF Ross re util safety review group commitment to report to general manager of licensing & environ within engineering & coist dept Commitment refers only to low power test program & does not preclude mods ECKERT.R M Public Service Electric & Gas Co of New Jersey 80/04/18 | Ip
- BOO4250366 Responds to BOO107 Itr re OA requirements for diesel fuel oil Fuel is supplied from day tanks which are fed from 20,000 gallon storage tanks Lists Tech Spoc requirements re surveillance of fuel LIBRIZZI.F P Public Service Electric & Oas Co of New Jersey BO/04/21 | 1p
- G Inspection reports. IE Bulletins & correspondence
- BOO4080318 Submits response to 1E Bulletin 77-27 re loss of instrument control power & effect an ability to achieve cold shutdown Failure analysis on circuit-by-circuit basis to check bus loads & alarms 40% complete Submittal by BO1001 SCHNEIDER.F W Public Service Electric & Gas Co of New Jersey BO702/26. 2pp
- 8004170288 Forwards IE Insp Repts 50-272/79-32 & 50-311/79-37 on 791118-1215 No noncompliance noted BRUNNER, E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004170293 IE Insp Repts 50-272//9-32 t 50-311/79-37 on 791118-1215 No noncompliance noted Major areas inspected plant operations, including bours of facility, log t record review, review of licensee events, IE circulars t bulletins t followup items KEIM16,R R Region I, Philadelphia, Reactor Operations Nuclear Support Branch JOHNSON, D F, NORHOLM, L J Region I, Philadelphia, Office of the Director 80/02/20 20pp

- --8004220429 IF Insp. Repts 50-272/79-32 % 50-311/79-37 on 791118-1215 % 800109 Noncompliance nuted unauthorized individual approved tagging request w/o knowledge of responsible shift
 - SUPERVISOR
 KEINIG D.F. JOHNSON D.F. Region 1. Philadelphia, Reactor
 Operations Nuclear Support Branch MORRHOLM L.J. Region 1.
 Philadelphia, Office of the Director 80/02/20 21pp
- 8004240494 Responds to IF Sulletin ED-03 Interim findings of visual IONEAU474 Responds to F Sutter Education Investing Findings of Visual inspiralizate adsorber cells are adequate w/few exceptions. Investigation & evaluation are continuing Final rept expected by 800331
 SCHNEIDER F W Public Service Electric & Gas Co of New Jersey 80/03/19
 3pp
- 8004010447 Forwards response to [£ Bulletin 79-06C, "Nuclear Incident at Thi-Suppi 'Amalyses re inadequate core cooling uill be performed hitTL.R L Public Service Electric & Oas Co of New Jersey 80/03/28 Jp
- GOO4150299 Forwards IE Info Notice BO-12, 'Instrument Failure Causes Opening of PORV > Block Valve " No specific action or response necessary ORIER B H Region 5, Philadelphia, Office of the Director BO/03/31 | 19
- 8004070079 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia. Office of the Director 80/04/01 ip
- 8004110507 Forwards IE Into Notice 80-13, "GE Type SBM Control Suitches Defective CAM Followers " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004240346 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/02 1p
- 8004180185 Forwards IE Circulat 80-07, "Problems N/HPCI Turbing Oil Sys "No written response required GRIER.B M Region 1, Philadelphia, Office of the Director 80/04/03 ip
- 8004230455 Forwards IF Bulletin 79-03A, "Longitudinal Held Defects in ABME SA-312, Type 304 Stainless Steel Pipe " Action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004180276 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds." Written response required GRIER.B H. Region 1. Philadelphia. Office of the Director 80/04/07. 1p

8 Reportable occurrences, LERs & related correspondence

- 8004220084 PNU-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matt Cause unstated All utils w/pumps were notified NRC headquarters notified an 770612 HHITT, K U Region 2, Atlanta. Office of the Director 77/08/12
- 8004100611 Ack receipt of final deficiency rept re design defect in auxiliary feedwater storage tank water makeup CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/12 [p
- --B004100613 Final deficiency sept check valve 2DR-7 failed to meet applicable seismic Class E loading Caused by design defect AddI support will be completed by B00228 HARTIN, T.J. Public Service Electric & Gas Co. of New Jersey B0/02/15

V Operator Examinations

BO04030257 Provides add1 info per B00125 request Operator licensed for one unit of two-unit facility must take oral % written examination when applying for ficense on second unit Applicant must score min 80% overall to receive license COLLINS.P F Operator Licensing Branch B0/03/20 2pp

- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION F Security, medical, emergency tire protection plans
- 8004150177 Approves 80030/ revised cable tray firestop design for usp inside containment Revision makes minor changes to design approved 791214 Mods will not affect performance of firestop in preventing propagation of rire REID.R U Operating Reactors Branch 4 80/03/13 3pp
- 8004170209 Forwards results of NRC 800310 site visit to review status of emergency planning at facility REID.R N Operating Reactors Branch 4 80/04/02 6pp
- 8004280528 Responds to NRC 800327 request to incorporate vital area analysis results into physical security plan Amend 7 to security plan, submitted 791218 includes analysis results Requests verification of receipt of all five copies MATTIMOE. J Sacramento Municipal Utility District 80/04/21

G Adjudicatory correspondence

- 8004090187 Order granting extension of time until 800319 for NRC to DEANE,R H U S Court of Appeals 9th Circuit FREEMAN,K D California, State of 80/02/21 ip
- B004110074 Apologizes for not giving testimony at Sacramento hearings due to prior commitments Mods should incorporate state-of-the-art in safety of design & operation HAMMER.T J Affiliation Unknown B0/03/10 2pp
- 8004080705 Forwards licenses testimony by RA Dieterich in response to CA Energy Commission Issue 5-2 W/o encl BAXTER. T.A. Shaw, Pittman, Potts & Troubridge 80/03/11 1p
- 8004020454 Forwards Commission 800306 order to Met Ed mgt competence issues which may be relevant to proceeding LEMIS,8 H Hearing Branch 2 80/03/17 1p
- 8004030329 Forwards ACRS 800311 ltr re Bulletins & Orders Task Force recommendations, which may be relevant to proceeding LEWIS,8 H. Hearing Branch 2 80/03/20 1p
- ~~8004030333 Comments on Bulletins & Orders Task Force recommendations as result of 800306-08 ACRS 239th meeting Action plan review underway
 PLESSET M 8 ACRS - Advisory Committee on Reactor Safeguards
- B004010272 Forwards list of NRC admitted testimony which should be found following Transcript 1163 Requests that list be inserted in record of B0040B session
 LEWIS, B H Hearing Branch 2 80/03/24 2pp
- 8004010382 Requests that ltr 2 encl newspaper article be included in 800312 hearing record Protests misleading testimony of util anglineer Requests Emergency Preparedness Review team rept IBSER.H W Affiliation Unknown 80/03/25 2pp
- 8004080362 Forwards technical documents in response to ASLB request to be informed of 800226 incident analyses & implications NUREO-0647 re BBW apparent designed plant sensitivity will be transmitted when final LEWIS, S H Hearing Branch 2 80/03/25 2pp
- 8004080414 Forwards INPO-NASC "Analysis & Evaluation of Crystal River -Unit 3 Incident," as followup to 800325 ltr Forwards NUREG-0654.Vol 1 "Rept of Bulletins & Orders Task Force," for info to ASLB % parties W/o encl LEWIS.5 H Hearing Branch 2 80/03/26 ip
- 8004080329 Forwards NUREG-0645, Vol II, to ASLB & parties per Cole & Shon requests N/o encl LEMIS, S H Hearing Branch 2 80/03/27 ip
- 8904230090 Forwards Commission 800321 mamorandum & order reconsideration of Class 9 accidents beyond design basis in Black For Station proceeding BAXTER.T A Shaw. Pittman. Potts & Trowbridge 80/03/27 2pp
- 8004080322 Responds to CA Energy Commission 800321 request of B Mann for certain documents Crystal River event documents were provided in 800325 t 26 transmittals Mr Wing studies are in planning stage Task B-24 documents encl W/o encl LEWIS,S H Hearing Branch 2 80/03/28 2pp

- BOO4170109 Forwards notice of violation, notice of proposed imposition of civil penalties & order modifying license re operation of plant w/portions of ECCS in degraded conditions resulting from personnol eriols in implementing operating procedures STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/01 2pp
- --8004170115 Notice of violation from insp in Feb 1980 of Licence DPR-54 Noncompliance noted two valves in HPI cross-connect line closed & reactor critical w/only one HPI pump operable contrary to Tech Specs

 # Office of Inspection & Enforcement, Office of the Director BB/04/01 300
- ---8004170121 Notice of proposed imposition of civil penalties Util should pay civil penalties or protest by written answer within 20 days

 * Office of Inspection & Enforcement, Office of the Director 80/04/01 10
- --8004i70127 Order modifying Licence DPR-54 to include & implement administrative procedures requiring independent verification of valving line-ups & equipment operability when safety-related equipment is removed or placed into svc STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/01 Spp
- 8004030026 Memorandum of understanding between NRC % FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification COSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- GOO4110142 Forwards NRC testimony of HL Canter re SMVD competency to operate facility Supplements NRC testimony of AD Johnson & OB Zuetrig on Friends of the Earth Contention III(d) & ASLU Guestion 32
 ULACK,R L Hearing Branch 1 GO/04/02 2pp
- ---8004110151 NRC testimony of HL Canter re SMUD competency to operate facility Supplements NRC testimony of AD Johnson & OB Zwetzig on Friends of the Earth Contention III(d) & ASLB Question 32 Prof qualifications oncl CANTER, H L Region 5, San Francisco, Office of the Director 80/04/02
- 8004140482 Forwards Apr 1980 "Transient Response of B&W Designed Reactors," Graft NUREO-0667 NRC witnesses will be able to address rept during 800408 testimony & examination M/o encl BLACK.R L Hearing Branch 1 80/04/03 2pp

- 7906290854 Responds to 790411 ltr on reactor sefety, clarifying concerns re Davis-Bosse shutdown & goologic faults near Diable Canyon EIBERHIUT, D G Division of Operating Reactors 79/05/22 2pp
- 8004030263 Expresses confidence in util mgt expertise, public consciousness & sonse of accountability Supports continued operation of plant FLYNN,P Affiliation Unknown 80/02/27 1p
- 8004140122 Responds to 791227 itr by forwarding PA Emergency Mgt Agency booklet, "What You Bhould Know About Nuclear Incidents " Specific info may be obtained from Sacramento County Ofc of Emergency Svcs President Carter 791207 statement encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 13pp
- 8004040001 Requests nuclear development to provide for agricultural future demands in addition to development of all energy sources if proven not detrimental to environ Sites facility as model nuclear plant Supports continued operation WILCOX.L. Affiliation Unknown 80/03/07 1p
- 8004030012 Demands immediate shutdown of plant, before realities of nuclear accident become reality in CA SCHASER, H. SCHWEID, S., KLEIN, B. Affiliation Unknown 80/03/15 3pp
- P Operating license stage documents & correspondence
- 7905190134 Forwards revised radiological effluent Tech Specs which include requirements of NUREG-0472
 MATTIMOE, J J Bacramento Municipal Utility District 79/05/15 ip
- --7905i90i37 Revised radiological effluent Tech Specs including cold & hot shutdown & protection instrumentation logic * Sacramento Municipal Utility District 79/05/30 300pp

- 8004040005 Furwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 to 800204 reactor trip at Crysta) River Sequence of events 5 planned corrective actions also encl
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit into from plants to Dathesda Operations Ctr EISENHUT.D © Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs"
 # Division of Operating Reactors 80/02/21 28pp
- 8004030230 Natification of 800318 meseting w/all operating BEW reactor licensees in Bethesda/Nb to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID.R W Operating Reactors Branch 4 80/03/14 2pp
- 8004080677 Notification of 800327 meeting w/B&W.DDE & util in Bethesda, MD to discuss lead test assemblies using U mill tailings SANDS.S P Reactor Sefety Branch 80/03/18 2pp
- 8004020449 Discusses hydraulic shubber surveillance performed during 1980 refueling outage Testing of Grinnel shubbers not needed during followon tests Rebuilding 2 testing of failed shubbers fulfilled Tech Specs requirements
 REID.R N Operating Reactors Branch 4 80/03/19 3pp
- 8004100115 Forwards results of NRC-sponsored vital area analysis for util for info & action Requests notification of revisions within 30 days of receipt of ltr Encl withheld (ref 10CFR2 790)
 REID.R W Operating Reactors Branch 4 80/03/27 3pp
- 8004100241 Forwards Amend 29 to License DPR-54.safety evaluation & notice of issuance & availability
 REID.R W. Operating Reaclors Branch 4 80/03/31 3pp
- --8004100246 Amend 29 to License DPR-54, terminating ECCS exemption to 10CFR50 46 for fuel loading used during Cycle 4 REID,R W Operating Reactors Branch 4 80/03/31 27pp
- --8004100251 Safety evaluation supporting Amend 29, to License DPR-54 * Office of Nuclear Reactor Regulation 80/03/31 13pp
- ---8004100255 Notice of issuance & availability of Amend 29, to License DPR-54
 REID,R W Operating Reactors Branch 4 80/03/31 2pp
- B004210328 Symmary of 800222 meeting w/BbW owners group in Bethesda,Md re abnormal transient operational guidelines BEIDEL, B i. Reactor Systems Branch 80/04/02 4pp
- B00425036B Summary of B00403 meeting w/utils,BbW, NUB Corp & McGraw-Hill in Bethesda,MD re draft MUREO-0667, "Transient Response of B&W-Designed Reactors" CAPRA,R A Standardization Branch 80/04/04 7pp
- 8004180490 Notification of 800423 meeting w/utils & B&W in Bethesda.MD to discuss implementation of recommendations by B&W Reactor Transient Response Task Force CAPRA.R A Standardization Branch 80/04/05 Ppp
- BOO4150439 Responds to NRC request for info to suppl 791017 response to NRC re grid voltage degradation Info will be submitted by 800425 MATTIMOE, J J Gacramento Municipal Utility District B0/04/08 1p
- 8004160234 Submits add1 info requested by NURCG-0578 postimplementation review team re Category A & 8 items MATTIMOE, J J Sacramento Municipal Utility District 80/04/19
- 8004210314 Notifies of fulfillment of conditions stipulated in order for mod of license which required licensee to adopt & implement administrative procedures for independent verification of valving lineups & aquipment operability MATTIMOE, J J Sacramento Municipal Utility District 80/04/14 200
- 8004220568 Hithdraws 800308 commitment concerning Part B. Item 7 of NRC 800226 ltr re proposed mod of auxiliary feedwater sys Operating Procedure A 51 Approval would imply plant could be safely shutdown w/o offsite power or dissel generators MATTIMDE. J Sacramento Municipal Utility District 80/04/14 2pp

- 8004220709 Recommends that removal of ref to 3 2 weight percent re U~235 be incorporated into next reload submitta! MATTIKOE,J J Sacramento Municipal Utility District 80/04/14 ip
- 8001230498 Revises 600107 response to NUMEG-0578 Category A. Item 2 2 % bromsite technical support ctrile interim communications operations MATTIMME J J Batramento Municipal Utility District 80/04/17 3pp
- 80042903'3B Forwards Re-islon i to inservice testing program Submits program changes & request for relief MATTIMDE. J. Sacramento Municipal Utilisty District 80/04/17 200
- --8004290524 Revision 1 to inservice testing program re ASME code class valve testing requirements * Sacramento Hunicipal Utility District 80/04/17 11pp
- 4 inspection reports, IF Bulletins * correspondence
- 6004040094 Forwards 16 Insp Rept 50-312/79-29 on /91213 No honcompliance noted BODK.H E Region 5. San Francisco, Fuel Facility & Materials Safety Branch 60/02/22 2pp
- --8004040055 lE Insp Rept 50-312/79-29 on 791213 No nonrompliance noted Major areas inspected one shipment of low level raduaste for disposal BOOK, H E . PECK, C C Region 5. San Francisco, Fuel Facility & Materials Safety Branch THOMAS, R D Region 5. San Francisco, Office of the Director 80/02/21 App
- G004280168 Forwards IE Insp Rept 50-312/80-05 on 800130-0201,12-15 & 17-18 No nancompliance noted SPENCER. G 5 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004280180 lE Insp Rept 50-312/80-09 on 800130-0201,12-15 & 17-16 No noncompliance noted Major areas inspected licenses activities performed in response to IE Bulletin 79-02 & ectivities performed for inservice insp for 1980 DDDS.R T Region 3, San Prancisco, Reactor Construction & Engineering Support Branch NARBUIT,P P Region 5, San Francisco, Office of the Director 80/03/03 7pp
- 6004210226 Forwards IE Insp Rept 50-312/80-01 on B00117-26 No noncompliance moted CREMS.J L. Region 5, Ban Francisco, Reactor Operations Nuclear Support Granch 60/03/10 2pp
- ~-8004210229 IE Insp Rept 50~312/80~01 on 800117-26 No noncompliance noted Major areas inspected progress in completion of required fire protection mods, major maint & surveillance performed during tefueling outage FAULARNBCRRY. 8 Region 5. San Francisco. Reactor Operations Nuclear Support Bianch Z(METZIG, 0 B. Region 5, San Francisco. Office of the Director 800/03/07 4pp
- 8004040126 Ack receipt of 800827 ltm informing NRC of steps taken to correct violations noted in 1E Insp Pept 50-312/79-17 SPENCER G S Region 3, San Francisco, Reactor Construction & Engineering Support Branch 80/03/17 ip
- --8004040137 Responds to NRC 800201 ltr re violations noted in IE Insp. Rept 50-312/79-17 Corrective actions revisions in Procedure MT 017 were approved 800202 2 insp. data has been reviewed according to revised acceptance criteria. HALBRIDGE, W.C. Bacramento Municipal Utility District 80/02/27
- --8004040146 Forwards IE Insp Rept 50-312/79-17 on 790724-25,0801-02,20, 27, \$ 800110-11 \$ notice of violation SPENCER: Q S Region 5. 2an Francisco, Reactor Construction & Engineering Support Branch 80/02/01 2pp
- --8004040151 Notice of violation from 1889 on 790724-25,0801-02,20,27 & 800110-11 * Region 5, San Francisco, Office of the Director 80/01/31 ip
- --8004040i61 IE Insp Rept 50-312/79-17 on 790724-29.0801-02.20.27 & 800110-11 Noncompliance noted failure to fill in acceptance criteria columns on data sheets for insp of concrete fasteners DDDD9.R 7 Region 5. San Francisco, Reactor Construction & Engineering Support Branch NARBUT, P D: HAIST, D P Region 5. San Francisco, Office of the Director 80/01/31 9pp

- 8004210422 Forwards IE Insp Rept 50-312/80-08 on 800304-05 No noncompliance noted SPERICER, G S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/03/21 2pp
- --8004210428 IE insp Rept 50-312/80-08 on 800304-05 No noncompliance noted Najor areas inspected activities performed in response to IE Sulletin 79 02. "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts"

 DDDDS: AT Region 5. Sam Francisco, Reactor Construction & Engineering Support Sianch NARBUT.P P Region 5. San Francisco, Office of the Director 80/03/20 Spp
- 8004210231 Ack receipt or 800312 itr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-312/80-02
 8000, HE Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/03/25 ip
- --8004210237 Responds to NRC 800221 Itr re violations noted in IE Insp Rept 50-312780-02 Corrective actions Maint Procedure M-112 revised to require two insps.cleanings & completion of checklist of items per week MALBRIDGE, W C Sacramento Municipal Utility District 80/03/12 2pp
- --8004210241 Forwards IC Insp Rept 50-312/80-02 on B00121-25 & notice of violation B004,H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 60/02/21 2pp
- --8004210243 Notice of violation from insp on 800121-25

 * Region 5, San Fiancisco, Office of the Director 80/02/20 is
- --800421024B IE Insp Rept 50-312/80-02 on 800121-25 Noncompliance noted total childrene contentiation in plant effluent exceeded limit BOOK. HE Region 5, San Francisco, Fuel Facility & Materiale Safety Branch FISH. R F Region 5, San Francisco, Office of the Director 80/02/20 12pp
- 8004280214 Forwards IE Insp Rept 50-312/80-04 on 800212-15,28-29 & 0303-07 No noncompliance noted CREMS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch ZMFTXIO, G B Region 5, San Francisco, Office of the Director 60/03/26 2pp
- ~-8004280226 IE Insp Rept 50-312/80-04 on 800212-15,28-29 % 0303-07 No noncompliance noted Major areas inspected status of completion of selected fire protection mode, completion of required mods & maint during refuling outage FAULKENDERRY.8 Region 5. San Francisco, Reactor Operations Nuclear Support Branch ZMETIGO.0 B Region 5. Ban Francisco, Office of the Director GD/03/25 App
- 8004150218 Forwards IC lafo Notice 80-12, "Instrument Failure Causes Opening of PDRV & Block Valvo " No specific action or response necessary ENGELKER,R H Region 5, San Francisco, Office of the Director BO/03/31 1p
- BOD4100108 Forwards IC Ciscular BO-OS, "Emergency Diasel Generator Lubricating Dil Addition & Oneito Supply "No written response required ENGELKEN.A H. Region 5. San Francisco, Office of the Director BO/O4/O1 ip
- 8004110115 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/04/02 1p
- 8004220050 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN.R II Region 5, San Francisco, Office of the Director 80/04/02 1p
- 8004180195 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Dil Sys " No written response required ENGELKEN,R HE Region 5. San Francisco. Office of the Director 80/04/03 ip
- 8004230360 Forwards 1E Bulletin 79-03A: "Longitudinal Held Defects in ABME 8A-312. Type 304 Stainless Steel Pipe " Action required ENGELKEN.R H Region 5. San Francisco: Office of the Director 80/04/04 1p
- BOD4300425 Ack receipt of BOO319 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/80-03 CREMS(J L Region 5, 9an Francisco, Reactor Operations Nuclear Support Branch BO/04/04 ip

- --8004300433 Responds to NRC ltr re violations noted in IE Insp Rept 50-312/80-03 Corrective actions appropriate individuals have been made cognitant of prompt reporting requirements MATTIKOE. J Sacramento Municipal Utility District 80/03/19 2pp
- --8004300437 Forwards IE Insp Rept 50-312/80-03 on 800102-31 & notice of violation CREW5.J L Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/02/28 2pp
- ---8004300448 Notice of violation from insp on 800102-31
 * Region 5: Ban Francisco, Office of the Director 80/02/26 ip
- --8004300453 IE Insp Rept 50-312/80-03 on 800102-31 Noncompliance noted RO not reported at proper time CANTER,H L. O'BRIEN,J P Region 5, San Francisco, Office of the Director FAULKENBERRY Region 5, San Francisco, Reactor Operations Nuclear Support Dranch 80/02/26 12pp
- 8004220190 Forwards IE Bullstin BO-OB, "Exam of Containment Liner Penetration Welds " Written response required ENGELKEI,R H Region 5, San Francisco, Office of the Director BO/04/07 lp
- R Periodic operating reports & related correspondence
- 8004160266 Forwards monthly operating rept for Mar 1980 RDDR10UEZ,R J Sacramento Municipal Utility District 80/04/03 1p
- --B004i60270 Monthly operating rept for Har 1780 CCLOMBO,R W Sacramento Municipal Utility District B0/03/3i Bao
- 8 Reportable occurrences, LERs & related correspondence
- BCD4070312 Forwards LER BO-015/01T-0 MATTINGE, J J Bacramento Hunicipal Utility District 80/03/25 200
- --B0040703ió LER 80-015/01T-O on B00312, during visual insp of cycle 3 discharge fuel, approx 4 inches of cladding discovered missing from fuel assembly (C47 Caused by cladding defect on one pin Insignificant amounts of fuel dispersed COLOMBO, R W Sacramento Municipal Utility District 80/03/25
- BOD4140397 Forwards LER 80-016/03L-0 MATTIMOE, J J Sacramento Municipal Utility District 80/04/03 2pp
- --B004140405 LER B0-016/03L-0 on B00310, while performing IE Bulletin 79-14 requirements, seismic analysis of supports 18-50052-1A, 18-50062-1A & 18-23626-1 indicated seismic stress would exceed allowable limit Supports modified COLOMBO, R W Bacramento Municipal Utility District B0/04/03 to
- 8004210259 Forwards LER 80-017/03L-0 MATTIMGE, J Sacramento Municipal Utility District B0/04/10 2pp
- ---8004210262 LER 80-017/03L-0 on 800322.after manually opening 8FV-25003 several turns to increase level in pressurizer valve failed to close electrically Caused by excessive wear to shaft clutch & clutch gear Defective parts replaced CDL OMBO.R W Sacramento Municipal Utility District 80/04/10 ip
- 8004270485 Forwards LER 80-018/03L-0 MATTINGE, J J Sacramento Municipal Utility District 80/04/11 ip
- --9004270491 LER 80-018/03L-0 on 600324, pressurizer gas sample valve. SFV-72502 failed to close Caused by wire separation in valve control circuitry Wire reconnected to terminal lug COLOMBO, RW Sacramento Municipal Utility District 80/04/11
- 8004220731 RO 80-23 on 800444, manager of nuclear operations was informed of receipt of Dresser Industries notification itr implying that no representation will be provided concerning valve reliability & operation Cause unstated RODRIGUEZ, R J Sacramento Municipal Utility District 80/04/15 is

- 8004290454 Forwards LER 80-021/04T-0 MATTIMOE, J. J. Sacramento Municipal Utility District 80/04/21 200
- --B004290465 LER 80-021/01T-0 on 800318, review of previous month plant effluent records indicated that effluent pH exceeded 8.5 for approx 3-h Caused by canal pumping station being out of svc for approx two months COLDMBO.R W Sacramento Municipal Utility District 80/04/21
- BOO4300421 Advises that RO BO-20 in BOO417 ltr incorrectly identified NAMCO switches on safety-related valves as functional during accidents Switches utilized only for light indication RO BO-20 will be deleted from LER file MATTIMOE, J J Sacramento Municipal Utility District BO/04/23 (p
- T Hearing transcripts on non-antitiust matters
- 8004090257 NRC testimony re ASLB question concerning CA Energy Commission Contention 1-2 on natural circulation if reactor coolant pumps trip as result of main feedwater loss.core can be adequately cooled by natural circulation NDRIAN.P E Analysis Branch 80/03/01 Bpp
- 9004100542 Testimony of D Nix,CA Energy Commission,re controlled filtered venting NIX,D California, State of GO/03/11 23pp
- 8004240457 Transcript of 800408 evidentiary hearing in Sacramento.CA Pp 1210-1375 * Atomic Safety and Licensing Board Panel 80/04/08 166pp
- 8004220774 Transcript of 800410 meeting in Sacramento, CA Pp 1569-1793 * Atomic Safety and Licensing Board Panel 80/04/10 224pp
- 8004220407 Transcript of 800411 meeting in Satramento.CA Pp 1794-1984 * Atomic Safety and Licensing Board Panel 80/04/11 190pp
- 8004250237 Transcript of G00414 meeting in Sacramento,CA Pp 1985-2159 * Atomic Safety and Licensing Board Panel B0/04/14 174pp
- 8004250245 Transcript of 800416 hearing in Sacramento, CA Pp 2344-2562 * Atomic Safety and Licensing Board Panel 80/04/16 210pp
- 8004250241 Transcript or 800417 hearing in Sacramento CA Pp 2563-2776 * Atomic Safety and Licensing Board Panel 80/04/17 234pp
- DOCKET 50-313 ARKANSAS NUCLEAR ONF. UNIT 1

 F Security, medical, emergency & fire protection plans
- 8004010384 Advises that all fire protection mods will be complete by 801001 except Unit 2 Items 3 14 & 3 18 Hardware mods for Item 3 18 scheduled for Itar 1981 cold shutdown Smoke detector sys for Item 3 14 will be installed when complete TRIMBLE, D C Arkansas Power & Light Co 80/03/26 2pp
- 8004220427 Submits info re mod performed on reactor coolant pumps.fire protection Itom 3 15 Soventeen photographs encl Drawings available in Central Files only TRIMBLE.D C Arkansas Power & Light Co 80/04/16 2pp
- --8004220431 "Motor Assembly " List of components encl # Allis-Chalmers Corp 70/12/30 7pp
- --8004220436 "9000 Harsepower Reactor Coolant Pump Motor Outline "
 * Allis-Chalmers Corp 70/09/02 19
- --8004220447 "Circulating Oil Sys Picture " Sheet 1 List of components enc!
 * Allis-Chalmers Corp 70/03/04 4pp
- ---8004220450 "Backstop Lubrication Sys Picture " Sheet 1 List of components enc! + Allis-Chalmers Corp 70/08/03 4pp
- --8004220453 "Lower Bearing Oil Piping Picture" List of components encl * Allis-Chalmers Corp 69/11/24 3pp

- --8004220454 'Upper Bearing Oil Piping Picture " List of components encl * Allis-Chalmers Corp 69/41/24 2pp
- --8004220455 "Piping & Instrumentation Diagram Control Rod Drives & Miscellaheous Coolant Pump Connections "

 Gechtel Corp 6600 79/10/25 1p
- H General correspondence
- 8004170240 Requests that util be required to submit EIS before authority is granted to expand nuclear waste fuel storage pools at site Prior EIS insurficient PETERS.B. Arialiation Unknown 80/04/09 2pp
- I Financial information
- 8004220535 Annual Financial Rept 1979 * Middle South Utilities, Inc 79/12/31 40pp
- 8004150235 Forwards Annual Financial Rept 1979
 TRIMBLE,D.C. Arkansas Power / Light Co. 80/04/10 ip
- ---B004150239 Annual Financial Rept 1979 * Arkansas Power / Light Co 60/0 80/04/10 46pp
- P Operating license stage documents & correspondence
- 8004110508 Summarizes walkdown re identifying seismic Category [piping & safety-related sys attached to or in close proximity to concrete block walls Numbers are pieliminary & may be adjusted upon survey completion on 800100 TRIMBLE.D C Arkanses Power & Light Co 80/01/28 ip
- BO04040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800206 reactor trip at Crystal River Sequence of events & planned corrective actions also encl
 DENTON.KR Office of Nuclear Reactor Regulation B0/03/06 26pp
- 8004070160 Forwards NRC evaluation of actions taken to satisfy Category A requirements of TMI-2 Lessons Learned All Category A requirements have been met satisfactorily w/exception of Item 2 1 7a for Unit 2 REID.R W Operating Reactors Branch 4 80/03/10 2pp
- --8004070165 "Evaluation of Licensee Compliance W/Category A Items of NRC Recommendations Resulting from TMI-2 Lassons Learned " Operating Reactors Branch 4 80/03/31 14pp
- --8004070170 "Evaluation of Licensee Compliance H/Category A Items of NRC Recommendations Resulting from THI-2 Lessons Learned " + Operating Reactors Branch 4 80/03/31 13pp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/2: 28pp
 - ification of 800318 meeeting w/all operating B&W reactor SethesdardD to evaluate implications of Crystal event & response to IE Bulletin 79-27 ing Reactors Branch 4 80/03/14 2pp
- low pressure turbine rotors Actions necessary to minimize stress corresson cracking will not be known until Mastinghouse dentifies causes of cracking TRIMBLE.D.C. Arkansas Power & Light CO. 80/03/24 1p
- 8004110559 Provides add1 info re implementation of requirements set forth in Item 2 1 7a of NUREO-0578 Commitment to install safety-grade sys prior to Bioloi required no later than 15 days after receipt of itr EISENHUT.D 0 Division of Operating Reactors 80/03/27 2pp
- 8004030209 Provides descriptions of long-term Lessons Learned changes to plant shielding & modified sampling sys to minimize personnel exposure during worst case accident conditions TRIMBLE.D C Arkansas Power & Light Co 80/03/31 7pp

- 8004070287 Forwards proposed change to Paragraph 15 2 2 constituting Revision 5 to APL-TOP-1A. "GA Manual Nonconforming Matl.
 Parts or Components "
 TRIMBLE D C Arkansas Power / Light Co 80/03/31 1p
- --BO04070403 Proposed change to Paragraph 15 2 2 of "QA Manual, Nonconforming Mati.Parts or Components" * Arkansas Power : Light Co ALP-TOP-1A 80/03/31 2pp
- 8004150304 Forwards brief description of safety evaluation for design changes completed in 1979 which require safety evaluation per 10CFR50 59 Mods include emergency cooling pond change, firehouse station addition & increase of sprinkler coverage TRIMBLE, D C Arkansas Power & Light Co 80/03/31 5pp
- 8004170086 Forwards description of safety evaluation for design changes completed in 1979
 TRIMBLE.D C Arkansas Power & Light Co 80/03/31 App
- 8004240506 Requests add1 info re once-through steam generator auxiliary reeduater thermal sleeve/collar weld attachments Gracking reported at weld attachment between collar & thermal sleeve HADSEN, G.L. Region 4, Pallas, Reactor Operations Nuclear Support Branch 80/04/01 2pp
- ~-80042405[1 Advises that BBW prepared & transmitted to affected utils info re failure discovered at weld attachment between collar & thermal sleeve on auxiliary feedwater nozzles of steam generator NRC should contact utils for info TAYLOR, J N Babcock & Wilcox Co 80/03/17 ip
- 8004210328 Summary of 800222 meeting w/B/W owners group in Bethesda. Ad re abnormal transient operational guidelines SEIOEL.B L Reactor Systems Branch 80/04/02 App
- 8004070344 Informs that Section 2 & 3,Revision 5 of QA manual re diesel generator fuel oil meets Tech Spec requirements per 800107 request TRIMBLE.D C Arkansas Power & Light Co 80/04/03 ip
- 8004220788 Requests Class III fee re 800ii5 reactor vessel surveillance program Payment should be remitted within 15 days after receipt of ltr MICLER.W D License Fee Management Branch 80/04/04 ip
- 8004250368 Summary of 800403 meeting w/utils,8&W.NUS Corp & McGraw-Hill in Bethosda.MD re draft NUREG-0667. "Transient Response of B&W-Designed Reactors " CAPRA.R A Standardication Branch 80/04/04 7pp
- ROO-1180490 Notification of 800423 meeting w/utils & N&W in Bethesda.MD to discuss implementation of recommendations by B&W Reactor Transient Response Task Force CAPRA.R A Standardization Branch 80/04/05 2pp
- 8004160185 Forwards Class III fee for review of 800115 reactor vessel surveillance program, per NRC 800213 & 0404 ltrs
 TRIMBLE, D.C. Arkansas Power & Light Co. 80/04/11 2pp
- 8004210148 Supplements 800118 itr re Lessons Learned Task Force implementation of RCS venting Util will install remotely operated reactor vessel head vent provided acceptable vent location can be found TRIMBLE.D C Arkansas Power & Light Co 80/04/11 1p
- 8004290137 Forwards safety evaluation of inservice testing program & relief request WANG: A Plant Bystems Branch BD/04/11 ip
- --8004290138 Safety evaluation of inservice testing program Util should be granted relief from ASME Section XI requirements, * Plant Systems Branch 80/04/11 17pp
- 8004220471 Provides clarification releast to show effects of various single power failures Subsequent to power supply upgrade, test will be performed to verify non-nuclear instrumentation sys design & power supply design mod TRIMBLE, D.C. Arkansas Power & Light Co. 80/04/14 10
- 8004290517 Forwards safety sequence diagrams, event trees developed from safety sequence diagrams & suziliary diagrams on behalf of B&W owners group, in response to NRC 800222 request Diagrams withheld (ref 10CFR2 790)
 TAYLOR, J H Babcock & Wilcox Co 80/04/16 2pp

- 8004240380 Advises that 800416 commitment to perform tests to show various single power failures for NNI-X & NNI-Y cabinets have been changed Per conversations w/G Vissing test will be performed involving 120 VAC transfer switch power loss RUETER.D A Arkansas Power & Light Co 80/04/18 App
- B004270244 Responds to B00327 ltr concerning Lessons Learned Task Force implementation re automatic initiation of emergency feedwater Specifics of proposed design are still under evaluation NUREO-0667 requirements may need incorporation TRIMBLE.D C Arkansas Power & Light Co B0/04/23 lp
- Q Inspection reports, IE Bulletins & correspondence
- B004090151 Forwards IE Insp Repts 50-313/80-01 & 50-368/80-01 on B00107-18 & notice of violation MADSEN,G L Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/02/01 Rpp
- --B004090153 Notice of violation from insp on B00107-18
 * Region 4. Dallas: Office of the Director 80/02/01 2pp
- --8004070159 IE Insp Repts 50-313/80-01 & 50-368/80-01 on 800107-18
 Noncompliance noted data sheets recorded relay setting only
 & did not contain sufficient info & calibr & testing program
 for protective relaying was deficient in procedures
 SPANOLERIR G , SMITHIR , MICHIERMANT F Region 4, Dallas, Office
 of the Director 80/02/01 6pp
- 8004100315 Forwards IE Insp Repts 50-313/80-02 & 50-368/80-02 on 791222-800121 & notice of violation MADSEN.O L NRC Regional Offices 80/02/08 2pp
- --8004100324 Notice of violation from insp on 791222-80012i * NRC Regional Offices 80/02/06 ip
- --B004100335 IE Insp Repts 30-313/80-02 & 50-368/80-02 on 791222-800121 Noncompliance noted failure to adhere to requirements of test procedure JOHNSON, W D , CALLAN, L J , WESTERMAN, T F (RC Regional Offices 80/02/04 800
- 8004250044 Confirms 800131 telcon re status of structural analysis of concrete block walls supporting Beismic Category 1 pipe hangers per 1E Bulletin 79-02 Analysis shows five hangers are structurally adequate for inertia forces & hanger load TRIMBLE.D C Arkansas Power & Light Co 80/02/12 3pp
- BOO4040087 Forwards IC Insp Repts 50-313/79-24 & 50-368/79-23 on 791109 No noncompliance noted MADSEN,O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch BO/02/26 2pp
- --B004040094 IE Insp Repts 30-313/79-24 & 50-368/79-23 on 791109 No noncompliance noted Major areas inspected current NRC & DOT regulations, current requirements of waste burial firms, instructions & operating procedures & audit program HARRISON, H C Region 4, Dallas, Office of the Director BROWN, O D Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/01/16 4pp
- 8004090143 Ack receipt of 800222 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-01 & 50-348/80-01.

 HADBEN,O.L. Region 4. Dailas, Reactor Operations Nuclear Support Branch 80/03/05 ip
- --8004070148 Responds to NRC ltr re violations noted in IE Insp Repts 50-313/80-01 & 50-368/80-01 Corrective actions comprehensive program under development for scheduling & performance of relay insp & testing Program will be completed by Nov 1980 TRIMBLE, D C Arkansas Power & Light Co 80/02/22 3pp
- 8004250293 Forwards 1E Insp Repts 50-313/80-04 & 50-368/80-04 on B00131 & 0201 No noncompilance noted BROWN.0 D Region 4. Dallas, Fuel Facility & Materials Bafety Branch. B0/03/17 2pp
- ---8004250299 IE Insp Repts 50-313/80-04 & 50-368/80-04 on 800131 & 0201 No nuncompliance noted Major areas inspected practices of licensee health physics personnel & maint contracted personnel BROWN.0 D Region 4, Dallas, Fuel Facility & Materials Safety Branch HESTERMAN.T F , JOHNSON, H D Region 4, Dallas, Office of the Director 80/03/13, 8pp

- 8004010416 Notifies that response to IE Bulletin 79-27 re loss of ac power supply to non-nuclear instrumentation buses will be provided by 800401 Delay caused by expansion of review to include Crystal River-3 event
 RUETER, D.A. Artansas Power & Light Co. 80/03/27 1p
- 8004150231 Forwards 1E Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary SEVFRIT.K V Region 4, Dallas, Office of the Director 80/03/31 to
- 8004080666 Forwards IC Circular 80-05, 'Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/01 10
- BOO4110097 Forwards JE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required SEYFRJT,K V Region 4, Dallas, Office of the Director 80/04/02
- 8004180493 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/02 ip
- BOO4180159 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director BO/04/03
- 8004230324 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pips " Action required SEYFRIT.X V Region 4, Dallas, Diffice of the Director BO/04/04 tp
- R Periodic operating reports & related correspondence
- 8004010216 Forwards "Intake Impingement Monitoring for Feb 1980 " TRIMBLE D C Artenses Power 5 Light Co 80/03/25 ip
- --B0040(0217 "Intake Impingement Monitoring for Feb 1980 " # Artansas Power & Light Co 80/03/22 lipp
- 8004210217 Forwards monthly operating rept for Har 1980 TRIMBLE.D C Arkansas Power & Light Co 80/04/11 1p
- --8004210220 Monthly operating rept for Nar 1980 BRAMLETT.L S Arkansas Power & Light Co 80/04/11 Spp
- 8004290361 Forwards results of impingement monitoring at facility intake, during Mar 1980 TRIMDLE.D C Arkansas Power & Light Co 80/04/25 1p
- --8004270366 Results of impingement monitoring at facility intake, during Mar 1980 * ATKANSAS Power & Light Co 80/04/22 20pp
- S Reportable occurrences, LERs & related correspondence
- 78iii00178 Describes 7809i6 event at sub; facil auto transfer of auxillary loads on both units to startup transformer #2 w/consequent overload Recommends licensee be advised of nonconformance w/0DC-i7 & modify his design ROSA,F Power Systems Branch SATTERFIELD.R Electric, Instrumentation & Control Systems Branch 78/11/01 8pp
- BOOA280487 RO 30-313/80-007 on BOO315, BtW notified util decay heat pumps contain making wear rings of unequal hardness value Making wear rings could gall & lock up BtW recommends replacement Decay heat pumps are functioning normally O'HANLON, J P Arkansas Power & Light Co BO/03/17 2pp
- 8004020349 Forwards LER 80-007/01T-0 TRIMBLE, D C Arkansas Power & Light Co 80/03/28 1p
- --BOD4020353 LER BO-007/01T-D on BOD314.B&W advised that mating wear rings on double suction pump could cause pump failure during accident conditions Caused by failure to document design revision on pump design drawlings SHIVELY.C N. Arkansas Power & Light Co 80/03/28 ip
- 8004140328 Forwards LER 80-005/03L-0 TRIMBLE, D C Alabama Power Co 80/04/07 in

- --BOQ4140333 LEN BU-U05/03L-O on 800336.during scheduled surveillance test or P7-A.CY-2617 alve railed to close remote electrically Gaused by valve finding in closed position Valve sten repacted; b proper operation verified DRAFLETT L S Alabama Power Co 80/04/07 1p
- 8004150630 Forwards LER GU-005/03L-0 TRIMBLE D C Arkansas Power / Light Co 80/04/07 1p
- --8004150641 LER 80-005/0% -0 on 800306 during scheduled surveil; ance test or P7-A, steam supply valve CV-2617 failed to close remote electrically Laused by valve binding in closed position Valve stem repacted BRAMLETT. L. S. Arkansas Power 2 Light Co. 80/04/07 1p
- 6004140356 Forwards LER 60-010/03L-0 TRIMBLE.D C Alabama Power Co 60/04/08 1p
- --BO04140360 LER 60-010/03L-0 on 800307-sys reviews per IE Bulletin 79-14 found hangers inaperable Cause not stated Hangers repaired 5 mods made by revision to DCP 80-D-1207 List of hangers enc!

 BRAMLETT.L S Alabama Power Co 80/04/08 2pp
- 8004150541 Forwards LER 80-010/03L-0 TRIMBLE:D C Arkansas Power & Light Co 80/04/08 1p
- --8004i50549 LER 80-010/03L-O on 800307, based on sys reviews per IE Bulletin 79-14, attached list of hangers found to be inoperable Affected hangers were modified 2/or repaired within time linit per Tech Specs BRAMLETT, LS Artansas Power & Light Co 80/04/08 2pp
- 800423047i Forwards LER 80-006/04L-0 TREMBLE, D.C. Arkansas Power & Light Co. 80/04/16 1p
- --8004230473 LER BG-006/04L-0 on BOD31B, average gross release rate for Jan-Mar 1980 found to be 4 3% of max permissible concentration, exceeding Tech Specs Major portion caused by reactor blug purge in Jan
 BRAMLETT. L.S. Arkansas Power & Light Co. 80/04/16 1p
- 6004290374 Forwards LER 80-008/03L-0 TRIMBLE, D.C. Arkansas Power & Light Co. B0/04/22 1p
- --8004290385 LER 80-008/03t-0 on 800324.while performing surveillance tests typess flow was observed to be zero due to failure of CV-212t in closed postion Gauset by blown control fuze Fuse replaced & velve proved opprable BRAMLETT.L G Arkansas fower & Light Co 80/04/22 1p
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & tire protection plans
- 8004300012 Forwards sys description & operation instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimilis traffix KEPPLER, J.C. Region 3, Chicago, Office of the Director 80/03/20 2pp
- B004080544 Forwards evacuation time estimates in response to NRC 791129 info request Time required to evacuate schools & nursing homes under adverse & favorable conditions assumed to be 2-h after notification & 4-h for hospitals DDLAN. J E Indiana & Bichigan Electric Co 80/04/01 21pp

- J Insurance & indemnity information
- 8003140324 Foruards Endorsement 35 to MAELU Policy MF-79, Endorsements 42 & 43 to NELIA Policy NF-206, Endorsement 3 to MAELU Binder XB-45, Endorsement 4 to MAELU Binder XB-45, Endorsement 5 to NELIA Binder EB-55 Endorsement 4 to NELIA Binder EB-54 HUNTER, R S Indiana 7, Michigan Electric Co 80/04/03 9pp
- P Operating license stage documents & correspondence
- 8004020457 Forwards NRC safety analysis of tracking discovered in feedwater sys Util regair program, nondestructive insps & leakage testing are adoquate to insure that integrity of feedwater piping will be maintained SCHWENCER, A Operating Reactors Branch 1 80/02/25 App
- GOO4150138 Forwards request for add1 into re review of 791207 request for amend to reflect proposed mods to auxiliary feedwater sys
 SCHMENCER.A Operating Reactors Branch 1 80/02/27 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D O Division of Operating Reactors 80/03/12 Spp.
- --8004030118 "Nuclear Data Lin's Specs "
 # Division of Operating Reactors 80/02/21 28pp
- 8004210415 Advises that facilities will be using Models CN6-80A.7-100. CNSI-21-300 / CNSI-14-195-H for shipment of radioactive maths DOLAN.J E Indiana & Michigan Electric Co 80/03/17 ip
- 8004240442 Approves review re potential boron dilution incidents at facility, per 770915 Itr about incident involving contents of spray additive tank FSAR analysis represents most limiting case No further action necessary SCHMENCER. A Operating Reactors Branch 1 80/03/19 2pp
- 8004100165 Requests that uncontrolled set of P&IDs be placed on controlled distribution list for any future revisions Revisions should be forwarded to attention of Region 3 incident response ctr KEPPLER.J G Region 3. Chicago, Dffice of the Director 80/03/20
- 8004010325 Advises that no Event 5 valve configurations exist at facility, in response to NRC BOO223 ltr lists valve configurations used at facility DOLAN.J E Indiana & Michigan Electric Co 80/03/24 3pp
- 8004010420 Requests permission to use divers to cut atous for replacement of racks in spent fuel pool Dose calculations computed under two separate conditions Mar observed dose would be 0.7 man-roms
 BDLAN.JE Indiana & Michigan Electric Co BO/03/24 2pp
- 8004010486 Advises that upgraded radiation monitoring channels inside containment will be installed during first outage of sufficient duration subsequent to equipment delivery Reset feature does not affect position of control room dampers DDLAN. J E Indiana & Michigan Electric Co 80/03/25 2pp
- 800424045G Approves use of divers for removal of anchor bolts during spent fuel mods Increase insignificant No change to 791016 safety evaluation necessary SCHMENCER.A Operating Reactors Branch 1 80/03/25 2pp
- 8004030204 Forwards add1 info to util 800310 ltr. Item 2 1,8 b re interim method for dotermining plant releases MALONEY, O P Indiana 5 Michigan Electric Co 80/03/27 6pp
- B0040B0534 Forwards responses to NRC B00227 ltr re mods to facility auxilitary feedwater sys & requests for addl info concerning util response to NRC 791030 ltr
 MALONEY, 0 P Indiana & Michigan Electric Co 80/03/28 4pp
- 8004150809 Forwards ETA Engineering Inc Mar 1780: "Summary Rept Comparing Thermal Plume Measurements w/Modeling Predictions" & facility NPDES permit HUNTER:R 6 Indiana & Michigan Electric Co 80/04/03. 2pp
- ---8004190920 "Summary Rept Comparing Thermal flume Measurements ω/Modeling Predictions " ★ £1A Engineering, Inc. 80/03/31 53pp

- --8004150531 NPDES Permit MI 0005827.issued to IN & MI Power Co CDURCHAINE, R J Michigan, State of 74/12/27 lipp
- Q Inspection reports, IE Bulletins h correspondence
- 8004040392 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/13 2pp
- --B004040399 Waste Packaging Imp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels, removable contamination & external packaging features POTTER, J P. BROWN, R A. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/13 4pp
- 8004040436 Forwards IE Insp Repts 50-315/80~02 & 50-316/80~02 on 791201-800111 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/16 Spp
- --8004040440 Notice of violation from insp on 791201-800111 * Region 3, Chicago, Office of the Director 80/02/11 1
- --B004040444 IE Insp Repts 50-315/80-02 % 50-316/80-02 on 791201-800111 Noncompliance noted standing orders not reviewed by licensed operators, as required MASBER E . BOYD, D C Region 3, Chicago, Office of the Director 80/02/11 6pp
- 8004040285 Forwards IE Investigation Rept 50-315/80-03 on 791217 & 800109-10 No noncompitance noted KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/20 200
- --8004040299 IE Investigation Rept 50-315/60-03 on 791217 & 800109-10 No noncompliance noted Major areas investigated allogations concerning improper wolding techniques & security procedures
 BOYD.D C NORELIUS.C E . HASSE.R Region 3. Chicago, Office of the Director 80/02/15 8pp
- 8004070411 Responds to Item 1 of IC Bulletin 79-018, "Environ Gualification of Class IC Equipment" Items 2-5 will be addressed before end of 70-day period Master list attached W/o encl DULAN, J E Indiana & Michigan Electric Co 80/03/07 3pp
- 8004100116 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J. G. Region 3, Chicago. Office of the Director 80/03/07
- 8004300611 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Btd Type II Two-Inch.Tray Adsorber Cells" Rivet spacing problem does not apply at facilities No evidence found of defective cells or casing-screen separations DULAN, J E Indiana & Michigan Electric Co 80/03/25 3pp
- BOC4140484 Advises that Investigation Repts 50-315/79-27 & 50-316/79-27 upper forwarded w/incorrect rept numbers Correct numbers are 50-315/79-27 & 50-316/79-25 KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/26 ip
- 8004150162 Advises of error in 800102 IE Insp Repts 50-319/79-27 & 50-316/79-27 Corrected repts are 50-315/79-27 & 50-316/79-25 KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/26
- 8004180172 Ack receipt of 800312 ltr informing NRC of steps taken to correct violations noted in IE insp HEI8HMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/03/27 ip
- --8004180181 Responds to NRC 800216 ltr re violations noted in IE insp Corrective actions method for standing order receipt & review has been changed requiring each reviewer to initial particular sheet HUNTER.R B. Indiana & Michigan Electric Co 80/03/12 2pp
- 8004150153 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific Action or response necessary KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/31

- SOO4080717 Forwards IE Circular 80-05, 'Emergency Diesel Generator Lubricating Oil Addition's Onsite Supply "No written response required #EPPLER, J.G. Region 3, Chicago, Office of the Director 80/04/01
- 8004150011 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers 'No specific action or response required VEPPLER.J O Region 3. Chicago, Office of the Director 80/04/02
- 8004180018 Forwards attachments to IC (licular 80-03, "Protection From Toxic Gas Hazaids," inadvertently omitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- BOO4220090 Forwards IE Into Notice 80-14. "Safety Suggestions From Employees" No action required KEPPLER.J G Region 3. Chicago. Office of the Director BO/04/02 10
- BOO4220339 Forwards IE Circular BO-O/, 'Problems W/HPCI Turbine Dil Sys " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director BO/O4/O3 15
- BOO4230211 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07 10
- 8004280398 Responds to 800213 IE Bulletin 80-04 "Analysis of PNR Main Steam Break w/Continued Feedwater Addition " FSAR analyses adequately address concerns DDLAN.J E Indiana 2 Michigan Electric Co 80/04/08 3pp
- 8004220129 Forwards IE Bulletin 80-08, "Cram of Containment Liner Penetration Welds " Written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- BOO4110445 Forwards "Semiannual Radioactive Effluent Release Rept.Jul-Dec 1979 " DOLAN.J E Indiana & Michigan Electric Co BO/03/04 1p
- ---8004110449 "Semiannual Radioactive Effluent Release Rept.Jul-Dec 1979 "
 * Indiana & Michigan Electric Co 80/03/04 81pp
- 8004080304 Notifies that annual environ operating rept for 1979 is being forwarded under separate cover MALONEY,O P Indiana & Michigan Electric Co 60/04/02 ip
- 8004150368 Forwards monthly operating tept for Mar 1980 SHALLER.D V Indiana & Michigan Electric Co 80/04/08 ip
- ~-8004150371 Monthly operating rept for Mar 1980 OILLETT:W T Indiana & Michigan Electric Co 80/04/02 7pp
- S Reportable occurrences, LERs & related correspondence
- 8004220084 PNG-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 7/08/12
 WHITT.K W Region 2, Atlanta, Office of the Director 77/08/12
 1p
- BOO4070427 PNO-III-BO-049 on BOO314, licenses notified inspector that small unexplained radioactive release via auxiliary blog stack was in progress Caused by leaking relief valve Failed fuel sys isolated BOYD. O C. HELBHMAN.R F Region 3, Chicago, Office of the Director BO/03/14 2pp
- 8004070192 PNG-11I-80-052 on 800317 portions of plant demineralized water sys found radicactively contaminated Probably caused by siphoning following use of temporary line to add demineralized water to spent fuel storage pit BOYD.D.C., DUBRY.N.E., HETSHANN.R.F. Region 3, Chicago, Office of the Director 80/03/17 2pp

1 . .

- 8004090030 PND-1[I-80-049n on 200314, Region 3 received notification of unplanned radioactive gas release Caused by relief valve lifting in in-line failed rucl detection sys due to orerthrottling of valve downstream BOYD. D.C., HEISHMAN, R.F. Region 3, Chicago, Ofrice of the Director 80/03/17 Ip
- BO04040059 PrO-fil-60-052A BO0317 investigations revealed contaminated tap to be located outside auxiliary bldg Personnel have been instructed that water from that source is not for human consumption * tap has been appropriately tagged BOYD, D.C., DUBRY N.E., HEISHMAN R.F. Region 3, Chicago, Office of the Director BO0/03/19 Zpp
- 8004140438 Forwards LER Eu-004/03L-0 SMALLER, D. V. Indiana & Michigan Electric Co. 80/04/08 Ip
- --8004(40444 LFR BC-004/05L-0 on BO031), while performing scan sequence, one or two detectors in use for axial power distribution monitoring sys Selame inoperable Caused by component failure Alternate scan used following detector limit entry * Indiana 'flichigan Electric Co BO/04/08 2pp
- B004230438 Forwards LERs 60-005/03L-0 % 80-005/03L-0 SHALLER, D V Indiana * Michigan Electric Co 80/04/18 1p
- --8004230444 LER 80-005/OSL-0 on 800321.discovered that Unit 1 axial power distribution manifoling sys % P-250 axial power distribution manifoling sys 1 mits were incorrect Caused by personnel using Unit 2 PG & K(1) limits in computer program DELONG.5 D Indiana % Michigan Electric Co 80/04/18 2PP
- --800423044/ LER GO-006/O3L-O on B00324 during surveillance test.Unit 1 650-rt alevation airloc) door leakage of 130CFH was found No cause for leak found Retest performed u/satisfactory results DELGNO.S D Indiana ? Michigan Electric Co B0/04/18 1p
- 8004290417 RO on 800412 during filling of chemical vol & control sysholdup tank w/dimineralized water holdup tank inadvertently pressurized over safety valve setpoint of 12 psig Xe-133 & I-13} released from vent
 SHALLER, D.V. Indiana & Michigan Electric Co. 80/04/22 2pp
- DOCKET 50-316 DONALD C COOP NUCLEAR POWER PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8004300012 Forwards sys description 5 operation instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AC Network may also be used for daily administrative or facsimilie traffic AEPPLER.J C Region 3. Chirago Office of the Director 80/03/20 Zop
- 8004080544 Forwards evacuation time estimates in response to NRC 791129 info request Time required to evacuate schools & nursing homes under adverse & ravorable conditions assumed to be 2-h after notification / 4-h for hospitals DDLAN. J E Indiana & Michigan Electric Co 80/04/01 21pp
- BOO4150507 Forwards proposed changes to fire protection Toch Specs to reflect mods made to plant per requirements of 790731 safety evaluation Tech Spec changes were reviewed & approved HUNTER.R S Indiana & Michigan Clectric Co 80/04/09 ip
- --8004150510 Proposed changes to Fire protection Tech Specs Changes reflect mods made to plant per requirements of 790731 fire protection safety evaluation HUNTER.R.C. Indiana & Michigan Flectric Co. 80/04/09 lipp
- 8004230369 Forwards re-ised sateguard contingency plan Plan withheld (ref 100FR2 790)
 DDLAN, J E Indiana & Michigan Power Co 80/04/21 ip
- J Insurance & indemnity information
- 8004140324 Forwards Endorsement 35 to MACLU Policy MF-79.Endorsements 42 & 43 to NELIA Policy NF-204.Endorsement 3 to MACLU Binder XB-45.Endorsement 4 to MACLU Binder XB-64.Endorsement 3 to NELIA Binder EB-64 HUNTER.R S Indiana & Michigan Electric Co 80/04/03 7pp

- P. Operating license stage documents δ correspondence
- 8004020457 Forwards NRC safety analysis of cracking discovered in feedwater sys Util repair program nondestructive insps & leakage testing are adequate to insure that integrity of feedwater piping will be maintained SCHWENCER. A Operating Reactors Branch 1 80/02/25 6pp
- 800415013B Forwards request for add1 info re review of 791207 request for amend to reflect proposed mods to auxiliary feedwater sys SCHWENCER. A Operating Reactors Branch 1 B0/02/27 3pp
- B004030102 Forwards "Auclear Data Link Specs," study of digital communication sys to transmit info from plants to Nethesda Operations Ctr EISENHUT, D G Division of Operating Reactors B0/03/12 Spp
- --B004030118 "Nuclear Data Link Specs "

 ** Division of Operating Reactors B0/02/21 28pp
- 8004210415 Advises that facilities will be using Models CN6-80A.7-100, CNSI-21-300 & CNSI-14-195-H for shipment of radioactive matts
 DDLAN, J E Indiana & Michigan Electric Co 80/03/17 ip
- B004220012 Summary of B00306 meeting w/Brown Boveri representatives returbine design features Vendor repts encl HIGGINTON: D Operating Reactors Branch 1 (Pre 791030) B0/03/1/
- --8004220017 "1160 MW Turbine for Facility "
 HOBSLI,W Brown Bover: Corp (subs Brown Bouver: & Co .Ltd)
 CH-T 060030 E 80/03/17 18pp
- --8004220023 "Welded Rotors for Steam Turbines"
 # Brown Bover: Corp (subs Brown Bouver: & Co.Ltd.) CH-T C60
 072 E 80/03/17 App
- --8004220027 "Rotors for Large Steam Turbines "
 HOHN, A Brown Bover: Corp (subs Brown Bouveri & Co , Ltd) CH (
 060 053 E 80/03/17 14pp
- --80042R0034 "Last-Stage Biades of Large Steam Turbines" HOHN.A , NOVACEK,P Brown Bover: Corp (subs Brown Bouver: & Co.Ltd) CH-T 060040 E 80/03/17 12pp
- --B00422037 "Some Aspects of Water Chemistry in LWR Power Stations " BODMER, M Brown Bover: Corp (subs Brown Bouveri & Co ,Ltd) CH-T 030 043 E 80/03/17 Bpp
- 8004240462 Approves review re potential boron dilution incidents at facility.per 770915 ltr about incident involving contents of apray additive tank FBAR analysis represents most limiting case No further action necessary SCHMENCER.A Operating Reactors Branch 1 80/03/19 2pp
- 8004100165 Requests that uncontrolled set of P&IDs be placed on controlled distribution list for any future revisions Revisions should be forwarded to attention of Region 3 incident response ctr
 KEPPLER: J G Region 3. Chicago, Office of the Director 80/03/20 tp
- 8004010329 Advises that no Event 5 valve configurations exist at facility, in response to NRC 800223 ltr Lists valve configurations used at facility DDLAN, J E Indiana & Michigan Electric Co 80/03/24 3pp
- 8004010420 Requests permission to use divers to cut study for replacement of racks in spent fuel pool Days calculations computed under two separate conditions Max observed dose would be 0.7 man-rams
 DDLAM, J.E. Indiana & Michigan Electric Co. 80/03/24 2pp
- 8004010486 Advises that upgraded radiation monitoring channels inside containment will be installed during first outage of sufficient duration subsequent to equipment delivery Reset feature does not affect position of control room dampers DOLAN, J E Indiana & Michigan Electric Co 80/03/25 2pp
- 8004240456 Approves use of divers for removal of anchor bolts during spent fuel mods Increase insignificant No change to 791016 safety evaluation necessary SCHMENGER.A. Operating Reactors Branch i 80/03/25 2pp

- B004030204 Forwards addl info to util 800310 ltr. Itam 2 1 8 b ra interim method for determining plant releases MALONEY.G P Indiana & Michigan Electric Co 80/03/27 App
- 80040B0520 Responds to NRC B00127 Itr requesting fee submittal for review of documents in 791218 Itr Fee already paid Discusses seismic qualification items MALDNEY, GP Indiana & Michigan Electric Co 80/03/28 3pp
- 8004080534 Forwards responses to NRC 800227 ltr re mods to facility auxiliary feedwater sys & requests for addl info concerning util response to NRC 791030 ltr MALONEY, O P Indiana & Michigan Electric Co 80/03/28 4pp
- 80040B0367 Forwards add1 info requested by NRC 790109 itr.re analyses of containment temp response to postulated main steam line breals
 MALONEY.G P Indiana / Michigan Electric Co B0/04/01 2tpp
- 8004160016 Returns WCAP-9566 Westinghouse proprietary rept is not necessary for NRC review of util proposed Tech Specs changes to power peaking limits W/o enci 8CHWENCER.A Operating Reactors Branch 1 80/04/01 2pp
- 8004170178 Requests submittal of Class III fee per NRC 800127 ltr advising classification of 791218 amend application Response required within 15 days of receipt of ltr MILLER.W D License Fee Management Branch 80/04/01 ip
- 8004150509 Forwards ETA Engineering Inc Mar 1980, "Summary Rept Comparing Thermal Plume Measurements w/Modeling Predictions" & facility NADES permit MUNITER R B Indiana & Michigan Electric Co 80/04/03 2pp
- --8004150520 "Summary Rept Comparing Thermal Plume Measurements u/Modeling Predictions" 4 ETA Engineering.Inc 80/03/31 53pp
- --BOD4150531 NPDES Permit MI 0005827, issued to IN & MI Power Co COURCHAINE, R J Michigan, State of 74/12/27 lipp
- Q Inspection reports. IE Bulletins & correspondence
- 8604040392 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No nencompliance neted DAVIS,A 8 Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/13 2pp
- ~~8004040399 Waste Packaging Insp Rept 79-06A on 791126-2B No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels, removable contamination & external packaging features POTTER, J P. BROWN, R A Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/13 4pp
- 800404046 Forwards IE Insp Repts 50-315/80-02 & 50-316/80-02 on 791201-800111 & notice of violation HEIBHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/02/16 Spp
- --800404040 Natice of violation from insp on 791201-800111 * Region 3, Chicago: Office of the Director 80/02/11 ip
- --8004040444 IE Insp Repts 50-315/80-02 & 50-316/80-02 on 791201-800111
 Noncompliance noted standing orders not reviewed by licensed operators, as required
 MASSER, E. BOYD, D. C. Region 3, Chicago, Office of the Director
- G0040704i1 Responds to Item 1 of IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Items 2-5 will be addressed before end of 90-day period Master list attached, W/o enc!
 DOLAN, J E Indiana & Michigan Electric Co 80/03/07 3pp
- 8004100116 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER.J & Region 3. Chicago, Office of the Director 80/09/07 ip,
- 8004300611 Forwards response to IE Bulletin BO-03, "Loss of Charcoal from 8td Type II Two-Inch,Tray Adsorber Cells " Rivet spacing problem does not apply at facilities No evidence found of defective cells or casing-screen separations DDLAN.J E. Indiana & Michigan Electric Co 80/03/25 3pp

- 8004140404 Advises that Investigation Repts 50-315/79-27 % 50-316/79-27 were forwarded wincorrect rept numbers Correct numbers are 50-315/79-27 % 50-316/79-25 KEPPLER. J G Region 3, Chicago, Orrice of the Director 80/03/26
- 8004150162 Advises of error in B00102 IC Insp Repts 50~315/79~27 & 50~316/79~27 Corrected repts are 50~315/79~27 t 50~316/79~25 KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/26 to
- 8004180172 Ack receipt or 800312 ltr informing NRC of steps taken to correct violations noted in IE insp HEISHMAN R Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/27 ip
- ---8004180181 Responds to NRC 800216 itr re violations noted in IE insp Corrective actions method for standing order receipt to review has been changed requiring each leviewer to initial particular sheet HUNTER/R S Indiana / Michigan Electric Co 80/03/12 2pp
- 8004150153 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Bloc) Valve "No specific action or response necessary KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/31
- 80040B0717 Forwards IE Circular B0-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/01
- B004150011 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/02
- 8004180018 Forwards attachments to IE Circular 80-03, "Protection From Toxic Qas Hozards," inadvertently omitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220090 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02 in
- GOO4220339 Forwards IE Circular 80-07, "Problems W/HFC! Turbine Oil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03 in
- 8004230211 Forwards IE Bulletin 79-03A, "Longitudina) Weld Defects in ASME 9A-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07

8004286 Stea ader Dr'

- --8004150365 Northly operating rept for Mar 1980 GILLETT, W.T. Indiana / Michigan Electric Co. 80/04/02 9pp
- 3 Reportable occurrences, LERs ? related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities u/production lot of 40 pumps mfg using sharts made of inferior matl Cause unstated All utils u/pumps were notified NRC headquesters notified on 770812 WHITT.K N Region 2. Atlanta. Office of the Director 77/08/12
- 8004070192 PNO-111-80-052 on 800317.portions of plant demineralized water sys found radioactively contaminated Probably caused by siphoning following use of temporary line to add demineralized water to spent zuel storage pit 80YO.D C. DURRY,N E. HEISHMAN.R F. Rogion 3, Chicago. Office of the Director 80/03/17 2pp
- 80040400r59 PNO-III-80 052A 800317 investigations revealed contaminated tap to be located outside auxiliary bldg Personnel have been instructed that water from that source is not for human consumption t tap has been appropriately tagged 80Y9.D C. DUBRY.N E. HEISHMAN R F. Region 3. Chicago. Office of the Director 80/03/19 2pp
- 8004010476 Forwards LER 80-011/03L-0 SHALLER,D V Indiana 2 Michigan Electric Co 80/03/21 ip
- --8004010481 LER 80-011/03L-0 on 800223 during weekly turbine testing, reduction in RCS pressure occurred Pressure dropped below min Tech Spec limit Caused by tripped supply breakers resulting in inoperable heaters Breakers result
- 8004010493 Forwards LER 80-012/03L-0 SHALLER.D V Indiana / Michigan Electric Co 80/03/25 Lp
- --8804010500 LER 80-012/031-0 on 800305, while performing surveillance test, steam generator water level low-low trip bistable found to trip at 11 05% narrow range instrument span Cause unstated Bistable recallbr & returned to svc RISCMLING, J L Indiana & Michigan Electric Co 80/03/25 1p
- 8004080510 Forwards LERs 80-013/03L-0 & 80-014/03L-0 SHALLER,D V Indiana & Michigan Electric Co B0/04/02 tp
- --8004080527 LER 80-013/03L-0 on E00307, during normal operation, circuit breaker for R-11 & R-12 sample pump tripped Caused by failure of rubber spider in Lovejoy L-100 coupling Complete coupling replaced & air sampler tested WIZNER, D O Indiana & Michigan Electric Co 80/04/02 ip
- --8004080345 LER 80-014/03L-O on 800216, during surveillance test, proximity switch for D main turbine stop valve fell off mounting bracket caused by threads in mounting bracket being stripped Hole intapped to larger size RISCHLING.J (Indiana & Michigan Electric Co 80/04/02 to
- 8004230430 Forwards LER 80-015/03L-0 SHALLER.D V Indiana & Michigan Electric Co 80/04/t5 1;
- ---8004230432 LER 80-015/03L-O on 800325 during auxiliary feed pump retest auxiliary feed valve FMD-221 for steam generator 2 did not operate Caused by armature lead from limitorque valve operator being pulled out of utre lug New 10g crimped BROWN, M S Indiana 2 Michigan Electric Co 80/04/15 1p
- 9004230351 Forwards LERs 80-016/03L-0 & 80-017/03L-0 SHALLER, D V Indiana ? Michigan Electric Co 80/04/18 Ip
- --8004230355 LER 80-016/03L-O on 800322. while performing routine panel insp. operator discovered cast RHR pump suction breaker IMO-310 open Cause not determined Operators have been alerted to keep close watch on panel indicators MURPHY.C E. Indiana & Michigan Electric Co. 80/04/18 | IP
- --8004230357 LER 80 017/03L-0 on B00321, during normal operation, TDAFP trip & throttle valve tripped & could not be reset Caused by defective reset solenoid Coil replacement not effective Trip linkage reset manually New coil & linkage adjusted RISCHLING, J.L. Indiana & Michigan Electric Co. 80/04/18 2pp
- 8004270417 RO on 800412.during filling of chemical vol & control sysholdup tank w/dimineralized water, holdup tank inadvertently pressurized over safety valve setpoint of 12 psig Xe-133 & 1-131 released from vent SHALLER, D V Indiana 3 Michigan Electric Co GO/04/22 2pp

- GOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 F Security, modical, emergency & fire protection plans
- 8004170316 Forwards summary of 800221 meeting w/util re LRO contingency plan.M Wohl trip rept & request for addl info necessary to complete roview of site emergency plan REID.R W Operating Reactors Branch 4 80/03/31 2pp
- --B004170318 Summary of ±00221 meeting w/util in Bethesda.MD to discuss LPN contingency plan Review will be completed concurrently w/emergency planining review Agenda and CONNER.E L Operating Reactors Branch 4 80/03/31 Spp
- --8004170323 Forwards articles to methane detection using lasors
 Recommends laser fence idea Sys would act as continuous
 fence under all conditions except heavy fag W/o encl
 WOODMAN, D P GTE Sylvania. Inc (subs of General Telephone &
 Electronics Corp) 79/12/26 ip
- 8004080391 Forwards Revision 6 to modified amended security plan Plan withheld (ref 10CFR2 /90) EVANS, V R Baltimore Gas & Electric Co 80/04/02 2pp
- 8004230483 Forwards input for fire protection review. Item 3 2 2 re emergency lighting Recommends NRC approval of licensee proposals contained in 791113 itr. Submits recommendations re-proposal to change from 1 5-h units to 8-h units HALL.RE Brookhaven National Laboratory 80/04/14 ip
- H General correspondence
- 8004040300 Objects to radioactive discharges from units Officials irresponsible % not concerned w/public interest People must take immediate, unified action to gain control over environ & lives RENKO, E Affiliation Unknown BO/02/15 2pp
- P Operating license stage documents & correspondence
- 8004080437 Advises that FR notice of consideration of proposed mod to facility spent fuel storage pool has been filed for publication Notice relates to util 800615 request to permit 1.760 on lieu of 1.368 fuel assemblies to be stored REID, R W Operating Reactors Branch 4 80/02/28 2pp
- --8004080440 Notice of consideration of proposed mod to facility spent funt storage pool REID:R W Operating Reactors Branch 4 80/02/20 4pp
- B004040091 Forwards Amends A2 & 25 to Licenses DPR~53 & DPR~69 respectively, safety evaluation & notice of issuance & availability
 REID.R N Operating Reactors Branch 4 80/03/10 3pp
- --B004040096 Amends 42 & 25 to Licenses DPR-53 & DPR-69 respectively, deleting satisfied License Condition 2 C(3), "Steam Generator Water Level Rise Rate," for Unit 2 & deleting satisfied license condition re LNO traffic for both REID,R W Operating Reactors Branch 4 B0/03/10 2pp
- --8004040105 Bafety evaluation supporting Amends 42 & 25 to Licenses DPR-B3 & DPR-69 respectively * Office of Nuclear Reactor Regulation 80/03/10 7pp
- --BO04040109 Notice of issuance & availability of Amends 42 & 20 to Licenses DPR-53 & DPR-69:respectively REID,R W Operating Reactors Branch 4 80/03/10 29p
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUI, D Q Division of Operating Reactors 80/03/12 5pp
- --9004030118 "Nuclear Data Link Specs "

 # Division of Operating Reactors 80/02/21 28pp
- GOO4100300 Submits add1 info re auto initiation of auxiliary of feedwater sys NRC 791030 ltr stated implementation of Itam 2 1 7a short-term required NRC approval Design must be verified before implementation EIBENHUT.D O Division of Operating Reactors 80/03/27 3pp

- 8004010463 Submits addl info re proposed design changes to satisfy requirements for auxiliary feedwater sys Auxiliary feedwater 5, steam turbine sys will be modified by 830101 Forwards piping & instrumentablen & logic diagrams
 LUNDVALL, A E Baltimore Gas 7 Electric Co 80/03/28 3pp
- ---B004010467 "Piping & Instrumentation Diagram Auxiliary Feedwater Bys "
 # Bechtel Corp 6750 B0/03/18 ip
- ---8004010471 "Auxiliary Feedwater Actuation Bys," preliminary drawings * Bechtel Corp 80/03/21 ip
- 8004240244 Ack receipt of 790703 application & 800115 ltr re spent fuel pool mod Results of preliminary review determined that Class IV fee is required for Unit 1 rather than Class III Requests prompt remittance
 DIGOS.R M License Fee Management Branch 80/03/28 ip
- 8004080465 Discusses action taken to correct spurious high power & temp monitor/low pressure trips on Channel A of reactor protection sys Single channel version of reporting identification symbol transmitters ordered LUNDVALL.A E Baitimore Gas & Electric Co 80/03/31 2pp
- BOO4230177 Requests addition to complete LOCA review of util 770405 application for partial-loop operation Info required re high to low density fuels, including initial clad inside (gap region) to outside paide thickness data REID.R W Operating Reactors Branch 4 80/03/31 2pp
- 8004090359 Forwards add1 fee for upgrading, from Class III to Class IV. of 790903 amend request to replace existing spent fuel racks w/high capacity racks
 OLSON.R C Baltimore Oas & Electric Co 80/04/03 2pp
- 8004100227 Furwards response to NRC 800225 request for add1 info re facility containment purge sys design Includes info re electrical reset, override & bypass LUNDVALL.A E Baltimore Gas & Electric Co 80/04/07 14pp
- 8004280154 Forwards evaluation concluding that implementation of Lassons Learned Task Force Category A requirements at facilities is acceptable Evaluation does not address Tech Specs re limiting conditions for operation REID.R W Grerating Reactors Branch 4 80/04/07 10pp
- 8004280025 Discusses 791030 itr to HR Denton Notifications per Toch Specs 2 3 A 7 or 2 3 B 8 should include dose assessment illustrating compliance w/40CFR190 REID:R W Operating Reactors Branch 4 80/04/08 2pp
- BOO417023B Forwards response to questions contained in NRC 790827 & 0721 ltrs re proposed spent fuel pool mods Requests that NRC allow storage of 1830 fuel assemblies instead of 1760 assemblies as originally requested LUNDVALL, A & Baltimore Gas & Electric Co 80/04/14 38pp
- 8004220782 Responds to request for add1 info re util 790703 license amend request Makeup rate to spent fuel pool from demineralizer tank is 325 gpm Makeup rate from two refucling water tanks is 1.390 gpm ASH.R F Daltimore Cas & Electric Co 80/04/18 lp
- 8004280435 Disscusses redirecting efforts of Operating Experience Assessments Committee to avoid overlap w/efforts of Plant Operations Bafety Review Committee Described changes meet intent of NUREG-0579 & will be implemented immediately LUNDVALL. A E. Baltimore Qas & Electric Co 80/04/22 2pp
- Q Inspection reports: IE Bulletins & correspondence
- 8004220441 Responds to IE Bulletin 80-04, "Analysis of Steam Line Break u/Continued Feedwater "Forwards results of analyses assessing ability of containment to withstand effects of break inside containment W/O encl LUNDVALL.A E Baltimore Gas & Electric Co 80/02/12 ip
- 8004070137 Advises that no NAMCO EA180 limit switches are in stock or on order re IE Bullatin 79-28
 LUNDVALL, A E Baltimore Gas & Electric Co 80/02/21 lp
- 8004030311 Responds to IC Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Voltmeters, sobential indicators & alarms exist in control room to alert operator to loss of power to bus LUNDVALL.A E Baltimore Gas & Electric Co B0/02/26 3pp

- 8004080335 Submits response to IF Builetin 79-27 re loss of instrument control power; effect on ability to achieve cold shutdown Mods to cold leg temp loops will allow one panel indicator for each loop temp for single investes loss LUNDVALL.A C Baltimore Gas * Electric Co 80/02/26 3pp
- 8004090243 Forwards 45 day response to IE Bulletin 79-018 W/o encl master list of safety-related electrical equipment, sys component evaluation worksheets h tabulation of syc conditions LUNDVALL, A F Baltimore Gas P Electric Co 80/03/v3 2pp
- 8004280280 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SHITH.G H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- --8004280288 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted flajor areas inspected shipping paper requirements, DDT placarding requirements, radiation levels & removable contamination WDDDRUFF, R. L., PEERY, W. W., POTTER, 1 P. Region 1, Philadelphia, Office of the Director 80/01/18 7pp
- 8004100265 Forwards correspondence w/Amphenol Space & Missile Sys & vendor rept re space electrical penetration test data in response to IE Bullotin 79-01 Util considers rept unacceptable due to lack of detail N/a encls
 BHATIA.P Baltimore Gas & Electric Co 80/03/06 lp
- 8004080324 Ack receipt of 800227 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/79-24 & 50-318/79-23 GRIER, B H Region I, Philadelphia, Dffice of the Director 80/03/08 Ip
- --8004080333 Responds to NRC 800213 ltr re violations noted in IE Insp Repts 50~317/77-24 & 50-318/79-23 Corrective actions design & installation of curbing for Wasting Neutralizing Tank 12 in progress & completion expected by 800229 LUNDVALL.A E Baltimore Gas & Electric Co 80/02/27 2pp
- --B0040B0341 Forwards IE Insp Repts 50-317/79-24 & 50-318/79-23 on 791210-11 & notice of violation ORIER,B H Region 1, Philadelphia, Office of the Director B0/02/13 2pp
- --8004080344 Notice of violation from insp on 791210-11 * Region 1, Philadelphia, Office of the Director 80/02/07 ip
- --8004080352 fE Insp Repts 30-317/79-24 & 50-318/79-23 on 791210-il Noncompliance noted soveral sys components including acid. caustic day tanks, caustic pumps & piping sys were corroded SHANBAXY, M M , KOTTAN, J J Region i, Philadelphia, Office of the Director BORES, R J Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/07 Bpp
- BOO4040271 Describes conformance of inservice insp program to deviation from ABNE Boiler & Pressure Vessel Code.Section XI.1974-1975 Forwards "Long-Term Inservice Exam Plan for Class i. Class 2 & Class 3 Sys & Components." Vol 1-3.final plan LUNDVALL.A E Baltimore Gas & Electric Co 80/03/29 18pp

- 8004110124 Forwards IF Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers' No written response required GRIER, B.M. Region 1 (Abiladelphia, Office of the Director 80/04/02)p
- 8004240293 Forwards IF into Notice 80 14. "Safety Suggestions From Employees." No action required GRIER,B H. Region 1. Philadelphia. Office of the Director 60/04/02. 1p
- 8004180257 Forwards IE Circulal Bu-07 'Problems W/HPCI Turbine Gil Sys " No written response required GRIER, B H Region 1 Philadelphia, Office of the Director 80/94/03 tp
- BO04230394 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Tupe 304 Stainless Steel Pipe " Action required GRIER, B H. Region 1. Philadelphia, Office of the Director BO/04/04 ip
- BOO41BO117 Forwards IE Bullerin BO-OB, "Exam of Containment Liner Penetration Welds" Written response required GRIER, B.M. Region 1. Philadelphia. Office of the Director BO/O4707 19
- R Periodic operating reports & related correspondence
- 8004210192 Forwards "Nontadiological Environ Monitoring Rept, Jan-Dec 1979 " LUNDVALL, A.E. Baltimore Gas & Electric Co. 80/03/14 p
- ~-80042[0197 "Nonradiological Environ Monitoring Rept.Jan-Dec 1979 "

 ◆ Baltimore Gas & Electric Co → Academy of Natural Sciences of Philadelpnia 80/03/31 400pp
- 8004070275 Forwards. "Radiological Environ Monitoring Program Annual Rept.1979" LUNDVALL.A E. Baltimore Gas & Electric Co. 80/03/28 1p
- --80040/0274 "Radiological Environ Monitoring Program Annual Reptit979 " BARTALL J : RAFI.A : REICHERI.E C Baltimore Gas & Electric Co 80/03/31 50pp
- 8004250406 Forwards monthly operating repts for Mar 1980 Correction to Feb 1980 monthly operating rept requested MERSON.S D. Baltimore Gas & Flectric Co. 80/04/15 1p
- --8004250407 Monthly operating repts for Mar 1980 MERSON/S D Saltimore Gas & Electric Co 60/04/14 18pp
- S Reportable occurrences, LERs > related correspondence
- 8004010430 Forwards LFR 80-013/03L-0 RUSSELL,L B Baltimore Gas & Electric Co 60/03/25 1p
- --8004010435 LER Gu-013/03L-0 on G00225, while performing surveillance test, channel D containment high pressure tilp setpoint was less conservative than value given in Fech Specs Caused by failed signal isolator 1-F/E-5313D HEIBEL, R P , RIZZO, P G Baltsmore Gas & Electric Co B0/03/25
- 8004080500 Forwards LER 80-002/04T-0 RUSSELL,L B Baltimore Gas & Electric Co B0/04/03 (p
- --8004050507 LER 80-002/04T-0 on 800322, instantaneous hourly average for condenser temp rise observed in excess of Tech Spec limit Caused by operator instruction to temp rise across condenser & environ conditions HEIBEL.R P Baltimore Gas & Electric Co 80/04/03 2pp
- 8004150606 Forwards LER 80-014/03L-0 RUSSELL,L G Baltimore Cas & Electric Co 80/04/10 ip
- --8004150620 LER GO-014/03L-0 on 800310, during surveillance testing, reactor core drain tank & quench tank oragen sample valves failed to shot on safety injection actuation signal Gaused by corrosson on output relay terminals LAGIEWSKI.J S., RIZZÖ.P G. Galtimore Oas & Electric Co. 80/04/10
- B004170219 Forwards LER B0-020/03L-0 RUSSELL,L B Baltimore Gas & Electric Co B0/04/14 1g

- --8004170221 LER 80-020/G3L-G on 800314, while operating at 98% power, fire marshall discovered rise barrier penetration between cable spreading room & turbine bidg not sealed w/Flamastic fire retardant matl Caused by inaccessible location WERGER, U.O., BUFFINGTON, D.C. Baltimore Gas & Electric Co. 80/04/14 200
- 8004210323 Submits info in confirmation of 800415 conversation u/RE Architis) ro generic deficiency & FSAR, Section 14-3 concerning boron dilution incident Operating procedures will be changed to require min 2/ shutdown margin DAVIS, 8 ff Baltimore Gas & Electric Co 80/04/16 1p
- --B004220719 LER 80-021/041-0 on 800404, during preventive maint for draining condensate from fuel oil storage tank, operator drained oil instead of water Caused by operator inability to discern difference between oil & water through bullseys DENTON.R & Baltimore Gas & Electric Co 80/04/16 2pp
- 8004220614 Forwards LER 80-015/03L-0 RUSSELLIL B Baltimore Gas 5 Electric Co 80/04/17 1p
- --8004220621 LER 80-015/03L-0 on 800317, steam generator auxiliary feed pump 11 was taken out of operation Caused by sightglass being broken by operator taking oil sample for analysis Broken glass replaced HUSEBY, D.E., HEIBEL, R.P. Baltimore Gas & Electric Co. 80/04/17
- 8004290372 Forwards LER 80-005/03L-0 RUSSELL: B Baltimore Gas & Electric Co 80/04/25 ip
- --8004290377 LER 80-005/03L-0 on 800325, during normal operation, control room air conditioning Unit 12 tripped Caused by failure of diaphragm on unipressire valve Valve replaced & unit returned to svc
 LAGIENSKI, J. S. PENCE, W. B. Baltimore Gas & Electric Co. 80/04/25
- 8004290382 Forwards LER 80-016/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 80/04/25 1p
- --8004290388 LER 80-014/03L-0 on 800325, during surveillance testing.

 Channel A wide range nuclear instrument did not respond in calibr mode Apparently caused by failure of channel preamplifier Power supply replaced w/spare

 LAGIENSKI, J S , RIZZO, P G Baltimore Gas & Electric Co GO/04/25
 200
- 8004290433 Forwards updated LER 79-052/03X-1 RUSSELL, L B Baltimore Gas & Electric Co 80/04/25 1p
- ---8004270438 Updated LER 79-052/03.-1 on 790928, containment gaseous & particulate radioactivity monitoring sys failed due to loss of sampling pump Caused by normal end-of-life failure of graphite particles depositing on bearings
 PENCE.N B Baltimore Gas & Electric Co 80/04/25 ip
- 8004290440 Forwards updated LER 80-011/03X-1 RUSSELL,t B Baltimore Oas & Electric Co 80/04/25 1p
- --8004270447 Updated LER 80-011/03X-t on 800208. w/RCS at 130 degrees \$250 psia: shutdown cooling suction header relief lifted \$failed to reset Caused by personnel error Valve reset DAVIS.S M . HUSEBY, D E Baltimore Gas & Electric Ca 80/04/25
- 8004290459 Forwards LER 80-019/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/04/25 ip
- --800A290472 LER 80-019/03L-0 on 800327 during normal operation, channel 9 loss of load trip occurred intermittently Caused by auxiliary master trip relay end-of-life type failure LAOIEMSKI, J S , RIZZO, P G Baltimore Gas & Electric Co 80/04/25 2pp
- --8004290484 LER 80-022/017-0 on 800415 util informed of possible deficiency in FSAR Section 14 3, boron dilution incident/for case when RCB is drained to hot leg w/1% shutdown margin Cause not stated Procedures changed DAVIS, S M Baltimore Gas & Electric Co 80/04/25 2pp

- 6004290490 Forwards LER 80-017/03L-0 RUBBELL, L B Baltimore Gas & Electric Co 80/04/25 1p
- --8004290499 LER 80-017/03L-0 on 800326, results of surveillance test indicated that ECCS exhaust filter train charcoal did not demonstrate removal efficiency of 90% or higher for radioactive methyl iodide Caused by age of filters
 HEIBEL.R P . BAUER.R Baltimore Gas & Electric Co 80/04/25 ip
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

 F Security, medical, smergency & fire protection plans
- B004170315 Forwards summary of B00221 meeting w/util re LNO contingency plan.M Hohl trip rept & request for addl info necessary to complete review of site emergency plan REID.R W Operating Reactors Branch 4 B0/03/31 2pp
- --8004170318 Summary of 800221 meeting w/util in Bethasda.MD to discuss LPN contingency plan Review will be completed concurrently w/emergency planning review Agenda encl CONNER.E L. Operating Reactors Branch 4 80/03/31 5pp
- --8004170323 Forwards articles re methane detection using lasers
 Recommends laser fence idea Bys would act as continuous
 fence under all conditions except heavy fog H/o oncl
 HOODMAN, DP GTE Sylvania, Inc (subs of General Telephone &
 Electronics Corp) /9/12/26 ip
- 8004080391 Forwards Revision 6 to modified amended security plan Plan withheld (ref 100FR2 790) EVANB,V R Baltimore Gas & Electric Co 80/04/02 2pp
- 8004230493 Forwards input for fire protection review, Item 3 2 2 re emergency lighting Recommends NRC approval of licensee proposals contained in 791113 ltr Submits recommendations re proposal to change from 1 5-h units to 8-h units HALL.R E Brookhaven National Laboratory 80/04/14 lp

- 8004040300 Objects to radioactive discharges from units Officials irresponsible & not concerned w/public interest People must take immediate unified action to gain control over environ & lives RENNO.E Affiliation Unknown 80/02/15 2pp
- P Operating license stage documents & correspondence
- BOO4080437 Advises that FR notice of consideration of proposed mod to facility spent fuel storage pool has been filed for publication Notice relates to util BOO115 request to permit 1,740 in lieu of 1,368 fuel assemblies to be stored REID.R W Operating Reactors Branch 4 BO/02/28 Zpp
- --9004090440 Natice of consideration of proposed mod to facility spent fuel storage pool REID,R 44 Operating Reactors Branch 4 80/02/28 4pp
- 6004040071 Forwards Amends 42 & 25 to Licenses DPR~53 & DPR~67 respectively safety evaluation & notice of issuance & availability REID.R W Uperating Reactors Branch 4 80/03/10 3pp
- --8004040094 Amends 42 & 25 to Licenses DPR-53 & DPR-69 respectively, deleting satisfied License Condition 2 C(3), "Bteam Generator Water Lovel Rise Rate," for Unit 2 & deleting satisfied license condition re LNG traffic for both REID,R W Operating Reactors Branch 4 80/03/10 2pp
- --8004040107 Notice of issuance & availability of Amends 42 & 25 to Licenses DPR-53 & DPR-69, respectively REID, R W Operating Reactors Branch 4 80/03/10 2pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISEMHUT, D O Division of Operating Reactors 80/03/12 5pp
- ---8004030118 "Nuclear Data Link Spacs "
 * Division of Operating Reactors 80/02/21 28pp

- 8004100300 Submits add1 into related initiation of auxiliary of feedwater sys NRC 791070 ltr stated implementation of Item 2 i 7a short-term required NRC approval Design must be verified before implementation EJSENHUT.D G Division of Operating Reactors 80/03/27 3pp
- 8004010463 Submits add into re proposed design changes to satisfy requirements for auxiliary feedwater sys Auxiliary feedwater & steam turbine sys will be modified by 830101 Forwards piping & instrumentation & logic diagrams
 LUNDVALL, A E Baltimore Gas ' Ejectric Co 80/03/28 3pp
- --8004010467 "Piping & Instrumentation Diagram Auxiliary Feedwater Sys "
 * Bechtel Corp 6750 80/03/18 1p
- --8004010471 "Auxiliary Feedwater Actuation Sys." preliminary drawings * Bechtel Corp 90/03/21 1p
- 8004240244 Ack receipt of 790703 application & 800115 ltr is spent fuel pool and Results of preliminary review determined that Class IV fee is required for Unit 1 rather than Class III Requests prompt remittance
 DIGOS.R M License Fee Management Branch 80/03/28 ip
- 8004010212 Forwards revision to Svc Data Items 0 2,0 3 % 0 4 of Attachment 3 to 800318 ltr re Westinghouse low pressure turbine disc insp QLSON.R C Baltimore Gas % Electric Co 80/03/29 2pp
- 8004080465 Discusses action taken to correct spurious high power & temp monitor/low pressure trips on Channel A of reactor protection sys Single channel version of reporting identification symbol transmitters urdered LUNDVALL, A E Baltimore Oas & Electric Co 80/03/31 2pp
- BOO4230177 Requests add1 into to complete LOCA review of util 790405 application for partial-loop operation Info required re high & low density fuels, including initial clad inside (gap region) & outside oxide thickness data REID.R W Operating Reactors Branch 4 80/03/31 2pp
- 8004090359 Forwards add1 fee for upgrading, from Class III to Class IV, of 790903 amend request to replace existing spent fuel racks w/high capacity racks OL60N.R C Baltimore Gas & Electric Co 80/04/03 2pp
- BOO4100227 Forwards response to NRC 800225 request for addl info re facility containment purge sys design includes info re olectrical reset, override & bypass LUNDVALL,A C Baltimore Gas & Electric Co 80/04/07 14pp
- BOOA2B0154 Forwards evaluation concluding that implementation of Lessons Leained Task Force Category A requirements at facilities is acceptable Evaluation does not address Tech Specs re limiting conditions for operation REID.R W Operating Reactors Branch 4 80/04/07 10pp
- 8004250025 Discusses 791030 ltl to HR Denton Notifications per Tech Specs 2 3 A 7 or 2 3 B 8 should include dose assessment illustrating compliance w/405FR190 REID.R W Operating Reactors Branch 4 80/04/08 2pp
- BOO4170238 Forwards response to questions contained in NRC 790B27 & 0921 ltrs re proposed spent fuel pool mods Requests that NRC allow storage of 1830 fuel assemblies instead of 1760 assemblies as originally requested LUNDVALL, A E Daltimore Gas & Electric Co B0/04/14 38pp
- 8004220782 Responds to request for add1 info re util 790703 license amend request Makeup rate to spent fuel pool from demineraliser tank is 325 gpm Makeup rate from two refueling water tanks is 1.340 gpm
 ASH.R F Baltimore Gas & Electric Co 80/04/18 1p
- 8004280435 Disscusses redirecting efforts of Operating Experience Assessments Committee to avoid overlap w/efforts of Plant Operations Safety Review Committee Described changes meet intent of NUREO-0578 & will be implemented immediately LUNDVALL.A E Baltimore Gas & Electric Co 80/04/22 2pp
- Q Inspection reports: If Bulletins & correspondence
- 8004220441 Responds to 1E Bulletin 80-04. "Analysis of Steam Line Break w/Continued Feedwater "Forwards results of analyses assessing ability of containment to withstand effects of break inside containment W/o encl LUNDVALL, A E Baltimore Gas & Electric Co 80/02/12 1p

- 8004070137 Advises that no HAMCO EA180 limit switches are in stock or on order to 18 Bulletin 79-28 LUNDVALLIA E Baltimore Gas / Electric Co 80/02/21 tp
- B004030311 Responds to IE Sulletin 79-27. "Loss of Non-Class IE Instrumentation 5 Control Power Sys Bus During Operation "Voltmeters, potential indicators 5 alams exist in control room to alert operator to loss or power to bus LUNDVALL.A E Baltimore Gas 7 Electric Co 80/02/26 3pp
- BOO4080335 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Mods to cold leg temp loops unlil allow one panel indicator for each loop temp for single inverter loss LUNDVALL.A E Daltimore Gas / Electric Co 80/02/26 3pp
- 8004090243 Forwards 45-day response to 18 Bulletin 79-018 W/o enc) master list of sarety-related electrical equipmentisys component evaluation worksheets 5 tabulation of svc conditions LUNDVALL, A E Baltimore Gas * Electric Co 60/03/03 2pp
- 8004280280 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 Overbogou ruberos waste ractaging inspirept /7 O/K uli //zeta-13 No noncompliance noted SMITH.G H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- --8004280288 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper requirements, DOT placificing requirements, radiation levels become and action and action ModRMLF.R.L., PEERY, W.W., POTTER, I.P. Region 1, Philadelphia. Office of the Director 80/01/18 7pp
- B004100265 Forwards correspondence w/Amphenol Space & Missile Sys & vendor lept re space electrical panetration test data in response to IE Bulletin 79-01 Util considers rept unacceptable due to lack of detail W/o encis BHATIA:P Baltimore Gas & Electric Co 80/03/06 1p
- BO04080324 Ack receipt of BO0227 ltm informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/79-24 t 50-318/79-23 ORIER.B H Region J, Philadelphia. Office of the Director BO/03/08 ip
- --8004080333 Responds to NRC 800213 ltr re violations noted in IE Insp Repts 50-317/79-24 5 50-318/79-23 Corrective actions design & installation of curbing for Wasting Neutrallating Tank 12 in progress 5 completion expected by 800229 LUNDVALLAE Baltimore Gas 5 Electric Co 80/02/27 2pp
- --B0040B0341 Forwards IE Insp Repts 50-317/79-24 & 50-31B/79-23 on 791210-11 & notice of violation GRIER, B H Region I. Philadelphia, Office of the Director B0/02/13 2pp
- --8004080344 Notice of violation from inspin 771210-11 * Region 1, Philadelphia. Office of the Director 80/02/07 lp
- --BOOAOBO352 IE insp Repts 50-317//9-24 / 50-318/79-23 on 791210-11
 Noncompliance noted several sys components including acidicastic day tanks.caustic pumps // piping sys were corroded
 SHANBAKY,M H , KOTTAN, J J Region 1, Philadelphia, Diffice of the
 Director BORES.R J Region 1, Philadelphia, Fuel Facility &
 Materials Safety Branch 80/02/07 8pp
- 9247 Forwards IE Info Notice 80-12. "Instrument Failure Causes) of FORV & Block Valve " No specific action or e necessary H Region 1, Philadelphia, Office of the Director
 - orwards IE Circular 80-05. "Emergency Diesel Generator Oct 844 ' Onsite Supply " No written

lelphia, Office of the Director

ice 80-13. "GE Type SBM Control Switches written response required
1. Office of the Director

800424029J Forwards 1E Info Notice 80-14 "Safety Suggestions From Employees "No action required ONIER.B H Region I, Philadelphia, Office of the Director GO/O4/O2 Jp

- 8004180257 Forwards IE Circulat 80-07, 'Problems W/HPCI Turbine Oil Sys " No written response required
 GRIER.B H Region 1, Philadelphia, Office of the Director
 80/04/03 1p
- 8004230394 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required GRIER, B.H. Region i. Philadelphia. Office of the Director BO/04/04 1p
- 8004180117 Forwards IE Bulletin 80-08, 'Eram of Containment Liner Penetration Welds " Written response required CRIER.B H Region 1. Philadelphia. Office of the Director 80/04/07 to
- R Periodic operating reports & related correspondence
- 8004210192 Forwards "Nonradiological Environ Monitoring Rept, Jan-Dec LUNDVALL, A E Baltimore Gas & Electric Co 80/03/14 1p
- -8004210197 "Nonradiological Environ Monitoring Rept. Jan-Dec 1979 " * Baltimore Gas & Electric Co * Academy of Natural Sciences of Philadelphia 80/03/Jl 400mb
- 8004070275 Forwards, "Radiological Environ Monitoring Program, Annual Rept.1979 " LUNDVALL,A E Baltimore Gas % Electric Co 80/03/28 ip
- --8004070276 "Radiological Environ Monitoring Program Annual Rept.1979 " BARTAL, L. J., RAFI, A., REICHERT, E.C. Baltimore Gas & Electric Co 80/03/31 50pp
- 8004250406 Forwards monthly operating repts for Har 1980 Correction to Feb 1980 monthly operating rept requested MERSON.S D Baltimore Gas & Electric Co 80/04/15 1p
- --8004250407 Monthly operating repts for Mar 1980 HERSON, S.D. Baltimore Gas & Electric Co. 80/04/14 18pp
- S Reportable occurrences, LERs & related correspondence
- 8004010437 Forwards LER 80-010/031-0 RUBSELL, L B Baltimore Gas & Electric Co 80/03/24 1p
- --8004010448 LFR 80-010/03L-0 on 800224 during surveillance testing, control element assemblies 31 % 34 dropped into core Caused by fault in timer module Module replaced LAGIENSKI, J S , BAUER, E R Baltimore Gas & Electric Co 80/03/24
- 8004010342 Forwards LER 80-001/03L-0 RUSBELL,L B Baltimore Gas & Electric Co 80/09/25 ip
- --800401035% LER 80-001/03L-0 on 800225, atthough low pressure safety injection pump 21 was placed out of svc for maint, containment spray pomp 21 was disassembled Caused by verbal communication error DAVIS.8 M. PENCE.W B Baltimore Gas & Electric Co 80/03/25
- 8004010376 Forwards LER 80-019/02L-0 RUSSELL, A Bajtimore Gas & Electric Co 80/03/25 1p
- ~~8004010383 LER 80 019/02L-0 on 800312,while performing QC insp, cable A2Y0929P was found incorrectly routed, which violated cable separation criteria Caused by personnel not following designed routing of cable Temporary cable installed BAUER.E R Baltimore Gas & Electric Co 80/03/25 ip
- 8004010380 Forwards LER 80-015/03L-0 RUSSELL,L B Baitimore Gas & Electric Co 80/03/25 ip
- --8004010389 LER 80-015/03L-0 on 800227, during maint, control element assembly 44 dropped into core Caused by electrician accidentally grounding prime 15 volt power supply Faulty backup power supply was changed LAGIENSKI, J S, BAUER, E R Baltimore Gas & Electric Co 80/03/25
- 8004010364 Forwards LER 40-016/03L-0 RUSBELL:L B Baltimore Gas & Electric Co 80/03/28 ip

DOCKETED ITEMS

- --8004010368 LER 80-016/03L-0 on 800303 emergency diesel generator 21 was placed out of svc after it failed to reach rated speed during start test Caused by diesel generator governor slow response Governor replaced all governors inspected DAVIS, 8 M . HUSEBY, D E Baltimore Gas 2, Electric Co 80/03/28
- 8004080480 Forwards LER 80-017/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/04/02 1s
- --8004080488 LER 80-013/03L-0 on 800303, channel ZF pressure input signal for steam generator isolation 22 was byposed Caused by signal isolater 2 E/E-1023C being out of calibr due to nonlinear response HEIBEL, R P , RIZZO, P G Baltimore Gas & Electric Co 80/04/02 2pp
- 8004150483 Forwards LER 80-017/03L-0 RUSSELL, L B Maitimo: e Gas & Electric Co 80/04/10 1p
- --8004150486 LER 80-017/03L-0 on 800316, saltwater svc water heat axchanger 22 was taken out of svc Caused by need to repair tube leak found & plugged HEIBEL, R P , PENCE, W D Baltimore Gas & Electric Co 80/04/10
- 8004150624 Forwards LER 80-018/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/04/10 1p
- --8004150438 LER 80-018/03L-0 on 600311. during routine insp tour.watch stander noticed loak weld on 23 charging pump suction relief valve causing depradation of sys designed to contain radioactive fluid Caused by vibration-induced metal fatigue DAVIS.8 M . HUSEBY, D E Baltimore Oas & Electric Co 80/04/10 1p
- 8004210323 Submits info in confirmation of 800415 conversation w/RE Architzel re generic deficiency & FSAR.Section 14 3 concerning boron dilution incident Operating procedures will be changed to require min 2% shutdown margin DAVIS.8 M Baltimore Gas & Electric Co 80/04/16 ip
- 8004220745 Forwards LER 80-021/03L-0 RUBBELL, L B Baltimore Gas & Electric Co B0/04/18 1p
- --8004220788 LER 80-021/03L-0 on 800318, during performance of surveillance test 23, saltwater pump did not start upon receipt of safety actuation signal Caused by faulty pin Pin replaced HEIBEL, R.P., RIZZO, P.G. Baltimore Cas & Electric Co. 80/04/18/200
- 8004250411 Forwards LER 80-020/03L-0 RUBBELL,L B Baltimoro Gas & Electric Co 80/04/18 ip
- --8004250417 LER 80-020/03L-0 on 800320.during surveillance testing. channel D high power went into trip condition Malfunction stopped before cause could be determined LAGIENBRI.P G Baltimore Oas & Electric Co 80/04/18 1p
- 8004290345 Forwards updated LER 79-001/03X-1 RUSBELL, L B Baltimore Gas & Electric Co 80/04/25 Ip
- ~-B004270350 Updated LER 77-001/03x-1 on 770106.RCS had unidentified leakage of 1 546 gpm.exceeding Tach Spec Caused by cracked weld located on socket weld downstream of second isolation valve Weld repaired HUSEBY, D E , DAVIS, 8 M Baltimore Cas & Electric Co B0/04/25
- 8004290410 Forwards updated LER 79-003/01X-2 RUSBELL, L B Daltimore Gas & Electric Co 80/04/29 ip
- --B004270416 Updated LER 79-003/01X-2 on 790120, reactor coolant pump 22A lower seal temp alarm activated & 2 gpm increase in leak rate noted Reactor manually tripped Caused by cracked weld on seal pressure sensing line Seal assembly replaced CARROLL.J D , HUSEBY.D E Baltimore Gas & Electric Co 80/04/25 ip.
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

 G Utility Environmental Report (ER), amends & correspondence
- 8004210072 FOIA request on behalf of UCS for documents re venting of Kr-85 gas from facility containment LEAB, J. Union of Concerned Scientists 80/03/13, 2pp

- BOO4210069 Responds to FOIA request for documents to venting of Kr-85 gas from facilisty containment Documents listed in app are being placed in Washington.DC PDR FELTON.J I. Division of Rules and Records 80/04/09 2pp
- F Security, medical, emergency & rise protection plans
- BOO4030142 Forwards index of recommendations appropriate for FEMA responsibilities to emergency proparedness planning around nuclear power plants & federal rule in responding to power emergencies GRIMES, B Emergency Preparedness Task Force 80/03/12 App
- 8004190350 Forwards Revision 6B to modified amended physical security plan Plan withheld (ref 100FR2 790) HERBEIN, J O Metropolitan Edison Co 80/04/02 1p
- B004300409 Advises that std market weather alert monitor is sufficient for use in notifying public, regardless of on-off switch HERBEIN, J G Metropolitan Edison Co 80/04/25 1p
- G Adjudicatory correspondence
- /708300622 Opposes reopening of TMJ & nuclear power in general because of risk of genetic damage by high energy subatamic particles
 STOKELY M F Affiliation Unknown 79/08/23 ip
- 8002040380 Criticizes waste removal & decontamination efforts at TMJ Charges (ARC w/abuse of public opinion & feelings:coverup & insensitivity to problems caused by nuclear power JONES, D. Affiliation Uninoun 80/01/25 7pp
- 8004070192 Explains circumstances involving 800222 svc of BNWL draft rept re measurements of underground mining radon releases 8 NRC testimony of RN Wilde re same rept Missing Page 6 enc)
 BORDENICK B M Hearing Branch 4 80/03/05 App
- BOO4140061 Requests public hearing to evaluate proposed Tech Specs, App A to License DYR-73, NUREG-0432 Will determine whether Tech Specs are sufficient to protect public health & safety for duration of cleanup operations Certificate of Svc encl JOHNSRUD, J H Environmental Coalition on Nuclear Power 80/03/15
- ---8004)40047 Emergency request for public hearing prior to alteration of current experimental & operational status of TMI-2 not in accordance w/Tech Spocs.App A Serious Tech Spocs violations have resulted in current degraded reactor core KEPFORD.C R Environmental Coalition on Nuclear Power 79/04/27
- --8004140075 Supplements 790427 emergency request for public hearing Receipt of petition has not been acknowledged by Director of Nuclear Reactor Regulation Suppl is submitted due to continuing crisis caused by 790328 accident KEPFORD, C Environmental Coalition on Nuclear Power 79/05/16
- 8004070056 Director's decision under 10CFR2 206 denying R Gary 800227 petition in which installation of cryagenic traps before radioactive gas venting, was requested NUREG-0662 of Mar 1980 considered & recommended solution to issue DENTON, H R Office of Nuclear Reactor Regulation 80/03/18 2pp
- 8004110078 Request for hearing & petition for leave to intervene in evidentiary hearings on proposed Tech Specs Tech Specs may be inadequate, resulting in unusually large radiation releases Certificate of Svc encl LOCKSTET. H A Affiliation Unknown 80/03/18 4pp
- BOO4140111 Forwards Director's decision under LOCFR2 206, Request for action dtd BOO227, denied Petition dtd BOO225 under consideration DENION, H R Office of Nuclear Reactor Regulation BO/03/18 ip
- --BOD4140117 Director's decision under 10CFR2 206 denying request that NRC require installation of cryogenic traps before planned venting of radioactive gas from TMI-2 DENTON:HR Office of Nuclear Reactor Regulation BO/03/18 2pp
- 8004110184 Requests hearing to determing whother requirements set forth in proposed Tech Specs are necessary & sufficient to protect public health & safety Tech Specs do not take into account hazards posed by continuing accident at TMI-2 SHOLLY, 8 C Affiliation Unknown 80/03/21 2pp

- #CO4090465 Muti in to upen toward for receipt or USUS 7.5 minute series maps PRC Enhibit 1 previously received as Enhibit 2.
 Transcript 247 Parties have no objection to motion
 Certificate of Sic enul
 LHANDLER L. J. Heating Araich L. #D/v3/31 App
- 8004220008 Response in opposition to Environ Coalition on Nuclear Power 800315 petition for healing 7 for participation for Tech Spec anend Urges profit assignment of MEIB 2 early scheduling of prehearing foliefence Certificate of Sic encl SLBERG J E BERRSTEIR. b. 1 Metropolitan Edison Co SILBERG J E Shaw, Pittnan Patts 7 Trombridge 80/03/31 9pp
- E004080574 Order granting NRC unopposed notion to reopen record for receipt of Exhibit 4 Order taken w/o M9 Johnson participation BISHOP C J Atomic Sarety and Licensing Appeal Panel 80/04/01
- 8004030026 Menorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Soard notification GOTSECK, V Office of the Electrive Director for Operations CAMM,F Federal Emergency Management Agency 60/04/02 34pp
- 8004220102 Response in apposition to UA Lochstet 800318 request for hearing? for intervention re Tech Spec amends Urges prompt assignment of ASLS & early schedule of prehearing conference to determine issue Certificate of Svc enci SILBERS, J E. BERISTEIN D L. Metropolitan Edison Co. SILBERG, J E. Shaw Pittman. Potts & Trowbridge 80/04/02 15pp
- 8004220405 Response to WA Locksfet request for hearing & petition to intervene Petition fails to neet code requirements reassertion of interest which may be affected by proceeding W/Certificate of Svc BERNSTEIN.D L Hetropolitan Edison Co BERNSTEIN.D L Shaw. Pittman. Potts & Troubridge 80/04/02 15pp
- 8004070370 Response in support of Environ Coalition on Nuclear Power 800315 request for hearing re Ofc or Nuclear Reactor Regulation 800311 order Although deficient petition may be cured by filing required contentions W/Certificate of Svc BORDENICK.B M Hearing Branch 4 80/04/04 7pp
- 6004090396 Response in support of WA Lochstot 800318 request for hearing & petition to intervene, per Ofc of Nuclear Reactor Regulation 800211 order Although partially deficient, petition may be cured Certificate of Svc encl BORDENICK.B M Hearing Branch 4 80/04/04 6pp
- 8004210085 Response stating no present opposition to SC Sholly 800321 request for hearing re interest in Tach Spec amend proceeding Urges prompt assignment of ASLB & early scheduling of special prehearing conference SILBERG. J E , BERNSTEIN. D L Metropolitan Edison Co SILBERG. J E Shaw. Pittman. Potts & Troubridge 80/04/07 4pp
- 304230084 Director's decision under 10CFR2 206 denying R Gary 800225 petition in which certain actions re-radiation monitoring & energency planning were requested Decision will constitute final action unless Cornission institutes review in 20 days DENTON. H R Office of Nuclear Reactor Regulation 80/04/07 6pp
- 8004300508 Forwards Director's decision denying 800225 request for action re radiation monitoring & emergency planning at site DENTON,H R Office of Nuclear Reactor Regulation 80/04/07 ip
- --8004300519 Advises that two requests for action have been received from R Cary re radiation monitoring & emergency planning at site Both requests have no legal foundation & Director's decision should be issued immediately MURRAY.J P Office of the Executive Legal Director 80/03/10 2pp
- 8004150226 Motion for extension until 800430 & 0526 per parties' agreement to submit post-hearing b reply memoranda, respectively re aircraft crash probability issues Certificate of Svc encl CHANDLER.L J . TREBY.S A Hearing Branch 1 80/04/11 3pp
- 8004150499 Forwards adjudicatory hearing stipulation of settlament document re NPDES Permit 0009920
 HERBEIN, J 9 Metropolitan Edison Co 80/04/11 4pp
- 8004300020 Determination deciding that TMI-2 accident does not constitute extraordinary nuclear occurrence within meaning of Atomic Energy Act & Commission regulations
 AHEARNE.J F Commission 80/04/16 22pp

- 8004250373 Requests review ' reconsideration of 800407 Director's decision under 10CFR2 206 denying 800225 petition Interests of public health demand that cleanup be started at facility CARY,R Affiliation Univoum 80/04/18 2pp
- 8004280222 Order granting extension until 800507 for Commission to elect whether to review Director's 800407 decision denying enforcement action under 100FR2 206 Certificate of Svc encl CHILK, S. J. Office of the Secretary of the Commission 80/04/23 2pp

- 7908210247 Ack 790412 receipt of water sensor catalog Suggests that industrial 5 utility users would be more appropriate recipients DENTON.H R Dffice of Nuclear Reactor Regulation 79/06/26 1p
- --7908210253 Forwards ratalog sheets to water lovel sensors Suggests application in teactor installations
 GRUENSFELLDER:K K F Industries.Inc 79/04/12 3pp
- 8004080106 Submits York County Board of Assistance resolution recommending that disaster evacuation plans for nuclear accidents be required to include adequate provisions to meet needs of indigent \$ handicapped SIPE,L W
- 8004020227 Responds to 790919 ltr expressing concern re NRC participation in decision to place reactor in operation & NRC monitoring activities of reactor const Deyond licensing requirements, commercial operation is corporate docision VOLLMER.R H TMI-2 Operations/Support 80/02/05 2pp
- --8004020234 Expresses concern re NRC participation in decision to place reactor in operation & NRC monitoring activities of reactor const Ltr of 791024 to Met Ed expressing concern re Unit 1 restart encl
 EDMONSOR, L.D. Affiliation Unknown 79/09/19 App
- 8004070200 FOIA request for info re facilities & damage due to earthquakes at Indian Point BEBAS,P G Affiliation Unknown 80/02/10 ip
- 8004040300 Objects to radioactive discharges from units Officials irresponsible & not concerned w/public interest People must take immediate, unified action to gain control over environ & lives
 RENNO.E Affiliation Unknown 80/02/15 2pp
- 8004040307 Opposes release of radwaste water into Susquehanna River FORREST, Z Affiliation Uninown 80/02/15 ip
- 8004040308 Objects to use of Susquehanna River as dumping site for radioactive matls Urges NRC to find other methods of dispositing of waste OPPENHEIM.L Affiliation Unknown 80/02/15 ip
- 8004020286 Ack receipt of 800215 itr commenting on programmatic EIB re decontamination & disposal of wastes from 790328 accident at site Comments will be considered Statement & name have been added to statement mailing list SELLS,D E Environmental Projects Branch 2 80/02/25 ip
- 8004020217 Responds to 790610 ltr expressing concern for annual insp of pressure relief valve Maint schedule provides for pressurizer relief valve testing approx once yearly during refueling outage
 DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 ip
- ~-8004020221 Expresses concern for annual insp of pressure relief valve GINTECK,P Affiliation Unknown 79/06/10 ip
- B004040225 Responds to 790502 ltr requesting info re accident Several groups organized to identify safety concerns Compliance w/recommendations re reactor design analysis & operations will be required of nuclear plants

 DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 ip
- ~~8004040234 Requests info re accident CONNER.D E Affiliation Unknown 79/05/02 ip
- 8004040247 Responds to 790723 comments on effects of accident Avorage exposure of population within 50 mile radius of TMI was approx 4 mrem Max exposure to any individual was less than 100 mrem which is less than normal annual exposure BENTON.H R Office of Nuclear Reactor Regulation 80/02/28 2pp

- --8004040257 Comments on effects of accident SNYDER, I E Affiliation Unknown 79/07/23 4pg
- B004020456 Responds to 791207 Itr re facility licensing & discusses preparation of action plan for implementing safety objectives
 DENTON, HR Defice of Nuclear Reactor Regulation 80/03/03 in
- ---8004020458 Requests re-evaluation of licensing moratorium & suggests individual review of proposed facilities
 MARCHAND,R Marchand Construction,Inc 80/03/03 1p
- 8004020461 Responds to 791203 ltr to President Carter expressing concern over moratorium on issuance of CPs & DLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DDE 800125 memo encl DENTON.H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004020465 Forwards JA Lehman 791203 itr to President Carter discussing moratorium on issuance of CPs & DLs White House 791227 transmittal & EM Loggins (Oulf States Utils Co) 791119 ltree moratorium encl
 RATHKOPF, C L Energy, Dept of 80/01/25 7pp
- BOO4030019 Responds to 791207 ltr re facility licensing & discusses preparation of action plan for implementing safety objectives
 DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 ip
- --8004030033 Urges lifting of licensing moratorium FIBHER, J R Affiliation Unknown 79/12/07 ip
- 8004030022 Responds to 791231 ltr re facility licensing & dicusses preparation of action plan for implementing safety objectives
 DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 lp
- --8004030028 Requests reversal of licensing moratorium & expeditious handling of nuclear energy development IRBY, 8 C Affiliation Unknown 79/12/31 ip
- 8004030035 Responds to 791221 ltr re facility licensing & discusses preparation of action plan for implementing safety objectives
 DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 lp
- --8004090038 Urges recognition of nuclear industry initiative since accident & removal of licensing freeze
 JEANES, J W Affiliation Unknown 79/12/21 lp
- 6004030052 Responds to 771128 ltr to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Komony Commission recommendations re YM investigation DCE 800122 memo encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030054 Forwards LF Megow 771128 ltm to President Carter discussing moretorium on issuence of CPs & QLs White House 791213 transmittal encl RATHKOPF, C.L. Energy, Dept of 80/01/22 3pp
- BOO4030061 Responds to 791126 ltr to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommondations re TMI investigation DE BOO125 memo encl DENTON, HR Office of Nuclear Reactor Regulation 60/03/03 2p
- --8004030065 Forwards CM Henry itr to President Carter discussing moratorium on issuance of CPs & OLs White House 771204 transmittal encl
 RATHKOPF,C L Energy,Dept of 80/01/25 3pp
- 8004030087 Responds to 741206 ltr to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommendations re THI investigation DDE 800122 memo encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030093 Forwards RE Putfark 791204 ltr to President Carter discussing monatorium on issuance of CPs & OLs White House 791213 transmittal encl RATHKOPF, C L Energy, Dept of 80/01/22 3pp
- 8004030123 Responds to 790816. Itr re plans to reopen TMI-i:nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ No diseases resulted from TMI DENTON; HR Office of Nuclear Reactor Regulation 80/03/03 2pp

- --8004030129 Opposes restart of THI-1, const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety
 FOSTER.K. Affiliation Unknown 79/08/16 2pp
- BOO4040211 Responds to 791118 ltm to President Carter expressing concern over moratorium on issuance of CPs & GLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DDE BOO122 memo encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004040237 Forwards P Stark 791118 ltr to President Carter discussing moratorium on issuance of CPs & OLs White House 791213 transmittal & San Diego Union news articles oncl RATHKOPF,C L. Energy, Dept of 80/01/22 App
- 8004040214 Responds to 791113 ltm to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommendations or BTM investigation DDE 800125 memo encl DENTON-HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- ---8004040245 Forwards WR Periault 791113 ltr to President Carter discussing moratorium on issuance of CPs ½ CLs White House 791203 transmittal encl RATHKOPF,C L. Energy, Dept of 80/01/25 3pp
- 8004040215 Responds to 791101 ltr to President Carter expressing concern over moratorium on issuance of CPs % OLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DDE 800122 memo encl DENTON, N R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --B004040248 Forwards M Russ 791101 1tr to President Carter discussing moratorium on issuance of CPs & QLs White House /91213 transmittal enc? RATHKQPF.C L Energy, Dept of 80/01/22 4pp
- BCO4040218 Responds to 791129 lt: to President Carter expressing contern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DDE 800125 memo encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004040265 Forwards FM Staszesky 791129 ltr to Prosident Carter discussing moratorium on issuance of CPs & OLs White House 791227 transmittal encl RATHMOPH.C L Energy.Dept of 80/01/25 4pp
- 8004040219 Responds to 791121 ltr to President Carter expressing concern over moratorium on issuance of CPs t OLs Discusses transition period during implementation of Komeny Commission recommendations re TMI investigation DOF 800122 memo encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004040253 Forwards El Nugent 791121 itr to President Carter discussing moratorium on issuance of CPs % OLs White House 791213 transmittal encl
 RATHKOPF,C L Energy, Dept of 80/01/22 3pp
- BO04040220 Responds to 791115 ltr to President Carter expressing concern over moratorium on issuance of CPs & DLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DDE B00125 memo encl DENTON:H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004040258 Forwards WR Bledsoe 791115 ltr to President Carter discussing moratorium on issuance of CPs & OLs White House 791204 transmittal & Engineering News Record 791101 article encl RATHKOPF.C L Energy.Dopt of 80/01/25 App
- 8004040223 Responds to 791121 lir to President Cartor expressing concern over moratorium on issuance of CPs & DLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DDE 800125 memor encl DENTON.H R Office of Nucleur Reactor Regulation 80/03/03 2pp
- ---B004040263 Forwards EM Page 791121 Itr to President Carter discussing moratorium on issuance of CPs & OLs White House 791204 transmittal & P Unch & J Udy article 'Personal Transportation Safety Evaluation of Evidence,' encl RATHKOPF.C L Energy Dept of 80/01/25 App
- BOO4220159 Responds to 800115 ltr Forwards Presidential statement on radwaste Two private nuclear energy liability insurance pools paid 13th annual refund of premium reserves to util policyholders NRC committed to public safety DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 6pp

- --8004220162 Discusses need to resume facility licensing Newspaper article encl RAYMOND.L W Affiliation Unknown 80/01/15 2pp
- 60040300/0 Responds to 791126 ltr to President Carter expressing concern over moratorium un issuance of CPs % OLs Discusses transition period during implementation of Keeneny Commission recommendations ie TNI investigation DUE 800122 memo encl DENTON-HR Office of Nurlear Reactor Regulation 80/03/05 2pp
- ---B0040300/1 Forwards LJ Styslinger 791126 ltm to President Carter discussing moratorium on assuance of CPs & OLs White House 791213 transmittal encl RATHKOPF.C L Energy.Dept of 80/01/22 4pp
- BO04040202 Responds to 79:128 lt; to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DDE 800122 memo encl DENTOWH R Office of Nuclear Reactor Regulation B0/03/05 2pp
- --8004040233 Forwards G Esser 791128 lts to President Carter discussing moretorium on issuance of CPs & DLs White House 791213 transmittal % J Cook article 'On Failure of Govt" encl RATHKOPF.C L Finergy, Dept of BO/01/22 9pp
- 8004040421 Discusses transition period during implementation of Kemeny Commission recommendations to TMI investigation, in response to 791123 ltr to President Carter expressing concern over moratorium on issuance or CP & OL DOE 800122 memo encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/05 2pp
- --8004040431 Forwards JO Weigand 791123 ltr to President Carter re moratorium on issuance of CP & OL White House 791203 meno transmitting ltr encl RATHKOPF.C L Fnergy.Dept of 80/01/22 3pp
- 8004020127 Responds to 800125 ltr commenting on programmatic EIS redecontamination & disposal of radwastes Comments will be considered in preparation of statement SELLS DE Environmental Projects Branch 2 80/03/10 ip
- B004030265 Responds to B00121 ltr expressing concern re radwaste disposal & emergency responso Preparation of programmatic EIS on decontamination & radwaste disposal underway Ltrencl
 SELLS.D E Environmental Projects Branch 2 80/03/10 1p
- 8004090268 Responds to 800207 ltr commenting on programmatic EIG re decontamination & disposel of radwastes Comments will be considered in preparation of statement SELLS,D E Environmental Projects Branch 2 80/03/10 ip
- --8004090274 Comments on programmatic E15 re decontamination & disposal of radwastes Statement should consider interstate agreements between MD-PA 1 NRC to assure cooperation in monitoring across state lines & in Susquebanna River KOWALCZYK.W J Affiliation Unknown 80/02/27 2pp
- 3004090276 Responds to B00218 ltr commenting on programmatic EIS redecontamination / disposal of radwastes Comments will be considered in preparation of statement BELLS.DE Environmental Projects Branch 2 B0/03/10 ip
- --8004070279 Submits comments made at 800215 meeting in Baltimore.MD re programmatic EIS on decontamination ? disposal of radwastes Important factors, such as NRC & util authority, have not been sufficiently examined KRIEMELMEYER.H Kriemlmeyer.H 80/02/18 1p
- 8004110096 Expresses concern over possible effects of release of krypton gas from racility PETRILLO.M Affiliation Unknown 80/03/11 2pp
- 8004030153 Responds to 800305 request for EIS re decentamination & disposal of radwaste resulting from facility incident DES has not been published Scheduled issuance is in June 1980 Copies will be forwarded SELLS.D E Environmental Projects Granch 2 80/03/12 tp
- --B004030156 Requests 2 ropies of E18 for alternative waste proposal for radwaste from facility incident MERCURI.J Western Washington State College 80/03/06 ip
- B004220136 Ack receipt of 791106 ltr criticizing nuclear power safety Forwards 791207 press release to Kemeny rept on TM1 Also forwards 791207 fact sheet re Presidential response to Kemeny Commission recommendations DENTON: HR Office of Nuclear Reactor Regulation 80/03/03 1600

- --B004220143 Forwards JC Sinclair 791106 ltm to President Cartem for reply Ltm misdirected to DDE RATHKOPF,C L. Energy,Dept of B0/01/22 3pp
- 8004040230 Ack receipt of D Burgess 800215 comments for programmatic EIS on decontamination / dispposal of raduaste from TMI accident Comments considered in preparation of EIS SELLS.D E Environmental Projects Branch 2 80/03/17 ip
- 8004280267 Comments on 'Frviion Assessment for Decontamination of Site Containment Bidg Atmosphere " Public hearing would be in order before final action Expeditious action needed, but not at cost of public health " safety CRUMLEY, J J Affiliation Unknown 80/03/18 ip
- 80042103Bl Responds to ltr re permanent shutdown of facility, cleanup of waste & payment of expenses concerning accident Dry wastes are packed in steel drums % shipped to burial sites Util customers do not pay for facility restoration DENTON, HR Office of Nuclear Reactor Regulation 80/03/19 2pp
- --8004210391 Opposes reopening of Unit 1 Expresses concern re mgt & storage of waste matls \$ payment of incurred costs
 KELLY.P Affiliation Unknown 79/08/14 ip
- 8004210396 Ack receipt of itrs re facility Public hearing to be conducted to determine whether facility should be operated Will conduct review of technical info on restait Forwards Commission order M/o enci DENTGN.H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- 8004220112 Responds to 791227 ltr to President Carter Forwards Presidentia) statement on Kemeny Commission rept Every effort being made to protect public health & safety at all nuclear power plants DENTON.H R Office of Nuclear Reactor Regulation 80/03/19 4pp
- --B004220124 Forwards D Funderud 791227 ltr to President Carter for reply Ltr misdirected to DOE RATHKOPF,C L Emergy,Dept of 80/01/25 3pp
- BOO422016B Responds to 790617 ltr re Unit 1 Every effort being made to protect public health & safety at all nuclear power plants currently operating or planned for operation Restart hearing has not yet begun

 DENTON.HR Office of Nuclear Reactor Regulation 80/03/17 ip
- --8004220171 Requests adherence to regulatory directives PHILLIPS.L B . PHILLIPS.V Affiliation Unknown 79/06/17 ip
- 8004220182 Responds to encl 790522 ltr to President Carter requesting facility shutdown Every effort being made to protect public health & safety at all nuclear power plants in operation or planned for operation BENTON. HR Office of Nuclear Reactor Regulation 80/03/19 4pp
- 8004220185 Responds to 791002 ltr to President Carter urging that Americans be informed of useful lessons manifested by Kemeny Commission study Forwards Presidential public statement on Kemeny rept DENTON:H R Office of Nuclear Reactor Regulation 80/03/19 4pp
- ---8004220191 Forwards FL McMillan 791002 ltr to President Carter for reply Ltr misdirected to DDE RATHKOPF.C L. Energy, Dept of 80/01/22 3pp
- 8004240270 Responds to 790815 ltr to Hendrie re concerns of polluting environ through EPICOR-11 sys Method is limited to decontamination of waste water Processing will not remove all radioactivity
 DENTON.H R Office of Nuclear Reactor Regulation 80/03/19 ip
- --8004240282 Expresses concern re use of EPICOR-11 sys to process water when NRC admits use will involve exposing plant workers to radiation 8 release Xe-133 & 1-131 to environ GILBERT.R 8 Affiliation Unknown 79/08/15 1p
- 8004240441 Responds to 790B15 ltr expressing concern re pollution of environ by use of EPICOR-11 sys Sys will clean water in auxiliary bldg to extent that no further risk will be posed Environ assessment will be issued prior to disposal DENTON.HR Office of Nuclear Reactor Regulation 80/03/19 Zpp
- --8004240447 Expresses concern re plans for disposal of contaminated water at TMI-2 Use of EPICOR-II sys will poliute environ & expose workers to radiation OILBERT,R S Affiliation Unknown 79/08/15 ip

- 8004250111 Responds to 790508 ltr & newspaper column re accident & advises that no Pu was released DENTON, H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- BO042B0260 Responds to 790B06 ltr suggesting ways to improve security at facilities * advises that compliance w/iOCFR73 55 & ANSI 18 17 protects against sabotage *b* unsatisfactory personnel, respectively
 DENTON, H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- --8004280268 Urges mandatory internal program be set up to screen potential employees for saboteurs & incompetents GORDON, L. Affiliation Unknown 79/08/06 ip
- 8004280273 Responds to 790802 ltr to President Carter re accident & forwards NUREC-0558, "Population Dose & Health Impact of Accident" & NUREC-0600 "Investigation into 800328 Accident by IE " W/o encl
 DENTON, H R Office of Nuclear Reactor Regulation 80/03/19 Jpp
- BOO42BO279 Responds to 790423 ltr to President Carter re health effects of accident 2 advises that NRC investigators concluded offsite collective radioactive dose was minimally risky Summaries of NUREO-0558 2 0600 enc! H/o enc!

 DENTON: H R Office of Nuclear Reactor Regulation BO/03/19 4pp
- BOO42B02B7 Responds to 790416 itr urging permanent shutdown of facility & advises that public hearing & technical review will take place before restart Licensee's authority to operate Unit 2 suspended by 79072O order DENTON, H R Office of Nuclear Reactor Regulation BO/03/19 3pp
- --B004280303 Urges permanent closing of facility to avoid nuclear destruction NEIDIG.M Affiliation Unknown 79/04/16 1p
- 8004280325 Responds to ltr to Commissioner Hendrie re dumping of radioactive water into Susquehanna River Releases of contaminated water are not currently permitted except for liquids containing low or nondetectable radiation levels DENTON, HR Office of Nuclear Reactor Regulation 80/03/17 80/03/19 2pp
- --8004280337 Opposes dumping of radioactive water into Busquehanna River NRC action represents malicious disrogard for well-being of humanity Urges proper permanent disposal of radwaste BOSSER, M A Affiliation Unknown 80/03/19 ip
- 8004280527 Responds to postcard urging permanent closing of facility & advises that no radiation induced deaths have occurred Notifies of public hearing & technical review planned before restart Forwards 790809 notice of hearing W/o encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/19 3pp
- --8004280532 Urges permanent closing of facility & expresses fear re health effects of accident HEITMULLER, H Affiliation Unknown 79/06/11 ip
- 8004280535 Responds to 790328 request for publications re accident investigation & discusses repts & availability Summaries of NUREO-0600 & 0558 encl W/d encl DENTON.H R Office of Nuclear Reactor Regulation B0/03/19 3pp
- --8004280540 Requests rept on accident investigation when available KIMBLE.K Affiliation Unknown 79/03/28 2pp
- 8004280542 Responds to 790410 request for info re NRC decision to license facility on 781230 & advises that Met Ed was issued OL several months prior to full generation BO/03/19 2pp RENTON:H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- -- 8004280545 Protests NRC decision to license facility on 781230 to save util taxes & requests access to subj info EBTRADA.P San Luis Obispo.CA 79/04/10 20p
- 8004290064 Responds to 790510 1tr to NRC re facility accident In May 1977.NRC adopted resident inspector program Inspectors are presently assigned to approx 30 sites Nuclear plants are equipped w/numerous alarms & automatic shutdown equipment DENTON,H R Office of Nuclear Reactor Regulation BO/03/19 5pp
- --8004270068 Requests info re facility accident, including presence of govt inspectors at nuclear facilities, effectiveness of plant warning sys, responsibility for accident & actions taken by foreign countries in post-TMI period YURLSICH, B Affiliation Unknown 79/05/10 2pp

- 8004290076 Responds to Iti te disposal of radioactive water from TMI-2 Release of contaminated water into Susquehanna River is not currently permitted, except for liquids containing low or nondetectable levels of radioactivity DENTON, H R Uffice of Nuclear Reactor Regulation 80/03/19 2pp
- --8004270083 Opposes releases or radioactive water from TMI-2 into Susquehanna River NRC is trying to save nuclear industry w/o regard to interests of public BROUDE, H Affiliation Unknown 80/03/19 1p
- 8004070350 Opposes proposed release of Indicactive gases into atmosphere 8 water into Susquehanna River
 WALTERS.E Environmental Policy Center 80/03/20 2pp
- 8004210406 Requests that no action be taken before facility status is changed to recovery mode MANFRED, K II Affiliation Unknown 80/03/20 ip
- BOO4140091 Forwards requested copy of NRC comments on Heidelberg Rept June 1977 & Dec 1978 memos on strontium monitoring also encl W/O encls VOLLMER, R H TMI-2 Operations/Support 60/03/21 ip
- 8004210402 Responds to 790618 postcards opposing resumption of operation of facility Every effort being made to protect public health & safety at all nuclear power plants currently operating or planned for operation DENTON.HS R Office of Nuclean Reactor Regulation 80/03/22
- ~~BOO4210403 Protests reopening of facility MASTER,N Affiliation Unknown 79/06/18 1p
- 8004210356 Responds to 790904 lir is release of Kr-851 from facility Util "Safety Analysis & Environ Rept" states that optimum choice for ielease of Kr-851 is atmospheric dispersion through controlled purging of reactor bidy atmosphere DENTON, HR Office of Nuclear Reactor Regulation 80/03/24 2pp
- --8004210360 Opposes reopening of facility % release of Kr-85 into atmosphere Requests plans for disposal of waste LEONARD, J Affiliation Unknown 79/09/04 ip
- 8004210363 Responds to its reholding of public hearings on facilities Commission has ordered that public hearing be conducted to determine whether Unit 1 should be operated Will conduct review of technical info on restart DENTON, IR Office of Nuclear Reactor Regulation BO/03/24 2pp
- --8004210373 Expresses conviction that public hearings must be held in communities within 25-mile radius of facility site LYDNS:E Affiliation Unknown 79/07/23 2pp
- 800421039B Responds to 800222 Itr inquiring whether ECCS for PWRs have been changed after TMI incident Short-term requirements implemented for PWRs, none of which is "more powerful safety injection sus." Injection sys "
 MATTSON, R J Division of Systems Safety 80/03/24
- --8004210397 Inquires whether FCCS for PWRs have been changed following TMI accident, list of changes, reasons & analytical basis & repts on changes WEBB.R E Affiliation Unknown 80/02/22 ip
- 8004280342 Responds to 791630 ltr to NRC re TMI NRC has ordered public hearing to determine whether TMI-1 should be restarted Licensee authority to operate Unit 2 was suspended by NRC 790720 order DENTON, HR Office of Nuclear Reactor Regulation 80/03/24 2pp
- -8004280350 Opposes reopening of TMI due to health hazard posed to area residents Requests info re plans to dispose of radioactive water which flooded reactor Hater may freeze in winter 8 burst containment wells

 GAMBIRO
- 8004280357 Responds to encl 790404 ltr to President Carter re facility After chemically inert noble gases entered auxiliary & fuel handling blogs release to atmosphere was inevitable All licenses required to leaf—test sys outside reactor bldg DENTON: HR Office of Nuclear Reactor Regulation 80/03/24 4pp
- 8004280550 Responds to 790401 mailgram supporting UCS position for immediate evacuation of residents within 30 mile radius of TMI & shutdown of other B&W PMRs Radioactive releases did not warrant evacuation Doses averaged lass than on jet trip DENTON.H R Office of Nuclear Reactor Regulation 80/03/24

- --8004280553 Supports UCS position for immediate evacuation of residents within 30 mile radiu. of TML 5 shutdown of all BPW PWRs for Friends United for Safe Energy 79/04/01 2pp
- 8004280565 Responds to 770502 ltr to President Cartei re facility restart & advisos that public hearing & technical review will first take place licensee is conducting feasibility studies re Unit 2 jecovery DENTOR:H Office of Nuclear Reactor Regulation 80/03/24 3pp
- B004150407 Forwards comments re NRC draft environ assessment for decontamination of reactor bldg atmosphere Environ assessment lacks perspective required for public to understand significance or proposed action FREDRICKSON.C Affiliation Unknown B0/03/25 4pp
- 8004180442 Forwards NUREG-0991 "Environ Assessment for Use of EPICOR-II at TM1.Unit 2 " W/o enc! VOLLMER.R H TM1-2 Operations/Support 80/03/25 ip
- 8004210319 Forwards NUREG-0591 "Environ Assessment for use of EPICOR-II at THI.Unit 2 ' W/o encl VOLLMER.R H TMI-2 Operations/Support 80/03/25 (p
- 8004210324 Forwards NUREG-0591 "En.ison Assessment for use of EPICOR-II at TMI,Unit 2 ' W/o encl VOLLMER.R H TMI-2 Operations/Support 80/03/25 1p
- 8004210332 Forwards NUREG-0591 "Environ Assessment for Use of EPICOR-II at TMI,Unit 2 " W/o enc! VOLLMER,R H TMI-2 Operations/Support 80/03/25 ip
- 8004210333 Forwards NUREC-0591 'Environ Assessment for Use of EPICOR-II at TM].Unit 2 " W/o encl VOLLMER.Я H TM]~2 Operations/Support 60/03/25 ;p
- 8004210337 Forwards NUREC-0591 "Environ Assessment for Use of EPICOR-II at TMI.Unit 2 " W/o enc! VDLLMER.R H TMI-2 Operations/Support 80/03/25 1p
- B004210338 Forwards NUREC-0391 "Environ Assessment for Use of EPICOR-II at TM1.Unit 2 " W/o enci VOLLMER.R H TM1-2 Operations/Support 80/03/25 1p
- 8004100574 Responds to 770615 lit restait up of reactor Both Units 1 & 2 shut down Unit 2 where accident occurred will be shut down for some time NRC hearings to ascertain safety of Unit 1 will be conducted before starfup DENTON: H R Office of huclear Reactor Regulation 60/03/27 ip
- --8004100578 Requests info re startup of Unit 1 NRC should be investigating competence of util to have reactor license Presidential Commission rept should be studied Questions NRC concern for safety
 HOSTETTER, J Affiliation Unknown 79/06/15 ip
- 8004100581 Responds to 791212 Its re computers to safety stds used in nuclear power plants Digital computers used for monitoring operations to core protection calculator sys provides protection functions

 DENTON. H. R. Office of Nuclear Reactor Regulation 80/03/27 Ip
- --B0041005B2 Requests info re reliability of computers that control nuclear plants % safety stds since accident BRADSHAW, M Affiliation Unknown 79/12/12 1p
- BOO4020324 Comments on El6 re decontamination & cleanup activities Cost should not be significant factor in selection of cleanup processes or methods
 HOLTAN, A A Affiliation Unknown BO/03/28 2pp
- 8004070340 Requests NRC deny util right to release Krypton gases from damaged reactor People are expected to pity owners re costly cleanup & allow further crippling of environ AHENGER.L Affiliation Uninown 80/03/28 2pp
- B004100973 Responds to 791214 ltr to President re view on nuclear energy Carter 791207 statement end! Radiation doses resulting from accident will not cause detectable add1 cases of cancer DENTON, HR Office of Nuclear Reactor Regulation 80/03/28 1p
- --B004100575 forwards misdirected Barry 79;214 ltr to President re views on nuclear energy RATHKOPF,C L. Energy.Dept of 80/01/25 3pp

- B004040294 Uiges permanent closure Recommends using util as training site for experimental equipment & decommissioning procedures
 TEETS.T A . TEETS.R A Affiliation Unknown 80/03/29 1p
- 8004040320 Ack receipt of 800118 ltr re statement of policy & notice of intent to prepare programatic EIS EIS not yet received & final decision to dump radioactive gases & liquids set for 800408 Protests release & recommends entombent BROSS. I D Roswell Park Memorial Institute 80/03/31 3pp
- BO04090357 Urges NRC to provide educational matls in effort to educate public on nuclear energy Educated public is only way for fair decision re future of nuclear energy, restart of TMI-1 & cleanup of TMI-2 SNYDER, M O Affiliation Unknown 80/03/31 2pp
- BO04240253 Responds to B00209 ltr to HR Denton Documents published by or funded by NRC are in public domain W/o encil NUREO/CR-1093. "I'MI Telephone Survey." & NUREO/CR-1215, "Social & Economic Effects at Till."

 ERNST, HL Division of Site Safety & Environmental Analysis B0/03/31 ip
- B004280558 Advises that name of TMI organization has been changed to TMI Program Ofc 8 Snyder is program manager in Bethesda & JT Collins is deputy program manager at TMI Official correspondence should reflect change COLLINS, J T NRC Three Mile Island Task Force B0/04/01 4pp
- 8004020377 Requests consideration of certain factors in preparing EIS, including public mental & physical health effect of low level radiation on radio & television transmission of radioactive releases on photographic matls
 WHITCOMB.D Affiliation Unknown 80/04/02 6pp
- 8004220173 Ack receipt of ltr re financial situation of General Public Utils NRC does not regulate rates charged by electrical utils RRC is conducting hearing to determine whether TMI-1 can be restarted while TMI-2 cleanup proceeds GILINSKY, V Commission 80/04/02, 1p
- --8004220181 Urges NRC to expedite rate relief requested by General Public Utils & return TMI-1 to svc Unfair treatment accorded to General Public Utils has encouraged demonstrators LESH.L Affiliation Unknown 80/03/24 2pp
- 8004190400 Submits suggestions re implementation of EIS Board of citizens, consisting of persons unknown to NRC, doctors, veterinerians & physicists, should participate in preparation of EIS No Erupton should be vented into atmosphere KUEHNLE,0 Affiliation Unknown 80/04/03 2pp
- 8004290049 Responds to 790823 ltr re nuclear fission & biological effects of radiation EPA, Occupational Safety & Health Administration & NRC are responsible for regulating exposure to radiation or radioactive mat!

 DENTON, H. R. Office of Nuclear Reactor Regulation 80/04/03 2pp
- 8004i50372 Urges funding so that independent specialists can review & comment on all EIB Comments on NUREO-0662 EIB was announced eight months after facility accident Alternative to venting should have been developed in Apr 1979
 MOSSLER, D E Affiliation Unknown 80/04/06 3pp
- 8004230283 Responds to 800317 congressional referral of ltr re util failure to accept loan of cryogenic processing sys from Limerick facility rather than purging to atomosphere Purging chosen for expedience
 DENTON.H R Office of huclear Reactor Regulation 80/04/07 2pp
- BO04180431 Responds to B00214 ltrs re meteorological monitoring Monitoring program fully operational during TMI-2 incident Activities underway to enhance response capability & review development of deployable instrument package DENTON.R Office of Nuclear Reactor Regulation B0/04/08 3pp
- ---8004180439 Expresses concern for public safety following discharge of radioactivity into atmosphere Company atmospheric sounding techniques which track wind field containing radioactivity could provide info crucial to public safety GILMORE.D W Beukers Laboratories, Inc. 80/02/14 2pp
- 8004140368 Comments on NUREG-0662 Criticizes selection of ANLS as contractor for TMI E18, inadequate public participation process, insufficient consultation to absence of mechanism for independent review of purge proposal BURGESB, D Affiliation Unknown 80/04/09 2pp

- 8004170040 Comments on Addendum 2 to NUREG-0662 Supports rapid cleanup of TMI-2, including prompt venting of Kr-85 Criticizes NRC for failure to make decisions quickly & communicate adequately to public HOWARD, A S Affiliation Unknown 80/04/09 1p
- 8004150478 Forwards updated svc copy distribution list for facilities Notifies that OK Hovey has replaced RF Wilson as director of Unit 2 ARNOLD,R C Metropolitan Edison Co 80/04/10 5pp
- 8004220569 Comments on NRC "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere " Opposes venting due to lack of trust in NRC to ensure that public interest is primary consideration in decisionmaking RICHTER,T Affiliation Unknown 80/04/14 2pp
- 8004220418 Expresses opposition to venting of krypton gas Util has not researched all methods & presented intelligent explanation for each method Reasons for using venting presented only after public prodding
 BEVEL.K A Affiliation Unknown BO/04/15 2pp
- 8004230514 Comments on "Frviron Assessment of TMI Reactor Bldg Atmosphere "Technical explanations of atternatives will make no difference on attitudes of residents near facility Strategy to regain credibility should be foremost issue GUARANTELLI.E Ohio State Univ 80/04/16 2pp
- 8004270188 Responds to FOIA request for rept to inventory of TMI containment radwastes ½ disposition planned for each inventory Forwards documents listed in App A W/o encls FELTON, J M Division of Rules and Records 80/04/17 1p
- 7908010475 Forwards 790515 ltr re TMI incident BHANK.M J Affiliation Unknown 79/07/20
- ---7908010479 Expresses approciation for HR Denton's assistance during TMI incident Opposes plant reopening SHANK,R D , SHANK,M J Affiliation Unknown 79/05/15 1p
- I Financial information
- 8004030241 Forwards update to util B00219 ltr re projected 1980 cash flow forecast, reflecting recent rate relief Company is able to meet max retrospective premium
 HERBEIN, J G Metropolitan Edison Co 80/03/31 3pp
- B004070477 Forwards supplementary financial info in support of TMI-i restart proceedings
 HAFER,F D General Public III-ilities OPU Service Corp B0/04/03
- --8004090478 Transcript of PA Public Util Commission 800213 hearing in Harrisburg,PA Pp 1.763-2.143 SHANAMAN,S Pennsylvania, State of RUSSELL,S 8 , BELTZER,A M Ryan, Russell & McConaghy 80/04/03
- --8004090479 Transcript of PA Public Util Commission 800227 hearing in Harrisburg.PA Pp 2,494-2,527A SHANAMAN.S Pennsylvania. State of RUSSELL.S B , SELTZER.A M Ryan, Russell & McConaghy 80/04/03 37pp
- ---8004090480 Transcript of PA Public Util Commission 800228 hearing in Harrisburg.PA Pp 2.828-2,682 BHANAMAN.S Peunsylvania, State of RUSSELL,S B , SELTZER,A M Ryan, Russell & McConaghy 80/04/03 154pp
- --8004070481 Transcript of PA Public Util Commission 800318 hearing in Harrisburg.PA Pp 3.217-3,419 BHANAMAN.6 Pennsylvania. State of RUSSCLL.8 B , SELTZER.A M Ryan, Russell & McConaghy 80/04/03 204pp
- --8004090482 Annual Financial Rept 1979 * General Public Utilities GPU Bervice Corp * Jer Power & Light Co * Metropolitan Edison Co 80/04/03 Jersey Central 4/03 44pp
- --- 8004090483 "Proposal to Conduct Analysis of Strategic Options for JCP&L "
 * Arthur Young & Co 80/02/29 125pp
- --8004070484 "TMI-2 Coal Burning Plant Summary of Study of Converting TMI-2 to Fossil-Fueled Plant " # Gilbert/Commonwealth Cos 80/02/25 13pp

- 9004280630 Forwards Met Ed certified Annual Financial Rept 1979 & General Public Utils Corp certified Annual Financial Rept 1979? Certified 'Uniform Statistical Rept 1979."

 HERBEINJ G. Metropolifan Edison Co. 80/04/22. Ip
- --8004280633 Certified Annual Financial Rept 1979
 * Metropolitan Edison Co 80/03/0/ 27pp
- ---8004280638 Certified Annual Financial Rept 1979 Certified "Uniform Statistical Rept.1977' enc! * General Public Utilities GPU Service Corp 80/04/22 71pp
- O Advisory Committee on Reactor Saregueids reports & correspondence
- B004030260 Forwards certified minutes of 790905 ACRS meeting of Ad Hoc Subcommittee on TMT Accident Implications for attachment to 790927 minutes TAM.P ACRS Advisory Cummittee on Seactor Safeguards 79/11/13
- --8004030264 Summary of ACRS 790905 Ad Hoc Subcommittee on THI Accident Implications meeting

 ACRS Advisory Committee on Reactor Safeguards 79/11/07
- 8004100508 Forwards certified minutes of ACRS Ad Hoc Subcommittee meeting is TMI-2 accident implications MAJORA K. ACRS Advisory Committee on Reactor Safeguards 80/03/04 lp
- --8004100512 Certified summary of ACRS Ad Hot Subcommittee 791105 meeting in Washington, DC re implications of TMI-2 790328 accident for plant design, policy & criteria # ACRS Advisory Committee on Reactor Safeguards 80/01/08 22pp
- --- 8004100517 Discusses sensitivity studies of B&W reactor designs to transients 3 accidents DENTON: H R Office of Nuclear Roactor Regulation 79/10/25 2pp
- --8004100521 Discusses development of general framework for conduct of limited ris' assessment of B'W reactor aimed at identifying unique risk-impacting sequences re reactor safety study MURPHY, J A. TAYLOR, M A. Probabilistic Analysis Branch (Pre 791030) 79/10/04 12pp
- ~8004100930 Forwards response to question raised during ACRS Subcommittee 791003 meeting re THI-2 implications for potential pressurizer pressure boundary failure if pressurizer heaters become uncovered & overhoated MATISON.R J Division of Systems Safety 79/11/05 7pp
- 8004100375 Forwards certified minutes of ACRS Ad Hoc Subcommittee 791003 meeting re IMI-2 accident implications MAJDR.R ACRS Advisory Committee on Reactor Safeguards 80/01/04
- --80041003Bl Certified summary of ACRS Ad Hoc Subcommittee 791003 meeting in Washington,DC re TMI-2 accident implications for plant design # ACRS Advisory Committee on Reactor Safeguards 79/12/07 1900
- P Operating license stage documents & correspondence
- 8004040231 Advises that util presently reviewing proposed interim solid radwaste staging facility Will forward proposal by 800331 WILSON, R F Metropolitan Edison Co 80/03/03 1p
- 8004040318 Discusses proposal for removing balance of plant diesel generators as backup sources to circulating water & condensate pumps Schedule for removing diesel generators from svc is early Apr 1980 WILSON,R F Metropolitan Edison Co 80/03/04 App
- 8004040321 Responds to JT Collins 800130 comments re personnel air lock contamination control facility design description Radiation monitor installed in ante room & monitors particulate, iodine & noble gas activity WILSON, R F Metropolitan Edison Co 80/03/04 2pp
- 8004040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800204 reactor trip at Crystal River Sequence of events & planned corrective actions also encl DENTON, HR Office of Nuclear Reactor Regulation 80/03/06 26pp

- 1 Thirty of Disc. . Sign. . If it is an above memoral systeller between all till it in the control of the same shot filter in the inclusion, the due ating aloraties to be long to alorating party. The continue of the filter entry of the Bull Street.
 WILEST IN TITLE TO STREET
 WILEST IN TITLE TO STREET
 TO GO'07 Zpp
- * ind/pdriff) Req ests permis in an only three maduste packages of EPH in 1 I mush lines with a limiting of shipment ban Personnel in 1 but at respectaging to transport received trainly are resinately as the old-bin 77-17 WILLY ARE Marripoliting course to 20/03/07 app
- BOUNDOCHE ALL reverse or right of a gener is commission on THE Commands of mass or the ers for trest class work with DRIFT of Commands to CAMPAGE of the Property of CAMPAGE of the CAMPAG
- 6 CO (4)/70/15 mm /s. in term of the error is Commission on TM1 W/o enclass (RW) (4) W/W 6 Pennsyl enclassion of 6 80/02/26 6 1p
- ECO41065/V Forwards inquiry e alustron or licensee performance re PO0211 [Joseph Autor of ductors of a second leaf Addition of the second of
- SOU4080121 Forwards take TMI weekly status mept Liquid effluents from TMI-1 released to Susquetinns River, after processing were within limits specified in Tech Specs No Liquid effluents were discharged from TMI-2 COLLINS J.T. TMI-2 Operations/Support 80/03/11 4pp
- BDO 407006) Peromends authorization or controlled purging of reactor bldg 2 that licensee be directed to propose method for purging over shorter time period than currently proposed 60 days
 DENTON HR Office of huclest Reactor Regulation SECY-80-132 BO/03/11 5pp
- 8004020476 Forwards marked-up replacement pages to Draft 3a of action plan, reflecting change in Task I D 3 from Decision Group B to C. clarifying that education requirements portion of Task I A 2 is Group C 5, submitting classing Task I G 2 MATTSQN.R J Division of Systems Garety 80/03/12 37pp
- BOO4030102 Forward: "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D G Discission of Operating Reactors 80/03/12 Spp
- --8004030118 Nuclear Data Lint Specs "
 Division of Operating Reactors 60/02/21 28pp
- 8004030272 Forwards Amend In the License DPR-73 revising App B Tech Specs re operation of EFICOR-11 filtration & ion exchange decontamination sys to decontaminate intermediate level radioaste in douillary bldg VDLLMER R H - IMI-2 Operations/Support 80/03/12 App
- ---8004630279 Amend 10 to License DPR-73 revising App B Tech Specs re operation of EPICOR-11 filtration & ion eichange decontamination sys to decontaminate intermediate level raduaste in auxiliary bidg VOLLMER 8 H JMI-2 Operations/Support 80/03/12 10pp
- --8004030293 Notice of assuance & availability of Amend 10 to License DPR-73 VOLLHER R H TMI-2 Operations/Support 80/03/12 3pp
- 8004080128 Ack receipt of /71219 ltr to Lieutenant Governor Scranton, transmitting York County Board of Assistance resolution respected provisions in nuclear evacuation plans for indigent & handicapped hRC endories enri NUREO-0376 ll/o encl GRIMES BK Assistant Director for Engineering & Projects 802/03/12 lp
- 8004090176 F01A request to records re TMI-2, including OL application, CP application % amends
 ENGECHARDT.T W Peterson, Ross & Schloerb & Seidel 80/03/13 ip
- 8004100499 Submits EPA preliminary data rept on air & water sampling for 800305-12 Gamma rate recorder data entl SMITH.A E Environmental Protection Agency 80/03/13 29p
- 8004010344 Supports use of data from Channel AM-5 for quantification of radiogas releases Errors involved in averaging data from three monitors greater than from one AM-5 calibr is traceable to NSS krypton 2 zenon stds

 HILSON.RF Metropolitan Edison Go 80/03/21 3pp

- Euu4100496 Forwalds comment/resolution re ploposed Surveillance Procedure 4203-H22, secondary svc closed cooling water pump opprability test Requests that procedures be revised to provide more definitive acceptance criteria COLLINS, J.T. Effluent Treatment Systems Branch 80/03/21 5pp
- 8004109385 Responds to PF Wilson 800321 ltr re request to enter reactor bldg prior to purging Entily denied until util provides documentation showing confainment atmosphere will sustain life in event or malfunction or respiratory equipment COLLIFS. J T Division of Site Safety & Environmental Analysis 80/03/25 Dpp
- 8004100502 Denies 800321 request re permission to enter reactor bldg prior to purging Util must provide documentation to show that containment atmosphere will sustain life Addl data required re eistence of toric contaminants COLLINS.J T Effluent Treatment Systems Branch 80/03/25 Spp
- 8004160034 Forwards 800324 ltr rept from GL Pollack of MI State Univ re alternatives for handling krypton in containment as described in NRC environ assessment GILINSKY.V Commission 60703726 lp
- --8004/60037 Discusses alternative methods for removing Kr-85 from atmosphere or reactor bldg Best method is selective absorption process sys Second best method is cryogenic process sys POLLACK.G L. Michigan State Univ 80/03/24 6pp
- 8004170299 Forwards, per 800326 telcon. SECY-80-132 & environ assessment re-decontamination of reactor bldg atmosphere W/o ancis VOLLMER, R H TMI 2 Operations/Support 60/03/26 ip
- 8004210342 Forwards NUREG-0662. "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere." Addendum 1 & FR notice Public comment period expires 800411 VOLLMER.R II TMI-2 Operations/Support 80/03/26 4pp
- --8004210346 Notice of issuance / availibility of Addendum 1 to NUREG-0462. "Environ Assessment for Decontamination of TMI-2 Reactor Bidg Atmosphere " Comments due by 800411 VOLLMER.R H TMI-2 Operations/Support 80/03/25 2pp
- --8004210351 "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere," Addendum I * THI-2 Operations/Support * Difice of Nuclear Reactor Regulation NUREO-0662 ABD (BD/03/31 App
- B004040304 Notifies that 115 kV interfie has been classified as acceptable backup source for balance of plant equipment; electrical power supply Forwards request for classification of 230 kV power supply as backup source
 WILSON, R F Metropolitan Edison Co B0/03/28 43pp
- 8004250102 Responds to util 800304 request re removal of balance of plant diesel generators Accepts proposal & requests additions of the safety evaluation collings of NRC Three Mile Island Task Force 80/03/28 App
- 8004020068 "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere " * TMI-2 Operations/Support NUREG-0462 BD/03/31 72pp
- 8004040375 Comments on NUREG-0662 re environ assessment of reactor bldq decontamination purging containment bldg best available option Recommends detailed spec of meteorological limitations prior to final purge approval WAGNER, H N Maryland, State of 80/03/31 7pp
- 8004070301 Forwards results of reactor containment bldg air samples analysed for Sr-89 % 90 WILSON,R F Metropolitan Edison Co B0/03/31 2pp
- 800407031B Advises that capacity of approx 160,000 gallons of Unit 2 water will be maintained by one reactor coolant bleed holdup tank in each unit Tanks will remain empty, per NRC requirements
 WILSON.R F Metropolitan Edison Co 80/03/31 ip
- 8004090171 Responds to FOIA request for records re TMI-2 Forwards NUREO-0568, Revision 1, Suppl 1 & NUREO-0568, Revision 1 W/o encl FELTON, J M Division of Rules and Records 80/03/31 ip
- B004110471 Notifies NRC that as of B00326, approx 160,000 gallons of shielded storage capacity for TMI-2 water will be maintained by reactor coolant bleed holdup tank 1A of Unit 1 & IA of Unit 2 Util B00328 memo re TMI-1 bleed tanks encl WILBON,R F Metropolitan Edison Co 80/03/31 2pp

- 8004280244 Forwards consultant rept to venting Kr-85 from reactor bldg. requested by V Gilinsky W/o encl COLLING.J T RRC Three Mile Island Task Force 80/04/01 1p
- ---8004280250 Forwards rept on venting Kr-85 from reactor bldg (MI State Univ) GILINSKY,V Commission 80/03/24 ip
- 8004240472 Forwards G Pollack 800331 rept re sustability of selective absorption process sys for removing Kn-85 from atmosphere of TMI-2 reactor bldg Rept based on visit to ORNL selective absorption sys pilot plant GILINSKY, V Commission 80/04/03 ip
- --B004240479 Submits rept re suitability of selective absorption process sys for removing Kr-65 from atmosphere of TMI-2 reactor bldg Rept based on visit to ORML gaseous diffusion plant Absorption process would work well POLLACK.G L Michigan State Univ 80/03/31 App
- 8004160179 Forwards Revision 7 to "Mini Decay Heat Removal Sys Design Criteria Document" HGVEY.O K Metropolitan Edison Co 80/04/07 ip
- --B0041601B4 Revision 7 to "Mini Decay Heat Removel Bys Design Criteria "
 SHILLMAN. 9 R , DUNFERD, E F Metropolitan Edison Co B0/02/26
 1550
- 8004170023 Notifies that recommendations for long-term solid radwaste staging facilities will be delayed until 800531 HOVEY, G.K. Metropolitan Edison Co. 80/04/07 1p
- B00424049B Forwards status rept for wk of B00329-0404 Processed liquid effluents from TMI-1 released into Busquehanna River were within Tech Spec limits No liquid effluents were discharged from TMI-2 COLLINS; J T TMI-2 Operations/Bupport 80/04/07 App
- 8004250271 Forwards tables containing demographic & income data for 50 mile region around TMI Significant differences emerge in 30-40 & 40-50 mile rings
 KALTMAN.M Cost Benefit Analysis Branch 80/04/07 5pp
- 8004300273 Forwards TMI Program Ofc weekly status rept for B00327-0404 GGLLINB, J T TMI Program Office 80/04/07 5pp
- B004150436 Requests NRC further consideration & approval of TMI-2 reactor bldg entry on B00419 Present data suggests that oxygen deficiency exists in containment atmosphere No data gxists to preclude presence of toxic contaminants HDVEY.O K Metropolitan Edison Co B0/04/09 6pp
- 8004160270 Forwards technical evaluation rept, "Gubmerged Demineralizer Sys," describing ion exchange process for decontamination of water in containment sump & RCS Decontamination required for continued recovery operation HOVEY 0 K Metropolitan Edison Co 80/04/10 2pp
- --8004160298 Technical evaluation rept. "Submarged Demineralization Sys "
 * Metropolitan Edison Co 80/04/30 72pp
- BOO4170039 Informs of necessity to locate new time office manual brass sileys in erea now occupied by NRC Forwards drawing showing locations NRC could be moved Requests preference indication by BOO417, Drawing available in Central Files only HOVEY.Q K Metropolitan Edison Co 80/04/10 2pp
- 8004150446 Forwards mods to encl permits & certificates for environ protection in response to NRC 800125 request HERBEIN, J G Metropolitan Edison Co 80/04/11 122pp
- BOO417004B Confirms NRC 800415 meeting w/UCS at Middlatown,PA Anticipates receiving clarification of intent of several questions re relevancy to issue of venting containment ARNOLD,R C Metropolitan Edison Co GO/04/ii 1p
- B004170239 Forwards comments re environ assessment for decontamination of reactor bldg atmosphere MOLHOLT, B Public Interest Law Center of Philadelphia 80/04/14
- 8004300303 Forwards TMI Program Ofc weekly status rept for 800405-11 COLLINS.J T TMI Program Office 80/04/14 5pp
- B004210335 Forwards Susquehanna River data in response to NRC B00407 request
 SKINNER() F Pennsylvania Power & Light Co B0/04/19 ip

- --8004210340 "Demonstration for Brunner Island Steam Electric Station Units 1-3.Vols 1 2 " * EC ' G. Inc 77/05/19 200pp
- --8004210344 "Potential Erfects of Drunner Island Steam Electric Station on Future Migrations of American Shad in Susquehanna River ' * EG % inc 77/08/13 23pp
- --B004210347 "Probabilities of Normal & Woist Case Conditions in Susquehanna River during Critical Periods for Nuskellunge Spauning & Smallmouth Bass Egg Survival & Development " * EG & G. Inc 77/09/15 lopp
- --8004210349 "Assessment of Thermal Effects from Brunner Island Steam Electric Station Based on Newly Derived Max (Reekly Average Temps " * EG & G. Inc 79/05/31 33pp
- --B004210355 "Ecological Study of Effects of Brunnet Island Steam Electric Station Cooling Water Intakes" JOHNSON, T D , PHOENIX, D R Roy F Weston, Inc 77/11/18 78pp
- --8004210358 "Biological Survey of Susquehanna River in Vicinity of York Haven, PA 1978 Terminal Rept " WURTZ, C B Charles B Nurtz 79/06/29 33pp
- --8004210366 "Ichthyofaunal & Creel Census/Fishing Pressure Surveys in Vicinity of Brunner Island Steam Electric Station " DENGNCGURT.R F R F Denoπcourt 78/05/31 161pp
- 8004220677 Supports Sureau of Radiologica) Health review of NUREO-0662 Venting of Kr-85 in containment bldg to atmosphere under controlled release is prudent & proper course NRC should provide definitive controls
 VILLFORTH. J C HEW. Dept of, Food & Drug Administration 80/04/16
- 8004240399 Responds to NRC 600328 ltr re hydrogen control sys filter housing negative plessure rating Filter housing not designed to meet ANSI/ABME 509 requirements issued in Dec 1976 Imposition of requirements considered inappropriate HOVEY.O K Metropolitan Edison Co 80/04/16 2pp
- BOO42803/B Forwards App Subsection Q to comments on EIS for decontamination of TMI-2 reactor bidg atmosphere Bection had been omitted from oviginal MOLHOLT, B Public Interest Law Center of Philadelphia BO/04/16 App
- BO04250433 Forwards comments on NUREO-0662, "Environ Assessment for Decontamination of Reactor Bldg Atmosphere & Addenda " Small releases will occur during each airlock & reactor bldg entry Less restricted access to reactor bldg required HOVEY, C K Metropolitan Edison Co GO/04/18 4pp
- 8004250354 Responds to 800321 & 28 meetings re requirement to protect MDHB Filter housing currently being changed to stainless steel Fister will be located in shielded cask in present position on east side of pump HDVEY.0 K Metropolitan Edison Co 80/04/21 2pp
- 8004290289 Forwards comments on Addendum 2 to environ assessment for venting of facility containment atmosphere Concludes that reduction of venting time for removal of Kr-85 gas will result in higher overall psychological stress MOLHOLT, B Public Interest Law Center of Philadelphia 80/04/21

- To the state of th
- 4 The Measure's full Figure 177-19, "Packaging of Low Level Pathaste for Thansport for Surial Personnel training requirements until the unfleted by Mpr 1920 Requests that tit freeZuaste the released for Suppont HV. Mor Mer op liman Ecison Co. 80/03/31 7pp
- 411 Let Peanords to N., 930523 ltr requesting status of actions All [F Bullet] if items essentially complete Personnel training requirements near completion V approval of three radiusite shipperts Las gained AddI status info enc! wilson of Metropolitan Edison Co. 80,03/31 7pp
- D4157_ & Privaris If Into Notice 80-12 "Instrument Failure Causes Opening of POPV (Clock Palve No specific action or response necessary SHER BM Pegion 1 Philadelphia Office of the Director 80,03.31 1p
- C1204210015 Farlands Waste Packaging Insp Rept 80-06 on 800128-0201 No monc-pliance roted SMIFM 9 H Region 1 Philadelphia, Fuel Facility & Materials Safety Drainn 60/03/51 2pp
- Ei 42:0020 waste Pausaging Insp Rept 80-06 on 800128-0201 No normonpliance rotes Hajor areas inspected proper vehicle plaraeding, petologie merginty & package labeling & marking Sunk H & Region 5 San Francisco, Fuel Facility & Haterials Cafety Erach Coll C & Region 4, Dallas, Office of the Director 10:002:27 opp
- to 204070005 Forwards IE Circular 80-05, 'Emergency Diesel Generator Lobri ating Dil Addition & Onsite Supply " No unitten response required SRICA B H Region 1 Philadelphia. Office of the Director 20,04/21 ip
- EB 33411014/ Forwards IE Info Notice 80-13. "GE Type SBM Control Switches Defective Com Follower," No written response required GPIER B H Region 1 Philadelphia. Office of the Director B 30/04/02 1p
- © 204240315 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees No action required GMIER.B H Region | Philadelphia, Office of the Director 10
- 15/17 D4:80200 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Oil Gys' No written response required GRIER 8 H. Region I. Philadelphia. Office of the Director BD/04/03 ip
- 33-10-4233505 Forwards IE Builetin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required GRIER () H. Region 1 Philadelphia Office of the Director 1p

- 8004010444 Submits "EPA Preliminary Data Rept 800312.14.17 & 21," prepared by Environ Monitoring Sys Lab SMITH, A E Environmental Protection Agency 80/03/24 1p
- 8004170344 Forwards status rept for wk of 800315-21 COLLING.J T THI-2 Operations/Support 80/03/24 App
- 8004010470 Submits "NRC Air Sample Results for 800305.12 & 19," prepared by Environ Monitoring Sys Lab.CPA SMITH.A E Environmental Protection Agency 80/03/26 ip
- 8004070222 Submits preliminally air & water sampling data for 800319-26 SMITH.A E Environmental Protection Agency 80/03/27 ip
- 8004140420 Forwards weekly status rept for wk ending 800328 re offsite emergency radiological environ monitoring program Burface & drinking water samples had normal tritium & gross beta activities
 GERTI.S M Porter-Gert: Consultants, Inc. 80/03/20 22pp
- 8004070335 Forwards "Radiological Environ Monitoring Program Annual Rept.1979," "Hydraulic Survey" / "1979 Monitoring of Cooling Tower Operational Effects on Vejetation in Vicinity of Facility "

 HERBEIN, J G Metropolitan Edison Co 80/03/31 2pp
- --8004070339 "Radialogical Environ Monitoring Program Annual Rept for 1979 " * Metropolitan Edison Co 80/04/30 98pp
- --B004070343 "Hydraulic Survey," for Jul 1979 Thice oversize drawings encl
 Gilbert/Commonwealth Cos 79/07/31 20pp
- --8004070347 "1979 Monitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of Facility " PELLEK,R R , FRIDAY,G P , JOHNSON,R R NVS Corp 80/02/29 32pp
- 8004110342 Forwards results of reactor bidg air samples analysed for 800130-0213 for Sr-89 % Sr-90 in accordance w/util 800104 commitment WILSON.R F Metropolitan Edison Co 80/03/31 2pp
- BOO42BO230 Forwards TMI weekly status rept for BOO322-28 COLLING, S T NRC Three Mile Island Task Force BO/03/31 tp
- --8004280234 TMI waskly status rept for 800322 28, providing facility status, environ 5 effluent informajor activities, future evolutions & public affairs info
 * NRC Three Mile Island Task Force 80/03/31 3pp
- 8004140250 Forwards info describing permanent radiological environ monitoring program & program rept for 1979 Continuous air sampling equipment & environ radiation monitors will be used for Kr-85 monitoring W/o encls RESSLER.W C General Public Utilities GPU Service Corp 80/04/01 ip
- 8004250375 Forwards preliminary data from offsite emergency radiological environ monitoring program consisting of program summary & status for wk of 800328-0403 GERTZ,S M Porter-Gertz Consultants, Inc. 80/04/01 14pp
- 8004070332 Submits average daily readings of radiation levels as measured by gamma rate recorder installed at Ocidshoro fire hall for 800322-29 BAST, J Environmental Protection Agency 80/04/07 ip
- 8004180338 Forwards TMI-II-RR-6, "TMI-2 Recovery Quarterly Progress
 Rept for Period Ending 800331 " Describes recovery-related
 progress since accident for Jan-Mar 1980
 HOREY, O.K. Metropolitan Edison Co. 80/04/15 1p
- --8004180339 "TMI-2 Recovery Quarterly Progress Rept for Period Ending 800331 " Hetropolitan Edison Co TMI-II-RR-6 80/04/30
- 8004220415 Forwards air sample data collected in vicinity of TMI from 800319-0410 CORRERN, W D , SMITH, A E Environmental Protection Agency 80/04/16 6pp
- 8004230375 Preliminary data rept of air & water sampling CORKERN, W D Environmental Protection Agency 80/04/16 1p

- S Reportable occurrences. LFRs & related correspondence
- 8004070103 PNG-TMI-80-008A on 800310.licensee intends to commence preparations to enter containment personnel airlock 2 Airlock atmosphere radioactivity has been analyzed & will be purged Containment integrity will be maintained CONTE.R J. FASAND.A N. Region 1. Philadelphia. Office of the Director COLLINS.J T. Office of Inspection & Enforcement. Office of the Director 80/03/05 1p
- 8004020072 PND-TMI-80-014 seal rings for outer door to personnel airlock 2 failed leak test conducted following entry of personnel into airlock per PND-TMI-80-013 Seals replaced, door adjusted & seal retested successfully CONTE.R J. FASAND.A N Region 1. Philadelphia. Office of the Director COLLINS.J T Office of Inspection & Enforcement, Office of the Director BO/03/14 2pp
- 8004020012 RO 80-10/IP on 800314 following use of outer door for first entry into airlock leak test of seals failed to meet acceptable criteria Airlock declared inoperable Door seal replaced & w/addi shims successfully leak tested WILSON, R & Metropolitan Edison Co 80/03/17 1p
- 8004020074 PND-TMI-BO-015 on 800318 employee left site in ambulance experiencing pains near right kidney individual was not in controlled area at time of event CONTE, R J. FAGAND, A N Region 1. Philadelphia, Office of the Director COLLINS, J T Office of Inspection & Enforcement, Office of the Director 80/03/18 ip
- 8004020077 PNO-TMI-80-016 on 800320.licensee plans emergency drill implementing emergency plan Onsite staff will monitor drill w/assistance from Region i CONTE.R J. FASANO.A N Region 1. Philadelphia. Office of the Director COLLINS.JT Office of Inspection & Enforcement. Office of the Director 80/03/19 1p
- 8004020077 PNO-TMI-BO-017 on 800320, several local air particulate monitors in auxiliary bldg alarmed Makeup sys leak suspected for high reading Preparations underway to locate & isolate leak Press release planned by util HAVERKAMP, D.R., FAGAND, A.N. Region i. Philadelphia, Office of the Director COLLINS, J.T. Office of Inspection & Enforcement, Office of the Director BO/03/20 ip
- 8004040336 Forwards LERs 80-005/97X-0 & 80-011/99X-0 HERBEIN.J G Metropolitan Edison Co 80/03/27 1
- --8004040344 LER 80-005/97X-0 on 800321.Rosemount 1152 pressure transmitter in limited cases exhibited output between 4 & 20 ma w/input pressure over or under calibr range Caused by long-term degradation from submergence in water CHAPLIN:S D Metropolitan Edison Co 80/03/27 ip
- --B004040349 LER 80-011/99X-0 on B00321.Rosemount 1192 pressure transmitter in limited cases exhibited output between 4 & 20 ma w/input pressure over or under calibr range Caused by long-term degradation from submergence in water CHAPLIN.S D Metropolitan Edison Co 80/03/27 4pp
- 8004280632 PNS-I-80-004 on 800327, two bomb threats were received both stating that bomb was set for 800328 Search conducted No bombs found MADDEN, W. DCVLIN, J., MARTIN, W. Region i. Philadelphia, Office of the Director
- 8004140372 Forwards LER 80-009/03L-0 WIL80N,R F Metropolitan Edison Co B0/04/03 ip
- --8004140377 LER 80-007/03L-0 on 800305, during recovery mode operation, w/emergency diesel generator A down for maint, emergency diesel generator B was tested for operability Generator would start but could not be loaded Caused by open switch CHAPLIN. B D Metropolitan Edison Co 80/04/05 3pp
- 8004230377 Forwards LER 80-010/01L-0 HDVEY, G K Metropolitan Edison Co 80/04/12 1p
- --8004250389 LER 80-010/01L-0 on 800314, using outside personnel air lock entry door, door seals were tested Leakage exceeded rate criteria Personnel air lock entry declared inoperable Caused by use of personnel door after one yr of nonuse CHAPLIN.8 D Metropolitan Edison Co 80/04/11 2pp
- 8004290510 RO-80-14/1P on 800422, boric acid mix tank liquid found to contain higher boron concentration than Tech Spec limit On 800424 boric acid mix tank declared operable following demineralized water addition to bring concentration down HAVEY, O K Metropolitan Edison Co 80/04/24 2pp

- T. Hearing transcripts on non-antitrust matters
- B004300612 Transcript of 791025 telephone interview te participation in 5 knowledge or industry support effort in TMI-2 Fp 1-30 ACKERMAN N Technology for Fnergy Corp. 79/10/25 32pp
- 9004020076 Transcript of 800127 public meeting in Harrisburg.PA te EIS on decontamination > cleanup of radwaste * TMI-2 Operations/Support 80/01/29 67pp
- 8004040235 Forwards corrected transcript Page 552/553 for hearing in SMITH, J International Verbatim Reporters, Inc. 80/03/11 2pp
- 8004020140 Transcript of 800312 bilefing le enviroit assessment for decontamination of TMI-1 bldg atmosphere in Washington DC Pp 1-51 Commission 80/03/12 51pp
- 8004080001 Transcript of 800320 meeting in Baltimore.MD re scope or programmatic EIS on decontamination & disposal of radwastes resulting from accident # Commission 80703720 200pp
- 8004140472 Transcript of B00401 meeting of ACRS Subcommittee on TMI-2 Action Plans in Bethesda, MD Pp 1-285 * ACRS ~ Advisory Committee on Reactor Sateguards 80/04/01 290pp
- 8004140474 Transcript of 800402 meeting or ACRS Subcommittee on TMI-2 Action Plans in Retheada, MD Pp 1-197 * ACRS Advisory Committee on Reactor Spreguards B0/04/02 20000
- 8004150323 Transcript of ACRS Subcommittee on THI Accident Implications 800409 meeting in Washington, DC Pp 1-147 # ACRS -- Advisory Committee on Reactor Safeguards 80/04/09
- U Congressional/Executive Correspondence
- 80040802/5 Ack recurpt of 800303 ltr providing comments for programmatic EIS on decontamination 2 disposal of radwastes resulting from facility 790328 accident Comments will be considered in preparation of statement MULLER,D.R. Division of Gite Bafety & Environmental Analysis 80/03/19 1p
- --8004080280 Comments on programmatic EIS on decontamination & disposal of radwastes resulting from facility 790328 accident Supports statement No actions should be permitted at site until impact on Gusquehanna River is determined BAUMAN.R E House of Rep., Merchant Marine & Fisheries 80/03/03
- 800422065? Comments on NRC approach re contaminated waste disposal from TMI No wastes should be released into Susquehanna River until completion / review of EIS NRC must consult w/state officials re any activities taken prior to EIS review SARBANES, P Senate 80/03/20 2pp
- 8004140270 Discusses NRC Special Inquiry Group review of questions on util conduct re info transfer during 1979 accident No direct evidence found to indicate info withheld intentionally IC will complete investigation

 AHEARNE, J F Commission 80/03/21 3pp
- DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1 Q Adjudicatory correspondence
- BOO4290460 Forwards NRC confirmatory orders BTELLO,V Office of Inspection & Enforcement, Office of the Director BO/04/04 1p
- ---8004290466 Dider confirming util commitment to perform review requested by IE Bulletin 79-27 by 800626 Info required outlined in Attachment A STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/04 Spp
- --8004290477 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800626 lafo required contained in Attachment A
 STELLO, V Office of Inspection & Enforcement, Office of the
 Director 80/04/04 Spp

- tips stin, list at star, it is not a prespiratence
- 1 (40) it a command of the large land opens, study of digital command at the same of the state of the same of the
 - u04umpted Nu lear Date to its specs
 Nivision of Upicating Feattors U0402721 28pp
- **TORUGUEZ: Describes residuous primany coolant aus pressure isolation valves in response to NN 600223 ltm ne potential for LOCA forwards synthese of peretrations exhibiting Event 5 valve ionfiguration for each unit HICTER N.A. Jeongia Power 65 80/03/31 8pp
- ".34270055 Forwards Edul-7 % 0211 ltms to GE me proposed control rod drive spanids related to elimination or cracking in return line roirles Guidelines for nots will be discussed in NOREG 0213, to be issued in For Compent' form in Apr 1980 [FFOLITO T A Operator] Reactors Branch 3 80/04/07 2pp
- FOURISHINGS Commits into the control rod operability, in response to ARC EGGIG Iti Furing cept 1/70 to Dec 1979 no instances occurred or control rods railing to insert fully Only malfunctions were nitrogen cartridge valve leaks WIDTEP, W.m. Georgia Power Co. 80/04/08 1p
- P304250370 Forwards rept re substantial safety hazard in RHR svc water pump motors cooling water supply line Loss of RHR cooling water would result in elceding safety limit specified in Tech Typers Cooling sys will be separated into two divs MCCRARY D.L. Southern Co Services. Inc. 80/04/15 4pp
- Q Inspection reports. IF Bulletins 5 correspondence
- 8004090349 Forwards IE Billetin 80-03. "Loss of Charcoal From 5td Type II.Two-Inch Tray Adsorber Cells ' Action required O'REILLY.J.P. Region 2 Atlanta Office of the Director 80/02/06
- R004010112 Partially responds to IE Bulletin 79-01B, "Environ Gualification of Class IE Equipment" Class IE components listed including environ analysis inadequate qualification data test acrident temp profiles W/o encl HIDNER W A Georgia Power Co 80/02/08 2pp
- 9304220215 Forwards IE Repts 50-321/80-08 & 50-366/80-08 on SUCCEST Forwards It Kepts 30-32/30-08 % 50-366/80-08 on ED0221-22 No noncompliance noted ERYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004220221 IE Insp Repts 50-371/80 08 & 50-366/80-08 on B00221-22 No noncompliance noted Major areas inspected followup on items of noncompliance re 10CFR21 BROWNLEE, V L CONLON 7 E Region 2 Atlanta, Office of the Director 80/03/04 3pp
- COG4090032 Ack receipt of 800310 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-321/80-01 & 50-366/80-01 LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/18 ip

- -8004070035 Responds to IARC 806205 ltr re violations noted in IE Insp Repts 50-321/80-01 % 50-366/80-01 Corrective actions data sheet revised to relocate rire pump fuel level checks & assignment sheet revised to use MFP-2-9503 MIDNER.W A Georgia Power Co 80/03/10 ip
- --8004090035 Forwards IE Irsp Repts 50-321/80-01 & 50-366/80-01 on 800108-11 & notice of violation LEWIS.R C Region 2 Atlanta, Reactor Operations Nuclear Support Branch 60/02/05 dpp
- ---BDD4090041 Notice of violation from insp on B00108-11 * Region 2. Atlanta. Office of the Director B0/0

- --8004090049 lE Insp Repts 56-321/80-01 / 50-366/80-01 on B00108-11 Nancompliance noted failure to follow surveillance UPRIGHT,C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch hODN,B T Region 2, Atlanta, Office of the Director 80/02/05 6pp
- 8004110565 Submits response to IE Bulletin BO-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " All filters are in good condition.all scieens are stable & housing frames are solld No carbon lost through screens HIDNER.W A Georgia Power Co 80/03/21 3pp
- 8004150198 Responds to IE Bulletin 80-03 re charcoal adsorber colls finsp of all Util 1 ventilation sys indicate that all filters are in good condition Util 2 uses deep bed type carbon rilter beds rather than cells WIDNER, W.A. Georgia Power Co. 80/03/21 3pp
- 8004170298 Responds to IE Bulletin 79-2/, "Loss of Non-Class IC Instrumentation", Control Power Sys Bus During Operation "Review of emergency procedures, required by Item 2, is now scheduled for completion by 800626 WIDNER, R A Georgia Power Co 80/03/26 ip
- 8004150521 Forwards IE Info Notice 80-12. "Instrument Failule Causes Opening of PORV & Block Valve 'No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 60/03/31
- BOO4080624 Forwards IC Circular BO-05, "Emergency Diesel Generator Lubricating Oil Addition / Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/01
- 8004150065 Ack receipt of 800211 1tr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-321/79-37 & 50-366/79-41 LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/01 1p
- --8004150072 Responds to NRC 800)17 ltr re violation noted in IC Inap Rept 50-321779-37 / 50-366/79-41 Corrective actions existing radiation work practices / procedures reviewed & modified WIDNER, W A Georgia Power Co 80/02/11 2pp
- --8004150079 Forwards IE Insp Repts 50-321/79-37 & 50-366/79-41 on 791110-1207 A notice of violation LEWIS,R C NRC Regional Offices 80/01/17 2pp
- --8004150086 Notice of violation from insp on 771110-1207 * Region 2. Atlanta, Office of the Director 80/01/
- 8004150096 IE Insp Repts 50-321/79-37 & 50-366/79-41 on 791110-120/ Noncompliance noted radiation work permits were not approved & posted prior to work contrary to procedures & Tech Specs

 DANCE, H. C. NRC Regional Offices ROGERS, R. F. Region 2, Atlanta, Office of the Director 80/01/15 5pp
- B004190126 Act receipt of 800313 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 90-321/80-04 & 50-326/80-04 Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/01 Ip
- --8004150136 Responds to NRC 800214 ltr re violation noted in IE Insp Repts 50-321/80-04 % 366/80-04 Corrective actions shift foreman & operators involved were relieved of duties for special training HIDNER.W A Georgia Power Co 80/03/13 ip
- --8004150142 Forwards IE Insp Repts 50-321/80-04 & 50-346/80-04 on 791212-800104 & notice of violation
 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/14 2pp
- --8004150147 Notice of violation from insp on 791212-800104 * NRC Regional Offices 80/02/13 ip
- --8004150155 IE Insp Rept 50-321/80-04 & 50-366/80-04 on 791212-800104 Noncompliance noted HPCI sys not proven operable as required by Tech Specs DANCE.H C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch ROGERS.R F Region 2. Atlanta, Office of the Director 80/02/13 4pp

8004150093 Forwards IE Info Notice 80~13, 'GE Type SBM Control Switches Defective CAN Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/02

8004240265 Forwards IE Info Notice 80-14, "Safety Suggestions From

Employees "No action required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/02 2pp

8004180303 Forwards IC Circular 80.07. "Problems U/HPCI Turbine Oil Sys " No writton response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/03

8004110011 Forwards IE Bulletin 80-07, "IWR Jet Pump Assembly Failure " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04

80042301/3 Forwards IE Bulletin 79-03A "Longitudinal Held Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04

8004180436 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Wolds " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07

8004230467 Submits info in response to 800121 ltr re IE Bulletin 80-02 Documentation associated w/receipt & installation of sparger assemblies & muds is on file at plant site WIDNER. If A Georgia Power Co 80/04/16 4pp

8004280452 Updates 800346 response to IE Bulletin 79-018 "Environ Qualification of Class IE Equipment " Enough info re Dechtel equipment will be available by 800801 to provide meaningful response Info needed from 0E will be complete by 801226 WIDNER, W A Georgia Power Co 80/04/21 2pp

R Periodic operating reports & related correspondence

8004010321 Forwards "Annual Environ Burveillance Rept for CY79 " MANRY.M Georgia Power Co 80/03/28 1p

--8004010324 "Annual Environ Surveillance Rept for CY79 " * Georgia Power Co 80/03/28 300pp

BOO4150388 Forwards monthly operating rept for Mar 1980 MANRY, M Georgia Power Co 80/04/10 ip

--8004150390 Monthly operating rept for Mar 1980 RODEN, J W Georgia Power Co 80/04/10 Spp

8004150377 Forwards monthly operating rept for Mar 1980 MANRY,M Georgia Power Co 80/04/10 1p

---8004150404 Monthly operating rept for Mar 1980 RODEN.J W Georgia Power Co BQ/04/10 Spp

8 Reportable occurrences, LERs & related correspondence

B004010474 Farwards LER 80-025/03L-0 MANRY,M Georgia Power Ca 80/03/25 ip

~-8004010477 LER 80-025/03L-O on 800301.during normal operation.reactor core isolation cooling pump discharge flow switch found out of spec. Caused by instrument drift Barton Model 289A flow switch recalibr
NIX.R T Georgia Fower Co 80/03/25 2pp

8004020354 Forwards LER 80-020/03L-0 MANRY,M Georgia Power Co 80/03/27 1p

--8004020359 LER 80-020/03L-O on 800308, during normal operation, 180 gallons of radwaste was released to river w/o prior analysis per Tech Specs Caused by technician error Reanalysis shawed ETS not exceeded ROGERS, W H Georgia Power Co 80/03/27 2pp

8004040416 Forwards LER 80-027/03L-0 MANRY,M Georgia Power Co 80/04/01 1; --8004040426 [ER 80-027/6] -- on &Gu310, during review of surveillance schedule, discovered 15d block monitor functional test // calibr not performed within required interval Caused by personnel oversight surveillance acceptably performed NIX.R T Georgia Power Co 80/04/01 2pp

8004070281 Forwards LER 80-028/03L-0 HANRY, 11 Georgia Power Co 80/04/01 1p

--B004070263 LER B0-028//J3L-O un B00313 * 1/.during full power operation secondary containment integrity momentarily violated at 164 rt elevation leak-fol bldg airlock Caused by design deficiency Design change request has been written CDG0flk.C L Georgia Power Co. B0/04/01 2pp

8004220713 Forwards LER 80-029/03L-0 MANRY, M Georgia Power Co 80/04/15 tp

~-8004220721 LER 80-029/03L -O on 800322, during normal surveillance, generator IR43-5001C failed to start * reach rated speed within I2-s Caused by bent shutdown solehold operating rod in engine governor */ Failed governor booster servo NIX.R T Georgia Power Co 80/04/14 3pp

8004220675 Forwards LER 80-031/03L-0 MANRY, M Georgia Power Co 80/04/17 lp

--8004220484 LER 80-031/03L-C on 800330, while operating at 97 87 of rated MWT, main stack radiation monitor sample pump failed Cause attributed to moisture swelling cathon vanés in pump, locking pump Sampling procedure will be revised ROGERS, W H Georgia Power Co 80/04/17 2pp

8004220689 Forwards LER 80 030/03L-0 MANRY,M Georgia Power Co 80/04/17 ip

--8004220710 LER 80-030/03L-0 on 800330, w/mode switch in run position & reactor at 2,432 MWT, discovered analyzer B or primary containment hydrogen! oxygen analyzer inoperable Caused by personnel error Problem corrected Analyzer returned to svc NIX,R T Georgia Power Co 80/04/17 2pp

0004280570 Forwards LER 80-032/03L-0 MANRY,M Georgia Power Co 80/04/22 ip

~~#8004280566 LER 80~032/03L O on 800402, during normal operation, primary containment oxygen concentration exceeded Tech Spec limit Caused by air in leakage across seals of torus to drywell delta pumps Pump seals yreased & in-leakage stopped # Georgia Power Co 80/04/22 2pp

8004280982 Forwards LER 80-034/03L-0 MANRY,M Georgia Power Co 80/04/22 ip

--8004280587 LER 80-034/G3L-O on 800403, during stoady state power operation on Unit 1 % cold shutdown on Unit 2, fire water level on both water tanks was discovered below Tech Specs Caused by valve trip at north end of 18 cooling tower NI(R T Georgia Power Co 80/04/22 2pp

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

8004040031 Advises of Issuance of NUREC-0588, "Interim Btaff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROBS B F Division of Project Management 80/02/05 7pp

8004040017 Bubmits addl guidance to NURLO-0588, "Interim Staff Position on Environ Qualification of Sarety Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,DF Division of Project Management 80/02/21 3pp

8004020466 Notification of 800326 & 27 meeting w/representatives from Mark II comers group in San Jose CA to discuss Mark II Creace Test Program. 47 C/o tests & foreign tests ELTAWILA.F Containment Systems Branch 80/03/10 12pp

8004030122 Notification of 800326-27 meeting w/Mark II owners group, NRC consultants & GE in San Jose,CA to discuss Mark II Creare test program. AT C/O & foreign tests Topics are proprietary Agenda enc! ELTAWILA,F Containment Systems Branch 80/03/10 12pp

- G004040124 Summary or Fortial" meeting arMant 11 owners group he status or several long term program has a including Tasks A 17. A 16. Itask including to origination of foreign test data ELTANILA Figure Landing Research School 80/03/18 104pp
- BOO4046314 Forwards response to InfC 790614 into sequests re traffic patterns * access to restricted * unrestricted areas Employees enter plant trivinglion: * svi bldg Figures indicating traffir patterns * plant diagrams enc! MOVARRO J P Long 1-land Lighting Co BOV03/31 22pp
- BU04140439 Request- submitted an pehalt of Util Group for Regulatory applications, that NRC (17196 RETRAN computer code Code will be used for transient analysis 5 supporting activities required for plant mod or reload licensing VALENTE, J V Long Island Lighting Co 50/04/01 1p
- 2004220620 Forward, responses to NRC Requests 331 31 % 423 1 Plant radiation protection program complies \(\omega/\)Reg Guides \(\omega\) B 10 \(\omega/\)Certain \(\omega\)Ceptions Program does not include specific measurement systems 3 foot monitors are unnecessary NQVARRO. J P Long Island (lighting Co 80/04/11 6pp
- 3004300064 Surmary of ROU326-27 meetings u/Maik II owners group in San Jose CA te discussion of MPC concerns on data from Creare tests I roroign full-scale test programs I relationships w/ Mark II designs Containment Systems Branch 80/04/14 22pp
- RUO4300049 Notification of 1.00508-09 menting w/util in Long Island.NY to evaluate status of renst 5 estimated fuel load date HILSUN JR light Water Reactors Branch 4 80/04/15 6pp
- F Security, medical, emergency : rise protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by IRC 791226 ltm.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES.B K Emergency Properedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004010521 Opposes operation of plant due to inadequate evacuation plan SCHILLER:U Affiliation Unknown - 80,02/19 - 1p
- 8004040129 Demands site no pribe licensed No plans or evacuation possibilities exist not east end or Long Island & surveys show with does not need plant XLEIN-P if Artiliation Uninown 80/02/23 2pp
- 8004010520 Opposes granting of license to operate plant due to inadequate evacuation plan BRINMMAN,T J. Afriliation Unknown 80/03/15 1p
- 8004030026 Memorandum of upderstanding between NRC & FEMA re-prompt improvement in radiological unergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004230051 Advises that NRC position re-consideration of Class 9 accidents will be submitted to ACLB when evaluation is completed in 1 seponse to 800305 order Forwards Commission 800301 & ASLAB 800401 orders as Interim Info BORDENICK B M. Hearing Branch 4 80/04/08 2pp

- 2004070122 Protests nucleur power due to concern of waste disposal TUTHILL E Afriliation Unknown 80/02/29 1p
- u Inspection reports IF Bulletins & correspondence
- 8004100072 Forwards E In-p Rept 50-322/79-23 on /91210-800113 No-noncompliance noted BRUNNER E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch $\pm 60/02/11$ 2pp
- --8004100077 IE Insp Rept 50-922/79-23 on 791210-800113 No noncompliance noted Major areas inspected work activities & preoperational testing. Including tours of racility, test uitnessing. GA activities & environ monitoring KISTER, H B Region 1, Philadelphia, Reactor Dperations Nuclear Support Branch HIGSINS, J C Region 1, Philadelphia, Office of the Director 80/02/06 7pp
- 8001090004 Responds to IE Sulletin 79-28 re defects in certain NAMCO Model Eni80 series switches Afrected switches procured per IE Buletin 78-04 Returned for rework NOVARRO, J.P. Long Island Lighting Co. 80/02/19 1p
- 8004210146 Forwards IE Insp Rept 50-322/80-03 on 800128-0201 No noncompliance noted BRUNNER: E J Region 1: Philadelphia. Reactor Operations Nuclear Support Branch 80/02/25 2pp
- -8004210151 IE Insp Rept 50-322/80-03 on 800128-0201 No moncompliance DUALIDIA IE Insp. Nept 30-322/20-03 on BOUIZB-0201 No noncompliani noted Major areas inspected preoperational test program. including implementation, status, procedure review & verification & followup on previous items CAPHTON, D. L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch TROSKOSKI, H. M. NICHOLAS, H. H. Region 1, Philadelphia, Office of the Director BO/02/21 ilpp
- 8004070114 Ack receipt of 600221 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/79-16 BRUNNER.E & Region I, Philadelphia, Reactor Operations Nuclear Support Branch 60/03/04 2pp
- ~-8004070117 Responds to HRC 800121 ltr re violations noted in IE Insp Rept 50-322/79-16 Corrective actions replaced caps.covers & plugs Space heaters in Panels 1H21*PNL10 & 1H21*PNL26 re-energized 8 battery room cleaned WOFFORD A W Long Island Lighting Co 80/02/21 3PP
- --80040/0120 Forwards 1E Insp Rept 50-322//9-16 on 791001-1106 & notice of violation

 BRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch GO/01/21 2pp
- --8004070121 Notice of violation from insp on 791001-1106 * Region 1, Philadelphia, Office of the Director 7 79/12/11 200
- ~-8004070123 IE Insp Rept 50~322/79~16 on 791001-1106 Noncompliance noted failure to provide suitably controlled conditions for activities affecting quality KISTER.H B. Region I. Philadelphia, Reactor Operations Nuclear Support Branch HIGGINS.J C. Region I. Philadelphia, Office of the Director 79/12/11 8pp
- 80040904i4 Advises that IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemica) Vol Control Sys (CVCS) Holdup Tanks." was incorrectly sent for action No response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/17 1p
- 8004150274 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary ORIER, BH Region 1, Philadelphia, Office of the Director 80/03/31 ip
- E004090063 Forwards IE Circular 80-03. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/04/01 tp
- 8004110140 Forwards 1E Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER,B H Region 1. Philadelphia. Diffice of the Director 80/04/02 ip
- 8004240313 Forwards IF Info Notice 80-14. "Safety Suggestions From Employees "No action required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 1p

- B004180179 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 012 Sys " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/03 1p
- 8004110053 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 8004230491 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects (n ABME 8A-312, Type 304 Stainless Steel Pipe " Action required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 8004180161 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds " Written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/07 1p
- T Hearing transcripts on non-antitrust matters
- 8004100440 Comments on proposed rule IOCFR50 issue of emergency planning has been prime concern of county as intervenor in CP proceedings for facilities Regulations may not adequately protect public health b safety

 LIKE.! Suffolk County, NY 80/02/26 13pp
- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D F Division of Project Management 80/02/05 7pp
- 8004040017 Bubmits add1 guidance to NUREQ-0388. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROS8.D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of OL Wenci ROSS,DF Division of Project Management 80/03/10 53pp
- 8004010436 Forwards add1 info re refueling water storage tank capacity in response to 790720 request FBAR commitments & Tech Spec limit is 350,000 gallons Possibility for 2X error exists in indication of tank level CRANE
- 8004010437 Forwards Draft 2.Revision 2 of proposed ETB for facility, in response to NRC request TIDRICK.O A Pacific Gas & Electric Co 80/03/21 lp.
- --8004010441 Draft 2.Revision 2 of proposed ET8 for facility
 * Facific Gas & Electric Co 80/03/31 2100
- BO040B0466 Forwards nonproprietary version of response to NRC 790912 ltr re tube wear Application for withholding proprietary info & Westinghouse supporting ltrs encl CRANE.P A Pacific Oas & Electric Co 80/03/25 34pp
- 8004020283 Advises that work of R Lesley ro offshore faults does not impact conclusions contained in Suppl 4 of safety evaluation concerning possible connection between San Simeon & Hosgrifault zones

 DEVINE/JF Interior.Dept of, Geological Survey 80/03/31 ip
- 8004040281 Forwards response to short-term Lessons Learned Task Force requirements Five oversize drawings encl CRANE,P A Pacific Gas & Electric Co 80/03/31 35pp
- 8004140016 Notification of 800404 meeting w/utils in Bethesda, MD to discuss applicants' progress & status in design review replant shielding & environ qualification of equipment for spaces/sys used in post-accident operations BUCKLEY, B C Light Water Reactors Brench 1 DROMERICK, A W, LICITRA, E A Light Water Reactors Branch 3 80/03/31 7pp

- 8004240248 Responds to 771115 telegram to F Press, science advisor to President Kemeny Commission lept on TMI accident is being incorporated into NRC Action Plan Applicants will need to implement recommendations prior to OL issuance ROSS, DF Division of Project Management 80/04/01 Spp
- 8004240520 Discusses potential design deficiencies in bypass override herest circuits of engineered serety features Cites specific examples safety significance? criteria to be satisfied Protection sys design conformance response due by 800405
 STGLZ.J F Light Water Reactors Branch | 80/04/01 5pp
- 8004080443 Forwards press clippings purpoiting to state NRC position in Chumash Indians' access to facility Util is willing to meet & discuss issue Access question derived from possible application of Native American Religious Freedom Act PETERS,R J Pacific Qas & Electric Co 80/04/03 4pp
- 8004150435 Forwards diaft "Archaeological Resources Mgt Plan" Plan covers area north of plant in area designated SLO-2 PETERS.R J Pacific Gas & Electric Co 80/04/07 2pp
- --B004i5044i Draft "Archaeological Resources Mot Plan "
 # Pacific Gas & Electric Co 80/04/30 45pp
- 8004150337 Forwards comparison of NUREG-0611 recommendations for auxiliary feedwater sys to design //oi operation of facility sys CRANC.P A Pacific Gas & Flectric Co 80/04/08 8pp
- 8004160253 Responds to NRC request for addlinfo re secondary water chemistry control & forwards administrative operating & chemical analysis procedures Procedures include schematic diagrams indicating sampling point locations CRANE,P A Pacific Gas & Electric Co 80/04/08 2pp
- --8004160296 Operating Procedure F-5.Revision 1. "Chamical Control Limits" * Pacific Gas & Electric Co & 8D/02/01 42pp
- --8004160259 Chemical Analysis Procedure A-2,Revision 2, "Secondary (yilk Sampling Schedule" * Patric Gas & Electric Co 79/12/04 Bpp
- ---8004160260 Chemical Analysis Procedure E-6. "Secondary Sys Sampling "
 * Pacific Gas & Electric Co 80/01/08 5pp
- ---8004160264 Administrative Procedure C~12.Revision 2, "Resolution A Reporting of Plant Problems" + Pacific Gas & Electric Co 78/03/06 12pp
- --8004160267 Administrative Procedure C-201.Revision 1, "General Requirements for Chemical & Radiochemical Control Programs " * Pacific Gas & Electric Co 79/11/24 3pp
- --8004160271 Suppl to Administrative Procedure C-20, "Chemistry Data Review & Record Mgt " Descriptions of secondary water chemistry control program encl * Pacific Gas & Electric Co 75/11/24 12pp
- 8004170076 Forwards Revision 3 to response to NUREO-0978 re short term Lessons Learned Task Forco recommendations GRANE,P A Pacific Gas & Electric Co 80/04/09 29pp
- 8004190343 Forwards Revision 4 to facility response to short-term Lessons Learned Task Force requirements CRANE.P A Pacific Oas & Electric Co 80/04/11 21pp
- 8004220406 Responds to NRC 800228 ltr requesting addl info required to evaluate mgt & technical resources available at PG&E facilities Advises that 800321 telcon w/J Powers of Teknekron relayed requested info CRANE.P A Pacific Gas & Flectric Co 80/04/15 ip
- 8004220692 Reissues Revision 2 to response to NUREG-0578 Also forwards modified instructions for Revision 2 insertion into manual & eight administrative procedures previously sent to review group Oversite drowings encl GRANE.P A Pacific Gas & Electric Co 80/04/18 33pp
- --8004220697 "General Authorities & Responsibilities of Shift Foreman " * Pacific Gas & Electric Co 80/03/27 2pp
- --8004220704 "Plant Staff Organization & Responsibilities for Normal Operations," Revision 2

 # Pacific Gas & Electric Co BO/03/27 3pp

- --8001220716 Gencial Authorities / Responsibilities of Nuclear Plant Operators, 'Revision 2 * Pacific Gas / Electri Co 80/03/2/ 5pp
- 8004220727 Gualitication & Training of Shift Technical Advisor (Shift Engineer: "
 # Pacific Gas / Flectric to 80/03/2/ 2pp
- --B004220/37 Availability 1 Notification of Off-duty Personnel."
 Revision 2
 - Pacific was ! Electric Co 80/03/27 2pp
- --80042P0744 'Relieving Watch (Shift Turnover)," Revision 3 * Pacific Gas & Electric Co 80/03/27 2pp
- ~=8004220751 'Control Roum Acress ' * Pacific Gas & Electric Co 80/03/31 2pp
- ~~8004220755 "Overtime & Emergency Relief Restrictions "
 Pacific Gas > Electric to 80/03/31 2pp
- 8004280373 Forwards Revision 5 to response to NUREG-0578 Changes result from questions by NRC reviewers preparing SER CRANE,P A Pacific Gas 3 Electric Co 80/04/22 Bpp
- f Securaty, medical, emergency & rire protection plans
- 8004240384 Forwards draft tept. "Evacuation Times Assessment Study," in response to NRC 791226 request Rept will be reissued w/possible minor changes by 800523 LOCKE.R F Pacific 8s & Electric Co 80/04/11 ip
- -- 8004240389 "Evacuation Times Assessment Study " PRC Systems Services Co 80/04/30 102pp
- G Adjudicatory correspondence
- S004020133 Request by joint intervenors for Commission early intercession of reconstitution or ASLB re seismic issues. Urges disqualification of JH Buck due to prior involvement Requests oral argument on issue Certificate of Svc encl FLEISCHAKER, D Fleischaker, D S PHILLIPS, J R Center for Law in the Public Interest 80/03/13 23pp
- B00409003B Request by joint intervenois, to stay 800403 oral argument re seismic issues Adequate time should be given to Commission to evaluate joint intervenors request for early intercession or reconstitution of ASLAB FLEISCHAKER, D.S. Fleischaker, D.S. PHILLIPS, J.R. Center for Law in the Public Interest B0/03/13 App
- 8004080712 Notiries of appearance on behalf of applicant at oral argument re intervenors exceptions concerning earthquake issues, per ASLAN 800225 order Centificate of Svc encl NORTON, B Bruce Norton 80/03/14 3pp
- B004030015 Opposes operation of facility CA is not safe place to build power plants due to seismic activity
 SNAPP.C Affiliation Unknown 80/03/15 ip
- 8004090033 Advises of appearance on behalf of Odvenor of State of CA:at 800403 hearing Curtificate of Svc and BROWN.H H Hill Christopher 5 Phillips 80/03/17 4pp
- 8004220001 Forwards notice of appearance of author.PC Valentine & A Baldwin on behalf of San Luis Obispo Nothers for Peace Intervenor JP Taylor prof qualifications encl JONES.Y I Jones, Brown & Clifford 80/03/17 (3pp
- 8004020086 Response in opposition to joint intervenors 800313 request to stay oral argument in spismic issues Urges denial of joint intervenors 800313 request for Commission early intercession or ASLAB reconstitution WCertificate of 8vc KETCHEN,E G Hearing Branch 4 80/03/21 20pp
- 8004080691 Order re Joint Intervenors' 800313 motions Commission shall not intercede in seismic proceeding JH Buck should publish decision by 800403 Oral argument denied CHILK:S J Orfice of the Secretary of the Commission 80/03/21
- 3004020020 Forwards affidavit of nondisclosure & protective order drafts,per ASLAS 600225 first prehearing conference order Advises that parties were unable to agree on certain provisions Encloses list of NRC witnesses re security issue STAENBURG,M R Regulations Division 60/03/24 17pp

- ;300 1090132 Response by Juint Intervenors in opposition to Commissioner Hendrie decision to hear proceeding Exparte communication is sufficient for withdrawal.per case law.regardless of bias against or in rayor of party Decision should be retracted FLEISCHAMER.D Fletschaver. D 5 PHILLIPS, J R Center for Law in the Public Interest 60/03/20 lipp
- --8004G90137 Response by Joint Intervenois in opposition to Commissioner Kennedy decision to hear proceeding Er parte communication is sufficient for uithdrawal.per case law, regardless of bias against or in favor or party Certificate of Svc encificETISCHANER, D. Fleischaker, D. S. PHILLIPS, J.R. Center for Law in the Public Intelest 80/03/26 14pp
- 8304230107 Forwards USGS Circular 795 containing conclusions re adjudicated issues, per ASLAB directive to provide new info if relevant % natl FLEISCHAMER.D | Fleischaker, D S 80/03/26 Sipp
- 8004080556 Petition by Joint Intervenors for review of JH Buck decision to remain member or ASLAR re-seismic appeal Prior involvement in racility seismic concerns may jeopardize ability to maintain total impartiality W/Certificate of Svc FLEISCHAKER, D Fleischaker, D S PHILLIPS, JR Center for Law in the Public Interest 80/03/28 8pp
- 8004210322 Motion by Joint Intervenors to reopen record to seismic issues & environ qualification of safety-related equipment. New info invalidates ASLB evaluation of Hosgri seismic fault W/Certificate of Svc & supporting documentation FLEISCHAKER, D. F) elschaker, D. S. PHILLIPS, J. Center for Law is the Public Interest FLEISCHAKER, D. San Luis Obispo Mothers for Peace 80/03/28 18pp Center for Law in
- -8004210325 Affidavit indicating that facility design accelerations, velocities & displacements are not established as conservative values for N-7 5 design earthquake Supporting documentation encl BRUME, J N California, Univ of, San Diego 80/02/29 43pp
- --8004210327 Arfidavit advising of recent investigations indicating that Hosgri & San Simeon iones represent continuous & throughgoing fault sys Chart encl
 LEBLIE.R B Galifornia, Univ of, Santa Cruz 80/02/28 7pp
- --8004210373 Affidavit demonstrating that independent review of safety related equipment qualification program should be conducted prior to CL issuance HUBBARD,R D HHB Technical Associates 80/02/28 13pp
- --8004210375 "Preliminary Rept on Strong-Notion Records from Imperial County Svcs Bldg " KDJAHN,C , RAGSDALE, J D Afriliation Unknown 80/02/28 18pp
- 8004090454 Order denying Joint Intervenors 800328 patition for review of JH Buck 800324 memorandum stating intention not to disquality from participation JH Buck prior involvement at CP stage does not require disqualification CHILKIS J Office of the Secretary of the Commission 80/04/01
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICKL V Office of the Executive Director for Operations, 80/04/02 34pp
- 8004210100 Memorandum to counsels re Joint Intervenors 771024 motion requesting Commissioner Hendrie's disqualification Intervenors have presented no new info proving bias or appearance of bias Self-disqualification not required HEMDRIE. J Commission 80/04/09 2pp
- 8004230091 Advises that applicant response to Joint intervenors 800328 motion to reopen evidentiary hearings is due on 800424 & NRC response on 800305, per 800403 stipulation approved by KETCHEN, E G Hearing Branch 4 80/04/09 2pp
- 8004240541 Ack receipt of Anson 800325 ltr distributed to all parties for consideration BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/04/09
- --8004240545 Forwards wap indicating inner evacuation area Expresses concerns re escape routes during meltdown event ANSON.W B Affiliation Unknown 80/03/25 App

- 8004210168 Order granting extension until 800415, for Commission to act to review ALAB-583 CHILK,S J Office of the Socretary of the Commission 80/04/10
- 8004230098 Order reporting 800402 second prehearing conference re procedures & schedules for receiving security plan evidence Licensee physical security plan is entitled to confidential treatment per encl protective order & affidavit BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/04/11 22v p
- --8004230103 Protective order (e licensee security plan, restricting San Luis Obispo Mothers for Peace access to protected info per encl affidavit of nondisclosure to be executed by counsel & BALZMAN, RS Atomic Safety and Licensing Appeal Panel 80/04/03
- 8004220371 Response in opposition to PQLE 800414 application for stay of ASLAB 800411 order re disclosure of sanitized version of security plan Applicant failed to show that util will be irreparably harmed from disclosure W/Certificate of Svc DAVIS.L D Hearing Branch 4 80/04/18 12pp

H General correspondence

- 7906290854 Responds to 790411 ltr on reactor safety, clarifying concerns re Davis-Besse shutdown & geologic faults near Diable Canyon CISENHUT.D O Division of Operating Reactors 79/05/22 2pp
- 8004040346 Forwards articles from Los Angeles Times re analysis of util financial problems aggravated by commitment to large coal & nuclear power plants
- Environmental Defense Fund 80/02/27 7pp
- 8004030010 Requests permanent denial of OL ANSHUTZ, T L Affiliation Unknown 80/03/08 1p
- 8004030008 Urges licensing of power plants ready or near ready for operation Reliable power reserves at stake in CA TERRELL,O D Affiliation Unknown 80/03/10 1p
- 8004030180 Urges release of hold on licensing plant for operation Area may suffer brownouts & blackouts if plant not licensed within one or two months MDRRIS.E W Affiliation Unknown 80/03/10 ip
- 8004020250 Responds to 800207 mailgram to President Carter re validity of rumor concerning 800531 issuance of OL to facility NRC has no knowledge of rumor & no such decision has been made NRC is preparing action plan to complete licensing reviews DENTON. If R Office of Nuclear Reactor Regulation 80/03/17 2pp
- 8004110303 Opposes nuclear power plants due to extreme danger to population resulting from meltdown Winds in area of facility would quickly spread radiation over 35-mile radius NRC should expand evacuation area accordingly ANSON, W. B. Affiliation Unknown 80/03/25 5pp

I Financial information

- 8004100233 Forwards Annual Financial Rept 1979 CRANC, P A Pacific Cas & Electric Co 80/04/03 ip
- --8004100244 Annual Financial Rept 1979
 * Pacific Gas & Electric Co 80/02/22 43pp
- G Inspection reports, IE Bulletins & correspondence
- B004280016 Forwards IE Insp Repts 50-275/80-02 & 50-323/80-01 on B00211-14 & 20 No noncompliance noted SPENCER, O S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004280022 IE Insp Repts 50-275/80-02 & 50-323/80-01 on 800211-14 & 20 No noncompliance noted Major areas inspected const & mod activities including licensee actions on previous findings, deficiency repts item. IE bulletins & circulars HAYNEB,R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch MORRILL.P J , KIRECH,D F Region 5, San Francisco, Office of the Director 80/03/04 7pp

- 8004150205 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening or PORV > 8 lock Valve " No specific action or response necessary ENGELKENR H Region 5, San Francisco, Office of the Director 80/03/31 ip
- 6004100101 Forwards 1E Circulai 80-05, "Emergency Diesel Generator Lubricating Oil Addition / Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/01 1p
- 8004110111 Forwards 1E Into Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required ENGELMEN.R H Region 5, San Francisco, Office of the Director 80/04/02
- 800422003B Folwards 16 Info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/02 ip
- 8004180148 Forwards IE Circular 80-07, 'Problems W/HPC1 Turbine Oil Sys " No written response required ENGCLKEN,R H Region 5, San Fiancisco. Office of the Director 80/04/03 ip
- 8004230379 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ARME SA-312, Type 304 Stainless Steel Pipe "Action required EMGELKEN R H Region S. San Francisco, Office of the Director 80/04/04 1p
- 8004220176 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required ENOELKEN,R H Region 3, San Francisco, Office of the Director 80/04/07 ip
- 8 Reportable occurrences. LERs & related correspondence
- 8004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made or inferior math Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT.K N Region 2. Atlanta. Office of the Director 77/08/12
- T Hearing transcripts on non-antitrust matters
- 8004140451 Transcript of 800403 hearing in San Luis Obispo CA re earthquakes Pp 1-179 * Atomic Safety and Licensing Board Panel B0/04/03 180pp
- U Congressional/Executive Correspondence
- 8004030013 Requests comments on encl HH HcDill ltr re failure by NRC & other govt agencies to properly handle responsibilities LAGOMARSINO,R J House of Rep 80/03/05 4pp

H General correspondence

- 8004300445 Discusses utilizing on interim basis, qualified plant personnel as shift technical advisors while regular shift technical advisors are undergoing training Program to be fully implemented by 810101 UTLEY. E.E. Carolina Power & Light Co. 80/04/25 1p
- l Financial information
- 8004010405 Forwards Annual Financial Report 1979 Also forwards info re cash flow projection to guarantee retrospective premium liability to nuclear hiability insurance carriers GRAHAM.W E Carolina Power シ Light Co 80/03/27 4pp
- ---8004010409 Annual Financial Rept 1979
 * Carolina Power & Light Co 80/03/01 36pp
- P Operating license stage documents & correspondence
- B004070184 Forwards agenda for 800325 & 26 meeting on emergency preparedness for facility site NRC/FEMA review team will discuss emergency preparedness status re details of problems identified in sessions wistate & local representatives GRIMES.8 K Emergency Preparedness Task Force 80/03/04 3pp
- --8004070188 Hemo of understanding between NRC & FEMA to accomplish prompt improvement in tadiological emergency planning & preparedness
 GOSSICK. L. V. Ottice of the Executive Director for Operations
 CAMM.F. Emergency Preparedness Task Force 80/03/04 10pp
- 8004070404 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MH-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITG.T A Operating Reactors Branch 3 80/03/10 3pp
- 6004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethasda Operations Ctr EIBENHUT.D G Division of Operating Reactors 80/03/12 Spp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004090294 Notification of 800321 meeting w/util in Bethesda.MD to discuss radiological ETS proposed changes, methodology for calculating dose release & process control program for solidification of waste HARNON.J N Operating Reactors Branch 3 80/03/19 ip
- 8004150053 Summary of 800321 meeting w/util in Bethesda.HD re radiological ETE changes:release dose calculations & waste solidification program control HANNON,J N Operating Reactors Branch 3 80/03/28 3pp
- B0040B03B3 Responds to NRC B00201 request for addl info on containment purging Reactor bldg vent radiation monitoring sys contains dual-independent monitors & trip sys which meet design requirements of IEEE Std 279-1971
 UTLEY, E.E. Carolina Power & Light Co. B0/04/01 42pp
- 8004160282 Responds to 800110 request for addl info re failure of control rods to fully insert Encl table provides list of failures during most recent ruel cycles Records not available for science Sefore Jan 1979

 UTLEY, E.E. Carolina Power & Light Co. 60/04/11 2pp
- 8004170015 Requests Tech Specs to begin Cycle 4 operation Forwards proposed Tech Specs & NEDO-24235, "Supplemental Reload Licensing Submittal for Reload 3," Revision (UTLEY, E.E. Carolina Fower & Light Co. 80/04/11 2pp
- --8004170019 Proposed sexisions to Tech Specs, Sections 1 & 3/4, reflecting changes necessary to begin Cycle 4 operation * Carolina Power & Light Co 80/04/!1 17pp
- --B004170020 "Bupplemental Reload Licensing Submittal for Reload 3,"
 Revision 1
 RASH, J L General Electric Co NEDO-24235 R1 80/03/31 35pp
- 8004250410 Submits info to fire bairier penetration seals & supervision of valve control circuits in response to 800214 ltr Valve control circuit mod completed & tested for Unit 2 Unit 1 will be completed by 800415 Forwards Tech Spec changes UTLEY,E E Carolina Power & Light Co 80/04/22 2pp

- --8004250412 Tech Specs 3 7 8 % 4 7 8 for fire barrier penetration seals * Carolina Power & Light Co 80/04/22 10pp
- BO04280497 Submits summary of min critical power ratio limits error corrected by Amend 49 to License DPR-62 ½ util corrective actions Verification guide for nuclear dynamics parameters data book has been changed UTLEY, E E Carolina Power ½ Light Co 80/04/23 2pp
- 8004300323 Submits proposal on allocation of radioactive effluents between racilities in response to 800321 request Liquid by gaseous releases will be allocated between facilities on squal basis
 UTLEY.E E Carolina Power & Light Co. 80/04/23 20a
- O Inspection reports. IE Bulletins & carrespondence
- 6004040461 Responds to IE Bulletin 79-01B, "Environ Gualification of Class IE Equipment" Delay in 45-day response caused by OE data discrepancies as noted in 800303 belcon w/NRC Addl data to be provided in 90-day response
 FURR, B J Carolina Power & Light Co 80/03/13 ip
- B004280050 Forwards IE lnsp Repts 50-324/80-06 & 50-325/80-06 on B00124 No noncompliance noted LEMIB.R C Region 2, Atlanta Reactor Operations Nuclear Support Branch B0/03/18 2pp
- --8004280057 IE Insp Repts 50-324/80-06 t 50-325/80-06 on 800124 No noncompliance noted Major areas inspected assessment of effect on plant safety re implementation of near-term items presented in NUREO-0660 KFLL0GO.P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch LEWIS.R C Region 2. Atlanta, Office of the Director MADSEN.G Region 4. Dallas, Office of the Director 80/03/17 3ee
- B004230076 Submits response to IE Bulletin B0-03 Five spare cells were pulled from stock & visually inspected w/n opening plastic shipping & storage bag No charcoal was noted in plastic bag Periodic visual insps & insp of cells are sufficient FURR, B J Carolina Power & Light Co 80/03/21 2pp
- 8004190497 Forwards IC Info Notice 80-12, "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/31
- 8004080578 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Gnette Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 20s
- B004190067 Forwards 1E info Notice 80-13, "OE Type 8BM Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- BOO4240245 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees "No action required Q'REILLY, J P Region 2, Atlanta, Office of the Director BO/04/02 2pp
- BOO4180378 Forwards IC Circular BD-07. "Problems W/HPCI Turbine Oil Bys " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/03
- BOO4110D10 Forwards & Bulletin 60-07. "BWR Jet Pump Assembly Failure "
 Writton response required

 Or REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004230117 Forwards 1F Bulletin 79-03A "Longitudinal Held Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180340 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/07

- 8004290116 Ack receipt of 800226 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/80-03 A SO-329/80-03
 STOHR, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety
- --8004290122 Responds to NRC 800212 ltr re violations noted in IE Insp Repts 50-324/80-03 % 50-325/80-03 Corrective actions hoses properly disposed of £ surveys conducted to assure correct radioactive math labeling TOLLISON, A C Carolina Power & Light Co 80/02/26 3pp
- --8004290128 Forwards 1E Insp Repts 50-324/80-03 & 50-325/80-03 on 800123-25 & notice of violation STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/12 2pp
- --8004290135 Natice of violation from insp on 800123-25

 * Region 2. Atlanta, Office of the Director 80/02 80/02/11 1p
- --8004290141 1E Insp Repts 50-324/80-03 & 50-325/80-03 on 800123-25
 Noncompliance noted failure to label containers of
 radicactive mat) & to evaluate & identify radiation hazards
 associated w/contaminated fire hose
 GIBSON.A F. JACKSON,L L. Region 2, Atlanta, Fuel Facility &
 Materials Safety Branch 80/02/11 5pp
- 8004210293 Responds to IF lnsp Repts 50-324/80-08 & 50-329/80-08 Repts contain no proprietary info Security Instruction SI-18 has been revised to require roll call printout within five minutes of vital area evacuation TOLLISON.A C Carolina Power & Light Co 80/04/14 2pp
- R Periodic operating reports & related correspondence
- 8004010461 Forwards "Environ Surveillance Rept, Jan-Dec 1979" TOLLISON A C Carolina Power & Light Co 80/03/28
- --8004010468 "Environ Surveillance Rept.Jan-Dec 1979 " EDWARDS.D H Carolina Power & Light Co 80/03/24
- 8004140445 Forwards monthly operating repts for Mar 1780 TOLLISON A C Carolina Power & Light Co 80/04/04
- --8004140447 Monthly operating repts for Mar 1980 WILLIS,E Carolina Fower & Light Co 80/04/03 12pp
- S Reportable occurrences, LERs & related correspondence
- 8004090111 PND-11-B0-043 on 8000315, subcontractor labor force started picketing site On 800315 & 16 majority of const forces did not report to work On 800318.97 of 600 individuals failed to report to work Estimated outage may be extended three days HARDIN.A K. KELLOGG.P J. Region 2. Atlanta. Office of the Director 80/03/18 | Ip
- 8004020297 RO-2-80·23 on 800319, during liquid penetrant test of reducing insert for 2D reactor recirculation pump committed to in LER 2-79-109, linear indication found at toe of weld between reducer & nipple Weld filed b
- 8004030176 RO 2-80-23 on 800319. during liquid penetrant test of reducing insert for reactor recirculation pump 2B. linear indication was found at too of weld between reducer k nipple Other welds satisfactorily liquid penetrant tested TOLLISON.A C Carolina Power & Light Co 80/03/19 lp
- 8004010394 Forwards LER 80-038/03L-0 TOLLISON,A C Carolina Power & Light Co 80/03/27 1p
- -8004010400 LER 80-038/03L-0 on 800229, while terminating wire to contact 3 on relay 52AX, recirculation pump M/O set tripped Caused by de-energizing of relay when connection was made for safety 8pocial procedure was revised & test successfully completed TOLLISON, A C Carolina Power & Light Co 80/03/27 2pp
- 8004080458 Forwards LER 80-023/01T~0 TOLLISON, A C Carolina Power & Light Co 80/03/28 ip
- --8004080464 LER 80-023/01T-0 on 800319, during liquid penetrant test of reducing insert for 20 reactor recirculation pump, linear indication was found at toe of weld between reducer & nipple Cause unknown Analysis planned TOLLISON; A C Carolina Power & Light Co 80/09/28 ip

- 8004080357 Notifies that triaxial time-history accelograph sys alarmed 20408U397 Notifies that triaxial time-history accelograph sy & recorded on 800208 Seismic monitoring at Shearon Harris Plant & Univ of SC indicated no seismic activity Recorders initiated by Nonseismic shock ! vibration TOLLISOII.A C Carolina Power ! Light Co 80/04/01 2pp
- 8004090332 RD on 800215, discovered approx 50% of fire detectors in Zone 14 of reactor bldg were inoperable Caused by reversal of polarity in electrical leads, probably occurring during recently completed plant mod Repairs planned TOLLISON.A C Carolina Power & Light Co 80/04/02 1p
- B004070333 Forwards LER 80-034/03L-0 TOLLISON, A C Carolina Power ? Lic Light Co 80/04/04 1p
- --8004070337 LER 80-034/03L-0 on 800307.while performing visual insp of accessible snubbers, snubbers 2041-18522,25W-17585166 & 2E-11-285105 found inoperable Caused by pipe clamp slippage, missing locking pin % leaking shaft seal, respectively TOLL180N,A C Carolina Power & Light Co 80/04/04 2PP
- 8004150466 RO on 800404.1/4-inch through-wall horizontal crack was located in heat-affected zone 1/4 inch below weld joining 3/4-inch test connection to half coupling on 6-inch reactor water cleanup header Repair being evaluated by engineering TOLLISON.A C Carolina Power 3 Light Co 80/04/04 1p
- 8004150504 RO on 800231.during investigation re lack of pressure during local leak rate text on reactor water cleanup isolation valves, found through-wall horizontal crack on heat-affected zone Repair under evaluation
 TOLLISON, A C Carolina Power & Light Co 80/04/04 ip
- 8004150444 Forwards LER 80-024/03L-0 TOLLISON,A C Carolina Power 3 Light Co 80/04/08 ip
- --8004±5044B LER 80-024/03L-0 on 800311, while decontaminating torus in preparation for mods, coating found blistered under normal water line Caused by demineralized water entrapped between steel liner & coating Samples to be tested in DBA environ TOLLISON A C Carolina Power & Light Co 80/04/08 ip
- 8004220572 Forwards LER 80-025/03L-0 TOLLISON, A C Carotina Power & Light Co 80/04/15 tp
- --B004220583 LER 80-025/03L-O on B00318, while performing refueling interlack check, one rod was withdrawn one notch to check refueling bridge interlacks w/shorting links installed Links should have been removed first TOLLISON.A C Carolina Power & Light Co 80/04/15 2PP
- 8004220732 Forwards LER 80-031/01T-0 TOLLIGON,A C Carolina Power & Light Co 80/04/15 ip
- ---8004220740 LER 80-031/01T-0 on 800404.while investigating why pressure could not be maintained during local leak rate test on RMCU isolation valves FOO: & FOOH-horizontal O 23-inch crack was found in heat-affected zone Cause being examined * Carelina Power & Light Co 80/04/15 1p
- 8004280587 Forwards LER 80-029/03L-0 TOLLISON.A C Carolina Power & Light Co 80/04/21 ip
- --8004280397 LER 60-029/03L on 600323, following reactor scram HPCI discharge valve E41-F006 would not remain open following low level initiation signal Caused by HPCI turbine stop valve E41-V8 opening too quictly Spring loaded bypass adjusted TOLLISDN.A C Carolina Power & Light Co 80/04/21 2pp
- 8004280583 Forwards LER 80-027/03L-0 Carolina Power & Light Co 80/04/22 ip
- ---B004280392 LER 80-027/03L-0 on 800325, while performing periodic test 1 7 IPC, leak detection level switch for HCU 24-47 did not actuate Caused by contacts on switch not meeting Switch replaced TOLLISON.A C Carolina Power & Light Co 80/04/22 1p
- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 8004070176 Summary of 800305 & O.6 meeting w/util at facility re adequacy of fire protection provided for redundant safe shutdown cabling separated by greater than five ft horizontal distance. HANNON, J Operating Reactors Branch 3 80/03/06 3pp

- 504033-75 (lating arounds 30500 74 -eeting world PAL & FEMA in Bolivia (to renew enjoying alan against NUREG-0654 / FEMA-RCP-1 HAV's, J.N. Cograting Realists Branch 3 60/03/11 2pp
- ToutAD2uxv2 Disvusses findings or 2002/05-06 meeting w/NAC be fibe protection issue. Forward orrective actions to be implemented by 801001 or two cases or inadequate cable separation
 WilEvill Carolina Power ' tight Co 80/04/01 4pp
- H General correspondence
- 6004330445 Discusses utilizing on interim basis qualified plant personnel as shift technical advisors unite regular shift technical advisors are undergoing training Program to be fully implemented by BICIOI UTLEY.E E Carolina Power & Light Co 80/04/25 ip
- I Financial inforcation
- 8004010405 Forwards Annual Financial Report 1979 Also forwards info re cash flow projection to guarantee tetrospective prenium liability to nuclear liability insurance carriers GRAHAM.W E Carolina Power ? Light Co 80/03/27 4pp
- --8004010407 Annual Financial Rept 1979 * Carolina Power & Light Co 80/03/01 35pp
- P Operating license stage socuments? correspondence
- 8004070184 Forwards agenda for 800325 t 26 meeting on emergency preparedness for facility site NPC/FEMA review team will discuss emergency preparedness status re details of problems in sessions white & local representatives

 Energency Preparedness Task Force 80/03/04 3pp GRIMES B K
- --B004070188 Meno of understanding between NRC & FEMA to accomplish prompt improvement in radiological emergency planning & preparedness GUSSICM. L. V. Office of the Executive Director for Operations CAMM.F. Emergency Pieparedness Task Force B0/03/04 10pp
- 8004070404 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MW-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors
 IPPOLITO T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "huclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISE/AGUT D G Division of Operating Reactors 80/03/12 Spp
- --8004030118 "Nuclear Data Lin' Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004090294 Notification of 800321 meeting u/util in Bethesda, MD to discuss radiological ETS proposed changes, methodology for calculating dose release & process control program for solidification of waste MARNON, J.N. Operating Reactors Branch 3 80/03/19 1p
- 8004150053 Summary of 800321 meeting w/util in Bethesda. MD re radiological ETS changes release dose calculations & waste solidification program control MANNON. J N Operating Reactors Branch 3 80/03/28 Opp
- S0040B03B3 Responds to NRC B00201 request for add1 info un containment purging Reactor bldg vent radiation monitoring sys contains dual, independent monitors & trip sys which meet design requirements of IEEE Bdd 279-1971 UTLEY-EE Carolina Power & Light Co 80/04/01 42pp
- B004160282 Responds to 800110 request for addl into re failure of control rods to fully insert Encl table provides list of failures during most recent fuel cycles Records not available for scrams before Jan 1979
 UTLEY.E E Carolina Power & Light Co 80/04/11 2pp
- BO04250410 Submits info is fire barrier penetration seals & supervision of valve control circuits in response to BO0214 ltr Valve control circuit mod completed i tested for Unit 2 Unit 1 will be completed by BO0615 Forwards Tech Spec changes UTLEY.E E Carolina Power & Light Co BO/04/22 2pp
- --8004250412 Tech Specs 3 7 8 % 4 7 8 for fire barrier penetration seals
 4 Carolina Power & Light Co 80/04/22 10pp

- 8004300323 Submits proposal on allocation of radioactive effluents between racilities in response to 800321 request Liquid > gaseous releases will be allocated between facilities on equal basis UTLEY, E E Carolina Power & Light Co 80/04/23 2pp
- @ Inspection reports, IF Bulletins & correspondence
- 8004040461 Responds to 16 Builetin 79-01B, "Environ Qualification of Class IE Equipment' Delay in 45-day response caused by OE data discrepancies as noted in 800303 telcon w/NRC Addl data to be provided in 90-day response
 FURR.B J Carolina Pouct & Light Co 80/03/13 ip
- 8004280150 Forwards IE Insp Rept 50-325//9-42 on 79(127-29 No noncompliance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/13 2pp
- --8004280157 IF Insp Rept 50-325/79-42 on 791127-29 No noncompliance noted Major areas inspected 791120 Unit I reactor trip KELLOGG.P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch RILEY,B W. OUZTS,J E Region 2. Atlanta, Office of the Director 80/03/13 4pp
- 8004280050 Forwards IE Insp Repts 50-324/80-06 \$ 50-325/80-06 on 800124 No noncompliance noted LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/18 2pp
- --8004280057 IE Insp Repts 50-324/80-06 / 50-325/80-06 on 800124 No noncompliance noted Major areas inspected assessment of effect on plant safety to implementation of near-term items presented in NUREG-0660 KELLOGG.P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch LEMIS.R C Region 2. Atlanta. Office of the Director MADSEN.G Region 4. Dallas. Office of the Director BO/03/17 Jpp
- 8004230076 Submits response to IE Builetin 60-03 Five spare cells wore pulled from stock & visually inspected w/o opening plastic shipping & storage bog No charcoal was noted in plastic bag Periodic visual insp & insp of cells are sufficient FURR.B J Carolina Power & Light Co 80/03/21 2pp
- 8004150497 Forwards IF Info Notice 80-12, "Instrument Failure Causes Dpening of PORV & Block Valve " No specific action or response necessary
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 O'REILLY, J P
- 800408059B Forwards IE Circulai 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director BO/04. Region 2. Atlanta, Office of the Director 80/04/01
- 8004150067 Forwards JE Info Notice 80-13, "OE Type 88M Control Switches Defective CAM Followers " No specific action or response D'REJELY, J. P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240245 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees" No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004180378 Forwards IE Circular 80-07, "Problems W/MPC! Turbine Dil No written response required

 LLY, J P Region 2, Atlanta, Office of the Director B0/04/03 Bys " No wr! D'REILLY, J P
- 8004110010 Forwards IE Builetin 80-07. "BWR Jet Pump Assembly Failure " Written response required B'REILLY, J P Region 2, Atlanta, Defice of the Director 80/04/04
- 9004230117 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME 6A-312, Type 304 Stainless Steel Pips " Action required O'REILLY, J. P. Region 2: Atlanta, Office of the Director 80/04/0/ BO/04/04
- 8004180340 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07

- 8004270116 Ack receipt of 600226 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/80-03 & 50-325/80-03 STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 60/04/10 ip
- --8004270122 Responds to NRC 800212 ltr re violations noted in 1E Insp Repts 50-324/80-03 & 50-325/80-03 Corrective actions hoses properly disposed of 5 surveys conducted to assure correct radioactive mati laboling TOLLISON, A C Carolina Power & Light Co 80/02/26 3pp
- --800427012B Forwards IE Insp Repts 50-324/80-03 & 50-325/80-03 on BOO123-25 & notice of violation STDHR.JP Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/12 2pp
- --8004290135 Notice of violation from insp on 800123-25 * Region 2, Atlanta, Office of the Director 80/0 60/02/11 in
- --8004270141 IE Insp Repts 50-324/80-03 & 50-325/80-03 on 800123-25 Noncompliance noted failure to label containers of radioactive matl & to evaluate & identify radiation hazards associated w/contaminated fire hose GIBBO
- 8004210293 Responds to 1E Insp Ropts 50-324/80-08 & 50-323/80-08 Repts contain no proprietary info Security Instruction BI-18 has been revised to require rall call printaut within five minutes of vital area evacuation TOLLISON.A C Carolina Power & Light Co 80/04/14 2pp
- R Periodic operating reports & related correspondence
- 8004010461 Forwards "Environ Surveillance Rept. Jan-Dec 1979 "
 TOLLISON: A C Carolina Power & Light Co B0/03/28 tp
- --8004010468 "Environ Surveillance Rept. Jan-Dec 1979 EDWARDS, D. H. Carolina Power & Light Co. 80/03/ 80/03/24 50pp
- 8004140445 Forwards monthly operating repts for Mar 1980 TOLLIBON, A C Carolina Power & Light Co 80/04/04
- --8004140447 Monthly operating repts for Mar 1980 WILLIS,E Carolina Power & Light Co 80/04/03
- S Reportable occurrences. LERs & related correspondence
- 80040901ii PNO-II-80-043 on 8000315, subcontractor labor force started picketing site On 800319 & 16 majority of const forces did not report to work On 800318.97 of 600 individuals failed to report to work Estimated outage may be extended three days HARDIN, A K, KELLOGO, P J Region 2. Atlanta, Office of the Director 80/03/18 ip
- 8004010385 Forwards LER 80-004/03L-0 TOLLISON,A C Carolina Power & Light Co 80/03/25 ip
- --8004010390 LER 80-004/03L-0 on 800308, during normal plant operation, oxygen channel of containment atmospheric monitor CAC-AT-1263-2 experienced 1% step change Caused by possible wiring or connection problem Monitor repair is underway TOLLISON, A C Carolina Power % Light Co 80/03/25 1p
- 8004080566 Forwards LER 80-015/03L-0 TOLLISON, A C Carolina Power & Light Co 80/03/31 1p
- --8004080575 LER 80-015/03L-0 on 800314, during attempt to close HPCI torus suction valve E41-F041, following aperability test, RTOB control switch for valve failed Cause not stated Switch replaced TOLLISON, A C Carolina Power & Light Co 80/03/31 ip
- 8004080357 Notifies that triaxial time-history accelograph sys alarmed & recorded on 800208 Seismic monitoring at Shearon Harris Plant & Univ of SC indicated no seismic activity Recorders initiated by nonseismic shock & vibration TOLLISON.A C Carolina Power & Light Co 80/04/01 2pp
- 8004080453 Ferwards LER 80-021/03L-0 TOLLISON, A C Carolina Power & Light Co 80/04/03 1p

- --8004080454 (ER 80-02) URL-0 on 600304, while altempting to start 10 RHR see water pump, pump would not start due to low section pressure signal in start logic Caused by shut instrument isolation valve for section pressure switch 1-5W-PS-1175 TOLL 155 4-A C Catolina Power % Light Co 80/04/03 2p
- 8004150466 RO on 800404,1/4-inch through-wall noritortal crack was JOHISON OF BOOMER, 1/4-Int through-wait not folicital trac located in heat-affected ione 1/4 inch below weld joining 3/4-inch test connection to half coupling on 6-inch reactor water cleanup header Repair being evaluated by engineering TOLLISON A C Carolina Power » Light Co 80/04/04 ip
- BOO4150504 RC on BOO231, during investigation ie lack of pressure during local leak rate test on reactor water cleanup isolation valves, found through-wall horizontal crack on heat-arfected ione Repair under evaluation TOLLISON, A C Carolina Power & Light Co 50/04/04 ip
- --800422060B LER 80-022/03L-0 on 800318, during normal operation, containment atmosphere monitor, CAC-AR-1263, was erratic Caused by doteriorated inlet hose plugging inlet valve Hase replaced (lither monitor) will be inspected * Carolina Power & Light Co 80/04/15 ip
- 8004220676 Forwards LER 60-019/03L-0 TOLLIBON, A.C. Carolina Power & Light Co. 80/04/15 ip
- ---8004220687 LER 80-019/03L-0 on 800318, while performing high steamline radiation channel alignment & runctional test drawer
 D12-RM-KAO3D Model 238XA6OG3 was found out of specs Caused
 by instrument diift Diawer recalibr

 d Carolina Power? Light Co 80/04/15 2pp
- 8004220538 Forwards LER 80-027/03L-0 TOLLISON,A C Carolina Power 4 Light Co 80/04/16 1p
- --8004220547 LER 80-027/03L-0 on 800319 during normal plant operation, standby gas treatment sys 18 would not reset Caused by tripped control power circuit breaver fleaker was reset, closed & standby gas treatment sys was successfully run TOLLISON, A C Carolina Power & Light Co 80/04/16 1p
- 8004280576 Forwards LER 80~030/03L-0 TOLLISOMA C Carolina Power % (1ght Co 80/04/21 1p
- --B004280584 LER 80-030/03L-0 on B00324 operator noticed that containment atmospheric monitor 1-CAC-AT-1259 had low flow alarm & would not remain lunning Caused by shorted air drypr compressor due to high cabinot moisture & bad sample pump TOLLIBON, A C Carolina Power & Light Co 80/04/21 tp
- 8004290397 Forwards LER 80-031/03t-0 TOLLIBON.A C Carolina Power 7 Light Co 80/04/24 1p
- --8004290401 LER 60-031/03L-0 on 800327 during normal operation, containment atmosphere organ monitor 1-CAC-AT-1263 had step change On 800330.1% step change observed Caused by shift in instrument callbr Caygen monitor will be replaced TOLLISON, A C Carolina Power & Light Co 80/04/24 ip
- BOO4290487 Forwards LER 60~025/03L-0
 TOLLISON,A C Carolina Power > Light Co 80/04/24 1p
- --8004270474 [ER 80-025/03L-0 on 800405, following reactor shutdown, control rod 30-03 had dual full in & full out core display position regardless of actual rod position Caused by short in probe buffer card terminal connections
 TOLLISON, A C Carolina Power & Light Co 80/04/24 1p
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040017 Submits addl guidance to {WREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment " Requests review of equipment qualification documentation to identify degree of compliance ROSS,DF Davision of Project Management 80/02/21 3pp
- 800429017i Recommends issuance of policy statement explaining relationship between Commission action to permit zero or low power operation & licensing pause Drart statement encl BICKWITLL Office of the Omeral Counsel HANRAHAN.E J Office of Policy Evaluations 8FCY-80-081A 80/02/22 App

- F. Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES, B K Energoncy Preparedness Task Force 80/03/11 App
- 8004180306 Forwards comments on facility safeguards contingency plan Encl withheld (sef 100FRZ 790) RUBENSTEIN L. S. Light Water Reactors Branch 4 80/04/01 2pp
- 8004110186 Forwards response to 7911.26-27 pre-acceptance safeguards visit Procedures to incorporate periodic testing of alarm line supervisory & tamper curcuits & evaluation of openings to vital areas reviewed Encl withheld (ref 10CFR2 790) MILLS-L M Tennossee Valley Authority 80/04/02 Ip
- 8004170225 Forwards draft revisions to emergency operating instructions EOI-0. "Immediate Actions & Diagnostics." EOI-1, "Loss of Reactor Coolant." & EOI-2. "Loss of Secondary Coolant." & EOI-3. "Steam Generator Tube Rupture "MILLS-L M Tennessee Valley Authority 80/04/15 ip
- --8004170227 Draft Emergency Operating Instructions EOI-O. "Immediate Actions & Diagnostics " WALKER J R . RECORD D J Tennessee Valley Authority 80/01/31 1300
- --8004170227 Draft Emergency Operating Instructions EOI-1, "Loss of Reactor Coolant," Re-ision 10 BENTON, C T , WALKER, J R , RECORD, D J Tennessee Valley Authority 80/03/31 27pp
- --80041/0231 Draft Emergency Operating Instructions EOL-2. "Loss of Secondary Coolant," Revision 9 WALKER, J.R., RECORD, D.J. Tennessee Valley Authority 80/03/31 1750
- --8004170234 Draft Emergency Operating Instructions EOI-3, "Steam Generator Tube Rupture," Revision 7 WILBON, G., WALKER, J.R., RECORD, D.J. Tennossee Valley Authority 80/03/31 13pp

G Adjudicatory correspondence

- 8004020483 Speaks strongly against opening plant so close to largely populated area NRC should be financially responsible & liable should accident occur PATTERN,X Affiliation Unknown 80/02/14 1p
- 8002290321 Requests per 10CFR2 206, public hearing in Knoxville, TN prior to granting of license to fuel facility
 SCOTT, A Affiliation Unknown 80/02/20 1p
- B004020489 Opposes recent licensing of plant Urges NRC to reverse decision 5 resume moratorium of licensing until Kemeny Commission recommendations have been implemented BOREIFO.T Affiliation Unknown 80/02/29 2pp
- 8004080209 Responds to 800220 request for public hearing under 10CFR2 206 prior to issuance of fuel load license to facility NRC approved issuance of low power test license on 800229 Forwards 740325 Ff notice & license W/o encl SHAPAR:H K. Office of the Evecutive Legal Director 80/03/11 1p

H General correspondence

- 8004070075 Responds to 791905 ltr addressed to President Carter re expediting of enhanced efforts to license all qualified nuclear plants NRC is in process of issuing several near-tern OLs Provides info re NRC licensing activities DENTON.H R Office of Euclear Reactor Regulation 80/03/17 2
- --8004070077 Forwards AF Dissell 771205 ltr encouraging early licensing of facility & all qualified nuclear plants Requests comments Resolution encl
 SEAL-M M President of US & Executive Offices 79/12/13 5pp

J Insurance & indemnity information

8004140442 Forwards Endorsements 1-12 to MAELU Policy MF-102 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/04/07 18pp

- K Utality Final Sarety Analysis Report (FSAR) & amends
- 8004170065 Forwards Amend 64 to FSAP MILLS,L II Tennessee Valley Authority 80/04/11 2pp
- --8004170067 Amend 64 to FSAR
 * Tennessee Valley Authority 80/04/11 150pp
- P Operating license stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0598, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance ROSS DF Division of Project Nanagement 80/02/95 7pp
- 8004070415 Discusses potential design deficiency in bypass, override & reset circuits of engineered safoty features Requests review of plant protoction sys design to determine degree of conformance U/listed criteria RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/19 4pp
- 8004070393 Forwards Suppl 1 to NUREG-DOLL, safety evaluation re application for facility Ols W/o encl RUBENSTEIN, L S Light Water Reactors Branch 4 80/03/20 2pp
- 8004020093 Forwards list of requests for addl info re process control program, needed to complete review Response requested by 800417 RUBENSTEIN, L.S. Light Water Reactors Branch 4 80/03/24 App
- B004010408 Responds to NRC B002E3 lti Discusses NRC acceptance of response to Question 6.65 provided in 791031 FSAR, Amend 62 Series check valves periodically tested to ensure closure No revisions planned MICLES.L M Tennessee Valley Authority B0/03/25 lp
- BOO4110493 Requests analysis of alequacy of equipment qualification program per NUREO-0588 Supplements NRC 791017 request for data te environ qualification of safety-related equipment RUBENSTEIN, L. S. Light Water Reactors Branch 4 80/03/25 3pp
- BOO4140016 Natification of BO0404 meeting w/utils in Bothusda.MD to discuss applicants' progress & status in design review re plant shielding & environ qualification of equipment for spaces/sys used in post-accident operations BUCKLEY.B C Light Water Reactors Branch i BO/03/31 7pp
- 8004070228 Forwards revisions to revised response to NUREO-0578,Lessons Learned Task Force short-turm requirements includes procedures for reducing & quantifying liquid sys leakage Revisions replace corresponding 771031 responses MitLS,L M Tennessee Valley Authority 80/04/02 127pp
- 8004140327 Forwards "Master Plan for Special Low Power Test Program " MRLL5.L M Tennessee Valley Authority 60/04/09 is
- --8004140332 "Master Plan for Special Low Power Test Program "
 * Tennessee Valley Authority 80/04/09 87pp
- 8004150551 Forwards application for renewal of NPDEB Permit TN0026450 EL-ASHRY, M T Tennessee Valley Authority 80/04/09 2pp
- --B004150559 Application for renewal of NPDES Permit TN0026450 EL-ASHRY T Tennessee Valley Authority B0/04/09 275pp
- 8004150608 Discusses revision to abnormal operating instruction for reactor trip (AG)-1), submitted 771017 Revision clarifies procedure for operator verification of ATMS Util has written separate emergency operating instruction for ATMS (EGI-14) MILLS, L. (1) Tennessee Valley Authority 80/04/11 7pp
- --8004150615 Emergency Operating Instruction EOI-14, "ATWB," Revision 1 MALKER.J R , CANTRELL.C E Tennessee Valley Authority BO/04/11 7pp
- 8004210202 Responds to NRC 800128 ltr re util participation in QRNL on-line analyzer program Complete analyzer sys should be installed by 800630 Forwards util procedure CQ-8QNP-8AP. "Startup Test Program" MILL8.L M Tennesse Valley Authority 80/04/31 ip
- --8004210205 "Startup Test Program "
 * Tennossee Valley Authority 80/02/22 23pp

- 8004170069 Proposed amend to License DPR-77, changing Tech Specs 3 1 2 4,4 1 2 4,3 6 5 9 5 4 6 5 9 MILLS, L M Tennessee Valley Authority 80/04/14 ip
- --B004170073 Proposed changes to Tech Specs 3 1 2 4,4 1 2 3 6 5 9 & 4 6 5 9, consisting of correction to parameter test for divider barrier seal & typing correction

 * Tennessee Valley Authority B0/04/14 6pp
- 8004170134 Forwards procedure to be used to conduct water hammer test on auxiliary feedwater says at facility
 MILLS,L M Tennessee Valley Authority 80/04/15 1p
- --8004170140 "Water Hamme: Test on Addition of Auxiliary Feedwater to Steam Generator" * Tennessee Valley Authority BO/04/15 14pp
- B00417014B Discusses facility low-pressure turbine preservice insp Util has completed visual & volumetric examinations for turbines Bingle disc indication discovered on Disc 5 of Turbine 1 Disc should operate reliably throughout plant life MILLS.L M Tennessee Valley Authority 80/04/15 2pp
- 8004280229 Forwards add1 info in response to NRC 800325 ltr re process control program
 MILLS, L M Tennessee Valley Authority 80/04/22 14pp
- --8004280235 "ECOPAC Sys Procedure for Onsite Solification of Low Level Radioactive Waste at Sequoyah Nuclear Plant" & addl info re process control program * Amefoo,inc 80/01/31 26pp
- 8004290404 Forwards summary of Westinghouse, TVA & NRC 800320 meeting re control rod guide tube support pins Affidavit for withholding & non-proprietary version enci ANDERGON, T M Westinghouse Electric Corp , PWR Systems Div 80/04/23 46pp
- 8004290290 Responds to NRC 800319 ltr re changes to engineered safety features Design changes initiated to bring util into compliance w/exception of overriding of one type of safety actuation signal by another which is Westinghouse design MILLS, L II Tennessee Valley Authority 80/04/24 7pp
- 8004300341 Forwards drawings & info per NRC request at 800125 meeting re adequacy of pilos supporting waste packaging area & condensate demineralizer waste evaporator bldg Drawings available in Central Files only MILLS, L M Tonnessee Valley Authority 80/04/24 37pp
- O Inspection reports, IF Bulletins & correspondence
- 8004090392 Forwards IE Bulletin 80-03, "Loss of Charcoal From Gtd Type II.Two-Inch,Tray Adsorber Colls " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06-200
- 8004090405 Forwards IE Insp Rept 50-327/80-03 on B00128-30 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/20 2pp
- --8004070413 IE Insp Rept 50-327/80-03 on 800128-30 No noncompliance noted Major areas inspected augmentation of plant personnel for startup test program, independent safety review, onsite & offsite mgt & technical capability DANCE; H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch KELL000, P, COTILE, W Region 2, Atlanta, Office of the Director 80/02/19 10pp
- 8004160066 Forwards IE Insp Repts 50-327/80-04 & 50-328/80-03 on 800208-07 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004160072 IE Insp Repts 50-327/80-04 & 50-328/80-03 on 800205-07 No noncompliance noted Major areas inspected followup on allegation.10CFR50 55 items.IE bulletins & circulars & observation of safety-related activities CANTRELL.F B Region 2. Atlanta, Reactor Construction & Engineering Support Branch GOUGE,M J Region 2. Atlanta, Office of the Director 80/02/27 5pp
- 8004070072 Requests that util provide procedures to be followed for visual & ultrasonic insp examinations of turbines to assure mutually acceptable insp program Test schedule should be submitted for NRC to observe examinations

 RUBENSTEIN: L B Light Water Reactors Branch 4 80/03/14 2pp

- 8004210178 Forwards response to 1E Bulletin 80-03, "Loss of Charcoal From Std Type 11.Two-Inch.Tray Adsorber Cells " Encl lists results or insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS, L M Tennessee Valley Authority 80/03/21 4pp
- 8004010374 Forwards util visual insp procedure SMI-1-1-1, "Preservice Baseline Insp of Low Piessure Turbine," in response to NRC 800313 request Ultrasonic / visual insp of low piessure turbines is scheduled to be completed by 800331 MILLS, L M Tennessee Valley Authority 80/03/26 \$p
- --B004010379 "Preservice Baseline Insp of Low Pressure Turbines " Westinghouse ultrasonic insp program encl ZIEOLER, SIMMONS Tennessee Valley Authority 80/03/11 12pp
- 8004190527 Forwards IE Info Notice 86-12, "Instrument Failure Causes Opening of FORV & Block Valve " No specific action or response necessary O'REILLY, J. F. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080636 Forwards IE Circulai 80-05, "Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director BO/04/01 200
- 8004150097 Forwards IC Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/04/02
- 8004240274 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/02 300
- 8004180275 Forwards 1E Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 2nn
- B004230142 Forwards IF Bulletin 79-03A "Longitudinal Weld Defects in ASME GA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/04
- 8004180445 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds" Written response required O'REILLY, J.P. Region 7. Atlanta, Orfice of the Director 80/04/07
- BOO4170155 Special Maint Instruction SMI-1-1-1, "Preservice Baseline Insp of Low Pressure Turbines" ZIEQLER, BIMMONS Tennessee Valley Authority 80/03/11 13pp
- 8004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLS.L.M. Tennessee Valley Authority 80/04/23 3pp
- 8004290400 Forwards Revision 9 to preservice baseline insp & inservice insp program, incorporating App E re notification of indications. Unit 2 drawings & revisions to Bection 2 MILLS.L M Tennessee Valley Authority 80/04/24 ip
- --B004290406 Preservice baseline insp % inservice insp program.
 Revision 9
 MCLOUD, D O , DANIELS, BELEW Tennessee Valley Authority B0/03/18
- R Periodic operating reports & related correspondence
- 8004180391 Forwards monthly operating rept for Mar 1980 BALLENTINE, J M Tennessee Valley Authority 80/04/11 ip
- --8004180394 Monthly operating rept for Mar 1980
 WALKER,F M Tennessee Valley Authority 80/04/03 9pp

```
5 Reportable orcurrence lin- ' related correspondence
 8004220084 PAI)-77-143 Paritic Pemp Co supplied facilities w/production
      Cause unstated All utils w/pumpa were nutified NRC headquarters notified on 778812
                                    Region 2 Atlanta Office of the Director 77/08/12
 8004280490 Forwards final deficiency tept to improperly installed 
reactor coolant drain
MILLS.L B. Tennessee Valley Authority 80/03/03 ip
 --8004280476 Final deficiency rept re improperly installed leactor
coolant drain line Reanalysis by util? Westinghouse has
changed noirle? support loads Two snubbers replaced
MillS.L M Tennessee Valley Authority 80/03/03 ip
 8004030245 RQ 50-927/802 on 800306, while in Mode 6, loading fuel for first core load, contents of cask decontamination collector tank discharged via liquid radwaste efficient line to cooling tower blowdown w'o flow estimate

BALLENTINE, II Tennessee Valley Authority 80/03/06 ip
 8004030233 RO 50-327/803 on 800310, sample: flow through radine &
      particulate filters in noviliary bidg ventilation sys
gaseous effluent monitor was not maintained for 3-h % (5
minutes Caused by delay in installing apriliary equipment
DALLENTIFE. II Tennessee Valley Authority 80/03/ii Ip
8004030222 RO-50-327/804 on 800311.au;iliaty bldg vent sys gaseous effluent monitor sample; flow rate monitor was made inoperable No flow estimates performed for approx 10-6 Caused by failure to initiate conditional safety injection BALLENTINE, J II Tennessee Vailey Authority 80/03/12 1p
 8004150418 RD on 800315, received notification that incorrect
     valve operator weight was used in seismic analysis for component cooling water valves FCV-70-133.134 & 183 Caused by analysis error Analysis will be serun w/correct weight BALLENTINE, J M Tenne, see Valley Authority 80/03/15
B004150402 Ro on B00314. Westinghouse Itr indicated potential for guide tube support pin cracking Possibly caused by insufficient heat treatment temp at control rod guide pins Guide pins will be replaced by pins while heat treatment temp BALLENTINE, J M Tennessee Valley Authority B0/03/17 jp
8004020366 Forwards LER 80-002/01T-0
CALHOUM J R Tennessee Valley Authority 80/03/19 ip
--80040203/i LER 80-002/01T-O on 800306, contents of task decontamination collector tank discharged via liquid radwaste effluent line to cooling tower bloodown w/o flow estimates being performed Caused by misunderstanding of Tech Specs KINSEY.W H Tennessee Valley Authority 80/03/17 2pp
8004010375 Forwards LER 80~004/017-0
CALHOUN, J.R. Tennessee Valley Authority 60/03/24
--80040103B1 LER 80-004/01T-0 on 800311, following initial fuel loading, flow estimates for auxiliary bldg vent monitor not performed for 10-h Caused by misunderstanding of Toch Specs Personnel reinstructed fre applicable requirements

RECORD. D J Tennessee Valley Authority 80/03/24 2pp
```

8004010399 Forwards LER 80-003/017-0 CALHOUM, J. R. Tennessee Valley Authority 80/03/24 1p

ER 80-003/01T-0 on 800310, following initial fuel loading,

uthority 60/03/26 1p

1 Authoraty 80/03/27 1p

A inoperable personnel dition of operation requires iretation of Tech Spacs y Authority 80/03/27 2pp

vency rept re control rod drop events igation on generic basis Next 13

1 800314, w/essential raw cooling water

aused by misunderstanding of Tech Specs
nstructed in applicable requirements
Tley Authority 80/03/24 2pp

01T-0

```
8004020440 Forwards NPDES noncompliance notification MILLS,L M Tennossee Valley Authority 80/03/27
                                                                                                                80/03/27 10
  --8004020447 NPDES noncompliance notification on 800305, Discharge 019 from svc bldg sump effluent exceeded max permit limitation Caused by periodic discharge of small vols of cleanup wastes Sump cleaned % measures taken to minimize input EL-ASIRY.M T Tennessee Valley Authority 80/03/13 1p
   8004010433 Forwards LFR 80-007/017-0
CALHOUN, J.R. Tennessee Valley Authority 80/03/28 1p
   --8004010440 LER 80-007/017-0 on 800315, following initial core loading, found incorrect (nonconservative) valve operator weights used in seismic analysis for component cooling water valves FCV-70-133, 134 © 183 Caused by incorrect vendor data TERPSTRA.O.L. Tennessee Valley Authority 80/03/28 2pp
  G004010464 Forwards LER 60-012/03L-0
CALHOUNLUR Tennessee Valley Authority 80/03/28 ip
  --8004010475 LFR 80-012/0JL-0 on B00301, during initial core loading. RHR flow secured or throttled above Tech Specs Caused by intentional increase to allow placement of fuel assemblies near loop 4 hot leg
RECORD.D J Tennessee Valley Authority 80/03/28 ip
  8004010502 Forwards LER 80-011/017-0
CALHOUN, J R Tennessee Valley Authority 80/03/28 1p
 --8004010506 LER 80-011/01T-0 on 800314, support pin insp at foreign plant nevealed stress corrosion cracking in Mestinghouse supplied pins Insp supported Westinghouse ltr informing utils of potential hazard Pins will be replaced KINSEY.N H Tennessee Valley Authority 80/03/28 2pp
 8004020312 Forwards final deficienty rept to Ruskin fire dampers
MILLS, L II Tennessee Valley Authority 80/03/28 tp
 --8004020316 final derictioncy rept re spring slipping problem on Ruskin fire dampers flod packages will be installed w/connection of Number 6 screw using washer, star lockwasher & hex nut through narrow portion of spring slot

* Tennessee Valley Authority 80/03/28 ip
 8004090418 Forwards LER 80-013/03L-0
CALHOUN, J.R. Tennessee Valley Authority 80/04/01 ip
 --8004090426 LFR 80-013/03L-0 on g00302 failed to analyze samples from Unit 7 shield bldg exhaust Caused by misunderstanding of surveillance requirements Lab personnel instructed on sampling 2 analysis requirements

KINSEY.W H Tennessee Valley Authority 80/04/01 2pp
8004080519 Forwards LFR 80-008/03L-0
CALHOUN.J R Tennessee Valley Authority 80/04/02 tp
--8004080526 LER 80-008/03L-0 on 800303 cooling tower blowdown effluent
line flow monito: 0-FR-27-1/5 was declared inoperable Flow
monitor consistently indicated higher flowrate than actually
existed Cause unknown Different instrument to be installed
KINSEY,U H Tennassee Valley Authority 80/04/02 2pp
8004080616 Forwards LER 80-009/03L-0
CALHOUN, J R Tennessee Valley Authority 80/04/02 1p
      8004080622 LCR 80-009/03L-0 on 800303, liquid radwaste effluent line
          flow monitor 0-ft-7/-42 consistently indicated higher discharge flow rate than actually observed Cause not stated figher than actually observed Cause not stated flow monitor modified & returned to svc KINSEY, H. H. Tennessee Valley Authority 80/04/02
                                                                                                                      80/04/02 200
8004090333 Forwards LFR 80-016/03L-0
      CALHOUN, J R
                                       Tennessee Valley Authority 80/04/03 ip
--8004090336 LER 80-016/03L-D on 800307.at campletion of fuel loading & w/core alterations still underway.81-65 was not performed Caused by misinterpretation of Tech Brecs by personnel No corrective actions necessary RECORD.D J Tennessee Valley Authority 80/04/03 2pp
8004090429 Forwards LER 80-010/03L-0
CALHOUN, J R Tennessee Valley Authority
                                                                                                                    BD/04/03 1p
```

--B004070433 LER 80-010/03L-0 on B00304.gaseous vent flow rate monitors for Units 1 & 2 shield bidgs & auxiliary bldg were declared inoperable Cause not stated Gaseous flow rate monitors to be redesigned
KINSEY,W H Tennessee Valley Authority 80/04/03 2pp

8004090453 Forwards LER 80-015/03L-0 CALHDUN, J. R. Tennessee Valley Aut Tennessee Valley Authority 80/04/03 1p

DAGGORD Let BUTUIS/DALTO BE BOUNDED BY Earn BOUNDED BY Earn BOUNDED BY BEING MOINTENED IN One a steam generator & reactor pressure vessel Caused by misunderstanding of survoillance instruction RECORD D J Tennessee Valley Authority 80/04/03 ip

800419040B RD on 800404, investigation of manufacturer std 1/4-inch U bolt, used on vendor-designed pipe supports for 3/4-inch Class A pipes, revealed overstress during seismic event Caused by design error Affected supports will be redssigned DALLENTINE, J M Tennessee Valley Authorsty 80/04/07 ip

BOO4180460 Forwards LER 80-021/03L-0 CALHOUN,J R Tennessee Valley Authority 80/04/07 ip

--B004180465 LER 80-021/03L-0 on 80030B, while in Mode & flow rates from auxiliary bldg ventilation sys flow rate monitor were not recorded for three shifts Caused by misreading of notation used in surveillance instruction Temporary change issued RECORD, D.J. Tennessee Valley Authority 80/04/07 2pp

BOO4140428 Forwards LER BO-018/017-0 CALHDUN, J R Tennessee Vailey Authority 80/04/08 ip

--B004140432 LER 80-01B/01T-0 on B00326, while in Mode 6 w/all fuel loaded, exposed cables inside containment between conduit & panetrations not qualified to re-evaluated post-LOCA max dose levels Cables shielded from exposure to new dose level ROBINSON, F Tennessee Valley Authority B0/04/08 2pp

8004150528 Forwards LER 80-005/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/08 ip

--8004150533 LER 80-005/03L-0, on 800311, while performing 81-247 605. reactor solid state protection sys was placed in input inhibit mode, removing high voltage from source range channel NGI Caused by removal of fuses from voltage cut out relay MCGRIFF, J M Tennessee Valley Authority 60/04/08 2pp

8004150539 Forwards LER 80-019/017-0 CALHOUN, J R Tennessee Valley Authority 80/04/08 ip

--8004150547 LER 80-019/01T-0 on 800326, found possibility of not maintaining control room habitability due to leakage of unflitered air Possibly caused by isolation dampers Corrective mods planned ROBINSDN.F Tennessee Valley Authority 80/04/08 2pp

B004180399 Forwards LER 80-017/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/08 ip

~-B004180407 LER 80-017/03L-0 on 800310, while in Mode 6, turbine bidg sump monitor 0-RM-90-212 alarm kept coming in Monitor was declared inoperable. Caused by malfunctioning flow switch not allowing sufficient flow through monitor RECORD.D J Tennessee Valley Authority 80/04/08 2pp

BOO4150500 Forwards LER 80-022/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/11 ip

--B004150512 LER 80-022/03L-0 on 800318, w/Unit 1 in Mode 6, nonessential & Train A air header isolated valves 0-FCV-32, -82, -80 & -110 closed, causing 1-FCV-90-108, -115, -109, -116, -114 & -110 to close Cause unknown RECORD, D J Tennessee Valley Authority 80/04/11 lp

BOO4150554 Forwards LER BO-025/03L-0 CALHOUN.J R Tennessee Valley Authority BO/04/11 ip

--BOO4150565 LER 80-025/03L-0 on BOO313 w/Unit 1 in Mode 6.0-RM 49-225 condensate demineralizer effluent line was taken out of svc for maint Caused by weak transistor Transistor replaced & monitor returned to svc RECORD.D J Tennessee Valley Authority BO/04/11 ip

BOO4170026 Forwards supplemental info to 790529 final deficiency rept re-pressurizer relief piping support MILLE,L M. Tennessee Valley Authority BO/04/11 1p.

---8004170031 Suppl to final deficiency lept to pressurizer relief piping support Results of tests to verify adequacy of draw bead welding on pressure inlier valve line show that weld is not sensitized Tennessee Valley Authority 80/04/11 Bpp

BOO4220715 Forwards LER 80-026/03L-0 CALHOUN, J.R. Tennessee Vailey Authority BO/04/16 1p

~-8004220722 LER 80-026/0.1 -0 on 800416, during Mode 6 operations, ERCW efficient line monitors declared inoperable & maint performed Caused by dirt in flow switch Switch cleaned by monitor returned to scc
RECORD, D J Tennessee Vailey Authority 80/04/16 2pp

8004220753 Forwards LER 80-027/03L-0 CALHOUN, J. R. Fennessee Valley Authority 80/04/16 ip

---BOD4220757 LER B0-027/03L-O on B00318, during Mode 6 operations, FCY-26-240, 241, 242, 243, 244 ½ 245 were identified closed Caused by inadequate Phase A recovery plocedure Valves opened Temporary change made to procedure to require reopening RECORD, D J Tennessee Valley Authority 60/04/16 2pp

8004220698 Forwards LER 80-020/017-0 CALHOUN, J. R. Tennessee Vailey Authority 80/04/17 1p

--8004220707 LER 80-020/0iT-O on 800404.investigation revealed that several vendor-designed pipe supports were designed utilizing manufacturer set o 25-inch U-bolt which overstressed during seismic event Caused by design error LAGERGREN, B Tennessee Vailey Authority 80/04/17 2pp

BOO4290311 Forwards LER 80-028/01T-0 CALHOUN, J.R. Tennessee Valley Authority 80/04/24 1p

---8004290316 LER 80-028/01T-0 on 800411.main steam header pressure transmitters i-PT-(-28.-9A.-9B.-2DA.-2DB & -270 found to lack environ qualification to substantiate long-term post-high energy line break operation Replacement ordered HEREFORD.J M Tennessee Valley Authority 80/04/24 2pp

8004290435 Forwards LER 80-014/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/25 1p

--8004290446 LER 80-014/03L-O on 800328, while performing theck source test, auxiliary bldg vent noble gas monitor had module power problem & failed in svc Caused by Zener diode 1N4740 % transistor FMP8 AI3 shorting out HEREFORD.J M Tennessee Valley Authority 80/04/25 1p

8004290515 Forwards LER 60-024/03L-0 Tennessee Valley Authority 80/04/25 ip CAL HOUN, J. R.

--8004290519 LER 80-024/03L-0 on 800331, flow switches on radiation monitors ORM-90-212 \$ 122 found inoperable Caused by small particulate matter in monitored liquid Design change request initiated Neekly preventive maint program established MCORIFF.J M Tennessee Valley Authority 80/04/25 ip

U Congressional/Executive Correspondence

80040B0254 Responds to B00115 ltr of concern re licensing delays Unit 1 license issued for fuel loading 8 low power testing on B00229 Post-TMI efforts to upgrade safety requirements causing licensing delay DIRGKB, W J Office of the Executive Director for Operations B0/03/12 2pp

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance is methods for compliance ROSB, D F Division of Project Management

8004040017 Submits addl guidance to NUREG-058B. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 60/02/21 3pp

- 8004290171 Recommends issuance of policy statement explaining relationship between Commission action to permit term or low power operation (licensing powes Praft statement encl BICKUITL Office of the General Counsel HANRAHAN, E.J. Office of Policy Evaluations SFCY-80-081A 80/02/22 App
- 8004070A15 Discusses potential design deficiency in bypass override & reset circuits of enginecied safety features Requests review of plant protection sy- sesign to determine degree of conformance wilstyd cirteria RUBENSTEIN.L S Light Warer Reactors Branch 4 80/03/19 4pp
- 8004070393 Forwards Suppl 1 to MUREG-0311, safety evaluation re application for racility Ols Nov encl RUBENSTEIN, L.S. Light Water Reactors Branch 4 80/03/20 2pp
- BOD4020093 Forwards list or requests for addl info re process control program, needed to complete review Response requested by BO0417 RUBENSTEIN. L S Light Water Reactors Branch 4 BO/03/24 App
- 8004110493 Requests analysis or adequacy of equipment qualification program per NUREG-0588 Supplements NRC 791017 request for data ie environ qualification or safety-related equipment RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/25 3pp
- B004140016 Notification of B00404 meeting woutlis in Bethesda.MD to discuss applicants' progress / status in design leview re plant shielding & environ qualification of Equipment for spaces/sys used in post accident operations
 BUCKLEY.B C Light Water Reactors Branch 1 80/03/31 7pp
- 8004090228 Forwards revisions to revised response to NUREG-0578.Lessons Learned Task Force short-term requirements Includes procedures for reducing b quantifying liquid sys leakage Revisions replace corresponding 791031 responses HILLS.L M Tennessee Valley Authority 80/04/02 129pp
- 8004180038 Forwards older extending const completion date to 810501 % safety evaluation for CPPR-73 RUGENSTEIN,L S Light Water Reactors Branch 4 80/04/04 2pp
- --8004180056 Older extending const completion date to 810501 for CPPR-73 ROSS, D F Division of Project Management 80/04/04 2pp
- --8004180070 Safety evaluation supporting request for Extension of const completion date to 810501 for CPPR-73 RUBENSTEIN.L S. Light Nater Reactors Branch 4 80/04/04 3pp
- 8004150551 Forwards application for renewal of NPDES Permit TN0026450 EL-ASHRY, M T Tennessee Valley Authority 80/04/09 2pp
- ~-8004150559 Application for renewal of NPDES Permit TN0026450 EL-ASHRY T Tennessee Valley Authority 80/04/09 275pp
- 8004150608 Discusses revision to abnormal operating instruction for reactor trip (AGI-1), submitted 791017 Revision clarifies procedure for operator verification of ATMS Util has written separate emergency operating instruction for ATMS (EGI-14) MILLS.L (I Tennessee Valley Authority 80/04/11 7pp
- --8004150615 Emergency Operating Instruction E01-14, "ATWS," Revision 1
 MALKER, J. R., CANTRELL, C.E. Tennessee Valley Authority 80/04/11
 7ao
- 8004210202 Responds to NRC 800128 ltr re util participation in QRNL on-line analyzer program Complete analyzer sys should be installed by 800430 Forwards util procedure CD-SONP-6AP, "Startup Test Program" MILLS.L M Tennessee Valley Authority 80/04/11 1p
- --B004210205 "Startup Test Program "
 * Tennessee Valley Authority 80/02/22 23pp
- 8004280229 Forwards additinfo in response to NRC 800325 ltr re-process control program
 MILLSCL M Tennessee Valley Authority 80/04/22 14pp
- --8004280235 "ECOPAC Sys Procedure for Onsite Sollfication of Low Level Radioactive Waste at Sequeyah Nuclear Plant" & add1 info re process control program * Anefco, Inc 80/01/31 26pp
- 8004270404 Forwards summary of Westinghouse, TVA & NRC 800320 meeting recontrol rod guide tube support pins Affidavit for uithholding & non-proprietary version encl ANDERSON, T M Westinghouse Electric Corp. PWR Systems Div 80/04/23 46pp

- 8004290290 Responds to NRC 800319 ltm re changes to engineered safety features Design changes unitabled to bring util into compliance w/exception of overriding of one type of safety actuation signal by another which is Nestinghouse design MILLS, L // Tennessee Valley Authority 80/04/24 7pp
- B004300341 Forwards drawings & into per NRC request at 800125 meeting re adequacy or piles supporting waste packaging area & condensate deminerallise waste evaporator bldg Drawings available in Central Files only MILLS.L M. Tennessee Valley Authority 80/04/24 37pp
- F Security, medical, emergency & rire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr, has been postponed pending GAO clearance under Federal Repts Act ORIMES, B K Emergoncy Preparedness Task Force 80/03/11 4pp
- 8004170225 Forwards draft revisions to emergency operating instructions EOI-D. "Immediate Actions & Diagnostics." EOI-1, "Loss of Reactor Coolant." EOI-2, "Loss of Secondary Coolant." & EOI-3, "Steam Generator Tube Rupture "
 MILLS.L II Tennessee Valley Authority 80/04/15 lp
- --8004170227 Draft Emergency Operating Instructions EOI-O, "Immediate Actions & Diagnostics"
 WALKER, J.R., RECORD, D.J. Tennessee Valley Authority 80/01/3i
 13ao
- --8004170229 Draft Emergency Operating Instructions E01-1. "Loss of Reactor Coolant," Revision 10 BENTON, C T , WALKER, J R , RECORD, D J Tennessee Valley Authority 80/03/31 29pp
- --8004170231 Draft Emergency Operating Instructions EDI-2. "Loss of Secondary Coolant." Revision 9
 WALKER. J R , RECORD, D J Tennessee Vailey Authority 80/03/31
- --8004170234 Draft Emergency Operating Instructions EOI-3, "Steam Generator Tube Rupture," Revision 7 HILSON. G., MALKER, J. R., RECORD, D. J. Tennessee Valley Authority 80/03/31 13pp
- G Adjudicatory correspondence
- 8004020483 Speaks strongly against opening plant so close to largely populated area NRC should be financially responsible & liable should accident occur PATTERN.K Affiliation Unknown 80/02/14 ip
- 8002290321 Requests per 10CFR2 206, public hearing in Knozville, TN prior to granting of license to fuel facility SCOTT, A Affiliation Unknown 80/02/20 ip
- 8004020489 Opposes recent licensing of plant Urges NRC to reverse decision & resume moratorium of licensing until Kemeny Commission recommendations have been implemented BUREIKO.T Affiliation Unknown 80/02/29 2pp
- 8004080209 Responds to 800220 request for gublic hearing under 10CFR2 206 prior to issuance of fuel load license to facility NRC approved issuance of low power test license on 800229 Forwards 740325 Fr notice & license W/o encl SHAPAR, H K Office of the Executive Legal Director 80/03/11 ip
- B004300266 Forwards order & safety evaluation extending const completion date until B10501
 RUBENSTEIN.L S Light Water Reactors Branch 4 80/04/04 2pp
- --8004300270 Safety evaluation stating that issuance of order extending const completion date until 810501 is reasonable t should be authorized STAHLE.C R . RUSENSTEIN.L B Light Water Reactors Branch 4 80/04/04 One
- H Ceneral correspondence
- 8004070075 Responds to 791205 itr addressed to President Carter re expediting of enhanced efforts to license all qualified nuclear plants NRC is in process of issuing several nearterm OLS Provides info re NRC licensing activities DENTON, HR Office of Nuclear Reactor Regulation 80/03/17 2pp

- --8004070077 Forwards AK Bissell 791205 ltr encouraging early licensing of facility & all qualified nuclear plants Requests comments Resolution encl
 SEAL,M M President of US & Executive Offices 79/12/13 Spp
- J Insurance & indemnity information
- 8004140442 Forwards Endorsements 1-12 to MAELU Policy MF-102 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/04/07 18pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004170065 Forwards Amend 64 to FSAR MILLS, L M Tennessee Valley Authority 80/04/11 2pp
- ---B004170067 Amend 64 to FBAR
 * Tennessee Valley Authority B0/04/11 150pp
- Q Inspection reports, IF Bulletins & correspondence
- 8004090352 Forwards IE Bulletin 80-03, "Loss of Chercoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06
- 8004160066 Forwards IE lnsp Repts 50-327/80-04 & 50-328/80-03 on 800205-07 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004160072 IE Insp Repts 50-327/80-04 & 50-328/80-03 on 800205-07 No noncompliance noted Major areas inspected followup on allegation, IOCFR90 S5 items. IE bulletins & circulars & observation of safety-related activities CANTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch COUCE, M J Region 2, Atlanta, Office of the Director 80/02/27 Spp
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC & util in Atlanta. GA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILLY, J P Region 2, Atlanta. Office of the Director 80/03/12-
- 8004070072 Requests that util provide procedures to be followed for visual & ultrasonic insp examinations of turbines to assure mutually acceptable insp program Tost schedule should be submitted for NRC to observe examinations RUBENSTEIN, L 8 Light Water Reactors Branch 4 80/03/14 2pp
- 800421017B Forwards response to IE Bulletin 80~03, "Loss of Charcoal from 8td Type II. Two-Inch. Tray Adsorber Cells" Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to 1E Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLB.L M Tennessee Valley Authority 60/03/28 2pp
- 8004i50527 Forwards IC info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta. Office of the Director 80/03/31 200
- 8004080636 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Unsite Supply " No written response required O'REILLY.J P Region 2, Atlanta. Office of the Director 80/04/01 2pp.
- B004150097 Forwards IE Info Notice 80-13, "GE Type SDM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240274 Farwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02

- BOO4180275 Forwards If Circular Burú7, "Problems W/HPC1 Turbine Oil Sys " No written response required O'REILLY, J.P. Region P. Atlanta, Orrice or the Director BO/04/03 2pp
- BO04230142 Forwards IE Bulletin 79-03A 'Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pipe "Action required O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/04/04 lp
- 8004|80445 Forwards (E Bulletin AO-OB, "Eram of Containment Liner Penetration Welds " Whitten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLB.L M. Tennessee Valley Authority 80/04/23 3pp
- BD04290400 Forwards Revision 9 to preservice baseline insp & inservice insp program, incorporating App E re notification of indications. Unit 2 drawlings & revisions to Section 2 MILLS.L. M Tennessee Valley Authority 80/04/24 ip
- --8004290406 Preservice baseline insp & inservice insp program, Revision 9 MCLOUD,D O , DANIELS, BELEW Tennessee Valley Authority 80/03/18 24pp
- S Reportable occurrences, LERs ' related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT, K W Region 2, Atlanta, Office of the Director 77/08/12 to
- 8004160284 Second interim deficiency lept re-central rod drop events Westinghouse continuing investigation on generic basis Next rept will be submitted by 800613 HILLS.L II Tennessee Valley Authority 80/03/26 1p
- GOO4020312 Forwards final deficiency rept re Ruskin fire dampers MILLB.L M Tennessee Valley Authority 80/03/28 1p
- --8004020314 Final deficiency rept re spring slipping problem on Ruskin fire dampers Mod packages will be installed w/connection of Number 4 screw using washer, star lockwasher & her nut through nariow portion of spring slot

 * Tennessee Valley Authority 80/03/28 ip
- BOO4280453 Forwards final deficiency lept re main control room habitability
 MILLS t. N Tonnessee Valley Authority 80/04/03 1p
- --8004280458 Final deficiency rept re main control room habitability
 During preoperational testing significant leakage of
 unfiltered outside air into main control during isolation
 conditions use discovered Air duct will be modified
 # Tennessee Valley Authority 80/04/03 ip
- 8004180365 Forwards final deficiency rept re incorrect motor operator weights in piping load analysis for component cooling water sys MILLS,L M Tennessae Valley Authority 80/04/11 ip
- --B004180367 Final deficiency tept re incorrect motor operator weights used in piping load analyses for 3-inch piping in component cooling water sys Analyses rerun w/new loads applied Support design inadequate Slight mod to support necessary # Tennessee Valley Authority 80/04/11 ip
- 8004270346 Forwards first interim deficiency lept re defective reactor vessel upper internals guide tube support pins
 MILLS,L M Tennessee Valley Authority 80/04/23 ip
- --B004290353 First interim deficiency rept re generic problem w/defective reactor vessel upper internals guide tube support pins. Caused by heat treatment Westinghouse will investigate to determine if design changes are required * Tennessee Valley Authority B0/04/23 ip
- 8004290329 Forwards first interim deficiency rept re unqualified safety-related cable inside containment MILLS.L M Tennessee Valley Authority 80/04/24 ip

- --8004270335 First Interim derictency rept re unqualified safety-related cable inside containment Exposed portions of cable cannot be environmentally qualified due to higher radiation dose levels recently calculated Cable uill be shielded Tennessee Valley Authority 80/04/24 ip
- 8004270455 Forwards risst interim deficiency mepting inconsistency benepeatability difficulty or upper head injection hydraulic isolation valve accumulator weighing sys MILLS.L.M. Fennessee Velley Authority 80/04/24 lp
- --8004290461 First interim dericiency mept me inconsistency & repeatability difficulty of upper head injection hydraulic isolation valve accumulator weighing sys Caused by stiffening or connecting hydraulic lines under pressure a Tennessee Valley Authority 80/04/24 lp

U Congressional/Elecutive Correspondence

B0040B6254 Responds to 800115 ltm of concern relicensing delays Unit 1 Islands issued for fuel loading 5 low power testing on B00227 Post-TML efforts to upgrade safety requirements causing licensing delay DIRCKS.W J. Orfice of the Elecutive Director for Operations 80/03/12 2pp

DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Qualification or Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits add: guidance to NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance RD88:DF Division of Project Management 80/02/21 3pp
- 8004140090 Requests that Naval Surface Weapons Ctr receive copies of correspondence re facility structural engineering matters Weapons Ctr will assist NRC in review of OL applications RUBENSTEIN.L S Light Water Reactors Branch 4 80/02/26 3pp
- 8004(10020 Summary of 800227-28 meeting w/util & Bechtet consultants in Midland, MJ re-safety review of geotechnical & interfacing matters
 MODD B Light Water Reactors Branch 4 80/03/31 7pp
- 8004080404 Forwards Revision 2 to 771130 response to NRC 791025 request on BNs sys sensitivity incorporates addl overcooling sensitivity analyses into Apps A & B HOMELL, B H Consumers Power Co 80/04/01 250pp
- 8004080431 Forwards response to NRC 800307 ltm re design adequacy of B&W sys Reviews will be in areas of instrumentation & controls & can be accommodated within current const schedule Requests restart if review of DL application HBWELL,S H Consumers Power Co 80/04/01 100pp
- 8004100384 Forwards application for Amend /6 to CPs & DLs & Revision 6 to "Responses to NRC Requests re Plant Fill," referenced by Amend 72 HOWELL-8 H Consumers Power Co 80/04/01 ip
- --8004100387 Application for Amend 76 to application for CPs & OLs Includes revised & new pages for incorporation in "Responses to NRC Requests re Plant Fill." Amend 72 HOWELL.S H Consumers Power Co 80/04/01 ip
- ---8004100390 "Responses to NRC Requests re Plant Fill." Vol 2 HOWELL.S H Consumers Power Co 80/04/01 50pp
- 8004250001 Requests repts, drawings & other info re plant fill settlement & effects Data should be submitted within 20 days after receipt of itr Sample listing encl RUBENSTEIN, L. 8 Light Water Reactors Branch 4 B0/04/01 6pp
- 8004220555 Forwards revised request for add1 borings & existing soil data
 MCCALLISTER.P Army.Dept of. Corps of Engineers 80/04/16 App

- F Security, medical, emergency & fire protection plans
- GOO4080077 Advises that submittal date for evacuation time estimates, requested by NAC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004280460 Requests extension to Oct 1980 for submittal of upgraded emergency plans Almost all util emergency plansing resources utilized to upgrade Big Rock Point & Palisades plans Local counties' portion may not be submitted until late 1980 HOMELL.S is Consumers Power Co. 80/04/21. 2pp

G Adjudicatory correspondence

- 8004030626 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Soard notification QBSICK, L. V. Office of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- 8004020213 Responds to encl 800201 ltr to President Carter urging acceleration of facility hearings & licensing process Discusses impact of TMI-2 accident on process RUSS.D F Division of Project Management 80/03/20 6pp
- 8004290197 FOIA request for PSAR for placement in CA Dow Memorial Library in Midland MI BANNER, A P Affiliation Unknown 80/03/27 tp
- 8004270195 Responds to FOIA request for PSAR for placement in QA Dow Memorial Library in Midland.MI PSAR microfiche is being sent to LPDR in Midland.MI FELTON.J M Division of Rules and Records 80/04/14 72pp
- 8004230393 Forwards util 800318 news release indicating changes in project engineering 5 const diganization Hill submit revisions to GA program by 800430 to incorporate organizational changes HOFFMAN D P Consumers Power Co
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004090248 Forwards Amend 75 to application for CPs & QLs, containing Revision 27 to FSAR, revised piping & instrumentation diagrams & electrical & instrumentation diagrams HQWELL.S H Consumers Power Co 80/03/31 ip
- ---BO04090251 Application for Amend 75 to CP & OL applications, containing Revision 27 to F9AR HOWELLS H Consumers Power Co B0/03/31 1p
- --8004090258 Revision 27 to FBAR containing revised piping & instrumentation diagrams & electrical & instrumentation diagrams Oversize drawlings available in Central Files only & Consumers Power Co 80/03/31 300pp
- 8004140391 Forwards Certificate of Svc For Amend 75 to application for OL containing Revision 27 to FSAR BACON J L Consumers Power Co 80/04/09 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8004040471 Forwards IF Insp Repts 50-329/79-30 & 50-330/79-31 on 791201-31 No noncompliance noted FIDRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/16 2pp
- --BO04040475 IE Insp Repts 50-329/79-30 & 50-330/79-31 on 791201-31.No nancompliance noted Major areas inspected site conditions & NRC order modifying CPs promulgated from settlement of diesel generator bldg & associated soil KNDP.R C . COOX.R J Region 3. Chicago. Office of the Director BO/02/08 Spp
- 8004100245 Forwards IE Insp Repts 50-329/80-04 & 50-330/80-04 on 800212-15 No noncompliance noted FIORELLI, G Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/03/03 2pp

- --8004100252 IE Insp Repts 50-329/80-04 % 50-330/80-04 on 800212-15 No JU410U252 It insp kepts 30-32**180-04 % 30-330/80-04 on 800212-15 No noncompliance noted Major areas inspected containment prestressing sys work procedures, work activities & quality records & status of soils work activities GALLAGHER.E J Region 3, Chicago. Office of the Director HAYES,D W Region 3, Chicago. Reactor Construction & Engineering Bupport Dranch 80/02/27 opp
- 8004100127 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response KEPPLER, J G Ragion 3, Chicago, Office of the Director 80/03/07
- 8004100368 Responds to IE Bulletin 80-03 No tray type absorber cells have been purchased HOWELL.8 H Consumers Power Co 80/03/19 ip
- 8004100260 Forwards IE Insp Repts 50-329/80-05 & 50-330/80-05 on 800204-05 & 14 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004100267 IE Insp Repts 50-329/80-05 & 50-330/80-05 on 800204-05 & 14
 No noncompliance noted Major areas inspected pressure vessel
 anchor bolts records fabrication info gathered by licensee &
 meeting at Southern Bolt Co re bolts supplied
 VANDEL.T E . ERB.C M , KNOP.R C Region 3, Chicago, Office of the
 Director 80/03/11 7pp
- 8004190167 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Velve " No specific action or response necessary KEPPLER J G Region 3, Chicago, Office of the Director 80/03/31
- 8004080702 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/4 Region 3, Chicago, Office of the Director 80/04/01
- 8004150035 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response required

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180041 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER(J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220124 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/02
- 8004220336 Forwards IE Circular 80-07, "Problems W/KPCI Turbine Oil Sys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/03
- 8004230219 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Action required KEPPLER. J O Region 3. Chicago, Office of the Director 80/04/07
- 800422012: Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- 8004070293 Forwards "Quarterly Rept 29. Apr-June 1980," in response to ALAB-106 HOWELL, 8 H Consumers Power Co 80/03/31 1p
- --8004070274 "Quarterly Rept 27.Apr-June 1980," in response to ALAB-106 # Consumers Pawer Co 80/03/31 34pp.

- S Reportable occurrences, LERs & related correspondence
- 8004020459 Part 21 rept on 800228, B&W made telephone rept re defect concerning potentially overstressed supports on reactor coolant letdown coolers due to inadequate support design Corrective action redesign or support stand B0/03/03 Ann
- 8004070204 Ack receipt of 800229 interim deficiency rept re component qualification test documentation re-review Review will commence upon receipt of final rept FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/17 ip Support Branch
- 8004090039 PND-III-80-050 on 800315, two pipe fitters attempting to find gas leak, broke hose coupling containing gas pressure of 40 psi Gas denotated by activation of two-way radio Three men received second & third degree burns over 15% of body KNOP,R C , FIDRELLI.O Region 3, Chicago, Office of the Director 80/03/17 ip
- 8004030177 Ack receipt of 800303 interim deficiency rept re reactor vessel broken anchor bolt Review will be completed on receipt at final rept FIORELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/19 ip
- 8004020083 Ack receipt of 800303 final deficiency rept re discrepant terminal block disconnect links Review will be completed during future insp FIDRELLI, Ø Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/03/20 ip
- 8004210124 Immediate action itr re deficiencies in implementation of GA requirements concerning site work being performed by Zack Corp KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/21 200
- 8004010397 Interim deficiency rept re-potential overstress condition in letdown cooler supports Nozzle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys HOMELL, 5 H Consumers Power Co 80/03/27 ip
- --B004010404 Forwards add1 info to Part 21 rept re potentially overstressed supports on reactor coolant letdown coolers at facilities under const by BbW TAYLOR, J H Babcock & Wilcox Co 80/03/03 6pp
- 8004150356 Interim deficiency rept re safe shutdown boration capability Conceptual design completed for emergency boration sys, containing sufficient boron to independently maintain shutdown margin & transition HOWELL, 8 H Consumers Power Co 80/04/11 2pp
- BOO41700B3 Interim deficiency rept re safe shutdown boration capability assuming restrictive core condition Delineates AE design criteria for separate sys to increase safety-grade boration capability AddI rept will be submitted by BOO731 HOHELL B H Consumers Fower Co 80/04/11 2pp
- 8004210318 Interim deficiency rept re in-containment coatings w/ adhesion loss between successive layers of coating sys Root cause under evaluation Coating acceptance procedure being developed Dechtel rept encl HOWELL, S H Consumers Power Co 80/04/15 3pp
- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREQ-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D F Division of Project Management
- BOO4040017 Submits addi guidance to NUREG-05BB. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,DF Division of Project Management 80/02/21 Spp
- BO04140090 Requests that Naval Surface Weapons Ctr receive copies of correspondence re facility structural engineering matters Weapons Ctr will assist NRC in review of OL applications RUBENSTEIN.L S Light Water Reactors Branch 4. B0/02/26 3pp

- 8004080404 Forwards Revision 2 to 791130 response to NRC 791025 request on BAN sys sensitivity Incorporates add1 overcooling sensitivity analyses into Apps N & B HOMELL, S H Consumers Power Co 80/04/01 250pp
- 8004080431 Foluards response to NRC 800307 ltm re design adequacy of 86W sys Reviews will be in areas of instrumentation & controls 5 can be accommodated within current const schedule Requests restart of review of GL application HOWELL, 8 H Consumers Power Co 80/04/01 100pp
- 8004100384 Forwards application for Amend 76 to CPs & OLs & Revision 6 to "Responses to NRC Requests re Plant Fill." referenced by Amend 72 HOWELL, S.H. Consumers Power Co. 80/04/01 19
- ---8004100387 Apalication for Amend 76 to application for CPs & OLs Includes revised & new pages for incorporation in "Responses to NRC Requests re Plant Fill." Amend 72 HOMELL, S H Consumers Power Co 80/04/01 1p
- ~~8004100390 "Responses to NRC Requests re Plant Fill," Vol 2 HOWELL.S H Consumers Power Co E0/04/01 50pp
- 8004250001 Requests repts drawings & other info re plant fill settlement > effects Data should be submitted within 20 days after receipt of its Bample listing encl RUBENSTEIN.L S Light Water Reactors Branch 4 80/04/01 6pp
- 8004220555 Forwards revised request for add1 borings & existing soil MCCALLISTER.P Army, Dept of Corps of Engineers 80/04/16 4pp
- F Security, medical, emergency t fire protection plans
- 8004080077 Advises that submittel date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending 0AO clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004280460 Requests extension to Oct 1900 for submittal of upgraded emergency plans Almost all util emergency planning resources utilized to upgrade Big Rock Point & Palisades plans Local counties' portion may not be submitted until late 1980 HOWELL-8 H Consumers Power Co 80/04/21 2pp

6 Adjudicatory correspondence

- 6004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & FEMA re primprovement in radiological emergency planning & preparedness distributed as Board notification GOBSICK.L V Office of the Executive Director for Operations BO/04/
- → General correspondence
- 6004020213 Responds to encl 800201 (tr to President Carter urging acceleration of facility hearings & licensing process Discusses impact of TMI-2 accident on process RQSS,D F Division of Project Management 80/03/20 App
- 8004290197 FOIA request for PSAR for placement in GA Dow Memorial Library in Midland.Mi BANNER, A P Affiliation Unknown 80/03/27 ip
- 6004290195 Responds to FOIA request for PSAR for placement in GA

 Dow Memorial Library in Midland, MI PSAR microfiche is being
 sent to LPDR in Midland, MI

 FELTON, J. M. Division of Rules and Records 80/04/14 72pp
- B0042303B3 Forwards util 80031B news release indicating changes in project, engineering \$ const organization Will submit revisions to GA program by 800430 to incorporate organizational changes HOFFMAN.D P Consumers Power Co 80/04/18 7pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004090248 Forwards Amend 75 to application for CPs & OLs.containing Revision 27 to FBAR.revised piping & instrumentation diagrams diagrams & electrical & instrumentation diagrams HOWELL.S H Consumers Power Co. 80/03/31 ip

- --8004090251 Application for Amend 75 to CP & OL applications, containing Revision 27 to FSAR
 HOWELL,S H Consumers Power Co 80/03/31 1p
- ---8004090258 Revision 27 to FSAR containing revised piping & instrumentation diagrams 4 electrical & instrumentation diagrams Oversize drawings available in Central Files only 6 consumers Power Co 80/03/31 300pp
- 8004140391 Forwards Certificate of Svc For Amend 75 to application for OL containing Revision 27 to FSAR BACON, J L Consumers Power Co 80/04/09 2pp
- O Inspection reports, IE Bulletins & correspondence
- 8004040471 Forwards IE Insp Repts 50-329/79-30 & 50-330/79-31 on 791201-31 No noncompliance noted
 FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 80/02/16 2pp
- --8004040475 IE Insp Repts 50-329/79-30 & 50-330/79-31 on 701201-31 No noncompliance noted Major areas inspected site conditions & NRC order modifying CPs promulgated from settlement of dissel generator bldg & associated soil KNDP, R C , COOK, R J Region 3. Chicago. Dffire of the Director 80/02/08 Spp
- 8004100245 Forwards IE Insp Repts 50-329/80-04 & 50-330/80-04 on 800212-15 No noncompliance noted FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/03 2pp
- --8004100252 IE Insp Repts 50-329/80-04 & 50-330/80-04 on 800212-15 No noncompliance noted Major areas inspected containment prestressing sys work procedures, work activities & quality records & status of soils work activities & GALLAGHER.E J Region 3. Chicago. Office of the Director HAYES, D W. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/27 App
- 8004100129 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/07
- 8004100368 Responds to 1E Bulletin 80-03 No tray type absorber cells have been purchased HOWELL,S H Consumers Power Co 80/03/19 1p
- 8004100260 Forwards IE Insp Repts 50-329/80-05 & 50-330/80-05 on 800204-05 b 14 No noncompliance noted FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004[00267 IE Insp Repts 50-327/80-05 & 50-330/80-05 on 800204-05 & 14 JUHIUU20/ IE, Insp Nepts 50-32/180-05 & 50-330/80-05 on B00204-05 & 1 No noncompliance noted Major areas inspected pressure vessel anchor bolts records, fabrication info gathered by licensee & meeting at Southern Bolt Co re bolts supplied VANDEL, T E , ERG, C M , KNOP, R C Region 3, Chicago, Office of the Director B0/03/11 7pp
- 8004150167 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve "No specific action or response necessary KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/31
- 8004080702 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/01
- 8004i30035 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required KEPPLERJ G Region 3, Chicago, Office of the Director 80/04/02
- 8004180041 Forwards attachments to TE Circular B0-03, "Protection From Toxic Gas Haxards," inadvertently omitted from 800306 transmittal KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004220126 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02

- 9004220336 Forwards IE Circular 80-07, "Ploblems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03 ip
- 8004230219 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe "Action required KEPPLER, J. G. Region 3, Chicago, Dffice of the Director 80/04/07 ip
- 8004220121 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- 8004070293 Forwards "Quarterly Rept 29,Apr-June 1980," in response to ALAB-106 MONELL.B H Consumers Power Co 80/03/31 ip
- --8004070294 "Quarterly Rept 29.Apr-June 1980." In response to ALAB-106 * Consumers Power Co 80/03/31 34pp
- S Reportable occurrences. LERs & related correspondence
- 8004020459 Part 21 rept on 800226, D&W made telephone rept re defect concerning potentially overstressed supports on reactor coalant letdown coolers due to inadequate support design Corrective action redesign of support stand TAYLOR, J H Babcock & Wilcox Co BO/03/03 App
- 8004070204 Ack receipt of 800229 interim deficiency rept re component qualification test documentation re-review Roview will commence upon receipt of final rept FIORELI.O Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/03/17 ip
- 8004090039 PNO-III-80-030 on 800313 two pipe fittors attempting to find gas leak, broke hose coupling containing gas pressure of 40 psi Gas denotated by activation of two-way radio Three men received second & third degree burns over 15% of body KNOP,R C , FIGRELLI,G Region 3, Chicago, Office of the Director 80/03/17 1p
- 8004030177 Ack receipt of 800303 interim deficiency rept re reactor vessel broken anchor bolt Review will be completed on receipt at final rept FIORELLI-0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/19 ip
- 8004020085 Ack receipt of 800303 final deficiency rept re discrepant terminal block disconnect links Review will be completed during future insp FIDRELLI.6 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/20 ip
- 8004210124 Immediate action 1tr re deficiencies in implementation of OA requirements concerning site work being performed by Zack Carp KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/21 2pp.
- 8004010397 Interim deficiency rept re potential overstress condition in letdown cooler supports Nozzle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys HOMELL.8 H Consumers Power Co 80/03/27 ip
- --B004010404 Forwards add1 info to Part 21 rept re potentially overstressed supports on reactor coolant letdown coolers at facilities under const by B&W TAYLOR.J H Babcock & Wilcox Co B0/03/03 6pp
- B004150356 Interim deficiency rept re safe shutdown boration capability Conceptual design completed for emergency boration sys.containing sufficient borom to independently maintain shutdown margin & transition HOWELL, S H Consumers Power Co B0/04/11 2pp
- 8004170083 Interim deficiency rept re safe shutdown boration capability assuming restrictive core condition Delineates AE design criteria for separate sys to increase safety-grade boration capability Addl rept will be submitted by E00731 HOHELL.8 H Consumers Power Co 80/04/11 2pp

- BOG4210318 Interior deficiency rept re in-containment coatings w/adhesion loss between successive layers of coating sys Root cause under evaluation Coating acceptance procedure being developed Bechtel rept encl
 HOWELL, S.H. Consumers Power Co. BO/04/15. 3pp
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER
- F Secusity, medical, emergency of the protection plans
- 8004220268 Forwards "Fire Endurance & Hose Stream Tests on Electrical Cable Penetration Fire Stop Designs " ROOT, L D Towa Electric Light & Power Co 80/04/01 1p
- --8004220273 "Fire Endurance > Hose Stream Tests on Electrical Cable Penetration Fire Stop Designs ' HOLLENBACHER.R EDS Nuclear, Inc 80/04/01 300pp
- 8004080447 Forwards fire protection teview Item 3 2 7 turbing bldg fires Recommends automatic sprinkler sys be provided throughout Zone 8D MALL:R E Brookhaven National Laboratory 80/04/04 3pp
- 8004240561 Confirms 800414 meeting at Region 3 ofc to discuss regulatory performance & security KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/04/07 to
- 8004250385 Forwards input on Item 5-15-6.diesel generator room.for fire protection leview HALL.R E Brookhaven National Laboratory 80/04/17 2pg
- 8004280454 Forwards revision to modified amended security plan Encl withheld (ref 10CFR2 790) ROOT,L D Jowa Electric Light > Power Co 80/04/25 ip
- G Adjudicatory correspondence
- 8004080576 Order granting extension, until 800428, for Commission to elect whether to review director's 800213 decision denying petition under 10CFR2 206, ie Mark I containment HDYLE, J C Office of the Secretary of the Commission 80/03/31
- P Operating license stage documents & correspondence
- 8004070395 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20.000 MM-day per metric ton Responses indirate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- 6004030102 Forwards "Nuclear Data Link Specs," study of digital communication systo bransmit info from plants to Bethesda Operations Ctr EISENHUT, D 0 Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/21 28pp
- 8004040112 Submits results of fuel assembly loading error evaluation involving fuel assemblies other than PEDPN287 in response to NRC request Only change in critical power ratio due to rotated PBDPN287 is large enough to effect Cycle 5 limits MEYER.K General Electric Co. 80/03/17 ip
- 8004070212 Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics into during incident or abnormal occurrence at facility KEPPLER. J O Region 3. Chicago. Office of the Director 80/03/19
- 8004100170 Requests controlled set of P&IDs for both Region 3 & headquarters Submittals should be forwarded to attention of Region 3 incident response ctr. / BIH Weiss, headquarters incident response ctr. within 20 days

 KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/03/20 in
- 8004210008 Forwards request for addl info re electrical aspects of engineered safety feautures per review of long-term resolution of containment purging 8 venting Info should be submitted within 30 days after receipt of tr IPPOLITO.TA Operating Reactors Branch 3 80/03/28 4pp

- 8004250024 Forwards 800128 / 0211 ltrs to GF re proposed control rod drive sys mods related to elimination of cracking in return line notities Mods should not be performed prior to issuance of NUREC-0619, scheduled for Apr 1980 IPPOLITO TA Operating Reactors Branch 3 80/04/07 2pp
- BOO4140380 Amend to 791022 application for amend of License DPR-49 Tech Specs Revisions add limiting conditions for operation \$\delta\$ surveillance of instruments that trip recirculation pumps \$\delta\$ change reactor high pressure trip level ROOTLD Towa Electric Light \$\delta\$ Power Cp 80/04/09 1p
- --8004140382 Proposed revisions to Tech Specs 3.2 g & 4.2 @,adding limiting conditions for operation & surveillance for instruments that trip lecirculation pumps & changing reactor high pressure trip level from 1.135 to 1.120 psig a lowa Electric Light & Power Ca 80/04/07 App
- 8004220519 Submits review of Amend 57 to License DPR-49, changing Tech Specs to allow count rate in source range monitor channels to drop below three counts per second during removal or replacement of core No comment necessary WALLACE: A T lowar State of 80/04/11 1p
- BOO4220507 Responds to NRC BOO110 ltr re control rod failing to fully insert on reactor scram No evidence found for CY78 & 79 of events occurring when reactor automatically or manually scrammed Cn 790313.control rod failed to scram ROOT.L D lowa Electric Light & Power Co BO/04/15 lp
- 8004280461 Responds to 800407 ltr re QA program for standby diesel generator fuel oil Fuel is checked monthly for viscosity, water & sediment Lists revisions to be made to appropriate test procedure to comply w/code & Reg Quide \(\) 137 RQOT.L \(\) lowa Electric Light & Power Co \(\) 80/04/21 \(\) 3pp
- Q Inspection reports: IE Bulletins & correspondence
- 8004040160 Forwards Waste Packaging Insp Rept 79-07A on 791219 & notice of violation DAVIS:A B Region 3. Chicago: Fuel Facility & Materials Safety Branch 80/02/25 2pp
- --8004040164 Notice of violation from insp on 791219
 * Region 3, Chicago, Office of the Director 80/02/25 ip
- ~~B00404017! Waste Packaging Insp Rept 79-07A on 791219 Noncompliance noted cask shipped from facility not marked "Radioactive LSA:" as required POTIER.J F. BROWN.R A Region 2, Atlanta, Fuel Facility & Materials Safety Brench 90/02/25 4pp
- 8004100135 Forwards IE Info Notice 80-08. "States Co Bliding Link Electrical Terminal Block" No specific action or response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/03/07
- 8004030259 Advises that item of noncompliance noted in NRC 800225 ltm % attached lnsp Rept 79 07A has been determined invalid No response necessary BAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/19 ip
- 8004160005 Responds to IE Builetin 80-03 re potential for loss of charcoal from ventilation sys tray-type charcoal adsorber cells Most charcoal units are deep-bed rather than tray-type Charcoal loss is negligible from tray-type cells ROOT, LD town Electric Light & Power Co 80/03/20 2pp
 - ifo Notice 80-12, "Instrument Failure Causes > Valve " No specific action or
 - Chicago, Office of the Director 80/03/31
 - lar 80-05. "Emergency Diesel Generator Onsite Supply " No written
 - icaga, Office of the Director 80/04/01
 - Defective CAM Followers " No specific action or response requires KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/02

- 8304180051 Forwards attachments to IE Circular 80-03, "Protection From Toric Gas Hajards," inadvartently omitted from 800306 transmittal MEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/02
- 8004220140 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required XEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004220373 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/03
- 8004110041 Forwards IE Bulletin 80-07, "DWR Jet Pump Assembly Failure " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07 to
- B004230274 Forwards 1E Bulletin 79-03A, "Longitudinal Held Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/07
- 8004220089 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER.J 0 Region 3. Chicago, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- B004030160 Forwards "Semiannual Rept Radioactive Effluent Releases, Jul-Dec 1979 " MINECK,D L lowa Electric Light & Power Co 80/02/21 ip
- --8004030161 "Semiannual Rept Radioactive Effluent Releases, Jul-Dec 1979" 4 Iowa Clectric Light & Power Co 80/02/21 7pp
- BOO4070252 Forwards "Annual Environ Rept,1979"
 MINECK,D L. lowa Electric Light & Power Co. 80/03/25 ip
- ---8004070256 "Annual Environ Rept, 1979 "
 * Towa Electric Light & Power Co 80/03/25 500pp
- BCO4220385 Forwards monthly operating ropt for Mar 1980 MINECK, D.L. Towa Electric Light & Power Co. BO/04/14 1p
- --8004220389 Monthly operating rept for Mar 1980 VAN BICKEL, J lowa Electric Light & Power Co 80/04/14 2p
- 8004230344 Forwards corrected monthly operating rept for Feb 1980 MINECK,D L lows Electric Light & Power Co 80/04/14 ip
- --8004230348 Corrected monthly operating rept for Feb 1980 VAN GICKEL, J Iowa Electric Light & Power Co 80/04/14 1p
- 5 Reportable occurrences, LERs 5 related correspondence
- 80042:10429 PND-77-50A on 770329 & 30,six main steam relief valves failed No apparent cause noted Valves will be replaced by manufacturer, Target Rock Mod will delay plant startup for two wks
 WHITT, K W , ROY, O W , THOMPSON, D Region 3, Chicago, Office of the Director 77/04/19 lp
- 8004080664 PNO-111-80-047 on 800312, unamalyzed water was pumped from circulating water pit offsite, through dilution structure to river for 1-h & 45 minutes Preliminary data indicates radioactivity of release less than 1% of limit JACKIW, I N , LITTLE, W S Region 3, Chicago, Office of the Director. 80/03/14 2pp
- 8004040400 Forwards LER 80-011/01T-0 MINECK,D L lowa Electric Light & Power Co 80/03/31 1p
- --B004040413 LER B0-011/01T-0 on B00317, during annual inep of standby diesel generator 10-21, lower crankshaft main thrust bearing found wiped on both thrust & journal surfaces Gaused by low lube oil level Bearing replaced & crankshaft relapped TOOMER, D W lowa Electric Light & Power Co B0/03/31 2pp.
- 8004080518 Forwards LER 80-012/01T-0 MINECK.D L | Jowa Electric Light & Power Co 80/03/31 1p

- --8004080531 LER 80-012/017-0 on 800317, during annual imap of diesel generator 10-31, lower crankshaft thrust 13 bearing found wiped on journal surface Caused by bearing/crankshaft clearance being out of spec TOOKER, D W Iowa Electric Light & Power Co 80/03/31 2pp
- 8004080605 Ro during core loading operations, fuel assembly was loaded into cell 06-23 w/o control rod 06-23 being fully inserted Cause unstated Control rod inserted & fuel moving plan reviewed prior to resuming core loading MINECK, D L Iowa Electric Light & Power Co 80/03/31 ip
- 8004150340 RD during core loading operations, fuel assembly loaded into cell 06-23 m/o control rod 06-23 being fully inserted Control rod inserted & fuel moving plan reviewed prior to resuming core loading MINECK, D. L. low Electric Light & Power Co. 80/03/31 ip
- 8004090447 RO on 800402, while preparing to change out cell in 125 volt dc battery, station electrician opened breaker between 1D2 & 125 buss causing loss of control power to essential buss & ather loads Breaker reclosed MINECK, D L lower Electric Light & Power Co 80/04/02 1p
- --E004140369 LER E0-014/017-0 on E00402; while preparing to change out 125-volt dc battery cell, breaker between battery changer & 125-volt dc bus 10-20, resulted in loss of control power Caused by personnel error Dissel auto started TODKER, D W Towa Electric Light & Power Co E0/04/10 2pp
- 8004140450 Forwards LER 80-013/017-0 MINECK, D L I I Dwa Electric Light & Power Co 80/04/10 ip
- ---8004140452 LER 80-013/01T-0 on 800330, during core loading operations, fuel assembly was loaded into cell 06-23 w/o control rod 06-23 eding fully inserted Caused by personnel error Fuel moving plan reviewed before loading was resumed TOOKER.D W Iowa Electric Light & Power Co 80/04/10 2pp

DOCKET 50-332 BARNWELL REPROCESSING PLANT

- Q Inspection reports, IE Bulletins % correspondence
- B004240226 Farwards 1E Info Notice 80-14. "Bafety Buggestions From Employees" No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02 in
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

 F Security, medical, emergency & fire protection plans
- 8004070243 Forwards list of fire protection review items for which licenses into has been received MALL.R.E. Brookhaven National Laboratory 80/03/27 Spp.
- 8004240167 Requests proposed emergency plan be revised re criteria identified in encl per NUREO-0654 All elements specified essential for adequate radiological emergency planning IPPOLITO, T. A. Operating Reactors Branch 3 80/03/27 i6pp
- J Insurance & indemnity information
- 8004020219 Forwards Endorsements 44 & 45 to NELIA Policies NF-208 & Endorsement 38 to MAELU Policy MF-77
 DEEQ,F H Power Authority of the State of New York 80/03/28 4pp
- P Operating license stage documents & correspondence
- 8004070400 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Rasponses indicate that no immediate licensing action is required for operating reactors IPPOLITO,T A Operating Reactors Branch 3 80/03/10 3pp
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Detheada Operations Ctr EIBENHUT, D G Division of Operating Reactors 80/03/12 5pp.
- --8004030i18 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28pp

- BOO4100602 Forwards evaluation of actions taken in response to TMI~2 Lessons Learned Task Force recommendations All requirements satisfactorily methercept installation of valve position indicating sys IE will verify adequacy of procedures & mods IPPOLITO.T A Operating Reactors Branch 3 80/03/25 1App
- BOO4010259 Notifies of delay in expected receipt of equipment concerning sys for direct indication of relief valve discharge Expected shipment date is BOO328 Reaffirms commitment for installation within 30 days of receipt EARLY, P. J. Power Authority of the State of New York BO/03/26 2Dp
- 8004010367 Forwards illustrations of isolation valve configurations of high pressure piping connecting primary coolant says piping to low pressure says piping No Event 5 isolation valve configurations indicated EARLY, P J Power Authority of the State of New York 80/03/26
- BOD4NB0473 Forwards response to NRC BO0307 request for addlinfo re spent fuel pool capacity expansion No changes proposed to spent fuel pool cooling sys in conjunction w/efforts to increase spent fuel storage capacity EARLY.P J Power Authority of the State of New York BO/04/01 4pp
- BOOA250032 Forwards BO0128 & 0211 ltrs to GE re proposed control rod drive sys mods related to elimination of cracking in return line nozzles Mods should not be performed prior to issuance of NURGO-0619 scheduled for Apr 1980 IPPOLITO.T A Operating Reactors Branch 3 BO/04/07 2pp
- BOO4130364 Responds to NRC 800201 ltr Receipt of equipment associated w/sys for direct indication of relief valve discharge delayed until 800411 Delay caused by problem w/output relays uncovered by R&W Installation completed by 800601

 EARLY,P J Power Authority of the State of New York 80/04/08 ip
- 8004170064 Forwards fee for 800202 application for Tech Spec changes re primary containment isolation Fee paid under protest EARLY.P J Power Authority of the State of New York 80/04/11 ip
- G Inspection reports, IE Builetins & correspondence
- 8004220445 Responds to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas " Requests extentions to 800307 for response LEONARD, J D Power Authority of the State of New York 80/02/14 ip
- 8004080419 Advises that response to [E Bulletin 79-27 re loss of instrumentation non-class [E will not be complete within 70-day period Requests add! 45 days for response LEGNARD. J D Power Authority of the State of New York 80/02/26
- B004090125 Forwards response to IE Bulletin 79-01D re environ qualification of Class IE equipment Master list of Class IE electrical components encl Qualification data outstanding W/o encl LEONARD. J D Power Authority of the State of New York B0/03/03
- 8004070452 Submits response to 1E Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys During Plant Operation" No mods required after review LEONARD, J D Power Authority of the State of New York 80/03/04
- 8004210334 Forwards Haste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- ---B004210337 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper requirements. DOT placarding requirements radiation levels, removable contamination & DOT/NRC marking & labeling POTTER.JP. PEERY,NW. WOODRUFF,RL Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/01/18 7pp
- 8004090409 Advises that IE Builstin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," was incorrectly sent for action No response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/03/17 ip

- 8004080258 Ack receipt of 800312 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/79-18 SMITH G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/19 ip
- --8004080266 Responds to NRC 800215 ltr re violations noted in IE Insp Rept 50-333/79-18 Corrective actions review of administrative controls re retraining requirements has been conducted LEGNARD. J D Power Authority or the State of New York 80/03/12 20p
- ---8004080271 Forwards 1E Insp Rept 50-303/79-18 on 791212-14 & notice of violation SMITH,G H. Region 1. Philadelphia, Fuel Facility & Materials Sarety Branch 60/02/15 2ρρ
- ~~8004080274 Notice of violation from 1115p on 791212-14 * Region I, Philadelphia. Office of the Director 80/02/12 ip
- --8004080262 IE Insp Rept 50-333/79-18 on 791212-14 Noncompliance noted records indicated that two employees had not received annual retraining in radiation protection THDMUS.L.H. Region I. Philadelphia. Office of the Director CROCKER.H.W. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 60/02/12 5pp
- BOO4150286 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening or PORV & Block Valve " No specific action or response necessary GRIER, B H Region 1. Philadelphia. Office of the Director 80/03/31 ip
- BOO4040083 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B.H. Region I. Philadelphia. Office of the Director
- 2004110499 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No written response required GRIER.B H Region I. Phitadelphia, Office of the Director 80/04/02 ip
- E3004240335 Forwards IE Info Natice B0-14, "Safety Suggestions From Employees " No action required GRIER, B H Region 1, Philadelphia, Office of the Director B0/04/02 ip
- BO04180236 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/03 | Ip
- ⇔ CO4110061 Forwards IE Bulletin RO-O7, "BWR Jet Pump Assembly Failure " Written response required GRIER.B H. Region 1, Philadelphia, Office of the Director BO/O4/O4 Ip
- 83004230439 Forwards IE Sulistin 79-03A, "Longitudinal Weld Defects in ASKE SA-312. Type 304 Stainless Steel Pipe" Action required GRIER, B H Region 1. Philadelphia. Office of the Director 80/04/04 1p
- BO04180245 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required GRIER.B H. Region i, Philadelphia. Office of the Director 80/04/07. 1p
- R Periodic operating reports & related correspondence
- EO04070276 Forwards "Radiological Environ Surveillance Rept.1979"
 LEDNARD, J D Power Authority of the State of New York 60/03/28
 1p
- ED04090318 Forwards monthly operating rept for Mar 1980
 PASTERNAX.R J Fower Authority of the State of New York 80/04/02
- ---8004090320 Monthly operating rept for Mar 1980

 ZUFELT.E Power Authority of the State of New York 80/04/02
 19pp

- S Reportable occurrences, LERs & related correspondence
- 8004030273 Forwards revised LER 79-038/03X-1 LEDNARD, J.D. Power Authority of the State of New York 80/03/27 to
- --8004030278 Revised LER 79-038/03X-1 on 790611 during cold shutdown surveillance revealed callbt instrument for main steam tunnel high temp switches could not be callbt Gaused by instrument 02-TIC-200 drift Alternate instrumentation used CHILDS: W V Power Authority of the State of New York 80/03/27 200
- 8004030216 Forwards LER 80-025/03L-0 LEDNARD, J D Power Authority of the State of New York 80/03/28
- --8004030218 LER 80-025/03L-0 on 800228, during normal operation while conducting surveillance tests, average power reactor monitor B remained inoperable when function switch was returned to operation position Caused by normal hysteresis effect CHELDS, W V Power Authority of the State of New York 80/03/28 20m
- 8004090436 Forwards LER 80-026/03L-0
 PASTERNAK.R J Power Authority of the State of New York 80/04/03
- --9004090440 LER 80-026/03L-0 on 800307 during steady state operation, drifting low power range monitor caused process computer to andicate operation in excess of thermal limits Caused by drifting low power range monitor 44-37C, due to age CHILDS, W V Power Authority of the State of New York 80/04/03
- 6004140398 Responds to NRC 791213 request For addl info re loss of offsite power events Two losses of offsite power identified since 1974 No partial losses & during both events, reactor in cold shutdown
 EARLY, P J Power Authority of the State of New York 80/04/08 200
- 8004150308 Submits summary of scrams from 780909-1231.in response to NRC request for more recent control rod failures Considering overhaul of control rod drives during upcoming outge EARLY.P J Pawer Authority of the State of New York 80/04/09 20n
- 8004220767 Forwards LER 80-027/03L-0
 PASTERNAK, R J Power Authority of the State of New York 80/04/17
- --8004220771 LER 80-027/03L-0 on 800322, HPCI was made inoperable to repair pipe support Caused by need to repair hanger re HPCI sys stems supply HCPI restored to operable status in standby mode
 CHILDS: H V Power Authority of the State of New York 80/04/17 200
- 8004280552 Forwards LER 80-028/03L-0 PASTERNAK, R J Power Authority of the State of New York 80/04/23
- ~~8004280559 LER 80-028/03L-0 on 800324 during normal operation, loop B of torus cooling was declared inoperable Caused by failure of base plate for hanger HIO-49A per IE Bullatin 79-02 Temporary repair restored sys to operable status CHILDS:U V Power Authority of the State of New York 80/04/23
- G004290504 Forwards LER G0-029/03L-0
 PABTERNAK, R J Power Authority of the State of New York B0/04/24
 10
- --8004290511 LER 80-027/03L-0 on 900325, condensate storage tank level switch 23-LS-74A set outside Tech Specs limit Event recurred one wt later Caused by dirt in switch Switch cleaned & Jubricated CHILDS,N V Power Authority of the State of New York 80/04/24
- 8004290476 Forwards LER 80-030/03L-0 PASTERNAK:R J Power Authority of the State of New York 80/04/25

DOCKETED ITEMS

- --8004290482 LER 80-030/03L-0 on 800327, visual insp of more than 6,000 electrical fire smals revealed 350 seals missing or requiring resealing Caused by initial installation being missed by initial installation being missed in most cases New seals were installed CHILDS.N V Power Authority of the State of New York 80/04/25
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8004040354 Forwards revision to 800305 draft emergency preparedness plan addressing areas of NVREO-0654 not included in original draft Plan will be appropriately revised when criteria requiring lead time are implemented. Dequesne Light Co 80/03/31 1p
- ---B004040359 Revision to 800305 draft emergency preparedness plan * Duquesne Light Co 80/04/01 250pp
- O Adjudicatory correspondence
- 8004010426 Forwards documents re investigation into extended outages at facility Documents include trial staff statement before PA Public Util Commission, consumer advocate statement & CN Dunn testimony LEVIN, J A Pennsylvania, State of BO/03/28 54pp
- I Financial information
- 8004070297 Forwards 1979 Annual Financial Rept. earnings statements for quarter ending 791231 to one-yr internal cash flow projection for 1980 w/actual cash flow for 1979 MILSON.M L. Pennsylvania Power Co. 80/03/31 3pp
- --8004070298 Annual Financial Rept 1979 * Pennsylvania Power Co 80/03/11 40pp
- B0040B0499 Submits util earnings statement for quarter ending 791231. one-yr internal cash flow projection for 1980 & actual cash flow for 1979 Forwards Annual Financial Rept for 1979 FIRESTONE, L Chio Edison Co 80/04/02 3pp
- --8004080502 Annual Financial Rept 1979 * Ohio Edison Co 80/03/19 48pp
- J Insurance & indemnity information
- 8004230517 Forwards cash flow statement re availability of funding for annual & quarterly payment of premiums CHRISTNER, R B Duquesne Light Co 80/04/19 3pp
- P Operating license stage documents & correspondence
- 8004280065 Responds to 800128 request for info re testimony before Public Utils Commission & forwards LER 78-53/017-0,781206 backup rept & list of documents on dockets for Oct 1978-Mar 1979 & Mar 1979-May 1979 Request list encl RUBSELL.W T Technical & Administrative Support Branch 80/02/05
- --8004280070 Forwards IE Insp Rept 50-334/78-34 on 781218-20 & notice of violation BRUNNER.E J Region 1. Philadelphia, Office of the Director 79/01/10 300
- --8004280098 Forwards OA Program Insp Rept 99900509/79-03 on 790501-04 & notices of violation & deviation Summarizes background info on related enforcement assue REINMUTH, O W Division of Reactor Construction Inspection 79/08/10 Spp
- --G004280078 LER 77-006/017-1 on 770126, hydraulic unubbers on feedwater lines found inadequate for seismic design condition Caused by design verification breakdown during const Hanger mods include increased annota bulk size & new hanger additions MERLING, J A Duquesne Light Co 79/03/14 2pp
- ---8004280079 Record of telcon ω/D Ford (UCS) on 790320 re chronology of NRC activities re pipestress issue BECKMAN,D A Region 1, Philadelphia, Office of the Director 79704/10 3pp
- --8004280085 SRP.Bection 3 7 2, "Seismic Sys Analysis" * Office of Nuclear Reactor Regulation NUREO-75/087 3 7 2 75/11/24 9pp

- --B004280090 Requests enri chronology or sarety injection piping stress analysis & reviews be forwarded to Engineering Branch for review Refs AITS-F14741H2. document record for dockets for Oct 1978-Mar 1979 & Mar-May 1979, respectively, encl KEIMIG, R. Region i, Philadelphia, Office of the Director KEIMIG, R R Re 79/01/18 95pp
- 8004150318 Forwards safety analysis supporting actions taken to correct cracking found in feedwater sys piping SCHWENCER, A Operating Reactors Dianch 1 80/02/25 App
- 8004140050 Advises that Commission has issued encl Amend 26 to License DPR-66 Tech Specs SCHWENCER A Operating Reactors Branch 1 80/02/29 Jpp
- --8004140054 Amend 26 to License DPR-66 adding condition requiring secondary water chemistry monitoring program & changing Tech Specs to prohibit containment purge by steam jet air ejector sys during hot shutdown SCHNENCER:A Operating Reactors Branch 1 80/02/29 15pp
- --8004140058 Notice of issuance & availability of Amend 26 to License SCHWENCER, A Operating Reactors Branch 1 80/02/29 2pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Communication by the Communication by the Communications Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 Spp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004090264 Notification of 800326 meeting w/util & S&N in Bethesda.MD to discuss decay heat eichanger sys integrity & operation required for ECCS-LCCA MIGGINTON.D Operating Reactors Branch 1 80/03/24 2pp
- 8004010459 Forwards response to NRC 800122 request for add1 info re requirements for auxiliary feedwater sys Complete response not available until completion of engineering evaluation DUNN.C M Duquesne Light Co 80/03/25 21pp
- BOD42400B7 Summary of 800307 meeting w/util re approval of site for long-term technical support ctr & short-term Lessons Learned Task Foice implementation plan WIGGINTON, D. Operating Reactors Branch 1 80/03/25 4pp
- --8004240089 "Conceptual Design of Braver Valley Power Station Technical Support Ctr" # Duquesne Light Co 80/03/04 11pp
- BOO4240445 Requests demonstration of qualifications re proposed changes to membership for onsite safety committee & offsite review committee, per ANSI 18 7-1976 requirements Response should be submitted within 30 days

 BCHWENCER.A Operating Reactors Branch | 80/03/25 2pp
- B004030201 Forwards Mar 1980 table w/current status of action items re short-term Lessons Learned requirements Items changed from Feb submittal concern emergency power supply pressurizer heater & onsite technical support
- 8004180045 Advises that 800131 proposed design basis re add1 smoke detectors for control room & 1-h fire tated barrier meet guidelines & are acceptable BICHHENCER.A Operating Reactors Dranch 1 80/04/04 2pp
- 8004290002 Requests add1 info & clarification re bypass & reset of engineered safety features as part of review of containment purge & ventilation sys at nuclear plants Response to Lessons Learned Task Force Criterion & should be included SCHWENCER.A Operating Reactors Branch 1 HO/04/04 4pp
- 8004110482 Discusses basic paramoters of reload design for Cycle 2 & review of safety & operational aspects of reload design by Westinchouse Duquesne Light Co 80/04/07 3pp

- --800430016B Amend 27 to License DPR-65, deleting refs to Table 4 4-4 from App A Tech Specs Wolves requirements for visual & surface or volumetric inservice insps examination of cladding or reactor vessel head Revised pages encl.

 SCHWENCER, A Operating Reactors Branch 1 80/04/07 11pp
- ~~8004300174 Safety evaluation supporting Amend 27 to License DPR-66 * Office of Nuclear Reactor Regulation 80/04/07 6pp
- --8004300183 Notice of granting of relief from ASME Section XI inservice inspirequirements A issuance of Amend 27 to License DPR-66 SCHWENCER. A Operating Reactors Branch 1 80/04/07 3pp
- 8004210263 Forwards revised Tables 18-1,2-1 & 3-1 to util 800325 response re auxiliary feedwater sys

 DUNN.C N Dequesne Light Co 80/04/14 4pp
- 8004220594 Responds to NRC 800107 ltr re QA requirements for emergency diesel generator fuel oil Will implement Reg Ouide 1 137. Sections C 2 a, C 2 b, C 2 c b, C 2 f during current refueling outage DUNN, C N Duquesne Light Co 80/04/14 lp
- O Inspection reports, IE Bulletins & correspondence
- 7906010118 FOIA request by UCS for all documents re Task Action Plans A-40 % A-41, info on seismic issues prepared for SEP % insp repts for Beaver Valley WEISS,E R Sheldon, Harmon & Weiss 77/03/19 2pp
- B004170304 Forwards Public Enforcement Conference Rept 50-334/80-04 on 800122 ORIER.B H Region 1. Philadelphia, Office of the Director 80/02/07 2pp
- --8004170307 Special Public Enforcement Meeting Rept 50-334/80-04 on 800122 Major areas discussed licensee actions pursuant to 791206 order modifying license BECKMAN.D A. MCCABE.E.C. Region 1. Philadelphia, Office of the Director 80/02/05 4pp
- 8004100059 Forwards IE Insp Rept 50-334/79-28 on 791210-14 Np noncompliance noted MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/02/11
- ~8004100068 IE Insp Rept 50-334/79-28 on 791210-14 No noncompliance noted Major areas inspected security plan.program audit, organization, physical barriers, lighting, access control & alarm stations Details withheld (ref 10CFR2 790)
 DEWLIN.J W. Region 1. Philadelphia. Bafeguards Branch LADUN, Region 1. Philadelphia. Office of the Director 80/02/07 ip
- 8004070195 Ack receipt of 800127 itr updating corrective action schedule re IE Insp Rept 50-334/79-18
 ORIER.B H Region 1, Philadelphia, Office of the Director 80/02/26 ip
- --8004070197 Responds to NRC 791219 ltr re violations noted in IE Insp Rept 50-334/79 18 Requests extension until 800401 for compliance re Item 79-18-05 DUNN-C N Duquesne Light Co 80/01/29 1p
- B004100347 Ack localpt or B00213 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-334/79-26 SMITH O H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch B0/02/27 tpp
- --8004100358 Responds to NRC 600118 ltr re violations noted in IE Insp. Rept 50-334/79-26 Corrective actions type of respiratory equipment cited in violation has been removed from general issue

 DUNN, C N Duquesne Light Co 80/02/13 3pp
- ---B004100373 Forwards IE Insp Rept 50-334/79-26 on 791126-29 & notice of violation SMITH, G H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch B0/01/18 2pp
- --8004100382 Notice of violation from insp on 791126-29 * NRC Regional Offices 80/01/11 ip
- --8004100391 IE Insp Rept 50-334/79-26 on 791126-29 Moncompliance noted contrary to procedures, respirators issued to personnel not on training list
 THONUS, L. H. NRC Regional Offices 80/01/11 6pp

- 8004090009 Requests extension until 800331 for response to IE Bulletin 79-01B. Items 1,2 % 3 Station shut down for refueling & mods Delay would not cause undue risk to safety & health of public DUNN: C N Duquesne Light Co 80/02/29 1p
- 8004150221 Submits interim rept re IE Bulletin 79-14 Drawing verification effort being compared against basis of seismic reanalysis Results indicated very good correspondence between as-built & as-installed sys
 DUNN, C.R. Duquesne Light Co. 80/02/29 2pp
- 8004110070 Responds to 791205 & 800222 ltrs re Enforcement Conference 50-334/79-21 Discusses responsibilities & authorities of general superintendent of power stations dept & director of nuclear operations GRIER.B H NRC Regional Offices 80/03/03 2pp
- 8004110160 Submits response to 1E Bulletin 79-27 re loss of class IE &/ar Non-Class IE instrument & control power sys bus during operation No mods necessary re alarm sys & emergency procedures Surficient instruments exist for coolant break DUNN,C N Duquesne Light Co 80/03/04 2pp
- B004040159 Ack receipt of 800227 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-334/79-24 GRIER.B H Region 1, Philadelphia. Office of the Director 80/03/11 ip
- ---8004040165 Responds to NRC 800201 ltr re violations noted in IE Insp Rept 50-334/79 24 Corrective actions plant maint manual, Chapter 1. Section A 7 revised to insure that current procedures available for safety-related activities DUNN.C N Duquesne Light Co 80/02/27 5pp
- --8004040168 Forwards IE Insp Rept 50-334/79-24 on 791105-09.ii-26 & 1203-14 & notice of violation BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch SD/02/01 2pp
- --8004040170 Notice of violation from insp on 791105-09, 11-26 & 1203-14 * Region 1, Philadelphia. Office of the Director 80/01/30 3pp
- --8004040177 [E Insp Rept 50-334/79-24 on 791105-09,11-26 & 1203-14 Noncompliance noted use of unapproved data for calibr of reactor protection instrumentation BECKMAN.D A. Region 1. Philadelphia. Office of the Director MCCABE.E C. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/20 22pp
- 8004110005 Ack receipt of 800229 ltr requesting extension of IE Bulletin 79-01D data submittal date Requests 24-h notification of any deviation from understanding that info will be completed by 800331 % received no later than 800403 GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 lp
- 6004150264 Forwards IC info Notice 80-12, "Instrument Failure Causea Opening of PORV & Block Valve " No specific action or response necessary ORIER, BH Region I, Philadelphia, Office of the Director 80/03/31 ip
- 8004090048 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, Bit Region I, Philadelphia, Office of the Director 80/04/01 1p
- B004110131 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Befective CAM Followers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/04/02 ip
- 9004240302 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required ORIER.8 H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180167 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/03 ip
- 8004230408 Forwards IE Builetin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe "Action required, ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 ip

- 8004180144 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- 8004030196 Forwards "NPDES Discharge Monitoring Rept for Feb 1780 " MODRE, Q W Duquesne Light Co 80/03/31 ip
- --8004030197 "NPDES Discharge Monitoring Rept for Feb 1980 "
 # Duquesne Light Co 80/02/29 12pp
- 8004070277 Forwards "Rept of Facility Changes, Tests & Experiments for 1979" WDDLEVER, E. J. Duquesne Light Co. 80/03/31 2pp
- --8004070280 "Rept of Facility Changes, Tests & Experiments for 1979 "
 * Duquesne Light Co 80/03/31 App
- 8004210261 Forwards "Offsite Dose Estimates Third & Fourth Quarters, 1979"
 DUNN.C N Duquesne Light Co 80/04/15 1p
- ---8004210266 "Offsite Dose Estimates Third & Fourth Quarters, 1979 "
 * Duquesne Light Co 80/04/15 2pp
- B004290354 Forwards monthly operating rept for Mar 1980 DUNN: C N Duquesne Light Co 80/04/25 ip
- --8004270355 Monthly operating rapt for Mar 1980 TIMKO.D R Duquesne Light Ca 80/04/02 ip
- 6 Reportable occurrences, LERs & related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT,X W Region 2, Atlanta, Office of the Director 77/08/12 ip.
- 8004020002 RO 80-12/01T on 800312.uti) informed of noncompliance re channel check not performed since Jul 1976 Caused by deletion of requirement Surveillance reinitiated & further checks will be made during startup WERLING.J A Duquesne Light Co 80/03/12 2pp
- B004220997 RO 80-025/01T during tank mod project, field engineers reported that weld on 12-inch norile penetrations to reflueling storage tank does not conform w/manufacturer design Cause unstated Add penetrations being checked WERLING J A Duquesne Light Co 80/03/16 1p
- 8004030198 RO 80-17/01T on 800926,5&W advised that reanalysis of seismic pipe stress on main steam piping indicates that for certain OBE conditions, long-term criteria allowable stress levels may be exceeded WERLING, J A Duquesne Light Co 80/03/26 2pp
- 8004030i9i RO 80-18/0iT on 800326, during portable fire pump surveillance test, section of fire main failed During pump testing sus, pressure was maintained w/difficulty Caused by rupture in fire main header Rupture isolated, sys restored WERLING, J. A. Duquesne Light Co 80/03/27. 2pp
- 8004070341 Forwards LERs 80-012/01T-0 & 80-016/03L-0 WERLING, J A Duquesne Light Co 80/03/31 2pp
- --8004070346 LER 80-012/01T-0 on 800312, emergency shutdown panel auxiliary feedwater flow instrumentation readings were deleted from surveillence testing Caused by meter reading zero in standby
 WERLING, J. A. Duquesne Light Co. 80/03/31 ip
- --8004070375 LER 80-016/03L-0 on 800311, while testing battery charger 2, ac input breaker tripped Caused by 100se control wiring Loose wires resoldered HERLINO, J A Duquesre Light Co 80/03/31 1P
- BOO4110385 RO. on BOO225, two frequencies on peak shock annunciator sysactuated visual alarms Cause unknown Problem w/70% (OBE) visual alarms may have been caused by reed switches or alarm circuitry Investigation is continuing WERLINO. J A Duquesne Light Co 80/04/03 2pp

- GOO4140329 RO 80-22/OIT on 800407/during operational Mode 5.complete loss of RHR flow occurred during attempt to increase flow Operating procedure changed to require venting RHR during flow increase WERLING, J.A. Duquesne Light Co. 80/04/OB. 2pp
- 8004140381 RO 80-022/01T on 800407.W/plant in operational Mode 5 W/ steam generators drained 5 RCS level at mid span in loops, complete loss of RHR flow occurred uhile attempting to increase flow Pumps vented 5 transmitter calibr checked WERLING, J A Duquesne Light Co 80/04/08 2pp
- 8004150516 Forward's LERs 80-017/017-0,80-018/017-0 & 80-019/03L-0 WERLING, J A Duquesne Light Co 80/04/08 2pp
- --8004150529 LER 80-017/01T-0 on 800326, reanalysis of seismic pipe stress of main steam piping inside valve house for OBE lang-term criteria showed, for some conditions, allowable stress level may be exceeded in headers ror main steam relited valves HERLING, J A Duquesne Light Co 80/04/08 2pp
- --8004150534 LER 80-018/017-0 on 800326, plant operators were testing temporary fire pump when section of fire main failed Caused by piping failure Failed section of piping replaced WERLING. J A Duquesne Light Co 80/04/08 2pp
- --8004150545 LER 80-019/03L-0 on 800310,while steam flushing,crack found in channel head of liquid waste evaporator bottoms heat exchanger Caused by equipment failure,probably due to chioride stress cornosium Sleeve welded over channel head WERLING, J A Duquesne Light Co 80/04/08 2pp
- B004230217 RO B0-022/01T on B00407, complete loss of RHR flow occurred when plant operators were attempting to increase RHR flow from 1,000 gpm to 5,000 gpm Operating procedure was modified to require venting at all times during evolution HERLING, J A Duquesne Light Co 80/04/08 2pp
- 8004170223 RO 80-023/01T during operational mode 5.w/steam generators & RCS level at mid-span in loops.complete loss of RHR flow occurred while plant operators were increasing heat exchanger flow Procedure rewritten
 WERLING.J A Duquesne Light Co 80/04/11 2pp
- B00423020B RO B0-023/01T on B00411, w/steam generators drained & RCS level at mid-span in loops, complete loss of RHR flow occurred Cause under investigation Problem may be connected w/deficiency in as-built piping layout WERLING, J A Duquasna Light Co B0/04/11 2pp
- 8004240385 RO 80-025/01T during tank mod project, field engineers reported that weld on 12-inch nozzie penetrations to refueling water storage tank does not conform w/manufacturer design Addi penetrations are being checked WERLING, J A Duquesne Light Co 80/04/16 2pp
- 8004290503 Forwards LER 80-022/017-0 WERLING, J. A. Duquesna Light Co. 80/04/22 2pp

V Operator Elaminations

8004070048 Denies util 800304 request for administering written examinations who f 860518 % delaying oral operating maintainns until Jul 1980 due to lack of reactivity manipulations

COLLINS.P F Operator Licensing Stanch 80/03/19 2pp

DOCKET 50-335 ST LUCIE PLANT, UVIT 1

- F Security, medical, emergency & fire protection plans
- 8004070279 Notifies of intention to use Kerite cable in underground duct bank sys for replacement of existing cross-linked polyethylene cables 3 mods to existing sys NRC approval of Kerite for use on Unit 2 also applies to Unit 1 UHRIGIR E Florida Power & Light Lo 80/03/31 2pp
- 8004140229 Informs that thermal/rute-of-risc fire detectors, instead of automatic early warning fire detectors, will be used to implement Section 3.13.2 of safety evaluation supporting Amend 33 to License BPR-67
 UHRIG.R E Florida Power & Light Co 80/04/09 1p
- I Financial information
- 8004150406 Forwards Annual Financial Rept 1979
 UHRIG.R E Florida Power & Light Co 80/04/08 1p
- --8004150411 Annual Financial Rept 1979 * Florida Power & Light Co 80/02/08 72pp
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit into from plants to Bethesda Operations Ctr EISENHUI, D G Division of Operating Reactors 80/09/12 5pp
- --800403011B "Nuclear Data Link Specs"

 # Division of Operating Reactors 80/02/21 28pp
- 8004110510 Provides addl info re implementation of requirements set forth in Item 2 1 7a of NUREG-0578 Requests response by 800501 indicating commitment to install safety-grade sys prior to 810101 EISENHUT, D G Division of Operating Reactors 80/03/27 2pp
- 8004160180 Requests response to encl Lessons Learned Task Force Category A Items from 800324 & 25 review by 800401 Schedule for qualification of valve position indication circuits should be provided REID-R W Operating Reactors Branch 4 80/03/27 5pp
- 8004190151 Forwards EIA supporting amend to License DPR-67, deleting certain water quality requirements & revised ETS pages for Sections 2 % 4.App B
 LEAR.0 Environmental Specialists Branch 80/04/01 2pp
- --B004IS0154 EIA supporting amend to License DPR-67, deleting certain water quality requirements from App B ETS
 * Office of Nuclear Reactor Regulation B0/04/01 12pp
- --8004150156 Revised Section 2 & 4 ETS pages for License DPR-67, deleting certain water quality requirements from App B
 * Florida Power & Light Co 80/04/01 4pp
- 8004080386 Responds to NRC 800327 ltr rp Lessons Learned Task Force short-term requirements forwards info re valve position indication, instrumentation for inadequate core cooling, containment isolation & auxiliary feedwater flow indication UHRIG,R E Florida Power & Light Co 80/04/03 18pp
- 004150341 Forwards application for renewal of NPDES Permit FL0002208 UHRIO,R E Florida Power & Light Co E0/04/03 110pp
- 204230461 Forwards proposed Tech Spec changes, increasing combined secondary containment bypass leakage rates & intake of outside air into control room
 UHRIO.R E Florida Power & Light Co 80/04/18 2pp
- B004230464 Proposed Tech Spec changes; increasing combined secondary containment bypass leakage rates & intake of outside air into control room * Florida Power & Light Co 80/04/18 8pp

- 8004280269 Responds to NRC 800410 Itr requesting that info re use of NUKER 750 be provided by 800530 Technical basis for use of NUKEM 750 as qualified cault requested from Ameron Info will not be available by 800570 Submittal expected 800730 UHRIG.R E Florida Power & Light Co 80/04/22 ip
- O Inspection reports, IE Bulletins & correspondence
- 8004090344 Forwards 1E Bulletin 80-03, "Loss of Charcoal From 6td Type 1; Two-Inch, Tray Adsorbet Cells " Action required 0'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/02/06
- 8004100178 Forwards IE Insp Rept 50-335/80-03 on 800122-24 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/19 2pp
- ---B004100182 IE Insp Rept 50-335/B0-03 on B00122-24 No nancompliance noted Major areas inspected small break loss of coolant procedures & training & followup on praviously identified (tems UPRIGHT: C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch JUHNSON, A H, MCHENRY, T J Region 2, Atlanta, Office of the Director B0/02/19 App
- 8004280233 Forwards IE Insp Rept 50-335/80-02 on 800219-22 No noncompliance noted LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/03/10 2pp
- --8004280241 IE Insp Rept 50-335/80-02 on 800219-22 No noncompliance noted Major areas inspected operations review, facility tours, LER review & IE builetin review MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch DYER, J A, ELROD,S A Region 2, Atlanta, Office of the Director 80/03/07 4pp
- 8004230537 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from STD Type 11 Two-Inch Tray Adsorber Cells" In-house sys have shown no screen sagging or charcoal loss problems since installation in 1974 according to periodic testing UHRIG:R E Florida Power & Light Co 80/03/26 2pp
- 8004150517 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31 200
- 8004080619 Forwards IE Circular 80-05, "Emergency Diesel Conerator Lubricating Dil Addition & Onsite Supply " No written response required U*REILLY. J P Region 2. Atlanta, Office of the Director 80/04/01
- 8004150081 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required O'REICLLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02 200
- 8004240260 Forwards JE Info Notice 80-14, "Safety Suggestions From Emplayees" No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004180321 Forwards (E Circular 80-07, "Problems W/HPCI Turbine Oil Bys "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 20p
- 8004230165 Forwards IE Bulletin 79-03A "Longitudinal Wald Defects in AEME 8A-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004180417 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07 200
- 8004300577 Updates 800304 response to IE Bullstin 79-018. "Environ Qualification of Class IE Equipment "Info re Item 7 a will be forwarded by 800601 Info re Item 7 b will be forwarded by 800731 UHRIGR E Florida Power & Light Co 80/04/09 ip

DOCKETED ITEMS

- R Periodic operating reports & related correspondence
- 8004240368 Forwards monthly operating repts for Mar 1978 SCHMIDT.A D Florida Power & Light Co 78/04/07 1p
- --8004240374 Monthly operating repts for Mar 1978 CHILSON, V T Florida Power & Light Co 78/04/06 13pp
- 8004240448 Forwards monthly operating repts for Apr 1978 8CHMIDT, A D Florida Power & Light Co 78/05/06 ip
- --8004240452 Monthly operating repts for Apr 1978 CHILBON, V.T. Florida Power & Light Co. 78/05/06
- 8004240350 Forwards monthly openating repts for May 1978 SCHMIDT, A D Florida Power / Light Co 78/06/03 ip
- --B004240356 Monthly operating repts for May 1978 CHILSON, V T Florida Power & Light Co 78/06/03
- 8004240470 Forwards monthly operating repts for June 1978 8CHMIDT, A D Florida Power & Light Co 78/07/01 ip
- --8004240474 Monthly operating repts for June 1978 CHILSON, V T Florida Power & Light Co 78/07/01 1400
- 8004240455 Ferwards monthly operating repts for Jul 1978 SCHMIDT, A D Florida Power & Light Co 78/08/10 ip
- --B004240459 Monthly operating repts for Jul 1978 CHILSON,V Y Florida Power & Light Co 78/08/10 1200
- 8004240359 Forwards monthly operating repts for Aug 1978 BCHMIDT, A D Florida Power & Light Co 78/09/04 1p
- --8004240363 Monthly operating ropts for Aug 1978 CHILBON V T Florida Power & Light Co 78/09/04 13pp
- 8004240443 Forwards monthly operating repts for Sept 1978 8CHMIDT, A D Florida Power & Light Co 78/10/07 ip
- --8004240444 Monthly operating topts for Sept 1978 CHILSON, V T Florida Power & Light Co 78/10/07 13pp
- 8004240464 Monthly operating repts for Oct 1978 CHILSON, V T Florida Power & Light Co 78/11/04 1500
- 8004240436 Forwards monthly operating repts for Nov 1978 SCHMIDT, A D Florida Power & Light Co 78/12/06 1p

--8004240440 Monthly operating repts for Nov 1978 CHILSON, V T Florida Power & Light Co 78/12/06

- BOO424041B Forwards monthly operating repts for Dec 1978 SCHMIDT, A D Florida Power & Light Co 79/01/06 1p
- --8004240422 Monthly operating repts for Dec 1978 CHILSON, V T Florida Power & Light Co 79/01/06
- 8004230330 Forwards monthly operating repts for May 1979 SCHMIDT, A D Florida Power & Light Co 79/06/09, 1p
- -8004230332 Monthly operating repts for May 1979 CHILBON,V T Florida Power & Light Co 79/06/09 12no
- 8004230484 Forwards monthly operating repts for June 1979 SCHMIDT.A D Florida Power & Light Co 79/07/07 1p
- --8004230490 Monthly operating repts for June 1979 CHILBON,V T Florida Power & Light Co 79/07/07
- 8004230321 Forwards monthly operating repts for Jul 1979 SCHMIDT, A D Florida Power & Light Co 79/08/04 ip
- ---B004230326 Monthly operating rapts for Jul 1979 CHILBON, V T Florida Power & Light Co 79/08/04
- BOO4240443 Forwards monthly operating repts for Oct 1978 BCHMIDT, A D Florida Power & Light Co 78/11/04 ip

- BOO4180524 Forwards monthly operating repts for Jan 1980 BCHMIDT.A D Florida Fower / Light Co 80/02/09 1p
- --8004180528 Honthly operating repts for Jan 1980 CHILSON, V T Florida Power 1 Light Co 80/02/09
- 8004180529 Forwards monthly operating repts for Feb 1980 SCHMIDY, A.D. Florida Power & Light Co. 80/03/08 ip
- --8004180530 Honthly operating repts for Feb 1780 CHILBON, V T Florida Power » Light Co 80/03/08
- BOO4080257 Forwards "1979 Annual Operating Rept "
 UHRIG: R E Florida Power & Light Co 80/03/20
- --B004080265 "1979 Annual Operating Rept "
 * Florida Power & Light Co 80/02/29 49pp
- 8004040425 Forwards "Annual Monradiological Honstoring Rept.1979," Vols 1,2 b 3 Vol 1 summarizes abiotic monitoring for 1979 b Vols 2 b 3 discuss biotic monitoring UHRIG.R E Florida Power & Light Co 80/03/28 ip
- --8004040434 "Annual Nomadiological Monitoring Rept.1978," Vol 1. abiotic monitoring * Florida Power 9 Light Co 79/12/31 42pp
- --8004040443 "Annual Nomiadiological Environ Monitoring Rept.1979 "
 - Vol 2, biotic monitoring * Applied Biology, Inc. 80/02/29 100pp
- --8004040448 "Annual Nomadiological Environ Monitoring Rept. 1979, " Vol
 - 3. biotic menitoring

 * Applied Biology, Inc. 80/02/29 150pp
- 8004090217 Forwards "Annual Environ Radiological Monitoring Rept." for UHRIGAR E Florida Power & Light Co 80/03/31 1p
- --8004070217 "Annual Environ Radiological Monitoring Rept." for 1979 * Florida Power & Light Co 80/03/21 7pp
- BOO4180373 Forwards monthly operating tepts for Mar 1780 SCHMIDT.A D Florida Power & Light Co 80/04/05 ip
- ---8004180374 Monthly operating repts for Mar 1980 CHILBON.V T Florida Power & Light Co 80/04/05 9pp
- S Reportable occurrences, LERs , related correspondence
- 8004210441 PNO-77-1/4 an 7/1003, while conducting routine JUNE 1041 FAULT/F-174 on //1003/while conducting routine surveillance testing of station batteries, 125 volt dc bus 18 was inadvertently de-energized Cause unstated State of FL notified IE inspector is onsite KLINGER, O, NOLAN,F , SMIEZEK,J Region 2, Allanta, Office of the Director 77/10/03 ip
- 8004020381 Forwards RD 335-B-80-01 re surface temp rise UHRIG,R E Florida Power & Light Co 80/03/12 tp
- --8004020384 RG 335-8-80-01 on 800212, site analysis of thermograph data indicated surface temp rise, in area of mar ocean temp, in excess of 5 9 f on 800113 Possibly caused by thermograph maifunction Thermograph returned to venion
 × Fiorida Power & Light Co 80/03/12 2pp
- 8004030167 RQ 335-80-13 on 800314, while plant was in cold shutdown, field leads to excitors on both diesel generator units were found undersized Caused by design error Field leads will be replaced & permanent repair studied WETHY.C M Florida Power & Light Co 80/03/17 ip
- 8004090051 PND-II-80-042 on 800317.while investigating wiring overheat problem in 120-volt dc circuit.from voltage regulator to field of emergency disest generator A. licensee aboutified incorrect wire size Licensee will replace w/correct wires ELROD.S. MARTIN.R. Region 2. Atlanta. Office of the Director 80/03/17 ip
- 8004030282 Forwards LER 80-013/07T-0 8CHMIDT, A D Florida Power & Light Co 80/03/25 ip

- --8004030285 (ER 60-013/097-0 on 80031/, during trauble shooting re inability of A diesel generator to accept full design load, hot excitor leads to generator field found w/burnt insulation Caused by Giror in AE installation drawings SCHOPPMANN, M.A. Florida Power & Light Co. 80/03/25
- 8004240334 Forwards LER 80-015/03L-0 SCHMIDT,A D Florida Power & Light Co 80/04/15 1p
- --8004240343 LER 80-015/03+-0 on 800316, while shutdown, periodic integrated test of engineered safety features revealed 10 DG loading timers out of tolerance. 2A & 1B cooling fans not starting 5 shield bldg vent sys not opening SCHOPPMANN, M A Florida Power 5 Light Co 80/04/19 1p
- 80D4240369 Forwards LER 80-016/097-0 BCHMIDT,A D Florida Power / Light Co 80/04/16 1p
- ---BO04240375 LER 80-016/09T-0 on 800411, engineering evaluation determined that application of two Rosemount Model 1152 pressure transmitters resulted in reportable situation Caused by design problem Transmitters to be replaced SCHOPPMANN, M A Figural Power & Light Co 80/04/16 2pp
- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- 8004030268 Notifies that NRC review of util Feb 1980 revised safeguards contingency plan has been completed Forwards comments indicating need for addl info within 30 days Comments withheld (ref 10CFR2 790)
 21EMANN.D L Operating Reactors Branch 2 80/03/11 2pp
- 8004020408 Forwards "Feasibility Rept on Evacuation of Area Around Facility "
 CDUNGIL-W G Northeast Utilities 80/03/31 2pp
- --8004020416 "Feesibility Rept on Evacuation of Area Around Facility "
 One oversize drawing encl
 RODDERS,L M. PELL.8 M. Storch Engineers MOLLOY,E J. Northeast
 Utilities Service Co. 80/03/31 58pp

H General correspondence

- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Rediction efficient levels determined by 10CFR20 & App 1 to 10CFR50 Environ info available in stated LPPMS

 BALLARD
- I Financial information
- 8004080557 Responds to NRC 800305 ltr re adequacies of cash flows to meet possible retrospective premium payments & forwards 1979 annual repts for CT Light & Power Co. Hartford Electric Light Co & Mestern MA Electric Co
- --8004080564 Annual Financial Rept 1979
 * Connecticut Light & Power Co 80/03/14 24pp
- ~-8004080581 Annual Financial Rest 1979 * Hartford Flectric Light Co 80/03/14 24pp
- --8004080590 Annual Financial Rept 1979 * Western Mart Setts Electric Co 80/03/14 21pp

- --BG04030118 "Nuclear Data Link Specs"

 Division of Operating Reactors 80/02/21 28pp
- 8004070266 Forwards safety evaluation re interim actions taken to eliminate feedwater piping cracks, performed in response to IE Bulletin 79-13 REID.R W Operating Reactors Branch 4 80/03/13 2pp
- --8004070268 Sarety evaluation to interim actions taken to eliminate feedwater piping cracks performed in response to IE Dulletin 79-13 Repair method, nondestructive & visual insp & inherent toughness of piping matts are adequate # Commission 80/03/13 4pp
- 8004070138 Notification of 800318 meeting w/util in Bethesda.MD to discuss upcoming Cycle 4 reload CONNER.E L. Operating Reactors Branch 4 80/03/14 2pp
- B004040249 Forwards "Basic Safety Rept " Proprietary version withheld (ref 10CFR2 790) Affidavit previously submitted on B00229 & 760727 CDUNSILLIF OF Northeast Utilities B0/03/24 ip
- -~9004040254 "Basic Safety Rept " * Northeast Utilities 80/03/31 300pp
- 8004110528 Provides add1 into re implementation requirements set forth in Item 2 1 7a of NNREG-0578 Requests response by 800601 indicating commitment to install safety-grade sys by 810101 EISENHUT.D G Division of Operating Reactors 80/03/27 2pp
- B004070265 Submits info re direct indication of PDRV & safety valve positions Recent discussions w/vendor revealed difficulty w/800401 completion date Revised date of completion is B10401 COUNSIL/H O Northeast Utilities B0/03/28 2pp
- 8004030232 Application to amend License DPR-65, in response to conterns expressed in NRC 791011 ltr Revisions add surveillance requirement for auxiliary feedwater flow test after cold shutdown exceeding one month Affidavit encl CDUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/31 3pp
- --B004030290 Progused revisions to Tech Specs 3 7 1 2 & 4 7 1 2, adding surveillance requirement for auxiliary feedwater flow test after cold shutdown exceeding one month * Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/03/31 3pp
- BO040B0309 Outlines plans for Cycle 4 reload outage steam generator insp per Amend 52 to License DPR-65 Resolution of Cycle 3 startup commitments encl COUNSIL.N G Northeast Utilities B0/03/31 6pp
- BOO4070274 Discusses current intentions to submit design for providing sampling capacity for primary coolant & containment air by BOO429 Utils are currently engaged in finalizing design details Blight delay is required to optimize design COUNSIL.N O Connecticut Yankee Atomic Power Co
- 8004300078 Forwards comments re technical considerations leading to recommendations given to util at 791106 meeting about steam generator feedwater line repair Util presentation did not provide conclusive evidence that crack had not grown DENTON. H R Office of Nuclear Reactor Regulation 80/04/04 4pp
- BOO4170012 D(scusses problems w/implementation of Lessons Learned Task Force recommendation re automatic initiation of auxiliary feedwaters sys Requests NRC concurrence w/plan for implementing requirement during 1980 refueling outage COUNSIL, W.O. Connecticut Yankee Atomic Power Co. COUNSIL, W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) BO/04/ii. 4pp
- 8004220364 Submits info in support of continued operation w/sleeved guide tubes in Cycle 4 Anticipates that negligible guide tube sleeve wear will be measured COUNBILL #0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/15 6pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004090131 Forwards IE lnsp Repts 50~213/79-20,50~245/79-26 & 50~336/79-28 on 791127-30 & 1203-07 No noncompliance noted BHUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 60/02/08 2pg

- --B00409013B IE Insp Repts 50-213/79-20,50-245/79-26 & 50-336/79-28 on 791127-30 & 1203-07 No noncompliance noted Major areas inspected GA program implementation re GA/GC administration, design changes & mods & document control program BAUNACK, W H Region 1. Philadelphia. Reactor Operations Nuclear Support Branch NAPUDA, G Region 1. Philadelphia. Office of the Director E0/02/07 15pp
- 8004070213 Ack receipt of 800206 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-245/79-25 & 50-336/79-27 CARLSON,R T Region i, Philadelphia, Reactor Construction & 50-336/79-27 CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/28 ip
- --B004070218 Responds to NRC B00111 ltr re violations noted in IE Insp Repts 50-249/79-25 & 50-336/79-27 Corrective actions open trash can replaced w/covered trash can & no smoking signs posted at entryways to main control boards COUNSIL.W g , FEE.W F Northeast Utilities B0/02/06 2pp
- --8004070223 Forwards IE Insp Repts 50~245/79~25 & 50~334/79~27 on 791105-09 & notice of violation CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Bupport Branch BO/01/11 2pp
- --8004070226 Notice of violation from insp on 791105-09
 * Region i, Philadelphia, Office of the Director 80/01/08 le
- --B004070231 IE Insp Repts 50-245/79-25 & 50-336/79-27 on 791105-09 Noncompliance noted failure to fallow housekeeping procedure
 KOLTAY.P S Region 1. Philadelphia, Office of the Director
 SBNETER,S D Region 1. Philadelphia. Reactor Construction EBNETER, S.D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/08 8pp
- 8004090466 Forwards response to IE Builetin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Facility has two nonvital buses & four vital buses w/alarms responding to invertor trouble & emergency panel COUNSIL.W O Northeast Utilities 80/02/29 8pp
- 8004100417 Responds to IE Bulletin 79-01 Forwards partial listing of Class IE electrical sys, environ for component to operate & environ to which component has been qualified to operate Submittal scheduled for docketing by 800417 M/o encl COUNSIL, N O Northeast Utilities 80/03/03 4pp
- 8004180138 Forwards IE Insp Repts 50-245/79-29 & 90-334/79-30 on 791201-31 No noncompliance noted BRUNKER: E. J. Region i. Philadelphis, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --8004180147 IE Insp Repts 50-245/79-29 & 50-334/79-30 on 791201-31 No DOTHER 147 IN 185 Repts 30-285/79-29 on 7120-31
 noncompliance noted Major areas inspected control rooms & accessible portions of Unit 1 containment, reactor, turbine, radwaster, gas turbine generator & Intake bidgs KEIMIG.R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch ZIMMERMAN, R P , SHEDLOSKY, J T Region 1, Philadelphia, Office of the Director 80/02/29 10pp
- 8004030261 Submits response to IE Bulletin 80-04, re analysis of PWR main steam line break w/continued feedwater addition Efforts are in progress to finalize details of control grade automatic initiation of auxiliary feedwater scheme COUNSIL. W Q Rortheast Utilities 80/03/05 1p
- 8004150279 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER.B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- 8004090074 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Gil Addition & Gnsite Supply " No written response required GRIER, BH Region 1. Philadelphia, Office of the Director 80/04/01 ip
- 8004110156 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required ORIER.B.H Region I, Philadelphia, Office of the Director 80/04/02 ip
- 8004240317 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required ORIER.B.H Region 1. Philadelphia. Office of the Director 80/04/02 1p

- 8004180231 Forwards IE Circular 80-07. 'Problems W/HPCI Turbine 01' Sys " No written response required CRIER.B H Region 1. Philadelphia, Office of the Director 80/04/03 1p
- 8004230433 Forwards IE Bulletin 79-03A, "Longitudinal Reld Defects in ASME 8A-0312, Type 304 Stainless Steel Pipe " Action required GRIER. B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 8004180201 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Penetration Welds "Written response required GRIER. B H Region 1, Philadelphia, Office of the Director 80/04/07 1p
- R Periodic operating reports & related correspondence
- 8004040205 Forwards annual environ operating rept, "Monitoring Marine Environ of Long Island Sound" Requests rept be incorporated into proceedings for Unit 3 COUNSIL.N G Northeast Utilities 80/03/30 ip
- --8004040206 "Monitoring Marine Environ of Long Island Sound," annual rept. 1979

 * Northeast Utilities 80/03/31 40000
 - Northeast Utilities 80/03/31 400pp
- 8004150327 "Annual Environ Operating Rept. 1979 " 80/03/31 100pp Northeast Utilities Service Co
- BOO4220411 Forwards munthly operating rept for Mar 1980 OPEKA-J F Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/04/14 ip
- --8004220413 Monthly operating rept for Mar 1980 HOWLETT, G H Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/08 App
- S Reportable occurrences. LFRs & related correspondence
- 800407011B PNO-I-80-043 on 800318, one truck full of chlorine rail tank 00409011B PNU-1-BD-043 on BU031B one truck full of chlorine rail to car denailed at broken switch on licensee property Car presently located outside protected area, but is upright, intact. & stable Formulating plans to replace car on rail KEIMIG.R R, BRUNNER,E J Region I, Philadelphia, Office of the Director 80/03/18 2pp
- 8004010407 Forwards LER 80-007/03L-0 OPEKA, J F Northeast Utilities 80/03/27 1p
- --8004010417 LER 80-007/03L-0 on 800227, during reactor plant startup, condensate storage tank level fell below Tech Spec limit for less than 30 m;nutes Caused by excessive water demand from blowdown & regeneration requirements
 STRATMAN,R A Northeast Utilities 80/03/27 ip
- 8004010423 Forwards LER 60-006/03L-0 OPEKA.J F Northeast Utilities 80/03/27 ip
- --8004010429 LER 80-006/OSL-0 on 800310.w/charging pump 8 inoperable for replacement, charging pump C placed out of svc to replace failed pump packing Caused by natural end-of-life of packing due to wear Pump packing replaced CRISCIONE.V L Northeast Utilities 80/03/27 ip
- 8004090308 Forwards LER 80-008/03L-0 OPEKA. J F Northeast Utilities 80/04/02 lp
- --80040903il LER 80-008/03L-0 on 800303 during routine operations, plant computer analog input values became erratic rendering pulse counting position indication sys inoperable Caused by faulty analog input driver card Sys restored FOSTER, ER Northeast Utilities 80/04/02 ip
- 8004170224 Forwards LER 80-010/03L-0 OPEKA.J F Northeast Utilities 80/04/07 ip
- -8004170226 LER BD-010/03L-0 on 800310, during surveillance, control element assembly exhibited erratic position indication & was declared inoperable Caused by intermittent open conductor in cable or connector from reed switch # Northeast Utilities 80/04/09 ip
- BOO4170194 Forwards LER 80-009/03L-0 OPEKA: J F Northeast Utilities BO/04/10 ip

- --B004170199 LER 80-009/03L-0 on B0032L following plant trip from 100/power.A autiliary feed pump was found leaking excessively from gland packing Caused by natural end of life for pump packing Pump repacked CRISCIGNEL D. Northeast Utilities 80/04/10 19
- 8004180398 Forwards LER 80-011/031-0 OPEKA.J F Northeast Auclear Energy Co (subs of Northeast Utilities) 80/04/11 ip
- ---8004180404 LER 80-011/07L-0 on 800313, following full power plant trip.
 two broken saddle clamp bolts were found on hydraulic
 snubber hanger 490008 on MS lead to 4P turbine Caused by
 fatigue cracking due to high vibilation? shear on trips
 * Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/04/11 2pp
- 8004180408 Forwards LER 60-012/03L-0 OPEKA, J F Noitheast Utilities (60/04/11 10
- --8004(804)) LER 80-012/03L-0 on 8003)4, during routine power operation, hydraulic snubber on hanger 49000) found w/no visible fluid level Caused by seal deterioration due to high vibration Snubber replaced CROCKETT, J Nor Northeast Utalities 80/04/11 1p
- B0042206/0 Forwards LER 80-015/03L-0 OPEKA,J F Northeast huclear Energy Co (subs of Northeast Utilities) 80/04/18 1p
- --8004220679 LER 80-015/u3L-0 on 80032; following reactor trip, condensate storage tank level was below Tech Spec requirements Caused by gland seel header relief valve being stuck open, necessitating use of auxiliary feedwater sys STRATMAN, R A Northeast Nuclear Energy Co (subs of Northeast Ut(litios) 80/04/19 1p
- 8004280525 Forwards LER 80-013/03L-0 DPERA.J F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/18 Ip
- --8004280530 LER B0-013/03L-0 on 800320, while moving group 7 control element assemblies for axial shape under control, assembly 1 dropped into rully inserted position Caused by failure of timer module in coil power programmer Timer replaced BATES,R W. Northeast Utilities 80/04/18 ip
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8004030276 Notifies that NRC initial review of util 790904 safeguards contingency plan complete Requests add) info within 30 days in order to complete review info request withheld (ref 10CFR2 790) SCHWENCER, A Operating Reactors Granch 1 80/02/27 2pp
- 8004140236 Notifies that review of util fire protection safety evaluation adequately reflects consultant concerns A recommendations Concurs W/NRC that implementation of mods will be acceptable Cage-Babcock Associates, Inc 80/04/08 Ip
- B00414025B Responds to NRC request at B00326 & 27 meeting for emergency plans revised in accordance w/NUREQ-0454 North Anna emergency plan will be submitted on B00501 Surry plan will be submitted on B00602 Burry plan will be Submitted on B00602 BAUM.F A Virginia Electric & Power Co G0/04/08 1p
- G Adjudicatory correspondence
- 8004080418 Requests all mati sent to ASLAB re D Swanson 800225 ltr forwarding NRC statement on turbine disc cracking & continued operation, be sent to UCS Mati is relevant to UCS amicus curiee issue WEISS.E R Sheldon, Harmon & Weiss 80/03/04 1p
 - 1080692 Advises that VEPCO will install device to detect pinhole taks from expansion joints, per ASLAG opinion ALAB-578, Pages 1-66 Plans to install rubber jacket around joints to solve echnical problems
 .HRISTMAN, J N Hunton & Williams 80/03/12 2pp
- 8004010311 Response to ASLAD 800303 memorandum & order Recent info re turbine disc cracking will not change NRC estimates of turbine missile risks NRC will indicate whether changes are needed re testimony Questians re cracking sent to licensees SWANSON.D T Rearing Branch (80/03/24 2pp

- --8004010313 "Derivation of Turbine Disc Crack Growth Rates " Certificate of Svc enc)
 HAZELTON, W.S. Engineering Branch 80/03/21 17pp
- BOO42503B1 Forwards JM Schmerling BOO320 arfidavit & five other documents re technical info on turbine disc cracking in response to ASLAB BOO303 memorandum & order VEPCO revised written testimony may be ready in mid-Oct W
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning to preparedness, distributed as Board notification COSSICK. I V Office of the Esecutive Director for Operations 60/04/02 34pp
- 8004280211 Petition for review of ALAB-584 on grounds of being DOAZEDO211 Petition for review or ALAB-DB4 on grounds or being erroneous as matter of law Expansion of spent fuel storage pool should not be permitted prior to consideration of effects subsequent to Ol expiration Certificate of Svc encl DOUGHERTY.J B Ottomac Alliance DOUGHERTY.J B Citizens Energy Forum DOUGHERTY.J B Dougherty, J B 80/04/14 9pp
- H General correspondence
- BOO4040006 Requests immediate thatough & intensive investigation of util operation re rate control Documentation of homeowner kw usage & charges encl ALVAREZ, K D Affiliation Unknown BO/02/28 5pp
- BOO4020400 Forwards resumes of persons holding revised employment positions resulting from 800401 mgt reorganization to assist in review of proposed Tech Spec changes Also forwards job descriptions of positions Info withheld (ref Privacy Act) STALLINGS.C II Virginia Electric & Power Co 80/03/31 1p
- I Financial information
- BOO4010269 Forwards Annual Rept 1979
 BAUM.E A Virginia Electric & Power Co 80/03/27 ip
- --8004010275 Annual Rept 1979 * Virginia Electric & Power Co 79/12/31 32pp
- J Insurance & indomnity information
- 8004250355 Unsigned Amend 7 to Indemnity Agreement B-80.deleting Item 3 & substituting new info.effective 800411 SALTZMAR,J Antitrust & Indemnity Group 80/04/11 ip
- 8004180232 Forwards check in payment for NRC Invoice 46B-80 Payment attends indemnity agreement for OL through 810415
 SYLVIA, R B Virginia Electric & Power Co 80/04/14 ip
- 8004250387 Forwards Amend 7 to Indomnity Agreement 8-80 changing Them 3 re license numbers

 DAUM.E A Virginia Electric & Power Co 80/04/21 2pp
- BO04300436 Confirms B00425 teleon granting extension until B00515 to file info per guarantee requirements set forth in Alternative 5 of NRC 770615 ltr re implementation of certain provisions of 1973 amends to Price Anderson Act JOHNSON.B D Virginia Electric & Power Co B0/04/25 ip
- P Operating license stage documents & correspondence
- BOD4030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Nethesda Operations Ctr EISENHUT.D G Division of Operating Reactors BO/03/12 5pp
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors 80/02/21 28pp
- 8004010363 Application for amend to Liconse NPF-4 consisting of proposed Change 29 to Tech Specs re safety-related hydraulic snubbers
 STALLINGS.C M Virginia Electric & Power Co 80/03/31 2pp
- --8004010366 Proposed Change 29 to Tech Specs Table 3 7 4 for safety-related hydraulic snubbers
 * Virginia Electric & Power Co 80/03/3i 6pp

- 8004030234 Forwards add1 info re implementation of TMI-2 Lessons Learned Task Force short-term Category A requirements, based on NRC onsite review SYLVIA:B R Virginia Flactric & Power Co 80/04/01 78pp
- 8004080621 Advises that info requested in NRC 800227 ltr will be provided by 800509 SYLVIA.B R Virginia Flectric & Power Co 80/04/03 1p
- 8004210372 Application to amend License NPF-4.changing Tech Spec Surveillance Requirement 4 4 9 3 1 d to require testing of pressurizer power operated relief valves per ASME requirements for Category C valves Affidavit & fee encl FERGUBON.J H Virginia Electric & Power Co 80/04/16 3pp
- --B004210376 Tech Specs Change 32, proposing changes to Tech Spec Surveillance Requirement 4 4 7 3 1 d to require testing of pressurizer power operated relief valves per ASME requirements for Category C valves * Virginia Electric & Power Co B0/04/16 ip
- 8004230519 Forwards detailed schedule for completion of control room mods & training to familianize operators w/proposed changes SYLVIA.D R Virginia Clectric & Power Co. 60/04/21 5pp
- BO04300472 Forwards info re implementation of FM1 short-term Category A Lessons Learned Requirements Remaining info will be forwarded at later date SYLVIA.R R Virginia Electric & Power Co BO/O4/28 4pp
- G Inspection reports, IE Bulletins & correspondence
- 8004090398 Forwards IE Builetin 80-03, "Loss of Charcoal From Std Type II, Two-Inch. Tray Adsorber Cells" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06 20p
- BO040401B2 Forwards IE Insp Repts 50 338/80-02 & 50-339/80-02 on 800128-31 No noncompliance noted STDHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch B0/02/15 2pp
- --8004040194 IE Insp Repts 50-338/80-02 & 50-339/80-02 on 800128-31 No noncompliance noted Major areas inspected solid waste packaging & transportation & followup of worker concerns GIBSON.A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch EWALD, B C Region 2, Atlanta, Office of the Director 80/02/13 6pp
- 8004080122 Forwards IE Insp Repts 50-339/80-08 & 50-339/80-06 on B00206-08 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/02/25 2pp
- --8004080127 IE Insp Repts 50-338/80-08 & 50-339/80-06 on 800206-08 No noncompliance noted Major areas inspected IE Bulletin 77-14.

 "Seismic Analysis for As-Built Safety-Related Piping Bys "
 HERDTAR Region 2, Atlanta, Reactor Construction & Engineering Support Branch CCMPTON,R M Region 2, Atlanta, Office of the Director 80/02/21 App
- 8004090173 Forwards IE Insp Rept 50-338/80-01 on 800129-0201 No noncompliance noted 8TOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/26 2pp
- --8004090195 IE Insp Rept 50-338/80-01 on 800129-0201 No noncompliance noted Major areas inspected nonradiological environ protection reduirements including water quality monitoring, biological surveillance & general ecological mgt JENKINB.0 R Region 2, Atlanta, Fuel Facility & Materials Bafety Branch MCARTHUR.T C. CUNNINGHAM.A L. Region 2, Atlanta, Office of the Director 80/02/25 4p
- 8004240393 Forwards IE Insp Repts 50-338/80-07 & 50-339/80-05 on 800102-18,24-25 & 0131-0201 & notice of violation LEWIS:R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --8004240396 Notice of violation from insp on 800102-18,24-25 & 0131-0201 * Region 2, Atlanta, Office of the Director 80/02/28 2pp
- ---8004240398 IE Insp Repts 50-338/80-07 & 50-339/80-05 on 800102-18.24-25 & 0131-0201 Noncompliance noted failure to establish acceptance critorion for equipment tests

 KELL000.P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch KIDD8,M 8 Region 2. Atlanta, Office of the Director 80/02/28 10pp

- 8004080270 Submits interim response to 1E Bulletin 79-27, "Loss of Non-Class IE Institumentation / Control Power Sys Bus During Operation "Operator can be alorted to loss of power by combination of alarms or indications from equipment STALLINGS.C M Virginia Electric & Power Co 80/03/07 4pp
- 8004080356 Submits response to IE Bulletin 79-018 re environ qualification of Class IF equipment Requested Master list will be ready by 800415 Equipment test repts in progress Review of facility svc conditions ready by 800
- BOO4150164 Forwards response to IE Bulletin 80-03 re charcoal adsorber cells North Anna charcoal adsorber cells in use do not have potential for loss of charcoal No evidence of degraded cells has been noted during recharging at Surry STALLINGS, C.M. Virginia Electric 3 Power Co. BO/03/21 7pp
- 8004110547 Forwards evaluation of licensee responses to IE Bulletins 79-06A 2 79-06A. Revision i provided by util 790426.0629 & 1015 ltrs Appropriate actions have been taken to meet requirements of bulletins SCHWENCER.A Operating Reactors Branch 1 80/03/25 16pp
- 8004030210 Responds to NRC 800314 itr re violation noted in IE Insp. Repts 50-338/80-05 & 50-339/80-04 Corrective actions. Procedure 1-PT-11 revised to ensure normal surveillance based on data from current plant status.

 STALLINGS, C.M. Virginia Electric & Power Co. 80/03/31 2pp
- 8004150540 Forwards IF Info Notice 80-12, "Instrument Failure Causes Upening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004070282 Forwards response to IE Bulletin 79-13, "Cracking in Feedwater Bys Piping" No indications of cracking found in any inspa performed All piping supports were verified operational & in conformance w/design critoria
 STALLINOS.C M Virginia Electric >> Power Co 80/04/01 8pp
- BOO4080652 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 200
- 8004150105 Forwards 1E Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 200
- B004240284 Forwards 1E Info Notice 80-14, "Safety Suggestions From Employees" No action required D'REILLY.J P Region 2. Atlanta. Office of the Director B0/04/02
- 8004080392 Forwards response to NRC 800307 ltm re violations noted in 1E Insp Repts 50-339/80-09 & 50-339/80-07 Corrective actions procedures written requiring periodic tests of health physics kits & verification of fire brigade presence SYLVIA, B R Virginia Electric & Power Co 80/04/03 3pp
- 8004180299 Forwards IE Circular 80-07, "Problems N/HPC! Turbine Gil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03 2nn
- 8004230108 Forwards IE Bulletin 79-03A "Longitudinal Held Defects in ASME 8A-312. Type 304 Stainless Steel Pipe" Action required D'REILLY. J P Region 2. Atlanta. Office of the Director 80/04/04 16
- 8004180401 Forwards JE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Writton response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07 2pp
- 8004110202 Ferwards response to IE Insp Repts 50-338/80-03 t 50-339/80-03 on 800212-15 Corrective actions conducted fire drills during first quarter of 1980 w/mproved records Personnel instructed re importance of attention to detail BYLVIA.B R Virginia Electric Fower Co 80/04/08 App
- 8004140446 Responds to IE Bulletin 79-13. Revision 2, "Cracking in Freedwater Sys Piping "Freedwater sys piping has been examined visually & inspected by magnetic particle No nonconformances or reportable indications were observed SYLVIA.B R Virginia Electric & Power Co 80/04/08 (p

474 or Heppins progress on erning IE Bulletin 79-14 Estimated or molection take row is (* 55) topiconformances identified to take have been reported by LEHs for Unit 1 f as deficiency repts for f, 17 Ξ 1+21-14 Ele *rin * Poter Co 80/04/18 1p

4227479 Firmards respinse to 191 807926 ltr re IE Insp Repts 50-338/ \odot 11 $^{\circ}$ 5 $^{\circ}$ 17 $^{\circ}$ 40-07 $_{\odot}$ \leftrightarrow 12 $^{\circ}$ 47 $^{\circ}$ 40 $^{\circ}$ 20 $^{$

- Periodic operating reports ? related correspondence
- FO 401 215 Forwards madicactive Effluent Release Rept Jul-Dec 1979 '
 TA Linux: H. Virginia Electric & Power Co. 80/04/01 1p
 - * 3340_02.3 Padicactive Effluent Release Rept Jul-Dec 1979 " GIERRT J [MLPPER, E CARTHAIGHT, N R Virginia Electric 5 Mouer fo CC704701 128pp
- Got 4170050 Forwards Annual Environ Operating Rept (Radiological) avilVIA B R. Vargania Electric & Pouer Co. 80/04/03 ip
- --83041/c352 Ar Jal Environ Operating Rept (Radiological) for 1979 " CLEERT J D HOPER, D M , SMITH, E R Virginia Electric & Power Co E3704703 175pp
- 6004170210 Forwards monthly operating rept for Mar 1980 & revised monthly operating rept for Feb 1980 StLVIA.B & Virginia Electric & Power Co. 80/04/14 ip
- -8004170211 Monthly operating rept for Mar 1980 MADISON W.R. Virginia Electric & Power Co 80/04/01 500
- -8034170212 Pevised monthly operating rept for Feb 1980 MADISGN W R Virginia Electric & Power Co 90/04/01
- S Reportable occurrences LERs & related correspondence
- 8304220394 Ph0-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made or inferior mati Cause unstated All utils w/pumps were notified tRC headquarters notified on 770812 WHITT.F U Region 2, Atlanta, Office of the Birector 77/08/12
- E004030242 PG E0-035/017-0 insps at Foreign plant revealed stress corrosion cracking in Westinghouse control rod guide tube support pin solution heat-treated at IB25 F Ultrasonic insps will be done

 Virginia Electric & Power Co 80/03/17 ip
- 8304010504 Forwards LER 80-035/99x-0 STALLINGS C M Varginia Electric & Power Co 80/03/20 tp
- -8004010505 LER 80-035/99x-0 on 800313. Westinghouse informed util of 004010505 LER 80-035/97X-0 on 800313. Westinghouse informed util potential for supplied control rod guide tube support pins to break due to stress corrosson cracking Caused by low solution heat treatment temp CARTKRIGHT W R Virginia Electric & Power Co 80/03/27 2pp
- 8004030219 Forwards LER 80-031/03L-0 STALLINGS.C M Virginia Electric & Power Co 80/03/28 1p
- --B004030221 LER 80-031/03L-0 on 800229 discovered Foxboro Model E17DM transmitter, installed to replace Rosemount model on casing cooling tank level transmitter, was not seismically qualified as required Caused by misinterpretation of data CARTMRIGHT, W. R. Virginia Electric & Power Co. 80/03/28 3pp
- 3004030225 Forwards LER 80-030/03L-0 STALLINGS.C M Virginia Electric & Power Go 80/03/28 ip
- --8004030226 LER 80-030/03L-O on 800227 during normal operation. B gaseous waste filter charcoal adsorber was operated for 934-h w/o lab analysis of carbon sample Caused by 720-h limit not being included in operator log after timer installation CARTHRICHT. W R Virginia Electric & Power Co 80/03/28 2pp
- 8004070307 Forwards LER 80-024/03L-0 CARTWRIGHT, H R Virginia Electric & Power Co 80/04/02 ip

- --8004070309 LER 80-024/03L-0 on 800304, during testing, heater for train safeguards area ventilation sys filter failed to energize rendering filter imperable Caused by dirty Hepa filter prefilter & improper location of high side sensor CARTWRIGHT, H. R. Virginia Electric & Power Co. 80/04/02
- 8004080528 Forwards LER 80-033/03L-0 SYLVIA,B R Virginia Flectric & Power Co 80/04/03 1p
- --8004080526 LER 80-033/03L-0 on 800303, during monthly verification of proper auxiliary feedwater sys valve lineup, discovered that position of valve MOV-FW1008 as written in procedure was incorrect Caved by typographical error in procedure CARTWRIGHT, W R Virginia Electric & Power Co 80/03/31 2pp
- 8004220646 Forwards LER 80-037/01T-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/04/16
- --8004220653 LER 80-037/01T-0 on 800403, at full power operation, ECCS was initiated due to full closure of main steam trip valve during part-stroke exercising of valve Caused by test boing performed at full steam flow CARTHRIGHT.W R Virginia Electric & Power Co 80/04/16 3pp
- 8004280549 Forwards LER 80-036/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/04/25 1p
- --8004280554 LER 80-036/03L-0 on 800330, during performance of preoperational test, control room bottled air sys inadvertently actuated & pressure depleted below Tech Spec limit Caused by improper procedure instructions CARTHRIGHT, W.R. Virginia Electric & Power Co. 80/04/25 2pp
- 8004280604 Forwards updated LER 80-016/01X-1 CARTHRIGHT, W R Virginia Electric & Power Co BO/04/25, 1p
- --8004280608 Updated LER 80-016/01X-1 on 800116, during calculation review, two svc water screen wash pump discharge lines overstressed Caused by use of chart method in previous load calculations Trunnion replaced CARTWRIGHT, W R Virginia Electric & Power Co 80/04/25 2pp
- DUCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 800404003i Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits add1 guidance to NUREO-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info ie auxiliary feedwater sys per Bulletins 4. Orders Task Force review of TMI-2 accident info should be provided as amend to application Submittal schedule should include HRC approval prior to issuance of DL W/encl.

 ROSS,D F Division of Project Management 80/03/10 \$3pp
- BOO4020247 Requests committment to perform described tests to obtain specific baseline hydraulic data w/core installed If accident occurs, similar data could be obtained & compared to baseline data to infer extent of core damage PARR.O D Light Hater Reactors Branch 3 80/03/13 3pp
- 8004030179 Notification of 800317-20 site visit to discuss matters re DROMERICK, A W Light Water Reactors Branch 3. 80/03/13 3pp.
- B00404042B Discusses potential design deficiencies in bypass, override & reset circuits of engineered safety features Outlines deficiencies, safety significance & staff position Requests review of protection sys design PARR.O D Light Water Reactors Branch 3 80/03/19 5pp
- 8004080396 Submits info to assist NRC in obtaining proper OL fee. Facility will be ready for fuel loading & low power testing by 800331 First license to be issued will be for fuel loading & low power testing at 5% of power PARR.O D Light Water Reactors Branch 3 80/03/18 2pp
- BOO4100318 Notification of 800320 meeting w/util in Bethesda, HD to discuss matters related to operation of facility. DROMERICK, A W Light Water Reactors Branch 3 80/03/18 3pp

- 8004140079 Summary of 800306 meeting w/util & Hestinghouse in Bethesda MD re cold shutdown of facility Safety evaluation permitting issuance of full power license will be able to be prepared based on applicant presentation DROMERICK.A W Light Water Reactors Branch 3 80/03/20 4pp
- 8004140033 Notification of 800328 meeting w/util in Bethesda.MD refacility control room design
 DROMERICK.A W Light Water Reactors Branch 3 80/03/25 3pp
- 8004180194 Advises that review of site is almost complete Forwards Supp 10 to draft SER, including disposition of residual pre-TMI issues & list of requirements for near-term DL Review identifies human factor deficioncies in control room DENTON, HR Office of Nuclear Reactor Regulation 80/03/26 7.
- --8004180160 Draft Supp 10 to SER,Part 1- "Review & Evaluation of Non-TMI-2 Issues" & Part II-"Review & Evaluation of TMI-2 Issues Related to Fuel Load & Low Power Test Program " * Office of Nuclear Reactor Regulation NUREG-0053 810 80/03/26 210pp
- 8004240092 Summary of 800320 meeting w/util in Bethesda, MD re importance of operator to safe operation
 DROMERICK, A Light Water Reactors Branch 3 80/03/26 4pp
- 8004010263 Forwards "Pressurizer Safety Valve or Power Operated Relief Valve Open" & "Loss of RCS Pressure," VEPCO proprietary versions
 STALLINGS.C M Virginia Electric & Power Co 80/03/28 1p
- BOO4140016 Notification of BO0404 meeting w/utils in Bethesda,MD to discuss applicants' progress & status in design review replant shielding & environ qualification of equipment for spaces/sys used in post-accident operations
 BUCKLEY.B C Light Water Reactors Branch 1 BO/03/31 7pp
- 8004030234 Forwards add1 info re implementation of TM1-2 Lessons Learned Task Force short-term Category A requirements.based on NRC onsite review SYLVIA.B R Virginia Electric & Power Co 80/04/01 78pp
- 8004030183 Forwards seven of nine test procedures outlined in 800319 ltr for NRC review of facility special test program Safety evaluation two remaining test procedures & revisions will be forwarded SYLVIA, B R Virginia Electric & Power Co 80/04/02 1p
- --B0040301B5 Bpecial Test Procedure 2-ST-6 "Cooldown Capability of emical & Vol Control Bys " Virginia Electric & Power Co 80/04/02 15pp
- --8004030190 Special Test Procedure 2-8T-7 "Forced Circulation Cooldown "
 * Virginia Electric & Power Co 80/04/02 3ipp
- --8004030173 Special Test Procedure 2-8T-8 "Natural Circulation Test"

 * Virginia Electric & Power Co B0/04/02 25pp
- --8004030195 Beecial Test Procedurg 2-8T-9 "Natural Circulation w/Simulated Loss of Offsite Power"

 * Virginia Electric & Power Co 80/04/02 30pp
- --8004030200 Special Test Procedure 2-ST-10 "Natural Circulation w/Loss of Pressurizer Hoaters "

 * Virginia Electric & Power Co 80/04/02 27pp
- --8004030205 Special Test Procedure 2-ST-11 "Effect of Steam Generator Secondary Side Isolation on Natural Circulation " * Virginia Electric & Power Co 80/04/02 24pp
- --8004030206 Apecial Test Procedure 28T-12 "Natural Circulation at Reduced Pressure" * Virginia Electric & Power Co 80/04/02 27pp
- 8004070261 Responds to 800402 telcon re availability & adequacy of procedural guidance for shift supervisor of unaffected reactor when companion unit is undergoing emergency Util commits to establishing procedures
 BYLVIA.B R Virginia Electric & Power Co 80/04/03 ip
- BOO4080312 Requests exemption from testing pressurizer power operated relief valves every three months Proposes alternate test program which will cycle valves once every three months & test at 18-month intervals during shutdown SYLVIA, IR R Virginia Electric & Power Co 80/04/03 !p

- 8004080621 Advises that into requested in NRC 800227 [tr will be provided by 800509 SYLVIA: B R Virginia Electric Pawer Co 80/04/03
- B004040302 Responds to NRC \u20040? telcon re availability & adequacy of procedural guidance for shift supervisor of unaffected reactor when companion unit undergoes emergency Commits to establishing procedures before criticality

 SYLVIA:B R Virginia Electric & Power Co 80/04/04 ip
- 8004290200 Discusses util application for low power GL Cracks found in reactor vessel noziles are within acceptance stds of Section XI of ASME boiler? pressure vessel code MRC evaluation of reactor vessel map & revised proposed GL entl DENTON, HR Office of Nuclear Reactor Regulation 80/04/08 22pp
- 8004210177 Forwards response to 800313 ltr re potential design deficiencies in bypass.override & reset circuits of engineered safety features addl info will be forwarded in response to IE Bulletin 80-06
 SYLVIA, B R Virginia flectiic * Power Co 60/04/19 3pp
- F Security, medical, emergency / fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr. has been postponed pending GAO clearance under Federal Repts Act GRIMES. R K Emergency Preparedness Task Force 80/03/11 4pp
- BOO4140236 Notifies that leview of util fire protection safety evaluation adequately reflects consultant concerns & recommendations Concurs w/NRC that implementation of mods will be acceptable BARNES,R D Gage-Babcock Associates. Inc. 80/04/08 1p
- 8004140258 Responds to NRC request at 800326 \$ 27 meeting for emergency plans revised in accordance w/NUREO-0654 North Anna emergency plan will be submitted on 800501 Surry plan will be submitted on 800602

 BAUM.E A Virginia Electric \$ Power Co 80/04/08 ip
- Q Adjudicatory correspondence
- 8004080418 Requests all matl sent to ASLAB re I) Swanson 800225 ltr forwarding NRC statement on turbine disc cracking & continued operation, be sent to UCS Matl is relevant to UCS amicus curiae issue WEISS.ER Sheldon. Harmon & Weiss GO/03/04
- 8004080692 Advisos that VEPCO will install device to detect pinhole leaks from expansion joints, per ASLAB opinion ALAB-570.Pages 64-66 Plans to install rubbel jacket around joints to solve technical problems CHRISTMAN, J N Hunton & Williams 80/03/12 2pp
- 8004010311 Response to ASLAR 800303 memorandum & order Recent info re turbine disc cracking will not change NRC estimates of turbine missile risks NRC will indicate whether changes are needed re testimony Questions re cracking sent to licensees BWANSON.D T Healing Branch 1 80/03/24 2pp

H General orrespondence

- H004040006 Request, immediate thousands a investigation of util operation is rate until lecumentation of homeowner kulusage? charges each ALVARFZ, K B Affiliation Unversion 80/02/28 5pp
- B30411055/ Acsponds to enti Av6130 ltr to President Carter orging authorization of all vil plant, to operate Discusses safety evaluation being prepared to reculity & present operation of Unit | Assistant Dirictor for Light Water Reactors 80/03/26 VARGA, S. A.
- 8004140093 Responds to 791701 lim to Prosident Carter expressing concern relactions taken by VA govt officials relative to licensing of facility forwards NRC lit to VA Atty Gen Coleman discussing NRC position W/o encl VARGA, S.A. Assistant Director for Light Water Reactors 80/03/26
- --B004140097 forwards for hRt response. North Anna Environ Coalition 791701 ltr to President tarter protesting pressure being ererted by Governor (Falkun? VA Atty Gen Coleman for Intensing of Facility SEAL/M M. President of Ht.? Executive Offices 79/12/26 2pp
- 8004140186 Responds to 791129 lits to Picsident Carter & NRC expressing concern to VA govt officials actions regarding licensing of facility Forwards NRC lit to Atty Gen Coleman discussing NRC position on Facility licensing I/A encl VARQA, S.A. Assistant Director For Light Water Reactors 80/03/26
- 8004140190 Forwards for NR/ response, Bit Scott itr to President Carter expressing concern re pressure being everted by VA govt officials for licensing of raility
 SEAL.M M. President of US f Executive Offices 79/12/26 2pp
- ~-B004[40195 Expresses concern re VA Governor.Atty Gen & Corp Commission actions for licensing of facility Govt officials favoring util interests over welfare of civilens Ltr dtd 791128 to "Goochland Gazette" encl
 SCOTT Affiliation Uninown 79/11/29 4pp
- 8004210028 Responds to 791211 ltm to President Carter requesting that facility be approved for operation Safety evaluation for facility being prepared Especied that low power discussions re facility will commence in late Mar 1960 VARGA.S A Assistant Director for Light Water Reactors 80/03/26
- ---B0042(QOJ) Forwards, for NRC response. L Brusso 791217 | tr requesting approval of facility for operation SEAL.M M. President of US? Executive Offices B0/01/14 2pp
- 8004020400 Forwards resumes or persons holding revised employment positions resulting from 800401 mgt reorganization to assist in review or proposed Tech Spec changes Also forwards job descriptions of positions Into withheld (ref Privacy Act) STALLINGS C.M. Virginia Electric & Power Co. 80703/31 ip

1 Financial intermation

- 8004010269 Forwards Annual Rept 1979

 BAUN, E.A. Virginia Electric * Power Co. 80/03/27 1p
 - 8004010275 Annual Rept 1979 * Viiginia Electric * Puwer to 79/12/31 32pp

Insurance / indemnity information

- 194250355 Unsigned Amend 7 to Indomnity Agreement B-80, deleting Itom 3 & substituting new inforerrective 800411 SALTZMAN J. Antitrust & Indomnity Group 80/04/11 ip
- 600425038/ Forwards Amend / to Indemnity Agreement B-80, changing Item 3 re license numbers

 BAUM E A Virginia Electric & Power Co 80/04/21 2pp
- GOO4300436 Confirms 800425 teleon granting extension until 800515 to file into per guarantee requirements set forth in Alternative 5 of NRC 770615 ltr is implementation of certain provisions of 1975 amends to Price Anderson Act JOHNSON B & Virginia Electric / Power Co 80/04/25 ip

- P Operating license stag locuments / correspondence
- R004250031 Summary or 800028 meeting woutil re results of human engineering audit of site confol room Certain deficient design features must be remedied prior to fuel loading CROMERICA.A W Light Water Reactors Branch 3 80/04/11 5pj
- 8004220641 Advises that rull response to 800219 request for change in review procedures for equipment qualification documentation will be submitted by 800804 BOORD AROWN, S C Virginia Electric & Power Co 80/04/15 ip
- 8004230337 Clarifies 800403 test program proposal re pressurizer power operated relief values Explains values stroke times & reason why test interval exceeded three-month requirement SYLVIA.B L Visginia Flectric & Power Co 80/04/18 2pp
- 8004230231 Forwards "Special (Low Power) Test Requirements & Administrative Controls" & special test procedures to loss of ac power, establishment of natural circulation from stagnant conditions & boron mixing / cooldown SYLVIA.B R Virginia Electric / Power Co 80/04/21 ip
- --8004230238 "Special (Low Power) Tests Requirements & Administrative Controls, App C

 * Virginia Electric ! Pawer Co 80/04/21 14pp
- --8004230246 Startup Test Procedure P-31-13, "Simulated Loss of All Onsite & Offsile Power" 4 Virginia Electric & Power Co 80/04/21 31pp
- 8004230255 Startup Test Procedure 2-ST 14. "Establishment of Natural Circulation from Stagnant Conditions" * Virginia Electric & Power Co 80/04/21 15pp
- --8004230260 Startup Test Procedure 2-ST-14, "Boron Mixing & Cooldown "

 4 Virginia Electric # Power Co 80/04/21 16pp
- 8004300472 Forwards info is implementation of TMI short-term Catatory A Lessons Learned Requirements Remaining into will be forwarded at later date SYLVIA:B R Virginia Electric & Powei Co 80/04/28 4pp
- O Inspection reports, If Bulletins & correspondence
- 8004090358 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type 11,Two-Inch, Itay Adsorber Cells" Action required O'REILLY, J.F. Region 2, Atlanta, Office of the Director 80/02/06
- 8004040182 forwards IF Insp Repts 50-338/80-02 & 50-339/80-02 on B00128-31 No noncompliance noted STDHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/15 2pp
- --8004040174 1E Insp Repts 50-338/80-02 \$ 50-339/80-02 on 800128-31 No 104440174 It Insp Repts 30-338780-02 & 30-33780-02 on BODISH-31 i noncompliance noted Major areas inspected solid waste packaging & transportation & followup of worker concerns GIBSON. A F Region 2. Atlanta. Fuel Facility & Materials Bafety Branch EWALD. S C Region 2. Atlanta. Office of the Director BO/02/13 6pp
- 8004090130 Forwards IE Insp Repts 50-339/80-01.50-404/80-01 & 50-405/80-01 on 800129-0201 No noncompilance noted STOMA.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004070134 IE Insa Repts 50-337/80-01,50-404/80-01 & 50-405/80-01 on 004090134 it hish Repts 30-339780-01:50-404780-01 & 50-405780-01 of 800129-0201 No noncompliance noted Major areas inspected erosion \$ junoff control, waste mgt, review of previous items & preoperational program JENKINS, O.R. Region 2, Atlanta, Fuel Facility & Materials Safety Branch CURNINGHM.A.L. Region 2, Atlanta, Office of the Director 80/02/19 3pp
- 8004080122 Forwards IE Insp Repts 50-338/80-08 & 50-339/80-06 on 800206-08 No noncompliance nabed BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 80/02/23 2pp
- --8004080129 IE insp Repts 50-338/80-08 & 50-339/80-06 on 800204-08 No noncompliance noted Major areas inspected IE Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Bys "HERDT, A Region 2, Atlanta, Reactor Construction & Engineering Support Branch COMPTON.R M Region 2, Atlanta, Office of the Director 80/02/21 App

- 8004240393 Forwards IE Insp Repts 50-338/80-07 & 50-339/80-05 on 800102-18.24-25 & 0131-0201 & notice of violation LEWIS,R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --8004240376 Notice of violation from insp on 800102-18.24-25 & 0131-0201
 * Region 2, Atlanta, Office of the Director 60/02/28 2pp
- --8004240378 IE Insp Repts 50-338/80-07 & 50-339/80-05 on 800102-18,24-25 & 0131-0201 Noncompliance noted failure to establish acceptance criterion for equipment tests KELLDOO.P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch KIDDS.M B Region 2, Atlanta, Office of the Director 80/02/28 10pp
- 8004080270 Submits interim response to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Operator can be alerted to loss of power by combination of alarms or indications from equipment STALLINGS.C M Virginia Electric & Power Co 80/03/07 4pp
- 8004080178 Discusses 800228 onsite meeting re NRC action plans for near-term OLs developed as result of TMI-2 accident IE Insp Rept 50-339780-12 encl LEHIG.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/19 1p
- --8004080183 IE Insp Rept 50-337/80-12 on 800128 No noncompliance noted Major areas inspected effect on plant safety re implementation of near-term OL action items presented in draft NUREG-0560 LEWIG.R C Region 2, Atlanta, Office of the Director KELLOGO.P J Region 2, Atlanta, Reactor Departions Nuclear Support Branch 80/03/19 3pp
- 8004150164 Forwards response to IE Bulletin 80-03 re charcoal adsorber cells North Anna charcoal adsorber cells in use do not have potential for loss of charcoal ho evidence of degraded cells has been noted during recharging at Surry STALLINGS,C M Virginia Electric & Power Co 80/03/21 7pp
- 8004030210 Responds to NRC 800314 ltr re violation noted in IE Insp Repts 50-338/80-05 & 50-339/80-04 Corrective actions Procedure 1-PT-11 revised to ensure normal surveillance based on data from current plant status BTALLINOS.C M Virginia Electric & Power Co 80/03/31 2pp
- B004150540 Forwards IE Info Natice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Rogion 2. Atlanta, Office of the Director 80/03/3i 2pp
- 8004070282 Forwards response to IE Bulletin 79-13. "Cracking in Feedwater Sys Piping " No indications of cracking found in any insps performed All piping supports were verified operational & in conformance w/design criteria BTALLINOS.C M Virginia Clectric & Power Co BO/04/01 Spp
- 8004080652 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01 2pp
- 8004150105 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240284 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004080392 Forwards response to NRC 800307 ltr re violations noted in IE Insp Repts 50-338/80-09 & 50-339/80-07 Corrective actions procedures written requiring periodic tests of health physics kits & verification of fire brigade presence SYLVIA,B R Virginia Electric & Power Co 80/04/03 3pp
- B004180279 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03

- 8004230109 Forwards If Bullets: 77-03A "Longitudinal Weld Defects in ASME 9A-312, Type 304 Stainless Steel Pipe" Action required D'REILLY: J.P. Region & Atlanta Office of the Director 80/04/04 To
- 8004100410 Forwards assessment of reheat cracks in reactor vessel nozile regions discussing lesults of ultrasonic insps Rept concludes that reheat cracks round in vessel noziles are within acceptance limits of ASME Code Section XI SLYVIA.B R Virginia Electric / Power Co 80/04/07 46pp
- 8004180401 Forwards [E Bulletin 80-08, 'Exam of Containment Liner Penetration Welds "Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 2nn
- 8004110202 Forwards response to JE Insp Repts 50-338/80-03 & 50-339/80-03 on 800212-15 Corrective actions conducted fire drills during first quarter of 1980 w/improved records Personnel instructed re importance of attention to detail SYLVIA.B R Virginia Electric / Power Co 80/04/08 Spp
- 8004140446 Responds to IE Bulletin 79-13. Revision 2, "Cracking in Feedwater Sys Piping " Feedwater sys piping has been examined visually b inspected by magnetic particle No nonconformances or reportable indications were observed SYLVIA, B R Virginia Electric / Power Co 80/04/08 ip
- 8004290151 Forwards IE lnsp Rept 50-339/80-16 on 800319 No noncompliance noted KENNA, W D Region 2 Atlanta, Safeguards Branch 80/04/10 2pp
- ---B004290157 IE Insp Rept 50-339/80-16 on 800316 No noncompliance noted Major areas inspected vital area alarm sys & communications equipment Details withheld (ref 100FR2 790)
 OILLEPIE.F P Region 2. Atlanta, Safeguards Branch MODRE, D E, HONELL, J C Region 2. Atlanta, Office of the Director B0/04/10
- 8004220397 Reports progress concerning 18 Builetin 79-14 Estimated completion date now is 800501 Nonconformances identified to date have been reported by LERs for Unit 1 & as deficiency repts for Unit 2
 BROWN, B C Virginia Electric 2 Power Co 80/04/18 ip
- 8004220493 Forwards response to NRC 800326 ltr re lF Insp Repts 50-338/80-11 & 50-339/80-09 on 800204-19 & 25-29 Mgt will re-emphasize requirements of special test program SYLVIA, B R Virginia Ejectric & Power Co 80/04/18 3pp
- R Periodic operating reports & related correspondence
- 8004030236 Forwards "Radioactive Effluent Release Rept Jul-Doc 1979" STALLINGS.C M Virginia Clectric & Power Co 80/04/01 tp
- ---800403023B "Radioactive Effluent Release Rept Jul-Dec 1979 "
 QIBERT, J D , HOPPFR, D M , CARTWRIGHT, W R Virginia Electric &
 Power Co 80/04/01 125pp
- S Reportable occurrences. LERs & related correspondence
- 8004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps afg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT, K W Region 2, Atlanta. Office of the Director 77/08/12 lp
- 8004020328 Interim deficiency rept re stress analysis of Class II lines in low & high head safety injection sys Several lines have not been stress analyzed for fluid temps below 70 F New support designs for pipe restraints will be implemented STALLINGS.C M Virginia Clectric & Power Co 80/03/14 Ppp
- 8004020336 Interim deficiency rept re potential control rod guide tube support pin breakage due to stress corrosion cracking Meetinghouse will conduct ultrasonic insps of guide tube support pins solution heat treated to less than 1800 F STALLINGS.C M Virginia Electric & Power Co 80/03/18 2pp
- 8004070019 Part 21 rept re potential for control rod guide tube support pins breaking due to stress coirosion cracking Results of support pin insp program & ongoing matis test program will determine corrective actions STALLINGS.C M Virginia Electric & Power Co 80/03/18 3pp

- R00414016/ Final derictioncy reptor stress analysis of certain lines in low // high head safety injection sys Affected pipe supports are being re-eramined under new loads Mods to existing design or three supports Jatelmaned unneccessary SYLVIA.8 R Virginia Electric S Power Co. 80/04/08 1p
- 8004150342 Final deficiency rept re potential for Nestinghouse control rod guide tube support pins to break due to corrosion cracking Mestinghouse evaluation concludes that operation not jeopardized Pins replaced w/higher temp resistant pins SYLVIA.B R Virginia Electric 2 Power Co 80/04/10 Ip
- 8004180446 final deficiency tept re improper installation of shaft fans for pump motors Caused by improper location of drive fans causing orcessive motor 5 motor bearing temps Inboard & authorard shaft drive fans interchanged by contractor SYLVIA.B R Virginia Electric & Power Co 80/04/14 1p
- 30042804/2 Final deficiency rept re improper installation of auxiliary feedwater pump motor shaft fans Both pump motors repaired by interchanging inboard 2 outboard shaft drive fans & undergoing eitensive testing SYLVIA.B R Virginia Electric & Power Co 80/04/14 lp
- T Hearing transcripts on non-antitrust matters
- 8004210315 Transcript of 800401 briefing in Washington, BC Pp 1-121
 Commission 80/04/01 122pp
- --B004210320 Forwards documented evaluation of control room review Organizational changes outlined in util 800322 ltr are under review Proposed safety engineering group blending function of STAs is acceptable DENTON, H R Office of Nuclear Reactor Regulation 80/03/31 10nn
- U Congressional/Executive Correspondence
- 8004140297 Responds to 800304 ltr orging prompt review of util application for low level license to facilitate immediate operation when general moratorium on new OLs is lifted Application review & SER preparation underway DIRCKS, N J. Office of the Executive Director for Operations 80/03/21 lp
- DOCKET 50-041 ENRICO FERMI ATOMIC POHER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 3004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment, 'providing guidence re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits add| guidance to NUREC-0598, "Interim Staff Position on Environ Qualification of Safaty-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- 8004020245 Forwards NRC BOGI28 & 0211 ltrs to GE discussing analysis of boiloff rates * mods to BWR control rod drive return line notifies to prevent cracking Mods should not be performed before issuance of NURGC-061F or w/o NRC guidance STDLZ,JF Light Water Reactors Branch i 80/03/07 2pp
- JO4110088 Notification of 800325 meeting w/util in Monroe.MI to visu safety-related piping sqs & select one for confirmatory piping analysis in GL application review KININER.L Light Water Reactors Branch 1 80/03/20 3pp
- RO04040278 Submits info re preservice examination of piping welds in partial response to NRC Question 121 \$3 in App C 5 to FSAR Util will provide complete response upon completion of preservice insp.
 TAUBER.H Detroit Edison Co. 80/03/28 10pp
- --8004040280 "Survey of Class 1 Piping & Components "
 + Sputhwest Research Institute 78/03/31 400pp
- 6004230193 Forwards request for add1 info re review of FSAR Schedule based on assumption that info will be available by 800422 FSAR should be amended to comply w/requirements listed in encl
 8TOL2.J F | 19ht Water Rescions Granch | 80/04/01 3pp

- 8004290165 Forwards request for addlines ore high density fuel storage for NRC review of FSAR FSAR should be amended to comply w/requirements listed in encl Names of codes & stds used in design of fuel racks should be provided STOLZ, J.F. Light Nate: Reactors Branch 1 80/04/10 4pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/11 App
- G Adjudicatory correspondence
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK, L V Office of the Executive Director for Operations 60/04/02 34pp
- 8004150464 Notice of appearance in proceeding Certificate of Svc encl TURK.S E Hearing Branch 1 80/04/14 2pp
- 8004150484 Forwards IE Insp Rept 50-341/60-02 on 800121-23 & 0211-12 & notice of violation Investigation resulted from ABC News allegations of QA program noncompliance
 TURK,S E Rearing Branch I 80/04/14 ip
- ---B004150489 Forwards IE Insp Rept 50-341/80-02 on 800121-23 & 0211-12 & notice of violation KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/11
- ---8004150490 Notice of violation from insp on 800121-23 & 0211-12 + Region 3, Chicago, Office of the Director 80/03/07 lp
- ---8004150496 IE Insp Rept 50-341/80-02 on 800121-23 & 0211-12
 Noncompliance noted personnel qualification requirements had
 not been established for onsite small bore pipe support
 design group & control for design work inadequate
 PHILLIP, G A . NURRLIUS, C E Region 3. Chicago, Office of the
 Director DANIELSON, D H Region 3. Chicago, Reactor Construction
 & Engineering Support Branch 80/03/07 7PP
- H General correspondence
- BOD4270111 FOIA request for info re NRC educational & training requirements for nuclear plant security force personnel & min requirements for weaponry & communication equipment use MURRAY. J. J. Affiliation Unknown BO744
- 8004290105 Responds to FOIA request for info re NRC educational & training requirements for nuclear plant security force personnel & min requirements for weaponry & communication equipment use forwards documents listed in App A Hyo encls FELTON J M Division of Rules and Records 80/04/15 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8004040022 Forwards IE Investigation Rept 50-341/79-26 on 790215-0302 & 800123 No noncompliance noted KEPPLER. J G Region 3. Chicago. Office of the Director 80/02/12.
- --8004040026 IF investigation Rept 50-341/79-26 on 79021-0302 & 800123
 No noncompliance noted Major areas inspected allegation that
 stainless steel pipe was improperly cut & installed by work
 crew which was under influence of drugs
 MARBH J J , NORELIUG. C E Region 3, Chicago, Office of the
 Director 80/02/04 5pp
- 8004040050 Forwards IE Insp Rept 50-341/80-01 on 800115-18 No namcompliance nated FIURELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/16 2pp
- --8004040052 IE Insp Rept 50-341/80-01 on B00115-18 No noncompliance moted Major areas inspected followup of previously identified noncompliances/unresolved items, project turnover electrical work activities & electrical records KMOP,R C , BARRICTT,P A , HUGHES,J Region 3, Chicago, Office of the Director 80/02/13 App
- 8004070130 Ack receipt of 800131 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/79-24 FIGRELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/06 lp

- --8004070135 Responds to NRC ltr re violations noted in IE Insp Rept 50-341/79-24 Corrective actions to be reported in detail to NRC inspectors on next visit Discussion of infraction encl HINES,E Detroit Edison Co 80/01/31 4pp
- 8004080645 Ack receipt of B00228 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/79-25 Notes supplemental info will be submitted re site GA & integration of engineers w/contractor personnel FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/24 ip
- --B0040B0649 Responds to NRC 800114 ltr re violations noted in IE Insp Rept 50-341/79-25 Corrective actions GA procedures re bypass of holding points revised to assure compliance HINES.E Detroit Edison Co 80/02/28 8pp
- B004;90172 Forwards IE Info Notice B0-12, "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary KEPPLER.J G Region 3. Chicago, Office of the Director B0/03/31
- 8004080708 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director BO/04/01
- 8004150040 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J Q Region 3, Chicago, Office of the Director 80/04/02
- B004180050 Forwards attachments to IC Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- 800422013B Forwards IE info Notice 80-14. "Bafety Suggestions From Employees" No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220354 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Oil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03 ip
- BOO4110036 Forwards IE Bulletin 80-07. "BWR Jet Pump Assembly Failure "
 No written response required
 KEPPLER, J. Q. Region 3, Chicago, Office of the Director BO/04/07
- 8004230245 Forwards IE Bulletin 79-03A, "Longitudinal Weid Defects in ASME 8A-312. Type 304 Stainless Steel Pipe" Action required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/04/07 in
- 8004220100 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/09 ip
- 8004300382 Forwards response to infractions noted in IE Insp Rept 50-341/80-02 on 800121-23 & 0211-12 Corrective actions calculations verified by Edison Design Engineering & changes are being made in procedure manual addressing design mods HINES.E Detroit Edison Co 80/04/22 10pp
- 8 Reportable occurrences, LERs & related correspondence
- 8D04040048 PND-III-80-054 on B00318, licensee informed Region 3 that Channel 7 news in Detroit,MI plans to televise B00321 interview w/site contractor employees re allegations of improper receipt insp of small bore pipe BARRETT.P A. KNDP,R C. FIDRELLI,G. Region 3. Chicago, Office of the Director B0/03/19 ip
- 8004020403 Interim deficiency rept re loose connections to terminals on QE receptacle pins for main reactor control panels. Number 20 wire to receptacles will be raterminated Final rept to be submitted prior to 800718 FAHRNER. H J Detroit Edison Co 80/03/21 ip

- G004110526 Ack receipt of G00228 interim dericiency rept re laminations in raceway hanger support skee! FIORLLLI.G Region 2, Atlanta, Office of the Director G0/03/27 lp
- B004230489 Final deficiency rept is limited heat number on A-36 steel Cause unstated Removal of supports initiated Deviation disposition request generated FAMMER.W J Detroit Foison Co. 80/03/28 1p
- BOO4;BO3Ot Ack receipt of BOO3(3) interim deficiency rept re final evaluation on misalighed assemblies not yet received from manufacturer. Tube Turns
 FIORELLI.O Region 3, Chicajo. Reactor Construction & Engineering Support Branch BO/04/01 ip
- 9004270053 Ack receipt of 800321 interim deficiency rept re termination to receptacies in main control room panels 601.602 & 603 Awaits rept suppl identifying apparent cause for loose connections & broken strands
 FigReLLI.G Region 3, Chicago, Reacto; Construction & Engineering Support Branch 80/04/14 ip
- DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC

 F Security, medical, emergency & fire protection plans
- BOD4240442 Bubmits evaluation of into submitted re fire protection for Train B switchgear room & requirements for addl mods Requests response within 20 days to indicate selected option or to schedule meeting for discussion Requirements encl SCHWENCER, A Operating Reactors Branch 1 80/03/18 12pp
- 8004140066 Responds to 791130 request that primary spokesman be physically located at state capitol bidg in event of incident Experience demonstrates that best info obtained from location as close as possible to reactor DENTON, H R Office of Nuclear Reactor Regulation 80/03/25 2pp
- 8004210014 Forwards safety evaluation for incomplete fire protection items identified in 780309 safety evaluation requiring add1 design details prior to implementation of mode Items resolved SCHWENCER, A Operating Reactors Branch 1 80/03/25 4pp
- --8004210018 Bafety evaluation for incomplete fire protection items identified in 760309 safety evaluation Items resolved * Operating Reactors Branch 1 80/03/25 App

9 Adjudicatory correspondence

8004020229 Motion suggesting filing of other parties' testimony on B00326 re adequacy of proposed modified complex & on 800317 re other subjs Proposes matters to be considered at each hearing session Certificate of Svc encl AXELRAD, M. JOHNSON, R. W. Portland General Electric Co. AXELRAD, M. Lowenstein, Newman, Reis, Azelrad & Toll 80/02/28 7pp

- 500.4230.273 Requests that entl 500.725 daily highlight be forwarded to Trojan Control Bidg Livensing Board & all parties on svc list for proceeding Certificate of Svc encl EISENHUT Is a Division of Uperating Reactors 80/04/02 App
- 800428000a Forwards CE Gaskin arridavit in response to ASLB 800311 prehearing conference request to review effects of drugs on security re proposed mods to control bldg Protection during V after mods provided adequately 9RAY, J R. Hearing Branch 1. 80/04/11. 2pp
- --8004280013 Afridavit stating that physical security measures provide adequate protection level during & after proposed mods to control bldg Prof qualification encl GASKIII.C E Reactor Safeguards Licensing Branch 80/04/10 App
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Lint Specs," study of digital communication sys to tiansmit info from plants to Dethesda Operations Ct: EISENHUT, D G Division or Operating Reactors 80/03/12 5pp
- ---B004030118 "Nuclear Data Link Specs "

 Davision of Operating Reactors B0/02/21 28pp
- BO04220087 Forwards request for addl info re containment purge generic issues Addl into needed to continue review of 790103 ltr SCHWENCER.A Operating Reactors Branch 1 80/03/18 4pp
- B004100307 Notification of B00327 meeting w/util & Westinghouse in Bethesda.MD to discuss 'M" computer sys & data transmission for onsite technical support ctr & to discuss short-term TMI-1 lessons learned implementation TRAMMELL.C Operating Reactors Branch ! 80/03/19 2pp
- S004010334 Forwards additinfo by Bethtel re A-frame support used in Plate 3 movement from equipment hatch in turbine bldg to position secured to plate support frames info assists in resolution of Item 1 of KS Herring & D Persinko testimony BRUEHL.D J Portland General Electric Co 30/03/27 3pp
- 8704020409 Destribes program for sample tube removal & subsequent analyses Submits background info re tube plugging BROEML, D.J. Portland General Electric Co. 80/03/27 49p
- 8004280296 Provides program description re removal of representative samples of steam generator tubes during Apr 1980 scheduled refueling outage.per util 791104 & 16 ltrs to NRC Bamples will be analyzed to determine cause of leak discovered BROEHL.D J Portland General Electric Co 60/03/27 4pp
- 8004080447 Submits info in response to NRC 800223 request re in-series check valves isolating high pressure RCS from LPIS piping Operating Test Procedure 2-4 will be modified to include second check valves for testing at refueling interval GOODMIN.C Pacific Oas / Electric Co 80/03/31 3pp
- 8004030240 Forwards Change Application 58 to amend License NPF-1. Tech Spec Section 4 (3 3.allowing 25% extension of surveillance interval for rod drop time CODWIN.C Portland General Electric Co 80/04/01 1p
 - 04030243 Change Application 58 to amend License NPF-1.Tech Spec Section 4 5 3 3-allowing 25% extension of surveillance interval for rod drop time GOODWHM.C Portland Coneral Electric Co GO/04/01 3pp
- JOC40803B8 Notifies that GA program for operations has been reviewed re diesel generator fuel oil Fuel oil has been included in GA program for some time GOODWIN.C Portland General Electric Co 80/04/01 ip
- GO040B0506 Forwards Mar 1980 Addendum 1 to "Rept on Testing of Composite Masonry Walls.Nov 1979 " Test results described in addendum indicate that 40 pai is appropriate principle tensile stress value at block core interface of wall GRUEHL.D J Portland General Electric Co BO/04/01 1p
- --8004080509 Addendum I to "Rept on Testing of Composite Masonry Walls "
 * Portland General Electric Co 60/04/01 Spp
- BO04100459 Forwards marked-up draft copy of proposed Tech Specs re second level undervoltage protection to expedite completion of safety evaluation concerning degraded grid voltage Also forwards corrected page of B00111 response GOODWIN, C Portland General Electric Cq B0/04/03 7pp

- 8004210005 Requests that licensee remit add1 sum per 10CFR170 requirements for Class III fee category re 791228 Tech Spec Changes revising 3 concentration & quantities Fee should be submitted within 15 days after receipt of 1tr MILLER.H O License Fee Management Branch 80/04/03 1p
- 6004300250 Forwards Amend 43 to License NPF-1, safety evaluation & notice or issuance & availability SCHMENGER.A Operating Reactors Branch 1 80/04/04 2pp
- --8004300255 Amend 43 to License NPF-1, changing Tech Specs to allow onetime two-day extension of surveillance interval for control rod drop times SCHWERCEP, A Operating Reactors Branch 1 80/04/04 5pp
- -8004300259 Safety evaluation supporting Amend 43 to License NPS-1
 * Office of Nuclear Reactor Regulation 80/04/04 2pp
- --8004300264 Notice of issuance & availability of Amend 43 to License NFF-1 SCHWENCER, A Operating Reactors Branch 1 80/04/04 2pp
- 8004180361 Forwards application to amond License NPF-1 authorizing mods to cable tray lests & containment fire suppression sys, submitted as Class III amend Certificate of Svc encl GODDWIN.C Portland General Electric Co 80/04/14 4pp
- --8004i80362 Application to amend License NPF-1 authorizing mode to cable tray test & containment fire suppression sus-submitted as Class III amend Util safety evaluation encl QQDDWIN.C Portland General Electric Co 80/04/14 5pp
- --B0041B0366 Proposed changes to Tech Specs 6 1 % 6 2 % Figure 6 2 1 for administrative controls % min shift crew composition * Portland General Electric Co B0/04/14 2pp
- 8004180466 Forwards responses, prepared by Dechtel, to NRC 800403 questions re-proposed mods to control bldg Also forwards proposed Tech Specs re-control bldg mod connection balts & proposed revision to Toch Spec, Section 5 7 1 BROCHL, D J Portland General Electric Co 80/04/14 12pp
- --8004180467 Proposed Tech Specs. Section 3/4 7 11, re control bldg mod connection bolts Addl responses to NRC 800403 questions re proposed mods to control bldg encl * Portland General Electric Co 80/04/14 23pp
- --B004180470 Proposed revision to Tech Spoc.Section 5 7 1,re seismic classification # Fortland General Electric Co B0/04/14 ip
- 8004220675 Forwards supplemental info re short-term Lessons Learned Task Force recommendations BROCHL.D J Fortland General Electric Co 80/04/15 26pp
- 8004300380 Forwards revised Section 2 1 6 a.to 800415 ltr. "Integrity of Sys Outside Containment Likely to Contain Radioactivity," re implementation of NUR-0-057B requirements Revisions reflect clairifications discussed in 800417 telcon BROEHL, D J Portland General Electric Co 80/04/25 3pp
- Q Inspection reports, If Bulletins & correspondence
- 8004180521 Forwards 1E Insp Rept 50-344/80-01 on 800102-31 & notice of violation CREMS, J L Region 5, Son Francisco: Office of the Director 80/02/21 2pp
- ---8004180523 Notice of violation from insp on 800102-31

 Region 5. San Francisco: Office of the Director 80/02/20 ip
- ---8004180527 IL Insp Rept 50-344/80-01 on 800102-31 Noncompliance noted failure to comply w/physical security procedure for securing of unsite vehicles
 STERNBERGOD II, MALHROG, M H Region 5, San Francisco, Office of the Director 80/02/20 Spp
- 8004010008 Forwards responses to 800215 notice of violation, notice of proposed imposition of civil penalties & request for identification & implementation of improvements in physical protection mgt Encls withheld (ref 10CFR2 790) WILLIAMS, J. L. Portland General Electric Co. 80/03/07 ip.
- B004100264 Ack receipt of B00227 itr Informing NRC of steps taken to correct violations noted in JE Insp Rept 50-344/80-02 CREWS, J L. NRC Regional Offices B0/03/13 1p

- --8004100273 Responds to NRC 800208 ltr re violations noted in IE Insp Rept 50-344/80-02 Corrective actions training assistant assigned to follow licensee reactivity manipulations & ensure documentation GOUDMIN.C Portland General Electric Co 80/02/27 3pp
- ---8004100282 Forwards IE Insp Rept 50-344/80-02 on 800121-23 & notices of violation & deviation CREWS.J.L. NRC Regional Offices 80/02/08 2pp
- --8004100288 Notice of violation from insp on 800121-23 * NRC Regional Offices 80/02/07 ip
- --B004100295 Notice of deviation from insp on B00121-23 * NRC Regional Offices B0/02/07 ip
- --B004100303 IE Into Rept 50-344/80-02 on 800121-23 Noncompliance noted failure to keep records of reactivity control manipulations & to prepare quarterly summaries of retraining programs STERNBERS,D M Region 5. San Francisco, Reactor Operations Nuclear Support Branch CARLSON,J C, JOHNSON,P H Region 5. San Francisco, Office of the Director 80/02/07 Spp
- B004070322 Forwards request for add1 info for review of util 791228 ltr re inservice insp program Response requested within 45 days SCHWENCER, A Operating Reactors Branch i 80/03/18 5pp
- 8004280080 Forwards IE Insp Rept 50-344/80-04 on 800201-29 No noncompliance noted CREMS, J. L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/03/24 Zpp
- --B0042800B7 IE Insp Rept 50-344/80-04 on 800201-29 No noncompliance noted Major areas inspected plant operations maintiphysical security refueling preparations & procedures
 STERNBERO,D M Region 5. San Francisco, Reactor Operations Nuclear Support Branch JOHNSTON,G W, MALMROS,M H Region 5. San Francisco, Office of the Director B0/03/20 App
- 8004150207 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of FORV & Block Valve " No specific action or response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/31 ip
- G004100104 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/01 1p
- 8004110113 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/02 1p
- 8004220046 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees " No action required ENGELKEN,R H. Region 5. San Francisco. Office of the Director 80/04/02 | 1p
- 8004180152 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Oil Bys " No written response required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/04/03 1p
- 8004080542 Provides schedule for 800426-0505 fuel insps during Cycle 2 refueling outage Insps will be performed by Heatinghouse & Util in spent fuel pool area Preliminary oral rept will be made prior to return to operation GODDHIN, C Portland General Electric Co 80/04/04 2pp
- 8004230376 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME BA-312,Type 304 Stainless Steel Pipe" Action required ENGELKEN,R H Region 5. Ban Francisco. Office of the Director 80/04/04 ip
- 8004220179 Forwards IE Bulletin 80-08, "Exam of Containment Liner Panetration Helds " Written response required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/04/07 in
- 8004300387 Responds to JE Info Notice 80-06, "Notification of Bignificant Events " Reporting guidance for events already defined in Reg Guide I 16 & specified in Tech Specs Need for new rulemaking unjustified BROEHL,D J Portland General Electric Co 80/04/25 3pp

- R Periodic operating reports % related correspondence
- 8004080442 Forwards monthly operating rept for Mar 1980 YUNDT,C P Portland General Electric Co 80/04/01 ip
- --B0040B0446 Nonthly operating tept for Mar 1780
 BAIR.G G Portland General Electric Co B0/04/01 4pp
- S Reportable occurrences, LERs & related correspondence
- B004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior maticals unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT,X W Region 2, Atlanta, Office of the Director 77/08/12 to
- 8004210224 PNO-77-203 on 771117.pips caps were discovered on sensing lines for all four wide range containment pressure sensors Condition existed since May 1977 Caps were removed from sensing lines immediately KLINCER, G. NOLANIF, SRIEZEK, J. Region 2. Atlanta, Office of the Director 77/11/18 ip
- BOO4150440 Forwards LER BO-004/03L-0
 YUNDT,C P Portland General Electric Co BO/04/07 2pp
- --BO04150442 LER 80-004/03(-0 on 800309, during periodic testing, control room emergency ventilation sys failed to have required flow rate Caused by personnel error Manual ventilation damper placed in throttled position Damper signs posted PERRY, J C Portland General Electric Co 80/04/07 1p
- 8004270471 Forwards LER 80-005/01T-0 YUNDT, C P Postland General Electric Co 80/04/22 2pp
- --8004290478 LER 80-005/01T-0 on 800411 during periodic surveillance testing, three of four main steam isolation valves failed to respond to manually initiated closing signal Caused by component fasture FERRY.J C Portland General Electric Co 80/04/22 ip
- T Hearing transcripts on non-antitrust matters
- 8004040063 Forwards licensee testimony on matters other than structural adequacy of complex testimony on structural adequacy of modified complex review of proposed design of mods for cantrol bldg & response to NRC request for suppl info JOHNSORN.R Partland General Electric Co 80/03/17 Jpp
- --8004040065 Testimony re matters other than structural adequacy of madified complex Prof qualifications of DJ Broehl, LJ Erickson, RC Anderson & LM White enc a RROEHL, DJ, ERICKSON, LW Pacific Oas & Electric Co ANDERSON, R C Dechtel Corp 80/03/17 150gp
- ---B004040067 Testimony re structural adequacy of modified complex Prof qualifications of RC Anderson.WH White.S Dimal & LC Chang-Lo encl ANDERSON,R C , BIHAL,S Bechtel Power Corp (subs of Bechtel Corp) WHITE.W W Bechtel Corp 80/03/17 105pp
- --8004040070 "Review of Proposed Mods for Control Bidg " HOLLEY,M J. Hanse, Nolley & Briggs, Inc. DRESLER,D. Wiss, Janney, Elstner & Association, Inc. 80/03/13 17pp
- --8004040073 Forwards supplemental info responding to NRC request at 800307 meeting re-structural considerations of proposed mods to control bldg BROEHL, D J Portland General Electric Co 80/03/17 50pp
- B004280002 Transcript of 800331 evidentiary hearing, Phase 2 in Portland, OR Pp 3640-3712
 Commission 80/03/31 277pp
- 8004190311 Transcript of Phase Two evidentiary hearing in Portland. ΩR Pp 3913-4123
 * Commission 80/04/01 210pp
- B004170314 Transcript of 800402 hearing in Portland OR Pp 4,300~4,453 * Atomic Safety and Licensing Board Panel 80/04/02 154pp,
- 8004170326 Transcript of 800403 evidentiary hearing.Phase 2.in Portland.OR Pp 4.454-4.497 * Atomic Safety and Licensing Board Panel 80/04/03 43pp

- 8004280003 Transcript of 200416 heating in Portland, OR Pp 4498-4658
 * Atomic Safety and Licensing Board Panel 80/04/16 161pp
- 8004250253 Transcript of 800417 hearing in Portland, OR Pp 4659-4828 * Atomic Sarety and Licensing Board Panel 80/04/17 197pp
- DOCKET 50-346 DAVIS-BESSE NUCLEAR POHER STATION. UNIT 1

 F Security, medical, emergency & fire protection plans
- 8004240524 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident of AO Network may also be used for daily administrative & facsimile traffic KEPFLER, J. C. Region G. Chicago, Ofrice of the Director 80/03/20
- --8004240526 Sys description & operating instructions for NRC health physics telephone network # Government Services, Inc. 79/11/30 App
- BOO4010419 Forwards upgraded emergency plan ' response to BO0219-21 onsite review of emergency planning Util will use updated version to implement procedures & conduct training by Spring or Summer 1980 CROUSE/R P Toledo Edison Co 80/03/27 9pp
- --8004010427 Emergency plan
 * Toledo Edison Co 80/03/28 130ap
- 8004180353 Forwards description of fire protection sys mods scheduled for completion by 800422 in support of util 791222 request for delay until 800930 Delay is based on revised estimates of work scope & manpower limitations
 CROUSE.R P Toledo Edison Co 80/04/11 3pp
- 8004280456 Forwards Revision 13 to industrial security plan, AD 1808 00 Encl withheld fref 10CrR2 7901 CRDUSE, R P Toledo Edison Co 80/04/22 1p
- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification CDSSICKL V Office of the Executive Director for Operations GO/04/02 34pp
- H General correspondence
- 7906290854 Responds to 790411 ltr on reactor safety, clarifying concerns re Davis-Besse shutdown & geologic faults near Diablo Canyon EISENHUT, D G Division of Operating Reactors 79/05/22 2pp
- I Financial information
- BOO4150471 Forwards three documents as evidence of guarantee of share of retrospective premium which may be levied against licensees in CYBO Adequate cash flow can be generated, if required, for retrospective premium. MAUGANS,E H Cleveland Eiectric []lluminating Co BO/04/10 2pp
- 8004280380 Forwards cash flow info for Toledo Edison & Cleveland Electric Illumination Co & Annual Financial Rept 1979 for Toledo Edison to demonstrate ability to pay combined retrospective premium for facility CROUSE.R P , ERTLE.R F Toledo Edison Co 80/04/18 6pp
- ---8004280382 Annual Financial Rept 1979 * Toledo Edison Co 80/04/18 26pp
- ---B0042B0396 Forwards cash flow info & Annual Financial Rept 1979 to demonstrate ability to pay retrospective premium for facility W/o annual rept MAUGANS.E H Cleveland Electric Illuminating Co 80/04/10 2pp
- J Insurance & indemnity information
- 8004140346 Forwards Endorsement 25 to MAELU Policy MF-92 CDRREA,C Marsh & McLennan, inc , M & M Nuclear Consultants, Inc Div 80/04/03 2pp

- P. Operating license stage documents b correspondence
- 8004040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 Te 800206 reactor trip at Crystal River Sequence of events & planned corrective actions also encl DENTON, H.R. Office of Nuclear Reactor Regulation 80/03/06 26pp
- 8004070215 Requests Class IV fees for review & approval of 800211 application proposing Tech Spec changes for Cycle 2 operation DIGGS,R M License Fee Management Branch 80/03/06 1p
- BOO4030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D G DIVISION of Operating Reactors BO/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- B004030230 Notification of 800318 meeting u/all operating 88W reactor licensees in Bethesda.MD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID.R W Operating Reactors Branch 4 80703/14 2pp
- 8004100176 Requests controlled set of PVIDs Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/03/20 in
- 8004150103 Forwards Amend 23 to License NPF-3 safety evaluation & notice of issuance & availability REED.R W Operating Reactors Branch 4 80/03/27 ip
- --8004150110 Amend 23 to License NPF-3 modifying Tech Specs to allow for delay in testing of reactor vessel internals vent valves REID.R W Operating Reactors Branch 4 80/03/27 2pp
- --8004150116 Safety evaluation supporting Amend 23 to License NPF-3
 * Office of Nuclear Reactor Regulation 80/03/27 2pp
- --8004150120 Notice of issuance & availability of Amend 23 to License NPF-3 REID.R W Operating Reactors Branch 4 80/03/27 2pp
- 8004080514 Forwards add1 responses to questions raised during 800225-26 site visit for review of implementation of NUREG-0570 requirements CRQUECR P Toledo Edison Co. 80/04/01 4pp
- 8004210328 Summary of B00222 meeting w/B&W owners group in Bethesda, Md re abnormal transient operational guidelines SEIGEL, B L Reactor Systems Branch 80/04/02 4pp
- B00425036B Summary of 800403 meeting w/utils.BtW.NUS Corp & McGraw-Hill in Bethesda.MD re draft NUREC-0667, "Transient Response of B&W-Designed Reactors " CAPRA.R A Standardization Branch 80/04/04 7pp
- B004180490 Notification of 800423 meeting w/utils & B&N in Bethesda,MD to discuss implementation of recommendations by B&H Reactor Transient Response Task Force CAPRA,R A Standardization Branch 80/04/05 2pp
- 8004220534 Advises that installation of proposed reactor vessel head vent is still under review Design requires vent path w/two isolation valves in sories Installation scheduled for 1981 refueling outage CROUSE.R P Toledo Edison Co 80/04/15 ip
- 8004220457 Clarifies Items 152 of util 800324 ltr re-actions in response to transient at Crystal River 3 Pilot operated relief 5 pressurizer stray valve will close during loss of power Power source removed during testing procedure CROUSE, R P Toledo Edison Co 80/04/14 2pp.
- 8004250376 Forwards info re GA requirements for dissel generator fuel oil in response to NRC 800107 request. Util does not cover dissel generator fuel oil 2 does not include Reg Guide i 137 in GA program Excepts of procedures encil CRCUSE, R P Taleda Edison Co 80/04/18 4pp.

Q Inspection reports, IE Bulletins & correspondence

- 8004020135 Forwards response to IE Insp Rept 50-346/79-23 re verification study of pipe whip restraints on RCS All analyses verify restraints are adequate CROUSE.R P Toledo Edison Co 79/12/07 76pp
- 8004040143 Forwards IE Insp Rept 50-346/79-33 on 791121,1212-14 & 800125 No noncompliance noted FIGRELLI.O Region 3. Obicago. Reactor Construction & Engineering Support Branch 80/02/14 2pp
- --B004040150 IE Insp Rept 50-346/79-33 on 791121,1212-14 & B00125 No noncompliance noted Major areas inspected resistance temp detector connection repair at hot leg risers & licensee implementation of IE Bulletins 79-02 & 79-14 DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch YIN,T Region 3, Chicago, Office of the Director B0/02/12 App
- 8004100013 Forwards IE Insp Rept 50-346/80-01 on 800102-04.07-11.14-18, 21-23,29-31 & 0201 & notice of violation HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/21 2pp
- --8004100016 Natice of violation from insp on 800102-04.07-11,14-18, 21-25.29-31 & 0201 * Region 3, Chicago, Office of the Director 80/02/20 ip
- --B004100022 IE Insp Rept 50-346/80-01 on 800102-04,07-11,14-18,21-25, 27-31 & O201 Noncompliance noted improper switch lineup in control room emergency ventilation sys REYES, L.A., TAMBLINO, T.N. Region 3, Chicago, Office of the Director 80/02/20 7pp
- 8004100146 Forwards IE Info Notice 80-00, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/07
- 8004040455 Responds to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.2 Inch.Adsorber Cells " Type II filtration charcoal typloading adsorbers welded w/o charcoal leakage Torque setting adjusted to obtain proper campression CRGUSE.R P Tolodo Edison Co 80/03/14 3pp
- 8004040115 Forwards IE Insp Rept 30-346/80-02 on 800114-18 & notice of violation Notice of violation witheld (ref 10CFR2 770)
 HIND, J A Region 3, Chicago, Safeguards Branch 80/03/18 2pp
- --B004040132 IE Insp Rept 50-346/80-02 on 800114-18 Noncompliance noted failurs to adequately control access Portion of active intrusion detection alarm sys not tamper-indicating Details withheld (ref 10CFR2 790)
 HINDJ A Region 3, Chicago, Bafeguards Branch USTICK,N R, BCHAPER,J F Region 3, Chicago, Office of the Director 80/03/07
- 8004090415 Ack receipt of 800304 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-346/77-30 HEIBHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/24 ip
- --8004070424 Responds to NRC 600212 itr re violations noted in IE Insp Rept 50-346/79-30 Corrective actions, reorganized authorized access list, updated drawings & monitored distribution & control of drawings GROUSE, R P Toledo Edison Co 60/03/04 3pp
- 8004100081 Ack receipt of 800314 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/80-01 HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/24 ip
- --B004100071 Responds to NRC 800221 itr re violations noted in IE Insp Rept 50-344/80-01 Corrective actions local/remote Switch HA 5261A handle removed & stored in adjacent location GROUBE, R P Toledo Edison Co 80/03/14 2pp
- 8004150191 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valva " No specific action or response necessary KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/31

- 8004080724 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER, J. G. Region 3, Chicago: Office of the Director 80/04/01 1p
- 8004150055 Forwards JE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/04/02
- 8004180060 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306
- transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220151 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220384 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/03 to
- 8004300617 Forwards partial response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " Response to Items 1, 3 & 5 are complete, w/partial response to Item 2 H/a encl CROUSE, R P Toledo Edison Co 80/04/03 2pp
- 8004230285 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/07
- 8004220057 Forwards IE Bulletin 80-0B, "Exam of Containment Liner Penetration Wolds " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- BOO4140350 Forwards monthly operating rept for Mar 1980 MURRAY,T D Tolodo Edison Co BO/04/07 ip
- S Reportable occurrences. LERs & related correspondence
- 8004180517 PND-111-78-117A review of failure of diesel generator sequencer circuit indicated that design error had occurred in translating logic drawing to contractor installation drawing Corrective action was documented in NRC 780612 ltr KLINGCR. G . NDLAN, F . SNIEZEK. J Region 3, Chicago. Office of the Director 78/06/13 ip

800

GUGA15:2+3 Formand, EER JUJ219 2L-0 NUMBAs, T.D. Toledo Edison Co. EG 04/10 Lp

8004150570 LER Points and form 800313 during diesel fire protection pump seetly restigate could not be stopped w/control button. Once stopped puly rustly and be stanted cause not determined by active receive feetral unipump probed successful FREGRER Tolego (dison to 80/04/10 3pp

E004210265 Forwards LER LO 022 03L-0 MURRAY T D. Toledo Fois n.c. 80/04 15 (p.

--3004210267 LER 80-0224-11-0 un RiQ317 operations personnel noticed loss of control room indication for containment dihydrogen analyzer 2 discharge line valve CV5010E Caused by const personnel accidentally opening breaker STOT2/JC 7-1edo Edison Lo 80/04/15 3pp

MURRAY T D Toledo Edison Cc 80/04/16 ig

- 0004220656 Re ised LER EC-004/03L-1 on 800211, gap discovered in wall where is a two-inch conducts so from electrical genetration room 2 to cable from Sir-Inch gap around ventilation duct also found Caused by improper initial installation CHESYO R C Toleto Edison Co 80/02/13 3pp

8004220752 Forcards revised LER 79 074/02L-1 MURRAY.T D Foledo Edison Co 80/04/16 19

--80342ZU/61 Re.ised LFR 77-074/03L-1 on 790707, auxiliary feedwater pump suction pressure swith inoperability made auxiliary reedwater train inoperable Caused by wrong type switch being installed Switches replaced HITCHENS.C C Toledo Edison Co 79/08/02 3pp

9004220765 Forwards revised LER 79-078/03L-0 MURRAY T D Toledo Edison Co 80/04/16 1

--8004220772 Revised LER 79-098/03L-1 on 791004, during performance of component cooling water monthly test decay heat cooler 1 romponent cooling outlef valve CC1467 would not operate Caused by valve linkage slippage Linkage realigned DEAKYNE.K Toledo Edison Co 79/10/30 2pp

8004280538 Forwards LER 60-023/03L-0 MURRAY, T D Toledo Edison Co 80/04/24 ip

--8004280546 LER 80-023/03L-0 on 800327 discovered that control rod groups 3 / 4 were no.ing in on their own Group 3 was 0% utthdrawn Group 4 was 90% withdrawn Caused by component failure Component replaced WERNER, B J Toledo Edison Co 80/04/24 3pp

8004280572 Forwards LER 80-024/03L-0 MURRAY.T D Toledo Edison Co 80/04/24 1p

--8004260575 LER 80 024/G3L-0 on 800327, following normally initiated reactor trip, auxiliary feed pump turbine 1-2 main steam isolation valve MS-107 closed Cause unknown Further investigation of raire 2 operator will be pursued MATHENY, D Toledo Edison Co 80/04/24 3pp

DOCKET 50-348 JOSEPA M FARLEY NUCLEAR PLANT, UNIT I F Security, medical, emergency & fire protection plans

8004110573 Notification or 806325,26 % 27 meetings w/util,States of AL, FL % GA & FEMA re emergency planning at facility REEVES.E Operating Reactors Branch 1 80/03/18 2pp

B004070267 Forwards revised safeguards security contingency plan Plan withheld (ref 10CFR2 790) CLAYTON, FL Alabama Power Co 80/03/28 19

J Insurance & indemnity information

8004080485 Forwards Endorsement 29 to NELIA Policy NF-238 FIELDER.J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/03/31 2pp Γ Operating license stage documents & correspondence

8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit into from plants to Bethasda Operations Ctr EISE(HUT.D G Division of Operating Reactors 80/03/12 Spp

--8004030118 "Nuclear Data Lin' Specs "
* Division of Operating Reactors 80/02/21 28pp

8004010372 Forwards addl into re compressed air sys Piping & instrumentation drawing encl MCCRACKENIK W Alabama Power Co 80/03/24 6pp

B004010425 Forwards response to NRC B00223 request for info re intersystem LOCA No valve configurations conform to Event 5 Plant design 8 insp. commitments are more than sufficient to ensure that Event 5 will not be problem at facility CLAYION.F L Alabama Power Co 80/03/24 9pp

8004080403 Commits to install backup sys to normal instrument air supply for pressurizer power operated relief valves, in response to Lessons Learned Review Team installation will be completed by end of Ott 1960 second refueling outage CLAYTON, FL Alabama Power Co 80/03/26 1p

8004030192 Application to amend License NPF~2 Tech Specs Figures 6 2-1, 6 2-2 & Tech Specs 6 5 1 2.6 5 1 8.6 5 2 2 % 6 5 3 1, re organization & responsibilities > Figure 3 2-3 & Bases 2 1 1 re change in rod bow penalty calculation CLAYTON.F.L. Alabama Power Co. 80/03/28 2pp

--8004030194 Proposed changes to Tech Spec Figures, & 2-1.6 2-2 & Toch Specs 6 5 1 2.6 5 1 8.6 5 2 2 & 6 5 3 1 re organization & responsibilities & Figure 3 2-3 > Bases 2 1 1 re change in rod bow penalty calculation

* Alabama Power Co. 80/03/28 iOpp

8004080657 Responds to tIRC 800226 request Forwards summary of heat transfer calculations used to justify two inches of ref leg insulation associated w/change discussed in 790830 ltr CLAYTON.F L. Alabama Power Co. 80/03/31

BOO4080651 Forwards response to NRC 791013 request for info re auxiliary feedwater sys Identifies reactor conditions that impose safety-related performance requirements on sys design CLAYTON,F L. Alabama Power Co. 80/04/01 12pp

8004230042 Advises that Commission has determined waiver of Class III amend see for Tech Sper changes re fire protection is appropriate Refund will be processed MILLER. W. O. License Fee Management Branch 80/04/03 ip

8004150447 Forwards draft ETS is proposed Tech Spec amend CLAYTON F L Alabama Power Co 80/04/07 5pp

--8004150452 Drafts ETS for radiological effluents * Alabama Power Co 80/04/07 84pp

8004250020 Forwards auxiliary feedwater sys evaluation status indicating portions currently acceptable per NRC 791013 ltr Requests addl info for certain items within 45 days Revised version of endurance test requirements encl SCHMENCER, A Operating Reactors Branch 1 80/04/08 7pp

8004280434 Confirms 800417 teleon re util intent to resolve auxiliary feedwater sys designs evaluation by following resolution on Unit 1 for Unit 2 CLAYTON,F L Alabama Power Co 80/04/21 1p

8004290284 Forwards Revision 2 to inservice testing program CLAYTON.F.L. Alabama Power Co. 80/04/21 1p

--8004290286 Revision 2 to inservice testing program re turbine driven auxiliary feedwater pump recirculation test line # Alabama Power Co 80/02/27 4pp

9 Enspection reparts. IE Bulletins > correspondence

B00416003B Forwards 1E Bulletin 79-01B, "Environ Qualification of Class
IE Equipment " Action required IE Bulletin 79-01B dtd 800114
should be disregarded
O'REILLY, J.P. Region 3. Chicago, Office of the Director B0/01/17
2pp

- 8004100076 Supplements 770726 to 0827 responses to Item 6 of IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Radiography was performed on each feedwater piping wold beyond first support FSAR Figure 3 8-8 encl CLAYTON, F L Alabama Power Co 80/01/30 3pp
- 8004090284 Forwards 1E Insp Rept 50-348/80-01 on 800130-31 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/21 Zpp
- --8004090291 IE Insp Rept 50-348/80-01 on 800130-31 No noncompliance noted Major areas inspected areas & activities re IE Bulletin 79-17
 HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch ECONOMOS.N Region 2. Atlanta. Office of the Director 80/02/19 4pp
- 8004080021 Ack receipt of 800221 ltr in forming NRC of steps taken to correct violations noted in IE Insp Rept 50-348/79-42 BTOHR, J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/03/11 2pp
- --8004080027 Responds to NRC 800204 ltr re violations noted in IE Insp Rept 50-348/79-42 Corrective actions Maint Work Request 19749 changed to accommodate plant conditions which whould affect procedure for proposed work CLAYTON, F. L. Alabama Power Co. 80/02/21 2pp
- --8004080034 Forwards IE Insp Rept 50-348/79-42 on 791210-14 & notice of violation STDHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/02/04 2pp
- --8004080040 Notice of violation from insp on 791210-14 * Region 2, Atlanta, Office of the Director 80/01/29 ip
- --8004080043 IE Insp Rept 50-340/79-42 on 791210-14 Nancompliance noted failure to follow procedures for reviewing maint work request GIBSON, A F. HOSEY, C M Region 2, Atlanta, Office of the Director 80/01/29 6pp
- 8004280134 Forwards IE Insp Rept 50-348/80-05 on 800219-22 No noncompliance noted LENIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/03/12 2pp
- ~-8004280143 IE Insp Rept 50-348/80-05 on 800219-22 No noncompliance noted Major areas inspected areas of small break loss of coolant procedures & training UPRIOHT, C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch BRADFORD, W H. JOHNSON, A H Region 2, Atlanta, Office of the Director 80/03/10 6pp
- 8004110003 Forwards response to 1E Bulletin 79-27 Loss of Class IE bus would not significantly affect instrumentation panels Some functions not related to achieving cold shutdown are temporarily lost CLAYTON:F L Alabama Power Co 80/03/13 5pp
- 8004i903l3 Forwards IC Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve "No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080582 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01
- 8004i50064 Forwards IE Info Notice 80-13, "GE Type 8DM Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240242 Forwards IE Info Notice 80-14, "Bafety Buggestions From Employees" No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180272 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Dil Bys "No written response required D'REILLY, J P Region 2, Atlanta. Office of the Director 80/04/03

- 8004230113 Forwards JE Sullefin 79-03A 'Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/04 ip
- 8004180323 Forwards IE Bulletin 80~08, "Exam of Containment Liner Penetration Welds " Willten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004300594 Submits quarterly tollowup status rept in response to [E Bulletin 79-14, "Seismic Analysis for As-Duilt Safety-Related Piping Sys" No deficient supports have been identified which affect operability of sys CLAYTON, F. L. Alabama Power Co 80/04/08 2pp
- R Periodic operating reports & related correspondence
- 8004030212 Forwards "Annual Operating Rept for 1979 " CLAYTON, F. L. Alabama Power Co. 80/03/26 1p
 - 8004030214 "Annual Operating Rept for 1979 " # Alabama Power Co 80/03/26 13pp
- 8004080492 Forwards "1979 Annual Environ Operating Rept.Part © Radiological" CLAYTON.F (, Alabama Power Co 80/03/31 lp
- ---8004080501 "Annual Environ Operating Rept,Part B Radiological "
 * Alabama Power Co 80/03/31 49pp
- 8004150426 Forwards monthly operating rept for Mar 1980 CLAYTON, F L. Alabama Power Co. 80/04/11 1p
- --8004150428 Monthly operating rept for Mar 1980 HAIRSTON,W G Alabama Power Co 80/04/01 7pp
- S Reportable occurrences, LERs / related correspondence
- 800A2200BA PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770B12
 WHITT,K W Region 2. Atlanta, Office of the Director 77/08/12
- B004010507 Forwards LERs 80-018/03L-0 % 80-019/03L-0 CLAYTON, F L. Alabama Power Co 80/03/21 1p
- --B004010510 LER 80-018/03L-0 on 800229. discovered bistable associated w/pressure transmitter 457 failed to meet trip setpoint requirements of surveillance test Caused by dirty gain potentiometer Potentiometer Cleaned HAIRSTON, W G Alabama Power Co 80/03/21 lp
- --8004010513 LER 80-019/03L-0 on 800229, during performance of control room Train A(B) ventilation operability test, recirculation fan 1B failed to start Caused by blown control power fuse & shorted alarm relay coil Coil & fuse replaced HAIRSTON, W O Alabama Power Co 80/03/21 lp
- 8004080540 Forwards LERs 80-020/03L-0 \$ 80-022/03L-0 CLAYTON, F L Alabama Fower Co 80/04/02 1p
- ---8004080947 LER 80-022/03L-0 on 800303 during performance of FNP-1-8TP-16 7.discharge valve to containment spray header did not open as required Cause not determined Problem did not reoccur witesting Surveillance test completed HAIRSTON.W 0 Alabama Power Co 80/04/02 1g
- --8004080554 LER 80-020/03L-0 on 800303, inaccurate pressure signal noted from PT-494,1C 8/9 pressure transmitter Caused by frozen sensing line due to abnormally cold weather & insufficient protection Sensing line thawed & channel check performed HAIRSTON, W G Alabama Power Co 80/04/02 1p
- --8004220738 LER 80-021/03L-0 on 800316, during review of surveillance test schedule, found FNP-1-STP-9 0, RCS leakage test had not been performed within time interval Cause not stated Personnel instructed re test interval HAIRSTUN, W G Alabama Power Co 80/04/09 2pp

- --8004220746 Updated LER 79-056/03L-1 on 791108 twenty fire barrier penstrations were determined not functional Caused by improper interpretation of procedures Limiting conditions Alabama Power Co 80/04/09 2pp
- 8004290367 Forwards LER 80-024/03L-0 CLAYFON.F L Alabama Power Co 80/04/22 1p
- --8004270369 LER 80-024/03L-0 on 800330 while performing turbine startup, IB SGFP tripped due to IB steam generator high level signal Caused by poor communication between plant operators Personnel instructed to emaintaining proper communication HAIRSTON, M G Alabama Power Co 80/04/22 ip

DOCKET 50-351 KOREA RESEARCH REACTOR

- 4 Inspection reports. IF Bulletins & correspondence
- 8004090352 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.JP Region 2. Atlanta, Office of the Director 80/02/06
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises or issuance of NUREO-DS88, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance remethods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8003200214 Summary of 791218 meeting w/Pottstown Trap-Rock Quarries Inc.Perkins Run Blasting, Inc.Leet Associates, CVW Industries, USOS & MRC re evaluation of effects of blasting at Sanatoga quarry on facility KANE, J D Geosciences Branch 80/02/27 App
- 8004020466 Notification of 800326 / 27 meeting w/representatives from Mark II owners group in San Jose CA to discuss Mark II Creace Test Program. 47 (~0 tests & foreign tests ELTANILA.F Containment Systems Branch 60/03/10 12pp
- GO04030122 Notification of B00326-27 meeting w/Mark II owners group, NRC consultants & GE in San Jose CA to discuss Mark II Creare test program, 4T C/O & foreign tests Topics are proprietary Agenda enci ELTAWILA.F Conten
- 8004020441 Forwards NRC 800128 & 0211 1trs to CE re mods to BWR control rod drive sys & add1 analyses of boiloff rates, respectively further ando & guidance to be issued in NUREO-0619 BAER.R L Light Water Reactors Branch 2 80/03/13 2pp

- 8004090077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAU clearance under Federal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- H General correspondence
- 8004070030 Urges NRC to take into consideration that 3 8 million people population density, area could not be evacuated easily STOUDT.T Affiliation Unknown 80/02/13 1p
- B004040224 Expresses concerns to util request for use of Delaware River water for facility W/3 8 million people in area & many obstacles, util continues to build plant Charges NRC w/responsibility to protect public from util POLLITT, K Affiliation Unknown 80/02/22 ip
- 8004040244 Approves favorable stand on public hearing request re evacuation plans at facility Power plant was mistake & const should be stopped before more money is wasted KEIL. J. Affiliation Unknown 80/02/22 ip
- 8004040251 Approves favorable stand on public hearing request re evacuation plans at facility Const should be stopped Plant should not be built in populated area KEIL.J Affiliation Unknown 80/02/22 ip
- 8004040119 Urges that all reactors come under new NRC regulations that do not allow reactors to operate in densely populated areas Faculity is classified as second most dangerous location re population proximity Const should stop immediately LONGSHORE.M L. Affiliation Unknown 80/02/23 ip
- BOO4040216 Requests that NRC stop yower plant const Area surrounding facility is densely populated Questions whether NRC would reimburse people for property losses & health damage if another Tff1 accident occurred FRIEDMAN.C Affiliation Unknown BO/03/05 1p
- 8004070024 Suggests const of facility should be halted immediately Cites earthquake fault (lack of adequake water supply as problems Facility is not needed by util now or in future CRATER, J. Affiliation Unknown 80/03/06 ip
- BO04020117 Responds to B00303 ltr requesting info re application of TMI-2 Lessons Learned Task Force to facility & certain other plants under const NTIB should be contacted for SER info ABLB proceedings announced in FR VAROA.B A Assistant Director for Light Water Reactors B0/03/22
- BOO4180196 Responds to BOO306 ltr re substituting coal plants for nuclear plants under const at site Since Unit 1 is 60% complete & Unit 2 40% complete, little capital cost could be saved by stopping const YOUNGBLOOD, B J Cost Benefit Analysis Branch 80/04/02 2pp
- 8004i0047i Expresses concern re faulting at site Job interview in 1974 w/0ilbert Associates in Pottstown, PA revealed that proposed site ranked third or fourth of six site studies Also learned that site chosen due to ability to control public opinion ORLANDO.E Murphy & Parish 80/04/03 2pp
- BOO42502B3 Responds to BOO317 congressional referral of ltr re util failure to accept loan of cryogenic processing sys from Limerick facility rather than purging to atomosphere Purging chosen for expedience DENTON.H R Office of Nuclear Reactor Regulation BO/04/07 2pp
- I Financial information
- BOO4140317 Forwards Annual Financial Rept 1979
 BRADLEY, E J Philadelphia Electric Co. B0/04/08 ip
- --8004140319 Annual Financial Rept 1979 * Philadelphia Electric Co 80/02/25 34pp
- Q Inspection reports: If Bulletins & correspondence
- 8004150139 Forwards IE Insp Repts 50-352/80-01 & 50-353/80-01 on 800109-11 & 16 No noncompliance noted CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/12 2pp

- --B004150143 IE Insp Repts 50-352/B0-01 / 50-353/B0-01 on B00109-11 & 16
 No noncompliance noted Major areas inspected QA program for
 task of installing reactor pressure vessel internals &
 control rod drive hydraulic & neutron monitoring sys
 GAGE/L, WALTUN.G , EBNETER,S Region 1, Philadelphia, Office of
 the Director B0/02/07 4pp
- 8004090435 Forwards [E insp Repts 50-352/79-14 & 50-353/79-13 on 791220,21,2/ ½ 28 No noncompliance noted CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/13 2pp
- --8004090438 IE Insp Repts 50-352/79-14 % 50-353/79-13 on 791220.21.27 % 28 No noncompliance noted Major areas inspected QA program work activities & records & QC records of nonconformance reporting sys QAGE, L. CHAUDHARY, S. Region 1. Philadelphia, Office of the Director CBNETER.S. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/07 App
- 8004100099 Forwards IE Insp Repts 50-352/79-13 & 50-353/79-12 on 791212-13 & 17-21 No nuncompliance noted CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/13 2pp
- ~-8004100112 IC Insp Repts 50-352/79-13 % 50-353/79-12 on 791212-13 % 17-21 No noncompliance noted Major areas inspected QA procedures, documentation % work activities pertaining to storage, handling % survailance of safety-related cables EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch PAYLING, R T , VARELA, A A Region 1, Philadelphia, Office of the Director 80/02/07 6pp
- 8004090397 Advises that IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks." was incorrectly sent for action No response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/17 ip
- 8004100421 Responds to IE Bullatin 80-03 Charcoal filters used will not be susceptible to charcoal leakage problems Filters from American Air have not been delivered to job site, but when received will verify screen attachment sparing KEMPER.J B Philadelphia Electric Co 80/03/17 ip
- 8004230059 Ack receipt of B00214 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/79-11 & 50-353/79-10 CARLSDIR T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/20 ip
- --B004230071 Responds to NRC 800111 ltr re violations noted in lE Insp Repts 50-352/79-11 & 50-353/79-10 Corrective actions superintendents have been instructed to keep equipment covered KEMPER, J S Philadelphia Electric Co 80/02/14 3pp
- --8004230079 Forwards IE Insp Repts 50-352/79-11 & 50-353/79-10 on 791015-31 & 1101-15 & notice of violation CARLSON:R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/01/11 2pp
- --8004230089 Notice of violation from insp on 791015-31 & 1101-15 * Region 1. Philadelphia. Office of the Director 79/12/27 2pp
- --B004230114 IE Insp Repts S0-352/79-1; & 50-353/79-11 on 791015-31 & 1101-15 Noncompliance noted failure to protect safety-related litem from const activities when stored & to follow weld procedures requirements to prevent undercutting HATTIGA-J C Region i, Philadelphia, Dffice of the Director MCGAUGHY,R W Region i, Philadelphia, Reactor Construction & Engineering Support Branch 79/12/27 14pp
- B004150293 Forwards (E Info Notice B0-12, "Instrument Fæilure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 1p
- 8004070093 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required GRIER B H Region 1. Philadelphia. Office of the Director 80/04/01 ip
- 8004110502 Forwards IE Info Natice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No written response required ORIER, B H Region I. Philadelphia, Office of the Director 80/04/02 ip

- 8004240337 Forwards IE Into Notice 80-14, 'Safety Suggestions From Enployees' No action required GRIER, B H Region 1, Philadelphia, Urfice of the Director 80/04/02 ip
- 8004180184 Forwards IC Circulat 80-67, 'Problems W/HPCI Turbine Oil Sys " No written response required GRIER.B H Region I. Philadelphia, Office of the Director 80/04/03 | Ip
- 8004)140063 Forwards IC Bulletin 60-07 'BMR Jet Pump Assembly Failure " No written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/04/04 1p
- B004230397 Forwards IE Bulletin 79-03A. "Longitudinal Wold Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required CRIER.B H. Region I. Philadelphia. Office of the Director 80/04/04 ip
- 8004180267 Forwards IC Bulletin 80-08, 'Exam of Containment Liner Penetration Helds " Written response required ORIER. B H Region 1. Philadelphia. Office of the Director 80/04/07 1p
- S Reportable occurrences, LERs & related correspondence
- 8004300348 Forwards final deficiency rept re electrical receway separation
 KEMPER, J S Philadelphia Flectric Co 80/04/24 ip
- --8004300376 Final deficiency ropt re electrical raceway separation Project QC Insp E-2 O has been revised to include final acceptance insp to verify that separation requirements have been maintained & training classes held # Philadelphia Electric Co 80/04/30 4pp
- DOCKET 50-353 LIMERICK GENERATING STATION. UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS D F Division of Praject Management B0/02/05 7pp
- 8003200214 Summary of 791218 meeting w/Pottstown Trap-Rock Quarries Inc.Perkins Run Blasting.Inc.Leet Associates.CVW Industries. USOB & NRC re evaluation of effects of blasting at Sanatoga quarry on facility
 KANE.J D Geosciences Branch 80/02/27 App
- 8004020466 Notification of 800326 % 27 meeting w/representatives from Mark II owners group in San Jose.CA to discuss Mark II Creace Tast Program.47 c/o tests & foreign tests ELTAMILA, F Containment Systems Branch 80/03/10 12pp
- 8004030122 Notification of 800326-27 meeting w/Mark II owners group. NRC consultants & OE in San Jose,CA to discuss Mark II

14300064 Summary of 800126-27 meetings w/Hark II owners group in San lose.CA to discussion of NRC concerns on data from Creare ests & foreign full-4cale test programs * relationships w/ lark II designs

Containment Systems Branch 80/04/14 22pp LIANILA F

Security, medical, emergency of the profestion plans

14100006 Comments on propused rule 10CFR50 no exemptions to license hould be given until energency reponse plans are deemed idequate NRC should reconsider issuance of CP to facility EIDTS, 4 G Arritation Unknown 80/03/03 ip

24080077 Advises that submittal date for evacuation time estimates, equested by NRC 791226 ltr.has been postponed pending CAO learance under Federal Repts Act RITES.B K Emergency Praparedness Task Force 80/03/11 4pp

General correspondence

14070030 Urges NRC to take into consideration that 3 8 million people eside within 30-mile radius of plant Considering apulation density, area could not be e-accuated easily TOUD7.T Affiliation Unknown E0/02/13 ip

14040224 Figresses construs to util request for use of Delaware River later for facility 4/3 8 million people in area & many lastacles, util continues to build plant Charges NRC livesponsibility to protect public from util OLCITT. # Affiliation Unknown 80/02/22 ip

4040244 Approves rayonable stand on public hearing request revacuation plans at facility Power plant was mistake b onst should be stopped before more money is wasted Eft. J. Affiliation Unknown 80/02/27 ip

4040251 Approves favorable stand on public hearing request revacuation plans at facility Const should be stopped Plant hould not be built in populated area EIL.J Affiliation Unknown 80/02/22 ip

4040119 Urges that all reactors come under new NRC regulations that o not allow reactors to operate in densely populated areas activity is classified as second most dangerous location a population proximity Const should stop inmediately ONGSHORE, M. L. Affiliation Uninown BO/02/23 ip

4040216 Requests that NRC stop power plant const Area surrounding relitly is densely populated Questions whether NRC would eimburse people for property lasses & health damage if nother TRI accident occurred RIEDMAN.C Affiliation Unknown 80/03/05 1p

1070024 Suggests const or facility should be halted immediately ites earthquake fault ' lack of adequate water supply as roblems Facility is not needed by util now or in future RATER. J. Affiliation Unknown 80/03/06 ip

020117 Responds to 800303 ltm requesting info re application of fI-2 Lessons Learned Task Force to farility & certain other lants under const NTIG should be contacted for SER info LB proceedings amounted in FR NRA.8 A Assistant Director for Light Water Reactors 80/03/22

1180196 Responds to 800366 ltr re substituting coal plants for iclear plants under const at site Since Unit 1 is 60% implete & Unit 2 40% implete. Little capital cost could be ived by stopping const.

NNGBLOOD, B.J. Cost Scherit Analysis Stanch 80/04/02 2pp

100471 Expresses contern re raulting at site Job interview in 1974 'Gilbert Associates in Pottstown, PA revealed that proposed te ranked third or fourth or six site studies Also learned at site chasen due to ability to control public opinion LANDO, E. Murphy & Parish Bu/04/03 2pp

I250283 Responds to BAC317 congressional leterral of ltr le utilitiume to accept loan of cryogenic piocessing sys from ineric racility rather than purging to atomosphere Purging iosen for expedience
NTON.H R Office of Nuclear Reactor Regulation 80/04/07 2pp

imancial information

140317 Forwards Annual Financial Rept 1979 ADLEY, E. J. Philadelphia Flectric Co. 80/04/08 ip

Q Inspection reports IF Bulletins 2 correspondence

8004150137 Forwards IE Into Repts 50 352/80-01 & 50-353/80-01 on 800109-11 & 16 No moncumpliance noted CARLSONR T Region 1 Philadelphia, Reactor Construction & Engineering Support Branch 00/02/12 App

--8004150143 lE insp Repts 50 J52/80-01 / 50-353/80-01 on B00107-11 / 16
No noncompliance noted Major areas inspected QA program for
task or installing reactor pressure vessel internals //
control rad drive hydiaulir * neutron monitoring sys
GAGLL , WALTON, G , EDNETER, S Region I, Philadelphia, Office of
the Director BO/O2/07 App

8004090435 Forward: IC Insp Repts 50-352/79-14 & 50-353/79-13 on 791220.21.27 ½ 20 No noncompliance noted CARLEON.R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch @0/02/13 2pp

--8004090438 IE Insp Repts 50-352/79-1) / 50-353/79-13 on 791220,21,27 & 28 No noncompliance noted Major areas inspected GA program work activities & secords & OC records of nonconformance GAGE.L. CHAUDHARY.S Region i. Philadelphia, Office of the Director EBNETER.S Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/07 6pp

8004100099 Forwards IE Insp Repts 50-352//9-13 & 50-353/79-12 on 791212-13 & 1/-21 No nuncompliance noted CARLEGMR T Region 1. Payladelphia, Reactor Construction & Engineering Support Branch 60/02/13 2pp

--8004100112 IE Insp Repts 50-352/79-13 % 50-353/79-12 on 791212-13 & 17-21 No noncompliance noted Major areas inspected OA procedures documentation & work activities pertaining to storage handling & surveillance of safety-related cables EUNETER. S D Region I. Philadelphia. Reactor Construction & Engineering Support Bianch PAVLIND. R T, VARELA A A Region I, Philadelphia. Office of the Director 80/02/07 App

8004090397 Advises that IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," was incorrectly sent for action No response required ORICE, B H Region I, Philadelphia, Office of the Director 80/03/17 1p

8004100421 Responds to IE Bullelin 80-03 Charcoal filters used will not be susceptible to charcoal leakage problems Filters from American Air have not been delivered to job site;but when received will verify screen attachment sparing KEMPER:J 5 Philadelphia Electric Co 80/03/17 ip

8004230059 Ack receipt or 800214 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/79-11 & 50-353/79-10 CARLSDNS T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/20 1p

--8004230971 Responds to HRC 800111 ltr re violations noted in IE Insp Repts 80-352/79-11 & 50-353/79-10 Corrective actions superintendents have been instructed to keep equipment KEMPER, J S Philadelphia Electric Co BO/02/14 3pp

--8004230079 Forwards IF Insp Repts 50-352/79-11 & 50-353/79-10 on /91015-31 % 1101-15 / notice of violation CARLSON.R T Region I. Philadelphia, Reactor Construction & Engineering Support Branch 80/01/11 2pp

--8004230087 Notice of violation from the on 791015-31 & 1101-15
• Region 1. Philadelphia. Office of the Director 79/12/27 79/12/27 2np

--8004230114 IF Insp Repts 50-352/79-11 % 50-353/79-11 on 791015-31 & 1101-15 Noncompliance noted failure to protoct safety-related item from const activities when stored & to follow weld procedures requirements to provent undercutting MATT10A.J C Region i. Philadelphia. Office of the Director MCGAUGHY.R W Region i, Philadelphia. Reactor Construction & Engineering Support Branch 79/12/2/ 14pp

8004150293 Forwards IE Into Notice 80~12, "Instrument Failure Causes Opening of PGRV & Block Valve" No specific action or response necessary GRIER, BH Region i. Philadelphia, Office of the Director 80/03/31 1p

1

- 8004090093 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BD/04/01 ip
- 8004110502 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No written lesponse required ORIER,B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004240337 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" Na action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 800418D184 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Oil 8ys " No written response required ORIER, B H. Region 1. Philadelphia. Office of the Director 80/04/03 1p
- 8004110063 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required GRIER, BH Region 1, Philadelphia, Office of the Director 80/04/04 | Ip
- 8004230399 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004180267 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/07 ip
- 8 Reportable occurrences, LCRs & related correspondence
- 800430036B Forwards final deficiency rept re electrical raceway separation KEMPER, J. 8 Philadelphia Electric Co 80/04/24 ip
- --8004300376 Final deficiency rept re electrical raceway separation Project QC Insp E-2 O has been revised to include final acceptance insp to verify that separation requirements have been maintained & training classes held # Philadelphia Electric Co 80/04/30 4pp
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT :

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDSS.D F Division of Project Management 80/02/05 7pp
- 8004020451 Forwards NRC 800128 & 0211 ltrs to GE re mods to BWR control rod drive sys & addl analyses of boiloff rates respectively Further info & guidance to be issued in NURES-0619
 BAER,R L Light Water Reactors Branch 2 80/03/13 3pp
- 8004020154 Forwards additinfore shorthose sturgeon in Delaware River Concludes that continued operation of Unit 1, future operation of Unit 2 & const completion of Hope Creek units will not jeopardise existence of shorthose sturgeon REGAN, W H Assistant Director for Environmental Projects 80/03/14
- B004170250 Responds to NRC 800314 biological assessment of impact of continued operation or const of facilities Forwards biological opinion & summary of informal consultation w/NRC re Salem Unit i Shortnose sturgeon are not in Joopardy LEITZELL.T L. Commerce. Dept of, National Marine Fisheries Service 80/04/15 20pp
- F Security, medical, emergency & fire protection plans
- B0040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending CAO clearance under Federal Repts Act
 ORIMES, B.K Emergency Preparedness Task Forca B0/03/11 4pp

- G Adjudicatory correspondence
- 8004040207 Comments on irresponsible way intervenors are being treated Sites case of ruling to allow Salem Unit 1 to operate despite no evidence that licensee could protect endangered shortnose sturgeon COLEMAN, A C Neft | listion Unknown 80/03/05 3pp
- BO04090192 Explains circumstances involving B00222 svc of BNWL draft rept in measurements of underground mining radon releases to NRC testimony of RM Wilde re same rept Hissing Page 6 encl
 BORDENICK. Bit Heating Blanch 4 80/03/05 4pp
- 8004030026 Nemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSS[CR.L V Office or the Executive Director for Operations 80/04/02 34pp
- 8004300585 Responds to 77jul8 petitions requesting that Commission issue show cause order to suspend or revote OL for Salem 1 & CPs for Salem 2 & Hope Creak 1 & 2. & stay issuance of OL for Salem 2 Request denied W/Director's decision DENTON, H R Office of Nuclear Reactor Regulation 80/04/18 ip
- --B004300590 Director's decision under 10CFR2 206 on E % A Coleman petition requesting that Commission issue show cause order re facilities DL & CP issuances Request denied DENTON.H R Office of Nuclear Reactor Regulation 80/04/18 App
- --8004300598 Notice of issuance? availability of Director's decision under IOCFR2 206 on A > E Coleman petition requesting that Commission issue show cause order re facilities OL & CP issuances

 DENTON H R Office of Nuclear Reactor Regulation 80/04/18 2pp
- --8004300600 "Assessment or Impacts of Facilities on Shortnose Sturgeon. Acipensor Brevirostrum Lesuor " HABNIK.M T , WILSON.J H Office of Nuclear Reactor Regulation 80/03/31 | Ip
- H General correspondence
- 8004030123 Responds to 790816, its re plans to reopen THI-1; nuclear plant const in NJ % nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ Ng diseases resulted from TMI DENTON, H R Office of Nuclea, Reactor Regulation 80/03/03 2pp
- --8004030129 Oppnses restart of TMI-i.canst of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety
 FOSTER.K Affiliation Unknown 79/08/16 2pp
- Q Inspection reports. IF Bulletins & correspondence
- 8004100152 Ack receipt of 800213 ltr informing NRC of steps taken to correct violations noted in Ir lnsp Repts 50-354/79-09 & 50-355/79-08 CARLSON:R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/12 ip
- ~-8004100157 Responds to NRC BU0115 ltr re violations noted in IC Insp Repts 50~354/79~09 % 50~355/79~0B Corrective actions opened new pour cards, updated concrete repair filing sys & revised Tech Specs SMP/P-C-1 MARTINIT J Public Service Electric & Gas Co of New Jersey B0/02/13 2pp
- --8004100158 Forwards IC Insp Repts S0-354//9-09 & 50-355/79-08 on 791126-30 & notice of violation CARLSDM.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/01/19 2pp
- --8004100160 Notice of violation from insp on 791126-30
 Region 1, Philadelphia, Office of the Director 80/01/11 ip
- --B004100168 IE Insp Repts 50-354/79-07 % 50-355/79-08 on 791126-30 Noncompliance noted failure to issue supplementary concrete pour card after signing off concrete placement checklist on pour w/deficient areas remaining to be repaired MCGAUCHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch VARELAIA A, BATEKAN, W H Region 1, Philadelphia, Office of the Director 80/01/11 10pp

- BO0409039B Advises that IE Bulletin 60-05, 'Vacuum Condition Resulting in Damage to Chemical 'ol Control Sys (CVCS) Holdup Tanks."

 was incorrectly sent for action to response required GRIER.B H. Region 1. Philadelphia, Office or the Director 80/03/1/ ip
- B004250224 Responds to IF Bulletin 60-03 Completed investigation espected by 800501, pending response from Bechtel MARTIN.T J. Public Settice Electric f Gas Co. of New Jersey 80/03/21 1p
- 8004150299 Forwards IE Into Notice 80-12, 'Instrument Failure Couses Opening of PORV / Block Valve ' No specific action or response necessary GRIER, B. H. Region i, Philadelphia, Office of the Director 90/07/33 in
- B004090099 Forwards IE Circular 80~05, 'Emergency Diesel Generator Lubricating 0:1 Addition & Onsite Supply " No written response required ORIER, B H. Region 1, Philadelphia, Office of the Director 80/04/01 10
- B004110507 Forwards IE Info Notice B0-13, "GE Type SBM Control Switches Defective CAM Follower," No Orlitten response required GRIER.B H Region I, Philadelphia, Office of the Director B0/04/02 Ip
- 8004246346 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required ORIER, BH Region 1, Philadelphia, Office of the Director 80/04/02 19
- 8004180186 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine 0:1 Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/03 ip
- B004110071 Forwards IE Bulletin B0-07, "BHR Jet Pump Assembly Failure" No written response required GRIER:B H Region 1, Philadelphia, Office of the Director BD/04/04 ip
- 8004230455 Forwards IE Bulletin 75-03A, "Longitudinal Neld Defects in ABME SA-312 Type 304 Stainless Steel Pipe" Action required CRIER.B H. Region 1. Philadelphia. Office of the Director 80/04/04 p
- 8004180276 Forwards IE Bullotin 80-08, "Eram of Containment Liner Penetiation Welds" Written response lequired ORIER.D H Region), Philadelphia. Office of the Director 80/04/07 (p
- S Reportable occurrences, LERs & related correspondence
- 8004080109 Act receipt of 800303 interim deficiently rept re main steam pipe spools CARLSON.R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/03/12 ip
 - 14 Interim deficiency rept re main steam pipe spools GE issued tions to restore affected wall thickness to original equirement Final rept will be submitted by 800321 ublic Service Electric & Gas Co of New Jersey 80/03/03

of 800314 interim deficiency rept re discrepancy d wire i. Philadelphia. Reactor Construction & anch 80/03/31 ip

> n procurement of sir of rewelding

MARTIN.T J Public Service Electric & Gas Co of New Jersey 80/03/14 2pp

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

爓

800404003i Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D F Division of Project Management 80/02/05 7pp

- 8004020451 Forward: NRC 800128 % u211 ltrs to GE re mods to BWR control rod drive sys % add1 analyses of boiloff rates respectively Further info % guidance to be issued in NUREG-0619
 8AER, R.L. Light Water Reactors Branch 2 80/03/13 3pp
- 8004020154 Forwards addl info re shorthose sturgeon in Delaware River Concludes that continued operation of Unit 1, future operation of Unit 2 & const completion of Hope Creek units will not jeopardize existence of shorthose sturgeon REGAN, W H Assistant Director for Environmental Projects 80/03/14 20n
- --8004020163 "Assessment of Impacts of Salem & Hope Creek Stations on Shorthote Sturgeon, Acipenser Brevirostrum Leaver " MASHIK, N T Office of Nuclear Reactor Regulation 80/03/05
- 8004170250 Responds to NRC 800314 biological assessment of impact of continued operation or const of facilities Forwards biological opinion t summary of informal consultation w/NRC re Salem Unit 1 Shortnose sturgeon are not in Jeopardy LEITZELL,T L. Commerce, Dept of, National Marine Fisheries Service 80/04/15 20pp
- F Security, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by IRC 791226 ltm. has been postponed pending QAD clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force BO/03/11 4pp
- G Adjudicatory correspondence
- 8004040207 Comments on irresponsible way intervenors are being treated Sites case of ruling to allow Salem Unit 1 to operate despite no evidence that licensee could protect endangered shortnose sturgeon COLEMAN.F G Affiliation Unknown 80/03/05 3pp
- 8004090192 Explains circumstances involving 800222 svc of BNNL draft rept re measurements of underground mining radon releases 6 NRC testimony of RM Wilde re same rept Missing Page 6 encl BORDENICK, B M Hearing Branch 4 80/03/05 4pp
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- BD04300585 Responds to 791018 petitions requesting that Commission issue show cause order to suspend or revoke OL for Balem 1 & CPs for Salem 2 & Hope Creek 1 & 2, & stay issuance of OL for Balem 2 Request denied W/Director's decision DENTON.H R Office of Nuclear Reactor Regulation 80/04/18 ip
- --8004300590 Director's decision under 10CFR2 206 on A&E Colemen petition requesting that Commission issue show cause order re facilities OL & CP issuances Request denied DENTON.H R Office of Nuclear Reactor Regulation 80/04/18 6pp
- ---8004300598 Notice of issuance & availability of Director's decision under 10CFR2 206 on A&E Coleman petition requesting that Commission issue show cause order re-facilities OL & CP issuances
 DENTON.H R Office of Nuclear Reactor Regulation 80/04/18 2pp
- --8004300600 "Assessment of Impacts of Facilities on Bhortnose Sturgeon, Acipenser Brevirostrum Lesuer " MASNIK, M T Office of Nuclear Reactor Regulation B0/03/31 ip
- H General correspondence
- 8004030123 Responds to 790816, itr me plans to reopen TMI-1, nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are recoived Provides info replants in NJ No diseases resulted from TMI DENTON.H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- -- 8004030127 Opposes restart of TMI-1:const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety FOSTER, K. Affiliation Unknown 79/08/16 2pp

Q Inspection reports, IF Bulletins & correspondence

- 8004100152 Ack receipt of 800213 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/79-09 & 50-355/79-08 CARLSDN.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/03/12 1p
- --8004100157 Responds to NRC B00115 ltr re violations noted in IE Insp Repts 50-354/79-09 & 50-355/79-08 Corrective actions opened new pour cards, updated concrete repair filing sys & revised Tech Specs SWP/P-C-1 MARTIN.T J Public Service Electric & Gas Co of New Jersey B0/02/13 2pp
- --8004100158 Forwards IE insp Repts 50-354//9-09 & 50-355/79-08 on 791126-30 & notice of violation CARLBON.R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/01/15 2pp
- --8004100160 Notice of violation from insp on 791126-30
 * Region 1, Philadelphia, Office of the Director 80/01/11 1p
- --8004100148 IE Insp Repts 50-354/79-09 & 50-355/79-08 ол 791126-30 004100168 IE Insp Repts 50~354/79-09 & 50~355/79-08 on 791126-30 Noncompliance noted failure to issue supplementary concrete pour card after signing off concrete placement checklist on pour w/deficient areas remaining to be repaired MCGAUGHY.R W Region 1. Philadeiphia, Reactor Construction & Engineering Support Branch VARELA.A A. BATEMAN.W H Region 1. Philadelphia, Office of the Director BO/01/11 10pp
- 8004090398 Advises that IE Bulletin 80~05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tants," was incorrectly sent for action No response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/17 1p
- 8004250224 Responds to IE Bulletin 80-03 Completed investigation expected by 800501, pending response from Bechtel MARTIN,T J Public Service Electric & Gas Co of New Jersey 80/03/21 lp
- 8004150299 Forwards JE Info Notice 80-12, "Instrument Failure Causes Opening of PCRV & Block Valve " No specific action of response necessary ORIER, B H Region i, Philadelphia, Office of the Director Region i, Philadelphia, Office of the Director 80/03/31
- B004090099 Forwards IE Circular B0-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B. H Region 1. Philadelphia, Office of the Director B0/04/01 1p
- 8004110507 Forwards IE Info Natice 80-13, "GE Type 8BM Control Switches Defective CAM Followers" No written response raquired ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004240346 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required GRIER.B.H Region 1, Philadelphia, Office of the Director 80/04/02 19
- 8004180186 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Oil 8ys " No written response required CRIER, B H Regian i. Philadelphia. Office of the Director 80/04/03 ip
- 8004110071 Forwards IE Bullstin 80-07, "BWR Jet Pump Assembly Failure " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/04/04 ip
- B004230455 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pipe" Action required, ORIER, B H. Region |, Philadelphia, Office of the Director B0/04/04 | Ip
- 8004180276 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response vequired ORIER,B H Region 1. Philadelphia, Office of the Director 80/04/07 ip

- S Reportable occultence». LERs & related correspondence
- 8004090314 Ack receipt of ±00211 interim deficiency rept advising that investigation of surface indication was not yet completed stion of sulface indication was not yet complet rept should be submitted when required info is CARLSON, R T CARLSON,R T Region 1, Philadelphia, Reactor Construction b Engineering Support Branch 80/03/06 ip
- --8004090317 Interim deficiency rept is surface indication on reactor pressure vessel Grinding rework to investigate indication will commence 800215 % be completed by 800228 MARTIN.T J. Public Service Electric % Gas Co. of New Jersey 80/02/11 2pp
- 8004080109 Ack receipt of 800303 interim deficiency rept re main steam pipe spools CARLSON,R T Region t. Philadelphia, Reactor Construction & Engineering Support Branch 60/03/12 Ip
- ~-8004080114 Interim deficiency rept re main steam pipe spools GE issued instructions to restore affected wall thickness to original GE spor requirement Final rept will be submitted by 800321 MARTIN Public Service Electric & Gas Co of New Jersey 80/03/03
- B0042B0171 Ack receipt or 800314 Interim deficiency rept re discrepancy in procurement of weld wire CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/31 ip
- -8004280174 Interim deficiency rept re discrepancy in procurement of weld wire Pittsburgh Des Moines has completed repair of stiffeners where coupons were temoved & removal & rewelding of seams of heat 1 D AB913

 MARTIN-T J Public Service Electric / Gas Co of New Jersey B0/03/14 2pp
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR G Inspection reports. IF Bulletins & correspondence
- 8004110259 Forwards IE Insp Repts 50-151/80-01 & 50-356/80-01 on 800204-06 No noncompliance nuted DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/03/03 2pp
- --8004110274 IE Insp Repts 50-151/80-01 / 50-354/80-01 on 800204-04 No noncompliance noted Major alreas inspected emergency planning including support pracedures, personnel interviews, review or training & drills & insp of equipment EBSIO, TH NRC Regional Offices OREER, R J Region 3, Chicago, Office of the Director 80/02/22 App
- DOCKET 50-358 WILLIAM H TIMMER NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management
- 8004040D17 Submits add1 guidance to NUREG-058B. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSB, D F Division of Project Management 80/02/21 3pp
- 8004020466 Notification of 800326 \$ 27 meeting w/representatives from Mark II owners group in San Jose,CA to discuss Mark II Creace Test Program,4T c/o tests \$ foreign tests ELTAMILA,F Containment Systems Branch 80703/10 12pp
- 8004030122 Notification of 800326-27 meeting w/Mark II owners group, NRC consultants & GE in Gan Jose CA to discuss Mark II Creare test program, 4T C/O & foreign tests Topics are proprietary Agenda encil ELTAWILA: F Containment Systems Branch B0/03/10 12pp
- 8004040474 Summary of 800227 meeting w/Mark II owners group re status of several long-term program tasks, including Tasks A 17, A 16 & task related to utilization of foreign test data ELTAWILA.F Containment Systems Branch 80/03/18 104pp

- 800408024a Request, revision of all form of notice for order estending const completion date for include add1 statements re envision considerations Pevision, should be effective as of facility notice CHRISTENSURY. E Hearings Dission £0/03/27 1p
 - .
- 8004250036 Rotification or 800531-w2 meeting woutil in Moscow,OH to discuss forecast panel site visit PELTIER,I A Light Water Reactors Branch i 80/04/08 4pp
- 800415036) Responds to NRC 800503 ltrie environ qualitication of Class IE instrumentation b electrical equipment Completion of documentation review expected by 800615 Requests info on mods to NUREG-055B resulting from comment process FLYNN.J D Cincinnati Gas 5 Electric Co 80/04/10 ip
- 8004300064 Summary of 800326-27 meetings w/Mark II owners group in San Jose,CA re discussion of IARC conceths on data from Create tasts > foreign full-scale test programs > relationships w/ Mark II designs ELTANILA,F Containment Systems Branch 80/04/14 22pp
- F Security, medical, emergency * fire protection plans
- BO040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES, B K Energency Preparedness Task Force 80/03/11 4pp
- 8004280317 Forwards Revision 15 to "Fire Protection Evaluation Rept." submitted as responses to questions BOROMARN.E A Cincinnat Gas 2 Electric Co 80/04/25 1p
- --8004280322 "Fire Protection Evaluation Rept," Revision 15 > Cincinnati Gas & Electric Co 80/04/30 7pp

G Adjudicatory correspondence

- 800403033B Response to State of KY 800304 petition to intervene as interested state if participation granted re emergency planning. State of KY must enter proceeding in present stage of development Certificate of Svc encl
 CONNER, T B , HETTERHAMM, M J Cincinnati Das & Electric Co CONNER, T B Conner, Moore & Corber 80/03/19 App
- 8004100468 Petition for leave to intervene by Zimmer Area Citizens & Zimmer Area Citizens of MV Petitioner is concerned about proximity of elementary & secondary schools to nuclear power plant Certificate of Svc encl DENNISON, A B Affiliation Unknown BOKNISON, A B Affiliation Unknown 80/03/24 9pp
- B004070182 Response in support of State of KY participation as interested state State emergency preparedness plan involved in safe operation of facility Recommends admission at present stage of development BARTH.C A Hearing Branch 3 80/03/26 4pp
- 8004080592 Memorandum / order admitting State of KY as interested state.subj to taking proceeding as found in present stage Order taken w/o GO Bright participation BECHHOEFER.C Atomic Bafety and Licensing Board Panel 80/04/01 2pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification COSSICK, V Office or the Elecutive Director for Operations 80/04/02 34pp
- 8004220156 Requests denial of Zimmer Area Citizens & Zimmer Area Citizens in KY petitions to intervene as interested person Petitioner has failed to demoistrate good cause for late filing Certificate of Svc encl CONNER.T B Cincinnati Gas & Electric Co CONNER.T B Conner, Moore & Corber 80/04/07 28pp
- 8004180111 Responds to 800321 inquiry, on behalf of Miams Valley Power Project, recost of subpoemaing SH Manauer to testify at OL proceedings NRC regulations do not permit NRC personnel to be subpoemaed for NRC proceedings

 BARTH.C A Rearing Branch 3 80/04/10 2pp
- --B004180208 Inquires on behalf of Miami Valley Power Project, re cost of subpoending SH Hanguer to testify at OL proceedings on status of info available from Mark 11 owners group OILLMAN, D Affiliation Uninown 80/03/21 lp

- 8004210445 Response recommending that Zimmer Area Citizens 800321 petition to intervene be granted, provided that contentions is emergency planning? riadiological monitoring be filed in 20 days Certificate or Svc orell BARTH-C A Hearing Branch 3 80/04/10 9pp
- H General correspondente
- 7908150559 Discusses 790530 ltr suggesting training of licensed operating personnel in handling casualty conditions & emergency situations Dutlines possible future NRC rule reconducting & observing in-plant drills NATTSON.R Division of Systems Safety 79/07/17 2pp
- --790B150564 Submits suggestions to need for more operator training in handling casualty conditions, in-plant casualty training during refueling. Publication of emergency teams during extreme casualty conditions.

 ADAMS, J E Affiliation Unknown 79/05/30 3pp
- 8004090157 Submits inquiry re see requirements if subpoenaed to testify at DL hearings on info available from Mark [I owners group GLLMAN, D. Miami Valley Power Project 80/03/21 ip
- I Financial information
- 8004040340 Forwards Annual Financial Rept 1979 for util.Columbus & Southern OH Electric Co / Dayton Power & Light Co BORGMANN.E A Cincinnati Gas & Electric Co 80/04/01 Ip
- ~~8004040343 Annual Financial Rept 1979 * Cincinnati Gas t Flectric Co 80/01/23 32pp
- ~-8004040350 Annual Financial Rept 1979
 4 Columbus & Southern Ohio Electric Co 80/02/07 36pp
- ~-8004040355 Annual Financial Rept 1979 * Dayton Power & Light Co 80/02/06 25pp
- Q Inspection reports, 1E Bulletins & correspondence
- 8004210134 Forwards IC Insp Rept 50-358/80-03 on 800122-24 & notice of violation FIGRELI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/29 App
- --8004210137 Natice of violation from insp on 800122-24
 Region 3. Chicago, Office of the Director 80/02/21 2pp
- --8004210142 IE Insp Rept 50-358/80-03 on 800127-24 Noncompliance noted failure to comply w/design requirements in approved tost procedures VANDEL, T E , GALLACHER, E J , KNOP, R C Region 3, Chicago, Office of the Director 80/02/21 App
- 8004300014 Forwards IE Insp Rept 50-358/79-36 on 791114-15.800128-31 & O201 No noncompliance noted HETSHKMAR F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/02/29 2pp
- --8004300022 IE Insp Rept 50-358/79-36 on 791114-15,800128-31 & 0201 No noncompliance noted Major areas inspected preoperational test program including test procedure review.license audits, unresolved items & fuel insp STREETER JF, MAURA,F Region 3, Chicago, Office of the Director 80/02/22 6pp
- 8004100123 Forwards If Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/07 1p
- 8004160009 Responds to IF Rulletin 80-03 re loss of charcoal from std adsorber cells Plant has no charcoal adsorber filter beds supplied by Flanders Adsorbers supplied by CVI Penwalt Corp & American Air Filter BORGMANN.E A Cincinnati Qas & Electric Co 80/03/21 2pp
- 8004150163 Forwards IC Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J & Region 3. Chicago, Office of the Director 80/03/31 ip

- 8004080694 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Dosite Supply " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/01
- 8004150024 Forwards IE Info Notice BO-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/02
- 8004180037 Forwards attachments to IC Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800305 transmittal KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220113 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J O Region 3, Chicago, Dffice of the Director 80/04/02
- BOO4220344 Forwards IE Circulai 80-07. "Problems WHPC! Torbine Oil Sys " No written response required KEPPLER, J.O. Region 3. Chicago, Office of the Director 80/04/03
- BOO4110032 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure"
 No written response required
 KEPPLER, J G Region 3, Chicago, Office of the Director BO/04/07
- 8004230207 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07
- 8004220108 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J.O. Region 3. Chicago. Office of the Director 80/04/09 to
- --8004300604 Responds to NRC 800215 ltr re violations noted in IE Insp Rept 50-358/79-37 Corrective actions pipe support insp program revised & generation coust dept requested to prepare procedure for preparation, distribution & revision of dept BOROMANN, E A Cincinnati Gas & Electric Co 80/03/18 1p
- S Reportable occurrences, LERs & related correspondence
- 8004180215 Ack receipt of 800314 interim deficiency rept re Anchor/ Darling gate valves NRC will review matter upon roceipt of final rept FIORELLI,O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/01 ip
- U Congressional/Executive Correspondence
- 8004140252 Responds to 800207 ltr re constituent group concerns about facility Util required to comply w/financial protection & indemnity provisions of Price-Anderson Act & 10CFR140 prior to OL issuance W/FES. Section 8. re need for power DIRCKS, W J Office of the Executive Director for Operations 80/03/29 2pp
- --8004140262 Requests info on behalf of constituent group re possible radiation exposure caused by accident similar to TMI-2 event Lists areas of concern HOPKINB, L J House of Rep 80/02/07 ip
- DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance RDS8.D F Division of Project Management 80/02/05 7pp

- 8004040017 Submits add) guidance to NURIG-0588. 'Interim Staff Position on Environ Qualification of Barety-Related Electrical Equipment "Requests review or equipment qualification documentation to identity degree or campliance ROSS.D F Division of Project Management 80/02/21 Spp
- 800423005B Requests into be advillarly feedwater sys per Bulletins & Orders Task Folico review of IMI-2 accident Info should be provided as amend to application Submitthi schedule should include NRC approval priot to issuance of OL W/encl ROSS.D F Division of Project Management 80/03/10 53pp
- 8004110028 Forwards requests for addl into re FSAR review Addl open item concerns approval or analysis methods used for loss of flow transients, depending on approval of CENBR code described in CENB-177-P BAER, R. L. Linht Water Reactors Branch 2 80/03/20 15ng
- 8004030181 Forwards info requested by NRC 800117 felcon re confirmatory analysis of shutdown cooling line Index to piping layout, isometric sheet 8 pipe support drawings encl HAYNES, J G Southern California Edison Co 80/04/01 16pp
- --8004030186 "Guality Class 1 3 II.ASMC Code.Section III Design Spec for RCS Piping Components, Sys 1201 'Thirty-two oversize drawings encl # Bechtel Corp 79/05/10 400pp
- 8004270133 Summary of B00305-07 meetings w/Friends of the Earth in San Diego.CA re seismology & emergency preparedness concerns ROOD:H Light Water Reactors Blanch 3 80/04/10 App
- B004220570 Notifies that difficulties w/proposed memorandum of agreement re transmission project have been resolved to satisfaction of CA DFc of Historic Preservation NRC should forward agreement to advisory council for action MELLON, K California, State of 80/04/15 ip
- BCO4290640 Forwards data on which review of seismic reflection profiles within 25 km San thofre will be based Response to NRC BO0320 request will be provided by approx BO0425 BASKIN, K P Southern California Edison Co BO/04/IB 4pp
- B004300011 Forwards LANDSAT photographs of southern CA to facilitate Geosciences Branch review Photographs will be referenced in FEAR. Section 1 & DASKIII. K.P. Southern California Edison Co. 80/04/18 ip
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8004300779 Responds to NRC 800917 request forwards revised tables from DES re operation of Facility including recorded data from 1976-79 & projections for 1980-85 Tables show production costs, peak demand, energy requirements & reserve margins BASKIN, K P Southern California Edison Co 80/04/11 App
- T Security, medical, emergency & fire protection plans
- BOO40B0077 Advises that submittal date for evacuation time estimates, requested by NRC 771226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 GRIMEG.B K Emergency Preparedness Task Foice BO/03/11 4pp
- 8004080515 Forwards review summary of fire protection covering Items 3 1 4, foam suppression sys.3 1 7, gas suppression sys.2 2 3, turbine bldg structure Items 3 1 1.3 1 2.3 1 5 are partially completed % summary will be provided accordingly HALL.R E Brookhaven National Laboratory 80/03/31 16pp
- 8004080395 Notifies that combined response to NRC 791211 & 800324 ltrs re safeguards contingency plan will be sent by 800421 HAYNES, J G Bouthern California Edison Co 80/04/01 1p
- BOO4230320 Forwards revision to BNL 800331 ltr re ltems 3 i 1(5),3 1 2 (b),3 1 5(d),3 1 6,3 1 7(a),3 1 7(b),3 i i5(b) ½ 3 2 3 for fire protection review HALL.R E Brookhaven National Laboratory 80/04/16 16pp
- 8004300363 Notifies NRC that util requires add1 time to revise safeguards contingency plan as described in NRC 800324 1tr Revised safeguards plan uill be forwarded by 800512 BASKIN.K P Bouthern California Edison Ca 80704721 1p

G Adjudicatory correspondence

- 30041004/7 Stipulation extending time for answers of intervenor Friends of the Earth third set or interrogatories Certificate of Skc encl PlOOTT.D R Southern California Edison Co PIGOTT.D R Chickering & Gregory 80/03/05 4pp
- 8004100537 Response to third set of interrugatories inloudes info re persons answering interrugatories & time ported when applicant decided to construct nuclear plant Certificate of Sec & DR Pigott verification encil
 PIGOTT.D R Southern California Edison Co PIGOTT.D R Chickering & Gregory 80/03/18 25pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological energency planning & preparedness distributed as Board notification GOSSICKL V Office of the Executive Director for Operations BO/04/02 34pp

H Deneral correspondence

- 8004150188 Responds to 80022] itr opposing issuance of OL for facilities Public hearings in vicinity of plants will probably be held neit year HANCHETI, J G Region 5. San Francisco, Office of the Director 80/03/11 1p
- --BO04150195 Requests that NRC not issue OL to util for proposed addl generating stations Continued operation of present facility represents immediate hazard to life & property All nuclear plants leak radiation / should be shut down SVESLOSKY.F Affiliation Unknown 80/02/21 3pp
- 8004020462 Forwards Commission statement of policy on conduct of adjudicatory proceedings, published in 791109 FR W/o encl CHANDLER, L. J. Hearing Branch 1 80/02/17 1p
- Q Inspection reports. IE Bulletins % correspondence
- 8004210181 Forwards IE Insp Repts 50-361/80-02 & 50-362/80-01 on 800103-04 & 21-28 he noncompliance noted SPENCER, 0 S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/03/ii 2pp
- --8004210186 IE Insp Rept 50-361/80-02 & 50-362/80-01 on 800103-04 & 21-28 No noncompliance noted Major areas inspected const activities including reactor pressure vesse) & internals protection deficiency followups & fire in fuel paci area MAYNES, R C Region 5. San Francisco, Reactor Construction & Engineering Support Branch PATE, R J Region 5, San Francisco, Office of the Director 80/03/11 App
- 8004210412 Forwards IE lnsp Repts 50-361/79-32 & 50-362/79-29 on 791201-31 No noncompliance noted SPENCER.G S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/03/11 2pp
- --8004210417 IE, Insp Repts 50-361/79-32 & 50-362/79-29 on 791201-31 Na noncompliance noted Major areas inspected const activities, including reactor pressure vessel & internals protection PATE.R J Region 5, San Francisco, Office of the Director HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Bianch 80/03/10 Spp
- 3004020045 Act receipt of 800304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/79-27 & 50-362/79-27 SPERCER.O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/03/17 ip
- --8004020049 Responds to NRC 800204 itr re violations noted in IE Insp Repts 50-361/79-29 & 50-362/79-27 Corrective actions cable will be replaced Open parts capped w/appropriate cover PAPAY,L T Southern California Edison Cq 80/03/04 Spp
- --8004020054 Forwards IE Insp Repts 50~361/79-27 % 50-362/79-27 on 791113-16 & 1211-14 & notice of violation SPENCER, 0 S Region 5. San Francisco. Uffice of the Director 80/02/04 2pp
- --8004020058 Notice of violation from insp on 791113-16 \$ 1211-j4

 * Region 5. San Francisco, Office of the Director 80/02/04
 2pp

- --8004020062 IE Insp Rept 50-361//9-29 & 50-362/79-27 on 791113-16 & 1211-14 Noncompliance noted failure to use cleanliness caps on instrumentation lines * to control unused £7018 weld rods
 DODDS: R T Region 5, San Francisco. Reactor Construction & Engineering Support Branch HERNANDEZ.G , ELIN.J O Region 5, San Francisco. Office or the Director 80/02/04 9pp
- 8004280092 Forwards IE Insp Repts 50-361/80-04 % 50-362/80-02 on 800219-27 No noncompliance noted SPENCER.6 S Region 5. San Francisco, Peactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004280095 IE insp Repts 50-361/80-04 & 50-362/80-02 on 800219-29 No noncompliance noted Major areas inspected const activities, including reactor pressure vessel & internals protection, piping storage & previous item re corrective actions HAYNES,R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch PATE,R J Region 5, San Francisco, Office of the Director 80/03/17 4pp
- 8004150214 Forwards IE Into Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELMEN.R H Region 5. San Francisco, Office of the Director 80/03/31 1p
- 8004100107 Forward. IE Corculat 80-05. "Emergency Diesel Generator Lubricating Oil Addition A Onsite Supply " No written response required ENOELMEN, R H Region 5, San Francisco. Office of the Director 80/04/01 1p
- 8004110314 Forwards IE Info Notice 80~13, "GE Type GBM Control Switches Defective CAM Followers" No specific action or response required ENGELKEN,R H Region S, San Francisco. Office of the Director 80/04/02 ip
- 8004220048 Forwards is Into Notice 80-14. "Safety Suggestions From Enployees" No action required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/02 1p
- B0041B0135 Forwards tE Circular B0-D7. "Problems W/HPCI Turbine Dil Sys " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/03 | Jp
- 8004230368 Forwards IE Bullotin 79-03A, "Langitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Attion required ENGELKEN, R H. Region 5, San Francisco, Office of the Director 80/04/04 to
- 8004220198 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written :espanse required ENGELKEN:R H Rogion 5. Ban Francisco. Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- 800407033B Forwards info re occupational exposure & environ surveillance programs for 1979
 OTTOSON,H L Southern California Edison Co 80/03/31 3pp
- --8004070345 "1979 Annual Operating Rept. Vol 1.Oceanographic Data Rept "
 * Brown & Caldwell 80/03/31 400pp
- --8004070348 "1979 Annual Operating Rept.Vol 2.Biological Data Rept Intertidal Infauna.Subtidal Infaunal.Kelp.Ichthyoplankton " * Marine Biological Consultants, Inc., 80/03/31 300pp
- --8004070392 "1979 Annual Operating Rept.Vol 3:Biological Data Rept Flankton:Hard Benthos Rocky Intertidal " * Lockheed Center for Marine Research 80/03/31 500pp
- --8004070357 "1979 Annual Operating Rept. Vol 4.Biological Data Rept. Nekton " * Brown & Caldwell 80/03/31 250pp
- 8004140161 Forwards "Annual Operating Rept, 1979, " Vols 1-4 H/o encl DICTCH-R South Carolina Electric & Qas Co 80/04/04 2pp

ortable accurrences, LERs & related correspondence

0492 Ack receipt of 800310 interim deficiency rept re measuring to inal root by 800530 receipt to Acker root by 800530 receipt root by 800530 R H Region 5, San Francisco, Office of the Director 1p

100500 Interim deficiency rept re measuring & test equipment calibr at vendor facilities Final rept will be submitted NN. 2500500

Southern California Edison Co 80/03/10 1p

0538 Forwards amended final deficiency tept to pipe support gn, updating 790706 rept
Y.L. T Southern California Edison Co 80/04/07 ip.

1505-36 Amended final deficiency mept me design deficiencies related cemtain safety-related pipe supports Updates 790706 mept including six addl deficiencies Program initiated to view total design of sys prior to change

C TINU ,NOITATE RABJOUR PROPRE PAGE - OF

lication/construction stage documents & correspondence

ODG 1 Advises of issuance of NUREG-0588, "Interim Staff Position nvir on Qualification of Safety-Related Electrical pmeett." providing guidance re methods for compliance , D F. Division of Project Management 80/02/05 7pp

OO17 Submits addl guidance to NUREO-0588. "Interim Staff Position nviron Qualification of Bafety-Related Electrical pment." Requests review of equipment qualification mentation to identify degree of compliance, D F. Division of Project Management 80/02/21 3pp

OODB Requests info re auxiliary feedwater sys per Bulletins & rs Task Force review of TMI-2 accident Info should be ided as amend to application Bubmittal schedule should ude NRC approval prior to issuance of CL Wencl . D F. Division of Project Management 80/03/10 53pp

0028 Forwards requests for add1 info re FBAR review Add1 open CORSC Brns approval of analysis methods used for loss of translations, depending on approval of CENOR code ribed in CENPD-177-P, R L. Light Water Reactors Branch 2 80/03/20 15pp

0181 Forwards info requested by NRC 800117 telcon re confirmatory ysis of shutdown cooling line Index to piping layout, etric sheat & pipe support drawings end.

55. J. O Southern California Edison Co 80/04/01 14pp

OBO 1 会会 "Quality Class I & II, ABME Code, Section III Design Spec for S Piping Components, Sys 1201 " Thirty-two oversits awings encl Bechtel Corp. 79/05/10 400pp

OIGH Summary of 800305-07 meetings w/Friends of the Earth in San o, CA re saismology & emergency preparedness concerns .
Light Water Reactors Branch 3 80/04/10 6pp

0570 Notifies that difficulties w/proposed memorandum of ODYO Notifies that difficulties w/proposed memorandum cemernt re transmission project have been resolved to sfaction of CA Ofc of Historic Preservation NRC should and agreement to advisory council for action ON. K. California, Btate of 80/04/15 ip

0640 Forwards data on which review of seismic reflection profiles in 25 km San Chofre will be based Response to NRC 20 request will be provided by approx 800425 IN. K. P. Southern California Edison Co. 80/04/18 6pp

Draft/Final Environmental Statements, supply & correspondence

OBTS Responds to NRC 800317 request Forwards revised tables from the operation of facility, including recorded data from operations for 1980-85 Tables show production of projections for 1980-85 Tables show production speak demand energy requirements to reserve margins speak demand energy requirements to reserve margins in K.P. Bouthern California Edison Co. 80/04/11 6pp

F. Security, medical, emergency * rire protection plans

B0040B0077 Advises that submittal date for evacuation time estimates, requested by NRC /91226 lfr.has been postponed pending GAO clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11 4pp

8004080515 Forwards review summary or fire protection covering Items 3 1 6, feam suppression sys.3 1 7, gas suppression sys & 3 2 3, turbine bldg structure Items 3 1 1,3 1 2,3 1 5 are partially completed A summary will be provided accordingly HALL.R E Brookhaven National Laboratory 80/03/31 16pp

B004080395 Notifies that combined response to NRC 791211 & B00324 ltrs re-safeguards contingency plan will be sent by B00421 HAYNES, J G Southern California Edison Co B0/04/01 1p

8004230320 Forwards revision to 3NL 800331 Itr re Items 3 1 1(5),3 1 2 (b),3 1 5(d),3 1 6,3 1 7(a),3 1 7(b),3 1 15(b) & 3 2 3 for fire protection review Bronkhaven National Laboratory 80/04/16 1600

8004300363 Notifies NRC that util requires additime to revise safeguards contingency plan as described in NRC 800324 ltr Revised safeguards plan will be forwarded by 800512 BABKIN K P Southern California Edison Co 80/04/21 lp

G Adjudicatory correspondence

8004100477 Stipulation extending time for answers of intervenor Friends of the Earth third set of interragatories Certificate of Syc encl PIGOTT, D R Southern California Edison Co PIGOTT, D R Chickering PIGATT, D.R. Southern & Gregory 80/03/05

3004100537 Response to third set of interrogatories Inloudes info repersons answering interrogatories & time period when applicant decided to construct nuclear plant Certificate of Svc & DR Pigott verification enci PIGOTT.D R Southern California Edison Co PIGOTT.D R Chickering & Gregory 80/03/18 25pp

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOBSICKL V Office of the Executive Director for Operations 80/04/02 34pp

H General correspondence

B00415018B Responds to 800221 Its opposing issuance of UL for facilities Public hearings in vicinity of plants will probably be held nest year HANCHETT.J G Region 3. San Francisco, Office of the Director 80/03/11 1p

---B004i50i75 Requests that NRC not issue CL to util for proposed addl generating stations Continued operation of present facility represents immediate hazard to lire 8 property Ail nuclear plants leak radiation & should be shut down 6VESLOSKY, F Affiliation Unknown 80/02/21 3pp

8004020462 Forwards Commission statement of policy on conduct of adjudicatory proceedings, published in 791109 FR W/o encl CHANDLER.L J Hearing Granch 1 80/03/17 1p

Q Inspection reports, IE Bulletins % correspondence

B004210181 Forwards IE lnsp Repts 50-361/80-02 & 50-362/80-01 on 800103-04 & 21-28 No noncompliance noted SPENCER,0 S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/03/11 2pp

--8004210186 JE Insp Rept 50-361/80-02 & 50-362/80-01 on 800103-04 & 21-28 No noncompliance noted Major areas inspected const activities, including reactor pressure vessel & internals protection, deficiency followups & fire in fuel pool area HAVNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch PATE, R J Region 5, San Francisco, Office of the Director 80/03/11 App

8004210412 Forwards IF Inso Repts 50-361/79-32 % 50-362/79-29 on 791201-31 No noncompliance noted SPENCER.G S Region 5. San Francisco. Reactor Construction 8 Engineering Support Branch BO/03/11 2pp

- -8C04210117 IE. In an inepre 50-251/17 32 t 50-252/77-29 on /91201-31 No noncompliance noted Major aleas inspected constrativities, including reactor plasming essel (internals protection PATE, R. J. Region 5, familiation, Office of the Director MAYNES, R. C. Region 5, familiation, Reactor Construction 5 Engineering support Khar, h. 80/03/10 5pp
- 8904020045 Act receipt or Condust its informing NRC of steps taken to correct violations acts in IC loap Repts 50-361/79-29 t 50-362/79-27 SPERCERG S. Region 5. San Francisco. Reactor Construction & Engineering Suppost Brouch. 60 03/17. 1p
- --8004020049 Responds to NRC BioClub Itr is violations noted in IE Insp Repts 50-361/77-29 / 50-36 '/79-27 Corrective actions cable will be replaced Open parts capped w/appropriate cover PAPAyil T Southern (alifoinia Edu
- --B004020054 Faruards IF Insp Repts 50-3517/9-29 / 50-3627/9-27 on 791113-16 / 1211-14 / natice of violation SPENCER.C S Region 5. San Francisco. Office of the Director B0702704 | 2pp
- 8004020058 Notice of violation from inep on 791113-16 & 1211-14

 Region 5 San francisco, Office of the Director 80/02/04
- --8004020042 IF Into Rept 50-361//9-27 50-362//9-27 on 791113-16 & 1211-14 Noncompliance noted reliate to use cleanliness caps on instrumentation lines 4 to control unused E7058 weld DODDS,R T Region 5. San Francisco, Reactor Construction be Engineering Support Branch HERNANDEZ,G . ELIN.J D Region Francisco, Office of the Director 80/02/04 9pp Region 5. San
- 8004280092 Forwards IF Inap Repts 50-361/80-04 \$ 50-362/80-02 on 800219-29 No moncompliance nuced SPENCER, G S. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 80/03/20. 2pp
- --8004280075 IE Insp Repts 50-361/80-04 / 50-362/80-02 on 800219-27 No noncompliance noted Major aleas inspected constractivities, including reactor pressure vessel // internals protection, piping stolage // previous item re corrective actions HAVPES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch PATE, R J Region 5, San Francisco, Office of the Director 80/03/17 Jp
- 8004150214 Forwards If Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Diock Valve " No specific action or response necessary ENGELKEIN R H. Region 5, San Francisco Office of the Director 60/03/31 Ip
- 8004500107 Forwards IE Circular 80°05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required ENGELKEN R H Region 5, San Francisco. Office of the Director H Region 5, San Francisco. Office of the Director Ip
- B004110114 Forwards IC Into Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers 'No specific action or response required ENGELKEN R H Region 5. San Francisco. Office of the Director B0/04/02
- 800422004B Forwards 1E Info Notice 80-14, "Bafety Suggestions From Employees" No action required ENGELKEILR H Region 5, San Francisco, Office of the Director 80/04/02 1p
- 8004180135 Forwards IE Circular 80-07. 'Problems N/HPCI Turbine Oil Sys " No written response required EMOELKEN.R H Region 5. San Francisco, Office of the Director BO/04/03 ip
- 8004230368 Forwards IE Bulletin 79-034, "Longitudinal Neld Defects in ASME SA-312-Type 304 Stainless Steel Pipe " Action required ENGELKEILR H Region 5. San Francisco. Office of the Director 80/04/04 1p
- B004220198 Forwards IE Bulletin 80-08 "Exam of Containment Liner Penetration Welds " Written response required ENGELKENIR H Region 5. San Francisco. Office of the Director 80/04/07 ip

- R Periodic operating tepsits ' related correspondence
- 800407u338 Forwards info to occupational exposure & environ surveillance programs for 1979
 OTTOSON, H. L. Southern California Edison Co. 80/03/31. 3pp
- --8004070345 "1979 Annual Uperating Rept.Vol 1.Oceanographic Data Rept "

 # Brown & Caldwell 80/03/31 400pp
- --8004070352 "1979 Annual Operating Rept, Vol. 3, Biological Data Rept Plankton, Hard Bonthos Rocky Intertidal " 4 Lockheed Cente; for Marine Research 80/03/31 500pp
- --8004070357 '1979 Annual Operating Rept. Vol 4, Biological Data Rept
 - Brown * Caldwell 80/03/31 250pp
- 6004140161 Forwards "Annual Operating Rept.1979," Vols 1-4 W/o encl DIETCH.R South Cargino Electric's Gas Co 80/04/04 2pp
- S Reportable occurrences (ERs) related correspondence
- 8004100492 Ack receipt of 800310 interim deficiency rept re measuring & equipment recalibi at vendor facilities Anticipates receipt of final rept by 800530 ENGELMEINS H Region 5. San Francisco, Office of the Director 80/03/15 ip
- --8004100500 Interim deficiency reptile measuring & test equipment recallibr at vendor facilities final rept will be submitted by 800530
 MINU-DE Southern California Edison Ca 80/03/10 1p
- 8004150538 Forwards amended final deficiency rept re pipe support design, updating 790706 tept PAPAY.L T Southern California Edison Co 80/04/07 1p
- ---8004150546 Amended final deficiency rept re design deficiencies related to certain safety-related pipe supports Updates 790706 rept by including six addi deficiencies Program initiated to review total design of sys prior to changeover to startup & Southern California Edison Co 80/04/07 4pp
- DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- GO04040G31 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management
- F Security, medical, emergency & fire protection plans
- 9004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 QRIMES, B K Emergency Preparedness Task Force 80/03/11 App
- H General correspondence
- 6004030123 Responds to 790816. Itr re plans to reopen TMI-1, nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info replants in NJ No diseases resulted from TMI DENTON, HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030129 Opposes restart of TMI-1, const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety FOSTER, K Affiliation Unknown 79/08/16 2pp
- I Financial information
- 8004090477 Forwards supplementary financial info in support of TMI-1 restart proceedings
 HAFER, F D General Public Utilities - GPU Service Corp 80/04/03
- --8004090482 Annual Financial Rept 1979. * General Public Utilities GPU Service Corp * Jersey Contral Power & Light Co * Metropolitan Edison Co 80/04/03, 44pp

@ Inspection reports, IE Bulletins & correspondence

- 8004020006 Responds to IE Bulletin 80-03 re visual insps of charcoal adsorber cells Equipment of this type has not been purchased to date FINFROCK, I R Jersey Central Power & Light Co 80/03/11
- 8004150271 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B. H. Region t, Philadelphia, Office of the Director response ... GRIER, B H Ri
- 8004090060 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, D H Region I, Philadelphia, Office of the Director 80/04/01 1p
- 8004110134 Forwards IE Info Notice 80~13, "GE Type SBM Control Switches Defective CAM Follows s " No written response required CRIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- B004240306 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER, B.H. Region 1, Philadelphia, Office of the Director B0/04/02 ip
- 8004180241 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Dil Sys " No written response required GRIER, D H Region 1, Philadelphia, Office of the Director 80/04/03 ip
- 8004230507 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required CRIER, B H Region I, Philadelphia, Office of the Director 80/04/04 ip
- 8004180194 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ORIER. B H Region 1, Philadelphia, Office of the Director 80/04/07 tp

DOCKET 50-344 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSB, DF Division of Project Management 80/02/05 7pp
- 8004040017 Submits add1 guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROS8.D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re auxiliary feedwater sys per Dulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of DL H/encl ROSB, D, F Division of Project Management 80/03/10 53pp
- 8004020473 Forwards License SNM-1868 for util, authorizing receipt, possession & storage of U enriched in U-235 isotope & Pu License also authorizes packaging of fuel assemblies for delivery to carrier Safety evaluation enci PAGE,R O Uranium Fuel Licensing Branch 80/03/12 2pp
- --8004020481 License SNM-1868 for utiliauthorizing receipt.possession.
 insp & storage of U enriched in U-235 isotope in fuel
 assemblies & fission counters. & Pu in encapsulated Puberyllium neutron sources & alpha sources
 PAOE,R O Uranium Fuel Licensing Branch 80/03/i2 2pp
- --8004020485 Safety evaluation supporting 770718 application for license for fuel & accessories Licensee should be granted exemption from 10CFR70 24 requirements

 DELANEY, J C Unantum Fuel Licensing Branch 80/03/12 2pp
- 8004250048 Forwards request for addl info re review of OL application Schedule based on assumption that info will be available by 800505 Requests response within seven days after receipt of 1tr if date cannot be met 8TOLZ.JF Light Water Reactors Branch i 80/04/01 11pp

- 8004100330 Forwards into the eismic qualification of safety-related non-MSES supplied electrical / mechanical equipment Summary equipment list encl
 CLAYTON.F. L. Alabams Fow-1 Co. 80/04/04 15pp
- 8004150447 Forwards didft ETs to proposed Tech Spec amend CLAYTON, F.L. Alabama Power to 80/04/07 5pp
- --8004150452 Diafts ETS to: radiological eftluents → Alabama Power Co 30/04/07 84pp
- 8004280434 Confirms 800417 teleon is util intent to resolve auxiliary feedwater sys designs evaluation by following resolution on Unit 1 for Unit 2 CLAYTON, F. L. Alabama Power Co. 80/04/21 ip
- F. Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.hos been postponed pending GAO clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11 4pp
- 8004110573 Notification of 800325,26 & 27 meetings w/utiliStates of AL, FL & GA & FEMA re emergency planning at facility REEVES.E Operating Reactors Branch 1 80/03/18 2pp
- 8001070267 Forwards tevised safeguards security contingency plan Plan withheld (ref 10CFR2 790) CLAYTON.F L. Alabama Power Co. 80/03/28 1p
- G. Inspection reports, IE Bulletins & correspondence
- 8004150313 Forwards IC Info Notice 80-12, "Instrument Failure Causes Opening of PORY / Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director B0/03/31
- 8004080582 Forwards IE Circular 80-05 "Emorgency Diesel Generator Lubricating Oil Addition > Onsito Supply " No written response required

 O'REILLY, J P Region P, Atlanta, Office of the Director 80/04/01 2pp
- 8004190064 Forwards JE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required
 G'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004240242 Forwards IF Info Hotice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region P. Atlanta, Office of the Director 80/04/02
- 8004180272 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/04/03
- 8004230113 Forwards IE Bulletin 79-03A "Longitudinal Weld Dofetts in ABME 8A-312.Type 304 Stainless Steel Pipe " Action required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/04/04
- 8004180323 Forwards IE Rulletin 60-00 "Exam of Containment Liner Penetration Wolds " Willton response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/07
- 8004250401 Forwards add1 info re facility preservice insp program in response to NRC 800403 request insp plan for Class 1 & 2 components presented which identifies items to be inspected CLAYTON.F L. Alabama Power Co 80/04/21
- S Reportable occurrences, LERs & related correspondence
- 8004220084 PNO-77-143 Parific Pump Cd supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT/K W Region 2, Atlanta, Office of the Director 77/08/12

- 04160242 Notifies that will his evaluated rod drop analysis discussed in Westinghouse 791115 for litration ARC Reportable deficiency exists Westinghouse topical rept re-solutions will be reviewed when issued in mid-1980 CLAYTON, Fill Mahama Power to 80/04/03 2pp
- OCKET 50 366 LOWIN ! HATCH NUCLEAR PLANT, UNIT 2 Adjudicatory correspondence
- 004290460 Forwards NRC confirmatory piders STELLO:V Orrice of Inspection & Enforcement, Office of the Director 80,04/04 Ip
- -8004290466 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800526 info required outlined in Attachment A STELLO, V Orfice of Inspection 2 Enforcement, Office of the Director 80/04/04 5pp
- -8004290477 Order confirming util commitment to perform review requested by IE Bulletin 79~27 by 800626 Into required contained in Attachment A STELLO, V Orfice of Inspection / Enforcement, Office of the Director 80/04/04 5pp
- Operating license stage documents & correspondence
- 004080189 Discusses NRC 761123 request that all LWR licensees assess higher rission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactor IFPOLITO,T A Operating Reactors Branch 3 80/03/10 3pp
- 04030102 Forwards "Nuclear Da'a Link Specs," study of digital communication sys to transmit info from plants to Dethesda Dperations Ctr EISENHUT,D G Division of Operating Reactors B0/03/12 Spp
- 8004030118 'Nuclear Data Link Specs "

 Division of Operating Reactors | 80/02/21 | 28pp
- 04030227 Destribes review of primary coolant sys pressure isolation valves in response to NRC 800223 ltr re potential for LBCA forwards stetches of penetrations exhibiting Event 5 valve configuration for each unit WIDNER.W A Georgia Power Co 80/03/31 Spp
- 104270055 Forwards 800179 % 0211 ltis to QE re proposed control rod drive sys mode related to elimination of cracking in return line nozzles Guidelines for mode will be discussed in NUREG-0619, to be issued in "For Comment" form in Apr 1980 IPPOLITO.T A Operating Reactors Branch 3 80/04/07 2pp
- 04150358 Submits info is control rod operability, in response to NRC 800110 ltr During Sept 1978 to Dec 1979 no instances occurred of control rods failing to insert fully Only malfunctions were nitiogen cartridge valve loaks HIDNER, N. A. Georgia Power Co. 80/04/08 lp
- Inspection reports, IF Bulletins & correspondence
- 04070349 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2, Atlanta Office of the Director 80/02/04
- O4010112 Partially responds to 1E Sulletin 79-010, "Environ valification of Class IF Equipment" Class IE components sted including environ analysis, inadequate qualification it test? accident temp profiles W/o encl "ER.W A Georgia Power Co E0/02/08 2pp
 - 215 Forwards IE Repts 50-321/80-08 \$ 50-366/80-08 on I-22 No noncompliance noted
 T.J C Region 2. Atlanta. Reactor Construction & Engineering
 rt Branch 60/03/04 2pp
 - 04220221 IE Insp Repts 50-32i/80-08 & 50-366/80-08 on 800221-22 No noncompliance noted Major areas inspected followsp on items of noncompliance re locra21 BROWNLEE.V L. CONLON.7 E Region 2. Atlanta. Office of the Director 80/03/04 3pp

- 8004090032 Ack receipt of 800310 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-01 &
- 50-36/80-01 LEWIS.R C Region & Atlanta, Reactor Operations Nuclear Support Branch 80/03/18 ip
- --8004090035 Responds to NRC 800205 ltr re violations noted in IE Insp Repts 50-321/80-01 % 50-366/80-01 Corrective actions data sheet revised to relocate rire pump fuel level checks & assignment sheet revised to use HNP-2-9503 WIDNER, N A Georgia Power Co 80/03/10 ip
- ~-8004090036 Forwards [E Insp Repts 50-321/80-01 & 50-366/80-01 on 800108-11 ; notice of violation LEWIS.R C Region 2. Allanta, Reactor Operations Nuclear Support Branch 80/02/05 2pp
- --8004090041 Notice of violation from insp on 800108-11 ≠ Region 2. Atlanta. Office of the Director 80/0
- --8004050049 IE Insp Repts 50-321/80-01 & 50-366/80-01 on 800108-11 Noncompliance noted failure to follow surveillance procedures

 UPRIGHT.C II Region 2. Atlanta, Reactor Operations Nuclear Support

 Branch MODN.B T Region 2. Atlanta, Office of the Director

 BO/02/05 App
- BOO4110565 Submits response to IE Bulletin BO-03, "Loss of Charcoal From Std Type II, Two-Inch. Tray Adsorber Cells " All filters are in good condition, all screens are stable & housing frames are solld No carbon lost through screens WIDNER, W.A. Georgia Power Co. BO/03/21 3pp
- 8004150198 Responds to IT Bulletin 80-03 re charcoal adsorber cells Insp of all Util 1 ventilation sys indicate that all filters are in good condition Util 2 uses deep bed type carbon filter beds rather than cells WIDNER, W A Georgia Power Co 80/03/21 3pp
- BOO4170298 Responds to IC Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation "Review of emergency procedures required by Item 2, is now scheduled for completion by BOO626
 HIDNER, W.A. Georgia Power Co. BO/03/26. ip
- 8004190521 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/31
- B0040B06P4 Forwards IF Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01
- 8004150065 Ack receipt of 800211 1tr informing NRC of steps taken to correct violation noted in IE (nsp Repts 50-321/79-37 & 50-366/79-41 LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/01 ip
- --8004150072 Responds to NRC 800117 ltr re violation noted in IE Insp Rept 50-321/79-37 & 30-366/79-41 Corrective actions existing radiation work practices & procedures reviewed & modified WIDNER,W A Georgia Power Co 80/02/11 2pp
- --8004150079 Forwards IE Insp Repts 50-321/79-37 & 50-366/79-41 on 791110-1207 & notice of violation LEWIS.R C NRC Regional Offices 80/01/17 2pp
- --8004150086 Notice of violation from insp on 791110-1207 * Region 2. Atlanta, Office of the Director 80/01/ 80/01/15 1p
- --B004150076 IF Insp Repts 50-321/79-37 & 50-364/79-41 on 791110-1207
 Noncompliance noted radiation work permits were not
 approved & posted prior to work contrary to procedures &
 Tech Specs
 DANCE, H C NRC Regional Offices ROGERS, R F Region 2, Atlanta,
 Office of the Director B0/01/15 Spp
- 8004150126 Ack receipt of B00313 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-321/80-04 & 50-366/80-04 LENIS,R C Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch 80/04/01 ip

- --8004150136 Responds to NRC 800214 Itr re violation noted in IE Insp Repts 50-321/80-04 & 366/80-04 Corrective actions shift foreman & operators involved were relieved of duties for special training WINNER:W A Deorgia Power Co 80/03/13 1p
- --8004150142 Forwards 1E Insp Repts 50-321/80-04 \$ 50-366/80-04 on 791212-800104 & matice of violation LEWIB,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/14 2pp
- --8004150147 Notice of violation from insp on 791212-800104 * NRC Regional Offices 80/02/19 ip
- --8004150155 IE Insp Rept 50-321/80-04 2 50-366/80-04 an 791212-800104 Noncompliance noted HPCI sys not proven operable as required by Tech Specs DANCE.H C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch ROSERS,R F Region 2. Atlanta, Office of the Director 80/02/13 4pp
- 8004150093 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required D'REILLY, J.P. Region 2: Atlanta, Office of the Director B0/04/02
- 8004240265 Forwards IE Info Natice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/04/02 2nd
- 8004180303 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03 200
- 8004110011 Forwards IF Bulletin 80-07, "BWR Jet Pump Assembly Failure "Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004230173 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME BA-312.Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04 to
- 8004180436 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07
- 8004230467 Submits info in response to 800121 ltr re IE Subletin 80-02 Documentation associated w/receipt & installation of sparger assemblies & mods is on file at plant site WIDNER, N A Georgia Power Co 80/04/16 4pp
- 8004280432 Updates 800346 response to IE Bulletin 79-01B "Environ Qualification of Class IE Equipment " Enough info re Bechtel equipment will be available by 800801 to provide meaningful response Info needed from 02 will be complete by 801226 HIDNER.W A Georgia Power Co 80/04/21 2pp
- R Periodic operating reports & related correspondence
- 8004010321 Forwards "Annual Environ Surveillance Rept for CY79 " MANRY, M Georgia Power Co. 80/03/28 1p
- --8004010324 "Annual Environ Surveillance Rept for CY79 " * Georgia Power Co 80/03/28 300pp
- 8004150383 Forwards monthly operating rept for Mar 1780 MANRY, M Georgia Power Co 80/04/10 lp
- --8004150385 Monthly operating rept for Mar 1980 RODEN.J W Georgia Power Co 80/04/10 10pp
- BOO4150393 Forwards monthly operating rapt for Mar 1980 MANRY,M Georgia Power Co 80/04/10 1p
- 8 Reportable occurrences, LERs & related correspondence
- B004150454 Forwards LER B0-017/03L-0 MANRY,M Georgia Power Co 80/03/13 1p

- --8004150460 LEP 80-017/O3L-O on 800219, during instrument check, B d dihydrogen dibilde recorder found reading low Caused by diaphragm facture in B analyzer vacuum pump Diaphragms replaced Analyzer recalibr * returned to svc NIX.R T Georgia Power Co 80/03/13 2pp
- 8004020343 Forwards LER 80-020/03L-0 MANRY: M Georgia Power Co 80/03/24 1p
- --8004020347 LER 80-020/03L-0 on 800229.during normal operation, who performing HPC1 exhaust diaphragm pressure switch surveillance, two switches greeded Tech Specs Caused by instrument drift Suitches recalltr NIX.R T Georgia Power Co 80/03/25 2pp
- 8004020361 Forwards LER 80-019/03L-0 MANRY, M Georgia Power Co 80/03/24 1p
- --8004020365 LER 80-019/03L-0 on 800227, during instrument check, A di H2C2 analyzer recorder found giving erroneous reading Caused by diaphragm forlure in A analyzer vacuum pump Diaphragma replaced Analyzer calibr \$ returned to svc NIX.R T Georgia Power Co 80/03/24 2pp
- 8004020315 Forwards LER 80-028/03L-0 MANRY, M Georgia Power Co 80/03/25 !p
- --8004020317 LER 80-028/03L-0 on 800228, during instrument chock, B dr H2-02 analyter recorder was found giving erroneous reading Caused by leakage in sys leak repaired Analytor calibr & returned to svc NIX, RT Georgia Power Co 80/03/25 2pp
- 8004020325 Forwards LER 80-027/03L-0 MANRY, M Georgia Power Co 80/03/25 1p
- --8004020330 LER 80-027/03t-0 on 800315, while performing, plant ave w pump auto function operability surveillance, isolation valve 2P41-E316A failed to actuate to isolation position upon signal Caused by instrument failure NIX.R T Georgia Power Co 80/03/25 2pp
- B004020428 Forwards LER 80-025/03L-0 MANRY, M Georgia Power Co 80/03/25 ip
- --8004020437 LER 80-025/03L O on 800308.during shutdown,while performance (LPCI) pump start timers calibr.relay 2C11-K75A setpoint exceeded Tech Specs Caused by setpoint drift Relay recalibr NIX,R T Georgia Power Co 80/03/25 2pp
- 8004150425 R0-50-366/1780-29 on 800324, battery chargers 20 & 2J. used while charging diesel batteries 2A & 2C. respectively, failed to maintain necessary load & voltage requirements Caused by possible testing component faslure Batteries recharged MANRY, M Georgia Power Co 60/03/25 2pp
- 8004070314 Forwards LER 80-021/03L-0 MANRY, M Georgia Power Co 80/03/26 1p
- --8004070324 LER 80-02\$/03L-0 on 800303, while in shutdown, surveyllan tests found MPCI turbine exhaust valve, feedwater check valve & equipment drain sump isolation valve w/unacceptable leakage Causes under investigation C0001N:CL Georgia Power Co 80/03/27 3pp
- 8004150410 RC-50-366/1980-031 on 800327, during cold shutdown, while performing 18-month surveillance, battery charges 2A, 28 & 2C were unable to maintain loading requirements Caused by SCRs & current limiting modules being out of adjustment MANRY, M Georgia Power Co 80/03/28 2pp
- 8004040427 Forwards LER 80-024/03L-0 MANRY, M Georgia Fower Co 80/03/31 1p
- --8004040438 LER 80-024/03L-O on 800308.w/reactor in cold shutdown.wiperforming ASME operability test on RHR water pumps, pump 2EII-C001D dropped from 4,000 gpm to 3,600 gpm Caused by debris being drawn into suction of pump NIX.R T Georgia Power Co 80/03/31 2pp
- 8004110472 Forwards LER 80-025/031-0 MANRY, M Georgia Power Co 80/04/02 1p
- ---8004110476 LER 80-026/03L-0 on 800314 during local leak rate testing hydrogen recombiner return isolation valve 2749-F0058 had unacceptable test results Caused by scratch on seat apparently due to valve closing on piece of debris C0001N:C L Georgia Power Co 80/04/02 2pp

ļ

```
2504110179 Fr. wards EER or 01: 01T 0
MANRY M. Georgia Power to E0704703 1p
- Pu04110463 (fit Au UC fits) for its 025225 during 18-nonth surveillance test on ereagenry station battery margers 20 f 25-both failed to maintain respective loss. Caused by voltage control module & correct limit module rejuicing rine tuning COSGIFC L Georgia house to 67044/03 2pp
8004150451 Forwards tER SU-C334031-0
MANRY, M. Georgia Power to 80 64/03 ip
- 8004150455 (ER 80-030/03c c on 800320, while performing turbine control valve rast closure pressure suitch calibri 2071-N005D found at less than Tech Sp. limit Caused by instrument dilft Instrument recalibli NIX R Y Georgia Power to 80/04/03 2pp
8004150476 Forwards LER 89-031/017-0
MARRY, M. Georgia Power Co. 80/04.
                                                                                     80/04/07 15
--8004150481 LER 80 031/017-0 on B00327 during performance of 18-month tests on station baftery chargers 2A.2B ½ 2C, chargers were unable to maintain load limits Caused by imbalanced silicon control rectifiers / halajosted current limit module COGGIN.C L Georgia Power Co 80/04/06 2pp
8004150562 Forwards LER 80-032/01T-0
MANRY II Georgia Power Co 80/04/07 ip
--B004150572 LER 80-032/01T-0 on 800327.during maint outage b
surveillance test-noted that 2D PSW pump sequenced to bus in
2 to 5-s Cause unknown
COGGIN-C L Georgia Power Co B0/04/08 2pp
8004280531 RO 50-366/1780-045 on 800405, during cold shutdown, leak rate
     test on automatic depressurization sys valve air supply accumulator check valves indicated unacceptable leakage rates Cause under investigation No immediate action taken HANRY.H Georgia Power Co 80/04/07 2pp
8004220515 Forwards LER 80-039/03L-0
MANRY.M Georgia Power Co 80/04/
                                                                                      80/04/15 1s
   -8004220617 LER 80 039/03L-0 on 800325, while performing standby gas treatment ventilation surveillance, no flow established at 2746-00016 filter train Caused by tailure of 2746-00018 fan motor urining Motor repaired NIX.R T Georgia Power Co 80/04/15 2pp
8004220628 Forwards LER 80-033/03L-0
MANRY.M Georgia Power Co 80/04/15 [p
  --8004220036 LER BO-033/03L-0 on BC0331, while in cold shutdown, triaxial peak recording accelerometers on reactor pedestal & feedwater inlet line were not callor within time limit Caused by instrument failure during callor NIX.R T Georgia Power Co 80/04/15 2pp
BO04220662 Forwards LER BO-034/03L-0
MANRY.M Georgia Power Co B3/04.
                                                                                    83/04/15 1p
--8004220667 LER 80-034/03L-0 on 800320, while performing calibr on main
steam line, temp switches 2321-N010A, N013A & N013D found to
have bad repeatability Gaused by Instrument drift Calibr
procedure revised
NIX.R T Georgia Power Co 80/04/15 2pp
          1220728 Forwards LER 80-045/017-0
INRY,M Georgia Power Co 80/04/15 1p
     3004220736 LER G0-045/01T-0 on 800404, while in cold shutdown, leak rate test was performed on auto depressurviation sys valves air supply accumulator check valves Leaks wore beyond acceptable rate Cause unknown Valves will be repaired prior to startup GUGOIN.C L Georgia Power Co H0/04/15 2pp
 004220664 Forwards LER 80-040/03L-0
MANRY,M Georgia Power Co 80/04/16 1p
   -8004220671 LER 80-040/03L-0 on 800331 during review of outage surveillances requirements, cycle surveillances required by Amend 12 to Tech Speecs had not been conducted Caused by operational conflict Tests will be performed before startup COGGIN.C L. Georgia Power Co. 80/04/16 2pp
```

```
8004220652 Forwards LER 80-03//03L-0
MANRY M Georgia Power Co 80/04
                                                                                           90/04/17 in
     --8004220658 LER 80-037/03L 0 on 800328, while in cold shutdown &
               204220638 LER 80-03/1012 O on 300326, while in columnia personning reactor water chemistry, noted chloride concentration was O 116 ppm Cause attributed to reactor water cleanup sys out for 26-days Cleanup sys fixed ROCERS, W H Georgia Power Co 80/04/17 2pp
    8004220705 Forwards LER 80-043/03L-0
MANRY,M Georgia Power Co 80,04/17 ip
    --80042207)7 LER 80 043/03(-0 on 80040), while in cold shutdown 8 performing insp required by IE Bulletin 80-03, noticeable amount of carbon found on Floor of both trains of refueling floor ventilation sys Probably caused by improper packing ROGERS, W H Georgia Power Co 80/04/17 2pp
   8004220706 Forwards LFR 80-044/03L-0
MANRY, M. Georgia Power Co. 80/04/17 10
    --8004220718 LER 80-014/03L-0 on 800402.during calibi procedure, found drywell sensor 2747-No/3 incorrectly connected to suppression pool vapor temp indicator to temp sensor 2748-No/3 incorrectly connected to drywell temp indicator NIX/R T Georgia Power Co 80/04/17 2pp
   8004220726 Forwards LER 80-035/03L-0
MANRY.M Georgia Power Co 80/04.
                                                                                            80/04/17 1p
   ~-8004220735 LER 80~039/03L-0 on 900321, during calibr procedure HNP-2-5329, all but six accumulator pressure switches found to be outside Tech Specs Caused by personnel error & component failure Pressure switches recallbr NIX.R T Georgia Power Co. 80/04/17 2pp
   8004280416 Forwards LER 80-041/03L-0
MANRY, M Georgia Power Co 80/04/21 ip
   --B004280419 LER 80-041/03L-0 on 800401, during performance of LLRT, feeduater isolation valve 2B21-F077A did not have acceptable results during initial test Caused by natural wear & tear to valve seat Leak 1ste limit met by corrective maint COGOIN, C. L. Georgia Power Co. 80704/21 2pp
  8004280441 Forwards LER 80-036/03L-0
MANRY, M OBORGLE Power Co 80/04/
                                                                                         80/04/22 1p
   --8004280447 LER 80-036/03L-0 on 800326, during ILRTs, while shut down for surveillance vent/header deflector installation outage, feedwater check valve digual purge inlet isolation valve & ILRT verfsfication flow isolation valve failed tests COGGIN.C Georgia Power Co 80/04/22 3pp
  DUCKET 50-367 BAILLY GENERATING STATION
  A Application/construction stage documents & correspondence
 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D. F. Division of Pieject Management 80/02/05 7pp
 8004020466 Notification of 800326 & 27 meeting w/representatives from Mark II owners group in San Jose, CA to discuss Mark II Creace Test Program, 4T c/o tests & foreign tests ELTAHILA,F Containment Systems Branch 80/03/10 12pp
8004030122 Notification of 800324-27 meeting w/Mark II owners group, NRC consultants & CE in San Jose:CA to discuss Mark II creare test program, 4T C/O % Foreign tests Topics are proprietary Agenda encl ELTANILA.F Containment Systems Branch 80/03/10 12pp
8004040474 Summary of 800227 meeting w/Hark II owners group re status of several long-term program tasks, including Tasks A 17 & A 16 & task related to utilization of foreign tost data ELTAWILA, F Containment Systems Branch 80/03/18 104pp
8004100507 Requests add1 info re methods used to measure corrosion potential of piles info as to whether std ABTM tests or std NACE tests were used is required RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/28 3p
```

- 8004150047 Summary of 800310 meeting w/Corps of Engineers & MRC consultants in Bethesda,MD re issues of pile driving at site
 THOMPSON,O O Geostiences Branch 80/04/02 7pp
- 8004150084 Notification of 800417 meeting w/util in Chicago, IL re pile driving sawes LYNCH.M D Light Water Reactors Branch 4 80/04/02 4pp
- 8004240502 Discusses status of plant review re foundation pilings Corps of Engineers is reviewing geotechnical engineering aspects of proposed plant Particular effort is being concentrated on Category I pile driving, suspended by NRC
 THOMPSON.O Q Geosciences Branch 80/04/03 2pp
- 8004300064 Summary of 800326-27 meetings w/Mark II owners group in Ban Jose,CA re discussion of NRC concerns on data from Create tests & foreign fuli-scale test programs & relationships w/ Mark II designs ELTAWILA,F Containment Systems Branch 80/04/14 22pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending 0AO clearance under Federal Repts Act ORIMES, B K Emergency Preparedness Task Force 80/03/i1 4pp
- Q Adjudicatory correspondence
- 8004230091 Requests to institute proceeding & to suspend or revoke CP Urges admittance of Porter County chapter of Izaak Walton League of America, Concerned Citizens Against Bailly Nuclear Site, et al. as parties W/Certificate of Svc & documentation VOLLEN.R J Vollen, R J DSANN, E W Osann, E W GRAHAM, R i Oraham, R L 76/11/24 107pp
- --8004230073 Symmary of 760604 meeting w/util & Natl Park Svc to discuss Bailly & IN Dunes Natl Lakeshore Meeting re technical discussion will take place in future OEKLER.R P Environmental Projects Branch 1 76/06/29 4pp
- --8004230096 Bummery of 760603 meting at IN Dunes Natl Lakeshore on Bailly site to discuss fossil & planned units & monitoring efforts Urges consideration of technical & mgt meetings GECKLER.R P Environmental Projects Branch 1 76/06/30 Spp
- --8004230101 Request for hearing re CP amend extending completion to 850901 Certificate of 8vc encl
 VOLLEN,R J Vollow, R J OSANN,E W OSANN,E W GRAHAM,R L
 Graham, R L 79702727 4pp
- 8004040069 Joint interveners response stating no objection to State of IL 800215 motion for continuance re CP extension proceeding Certificate of Svc encl VOLLEN.R J Vollen.R J 80/02/20 3pp
- 8004080169 Opposes extention of facility const data ARNURIUS, Q Affiliation Unknown 80/02/23 1p
- 8004020214 Natice advising of ASLB denial of Joint Intervenors' motion re CP extension Formal order will be issued on 800303 Certificate of Syc encl VOLLENRY Vollen, R. J. 80/02/25 App.
- 8004010294 Contention by City of Cary, IN. United Steelworkers of America, Bailly Alliance, Bave the Dunes Council & Critical Mass Energy Project Guestions whether realistic evacuation & emergency plans may be implemented adequately, COHN, D B Cohn, D B SCHULTZ, W B Schultz, W B 80/02/26 1p
- --8004010300 Reply in opposition to NRC & Northern IN Public Svc Commission responses to petition to intervene re CP extension Supporting affidavits & Certificate of Svc enci COMN.D B Cohn. D B SCHULTZ.N B Schultz. N B 80/02/26
- 8004020478 First suppl to putition to intervene by joint intervenors, alleging that extension of completion date is not based on good cause required by Atomic Energy Act Certificate of Svc VOLLEN, R J Vollan, R J 80/02/24 22pp
- 8004020280 Responds to Eichhorn 800227 Itr Arrangements will be made re pick up of applicant responses to supplemental petitions at convenient time Certificate of Syc encl SHEA, K H Lowenstein, Newman, Reis, Axelrad & Toli 80/02/27 4pp

- 8004020092 Response in opposition to G Echulti, A ? G Grabowski, State of IL.City or wary ? Porter County Chapter supplemented petitions to intervene riled in response to ASLB 800207 order Urges denial of hearing requests W/Certificate of Svc EICHHORN, W H., SMEA, J. R. Noithern Indiana Public Service Co EICHHORN, W H., Eichhoin, Eichhorn ? Link 80/03/07 75pp
- 8004049053 Kotice of appearance in CP extension proceeding FRANTZ,S P Northern Indiana Public Service Co FRANTZ,S P Lowenstein, Neuman, Reis, Azelrad & Toll 80/03/12 ip
- 8004140125 Forwards NRC 770926 memorandum re NUREG-0625, "Rept of Siting Policy Task Force" Memorandes that Bailly alone of all nuclear plants farl, ill six siting criteria State of IL will assist pio se intervenor filing HANSCLL.D Illinois, State of 80/03/19 4pp
- ~-8004140127 Discusses NUREG-0625. Pecommendation 2 Complete survey of QL & CP sites for hazardous facilities, airports A pipelines cannot be completed for 771004 briefing Approx 10-20/ of existing sites would fail first three distance criteria HDUSTON, R W Accident Analysis Branch 77/09/26 Bpp
- 8004140130 Request for hearing se aplicant 790207 request for extension until 850901 to complete const NRC cannot determine that amend involves no significant hazards consideration Centificate of Svc encl HANSELL, D 111:nois. State of 79/03/05 4pp
- 8004300133 Supplemental statement re standing Contends that members of United Steel Workers of America Local 1010 are users of IN Dunes Natl Lakeshore in which site dewatering will take place due to const W/afridavit N. Certivicate of Svc FRANTZ.J United Steelworkers of America 80/03/26 1p
- 8004230105 Draws attention to Commission 800313 order to be considered prior to issuance of pichearing conference order re stds applied for standing to intervene SHEA.K H Lowenstein.Kowman.Reis.Axelrad % Toll 80/03/27 2pp
- 8004080567 Order requesting parties to submit views on apparent deficiencies in 800312-13 special prohesiing conference transcriptiby 800416.ie CP extension proceeding GROSSMAN,H Atomic Mafety and Licensing Board Panel 80/03/28
- 8004230028 Motion for add1 time to file contentions & first suppl to intervention petition in CP extension proceeding Dewatering info should be reconsidered at 3-yr interval Affidavit, motion & Ceptificate of Syc enc!

 ROBBINS, R. L. Lake Michigan Federation 80/03/28 lipp
- GOO4110576 Responds to request for info ie CP extension proceeding Participant pro-se in NRC adjudication may be relieved of requirement to file 20 copies of all documents on Secretary of Commission in accordance w/100FR2 708(4) GOLDBERG. S C Hearing Branch 2 80/03/31 2pp
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- BOO410000B Order relieving G % A Grabowski from 20-copy requirement for pleading & documents filing in CP extension proceeding GROSSMAN.H Atomic Safety and Licensing Board Panel 80/04/02
- B004210425 Brief in response to ARLB request during B00312-13 special prehearing conference Interrelationship between ash pond sagpage & const dewatering was fully litigated during CP hearings % is now baried from reconsideration GOLDBERG, B C Hearing Branch Z 83/04/10 5pp
- --8004210431 Affidavit stating observations on relationship between ash ponds for applicant coal-fired plants 2 facility const site dowatering Prof qualifications 3. Certificate of Svz encl GECKLER, R P Division of Site Safety 1. Environmental Analysis 80/04/09 9pp
- 8004150223 Position stating that good cause for CP extension need not be beyond control of permit holder under 10CFR50 35(b) Prior practice, pur Diablo Canyon & other cases, has accepted need for applicant evaluation, as good cause W/Certificate of Svc GDDDARD, R J Hearing Branch 2 80/04/11 11pp

- 3004150258 Response to ARLS 300328 order seeking views re-preheating conference transcript of CP extension proceeding Suggests issuance of claritying instructions due to inferior quality or transcript that may arrect trindings WiCertificate of Svc OODDARD: R J. Hearing Branch 2 30/04/11 5pp
- 8004210209 Response in opposition to Lake MI Federation 800328 motion to file contentions ? first suppl to petation to intervene If Federation is granted intervention, participation should be limited to issue of const dewatering (//Certificate of Svc GOLDBERG,S C Hearing Branch 2 80/04/17 8pp
- 8004250415 Confirms 800502 meeting at IL Atty General Ofc, Chicago IL to discuss contentions ad anced in CP extension proceeding GOLDBERG.S C Hearing Branch 2 H0/04/23 1p
- BOO4300388 States no objection to granting C & A Grabowski BOO402 second supplied intervention potition in CP extension proceeding NRC has no intention to tile formal response GOLDBERG.S C Hearing Branch 2 BO/04/28 ip

H General correspondence

- 8004080170 Opposes extension of CP Plant so close to homes of millions of people is too dangerous

 HECK.A E Affiliation Uninoun 80/02/22 ip
- 8004070364 Responds to 790916 request that LPDR be established in Indianapolis, IN MRC establishes LPDR in immediate vicinity of proposed 5 operating commercial nuclear power plants Applicable LPDR locations 6 hours of operation enci SOUDER.J L Division of Rules and Records 80/03/13 3pp
- --8004070973 Requests establishment of LPDR in Indianapolis.IN Believes that LPDR would be appreciated & well-used by citizens of Indianapolis BENNETT,C L Affiliation Unknown 79/09/16 2pp
- 8004080165 Opposes const of facility due to proximity to Chicago & increase in disaster potential CLARK,M , FRIGO.R , WHITSHURST.C Affiliation Unknown 80/03/15
- P Operating license stage documents & correspondence
- 8004150461 Pleading supplementing State of IL 791121 ltr treated under 10CFR2 206 Urges institution of hearing re siting adequacy to development of emergency evacuation plan Requests that issue he decided by Commission or ASLS Cartificate of Svc encl SCOTT. U.J., HANSELL, D. 1111nois, State of 80/04/10 Spp

O inspection reports, IE Bulletins & correspondence

- 8004100139 Forwards IE Info Notice 80-09, "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEFPLER.J G Region 3. Chicago. Office of the Director 80/03/07
- 8004150180 Forwards lE Info Notice 80-12. "Instrument Failure Causes Opening of FORV & Biock Valve " No specific action or response necessary KEPPLER, J G Region G. Chicago, Office of the Director 80/03/31
- 8004080718 Forwards IE Circular 80-05. "Emergency Dirsel Generator Lubricating Oil Addition & Onsite Supply " No written response required EPPLER.J © Region 3. Chicago. Office of the Director 80/04/01

 - 150048 Forwards IE Info Notice 80-13, "GE Type SEM Control Switches fective CAM Followers " No specific action or response
 - EPPLER, J G Region 3, Chicago, Ofrice of the Director 80/04/02
 - 04180054 Forwards attachments to [E Circular 80-03, "Protection From Foxic Gas Hazards," inadvertently omitted from 800306 (EPPLER, J & Region 3, Chicago, Office of the Director 80/04/02
 - 04220149 Forwards 1E Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02

- 8004220382 Forwards IC Circular 80-07, "Problems W/HPCI Turbine Oil Sys "No written response required
 KEPPLER, J G Region 3. Chicago. Office of the Director 80/04/03
- 8004110043 Forwards IF Bulletin 80-07, "BWR Jet Pump Assembly Failure" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07
- 8004230280 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required KEPPLER. J G Region 3. Chicago, Office of the Director 80/04/07
- 8004220114 Forwards IE Builetin 80~08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J.G. Region J. Chicago, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- 8004080331 Forwards well charts for 800313-19, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water mater leadings / USGS wells for 800319 BONN,R J Northern Indiana Public Service Co 80/03/28 33pp
- 8004150453 Forwards well charts for 800319-26 & Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USCS wells for 800326 NGHN,R J Northern Indiana Public Service Co 80/04/07 33pp
- B004220553 Forwards well charts for B00326-0402.Bailly wells w/o recorders, pand levels, pneumatic pressure transducers, water meter readings & USGS wells for B00402 BCHN.R J Northern Indiana Public Service Co B0/04/11 33pp
- 8004280494 Forwards well charts for 800402-10, Bailly wells w/o recorders for 800410, pond levels for 800410, pneumatic pressure transducers, water meter readings for 800409, USOS wells for 800409 & rainfall data for 800401-0331 BOHN, R J Northern Indiana Public Service Co 80/04/18 3 80/04/18 34pp
- 8004300431 Forwards well charts for 800410-16, Bailly wells w/o recorders pond levels, pneumatic pressure transducers; water mater readings & USGS wells for 800416 BOHN,R J Northern Indiana Public Service Co 80/04/25 33pp
- DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2 F Security, medical, emergency & fire protection plans
- 8004030107 Approves design of cable spreading room fire barrier, in response to util 800220 request Barrier located at cabling nexus of redundant same shutdown divisions Status of fire protection review mods encl
 LAINAS.0 Plant Systems Branch 80/03/17 2pp
- 8004010386 Advises that all fire protection mods will be complete by 801001 except Unit 2 Items 3 14 & 3 18 Hardware mods for Item 3 18 scheduled for Mar 1781 cold shutdown Smoke detector sys for Item 3 14 will be installed when complete TRIMBLE, D C Arkanses Power & Light Co 80/03/26 2pp
- 8004150567 Forwards drawings & description of mods for containment bldg manual hose stations as required by fire protection safety evaluation Drawings available in Central Files only TRIMBLE.D C Arkansas Power & Light CO 80/04/09 20pp
- ---8004150579 "Hydravisc Calculation for Containment Hose Reel Project " HUFF.M , FRANCE,E R , SANDERG,D Artansas Power & Light Co 80/02/04 17pp
- --8004150590 "FAAST Fluid Analysis & Simulation Technique, Usar Info * Control Data Corp 78/03/19 13800
- --8004150601 "Hydraulic Calculations Containment Hose Reel Project (DCP-2085)(FAAST Output) " HUFF,M., FRANCE,E R., SANDERS,D. Arkansas Power & Light Co 80/01/17 Blpp

H General correspondence

- 8004100581 Responds to 791212 ltr re computers & safety stds used in nuclear power plants Digital computers used for monitoring operations & core protection calculator sys provides protection functions DENTON.H R Office of Nuclear Reactor Regulation 80/03/27 ip
- ~-8004100582 Requests info re reliability of computers that control nuclear plants & safety stds since accident BRADSHAW,M Affiliation Unknown 79/12/12. ip
- 8004280347 Responds to 800321 ltr requesting summary sheets for aperating reactors Forwards sheets prepared in months prior to issuance of OLs W/o encl DENTOW, R R Defice of Nuclear Reactor Regulation 80/04/04 1p
- --8004280352 Requests info re performance evaluations of all reactors since first CP was granted
 WEST, B Affiliation Unknown 80/03/01 ip
- B004170240 Requests that util be required to submit EIS before authority is granted to expand nuclear waste fuel storage pools at site Prior EIS insufficient PETERS.B. Affiliation Unknown 80/04/09 2pp

I Financial information

- 8004220535 Annual Financial Rept 1979 * Middle South Utilities, Inc. 79/12/31 40pp
- 8004150235 Forwards Annual Financial Rept 1979
 TRIMBLE,D C Arkenses Power & Light Co 80/04/10 ip
- --B004150239 Annual Financial Rept 1979 * Arkansas Power & Light Co 80/04/10 46pp

P Operating license stage documents & correspondence

- 8004110508 Summarizes walkdown re identifying seismic Category I piping & safety-related sys attached to or in close proximity to concrete block walls Numbers are preliminary & may be adjusted upon survey completion on 800130
 TRIMBLE, D C Arkansas Power & Light Ca 80/01/28 ip
- B004070160 Forwards NRC evaluation of actions taken to satisfy Category A requirements of TMI-2 Lessons Learned All Category A requirements have been met satisfactorily w/exception of Item 2 i 7a for Unit 2 REID.R W Operating Reactors Branch 4 80/03/10 2pp.
- --8004070170 "Evaluation of Licensee Compliance W/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned " # Operating Reactors Branch 4 80/03/31 13pp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Derations Ctr EISENHUT, D O Division of Operating Reactors 80/03/12 5pp
- ~~8004030118 "Nuclear Data Link Epecs " # Division of Operating Reactors 80/02/21, 28pp.
- 8004030209 Provides descriptions of long-term Lessons Lwarned changes to plant shielding & modified sampling sys to minimize personnel exposure during worst case accident conditions TRIMBLE, D C Artansas Power & Light Co 80/03/31 7pp
- BOO4070287 Forwards proposed change to Paragraph 15 2 2 constituting Ravision 5 to APL-TOP-1A, "GA Manual, Nonconforming Matl, Parts or Components" TRIMBLE, D. C. Arkansas Power & Light Co. 80/03/31 1p
- --8004070403 Proposed change to Paragraph 15 2 2 of "QA Manual, Nonconforming Mati.Parts or Components" # Arkansas Power & Light Co ALP-TOP-1A 80/03/31 2pp
- 8004150304 Forwards brief description of safety evaluation for design changes completed in 1979 which require safety evaluation per IOCFRSO 59 Mods include emergency cooling pond change, firehouse station addition & increase of sprinkler covarage TRIMBLE.D C Arkansas Power & Light Co 80/03/31 5pp.
- 8004170086 Forwards description of safety evaluation for design changes completed in 1979, TRIMBLE D C Arkansas Power & Light Co 80/03/31 6pp.

- 8004070344 Informs that Sertion 2 & 3,Revision 5 of OA manual re diesel generator fuel oil meets Tech Spec requirements per 800107 request TRIMBLE.D C Artansas Power & Light Co 80/04/03 1p
- 8004280089 Forwards request for addl info re 790924 request for amend to License NPF-6 conceining response time for steam driven emergency feedwater pumps Supporting analysis showing no decrease in safety margin from change should be provided REID.R W Operating Reactors Branch 4 80/04/04 Jpp
- @ Inspection reports: 16 Bulletins & correspondence
- 8004090151 Forwards IE Insp Repts 50-313/80-01 & 50-368/80-01 on 800107-18 % notice of violation MADSEN.G L Region 4, Dallas. Reactor Operations Nuclear Support Branch 80/02/01 2pp
- --8004070153 Notice of violation from insp on 800107-18
 * Region 4. Dallas. Office of the Director 80/02/ 80/02/01 2pp
- --8004090159 IE Insp Repts 50-313/80-01 & 50-348/80-01 on 800107-18 DAMYOLDY IE. Insp. Repts. 50-313/80-01 & 50-368/80-01 on HOOLD/Noncompliance noted data sheets recorded relay setting only
 & did not contain sufficient info & calibr & testing program
 for protective relaying was deficient in procedures
 SPANGLER, R. G. SMITH, R. WESTERMAN, T. F. Region 4, Dallas, Di
 of the Director 80/02/01 App Region 4, Dallas, Office
- 8004100315 Forwards 1E Insp Repts 50~313/80-02 & 50~368/80-02 on 791222-800121 & notice of violation MADSEN.G L NRC Regional Offices 80/02/08 2pp
- --B004100324 Notice of violation from insp on 791222-800121 * NRC Regional Offices B0/02/06 1p
- --8004100335 IE Insp Repts 50-313/80-02 & 50-368/80-02 on 791222-800121
 Noncompliance noted failure to adhere to requirements of
 test procedure
 JOHNSON-W D . CALLAN.L J . WESTERMAN.T F NRC Regional Offices
 80/02/06 Spp
- 8004040089 Forwards IE Insp Repts 50-313/79-24 & 50-368/79-23 on 791109 No noncompliance noted MADBEN.O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004040094 IE Insp Repts 50-313/79-24 & 50-368/79-23 on 791109 No noncompliance noted Major areas inspected current NRC & DOT regulations, current requirements of waste burial firms, instructions & operating procedures & audit program HARRISON.H C Region 4. Dallas, Office of the Director BROWN, 0 D. Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/01/16 App
- 8004250103 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Util has reviewed applicable buses No buses identified which could affect ability to achieve cold shutdown TRIMBLE.D C Arkansas Power & Light CO 80/02/28 2pp

- @CO4250.45 If the Propher of the Shindle SO-368/80-04 on 800131 & 0201 to notice application in the literature and an inspected practices of licensee has the ray of some arms of maint contracted.
 - personnel BRANKE & D. Pegron 4 (sites, fuel facility 1 Materials Safety Branco WE Edicket > 10 MEOR & Region 4. Dallas, Office the Director 30 MB), Tpp Region 4. Dallas, Office of the Director
- 9004190231 F. wains le Int. Intice De-I. Instrument Failure Causes Opening of (1860) Aloni (I.A. In specific action or response necessar) SEMFRITIE V Region & Calley Office of the Director 80/03/31
- 3004090566 Forward, IE Cit-blat 20-05, "Emergency Diesel Generator Lubricating (1) Addition 1 diesels Supply 1 No written response required
- Region 4, Inilia Offsia of the Director 80/04/01
- 8004110097 Forwards IE Info Nation 80-13, "GE Type SBN Control Switches Defective CAM Followers" No specific action or response required SEYFRITAN & Region 4 Dallas, Office of the Director 80/04/02
- 8004180493 Forwards If Into Notice 60-14, "Safety Suggestions From Employees No action required SEYFRIT./ V Region 4. Dallas Office of the Director 80/04/02
- 8004180159 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Oil Sys 'No written response required SEYFRITIP V Rejion 4, Pallas, Office of the Director 80/04/03
- BOO4R30324 Forwards It Builetin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required SEYFRIT. K. V. Region 4 Uillas Office of the Director BO/04/04
- R Periodic operating teports & related correspondence
- 8004210274 Forwards monthly operating rept for Mar 1980 TRIMBLE.D C Arkansas Power & Light Co 80/04/11 1p
- --8004210280 Monthly operating rept for Mar 1980 PENDERGRAFT, R Artansas Power & Light Co & 80/04/11 6pp
- 8004290450 Forwards corrections to monthly operating rept for Mar 1980 TRIMBLE D C Arkanias Power & Light Co 80/04/17 1p
- -8004240451 Corrections to monthly operating rept for Mar 1980 PENDERGRAFT.R Arkansas Power / Light Co 80/04/11 3pp
- S Reportable occurrences, LERs & related correspondence
- 7811100178 Describes 780916 event at subj facil auto transfer of autiliary loads on both units to startup transferner #2 w/consequent overload Recomments licensee be advised of nonconformance w/GDC-17 h modify his design ROBA-F Power Systems Branch GATTERFIELD.R Electric. Instrumentation & Control Systems Branch 78/11/01 Bpp
- 3004280521 RD 50-368/80-014 on 800318, after reviewing C-E ltr re discrepancy in shutdown margin for boron dilution in Mode 5 /til notified KRC by tellon Tech Spec change request will be obmitted to ensure greater than 2% shutdown margin 3/HANLGW, J P Arkansas Power & Light Co 80/03/19 ip
 - >4020342 Forwards LER 80-013/03L-0 IRIMBLE.D C Arkansas Power % tight Co 80/03/28 1p
 - 3004020346 LER BO-013/03L-0 on BC0229.during mode 5 operation, reactor cooling sys chloride concentration found to be approx 0 5 ppm.violating Tech Spers Probably caused by batch contaminated during maint on safety injection check valve PENDERGRAFT,R Arkansas Power & Light Co 80/03/28 ip
 - >4080577 Forwards LER 80-016/01T-0 RIMBLE, D C Attansas Power & Light Arkansas Power & Light Co B0/04/01 1p
 - 1004080576 LER 80-016/017-0 on 800318.inconsistency identified between DAGEBOOTO LEE BU-0107011-0 on DOUGLES INCONSISSED UNGLES
 Tech Specs & FSAR sarety analysis Caused by failure of
 initial Tech Specs to determine safety analysis limits
 Reactivity balance calculation procedure revised
 SHIVELY, C N Arkansas Power 3 Light Co 80/04/01 2pp

- 8604150605 Forwards LER 86 014/03L-0 TRIMBLE, D.C. Arkansas Power * Light Co. 80/04/11 1p
- --8004150618 | EF 80 014/URL-D on 800313.during mode 5 operation, local leak rate testing at containment penetration 2V2 revealed excessive lear rate to these valve actuation & heatup processes Caused by partially open inside isolation valve SHIVELY.C N Arkansas Power & Light Co. 80/04/11 1p
- 8004220691 Forwards LFR 80-017/03L-0 TRIMBLE.D C Artansas Power * Light Co 80/04/15 ip
- -8904220703 LER 80-017/03L-0 on 800316 during mode 3 operation, A steam generator pressure indicator 2 Pl-1041-4N on Channel D failed high Caused by electronic output of pressure transmitter plant protection sys failing high SHIVELY C N Arvansas Power 5 Light Co 80/04/15 ip
- DOCKET 50-369 WILLIAM D. MCQUIRE NUCLEAR STATION. UNIT 1 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-058B, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits add1 guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance ROSS,DF Division of Project Management 80/02/21 3pp
- 900423005B Requests info ie auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include tRC approval prior to issuance of OL M/enc!

 ROSS,D F Division of Project Management 80/03/10 53pp
- 8004140123 Forwards request for add1 info re NRC review of LOCA analyses provided in plant FSAR Revisions 29,33,34 & 36 Info should be provided by 800421 BAER,R L. Light Water Reactors Branch 2 80/03/19 4pp
- 8004(70327 "Thi-Plus One Toward a Safer Nuclear Power Program "

 * Dute Power Co 80/03/26 13pp
- 8004070234 Forwards Page 3-10 / Table 3 1-1 of offsite dose caluculation manual, correcting typographical errors Also forwards Page B-1 inadvertently omitted from 800317 submitted or manual PARKER.W O Dute Power Co 80/03/27 1p
- --B004070234 Pages 3-10 5 B-1 & Table 3 1-1 of offsite dose calculation manual * Duke Power Co 80/03/27 3pp
- 9004190051 Summary of 800327 meeting w/util in Bethesda.MD.re scheduling of initial fuel loading & license application BIRKEL, R A Light Water Reactors Branch 2 80/03/28 5pp
- 8004080366 Forwards add1 info requested by NRC 800129 ltr.re emergency diesel generator reliability / implementation of NUREG-0660 recommendations
 PARKER, N O Duke Power Co 80/04/03 11pp
- 8004140430 Forwards comparison of draft STS w/snubber functional test sampling plan COLLINGS, D M Duke Power Co 80/04/03 11pp
- 000400455 Forwards "316(b) Predictive Study of Impingement & Entrainment" % "Consolidated Overview, Baseline Yr 1978-79, " as requested PARKER, W O Duke Power Co 80/04/04 ip
- --8004080459 "316(b) Predictive Study of Impingement & Entrainment "

 ** Duke Power Co 78/10/31 300pp
- --8004680461 "Consolidated Overview, Baseline Yr 1978-79 "
 * Duke Power Co 80/03/31 300pp
- 0004140348 Forwards response to NRC 800219 request for info re environ QUalification of containment pressure transmitters & "Qualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors," Vols 1 & 2 PARKER, W O Duke Power Co 80/04/08 4pp

- --8004140354 "Qualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors," Vol 1, Revision D HATHAKER, D F., DAVIES, L M. Wyle Laboratories 43904-1 V1 RD 78/07/06 4300
- --8004140358 "Qualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors," Vol 2, Revision C BROWN, J , CAMPDELLE R Wgle Laboratories 43904 V2 RC 78/07706 Loopp
- 8004280072 Discusses review of qualitative evaluation of combined failure of 10-inch accumulator line & impinged six-inch hot leg injection line Requests sensitivity analysis of 10-inch coid leg spiit break wisix-inch spiit break LOCA BAER.R L Light Water Reactors Branch 2 80/04/09 3pp
- 8004280076 Ack receipt of util 791226 response to NRC request for independent field audit of installed electrical sys & equipment Util review lacks performance of detailed field audit by independent group BAER.R L Light Water Reactors Branch 2 80/04/09 4pp
- 8004300142 Requests submittal of three listed items on NRC docket to provide retrievable technical ref sources on guide tube user Info should be incorporated in next revision to FBAR BAER,R L Light Water Reactors Branch 2 80/04/11 3pp
- 8004220720 Incorporates three ltr refs into 791214 response to NRC 790911 request for info re fuel assambly guide thimble tube wear Refs consist of TM Anderson 780912, 1015 & 790627 ltrs to DO Eisenhut PARKER, W O Duke Power Co 80/04/16 ip
- 8004270493 Forwards "Statistical Analysis of Mechanical Properties for Containment Plates & Weld Filler Metal " & drawings re Ames Lab statistical design parameters for containment Drawings available in Central Files only PARKER, W O Duke Power Co 80/04/24 2pp
- --8004270501 "Statistical Analysis of Mechanical Properties for Containment Plates & Weld Filler Metal " HUFFAKER,T Duke Power Co IRLEYN,K S Consumers Power Co BO/04/21 5pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending 0A0 clearance under Federal Repts Act ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004030152 Forwards info in support of standby shutdown facility Encl withheld (rof 10CFR2 770) PARKER.W O Duke Power Co 80/03/31 1p
- 8004180273 Forwards Revision 7 to modified amended security plan Flan withheld (ref 1007R2 790) PARKER.W O Duke Power Co 80/04/14 1p
- 9 Adjudicatory correspondence
- 8004230078 Forwards 800328 SECY-80-166 requesting amend to irradiated reactor fuel in-transit physical protection requirements If amend approved effect on NRC case re spant fuel transportation & storage will be provided HOEFLING.R K Hearing Branch 4 80/04/01 1p
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 00S81CK/L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004180432 Forwards NRC 800403 ltr w/encl commercial newspaper advertisement re resumption of evidentiary hearings NRC wishes to notify public officials of counties in which proposed alternate routes are located KETCHEN.E O Hearing Branch 4 80/04/08 ip
- --B004180441 Notifies of resumption of evidentiary hearings re amend of License 8MM-1773 Proposed action is to transport up to 300 spent fuel assemblies from Oconee nuclear facility to McOuire nuclear facility Commercial newspaper notice encl RDUBE.L C Advanced Fuel & Spent Fuel Licensing Branch 80/04/03

- 8004160197 Forward, by Spitalny, Jk Dorichew CR Harotta & E Lantz prefiled testinonies se amend to License SNH-1773 for Oconeo spent fuel transportation & storage at McGuise KETCHEN, E.G. Hearing Brinch 4 80,04/11 2pp
- --8004160179 Prefiled textimony re 800428 hearing Updatos license ame recoid re-spent fuel handling % storage alternatives status of NRC spent fuel cash review / pin compaction application SPITALNY, B S Advanced Fuel / Spent Fuel Licensing Branch 80/04/11 Spp
- --8004160210 Supplemental NRC rept "Spent Fuel Storage of Oconee Spen Fuel at McGuire Nuclear Station - Unit 1 " * Commission 60/04/11 Ppp
- --8004160219 Prefiled tostimony re-doses caused by Doonee spent fuel assembly rupture while stored at McGuire spent fuel pool Converts MRC 800208 arridavits to question & answer format Profi qualifications encl DONDHEW.J N Environmental Evaluation Branch 80/04/11 13pp
- --8004160221 Testimony re ASLB questions at Transcript A027 % 4432-47 concerning whether fuel stored in McGuile spont fuel pool would remain subcritical it cask falls onto pool Converts NRC 600208 affidavits to question % answer format MARDITA, C.R. Office of Nuclear Material Safety & Safeguards 80/04/11 2pp
- --8004160224 "NRC Criticality Analysis of McGuire Spent Fuel Pool Containing Geomeo Spent Fuel for Cask-Drop Accident " Prof qualifications encl MAROTTA.C R Uffice of Nuclear Material Safety & Safeguards 80/04/11 10pp
- --8004160227 Testimony re ASLB questions at Transcript 4027 & 4432-47 concerning whether fuel stored in McGuire spent fuel pool would remain subcritical it cask falls onto pool Converts NRC 800208 affidavits to question & answer format LANTZ.E Division of Operating Reactors 80/04/11 2pp
- --8004i60230 "Supplemental Criticality Analysis for Proposed Transfer Spent Fuel From Oconee to McGuire " Prof qualifications encl LANTZ.E Division or Operating Reactors 60/04/11 5pp
- --8004160235 Affidavit re occupational doses caused by Oconee spent for assembly rupture, at 270 days in age, when stored in McGuire spent fuel pool Completes NRC response to ASLB 791031 order Supporting documentation encl
 DDNUHEW, J N Environmental Evaluation Branch 80/04/10 8pp
- --8004160240 Affidavit re occupational doses caused by Occupe spent for assembly rupture, at 40 days in age, when stored in McQuire spent fuel pool Completes NRC response to ASLU 791031 order Supporting documentation encl
 DONOHEW, J N Environmental Evaluation Branch 80/04/10 App

- 8004150070 Forwards IE Info Notice 80-13 "GE Type SBM Control Switches Defective CAM Followers ' No specific action or response required
 O'REILLY, J. F. Region 2. Ailanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Into Notice 80~14 "Safety Suggestions From Employees "No action required O'REILLY J P Region 2: Atlanta, Orfice of the Director 80/04/02
- 8004180326 Forwards IE Circulai 80-07, "Problems W/HPCI Turbine Dil Sys " No written response required O'REILLY. J P Region 2 Atlanta, Office of the Director 80/04/03 200
- 8004230132 Forwards IE Bulletin 77-03A 'Longitudinal Held Defects in ASHE SA-312.Type 304 Stainless Steel Pipe " Action required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/04 80/04/04
- 8004180358 Forwards IE Bulletin 80-08, "Eram of Containment Liner Penetration Welds "Written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director B0/04/07
- S Reportable occurrences. LERs 3 related correspondence
- 8004080101 Part 21 rept re deviation which could result in reduction of integrity of RCPB Valve bonnet flange weldment was liquid penetrant examined on one side only Personnel will complete examination
 HILLER, H L Dute Power Co 80/03/11 3co
- 8004020348 Forwards Significant Deficiency Rept SD 369-370/80-02 re steam generator narrow range level transmitter cables PARKER.N O Duke Power Co 80/03/27 lp
- --B00402035B Significant Deficiency Rept SD 3A9-370/80-02 re failure of steam generator narrow range level transmitter cables to meet environ qualification requirements Sixteen cables in Unit 1 will be replaced & new cables installed in Unit 2 a Duke Power Co 80/03/27 ip
- DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addi guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance RQSS.DF D'vision of Project Management 80/02/21 3pp
- B004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Tasi Force review of TML-2 accident info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of DC M//encl ROSS.D F Division of Project Management 80/03/10 53pp
- 9004140123 Forwards request for addl info re NRC review of LOCA analyses provided in plant FSAR Revisions 29.33.34 & 36 Info should be provided by 800421 BAER.R L Light Water Reactors Branch 2 80/03/19 4pp
- 8004170327 "THI-Plus One Toward a Safer Nuclear Power Program " # Duke Pawer Co 80/03/26 13pp
- BG04070234 Forwards Page 3-10 & Table 3 1-1 of offsite dose caluculation manual.correcting typographical errors Also forwards Page 8-1 inadvertently omitted from 800317 submittal of manual PARKER.W O Duke Power Co 80/03/27 ip
- --8004070236 Pages 3-10 & B-1 & Yable 3 1-1 of offsite dose calculation * Duke Poter Co 80/03/27 3pp
- 8004150051 Summary of B00327 meeting w/util in Bethesda.MD.re scheduling of initial fuel loading & license application BIRKELIR A Light Water Reactors Branch 2 80/03/28 5pp

- 8004080366 Forwards add1 info requested by NRC 800129 ltr,re emergency diesel generator reliability & implementation of NUREO-0660 recommendations
 PARKER-W O Duke Power Co 80/04/03 lipp
- 8004140430 Forwards comparison of draft STS w/snubber functional test sampling plan COLLINGS,D M Dute Power Co BD/04/03 11pp
- 8004080455 Forwards "316(b) Predictive Study of Impingement & Entrainment" & "Consolidated Overview Baseline Yr 1978-79." Duke Power Co 80/04/04 1p
- --8004080459 "316(b) Predictive Study of Impingement & Entrainment "

 Duke Power Co 78/10/31 300pp
- --8004680461 "Cansolidated Overview, Naseline Yr 1978-79 "
 -- Buke Power Co 80/03/31 300pp
- 8004146348 Forwards response to NRC 800219 request for info re environ qualification of containment pressure transmitters & "Qualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors," Vols 1 & 2 PARKER. W O Duke Power Co 80/04/08 4pp
- --8004140354 "Gualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors," Vol 1, Revision B HATMAKER, D. F., DAVIES, L. M. Hyle Laboratories 43904-1 V1 AB
- ---B004140358 "Qualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors: "Vol 2.Revision C BRGNN,J , CAMPBELL.E R Wyle Laboratories 43904 V2 RC 78/07/06 loopp
- B0042B0072 Discusses review of qualitative evaluation of combined failure of 10-inch accumulator line & impinged six-inch hot leg injection line Requests sensitivity analysis of 10-inch cold leg split break whist-inch split break LOCA BAER.R L Light Water Reactors Branch 2 80/04/09 3pp
- 8004280076 Ack receipt of util 791226 response to NRC request for independent field audit of installed electrical sys & equipment Util review lacks performance of detailed field audit by independent group BAER.R L Light Water Reactors Branch 2 80/04/09 4pp
- B004300142 Requests submittal of three listed items on NRC docket to provide retrievable technical ref sources on guide tube wear Info should be incorporated in next revision to FBAR. BAER. R L Light Water Reactors Branch 2 80/04/11 3pp
- 8004220720 Incorporates three ltr refs into 791214 response to NRC 790911 request for info re fuel assembly guide thimble tube wear Refs consist of TM Anderson 780912,1015 & 790627 Itrs to DO Eisenhut
 PARKER. W O Duke Power Co 80/04/16 ip
- 8004270493 Forwards "Statistical Analysis of Mechanical Properties for Containment Plates & Weld Filler Metal " & drawings re Ames Lab statistical design parameters for containment Drawings available in Central Files only PARKER, W O Duke Power Co 80/04/24 2pp
- Containment HUFFAKER: T D
- F Security, medical, emergency & fire protection plans
- 80040B0077 Advises that submittal date for evacuation time setimates, requested by NRC 791224 ltr.has been postponed pending GAD clearance under Federal Repts Act ORIMES, B K Emergency Preparedness Task Force 80/03/11 App.
- 8004030192 Forwards info in support of standby shutdown facility Encl withheld (ref 100FR2 790) PARKER, H O Dute Power Co 80/03/31, 1p
- @ Adjudicatory correspondence
- BO0423007B Forwards B0032B SEGY-B0-166 requesting amend to irradiated reactor fuel in-transit physical protection requirements if amend approved effect on NRC case re spent fuel transportation & storage will be provided HOEF4.ING,R K Hearing Branch 4 80/04/01 ip

- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification QOSSICK.L. V Office of the Executive Director for Operations 80/04/02 34pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004180516 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Btd Type II.Two-Inch,Tray Adsorber Cells " Lists charcoal filters for which visual insp was performed No significant charcoal leakage found PARKER.W O Duke Power Co 80/03/21 2pp
- 8004180511 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080611 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oll Addition & Onsite Supply " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/01
- 8004150070 Forwards 1E Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180326 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 011 8ys " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004230132 Forwards IE Bulletin 79-03A "Longitudinal Wald Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Action required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004180358 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Helds " Written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/07 2pp
- 8 Reportable occurrences. LERs & related correspondence
- 8004080101 Part 21 rept re deviation which could result in reduction of integrity of RCPD Valve bonnet flange weldment was liquid penetrant examined on one side only fersonnel will complete examination
 MILLER, H L. Duke Power Co 80/03/11 3pp
- 8004020348 Forwards Significant Deficiency Rept SD 369-370/80-02 resteam generator narrow range level transmitter cables
 PARKER, H O Duke Power Co 80/03/27 1p
- --8004020358 Significant Deficiency Rept SD 369-370/BO-02 re failure of steam generator narrow range level transmitter cables to meet environ qualification requirements. Sixteen cables in Unit 1 will be replaced & new cables installed in Unit 2 * Duke Power Co 80/03/27 lp
- DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Gualification of Bafety-Related Electrical Equipment," providing guidance re methods for compliance ROSED F Division of Project Management.
- 8004040017 Bubmits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp

- 8004020466 Notification of 800326 t 27 meeting w/representatives from Mark II owners gloup in Sam Jose CA to discuss Mark II Creace Test Program.4T c/o tests & foreign tests ELTAMILA.F Containment Systems Branch 80703/10 12pp
- 8004030122 Notification of 800326-27 meeting w/Mark II dwners group. NRC consultants & GE in San Jose.CA to discuss Mark II Creare test program.4T C/O & Foreign tests Topics are proprietary Agenda encl ELTAWILA.F Containment Systems Branch 80/03/10 12pp
- 8004070097 Advises that ASME Code Case N-241 is acceptable & may be used in hydrostatic testing program to exempt certain piping from testing PARRIO D Light Water Reactors Branch 3 80/03/17 2pp
- B004040474 Summary of B00227 meeting w/Mark II owners group re status of several long-term program tasks, including Tasks A 17 & A 16 & task related to utilization of foreign test data ELTAWILA:F Containment Systems Branch B0/03/18 104pp
- 8004100102 Requests controlled set of PDIDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days

 KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/20
- 8004150316 Ferwards revised pages constituting Revision 13 to CE-1-A.

 OA program Revisions reflect recent organization title
 changes
 NAUQHTQN.44 F Commonwealth Edison Co 80/04/02 lp
- --8004150328 Revised pages constituting Revision 13 to GA program
 Revisions reflect recent organizational title changes
 # Commonwealth Edison Co CE-1-A RIJ 80/04/04 7pp
- 8004190416 Forwards ASME Section XI repairs & revisions rept,Procedure L S Q P 3 i.Revision Q HATTS.T E Componwealth Edison Co 80/04/03 ip
- --8004150419 Procedure for ASHE Section XI repairs & revisions Repair/ revision Repts 5-8 & 23-30 encl * Commonwealth Edison Co 79/04/11 17pp
- BO04280051 Discusses NRC caseload forecast panel B00326-27 site visit to review status of const 5 readiness for fuel loading at Unit 1 NRC projects fuel load date two months later than util List of attendees at B00326-27 meetings encl B00RNIA:A Light Water Reactors Branch 3 80/04/09 Spp
- 8004300064 Summary of 800326-27 meetings w/Mark II numers group in San Jose, CA re discussion of NRC concerns on data from Greare tosts & foreign full-scale test programs & relationships w/ Mark II designs ELTANILA: F Containment Systems Sranch 80/04/14 22pp
- 8004230479 Requests guidance on approach required to complete SER Fuel is scheduled for loading on 800930 NRC Porecast panel audit approves Nov 1980 fuel loading Expediting review would be appreciated PEOPLES.D L. Commonwealth Edison Co. 80/04/15 2pp
- BO04250427 Forwards response to NUREG-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lasalle County site-specific emergency plan PEOPLES,D L Commonwealth Edison Co 80/04/15 60pp
- ---8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004280410 Forwards draft radiological ETS & draft "Onsite Dose Calculation Manual" Urges that App I matis be reviewed in conjunction w/ongoing operating plant review PEOPLES, D L. Commonwealth Edison Co. 80/04/21 2pp
- --B004280412 Draft radiological ETS Sections 1-6 * Commonwealth Edison Co 78/10/31 100pp
- ---8004280414 Draft Unsite Pose Calculation Manual * Commonwealth Edison Co 79/12/20 15Opp
- F Becurity, medical, amergency & fire protection plans
- B004020413 Forwards NRC 800305 trip rept re 800228 site visit to complete fire protection review B0URNIA.A Light Hater Reactors Branch 3 80/03/10 ip

- --8004020419 Submits trip rept re 800228 site visit to complete fire protection review Unly one area of concern exists re need for sprinklers Applicant committed to correct situation using one of three specified alternatives HARRISDY G Auviliary Systems Branch 80/03/04 Jpp
- B004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791726 ltr.has been postponed pending GAO clearance under Foderal Repts Act GRIMES, B K Emergency Freparedness Task Force B0/03/11 4pp
- 8004010352 Forwards positions on fire protection issue Provides commitments made at 800207-08 meetings DELGEORGE, L.O. Commonwealth Edison Co. 80/03/24 22pp
- 8004070273 Forwards Pages C-26 & C-27 of Revision 5 to security plans, omitted from 800321 submittal Encl withheld (ref 10CFR2 790)
 PEOPLES, D. L. Commonwealth Edison Co. 80/04/02 1p

I Financial information

- 8004140213 Responds to 791013 request for financial info Prospectus for most recent security issue, exhibits ? testimony re plant investment data, cost of capital, rate of return. & economic conditions encl
 DELGEORGE, L 0 Commonwealth Edison Co. 80/02/28 600pp
- V Utility Final Sarety Analysis Report (FSAR) & amends
- 8004080522 Forwards affodavot stating that distribution of Amend 48 to FSAR has been made in accordance w/OD Parr 7/0526 ltr DELGEORGE, L. O. Commonwealth Eduson Co. 60/04/02 2pp
- G inspection reports. If Bulletins & correspondence
- 8004070172 Forwards [E Insp Rept 50~373/80-01 on 800109-11 & 15 No noncomplianace noted DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/07 2pp
- --B004070174 IE Insp Rept 50-374/80-01 on B00109-11 % 15 No noncompliance noted Major areas inspected radiation protection & radwaste mgt programs
 FISHER.W L Region 3, Chicago, Fuel Facility & Materials Safety Branch MLLER, D E Region 3, Chicago, Office of the Director 80/01/31 4pp
- 8004040036 Forwards If Insp Repts 50-373/80-03 & 50-374/80-02 on 800117-18 No noncompliance noted FIGRELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --8004040040 IE Insp Repts 50-373/80-03 v 50-374/80-02 on 800117-18 No noncompliance noted Major areas inspected status re safety-related portions of heating, entilation b air conditioning sys WILLIAMS, C.C., JONES, C.E. Region 3. Chicago, Office of the Director 80/02/11 App
 - 94080629 Forwards IF Insp Repts 50-373/80-04 & 50-374/80-03 on 90129-31 & notice of violation | IORELLI.6 Region 3. Chicago. Reactor Construction & Engineering apport Branch 80/02/20 2p
 - JO4080635 Notice of violation from insp on 800129-31 * Region 3. Chicago. Office of the Director 80/02/15 is
- 8004080647 IE insp Repts 50-3/3/80-04 : 50-3/4/80-03 on 800129-31 Noncompliance noted inadaquate updating of specs & drawings YIN-I T : DANIELSON.D H Region 3, Chicago, Office of the Director 80/02/15 Spp
- 04090272 Forwards IE In-p Repts 50-373/80-09 & 50-374/80-05 on 800207-08 No noncompliance noted FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/25 2pp
- BOO4070278 IE Insp Repts 50-373/80-09 & 50-374/80-05 on 800207-08 No noncompliance noted Major areas inspected suppression pool & reactor recirculating sys mods HILLIAMS.C C. NELSLER, J H. Region 3. Chicago, Office of the Director 80/02/21 4pp

- 8004080182 Forwards If Insp Repts 50-373/80-06 % 50-374/80-06 on 800130-31 1 0201 No noncompliance noted FigRELLI.G Region 3. Chicago Reactor Construction & Engineering Support Branch 83/02/27 2p
- --B0040B0190 IC Insp Repts 50-J/3/80-06 / 50-374/B0-06 on B00130-31 & 0201 No noncompliance noted Major areas inspected const status, electrical testing & electrical records HAVES,D N Region 3, Chicago, Reactor Operations Nuclear Support Branch BARRETTP n Region 3, Chicago, Office of the Director 80/02/25 Spp
- 8004180187 Forwards IE Insp Rept 50-3/3/80-05 on 800101-31 & natice of violation
 HEISHIMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/04 epp
- --8004180199 Notice of violation from insp on 800101-31 * Region 3. Chicago. Office of the Director 80/02/26 ip
- --8004180203 IE Insp Rept 50-3/3/80-05 on 800101-31 Noncompliance noted failure to control temporary electrical leads to permanent station equipment SPESARD, R. L. WALKER R. D. Region 3, Chicago, Office of the Director 80/02/26 17pp
- 8004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER.J G. Region 3. Chicago. Office of the Director 80/03/07
- BOO4140119 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Btd Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES, D L Commonwealth Edison Co 80/03/20 5pp
- 8004180157 Forwards IE Info Notice 80-12, "Instrument Failure Causas Opening of PORV % Diock Valve "No specific action or response necessary KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/31
- 8004080686 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition > Onsite Supply "No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/01
- 8004i500l4 Folwards IF Info Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER J G Region 7. Chicago. Office of the Director 80/04/02
- B0041B0030 Forwards attachments to IE Circular B0-03, "Protection From Toxic Gas Hazards," inadvertently umitted from 800304 transmittal KEPPLER, J 0 Region 3. Chicago, Office of the Director 80/04/02
- 8004220073 Forwards 1E Info Notice 80~14. "Bafety Suggestions From Employees " No action required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004220324 Forwards IE Circular 80-07, "Problems W/HPC: Turbine Oil Sys " No written response required KFPPLER: J O Region 3, Chicago, Office of the Director 80/04/03 to
- 8004220069 Forwards IE Bullotin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 10
- 8004110023 Forwards 1F Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/07
- BO04230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME BA-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J G Region 3, Chicago, Office of the Director BO/04/07

- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Saroty-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- 8004020466 Notification of 800326 & 27 meeting w/representatives from Mark II owners group in San Juse,CA to discuss Mark II Creace Test Program,4T c/o tests & foreign tests ELTANILA,F Containment Systems Branch 80703/10 12pp
- B004030122 Notification of B00326-27 meeting w/Mark 11 owners group. NRC consultants & GE in San Jose.CA to discuss Mark II Creare test program.4T C/O & foreign tests Topics are proprietary Agenda encl ELTAWILA.F Containment Systems Branch B0/03/10 12pp
- 8004070097 Advises that ASME Code Case N-241 is acceptable & may be used in hydrostatic testing program to exempt certain piping from testing PARR.O D Light Water Reactors Branch 3 80/03/17 2pp
- 8004040474 Summary of 800227 meeting w/Mark ll owners group re status of several long-term program tasks.including Tasks A 17 & A 10 & task related to utilization of foreign test data ELTAMILA,r Containment Systems Branch 80/03/18 104pp
- 8004100102 Requests controlled set of PAIDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/20
- 8004150316 Forwards ravised pages constituting Revision 13 to CE-1-A, QA program Revisions reflect recent organization title changes NAUGHTON,W F Commanwealth Edison Co 80/04/02 1p
- --8004150328 Revised pages constituting Revision 13 to GA program
 Revisions reflect recent drganizational title changes
 * Commonwealth Edison Co CE-1-A RI3 80/04/04 7pp
- B004150416 Forwards ABME Section XI repairs & revisions rept,Procedure L S G P $\,$ G i.Revision D WATTS,T $\,$ E Commonwealth Edison Co $\,$ G0/O4/O3 $\,$ Ip
- ---B004150419 Procedure for ASME Section XI repairs & revisions Repair/ revision Repts 5-8 & 23-30 encl # Commonwealth Edison Co 79/04/11 17pp
- 8004280051 Discusses NRC caseload forecast panel 800326-27 site visit to review status of const & readiness for fuel loading at Unit 1 NRC projects fuel load date two months labor than util List of attendees at 800326-27 meetings encl 80040407 Spp
- 8004300044 Summary of 800326-27 meetings w/Mark II owners group in San Jose,CA re discussion of NRC concerns on data from Creare tests & foreign full-scale test programs & relationships w/ Mark II designs ELTAWILA.F Containment Systems Branch 80/04/14 22pp
- 8004250427 Forwards response to NUREG-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lesalle County site-specific emergency plan PEDPLES.D L Commanwealth Edison Co 80/04/15 &Opp
- --8004250428 "Design Criteria & Conceptual Besign Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004280410 Forwards draft radiological ETS & draft "Unsite Dose Calculation Manual" Urges that App I matls be reviewed in conjunction w/ongoing operating plant review PEOPLES.D L Commonwealth Edison Co 80/04/21 2pp
- --8004280412 Draft radiological ETS,8sctions 1-6 * Commonwealth Edison Co 78/10/31 100pp

- ---8004280414 Braft Unsite Lose Calculation Hanual * Commonwealth Edison Co 79/12/20 150pp
- F Security, medical, emrgancy * rire protection plans
- 8004020413 Forwards NRC 80030s trip tept re 800228 site visit to complete file protection review DOURNIA,A Light Water Reacfors Branch 3 80/03/10 1p
- --8004020419 Bubmits trip rept to 800228 site visit to complete fire protection review Only one area of concern exists re need for sprinklers Applicant committed to correct situation using one of three specified alternatives HARRISON, G. Auxiliary Systems Branch 80/03/06 3pp
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm, has been postponed pending GAD clearance under Federal Repts Aut.
 GRIMES.B K Emergency Preparedness Tas' Force 60/03/11 4pp
- 8004010352 Forwards positions on fire protection issue Provides commitments made at 800207-08 meetings DELGEORGF, L D Commonwealth Edison Co 80/03/24 22pp
- 8004070273 Forwards Pages C-26 > C-27 of Revision 5 to security plans, omitted from 800324 submittal Encl withheld (ref 100FR2 790)
 PEOPLES, D. L. Commonwealth Edison Co. 80/04/02 ip
- I Financial information
- 8004140213 Responds to 791013 request for financial info Prospectus for most recent security issue, exhibits & testimony re plant investment data, cost or capital, rate of return, & economic conditions onci DELOFORGE, L.O. Commonwealth Edison Co. 80/02/28 600pp
- K Utility Final Safety Analysis Report (FSAR) 5 amends
- 8004080522 Forwards affidavit stating that distribution of Amend 48 to FSAR has been made in accordance w/OD Parr 770526 ltr DELGEORGE, L O Commonwealth Edison Co 80/04/02 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8004040036 Forwards 1E Insp Repts 50-373/80-03 & 50-3/4/80-02 on B00117-18 No noncompliance noted FIGRELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/02/13 2pp
- ---B004040040 IE Insp Repts 50-3/3/80-03 & 50-3/4/80-02 on 800117-18 No noncompliance noted Major aleas inspected status re safety-related portions of heating, ventilation & air conditioning sys WILLIAMS, C.C., JONES, C.E. Region 3, Chicago, Office of the Director 80/02/11 4pp

- ---8004080190 IE Insp Repts 50-3/3/80-06 % 50-374/80-06 on 800130-31 % O201 No noncompliance noted Major areas inspected const status, electrical testing % electrical records HAYES.D W Region 3 Chicago, Reactor Operations Nuclear Support Branch BARREIT, P A Region 3, Chicago, Office of the Director 80/02/25 5pp
- 8004100118 Forwards IF into Notice 80-08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/07 16
- BOO4140119 Forwards response to IE Bulletin BO-03. "Loss of Charcoal from Std Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES, D.L. Commonwealth Edison Co. BO/03/20 5pp
- BOO4150157 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/31
- 5004080686 Forwards IF Circular 80-05, 'Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required KEPPLER, J G Region G. Chicago Office of the Director 80/04/01
- B004150014 Forwards IE Info Notice 80-13, "GE Type SBH Control Ewitches Defective CAH Followers " No specific action or response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Haiards," Inadvertently omitted from 800306 transmittal KEPPLER,J C Region 3. Chicago, Office of the Director 80/04/02
- 8004220093 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02 to
- BOO4220324 Forwards LE Circular 80-07. "Problems W/HPC1 Turbine Oil Sqs " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/03 1p
- B004220047 Forwards IE Bulletin 80-08, 'Eram of Containment Liner Ponetration Welds " Written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/09 19
- B004110023 Forwards IE Bulletin 80-07, "BMR Jet Pump Assembly Failure " No written response required KEPPLER, J O Region 3. Chicago. Office of the Director 80/04/07 ip
- 304230224 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASNE SA-312. Type 304 Stainless Steel Pipe " Action required KEPPLER. J G Region 3. Chicago. Office of the Director 80/04/07 is
- S Reportable occurrences, LERs & related correspondence
- 8004030173 Ack receipt of 800227 final deficiency rept re reactor containment structural steel Review will be completed during future insp FiORELI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/19 ip
- DOCKET 50-376 NORTH COAST NUC PLANT
- G Adjudicatory correspondence

- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3
- A Application/construction stage documents & correspondence
- B004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management B0/02/05 7pp
- 8004040017 Submits add1 guidance to NUREC-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance ROSS,DF Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include IRC approval prior to issuance of DL Wiencl ROSS.D F Division of Project Management 80/03/10 53pp
- B004020206 Refers to encl ltr from EB Carrier.State Historic Preservation Officier.concerning field survey for archeological resources at plant const site Literature search should be made & NRC informed of survey results BALLARD.R L Environmental Projects Branch 1 80/03/19 2pp
- 8004190420 Forwards proposed revisions to "Preoperational Environ Surveillance Program "OL stage environ rept will be amended in future to include changes ASWELLD L Louisiana Power & Light Co 80/04/11 Spp
- --8004150424 Proposed revisions to "Preoperational Environ Surveillance Program " + Louisiana Power & Light Co 80/04/11 78pp
- F Security, medical, emergency & fire protection plans
- B0040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.hos been postponed pending OACI clearance under Federal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OBSECKL V Diffice of the Executive Director for Operations 80/04/02 34pp
- 800417024B Forwards NRC 800229 interrogatories & request for documents directed to LA Consume: League Ack informal agreement to respond within one wk MCGURREN.II J Hearing Branch 1 80/04/19 1p
- H General correspondence
- 8004030352 FOIA request for info re facility FSAR & documents re NRC regulations including App J of 10CFR20
 KRAUSE, L Affiliation Unknown 80/03/07 1p
- 8004030395 Responds to FOIA request for info re facility F8AR & documents re NRC regulations including App I of 10CFR20 Forwards documents listed in App A Document 5 includes App I M/o encl
 FELTON, J K Division of Rules and Records 80/03/21 2pp
- I Financial information
- 8004220535 Annual Financial Rept 1979 * Middle South Utilities.Inc 79/12/31 40pp
- 8004250365 Forwards Annual Financial Rept 1979 AGMELL.D L. Arkansas Power & Light Co. 80/04/22 1p
- --8004250369 Annual Financial Rept 1979
 * Arkansas Power & Light Co 80/02/15 24pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004240220 Forwards IE Info Notice 80-14, "Bafaty Suggestions From Employees" No action required,
 SEYFRIT.K.V Region 4, Dallas, Office of the Director B0/04/02 to

- 8004220281 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 0:1 Sys " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/03 in
- 8004220783 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 6A-312.Type 304 Stainless Steel Pipe " Action required BEYFRIT,K V Region 4, Dallas. Office of the Director 80/04/04 in
- 8004220228 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Holds " Written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/07
- 8 Reportable accurrences, LERs & related correspondence
- 8004010343 Forwards final rept of Significant Deficiency 11 re switchgear breaker position switch operator defect ABMELL.D.L. Louisiana Power & Light Co 80/03/28 ip
- --8004010347 Final rept of Significant Deficiency 11,re switchgear breaker position switch operator defect Thirty-three breaker position switch operators replaced w/newly designed GE assembles Operators have guides preventing bending CRNICH.J. MILHISER.R.J. HART.J. Louisianu Power & Light Co 80/03/18 2pp
- 8004070308 Forwards final deficiency rept re noncompliance to welding requirements for heating ventilation & air conditioning seismic support hanger to embedded plates
 ASHELL.D L Louisiana Power & Light Co 80/03/31 ip
- --8004070310 Final deficiency rept re noncompliance to welding requirements for heating, ventilation & air conditioning seismic support hanger to embodded plates All affected welds repaired & insps documented for QA files CRNICH.J. MILHIBER.R.J. HARTNETT.R.A. Lauisiana Power & Light Co. 80/03/31 3pp
- 8004250347 Forwards final deficiency rept re Significant Const Deficiency 13 re reactor containment bldg dome concrete ASHELL.D L Arkansas Power & Light Co. 80/04/21 1p
- --8004250352 Final deficiency rept re improper consolidation of concrete in lower portion of wall in reactor containment bldg dome Caused by improper random vibration during concrete placement CONICH, J. MILHISER, R. J. HARTNETT, R. A. Arkansas Power & Light Co. 80/04/08
- B0042B0594 Forwards final rept of Significant Const Deficiency i3 All corrective action repairs have been completed & verification testing accomplished ASMELL,D,L Louisiana Power & Light Co 80/04/21 ip
- --8004280605 Final rept of Significant Const Deficiency 13 re defects in containment bldg dome concrete Caused by improper random vibration due to vibrators that were inadequate in size & number Qualified job superintendent will be provided CRNICH, J. MILHIBER.R. J. HARTNETT, R. A. Louisiana Power & Light Co. 80/04/08 App

DOCKET 50-384 INDONESIA RESEARCH REACTOR

- P. Operating license stage documents & correspondence
- 8004220601 Request that License R-121 be amended to authorize possession only Core fuel will remain inside reactor until NRC approval for dismantling is obtained ADAMSON.R W California Polytechnic State Univ. 79/11/05 ip
- DOCKET 50-387 BUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROS8.D F Division of Project Management
- 8004040017 Bubmite addl guidance to NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSB, D F Division of Project Management, 80/02/21 3pp

- 8004020446 Notification of 800326 / 27 meeting w/representatives from Mark II owners group in 5an Jose,CA to discuss Mark II Creace Test Program,4T c/o tests / foreign tests ELTANILA,F Containment Systems Branch 80/03/10 12pp
- 8004030]22 Notification of 800326-2/ meeting w/Hark II owners group, NRC consultants & QE in San Jose,CA to discuss Mark II Creare test program.4T C/O & foreign tests Topics are proprietary Agonda enci ELTAWILA,F Containment Systems Branch 80/03/10 12pp
- 8004080654 Forwards summary of 800228 meeting w/util re plant-unique containment program
 PARR.O D Light Water Reactors Branch 3 80/03/14 ip
- --8004080660 Summary of 800228 meeting w/util BNL.KMU.KFK.SRI Intl. BechtelrNUS Corp & CNSMS to discuss plant-unique containment program List of attendees & agenda encl ELTAMILA:F Containment Systems Branch 80/03/07 18pp
- 8004040474 Gummary of 800227 meeting w/Mark II owners group re status of several long-term program tasks including Tasks A 17 & A 16 & task related to utilization of foreign test data ELTANILA.F Containment Systems Branch 80/03/18 104pp
- 8004210410 Requests add1 info re reactor sys to continue review of application for OL PARR.O D Light Water Reactors Branch 3 80/03/21 16pp
- 8004100484 Responds to 800313 request for approval to use ABME Code Cases N-234 & N-235 during preservice examination of reactor pressure vessel Code cases acceptable PARR.O D Light Water Reactors Branch 3 80/03/27 2pp
- 8004140352 Confirms NRC 800411 meeting w/util & ANL re operational biological monitoring programs & ETS Proposed agenda encl CURTIS,N W Pennsylvania Power & Light Co 80/04/07 2pp
- 8004140268 Comments on archaeology project at site Quotation for survey work is excessive Requests study to define satisfactory Phase I study of area
 KENT,B C Pennsylvania, State of 80/04/08 (p
- 8004300064 Summary of 800326-27 meetings w/Mark II owners group in San Jose,CA re discussion of NRC concerns on data from Creare tests & foreign full-scale test programs & relationships w/ Mark II designs. ELTAMILA,F Containment Systems Granch 80/04/14 22pp
- 8004210335 Forwards Susquehanna River data in response to NRC 800407 request
 SKINNER:IF Pennsylvania Power & Light Co 80/04/15 1p
- --8004210340 "Demonstration for Brunner Island Steam Electric Station Units 1-3, Vols 1 & 2 " * EG & G. Inc. /7/05/19 200pp
- --8004210344 "Potential Effects of Brunner Island Steam Electric Station on Future Higrations of American Shad in Susquehanna River " * EQ & O: Inc 77/08/13 23pp
- * EG & G. Inc 77/08/13 23pp
- --8004210347 "Probabilities of Normal & Worst Case Conditions in Susquehanna River during Critical Periods for Muskellunge Spawning & Smallmouth Bass Egg Survival & Development " * EQ & O: Inc 77/09/19 16pp
- --8004210349 "Assessment of Thermal Effects from Drunner Island Steam Electric Station Based on Newly Derived Max Weekly Average Temps " # EO & O, Inc 79/05/31 33pp
- →B004210355 "Ecological Study of Effects of Brunner Island Steam Electric Station Cooling Water Intakes " JOHNSON,T D , PHOENIX, D R Roy F Weston, Inc. 77/11/18 78ρρ
- --8004210358 "Biological Burvey of Busquehanna River in Vicinity of York Haven, PA 1978 Terminal Rept " HURTZ, C B Charles B Hurtz 79/06/29 33pp
- --8004210364 "Ichthyofaunal & Creel Census/Fishing Pressure Burveys in Vicinity of Brunner Island Steam Electric Station " DENONCOURT, R F R F Denancourt 78/05/31 141pp
- 8004280492 Comments on NUREG-0564. App B re archaelogical survey of Pond Hill Reservoir location Plan is preliminary rept containing no factual info re prehistoric mat] that might be found SOLENBERGER Bloomsberg State College BD/04/17 3pp

- D. NAC Draft/Fired Environmental Statements, supply / correspondence
- P004220079 Forwards diafr sup; to Mar 1980 DES 6/o encl SELLS D F For impmental Projects Branch 2 80/03/31 8pp
- F. Security, medical, emergency i fire protection plans
- 80040B0077 Advises that «chmittal date for evacuation time estimates» requested by NRC 791220 ltm has been postponed pending GAO clearance under Feoeral Repts Act
 GRIMES, B.K. Emergency Preparedness Task Force 80/03/11 App
- G Adjudicatory correspondence
- 8004080175 Requests to make limited appearance statement at 800320 Pearing ENDRIZZI,D Aftiliation Unknown 80/02/27 ip
- 8004100571 Notifies that MRF issued diaff suppl to DES on 800331 Suppl b DES labelled NUREG-0564 DES issued b served on ASLB \$ all parties in June 1979 Diaff suppl has been served on all persons on svr list Exceptions listed CUTCHIMUM Hearing Branch 3 80/03/03 1p
- BOO4090571 Requests to make limited appearance statement on behalf of Taxpayers Association of Lackawanna County at licensing hearings Evening or weekend sessions should be held for citizen participation

 BCHUMACHER.K. Affiliation Unknown BO/03/07 ip
- 8004080154 Requests to make limited appearance statement at licensing hearings HEMMENDINGER, R Affiliation Unknown 80/03/10 2pp
- 8004300006 Requests notification of upcoming licensing hearings refacilities Hearings should be on weekends or evenings WESTON.K Affiliation Unknown 80/03/10 ip
- --8004300008 Requests notification of time & location of licensing hearing for facilities Portion of hearings should be scheduled on weekends or evenings to offer public better chance to attend FARBER, R.C. Affiliation Unknown 80/03/10 1p
- --8004300009 Requests notification of time & location of licensing hearings for facilities & to make limited appearance statement Hearings should be scheduled during evenings or weekends CAMILL, W.J. Affiliation Unknown 80/03/12 ip
- --8004300013 Requests notification of time 3 location of licensing hearings for farilities & to make limited appearance statement Min of half of hearings should be scheduled at night or on weekends
 DDROUGH, R Affiliation Uninoum 80/02/29 ip
- ---8004300019 Requests notification of time & location of licensing hearings for tacilities & to make limited appearance statement Hearings should be scheduled on evenings & weekends LARINI.O J Affiliation Unknown 80/03/12 1p
- --8004300023 Requests notification of time & location of licensing hearings for facilities Requests to make limited appearance statement
 DETRICH, B F Affiliation Uninown 80/03/10 ip
- 8004300025 Requests notification of time & location of licensing hearings for facilities Requests to make limited appearance statement Postion of hearings should be held on evenings & weekends
 WINTER: A J Affiliation Unknown 80/02/29 1p
- ---8004300029 Requests notification of time & location of licensing hearings for facilities Requests to make limited appearance statements Portion of hearings should be scheduled on on evenings of weekends FALLON-P Affiliation Uninoum 80/03/10 ip
- --8004300033 Requests notification of time & location of licensing hearings for facilities Requests to make limited appearance statement Portion of hearings should be scheduled for evenings or weekends LEM: A Affiliation Unknown 80/03/10 ip

- --B004300035 Requests notification of time & location of licensing hearings for facilities Requests to make limited appearance statement Portion of hearings should be schoduled for evenings f weekends GRAY, P.F. Affiliation Unknown 80/03/10 ip
- --8004200037 Expresses concern that util is attempting to limit participation or intervenois at opcoming licensing hearings SKISLA4.5 Affiliation Uninoun 80/03/10 1p
- --8004300042 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings DUBJN.K J. Affiliation Unknown 80/02/29 1p
- --8004300046 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings DERAYHOND, J.S. Affiliation Unknown 80/03/10 Ip
- --8004300054 Requests making limited appearance statement concerning three motions on agenda or ASL3 hearings in Wilkes-Barre,PA BUTCHKO,P R Affiliation Unknown 80/03/12 1p
- --B004300057 Requests notification of time & location of licensing hearings for facilities & to make limited appearance statement Polition of hearings should be held on evenings or MERRILL, D K Affiliation Unknown 80/03/08
- ---8004300061 Requests to make limited appearance statement at facility licensing hearings & notification of time & location of meeting Time for statements should be made available on weetends on evenings

 KRSYKWA,E J Affiliation Unknown 80/03/11 ip
- --8004300063 Requests to make limited appearance statement at facility licensing hearings & notification of time & location of meeting Hearings &hould be held on evenings or weekends SMITH.D Affiliation Unknown 80/03/21 (p
- --8004300066 Requests to make limited appearance statement at facility licensing hearings & notification of time & location of meeting Time should be made available on evenings or weekends for statements MACHAMER, G.E. Affiliation Unknown 80/03/10 ip
- --B004300067 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings H100INS.8 M Affiliation Unknown B0/02/29 ip
- --8004300069 Requests to make limited appearance statement in favor of util motions at 800320 ABLB hearings in Wilkes-Barre,PA MURRAY.F Scranton, Univ of 80/03/12 1p
- --8004300070 Requests to make limited appearance statement at ASLB 800320 prehearing conference in Wilkes-BarresPA
 THOMPSON.F Affiliation Unknown 60/03/12 1p
- --B004300971 Requests on behalf of Citizens Lobby, to make limited appearance statement at B00320 licensing hearing in Hilkes-Barre.PA
 BASALYOA: G Affiliation Unknown 80/03/11 ip
- --8004300073 Requests to make limited appearance statement at facility licensing hearings & notification of time & location of meeting Time should be made available for statements on evenings & weekends BRAMSON.L Affiliation Unknown 80/03/13 ip
- --8004300074 Requests to make limited appearance statement at 800320 licensing hearing in Wilkes-Barres-PA ELLIOTT.C P Affiliation Unknown 80/03/17 1p
- --8004300080 Expresses concern re ASLB consideration of util motion to restrict public intervenors in licensing proceedings Full inquiry should be made re any attempts to demy public due process & rights within established NRC procedures SALZMAN,L Friends of the Earth 80/03/13 ip
- --80043000B3 Requests to make limited appearance statement at facility licensing hearings & notification of time & location of meeting Time for statements should be made available on evenings or weekends

 SAUERS M A Affiliation Unknown 80/03/10 lp
- --8004300088 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings # Affiliation Unknown 80/02/29 ip

- 8004020040 Response to ASLB 800222 prehearing conference memorandum & order Alleges restilctive & biased agenda Urges discussion of onsite inspladvisability & reconsideration of denied contentions kV/Cortificate of Svc HALLIGAN, T J Citizens Against Nuclear Dangers 80/03/12 4pp
- 8004080143 Response to ASLB 800222 order sotting oral argument reapplicant motions to prohibit Susquehanna Environ Advocates 5 Environ Coalition on Nuclear Power from Intigation of contentions Urgos to cancel argument W/Cortificate of Svc JONHERUD, J H Environmental Coalition on Nuclear Power 80/03/14
- 8004080697 Request for expedited consideration of ASLD actions re discovery limits & decision-making Urges omission of util motions to restrict intervenous participation in 800320 oral argument Requests certification Certificate of Svc encl JDHNSRUD, J H Environmental Coalition on Nuclear Power 80/03/14
- 800423000A Potation to raise specific issues at 800920 prehearing conference, re intervenors' motions for protective order on Contentions 1 & 2 % status as full party in proceeding SCHULTZ.0 R Susquehanna Environmental Advocates 80/03/14 2pp
- 80040B0156 Requests to make limited appearance statement at licensing hearing BURNS,D Affiliation Unknown 80/03/15 ip
- 8004080161 Requests to make limited appearance statement at licensing hearing GEIOER.O Affiliation Unknown 80/03/15 2pp
- 8004180136 Responds to 800214 itr to Gilinsky re concern about treatment of public participant, Environ Coalition on Nuclear Power & director, Jubinsrud in license proceeding NRC regulations does not permit views off-the-record FITZGERALD, J A Office of the Executive Legal Director 80/03/20
- 8004080585 Memorandum re ASLB 800320-21 prehearing denial of applicants motions against Environ Coalition on Nuclear Power & Susquehanna Environ Advocates Delineates areas in which intervenors should supplement answers to interrogatories PARIB,O H. BECHNOFFER.C Atomic Safety and Licensing Board Panel 80/03/27 App
- 8004220032 Submits comments re NRC in post-TMI period & licensing situation at facilities Recommends suspension of CP until independent auditors assess need for power & alternatives PERKINS.J L Affiliation Unknown 80/03/27 3pp
- 8004180247 Requests to make limited appearance statement at licensing hearing SHELLY.F. L. Affiliation Unknown 80/03/31 ip
- 8004100331 Requests to make limited appearance statement at licensing prehearing LAMBON.L Affiliation Unknown B0/04/01 ip
- BOO4100334 Requests to make limited appearance statement at licensing prehearing MILLS B D Affiliation Unknown BO/04/01 1p
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 90851CKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004110016 Responds to ASLB 800320-21 prehearing conference request to examine possibility of making available in Wilkes-Barre area complete set of AEC & NRC repts of cases decided by Commission Repts will be loaned to O
- --8004110019 Submits trip rept re 800313-14 visit to Osterhout Free Library, Wilkes-Barre, PA Library houses Susquehanna LPDR documents Library does not loan out documents to patrons Documents in good order but in need of revemping LOQAN, F Division of Rules and Records 80/04/03 2pp
- B004130047 Response in opposition to Environ Coalition on Nuclear Power B00315 petition for review of ASLB prehearing rulings Requests to address merits if appeal is granted Certificate of Buc encl CUTCHINJ M Hearing Branch 3 80/04/04 11pp

- 8004230111 Swrond prohearing conterence order denying applicants' motions to restrict Susquehamna Fining Advocates 'Environ Coalition on Nuclear Power participation, Citizens Against Nuclear Dangers environ contentions limited to our filing PARIS, O H. BECHHOEFER C. Atomic Sarety and Licensing Board Panel 80/04/11. 21pp
- 800A280746 Forwards Univ of Heidelbeig levised Translation 920. "Radiological Assessment of Hybl Nuclear Power Plant" "Review of Mybl Rept" will be available to public in form of NURCO W/o enc! CUTCHIN, J M. Hearing Branch 4. 80/04/24. †p
- H General correspondence
- 8004080065 Expresses concern to excessive number of interlogatories sent to J Johnstud as intervenor in licensing healings Appears that NRC is tying to hinder J Johnstud effectiveness Certificate of Svc encl WARDEN, W G Affiliation Unknown 80/02/14 App
- 8004040176 Advises that news media 3 info groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Protests util efforts

 LEON: A Affiliation Unknown 80/02/29 Ip
- 8004070[85 Requests notification of time? [ocation of upcoming hearing on facility licensing digos scheduling of hearings on weekends of evenings MIGGINSIR ti Affiliation Uninown 80/02/27 2pp
- 8004070191 Requests notification of time & location of upcoming hearing on facility licensing Urges scheduling of hearings on weekends or evenings RHEINHEIMER.D Affiliation Unknown 80/02/29 2pp
- 8004040166 Requests notification or time & location of upcoming hearing on meekends or evening & limited appearance at hearing WESTNEDGE, T. Affiliation Unknown 80/03/03 2pp
- 8004070064 Advises that news media & info groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Piotests util efforts
 RHEINHEIMER.D Affiliation Unknown 80/03/03 ip
- B004070193 Requests notification or time & location of upcoming hearing on facility licensing Urges scheduling of hearings on weekends or evenings Requests timited appearance at hearing BRISTOL.M Affiliation Unknown 80/03/04 2pp
- B004090184 Expresses feat for potential castastrophe resulting from const of facility
 RODACK, M Affiliation Unknown 80/03/05 ip

- --7812110271 IE Insp Repts 50-287//8-15 t 50-388/78-13 on 780821-0921
 Noncompliance noted realiure to qualify welders & failure to
 use specified curing rompound for spray poind
 GALLOLR H. Region 1. Philadelphia. Defice of the Director
 MCCAUCHY.R W. Region 1. Philadelphia. Reactor Construction &
 Engineering Support Nianch 78/10/17 13pp
- 8004076379 Ark receipt of 860227 ltr informing NRC of steps taten to correct violations noted in LE linsp Repts 50-38779-36 & 50-388779-19 CARLSON,R T Region & Philadelphia. Reactor Construction & Engineering Support Branch 60/03/07 1p
- --B004070382 Responds to NRC 800123 ltr re violations nated in IE Insp Repts 50-387/79-36 & 50-388/79-19 Corrective actions amended Bechtel Field Insp Hanual Procedure 6-3-Revision & & held training sessions for field engineers on bolt installation SABOL/A R Pennsylvania Power & Light Co 80/02/27 5pp
- --8004070385 Forwards IE (nsp Repts 50-387/79-36 & 50-388/79-19 on 791029-1102 & notice of violation CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/23 2pp
- --8004070391 Notice of violation from insp on 791029--1102

 * Region I. Philadelphia, Office of the Director 80/01/11 2pp
- --8004070396 IE insp Repts 90-387/79-36 & 50-388/79-19 on 791029-1102
 Noncomptiance noted failure to provide adequate design
 review resulting in nonconforming installation & failure to
 follow procedure for tagging nonconforming stems
 PACLIND.R J Region i. Philadelphia. Office of the Director
 EDNETERS D Region i. Philadelphia. Reactor Construction &
 Engineering Support Branch 80/01/11 6pp
- 8004090402 Advises that IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks."

 Was incorrectly sent for action No response required ORIER, B it Region i. Philadelphia, Office of the Director 80/03/17 in
- 8004100094 Ack receipt of 800229 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-31 & 50-388/79-16 CARLSON.R F Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 60/03/17 | p
- --8004100098 Responds to NRC 800118 itr re violations noted in IE Insp Repts 50-387/77-31 & 50-388/79-16 Corrective actions revised Tech Specs re correct welder qualification procedure & quenching method for N2 noticle mods SABOL: A R Pennsylvania Power & Light Co 80/02/29 3pp
- --8004100103 Forwards IE insp Repts 50-387/79-31 & 50-388/79-14 on 790910-1005 & notice of violation CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/18 ip
- --8004100106 Natice of violation from insp on 790910-1005
 A Region 1, Philadelphia, Office of the Director 80/01/09 2pp
- --8004100111 IE Insp Repts 50-387/79-31 & 50-388/79-16 on 790910-1005
 Noncompliance noted failure to review SRSE 1-12, Revision 2
 & to provide documented instruction to control completion
 re water quenching of weld VRR-891-2-FW-13M
 MCOAUGH/.R W Region 1, Philadelphia, Reactor Construction &
 Engineering Support Branch HIOCINS.J C . OALLO,R M Region 1,
 Philadelphia, Office of the Director 80/01/09 12pp
- 3004150295 Forwards IF Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER. B M Region 1. Philadelphia. Office of the Director 80/03/31 1p
- JOO4070077 Forwards 1& Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region (, Philadelphia, Office of the Director BO/04/01 ip
- 8004110504 Forwards IE Info Natice 80-13. "GE Type SBM Control Switches Defective CAM Followers " No written response required ORIER,B H Region 1. Philadelphia, Office of the Director 80/04/02 ip
- 8004240341 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER, BH Region 1, Philadelphia, Office of the Director 80/04/02 1p

- 8004180189 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Oil Sys " No written response required CRIER,8 H Region I. Philadelphia, Office of the Director 80/04/03 ip
- 8004110068 Forwards [E Builetin 80-07, '8WR Jet Pump Assembly Failure " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 8D/04/04 | 1p
- 8004230481 Forwards IE Bulletin 79-03A. "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/04 ip
- 8004180270 Forwards IE Bultetin 80-08, "Exam of Containment Liner Penetiation Wolds " Written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/07 ip
- S Reportable accurrences, LERs & related correspondence
- 8004080516 Final deficiency rept re hydramotor actuator springs
 Affected dampers have been identified & being controlled
 Actuators will either be replaced or tested to establish
 adequacy
 CURTIS.N W Pennsylvania Power & Light Co 80/03/28 2pp
- ---8004080521 Informs NRC of notification to 13 purchasers of NH model milliampere hydramotor actuators Actuators have been discovered to be mfg from incorrect mati FORMELLA:R L ITY General Controls, Division of Intl Tel & Tel Corp 79/12/07 4pp
- BOO40B0363 Interim deficiency rept re defective cast carbon steel swing check valves mfg by Pacific Valve.Inc Final rept will be forwarded during June 1980 CURTIB.N N Pennsylvania Power & Light Co 80/03/31 2pp
- 8004290394 Forwards final deficiency rept re Culter Hammer E-30 pushbutton sticking problem & dislodgement of Switch CH E-30AB from contact block Conditions of Amphenol female connectors not reportable under 10CFR50 Rationale encl CURTIS.N W Pennsylvania Power & Light Co 80/04/18 3pp
- --8004270397 Final deficiency rept re Cutler Hammer E-30 pushbutton sticking problem & dislodgement of Switch CH E-30AD from contact block Sticking pushbutton corrected by scraping adge Locking devices for CH E-30 switches retightened * Pennsylvania Power & Light Co 80/04/18 3pp
- 8004300374 Forwards final deficiency rept re Cutler-Hammer E-30 pushbutton switches
 CURTIS.N W Pennsylvania Power & Light Co 80/04/18 2pp
- --8004300383 Final deficiency rept re Cutler-Hammer E-30 pushbutton switches Sticking of pushbutton occurs on two-button modules Dislodgement of operating module apparently caused by mechanical locking ring not being tightly locked * Pennsylvania Power & Light Co 80/04/18 4pp
- T Hearing transcripts on non-antitrust matters
- 8004020087 Transcript of 800320 prehearing conference in Wilkes-Barre, PA Pp 375-645 DECHOEFER, C E Atomic Safety and Licensing Board Panel 80/03/20 27200
- 8004180233 Transcript of 800320 prehearing conference P 375 only Atomic Safety and Licensing Board Panel 80/03/20 tp
- --8004180238 Transcript of 800320 prehearing conference P 1 only • Atomic Bafety and Licensing Board Panel 80/03/21 ip
- BO04020146 Transcript of 800321 prehearing conference in Wilkes-Barre, PA Pp 646-797 BECHMORFER.C E Atomic Safety and Licensing Board Panel 80/03/21 11400
- U Congressional/Executive Correspondence
- 8004080212 Responds to J Ulma request for status of facility licensing Licensing process delayed due to post-TMI efforts to upgrade safety requirements NRC is evaluating available resources to re-establish applicant review schedules DIRCKS.W J Office of the Executive Director for Operations 80/03/06 3pp

- --8004080218 Forwards ltr re J Ulman request for status of facility licensing MCDADE.J M House of Rep 80/02/07 2pp
- DOCKET 90-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588. "Interim Etaff Position on Environ Qualification of Safety-Related Electrical Equipment," providing quidance remethods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- 8004020466 Notification of 800326 & 27 meeting w/representatives from Mark II owners group in San Jose,CA to discuss Mark II Creace Test Program, 47 c/a tests & foreign tests ELTAMILA.F Containment Systems Branch 80/03/10 12pp
- 8004030122 Notification of 800326-27 meeting w/Mark II owners group, NRC consultants & GE in Ban Jose, CA to discuss Mark II Creare test program, 4T C/O & foreign tests Topics are proprietary Agenda oncl ELYAWJLA.F Containment Systems Branch 80/03/10 12pp
- B0040B0654 Forwards summary of 800228 meeting w/util re plant-unique containment program
 PARR.0 D Light Water Reactors Branch 3 B0/03/14 Ip
- ~-8004080660 Summary of 800228 meeting w/util BNL,KWU,KFK,SRI Inti. Bechtel:NVS Corp & CNSNS to discuss plant-unique containment program List of attendees & agenda encl ELTAWILA:F Containment Systems Branch 80/03/07 18pp
- 8004040474 Summary of 800227 meeting w/Mark II owners group re status of several long-term program tasks.including Taska A 17 & A 16 & task related to utilization of foreign test data ELTAMILA.F Containment Systems Branch 80/03/18 104pp
- 8004210410 Requests addl info re reactor sys to continue review of application for DL PARR.O D Light Water Reactors Branch 3 80/03/21 14pp
- 8004100484 Responds to 800313 request for approval to use ABHE Code Cases N-234 & N-235 during preservice examination of reactor pressure vessel Code cases acceptable PARR.O D Light Water Reactors Branch 3 80/03/27. 2pp
- 8004140352 Confirms NRC 800411 meeting w/util & ANL re operational biological monitoring programs & ETB Proposed agenda encl CURTIS,N W Pennsylvania Power & Light Co 80/04/07 2pp
- 8004140268 Comments on archaeology project at site Guotation for survey work is excessive Requests study to define satisfactory Phase I study of area KENT,B C Pennsylvania, State of 80/04/08 1p
- 8004300064 Bummary of 800326-27 meetings w/Mark II owners group in San Jose,CA re discussion of NRC concerns on data from Creare tests & foreign full-scale test programs & relationships w/ Mark II designs

Containment Systems Branch 80/04/14 22pp

- 8004210335 Forwards Busquehanna River data in response to NRC 800407 request BKINNER:W F Pennsylvania Power & Light Co 80/04/15 ip
- --8004210340 "Demonstration for Brunner Island Steam Electric Station Units 1-3, vols 1 & 2 " * E0 & 0. Inc 77/05/19 200pp
- --8004210344 "Potential Effects of Brunner Island Steam Electric Station on Future Higrations of American Shad in Susquehanna River."

 * E0 & 9. Inc 77/08/13 23pp
- --8004210347 "Probabilities of Normal & Worst Case Conditions in Busquehanna River during Critical Periods for Muskellunge Bpauning & Smallmouth Bass Egg Burvival & Davelopment " # EØ & Q, Inc 77/09/15 lópp

- --8004210349 "Assessment of Thermal Effects from Brunner Island Steam Electric Station Based on Newly Derived Max Weetly Average Temps " * EG & G. Inc 79/05/31 33pp
- ---8004210355 "Ecological Study of Effects of Brunner Island Steam Electric Station Cooling Water Intakes" JOHNSON, T D. PHOENIX, D.R. Roy F. Weston, Inc. 77/11/18 78pp
- --8004210358 "Biological Survey of Susquehanna River in Vicinity of York Haven-PA 1978 Terminal Rept WURTZ.C B Charles B Wurtz 79/06/29 33pp
- ---8004210366 "Ichthyofaunal & Creel Census/Fishing Pressure Surveys in Vicinity of Brunner Island Steam Electric Station" DENONCOURT, R. F. R. F. Denoncourt /8/05/31 161pp
- 8004280492 Comments on NUREC-0564. App B re archaelogical survey of Pond Hill Reservos: location Plan is preliminary rept containing no factural info re prehisturic matlithat might be found SOLENBERGER, R Bloomsberg State College 80/04/17 3pp
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8004220079 Forwards draft supp to Mar 1980 DES H/o encl BELLB,D E Environmental Projects Branch 2 80/03/31 Spp
- F Security, medical, emergency & fire protection plans
- BD04080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending 0AD clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- BOO4080175 Requests to make limited appearance statement at 800320 hearing ENDRIZZI,D Affiliation Unknown 80/02/27 Ip
- 8004100571 Notifies that NRC issued draft suppl to DES on 800331 Suppl & DES labelled NUREC-0564 DES issued & served on ASLB & all parties in June 1979 Draft suppl has been served on all persons on svc list Exceptions listed CUTCHIN. J M Hearing Branch 3 80/03/03 lp
- 8004080571 Requests to make limited appearance statement on behalf of Taxpayers Association of Lackawanna County at licensing hearings Evening on weekend sessions should be held for citizen participation

 SCHUMAGNER, K. Affiliation Unknown 80/03/07 ip
- 8004080154 Requests to make limited appearance statement at licensing hearings
 HEMMENDINGER. R Affiliation Uninoum 80/03/10 Spp

- --8004300073 Requests notification of time b location of licensing hearings for theirith, Acquists to make limited appearance statement
 DEIPICH. R. F. Arrillania of University 50 63-10 in
- --8004360015 Requeriantification of time 2 location of licensing heatings and facilities Regieves to make limited appearance statement Portion of reserves should be held on evenings? weekenos WINTER A. ! Artillation Un nown Bu/U2/29 ip
- --8004300029 Requests notification of time * location of licensing heatings for racilities Request, to make limited appearance statements Portion or feating thould be achoduled on on evenings of weekends
 FALLON P Affiliation inhomous 80/03/10 ip
- --8004300033 Requests notification of time 2 location of licensing hearings for facilities Pewie to to make limited appearance statement Portion or hemings should be scheduled for evenings of vectends Affiliation Unincum 80/03/10 1p
- --8004300036 Requests not privation of time to location of licensing hearings for facilities Requests to make limited appearance statement Portion of herrings should be scheduled for evening, the events of RAY-FF Afriliation Uninous 83/03/10 ip
- --8004300039 Expresses concern that util is attempting to limit participation of intervenor, at opcoming licensing hearings SKISLAF, S. Affiliation Unknown 80/03/10 1p
- --8004300042 Figresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings DUBIN K J. Affiliation Unknown 80/02/29 ip
- --8004300946 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings DERAYMOND, J.S. Affiliation Uninoun 80/03/10 1p
- --800430054 Requests making limited appearance statement concerning three motions on agenia of ARLB hearings in Wilkes-Barre,PA BUTCHKO.P R Affiliation Unknown 80/03/12 (p
- --8004300057 Requests notification of time & location of licensing hearings for facilities? to make limited appearance statement Portion of bearings should be held on evenings or weekends MERRILL, D K Affiliation Unknoon 80/03/08 ip
- --8004300061 Requests to make limited appearance statement at facility licensing hearings % notification of time % location of meeting lime for slaturents should be made available on weekends or evenings

 KRSYKWALE J Affiliation Unknown 80/03/11 ip
- --B004300063 Requests to make limited appearance statement at facility licensing had ings % notification of time 2 location of meeting Hearings should be held on evenings or weekends SMITH, D. Afriliation Uninown 80/03/21 ip
- 8004306066 Requests to make limited appearance statement at facility licensing hearings > nutification of time 2 location of meeting Time should be made available on evenings or weekends for statements

 MACHAKER, G. C. Affiliation Uninown 80/03/10 lp
 - 8004306067 Expresses concern that util is attempting to limit participation of intervendes at upcoming licensing hearings MIGGINS.R M. Affiliation Unknown 80/02/29 ip
- --8004300059 Requests to make lamited appearance statement in favor of util motions at 800320 ASLR hearings in Wilkes-Barre, PA MURRAY, F Scrunton Univ or 80/03/12 ip
- ---8004300070 Requests to make limited appearance statement at ASLB 800320 prefibering conference in Wilkes-Barre, PA THAMBERN E AREIL --- on Unknown BO/03/12 1p
 - f of Citizens Lobby, to make limited U320 licensing hearing in Wilkes-
 - 1known 80/03/11 1p

- --80043GUU73 Requests to make lamifed appearance statement at facility licensing hearing. * notrication of time A location of meeting Time should to made available for statements on evenings t weekends BRAMSO'4.L Arfiliation Unknown 80/03/13 ip
- -8004300076 Requests to make limited appearance statement at 800320 licensing hearing in Wilkes-Barre, PA ELLIOTTIC P. Arrilistion Unknown 80/03/1/ ip
- --8004300080 Expresses concern re /SLE consideration of util motion to restrict public interveners in licensing proceedings Full inquiry should be made in any attempts to demy public due process / rights within established NPC procedures SALZKANIL Friends of the Farth 60/03/13 1p
- --80043000B3 Requests to make limited appearance statement at facility licensing heatings to notification of time to location of meeting Time for statements should be made available on evenings or weekends

 BAULR5. R A Affiliation Unknown 80/03/10 1p
- --8004300088 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings * Affiliation Unknown 80/02/29 ip
- 8004020040 Response to ASLB 800722 prehearing conference memorandum & order Alleges restrictive & biased agenda Urges discussion of onsite inspladvisability & reconsideration of denied contentions W/Certificate of Svc HALLIGAN, T.J. Citizens Against Nuclear Dangers 80/03/12 4pp
- 8004080143 Response to ASLB GU0222 order setting oral argument re applicant motions to prohibit Susquehanna Environ Advocates & Environ Coalition on Nuclear Power from litigation of contentions Urges to cancel argument M/Certificate of Svc JONHSRUD-J H Environmental Coalition on Nuclear Power 80/03.
- 8004080697 Request for expedited consideration of AGLN actions re discovery limits 5 decision-making Urges omission of util motions to restrict intervenors participation in 800320 oral argument Requests certification Certificate of Byc encl JOHNSRUD. J H Environmental Coalition on Nuclear Power BO Environmental Coalition on Nuclear Power 80/03/14
- 8004230006 Petition to raise specific issues at 800320 prehearing conference, re intervenors' motions for protective order on Contentions 1 0 20 status as full party in proceeding SCHULTZ, G R Susquehama Environmental Advocates 80/03/14 B0/03/14 2pp
- 8004080156 Requests to make limited appearance statement at licensing hearing BURNS,D Affiliation Unknown 80/03/15 ip
- 8004080161 Requests to make limited appearance statement at licensing hearing GEIGER, G Affiliation Unknown 80/03/15 2pb
- 8004180136 Responds to B00214 ltr to Gilinsky re concern about treatment of public participant. Environ Coalition on Nuclear Power & directors J Johnssod in license proceeding NRC regulations does not permit views off-the-record FITZ0ERALD, J A Office of the Executive Legal Director B0/03/20
- 8004080685 Memorandum re ASLB 800320-21 prehearing denial of applicants motions against Environ Coalition on Nuclear Power & Susquehanna Environ Advocates Delineates areas in which intervenors should supplement answers to interrogatorios PARIS.O H , BECHHOEFER.C Atomic Safety and Licensing Board Panel 80/03/27 opp
- 8004220032 Submits comments re NRC in post-TMI period & licensing situation at facilities Recommends suspension of CP until independent auditors assess need for power & alternatives PERKINS.J.L. Affiliation Unknown 80/03/27 3pp
- 8004180249 Requests to make limited appearance statement at licensing hearing SHELLY:FL Affiliation Unknown 80/03/31 ip
- 8004100331 Requests to make limited appoarance statement at licensing grehearing LAWSUN, L. Affiliation Unknown 80/04/01 1p

- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GUSSICK, U Office of the Executive Director for Operations 80/04/02 34pp
- 8004110016 Responds to ASLB 800320-21 prehearing conference request to examine possibility of making available in Wilkos-Barre area complete set of AEC & NRC repts of cases decided by Commission Repts will be loaned to Osterhout Free Library CUTCHIN. J M Hearing Branch 3 80/04/03 2pp
- --8004110019 Submits trip rept re 800313-14 visit to Osterhout Free Library, Wilkes-Barre, PA Library houses Susquehanna LPDR documents Library does not loan out documents to patrons Documents in good order but in need of revamping LOGAN, F Division of Rules and Records 80/04/03 2pp
- 8004150067 Response in opposition to Environ Coalition on Nuclear Power 800315 petition for review of ASLB prehearing rulings Requests to address merity if appeal is granted Certificate of Svc encl CUYCHIN.J M Hearing Branch 3 80/04/04 11pp
- 8004230111 Second prehearing conference order denying applicants' motions to restrict Susquehanna Environ Advocates & Environ Coalition on Nuclear Power participation Citizens Against Nuclear Dangers environ contentions limited to dwn filing PARIS.O H , BECHHOEFER.C Atomic Safety and Licensing Board Panel 80/04/11 21pp
- 8004280246 Forwards Univ of Heidelberg revised Translation 520, "Radiological Assessment of With Nuclear Power Plant" "Review of Myhl Rept" will be available to public in form of NUREO M/o oncl CUTCHIN.J M Hearing Branch 4 80/04/24 ip

H General correspondence

- 8004080065 Expresses concern re excessive number of interrogatories sent to J Johnsrud as intervenor in licensing hearings Appears that NRC is trying to hinder J Johnsrud effectiveness Certificate of Svc encl WARDEN.W O Affiliation Unknown 80/02/14 4pp
- 8004040176 Advises that news media & info groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Protests util afforts

 LEON, A Affiliation Unknown 80/02/27 ip
- 8004070185 Requests notification of time & location of upcoming hearing on facility licensing Urges scheduling of hearings on weekends or evenings WIGOINS, R M. Affillation Unknown GO/02/27 2pp
- BOO4070191 Requests notification of time & location of upcoming hearing on facility licensing Urges scheduling of hearings on weekends or evenings
 RHEINHEIMER, D Affiliation Unknown BO/02/29 2pp
- 8004040166 Requests notification of time & location of upcoming hearing on facility licensing, scheduling hearing on weekends or evening & limited appearance at hearing WESTNEDOE, T. Affiliation Unknown 80/03/03 2pp
- 8004070064 Advises that news media & info groups show util attempting to mixuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Protests util efforts
 RHEINHEIMER.D Affiliation Unknown B0/03/03 ip
- BO04070193 Requests notification of time & location of upcoming hearing on facility licensing Unges scheduling of hearings on weekends or evenings Requests limited appearance at hearing BRISTOL.M Affiliation Unknown 80/03/04 2pp
- 8004090184 Expresses fear for potential castastrophe resulting from const of facility RODACK.M Affiliation Unknown 80/03/05 ip
- 8004030334 Suggests util is attempting to limit participation of intervenors at open licensing hearings All interested parties should be heard NRC should be aware of situation CREE, R E Affiliation Unknown 80/03/15 ip

- 8004040108 Advises that news media & info groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Protests util efforts

 KULICH,D J Affiliation Unknown 80'03'15 !P
- 8004040226 Advises that news modia & into groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Protests util efforts
 FASCIO,P Affiliation Unknown 80/03/15 ip
- 8004040333 Expresses concern about prospect of plant in Berwick area Nuclear power is impractical? dangerous Future generations will be untainly saddled whresponsibility of our energy consumption
 RELSON, K. J. Aftiliation Uninown 80/03/15 in
- 9 Inspection reports, 18 Bulletins & correspondence
- /812[10287 Forwards IE Insp Repts 50-38/78-15 % 50-388/78-13 on 780821-0921 % notice or violation CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 78/10/17 2pp
- --7812110289 Notice of violation from insp on 780821-0921
 * Region 1 Philadelphia, Office of the Director 78/10/17 2pp
- --7812110291 IE Insp Repts 50-387/78-15 % 50-388/79-13 on 780821-0921 Nancompliance noted railure to qualify wolders & failure to use specified curing compound for spray pond GALLO.R // Region 1, Philadelphia, Office of the Director MCOAUCHY,R W Region 1, Philadelphia, Reactor Construction & Engineering Support Blanch 78/10/1/ 13pp
- 8004070379 Ack receipt of 800227 ltr informing NRC of steps taken to correct violations noted in If Imap Repts 50-387/79-36 & 50-388/79-19 CARLSON, R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 30/03/07 ip
- --B004070382 Responds to NRC 800123 ltr re violations noted in IE Insp Repts 50-387/79-36 & 50-388/79-19 Corrective actions amended Bechtel Field Insp Manual Procedure G-3/Revision 6 & held training sessions for field engineers on bolt installation SABOL/A R Pennsylvania Powor & Light Co 80/02/27 5pp
- --8004070385 Forwards LF Insp Repts 50-39///9-36 % 50-388/79-19 on 791029-1102 % notice of violation CARLSON, R T Region L. Philadelphia. Reactor Construction & Engineering Support Branch 80/01/23 2pp
- --8004070391 Notice of violation from insp on 791029-1102
 * Region 1, Philadelphia, Office of the Director 80/01/11 2pp
- --8004070396 IE Insp Repts 50-387/79-36 & 50-388/79-19 on 791029-1102
 Noncompliance noted failure to provide adequate design
 review resulting in nunconforming installation & failure to
 follow procedure for Lagging nonconforming items
 PACLING.R J Region I. Philadelphia. Office of the Director
 ESNETER.S D Region I. Philadelphia. Reactor Construction &
 Engineering Support Branch

- --8004100111 IE Insp Pepts 5C-337/79-31 & 50-388/79-16 on 790910-1005
 Noncompliance noted failure to review SRSE 1-12.Revision 2
 & to provide documented instruction to control completion
 re water quenching of weld VRR-331-2-FW-13M
 MCCAUCHY.R W Region 1. Philadelphia. Reactor Construction &
 Engineering Support Branch HIGGINS, J C . GALLO.R M Region 1.
 Philadelphia. Office of the Director 80/01/09 12pp
- 8004)50£75 Forwards IF Info Notice 80-j2. "Instrument Failure Causes Opening or PORV & Block Valve ' No specific action or response necessary GRIER, B H Region i, Philadelphia, Office of the Director 80/03/31 1p
- 8004090097 Forwards IE Circulai 80-05, 'Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply 'No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 ip
- BO04110504 Forwards IF Info Notice BO-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER.B H. Region J. Philadelphia, Office of the Director BO/04/02 ip
- 8004240341 Forwards lE Info Notice 80-14. "Safety Suggestions From Employees" No action required QRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004180189 Forwards lE Circular 80-07. "Problems W/MPCI Turbine Oil Sys " No written response required CRIER.B H Region 1. Philadelphia. Office of the Director 80/04/03 ip
- B00411006B Forwards IE Builetin AO-07, 'BWR Jet Pump Assembly Failure " No written response required QRIER, B H Region 1, Philadelphia, Office of the Director B0/04/04 ip
- 8004230481 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required CRIER, B H Region 1. Philadelphia. Office of the Director 80/04/04 Ip
- 8004180270 Forwards LE Sulletin 80-08, "Esam of Containment Liner Penetration Welds " Written response required ORIER, B II Region 1, Philadelphia, Office of the Director 80/04/07 ip
- S Reportable accurrences, LERs & related correspondence
- 8004080516 Final deficiency rept re hydramotor actuator springs Affected dampers have been identified & being controlled Actuators will either be replaced or tested to establish adequacy CURTIS.N W Pennsylvania Power & Light Co 80/03/20 2pp
- --8004080521 Informs NRC of notification to 13 purchasers of NH model milliampere hydramotor actuators Actuators have been discovered to be mfg from incorrect matl FORMELLA,R L. ITT General Controls. Division of Intl. Tel. & Tel. Corp. 79/12/07 4pp
- 8004080363 Interim deficiency rept re defective cast carbon steel swing check valves mfg by Pacific Valve.Inc Final rept will be forwarded during Jone 1980

 CURTIS.N W Pennsylvania Power & Light Co 80/03/31 2pp
 - 04290394 Forwards final deficiency rept re Culter Hammer E-30 pushbutton sticking problem & dislodgement of Switch CH E-30AB from contact block Conditions of Amphenol female connectors not reportable under 10CFR50 Rationale encl. CURYIS.// U Pennsylvania Power & Light Co 80/04/18 Spp.
- -8004290399 Final deficiency rept re Cutler Hammer E-GO pushbutton sticking problem % dislodgement of Switch CH E-GOAB from contact block Sticking pushbutton corrected by acraping adge Locking devices for CH E-GO switches retightened Pennsylvania Power % Light Co 80/04/18 3pp
- 8004300374 Forwards final deficiency rept re Cutler-Hammer E-30 pushbutton switches CURTIS, N W Pennsylvania Power & Light Co 80/04/18 2pp
- --8004300383 Final deficiency rept re Cutler-Hammer E-30 pushbutton suitches Sticting of pushbutton occurs on two-button modules Disiodgement of operating module apparently caused by mechanical locking ring not being tightly locked a Pennsylvania Power & Light Co 80/04/18 4pp

- T Hearing transcripts on non-antitrust matters
- B004020687 Transcript of 800320 prehearing conference in Wilkes-Barre, PA Pp 375-645 BECHOFFER.C E Atomic Safety and Licensing Board Panel 80/03/20 272na
- 8004180233 Transcript of 800320 prehearing conference P 375 only * Atomic Safety and Licensing Board Panel 80/03/20 1p
- ---8004180238 Transcript of 800320 prehearing conference P 1 only
 Atomic Safety and Licensing Board Panel 80/03/21 ip
- BO04020146 Transcript of B00321 prehearing conference in Wilkes-Barre, PA Pp 646-757
 BECHNOEFER.C E Atomic Safety and Licensing Board Panel B0/03/21
- U Congressional/Executive Correspondence
- 6004080212 Responds to J Ulma request for status of facility licensing Licensing process delayed due to post-TMI efforts to upgrade safety requirements NRC is evaluating available resources to re-establish applicant review schedules DIRCKS, W J Office of the Executive Director for Operations. 80/03/06 3pp
- ---8004080218 Forwards 1tr re J Ulman request for status of facility licensing MCDADE.J M House of Rep 80/02/07 2pp
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 800404031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS,DF Division of Project Management 80/02/05 7pp
- 8004220239 Forwards general info section of application for OL UHRIGAR E Florida Power & Light Co 80/03/24 ip
- --8004220243 General info section of application for DL UHRIO.R E Florida Power & Light Co 80/03/31 10pp
- B00425003B Requests technical basis, analysis & experimental data re use of Ameron NUKEM 750 cault as expansion joint filler inside containment info should be provided by B00530 or NRC should be informed in seven days if unable to meet schedule BAER.R L Light Water Reactors Branch 2 80/04/10 2pp
- 8004280267 Responds to NRC 800410 ltr requesting that info re use of NUKEM 750 be provided by 800530 Technical basis for use of NUKEM 750 as qualified caulk requested from Ameron Info will not be available by 800530 Bubmittal expected 800730 UHRIG:R E Florida Power & Light Co 80/04/22 ip.
- C Utility Environmental Report (ER), amends & correspondence
- 8004220313 Forwards environ rept for plant, Vols 1 & 2 Rept available in PDR UHRIG.R E Florida Power & Light Co 80/03/24 1p
- --8004220317 Environ rept. Vol 1 4 Florida Power & Light Co 80/03/24 700pp
- --8004220321 Environ rept, Val 2 * Florida Power & Light Co 80/03/24 700pp
- F Security, medical, emergency & fire protection plans
- BOO40B0077 Advises that submittal data for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending OAU clearance under Federal Repts Act ORIMES, B K Emergency Preparadness Task Force 80/03/11, 4pp
- 8004030229 Provides status of response to 791226 request for evacuation time estimates Draft inputs from consultants expected by 800331 Final draft circulation to state & local officials will precede 800430 submittal of final rept to NRC.

 URRIQ.R E Florida Power & Light Co 80/03/31 1p

G Adjudicatory correspondence

- 8004210109 Motion re Commission 790914 order requesting issuance of FES suppl giving consideration to envilon consequences of Class 9 accidents
 HODDER M H Affiliation Unknown 79/12/12 4pp
- B004220141 Requests denial or intervenor 791212 motion re Class 9 accidents Class 9 issue was disposed of in CP proceeding Intervenors should invoke different procedural remedy Supporting documentation encl REIS.H F Florida Power & Light Co REIS.H F Lowenstein, Nowman, Reis, Axelrad & Toll B0/01/16 23pp
- 8004190160 Response to intervenors RE Roberts, et al.800118 motion to consider Class 9 accidents Intervenors may potition NRC per 10CFR2 206, due to ASLAO lack of jurisdiction to grant OLMSTEAD, W J , PATON, W D Hearing Branch 4 80/01/18 11pp
- 8004150148 Hemarandum & order re intervenors' 791212 motion for consideration of Class 9 accidents Motion dismissed & documents referred to director of Nuclear Reactor Regulation to be treated under IOCFR2 2 6
 BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/02/14
- BOO402021B Informs that motion for consideration of Class 9 accidents will be handled as request for action under IOCFR2 206
 Response to motion within 30 days cannot be guaranteed
 Supporting documentation enci
 DENTON, H R Dffice of Nuclear Reactor Regulation 80/03/06 2pp
- --8004020222 Notice that MH Hodder & TJ Anderson request for action has been referred to Director of Nuclear Reactor Regulation for consideration under 10CFR2 206 DENTON,H R Office of Nuclear Reactor Regulation 80/03/06 1p
- ---8004020228 Forwards formal ASLAB referral of intervenors' motion to consider environ offects of Class 9 accidents Requests consideration under 10CFR2 206
 NURRAY, J P Office of the Executive Legal Director 60/02/22
- ~-8004020231 Forwards intervenors' motion to consider environ consequences of Class 9 accidents Supporting documentation encl DIBHOP,C J Atomic Safety and Licensing Appeal Panel 80/02/14
- --B004020237 Motion for order to consider environ consequences of Class 9 accidents in determination of environ impact of proposed plant const Certificate of Svc & marked-up Commission 790914 memorandum & order re floating nuclear plants encl HDDDER.H H Hodder,M H ANDERSON,T J Miami, FL, Univ of 79/12/12 18pp
- --8004020265 Response in opposition to interveners' motion for consideration of environ impact of Class 9 accidents. Cartificate of Svc & supporting documentation enci RRIS.H F . COLL.N A Florida Power & Light Co REIS.H. F Lowenstein, Neuman, Reis, Axelrad & Toll 80/01/16 29pp
- --8004020277 Response to RE Roberts, at al, motion to consider Class 9 accidents ABLAB lacks jurisdiction to grant motion Alternative forms of relief are available Class 9 accidents should not be addressed in proceeding W/Certificate of 8vc DLMSTEAD, N J , PATON, N D Hearing Branch 4 80/01/18 13pp
- --8004020272 Reply to applicant & NRC response to intervenors' motion for consideration of environ effects of Class 9 accidents Proximity between proposed plant on Hutchinson Island & Atlantic Gulfstream requires Class 9 consideration ANDERSON, T J Miami, FL, Univ of HODDER, M H Hodder, M H BO/02/05 19pp
- --B004020282 Order for dismissal of intervenors' motion for consideration of Class 9 accidents ASLAB is without authority to consider issues Motion referred to Director of Nuclear Reactor Regulation for consideration under 100FR2 206
 BIGHOP.C J Atomic Safety and Licensing Appeal Panel 80/02/14
- 8004020005 Forwards applicant affidavit of GF Lieber re performance of Unit 1 diesel generator Certificate of Svc encl. COLL,N A Steel, Hector & Davis 80/03/14 3pp
- --8004020011 Affidavit re performance of Unit 1 diesel generator Supporting documentation encl LIEBLER, O E Florida Power & Light Co 80/03/14 17pp

- 8004090043 Advises that no add! NRC response necessary to util 800413 submittal re-performance of Unit 1 diesel generator NRC perspective re-relevants of Unit 1 diesel data to proceeding reported at Transcript 732 734 PATON.W D Hearing Branch 1 FO/03/28 1p
- 8004030026 Memorandum of understanding between NPC & FEMA re prompt improvement in radiological emergency planning "
 preparedness distributed as Board notification
 GOSSICKL V Office of the Crecutive Director for Operations
 BO/04/02 34pp

I Financial information

- 8004150406 Forwards Annual Financial Rept 1979 UHRIG.R E Florida Power & Light Co 80/04 80/04/08 10
- --8004150411 Annual Financial Rept 1979 + Florida Power & Light Co 80/02/08 72pp
- K Utility Final Samety Analysis Report (FSAR) & amends
- 8004220248 Forwards FSAR Vols 1-11 FBAR available in PDR UHRIG.R E Florida Power & Light Co 80/03/24 ip
- ---8004220250 FSAR for Saint Lucie Unit 2, Vols 1-11 * Florida Power 2 Light Co 60/03/24 11, 26
- 8004220256 Chapter 1 of Saint Lucie FSAR." Introduction & General Description of Plant Site Characteristics " * Florida Power & Light Co 80/03/24 400pp
- 8004220258 Chapter 2 of Saint Lucie FSAR. * Florida Power 3 Light Co 80/03/24 "Site Characteristics " 3000pp
- 8004220261 Chapter 3 of Saint Lucie FSAR, "Design of Structure, Components, Equipment & Sys."

 * Florida Power & Light Co. 80/03/24 2000pp
- 8004220264 Chapter 4 of Saint Lucie FSAR. * Florida Power & Light Co 80/03/24 "Reactor " 600pp
- 8004220264 Chapter 5 of Saint Lucie FSAR, * Florida Power & Light Co 80/03/24 "RCS & Connected Sus "
- "Engineered Safety Features " 1000pp 8004220271 Chapter 6 of Saint Lucie FSAR * Florida Power & Light Co 00/03/24
- 8004220275 Chapter 7 of Saint Lucie FSAR, * Florida Power & Light Co 80/03/24 "Instrumentation & Control " 400pp
- 8004220279 Chapter 8 of Saint Lucie FSAR * Florida Power 9 Light Co 80/03/24 "Electric Power "
- 8004220283 Chapter 9 of Saint Lucie FSAR. * Florida Power & Light Co 80/03/24 "Auxiliary Sys " 100000
- 8004220287 Chapter 10 of Saint Lucie FSAR, "Steam & Power Conversion Bys " * Florida Power % Light Co 80/03/24
- 8004220296 Chapter 11 of Saint Lucie FSAR.

 # Florida Power 4 Light Co 80/03/24 "Radwaste Mot "
- 8004220298 Chapter 12 of Saint Lucie FSAR. * Florida Power * Light Co 80/03/24 400pp

"Radiation Protection "

- 8004220300 Chapter 13 of Saint Lucie FSAR: * Florida Power & Light Co 80/03/24 "Conduct of Operations " 150pp
- 8004220305 Chapter 14 of Saint Lucie FBAR, * Florida Power & Light Co 80/03/24 "Initial Test Program " 200pp
- 8004220306 Chapter 15 of Saint Lucie FBAR. * Florida Power & Light Co 80/03/24 "Accident Analysis " 1000pp
- 800422030B Chapter 16 of Saint Lucie FSAR, "Tech Specs" # Florida Power & Light Co 80/03/24 ip
- 8004220309 Chapter 17 of Saint Lucie FSAR. "0A" * Florida Power & Light Co 80/03/24 10pp

M Antitrus Correspondence

- B004230176 Response to B0C111 ltm (icense conditions referenced in ltm have not been received Centificate of Svc encl JABLON & A Florida Cities B0/04/15 2pp
- G. Inspection reports. IE Bulletin, & correspondence
- 6004090344 Forwards IF Bull-'in 80-03, 'Loss of Charcoal From Std Type II, Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J.F. Region 2, Atlanta, Orfice of the Director 80/02/06 200
- 8004040167 Ack receipt of 800304 ltr informing NRC of steps taken to correct violations noted in IF Insp Rept 50-389/79-18 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/21 tp
- --8004040173 Responds to NRC 791105 ltr re violations noted in IE linsp Rept 50-389/79-18 Corrective actions lot numbers for resin & cure containers verified as same Surveillance verified delivery & segregation of natis UHRIG.R E Florida Fower & Light Co 80/03/04 1p
- 8004240217 Responds to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys " Relays noted in bulletin are not used or planned for use in safety-related sys at facility UHRIQ.R E Florida Power & Light Co 80/03/28 1p
- 8004190517 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening or PORV & Block Valve " No specific action or response necessary D'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/03/31 200
- 8004080619 Forwards IE Circular 80-05. "Emergency Dieset Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01
- 8004150081 Farwards IE Info Notice 80-13. "OE Type SDM Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240260 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees "No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pg
- B004180321 Forwards 1E Circulai 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required O'REILLY J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004230165 Forwards IE Bulletin 79-03A "Longitudinat Weld Defects in ASME SA 312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004180417 Forwards IE Bulletin 80-08. 'Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/07 200
- Reportable occurrences, LERs & related correspondence
- 3004210170 Forwards 80032: interim deficiency rept re spring in certain hydramotor accustors for dampers being mfg from incorrect matl & possibility of selection nomographs being interpreted incorrectly Final rept will be submitted by 800430 UHRIG.R E Florida Power 5 Light Co 80/03/25 1p
- ~~8004210184 Interim deficiency rept re spring in certain hydramotor actuators for dampers being mfg from incurrect math & possibility or selection nomographs being interpreted incorrectly Affected dampers being placed on hold # Florida Power & Light Co 90/03/21 4pp

- DOCKET 50-370 WATTS BAR NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Btaff Position on Environ Qualification of Safety-Related Electrical Equipment "providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS, D.F. Division of Project Management 80/02/21 3pp
- 800423005B Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of DL W/encl ROSS, D F Division of Project Management 80/03/10 S3pp
- 8004020385 Forwards "Operational Stage Nonradiological Fisheries Monitoring Program " Info supplements operational water quality & aquatic biology monitoring program provided on 791012 EL-ASBRY.M T Tennessee Valley Authority 80/03/24 2pp
- --800402039B "Operational Stage Nonradiological Fisheries Monitoring Program " * Tennessee Valley Authority 80/03/24 7pp
- 8004110425 Forwards application for renewal of NPDES Permit TN0020168 Supporting documentation encl EL-ASHRY.M T Tennessee Valley Authority 80/04/07 100pp
- 8004170213 Requests meeting between NRC & util to ensure that qualification requirements for reactor operators & senior reactor operators are met Forwards licensing & training criteria for license candidates
 MILLS.L II Tennessee Valley Authority 80/04/14 2pp
- 8004290453 Responds to NRC 790730 1tr by forwarding comments on NRC-proposed ETS 3. Status of transmission lines Repts supporting suggested mods oncl
 MILLS.L.M Fennessee Vailey Authority 80/04/22 19pp
- --8004290458 "Evaluation of Volunteer Vegetation Along Newly Cleared Rights of Way " FOHLER,D K , ADKISSION,L F , TURNER,L J Tennesses Valley Authority RW 2 79/07/31 31pp
- --8004290462 "Preoperational Sounds Levels "
 * Tennessec Valley Authority 80/04/22 13pp
- --B004290467 "Cooling Touer & Steam Plant Plumo Morgence at Site " KNUDSON.D A Tennessee Valley Authority TVA/AQB-179/13 79/07/31 52pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 itr has been postponed pending GAD clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 App
- 8004240402 Forwards comments on safeguards contingency plan Comments withheld (ref IOCFR2 790) RUBENSTEIN.L 9 Light Water Reactors Branch 4 80/04/10 2pp
- a Inspection reports. IE Bulletins & correspondence
- 8004090392 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type 11.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/04.
- 8004230036 Forwards IE Insp Repts 50-390/80-03 & 50-391/80-02 on 800129-0201 No noncomplience noted ERYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/22 2pp

- --8004230044 IF Inst Repts 50-390/60-03 t 50-391/80-02 on 800129-0201 No 104230046 IE Insp Repts 50-390/80-03 & 30-391/80-02 on 800 noncompliance noted Major areas inspected 10CFR50 35(e) items.chipping activities in auxiliary bldg,vital battery rooms & diesel generator bldg CANTRELL,F S Region 2. Atlanta. Reactor Construction & Engineering Support Branch THOMAS.K Region 2. Atlanta of the Director 80/02/21 4pp Region 2, Atlanta, Office
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC 8 util in Atlanta, GA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by GA program UREILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/12
- 8004210178 Forwards response to IE Sulletin 80-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Cells " Encl lists results of insps at facilities to detormine if potential for loss of charcoal incidental to handling or use exists HILLS,L ff Tennessee Valley Authority 80/03/21 App
- 8004180104 Forwards response to 1C Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskots have been ordered MILLG,L M Tennessee Valley Authority 80/03/28 2pp
- 8004150527 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080636 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/04/ Region 2, Atlanta, Office of the Director BO/04/01
- 8004150097 Ferwards IE Info Notice 80-13, "GE Type GBM Control Switches Defective CAM Followers " No specific action or response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80704702
- 8004240274 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04 80/04/04
- 8004180445 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07
- 8004300462 Ack receipt of 800314 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-390/79-47 & 50-391/79-40 HWRPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/07 2pp
- --8004300474 Bubmits revised response to NRC 800114 ltr re violations noted in IE Insp Repts 50-390/79-47 & 50-371/79-40 Corrective actions incorrectly tagged cable has been properly certified & recorded in certification status rept NILLS.L.M Tennessee Valley Authority 80/03/14 3pp
- 6004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice MILLS, L M Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- 8004180331 Forwards "Preoperational Fisheries Monitoring Rept.1977-79 "
 Preoperational rept describing water quality & nonFisheries
 biological monitoring results will be submitted by B00627
 EL-ASHRY.M T Yennessee Valley Authority 80/04/15 2pp

- --8004180337 "Preoperational Fisheries Monitoring Rept.1977-79 "
 BUCHANAN, J.P., KIRBY, N.S., PECK, G.E., Tennessee Valley Authority
 80/03/31 157pp
- 5 Reportable occurrences, LERs > related correspondence
- 8004020312 Forwards final deficiency rept re Russin fire dampers
 MILLS.L M Tennessee Valley Authority 80/03/28 ip HILLS L H
- --8004020316 Final deficiency rept re spring slipping problem on Ruskin fire dampers Mod packages will be installed w/connection of Number 6 screw using washer, star lockwasher & her nut through narrow portion of spring slot * Tennessee Valley Authority 80/03/28 tp
- 8004150413 Second interim deficiency rept re control rod drop events yielding less conservative DIBR than stated in FSAR Westinghouse investigation in progress Next rept will be submitted by 800506 MILLBIL M Tennessee Valley Authority 80/04/01 ip
- 8004150437 Forwards final deficiency rept re potential lubrication problem in diesel generator turbochanger MILLS:L N Tennessee Valley Authority 80/04/01 (p
- --8004150450 Final deficiency rept re potential lubrication problem in generator turbocharger Diesel generators will not be unnecessarily started between 15 minutes & 3-h following shutdown from previous run at full operating temp # Tennessee Valley Authority 80/04/01 3pp
- 8004280537 Forwards second interim deficiency rept re incorrect bore in Drave transmitter bosses MILLS.L M Texnessee Valley Authoraty 80/04/07 ip
- --8004280544 Second interim dericiency rept re incorrect bore in five Dravo transmitter bosses Caused by breakdown in Dravo GA insp program Flow restrictor will be installed between one boss & valve Remaining bosses will be checked * Tennessee Valley Authority 80/04/07 ip
- 8004280536 Third interim deficiency rept re surface crack in loop one steam generator Westinghouse investigation has not been campleted Next rept will be submitted by 800613 MILLS.L.M Tennessee Valley Authority 80/04/09 ip
- 8004180377 Forwards final deficiency rept re grouted anchor bolts on main steam line support MILLS, L M Tennessee Valley Authority GO/04/10 (p
- ---8004[8038] Final deficiency rept re grouted anchor bolts on main steam line supports Original anchor bolt design will be replaced w/redesigned bolts fabricated from A173 steel w/A174 nuts by 800801 for Unit 1 & 8(07)1 for Unit 2 MILLS.L M Tennessee Valley Authority 80/04/10 1p

- 8004290346 Forwards first interim deficiency rept re defective reactor vessel upper internals guide tube support pins MILLS.L IS Tennessee Valley Authority 80/04/23 ip
- --8004270.353 First interim deficiency meptine generic problem w/defective reactor vessel upper internals guide tube support pins.
 Caused by heat treatment Westinghouse will investigate to determine in design changes are required a Tennessee Valley Authority 80/04/23 ip
- 8004290596 Informs of error in dates re submittal of interim deficiency rept re control rod disp events yielding less convervative DNBRs than stated in FSAR Hert rept will be submitted by 8004600 not 800506 as eliconeously, stated in 800401 ltr MILLG.L M Tennossee Valley Authority 80/04/24 ip
- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment, providing guidance re methods for compliance ROSS, D.F. Division of Project Management
- 8004040017 Submits addl guidance to NUREG-0588. "Interim Btaff Position on Environ Qualitication of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- B00423005B Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of CL W-encl ROSS,D F Division of Project Management B0/03/10 53pp
- 8004020385 Forwards "Operational Stage Nonradiological Fisheries Monitoring Program" Info Supplements operational water quality & equatic biology monitoring program provided on 791012 EL-ASBRY, M T Tennessee Valley Authority 80/03/24 2pp
- ~-8004020388 "Operational Stage Nonradiological Fisheries Monitoring Program " * Tennessee Valley Authority 80/03/24 7pp
- 8004110425 Forwards application for renewal of NPDES Permit TN0020168 Supporting documentation encl EL-ASHRY, M T Tennessee Valley Authority 80/04/07 100pp
- 8004170213 Requests meeting between NRC & util to ensure that qualification requirements for reactor operators & senior reactor operators are met Forwards licensing & training criteria for license candidates
 MILLS.C. M. Tennessee Valley Authority 80/04/14 2pp
- B004290453 Responds to NRC 790730 itr by forwarding comments on NRC-proposed ETS & status of transmission lines Repts supporting suggested mods encl
 MILLS,L M Tennessee Valley Authority 80/04/22 19pp
- --8004290458 "Evaluation of Volunteer Vegetation Along Newly Cleared Rights of Way " FORLER, D K . ADXISSION, L F . TURNER, L J Tennessee Valley Authority RH 2 79/07/31 31pp
- --8004290462 "Preoperational Sounds Levels "
 * Tennessee Valley Authority 80/04/22 13pp
- ~-8004290467 "Cooling Tower & Steam Plant Plume Mergence at Bite " XNUDSON.D A Tennessee Valley Authority TVA/AGB-179/13 79/07/31 52pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 794226 ltr.has been postponed pending CAO clearance under Federal Repts Act
 ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004240482 Forwards comments on safequards contingency plan Comments withheld (ref 1005R2 790)
 RUGENSTEINLS Light Water Reactors Branch 4 80/04/10 2pp

- Q Inspection reports, IE Builetins & correspondence
- 8004090352 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type 11. Two-Inch, Tray Adsorber Colls' Action required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/06
- 8004230036 Forwards IE Insp Repts 50-390/80-03 & 90-391/80-02 on BO0129-0201 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/22 2pp
- --B004230045 IE Insp Repts 50-390/80-03 2, 50-391/80-02 on 800129-0201 No noncompliance noted Major areas inspected 10CFR50 55(a) items-chipping activities in auxiliary bldg.vital battery rooms & diesel generator bldg CANTRELL; S Region 2, Atlanta, Reactor Construction & Engineering Support Branch THOMAS.M Region 2, Atlanta, Office of the Director 80/02/21 App
- 8004070025 Confirms 800310 telcon arranging 800320 meeting between NRC butil in Atlanta, GA to discuss accuracy of written repts provided to 1E NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/12 2pp
- B004210178 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II. Two-Inch. Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bullotin 79-28 re possible malfunction of NAMCO Model EAIBO limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS,L N Tennessee Valley Authority 80/03/28 2pp
- 8004i50527 Forwards IE [nfo Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/31
- B004080636 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01 200
- 6004150097 Forwards IE Info Notice 80-13. "GE Type BBM Control Switches
 Defective CAM Followers " No specific action or response
 required
 D'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/02
- 8004240274 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees "No action required O'REILLY. J P Region 2. Atlanta, Office of the Director 80/04/02
- 8004180275 Forwards lE Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director B0/04/03
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME 6A-312, Type 304 Stainless Steel Pipe " Action required O'REILLY-J P Region 2. Atlanta, Orfice of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Helds " Written response required D'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/04/07.
- 8004300462 Ack receipt of 800314 ltr informing NRC of steps taken to correct violations noted in 1E Insp Ropts 50-390/79-47 & 50-391/79-40 MURPHYC E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/07 2pp
- --8004300474 Submits revised response to NRC B00114 ltr re violations noted in IE Insp Repts 30-390/79-47 & 50-391/79-40 Corrective actions incorrectly tagged cable has been properly certified 8 recorded in certification status rapt MILLS.L M Tennessee Valley Authority 80/03/14 3pp

- 8004270379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp
- MILLS, L M Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- 8004180331 Forwards "Preoperational Fisheries Monitoring Rept,1977-79 " Preoperational rept describing water quality & nonfisheries biological monitoring results will be submitted by 800627 EL-ABHRY,M T Tennessee Valley Authority 80/04/15 2pp
- --8004180337 "Preoperational Fisheries Monitoring Rept.1977-79 "
 BUCHANAN, J.P., KIRBY, M.S., PECK, G.E. Tennessee Valley Authority
 80/03/31 157pp
- 8 Reportable occurrences. LERs & related correspondence
- 8004020312 Forwards final deficiency rept re Ruskin fire dampers MILLS,L M Tennesses Valley Authority 80/03/28 ip
- --8004020316 Final deficiency rept re spring slipping problem on Ruskin fire dampers Mod packages will be installed w/connection of Number 6 screw using washer star lockwasher & her nut through narrow portion of spring slat # Tennessee Valley Authority 80/03/28 lp
- 8004150413 Second interim deficiency rept re control rod drop events yielding less conservative DNBR than stated in FBAR Westinghouse investigation in progress Next rept will be submitted by 800506 MILLS/L M Tennessee Valley Authority 80/04/01 ip
- 8004150437 Forwards final deficiency rept re potential lubrication problem in diesel generator turbocharger MILLS.L (1 Tennessee Valley Authority 80/04/01 1p
- --B004;50450 Final deficiency rept re potential lubrication problem in generator turbucharger Diesel generators will not be unnecessarily started between 15 minutes & 3-h following shutdown from previous run at full operating temp * Tennessee Valley Authority B0/04/01 3pp
- 8004180377 Forwards final deficiency rept re grouted anchor bolts on main steam line support MILLS.L M Tennessee Valley Authority 80/04/10 ip
- ---BOO41BO3B1 Final deficiency rept re grouted anchor bults on main steam
 line supports Original anchor bult design will be replaced
 w/redesigned bolts fabricated from A193 steel w/A194 nuts
 by BO0901 for Unit 1 & B10711 for Unit 2
 MILLB.L M Tennessee Valley Authority BO/04/10 ip
- B0042B094B Forwards final deficiency rept re grouted anchor bolts on main steam line supports
 MILLB.L M Tennessee Valley Authority B0/04/10 1p
- B004180444 Fourth interim deficiency rept re fabrication of refueling water storage tank overflow line, in violation of ASME code Final rept will be submitted upon receipt & subsequent evaluation of repair procedures from steel company MILLS,L M Tennesses Valley Authority 80/04/11 ip
- 8004280388 Fourth interim deficiency rept re refueling water storage tank overflow line not fabricated to ASME code Repair procedures not received from vendor Next rept will be submitted by 800616.
 MILLS.L M Tennesses Valley Authority B0/04/11 1p
- 8004240405 Interim deficiency rept re shock arrestor strut assembly interference Next rept will be submitted by 800530 MILLS.L M Tennessee Valley Authority 80/04/18 ip
- 8004250413 Forwards final daficiency rept re TPIPE computer user failure to check frequency analysis of piping sys MILL8,L M Tennessee Valley Authority 80/04/21 ip
- --8004250424 Final deficiency rept re TPIPE computer user failure to check frequency analysis No erroneous design info has resulted Program mod to stop any program run when frequency analysis not converging

 * Tennessee Valley Authority 80/04/21 6p
- 8004270346 Forwards first interim deficiency rept re defective reactor vessel upper internals guide tube support pins
 MILLS,L M Tennessee Valley Authority 80/04/23 ip

- --8004270353 First interim deficiency Lept re generic problem w/defective reactor vessel upper internals guide tube support pins. Caused by heat treatment Westinghouse will investigate to determine if design changes are required a Tennessee Valley Authority 80/04/23 ip
- 8004290296 Informs of error in dates re submittal of interim deficiency rept re control rod drop events yielding less convervative DNBRs than stated in FBAR Neit rept will be submitted by 800406 not 800906 as erroneously stated in 800401 ltr MILLS.L.M Tennessee Valley Authority 80/04/24 ip
- DOCKET 50-395 VIRGIL C SUMMER MUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- BO04040017 Submits add1 guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment " Requests roview of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Pioject Hanagement 80/02/21 3pp
- 8004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TM1-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of DL Wenci ROSS, D F Division of Project Management 80/03/10 53pp
- B004090054 Summary of 800222 meeting w/util t NVS Corp re draft of Tech Specs Altendee list encl TIBBITS.D Light Water Reactors Branch 1 80/03/21 5pp
- 8004090286 Summary of 800221 meeting \$ site visit w/util.Dames & Moore & LASL re geology & seismology review for site Attendee list & log of boring adjacent to USGS strong motion accelerator encl TIBDETTS.D L & Light Water Reactors Branch 2 80/03/21 800
- 8004300468 Forwards request for add1 info per review of recent FSAR amends
 BAER.R L Light Water Reactors Branch 2 80/04/04 5pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Ropts Act
 GRIMES B K Emergency Preparedness Task Force 90/03/11 4pp

Antitrust correspondence

- 004280004 Responds to T Conner 800314 ltr Nothing presented by applicant indicates that State or SC is actively supervising use by CARVA Lartel of economic market power over exchange sics.

 BRAND, W.E. Brand 1 Hall 80/03/21 Jpp
 - WHITE PARTY S HALL GOLOGIES 344
 - Inspection reports If Bulletins & correspondence
- 004020029 Ack receipt or 791217 ltr informing NRC of steps taken to correct violations noted in 1E lasp Rept 50-395/79-34 BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/16 Ip
- -8004020035 Responds to NRC 791120 ltr re violations noted in IE insp Rept 50-395/79-34 Corrective actions documented as-built condition of pipe support CSH-019 b procedural violations involved documented Add1 GA steps created JOHNSON, M.C. South Carolina Electric & Gas Co. 79/12/17 4pp
- -8004020036 Forwards IE Insp Rept 50-395/79-34 on 791030-1101 & notice of violation MURPHY.C E. Region 2 Atlanta. Reactor Construction & Engineering Support Branch 79/11/20 2pp
- *8004020039 Notice of violation from insp on 791030-1101 * Region 2, Atlanta, Office of the Director 79/11/19 lp
- 8004020043 IE Insp Rept 50-375/79-34 on 791030-1101 Noncompliance noted inadequate imap of pipe support CSH-019 HERDIA Region 2. Attanta. Reactor Construction & Engineering Support Branch ANG.40 P Region 2. Atlanta, Office of the Director 79/11/19 4pp
- 04090340 Forwards IC Bulletin BO-03. "Loss of Charcoal From Std Type II,Two-lnch.Tray Adsorber Cells " Action required D'REILLY.J P Region 2. Atlanta. Office of the Director 80/02/06
- 04090343 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II. Two-Inch. Tray Adsorber Cells " Action required B'AEILLY. J P Region 2. Atlanta, Office of the Director 80/02/06
- 04:10572 Forwards IE Insp Rept 50-395/80-02 on G00:08-11 No noncompliance noted BRYANT-J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- 8004110575 IE Inep Rept 50-395/80-02 on 800108-11 No noncompliance noted Major areas inspected work activities & quality records for electrical components & instrumentation CONLON.TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch GIBBUIST D. HARDWICK.R J Region 2. Atlanta, Office of the Director 60/02/26 7pp
- 2400201 Ack receipt of IE Insp Rapt 50-995/79-38 on 791119-29 No proprietary info JOHNSOW, C South Carolina Electric & Gas Co 80/02/29 jp
- 3004020211 Forwards IE Insp Rept 50-395/79-38 on 791119-29 No noncompliance noted O'REILLY.J P Region P, Atlanta, Office of the Director 80/02/07 2pp
- 100402020 IF lnsp Rept 50-395/79-3B on 771119-29 No noncompliance noted Major areas inspected allegations re-cold joint in reactor bidg ring girder & cracks in svc water tunnel G'REILLY,J P. MARSH,R. LENAHAN,J J. Region 2. Atlanta, Office of the Director 60/02/07 lipp
- 4040467 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std ype II, 2 Inch.Tray Adsorber Cells " Visual insp of safety nonsafety filter plenums revealed that spot welding used n cell const & screen sagging or degradation not noted REMS.E H South Carolina Electric & Oas Co 80/03/11 2pp
- 4100359 Responds to IF Bulletin 79-13 Hot functional testing cheduled for 800501 & feel loading scheduled for 801201 perating & emergency operating procedures for main steam into Areak & main feedwater line break are being finalized REMS.E M. South Carolina Electric & Qas Co 80/03/12 2pp
- #280005 Forwards IE Insp Rept 50-395/80-01 on 800101-31 & notice of iolation
 WIS.R C Region 2. Atlanta Reactor Operations Nuclear Support

- --8004250009 Natice of violation from insp on 800101-31
 * Region 2, Ablanta, Office of the Director 80/03/10 ip
- --8004260014 IE Insp Rept 50-395/60-01 on 800101-31 Noncompliance noted #ailure to perform audit of lifted lead * jumper log KELLOGO.P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch SMCLOS.J L Region 2 Atlanta, Office of the Director 80/03/10 6pp
- 8004090J91 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required D'REILLY. J P Region 2, Atlenta, Office of the Director 80/03/14
- 8004100395 Ack receipt of 800205 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-395/79-41 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/17 ip
- --8004160402 Responds to NRC 800118 itr re violation noted in IE inap Rept 50-395/79-41 Corrective actions attached safety tags to correct valves & wrote Startup Field Rept 1972 NICHOLS: T C South Carolina Electric & Gas Co 80/02/05 Spp
- --8004100409 Forwards IE Insp Rept 50-395/79-41 on 791110-1231 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/18 2pp
- --8004100412 Notice of violation from insp on 791110-1231
 * Region 2, Atlanta, Office of the Director 80/01/11 ip
- --8004100416 IE Insp Rept S0-395/79-41 on 791110-1231 Noncompliance noted improperly positioned safety tags & failure to document deficiency in main steam hydrostatic test KELLOGO,P J. SKOLDS.J L. Region 2, Atlanta, Office of the Director 80/01/11 8pp
- B004160110 Ack receipt or IS Insp Rept 50-395/80-02 on 800227 No proprietary info JOHNSON,M C South Carolina Electric & Qas Co 80/03/28 ip
- 8004150492 Forwards 1E Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/31
- 8004150495 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/31 200
- 8004080593 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required G'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/01.
- 8004080587 Forwards IE Circular 80-05, "Emergancy Diesel Generator Lubricating Dil Addition & Onsite Supply " No written responso required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/01
- 8004150087 Forwards IE Info Notice B0-13, "GE Type 88M Control Switches Defective CAM Followers" No specific action or response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/02 ip
- 8004190091 Forwards IE Info Notice 80-13, "QE Type 8BM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/04/02,
- 8004240269 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004240271 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02

- 269 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil No written response required LLY,J P Region 2. Atlanta. Office of the Director 80/04/03
- 271 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Bil No written response required Ly.J P. Region 2. Atlanta. Office of the Director 80/04/03
- 09 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in N-312.Tupe 304 Stainless Steel Pipe " Action required LY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 58 Forwards IE Bulletin 79-03A "Longitudinal Høld Defects in A-312, Type 304 Stainless Steel Pipe" Action required LY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 32 Forwards IE Bulletin 80-08, "Exam of Containment Liner atton Welds " Written response required LY, J P Region 2, Atlanta, Office of the Director 80/04/07
- 35 Forwards IE Bulletin 80-08, "Exam of Containment Liner ation Welds" Written response required LY, J P Region 2, Atlanta, Office of the Director 80/04/07,
- 12 Ack receipt of 800312 ltr informing NRC of steps taken to tylolations noted in IE Invostigation Repts 50-395/k $50^{-395/80-03}$ C. E. Region 2, Atlanta, Reacto: Construction & Engineering b Branch 80/04/07 ip
-)119 Responds to violations noted in IE Investigation Repts /8/79-35, & 50-395/80-03 Corrective actions Drawing 202 revised on 791102 to incorporate ABME code rements for weld fillet size of socket welding flanges :0N, M C South Carolina Electric & Gas Co 80/03/12 3pp
- 124 Forwards IE Investigation Rept 50~395/79~35 on 790910~1219 & e of violation LLY.JP Region 2. Atlanta. Office of the Director Vi3 2pp
- 128 Notice of violation from insp on 790910-1219 gion 2, Atlanta, Office of the Director 80/02/12 ip
- i35 IE Investigation Rept 50-395/79-35 on 790910-1219 mpliance noted procedures did not include fillet weld requirements per ASME Section III for socket welding ess & sample weld failed to meet ASME code RE.D.R. HARSH.R.J. LONG.F.J. Region 2. Atlanta. Office of irector 80/02/12 24pp.
- 8 Ack receipt of IE Insp Rept 50-395/80-05 No proprietary
- .M C South Carolina Electric & Gas Co 80/04/08, 1p
- 484 Forwards IE Insp Rept 50-395/80-05 on 800225-28 toompliance noted fr./ C. Region 2. Atlanta, Reactor Construction & Engineering t Branch 80/03/12 2pp
- i93 IE Insp Rept 50-395/80-05 on 800225-28 No noncompliance Major areas inspected deficiency items, IE bulletins. [E ars & const activities
 TE.T E. Region 2. Atlanta, Office of the Director.
 I.J K. Region 2. Atlanta, Reactor Construction & Engineering t Branch 80/03/12 App
- Forwards preliminary preservice insp program for weld insps tatic tests H South Carolina Electric & Qas Co BO/04/15 ip
- 59 Preliminary preservice insp program for weld insps & tatic tests, including basic insp program, insp ures, lists of items inspected & preliminary list of requests th Carolina Electric & Qas Co 80/Q4/15 400pp

- S Reportable occurrences, LERs & related correspondence
- 8004020292 Part 21 rept on 800114.Colt Industries reported failure of thrust bearing in diesel generator due to omission of plugs from oil supply sys Thrust bearing & thrust collar are being replaced & plugs installed CREMS.E H South Carolina Electric & Gas Co 80/03/05 2pp
- 8004020455 Part 2) rept insp completed on crackshaft thrust bearing on generator A Plugs proposly installed & unit free of potential defect HORIARTY, J M Colt Industries, Inc. 80/03/06 tp
- 8004140174 Part 21 rept re emergency reedwater pump, turbine governor valve linkage Governor linkage modified to accommodate spring which proloads valve linhage so governor valve remains open during standby CREWS,E R South Carolina Electric & Gas Co 80/03/07 3pp
- B004020321 Forwards deficiency leptire problems identified in Bergen-Patterson Part 2540 strut issembly used w/Pacific Scientific mechanical shock arrestors CREWS, E. H. South Carolina Electric & Qas. Co. 80/03/10 2pg
- --8004020322 Deficiency rept re problems identified in Bergon-Patterson Part 2540 strut assembly used w/Pacific Scientific mechanical shock arrestors Cause unstated Larger assemblies being replaced Smaller assemblies modified & South Carolina Electric / Oas Co B0/03/10 3pp
- 8004220049 Part 21 rept on 800304, received notification of potential problems w/Dorgen-Patterson mechanical shock arrestor assemblies Defective assemblies located on RCB, safoty-related component cooling sys 5 reactor bldg spray sys CREWS,E H South Carolina Electric & Gas Co 80/03/10 5pp
- 8004170085 Deficiency Rept 50-395/80-05-07 re piping supplier drawings of reinforcing fillet weld for branch connections & contractor revisions not providing min throat thickness for specified weld sites Caused by program deviation JOHNGON,M C South Carolina Electric & Gas Co 80/03/21 3pp
- 8004170004 Interim deficiency lept re potential stress corrosion cracking of control rod guide tubo support pins Cause unstated Westinghouse will perform ultrasonic insp of support pins in two or more operating domestic plants CREWS.E H South Carolina Electric & Gas Co 80/03/27 App
- 8004300561 Part 21 rept re control rod guide tube support pin cracking due to possible stress corrosion cracking Bioken support pin could prevent proper control rod operation
 CREMS,C H South Carolina Electric & Gas Co 60/03/27 5pp
- 8004150501 Final deficiency rept re failure of thrust bearing on diesel generator meg by Colt Industries Farwards Calt Industries BOCOOF ltr regarding successful completion of shop tests CREWS.E M South Carolina Electric 5 Gas Co. 80/04/09 2pp
- 8004150548 Final deficiency rept re measurement of steam generator water level Steam generator impulse lines are being thermally insulated to minimize heatup Mod witl ensure proper accuracies w/o requiring large setpoint increase CREWS.E H Bouth Carolina Diectric & Gas Co 80/04/08 2pp
- 8004280498 Final deficiency rept re measurement of steam generator water level Steam generator level impulse lines being thermally insulated to minimize heatup during time required to perform trip function, after high energy line break CREMBLE H South Carolina Electric & Qas Co 80/04/08 2pg
- 8004230404 Final deficiency rept re #3000 fittings installed where piping specs required #6000 fittings Caused by failure to perform & comply w/procedures to verify matl prior to installation.

 JOHNSON M C South Carolina Electric & Gas Co 80/04/18 3pp
- 8004250427 Final deficiency rept re welding of safety-related instrument hanger/supports Caused by failure to perform b comply w/procedures controlled reinsp program instituted JOHNSON.M C South Carolina Electric & Gas Co 80/04/18 3pp
- DOCKET 50-397 WPPSS NUCLEAR PROJECT: UNIT 2
- A Application/construction stage documents & correspondence
- BD04040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp

- 1,1 '- Land ': 1 | ':211 lites to GE discussing analysas of ill form which may remain not drive veture land agree to the veture land around not be performed where issue or the guidance mail for the guidance mail for the guidance mail for the form of the form
- Under the first set that the first at the plan for sacrificial shield ustil first set firsts, for the first set first and the first set first set for the first set first set first set first fi
- D4: 4: TO Project engineering directive of replacement of slot welds

 partial personal in 10
 furnal fine Cull (10:00 d5)
 fig.
 - UR (70)71 Frujh * ergarewhing directle he replacement of slot welds urgarital penetration units.

 * Curms * Roe Short (10)12 app
- will if firely f engineering directive to proponation of partial generation read joint to be used on sacrificial wall of firms? Rise of the (3/4) app
- 50340 (1) 14 Fraject engineering directive re preparation for welding by dual smooth Flow process
 Burns / Roe Co. 3 1/03/14 1p
- 1334170607 Forwards responses to Round One questions, Set 7 from Pechanical Engineering Stanck
 RENEERGER D.L. Washington Public Power Supply System 80/03/26
 2530p
- COMMISSAS Summary of Bringod meeting usually in Bethesda, MD re potential conflict of interest arrecting QA program ARC adulted that conflict of interest involvement would adversel, arfect cubic Savery Local M D Light Hater Reactors Branch H BOSOMSOZ 15pp
- FCn42d0b17 Advises that "F122" request for approval of alternative test method to terify has motisture to low hydrogen electrode coating is accepted Regiests that notarised version of hequest go sent in addition to specific sites for use AUCRATER's L.S. Light hater Reactors Branch 4 80/04/04 Spp
- 2014;90118 Att receipt or (10305 ltr re corrective action plan resolving quality problems identified w/joining sacrificial stretd all rings ELOTE-ENR AL Region 5 San Francisco, Office of the Director 30/04 04 10
 - 241602d5 Ad-ises of fundamental nitstatement in 800402 minutes of 332104 greating outtiline GA program unionization Requests carrection to reflect that fact had no incluence on Local SPB election
 RETROLOGIST Debevoise Liberman 80/04/10 ip
- CSC4210285 Responds to 600221 ltr re schedule for completing review of qualification of tafety-related electrical equipment schedule for completion of review unlibe provided after final issuance of NURGC-0558 REMBERGER.D L Washington Public Power Supply System 80/04/11 10
- GOO47000& Summary of BOD324-R7 meetings w/Mark II owners group in San Jose CA re discussion of ARC concerns on data from Greape tests & foreign full scale rest programs & relationships w/ Mark II designs ELTANGLA F Containment Systems Branch 80/04/14 22pp
- F Security, medical, emergency t fire protection plans
- EICO4080027 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr has been postponed pending GAD clearance under Federal Repts Act CRIMES. B K Emergency Preparedness Task Force 80/03/11 4pp

- Adjudicatory correspondence
- Sup4030076 Memorandum of understanding between NRC & FEMA re prompt improvement in ladiological emergency planning & preparedness, distilluted as Board notification COSSICKL V Office of the Frecutive Director for Operations 80/04/02 34pp
- k Utility Final Safety Analysis Report (FSAR) & amonds
- --8004020341 Amend 6 to FCAR

 # Washington Public Fower Supply System 80/02/29 820pp
- 9304140345 Forwards Certificate of Syc for Amend 8 to FSAR REMBERGER.D L. Washington Public Power Supply System 80/04/04 20p
- G Inspection reports, IF Bulletins & correspondence
- 8004300293 Forwards IE Insp Ropt 50-397/80-01 on BOO115-1B SPENCER.G E Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --B004300298 IE Insp Rept 50-397/80-01 on 800115-18 Noncompliance noted inadequate closure of sensing lines b failure to control velding filler mat!

 DDDDS:R f , ELIN.J O , HAIST, D P Region 5, San Francisco, Office of the Director 80/02/26 8pp
- 8004280272 Forwards IE Insp Rept 50-39//60-05 on 800310-12 No noncompliance noted CREMS, J L Region 5, San Frencisco, Reactor Operations Nuclear Support Branch 80/03/24 Zpp
- --8004280277 IE Insp Rept 50-397/80-05 on 800310-12 No noncompliance noted Major areas inspected preoperational test procedures & overall preoperational program Inspectors toured plant for independent update of const status
 STERNBERG, D M Region 5, San Francisco, Reactor Derations Nuclear Support Branch CARLEON, J D , JOHNSON, P N Region 5, Ban Francisco, Office of the Director 80/03/21 3pp
- 8004150220 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary Elistivetic H. H. Region S. San Francisco, Office of the Director 80/03/31 Ip
- 8004100109 Forwards IE Circular 80-05, "Emergency Diosel Compretor Lobricating Gil Addition & Onsite Supply " No written response required ENGELKEN, H Region 5, San Francisco, Office of the Director 80/04/01)p
- 80041(0119 Forwards IE Info Notice 80-13, "QE Type 88M Control Switches Defective CAM Fo)lowers " No specific action or response required ENGELKEN.R H. Region 5, San Francisco. Office of the Director 80/04/02 ip
- 8004220052 Forwards IR Info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN.R H. Region 5, San Francisco: Diffice of the Director 80/04/02 ip
- 8004180137 Forwards IC Circular 80-07, "Problems H/HPC! Turbine Dil Sys " No written response required EMSELKEN.R H Region 5. San Francisco. Office of the Director. 80/04/03 ip
- B004110007 Forwards IE Bulletin 90-07, "BMR Jet Pump Assembly Failure "
 No written response required
 ENGELKEN, R H Region S. San Francisco, Office of the Director,
- 8004230370 Forwards IE Builetin 79-03A, "Longitudinal Held Defects in ABME SA-312.Type 304 Stainless Steel Pipe " Action required BO/04/04 Ip Region 5, San Francisco, Office of the Director
- 8004720201 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ENGELNETIR H Region 5, Ban Francisco, Office of the Director 80/04/07 1p

- S Reportable occurrences, LERs & related correspondence
- 8004020293 Forwards interim deficiency rept re-potential missile~producing nonsafety-related equipment installed in Class IE area RENBERGER.D.L. Washington Public Power Supply System 80/03/21 lp
- ---B004020294 Interim deficiency rept re potential missile-producing nonsafety-related equipment installed in Class IE area Frotective barriers are being designed to proclude damage to Class IE equipment in event of flywheel failure # Washington Public Power Supply System B0/03/21 1p
- 8004020302 Forwards final deficiency rept re pipe whip restraint problems
 RENBERGER, D.C. Washington Public Power Supply System 60/03/21
 200
- --8004020305 Final deficiency rept re pipe whip restraint GA records & fabrication deficiencies Documentation deficiencies have been identified All restraints will be reinspected by ultrasonic magnetic particle & visual methods * Washington Public Power Supply System 80/03/21 2pp
- 8004100488 Ack receipt of 800314 ltr fowarding deficiency rept re condensate collection in reactor core isolation piping ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/03/25 ip
- 8004280466 Forwards deficiency rept re small bore piping design RENBERGER, D. L. Washington Public Power Supply System 80/04/21 in
- --8004280449 Deficiency rept re small bore piping design Piping & support drawings have been released for fabrication of incomplete & unchecked design calculations Independent engineering firm will complete remaining designs
 * Washington Public Power Supply System 80/04/21 1p
- 80042B0475 Forwards interim deficiency rept re violation of min wall thickness on small bore piping RENBERGER, D. L. Washington Public Power Supply System 80/04/21
- ---B0042B0476 Interim deficiency rept re carbon steel small diameter pipe installed w/loss than min allowable wall thickness Caused by contractor utilizing grinders to remove oxide & mill scale from pipe in preparetion for welding # Washington Public Power Supply System B0/04/21 1p
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- BOO404003i Advises of issuance of NUREG-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSB, D F Division of Project Management 80/02/05 7pp
- BOO4170047 Discusses deficiency re defective seismic Class I hanger welds Deficiency no longer considered reportable under IOCFRSO 55(e) Corrective action completed & found to be acceptable CHIANOI.N J Carolina Power & Light Co 80/02/22 1p
- 8004080451 Forwards const milestones & activities schedule, updated to 800331 MCDUFFIE, M A Caroline Power & Light Co 80/04/02 13pp.
- B004220451 Bubmits info in response to NRC 800324 questions re electrical field gradients surrounding proposed Harris-Harnett 500-kV line MCDUFFIE,M A Carolina Power & Light Co 80/04/15 2pp
- B004230328 Submits info re electrical field gradients surrounding proposed 500 kV line, requested in NRC B00324 ltr MCDUFFIE,M A Carolina Power & Light Co B0/04/15 2pp
- F Becurity, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 itr, has been postponed pending OAO clearance under Federal Repts Act ORIMES, B.K. Emergency Preparedness Task Force 80/03/11 4pp

- G Adjudicatory correspondence
- 8004010519 Petition for review of ASLAB 800220 decision denying applicant motion for mod of ALAB-577 re mgt capability Supports NRC argument that ACLAB exceeded authority re staff procedures to treat OL Certificate of Svc encl TROWBRIDGE, G F . O'NEILL J H Carolina Power & Light Co TROWBRIDGE, G F . Shaw, Pittman, Potts J Trowbridge 80/03/11 13pp
- 8004030026 Memorandum of understanding between NRC & FEMA re groupt improvement in radiological emergency planning & preparedness distributed as Board notification GOSBICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004210180 Order granting extension until 800418, for Commission to take action re review of ALAB-577 & ALAB-591
 CHILK, S. J. Office of the Secretary of the Commission 80/04/11
- BO0428017B Memorandum 5 order reversing portions of ALAB-577 & ALAB-581 re performance of administrative tasks in separate proceeding Declines to review applicant issues re ALAB-5B1 Directs NRC to conduct proliminary assessment re ALAB-577 CHILK/S J Uffice of the Secretary of the Commission B0/04/17 3pp
- G Inspection reports, IF Bulletins & correspondence
- 8004070058 Ack receipt of IE lnsp Repts 50-400/80-02, 50-401/80-02. 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No proprietary info HOWE: P W Carolina Power & Light Co 80/02/28 \$p
- --8004090071 Forwards IE Insp Repts 50-400/80-02,50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No noncompliance noted BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004070084 IE Insp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 \$
 50-403/80-02 on 791228 & 800121-25 No noncompliance noted
 Major areas inspected const status, licensee action on
 previous findings & IE Bulletin 79-25

 DRADELY: R D Region 2, Atlanta, Office of the Director HUNT, M D
 Region 2, Atlanta, Reactor Construction & Engineering Support
 Branch 80/02/20 5pp
- 8004070275 Ack receipt of IE Insp Repts 50-400/80-04, 50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No propietary info HOME.P W Carolina Power & Light Co 80/03/06 to
- --8004070315 Forwards IE Insp Repts 50-400/80-04,50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/02/27 ^

- BOO40B059B Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply ' No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/01
- BOO4150067 Forwards IE Into Notice 80-13, "GE Type SBM Control Suitches Defective CAM Followers " No specific action or response
- required O REILLY, J P Region 2. Atlanta, Orfice of the Director B0/04/02
- 8004240245 Forwards 1£ Info Notice 80-14, "Safety Suggestions From " No action required
 P Region 2, Atlanta Orfice of the Director 80/04/02
- 8004180378 Forwards 1E Circular 80-07. Problems W/HPCI Turbine Oil Sys "No unitten response required
 O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director BD/04/03
- 8004230117 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2. Atlanta, Orrice of the Director 80/04/04 80/04/04
- 8004180340 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Penetration Welds " Written response required G'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/04/07
- S Reportable occurrences, LERs & related correspondence
- 8DO4170053 Interim dericiency lept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment 5 support of safety-related loads Estimates corrective action will be completed by 800601 CHIANGLIN J Carolina Power & Light Co 80/02/29 ip
- 8004280560 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall Caused by unique ref notation of "addl steel" (25 bars) on main reinforcing drawing Significance not fully recongnized on drawing JONES, J A Carolina Power & Light Co 80/04/16 5pp
- 8004280561 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall, adjacent to const opening for equipment hatch Review will be expanded to include drawing review of reinforcing steel in Class I structures JUNES, J A Carolina Power & Light Co 80/04/18 2pp
- DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2 A Application/construction stage documents & correspondence
- EDD4040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical
 Equipment," providing guidance re methods for compliance
 ROSS, D.F. Division of Project Management 80/02/05 7
- 304170047 Discusses deficiency re defective seismic Class I hanger welds Deficiency no longer considered reportable under 100FR50 55(e) Corrective action completed & found to be acceptable CHIANGI, N J Carolina Power & Light Co 80/02/22 1p.
- 3004080451 Forwards const milestones & activities schedule, updated to MCDUFFIE.M A Carolina Power \$ Light Co 80/04/02 13pp
- 8004220451 Submits info in response to NRC 800324 questions re electrical field gradients surrounding proposed Harris-Harnett 500-kV line MCDUFFIE.M A Carolina Power & Light Co 80/04/15 2pp
- 8004230028 Submits info re electrical field gradients surrounding proposed 500 tV line, requested in NRC 800324 ltr MCDUFFIE,M A Carolina Power & Light Ca 80/04/15 2pp
- F Security, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 Itr.has been postponed pending GAU clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp

- G Adjudicatory correspondence
- 8004010519 Petition for review or ASLAB 800220 decision denying applicant motion for mod of ALAB-577 re mpt capability Supports NRC argument that ASLAB exceeded authority is staff procedures to treat OL Certificate of Svc encl TROMBRIDGE. G F . D'MEILL. J H Carolina Power 1 Light Co TROMBRIDGE. G F . Shaw, Pithman, Potts & Trowbridge 80/03/11
- 8001030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning A prepaiedness, distributed as Board notification GUSSICK.L V Office or the Executive Director for Operations 80/04/02 34pp
- 8004210180 Order granting extension until 800418, for Commission to take action re review of ALAB-577 5 ALAB-581
 CHILK,S J Office of the Secretary of the Commission 80/04/11
- 80042B017B Memorandum % order reversing portions of ALAB-577 & ALAB-50(re performance of administrative tasks in separate proceeding Declines to review applicant issues re ALAB-50(Directs NRC to conduct preliminary assessment re ALAB-577 CHILK.5 J Office of the Socretary of the Commission B0/04/17
- G Inspection reports, IE Bulletins & correspondence
- 8004070058 Ack receipt of IE lnsp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No proprietary info HOWE, P W Carolina Power & Light Co 80/02/28
- -8004090071 Forwards IE Insp Repts 50-400/80-02,50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Eusport Branch 80/02/20 200
- --8004090004 IE Insp Repts 50-400/80-02.50-401/80-02.50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No noncompliance noted Major areas inspected const status. Licensee action on previous fandings & If Bulletin 79-25 BRADELY.R D Region 2. Atlanta. Office of the Director HUNT, PRegion 2. Atlanta Reactor Construction & Engineering Support Branch 80/02/20 Spp HUNT, M D
- B004070295 Ack receipt of IE Insp Repts 90-400/80-04, 50-401/80-04, 50-402/80-04 % 50-403/80-04 on 800205-07 No propietary info HOME.P W Carolina Power & Light Co 80/03/06 ip
- --8004070315 Forwards IE Insp Repts 50-400/80-04, 50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No noncompliance nated Region 2, Atlanta, Reactor Construction & Engineering nch 80/02/27 2pp BRYANT, J. C. Support Branch
- --8004070331 IE Insp Repts 50-400/80-04.50-401/80-04.50-402/80-04 & 50-403/80-04 on 800205-07 No noncompliance noted Major areas inspected const progress & licensee action on previously identified items
 HUNTIM D Region 2. Atlanta. Office of the Director BRADLEY, R D NRC Regional Offices 80/02/22 Spp
- B004070035 Ack receipt of 1E Insp Repts 30-400/80-05, 50-401/80-05, 50-402/80-05 & 50-403/80-05 on B00214-15 No proprietary HOWE, PW Carolina Power & Light Co 80/03/07
- --8004070039 Ferwards 1E Insp Repts 50-400/80-05, 50-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No noncompliance noted DRYANTJ C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 60/02/28 2pp
- --8004070043 IE Insp Repts 90-400/80-05.50-401/80-05.50-402/80-05 & 50-403/80-05 on 800214-15 No noncompliance noted Major areas inspected structural concrete & lakes dams & canals HARRIS.J R Region 2. Atlanta, Office of the Director CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Eupport Branch 80/02/28 4pp
- B004150497 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director B0/03/31 260

- 8004080598 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04.
 - Region 2, Atlanta, Office of the Director 80/04/01
- B004150067 Forwards IE Info Notice 80-13, "GE Type SBM Control Emitches Defective CAM Followers " No specific action or response
- 'REILLY, J P Region 2, Atlanta, Office of the Director 60/04/02
- 8004240245 Forwards IE Info Notice BO-14, "Safety Suggestions From Employees " No action required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- B004180378 Forwards IE Circular 80~07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director B0/Q4/O3
- 8004230117 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004180340 Forwards IE Bulistin 80-08. "Exam of Containment Liner Penetration Welds " Writton response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/07
- S Reportable occurrences, LERs & related correspondence
- B004170053 Interim deficiency rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embeddent & support of safety-related luads Estimates corrective action will be completed by 800601 CHIANGI,N J Carolina Power & Light Co 80/02/29 1p
- 8004280540 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall Caused by unique ref notation of "addi steel" (25 bars) on main reinforcing drawing Significance not fully recongnized on drawing JCNES.J A Caroline Power & Light Co 80/04/16 Spp
- 8004280561 Interim deficiency rept re omission of rebar in Unit i containment bldg exterior wall, adjacent to const opening for equipment hatch Review will be expanded to include drawing review of reinforcing steel in Class I structures JONES, J A Carolina Power & Light Co 80/04/18 2pp
- DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS,D F Division of Project Management
- 8004170047 Discusses deficiency re defective seismic Claus I hanger welds Deficiency no longer considered reportable under iOCFR30 55(e) Corrective action completed & found to be acceptable CHIANGI,N J Carolina Power & Light Co 80/02/22 1p
- 8004080451 Forwards const milestones & activities schedule, updated to MCDUFFIE, M A Carolina Power & Light Co 80/04/02 13pp
- 8004220451 Bubmits info in response to NRC 800324 questions re electrical field gradients surrounding proposed Harris— Harnett 500-kV line. Carolina Power & Light Co. 80/04/15 2pp MCDUFFIE, M A
- 8004230328 Submits info re electrical field gradients surrounding proposed 500 tV line, requested in NRC 800324 ltr MCDUFFIE, M A Carolina Power & Light Co 80/04/15 2pp
- F Security, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act
 ORIME8.B K Emergency Preparedness Task Force 80/03/11 4pp

G Adjudicatory correspondence

- 8004010519 Petition for review of ASLAB 800220 decision denying applicant motion for mod of ALAB-577 re mgt capability Supports RRC argument that ASLAB exceeded authority re staff procedures to treat OL Certificate of Syc encl TROWBRIDGE, G F. O'NEILL, J H. Carolina Power & Light Co TROWBRIDGE, G F. Shaw, Pittman, Potte & Trowbridge 80/1 80/03/11 13pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radialogical emergency planning by preparedness, distributed as Board notification ODSTCK.L V Defice of the Executive Director for Operations 80/04/02 34pp
- 8004210180 Order granting extension, until 800418, for Commission to take action re-review of ALAH-577 & ALAH-581
 CHILK, S. J. Office of the Secretary of the Commission 80/04/11
- 8004280178 Memorandum & order reversing portions of ALAB-577 & ALAB-581 reperformance of administrative tasks in separate proceeding Beclines to leview applicant issues to ALAB-581 Directs NRC to conduct preliminary assessment re ALAB-577 CHILK, BJ Office of the Secretary of the Commission 80/04/17
- @ Inspection reports, 15 Bulletins & correspondence
- 8004090058 Ack receipt of 1E Insp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 & 50-403/80-02 on /91228 & 800121-25 No proprietary info HOWE.P W Carolina Power & Light Co 80/02/28
- --8004090071 Ferwards IE Insp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 600121-25 No moncompliance noted BRYANT.J C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004090084 IE insp Repts 50-400/80-02.50-401/80-02.50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No noncompliance noted Major areas inspected const status. Hicensee action on previous findings & IE Bullotin 79-25
 BRADELY.R D. Region 2. Atlanta, Office of the Director HUNT, Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 80/05/50 Spp
- 8004070295 Ack receipt of LE Insp Repts 50-400/80-04,50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No prepietary info HOHE,P W Carolina Power & Light Co 80/03/06 1p
- --8004070315 Forwards IE Insp Repts 50-400/80-04,50-401/80-04, 50-402/80-04 & 50-403/80-04 on B00205-07 No noncompliance BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --B004070331 IE Insp Repts 50-400/80-04.50-401/80-04.50-402/80-04 & 50-403/80-04 on B00205-07 No noncompliance noted Major areas inspected const progress & licensee action on previously identified items HUNT,M D Region & Atlanta. Office of the Director BRADLEY.R D NRC Regional Offices B0/02/22 5pp
- 8004070035 Ack receipt of 1E Insp Repts 50-400/80-05, 90-401/80-05, 90-402/80-05 & 50-403/80-05 on 800214-15 No proprietary HOWE, P W Carolina Power & Light Co 80/03/07
- ---8004070039 Forwards IE Insp Repts 50-400/80-05, 50-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No noncompliance BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8004070043 IE insp Repts 50-400/80-05.50-401/80-05.50-402/80-05 & 50-403/80-05 on 800214-15 No noncompliance noted Hayor areas inspected structural concrete & lakes, dams & canals HARRIS, J.R. Region 2. Atlanta, Office of the Director CONLON.T E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 App
- BO04150497 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/3: Region 2. Atlanta. Office of the Director 80/03/31

- 8004080558 Foruards 1F Circilar 80-05. Emergency Dissel Generator Lubricating Uil Addition? Unsile Supply "No written response require?

 G'REILLI, J.P. Region D. Atlanta Orfice of the Director 80/04/
 - Region 2 Atlanta Office of the Director B0/04/01
- 8004150067 Forwards (F. Irro Notice SU-13, 'GE Type SBM Control Suitches Defective CAM Followers No specific action or response
- required O'REILLY JP Region 2, Atlanta, Office of the Director
- 8004240245 Forwards IE Info Notice 80-14, 'Sarety Suggestions From Employees 'No action required
 O'REILLY J.P. Region 2 Atlanta, Orfice of the Director 80/04/02
- 8004180378 Forwards IE Cir ular 80-07, "Problems W/HPC: Turbine Dil Sys "No written response required
 D'REILLY, J.P. Region 2, Atlanta, Orrice of the Director 80/04/03
- 8004230117 Forwards 1E Bullefin 79-03A "Longitudinal Held Defects in ASME SA-312.Type 304 Stainless Steel Pipe" Action required O'RE[LL7.J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004180340 Forwards IE Bulletin 80-08. 'Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2. Atlanta Orfice of the Director 80/04/07
- S Reportable occurrences. LERs ' related correspondence
- 8004170053 Interim deficiency rept re deficiencies in procurement. fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Estimates corrective action will be completed by 800401 CHIAMOI N J Carolina Power & Light Co 80/02/29 ip
- 8004280560 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall Caused by unique ref notation of 'addl steel" (25 bars) on main reinforcing drawing Significance not fully recongnized on drawing JONES. J A Carolina Power & Light Co 80/04/16 5pp
- 8004280561 Interim deficiency rept re omission of rebar in Unit i containment bldg exterior wall, adjacent to const opening for equipment batch Review will be expanded to include drawing review of reinforcing steel in Class I structures JONES, J. A. Carolina Power & Light Co. 80/04/18 2pp
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4 A Application/construction stage documents & correspondence
- BO04040031 Advises of issuance of NUREO-0588 "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment." providing guidance remethods for compliance AGSS.D F Division of Project Management B0/02/05 7pp
- 004170047 Discusses deficiency re-defective seismic Class I hanger welds Deficiency no longer considered reportable under 10CFR50 55(e) Corrective action completed % found to be acceptable CHIANGIR J Carolina Power & Light Co BO/02/22 1p
- 800408045: Forwards const milestones? activities schedule.updated to MCDUFFIE: M A Carolina Power & Light Co 80/04/02 13pp
- 8004220451 Submits info in response to NRC 800324 questions re electrical field gradients surrounding proposed Harris-Harnest 500-kV line Monumers in a Power 5 Light Co 80/04/15 200 ina Power 5 Light Co 80/04/15 2pp

re electrical field gradients surrounding equested in NRC 800324 ltr Tweer & Light Co 80/04/15 2pp

fire protection plans

- e for evacuation time estimates. n postponed pending GAD
- Task Force 80/03/11 4pp

- G Adjudicatory correspondence
- 8004010519 Petition for review of ASLAB 800220 decision denying applicant motion for mod of ALAB-577 re mgt capability Supports NRC argument that ASLAB exceeded authority re staff procedures to treat OL Certificate of Svc encl TROHDRIDGE, G F Carolina Power % Light Co D'NEILL, J H Shaw, Pittman, Potts & Trowbridge 80/03/11 13pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Noard notification COBSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004210180 Order granting extension until 800418, for Commission to take action relevieu of ALAB-577 & ALAB-581

 CHILK, S. J. Office of the Socretary of the Commission 80/04/11
- 8004280178 Memorandum ? order reversing portions of ALAB-577 & ALAB-581 re performance of administrative tasks in sevarate proceeding Declines to review applicant issues of ALAB-591 Directs NRC to conduct preliminary assessment re ALAB-577 CHILK, S. J. Office of the Secretary of the Commission 80/04/17
- @ Inspection reports, IF Bulletins & correspondence
- 8004070058 Ack receipt of IE Insp Repts 50-400/80-02,50-401/80-02, 50-402/80-02 % 50-403/80-02 on 791228 & 800121-25 Na proprietary info HOWE.P W Carolina Power & Light Co 80/02/28
- --8004090071 Forwards IE Insp Repts 50-400/80-02,50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004090084 IE insp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No noncompliance moted Major areas inspected const status, licensee action on previous findings & IE Buljetin 79-25 BRADELY, R D Region 2, Atlanta, Office of the Director 80/02/20
- B004070295 AcV receipt of IE Insp Repts 50-400/80-04.50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No propietary info HOWE.P W Carolina Power & Light Co 80/03/06 1p
- --8004070315 Forwards IE Insp Repts 50-400/80-04, 50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/02/27 2pp
- 8004070035 Ack receipt of IE lnsp Repts 50-400/80-05,50-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No proprietary HONE, P W Carolina Power & Light Co 80/03/07
- --8004070039 Forwards IE insp Repts 50-400/80-05,50-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No noncompliance moted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering ch 80/02/28 2pp Support Branch
- ---8004070043 IE Insp Repts 50-400/80-05.50-401/80-05.50-402/80-05 & 50-403/80-05 on B00214-15 No noncompilance noted Major areas inspected structural concrete & lakes, dams & canals HARRIS.J R Region 2. Atlanta. Office of the Director 80/02/28.
- 8004i50497 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080398 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written Corresponse required

 O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/04/01

- 8004150067 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240245 Forwards IE Info Notice 80-14. "Sørety Suggestions From Employees " No action required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/02
- 8004180378 Forwards IE Circular 80-07, "Problems N/HPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/04/03
- 8004230117 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/04/04
- 8004180340 Forwards IF Bulletin 80-08, "Exam of Containment Liner Penetration Wolds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8 Reportable occurrences, LERs & related correspondence
- BO04170053 Interim deficiency rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Estimates corrective action will be completed by BO0601 CHIANGI,N J Garalina Power & Light Co BO/02/29 ip
- 8004280560 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall Caused by unique ref notation of "addl steel" (25 bars) on main reinforcing drawing Significance not fully recognized on drawing JONES, J A Carolina Power & Light Co 80/04/16 5pp
- 8004280541 Interim deficiency rept re emission of robar in Unit 1 containment bldg exterior wall, adjacent to const opening for equipment hatch Review will be expanded to include drawing review of reinforcing steel in Class I structures JONES, J A Carolina Power & Light Co 80/04/18 2pp
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- BOO4040031 Advises of issuance of NUREG-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management
- 8004220234 Forwards response to NRC 800306 request for addl info re review of design groundwater levels BROWN.8 C Virginia Electric & Power Co 80/04/18 5pp
- F Becurity, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending OAD clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11 4pp
- I Financial information
- 8004010269 Forwards Annual Rept 1979 BAUM,E A Virginia Electric & Power Co 80/03/27 1p
- ~~8004010275 Annual Rept 1979 * Virginia Electric & Power Co 79/12/31 32pp
- Q Inspection reports, IE Bulletins & correspondence
- 800409035B Forwards IE Builetin 80-03, "Loss of Charcoal From Std Type II, Two-Inch. Tray Adsorber Calls," Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06
- 8004090130 Forwards IE Insp Repts 50-339/H0-01,50-404/80-01 & 50-405/80-01 on 800129-0201 No noncompliance noted STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/22 2pp

- --8004090134 IE Insp Repts 90-15--80-01,50-404/80-01 & 50-405/80-01 an DOGGYOLTH IE http://eprivolence.com/com/DOGGYOLTH Doggyolth States and States
- 8004010465 Notifies of suspension of review or IF Bulletin 80-05 revacuum condition resulting in damage to chemical vol control sys holdup tanks Suspension due to feasibility study BROWN,S C. Viiginia Fictoric & Power Co. 80/03/28 19
- 8004190540 Forwards IF Into Notice 80-17, "Instrument Failure Causes Opening or PORV ' Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Ortice of the Director 80/03/3 Region 2, Atlanta, Orfice of the Director 80/03/31
- 8004080652 Forwards lE Circulai A0-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply 'No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01
- 8004150105 Forwards lE Info Notice 80-13. "GE Type GBM Control Switches Defective CAM Followers " No specific action or response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director
- 8004240284 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180299 Forwards IE Circular 80-07, "Problems U/HPCI Turbine Dil Bys " No written response required D'REILLY, J P Region P. Atlanta, Orfice of the Director 80/04/03
- 8004230108 Forwards If Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY.J P Region 2. Atlanta, Urfice of the Director 80/04/04
- 8004180401 Forwards [E Rulletin 80-08, "Eiam of Containment Liner Penetration Welds " Written Tesponse required O'REILLY, J P Region ≥, Atlanta, Office of the Director 80/04/07
- 8004300415 Informs NRC that response to IF Bulletin 79-03, "Longitudinal Weld Defects in ASAE Type 304 Stainless Steel Pipe." has been suspended due to feasibility study at factility All nuclean-related activities have been curtailed BROWN S C Virginia Electric & Power Co 60/04/25 ip
- R Periodic operating reports & related correspondence
- 8004020157 Forwards, "Annual Update Rept-1980 on Const Settlement Monitoring Program " Due to limited amount of data obtained during present period of const activity, second update rept will be forwarded one yr after const is resumed BROWN,8 C Virginia Electric & Power Co 80/03/31 ip
- --8004020161 "Annual Update Rept-1980 on Const Settlement Manitoring Program " * Virginia Electric & Power Co 80/02/29 17pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 HHITT,K W Region 2, Atlanta, Office of the Director 77/08/12
- 8004020459 Part 21 rept on 800728.884 made telephone rept re defect concerning potentially overstressed supports on reactor coulant letdown coolers due to inadequate support design Corrective action redesign of support stand TAYLOR.J H Babcock & Wilcox Co 80/03/03 App
- 8004010397 Interim deficiency tept re potential overstress condition in letdown cooler supports Noticle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys HOMELL.S H Consumers Power Co 80/03/27 (p

- ~-8004010404 forwalds add) info to Part 21 rept re potentially giverstressed supports on macPor coolant letdown coolers at facilities under const by BBN
 TANLOR, J H. Babcock / Wilcor Co. 80/03/03 6pp
- B004220611 Interim deficiency rept re overfilling steam generators by excessive addition of auxiliary feedwater Potential results include elective steam generator tube stress t containment overpressurization BROWN 5 C Virginia Electric to Power Co. 80/04/18 2pp
- DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of MUREO-0588, "Interim Staff Position on Environ Qualification of Sarety-Rolated Electrical Equipment," providing guidance is methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004220234 Forwards response to NRC 800306 request for additinfo retriew of design groundwater levels
 BROWN S C Virginia Electric & Power Co 80/04/18 5pp
- F Security, medical, emergency & tire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791326 ltr.has been postponed pending QAO clearance under Federal Repts Act
 ORIMES.8 V Emergency Preparedness Task Force 80/03/11 4pp
- I Financial information
- 8004010269 Folwards Annual Rept 1979
 BAUM, E.A. Virginia Electric & Power Co. 80/03/27 1p
- --8004010275 Annual Rept 1979

 * Virginia Electric * Power Co 79/12/31 32pp
- 9 Inspectson reports. If Bulletins & correspondence
- 8004090358 Forwards IE Bulletin 80 03. "Loss of Charcoal From Std Type 11.Two-Inch.Tray Adsorber Cells " Action required D'REILLY.J P Region 2. Atlanta, Office of the Director 80/02/06 200
- 8004090130 Forwards IE Insp Repts 50~339/80~01.50~404/80~01 & 50~405/80~01 on 800127~0201 No noncompliance noted STOHR, J P Region P. Atlanta, fuel Facility & Materials Safety Branch 80/02/22 Pp
- --8004090134 IE Insp Repts 50-339/80-01,50-401/80-01 & 50-405/80-01 on B00129-0201 No noncompliance noted Major areas inspected erosion & runof* control,waste mpt.review of previous items & preoperational program JENKINS, 0 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch CUNNIIOHAM:A L Region 2, Atlanta, Office of the Director 80/02/19 3pp
- B004010465 Notifies of suspension of review of IE Bulletin 80-05 re vacuum condition resulting in damage to chemical vol control sys holder tanks Suspension due to feasibility study BROWN-S C Virginia Electric & Power Co 80/03/28 ip
- 8004150940 Forwards IE Into Notice 80-12. 'Instrument Failure Causes Opening of PCRV & Block Valve' No specific action or response necessary
 O'REILLY, J P Region 2 Atlanta, Ortice of the Director 80/03/31
- 8004080552 Forwards IF Carcular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onaite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 268
- B004150105 Forwards IB Info Notice 80~13, "GE Type SOM Control Switches Defective CAM Followers " No specific action or response required Q'REILLY, J P Region 2, Atlanta, Office of the Director B0/04/02
- 8004240284 Farwards 1F Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/04/02

- 8004180299 Forwards IE Circulat 80-07, 'Problems WHPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03 200
- BO04230108 Forwards IE Bulletin 79-03A 'Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY.J P Region 2. Atlanta. Office of the Director B0/04/04 1p
- BOO4180401 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director BO/04/07 200
- 8004300415 Informs NRC that response to IE Bulletin 79-03, "Longitudinal Weld Derects in ASME Type 304 Stainless Steel Pipe," has been suspended due to reasibility study at facility All nuclear-related activities have been curtailed BROWN, S.C. Virginia Electric & Power Co. 80/04/25 ip
- R Periodic operating reports & related correspondence
- BO04020157 Forualds. "Annual Update Rept-1980 on Const Settlement Monitoring Program " Due to limited amount of data obtained during present period of const activity, second update rept will be forwarded one yr after const is resumed BROWN.S C Virginia Electric & Power Co 80/03/31 1p
- --8004020161 "Annual Update Rept-1980 on Const Settlement Monitoring Program" * Virginia Electric & Power Co 80/02/27 17ag
- S Reportable occurrences. LERs & related correspondence
- 8004220084 PNO-77-143 Pacific fump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT, X W Region 2. Atlanta, Office of the Director 77/08/12
- 8004020457 Part 21 rept on 800228, B&W made telephone rept re defect concerning potentially overstressed supports on reactor coolant letdown coolers due to inadequate support design Corrective action redesign of support stand TAYLOR, J H Dabcock & Wilcos Co 80/03/03 App
- B004010397 Interim deficiency jept re-potential overstress condition in letdown cooler supports Nozzle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys

 HOWELL, S H Consumers Power Co 80/03/27 ip
- --B004010404 Forwards addl into to Part 21 rept re potentially overstressed supports on reactor coolant letdown coolers at facilities under const by IBAI/ TAYLOR.J H Babcock & Milcox Co B0/03/03 App
- 8004220611 Interim deficiency rept re overfilling steam generators by excessive addition of auxiliary fredwater Potential results include excessive steam generator tube stress & containment overpressurization DROWN S C Virginia Electric & Power Co 80/04/18 2pp
- DUCKET 50-409 LA CROSSE BUILING WATER REACTOR

 A Application/construction stage documents & correspondence
- 7809270003 Forwards add] info in response to request of Dairyland Power Cooperative representatives at 780808 meeting re SEP STEPP, J C Geosciences Branch 78/09/11 3pp
- 8004040076 Notification of 800325-26 meeting w/util in La Crosse.WI to discuss inservice testing program SHEA.J J Operating Reactors Branch 2 80/03/05 2pp
- F Security, medical, emergency & fire protection plans
- 8004010410 Forwards discussion of info received from licensee on fire protection review items includes info ro interior hose stations, fixed suppression systematic circuit supervision & breathing all HALL-R E Brookhaven National Laboratory 80/03/26 9pp

G Adjudicatory correspondence

- 8004220417 Forwards Decision DD-80-9, granting partial acceptance of AK Morse 700521 petition for issuance of order to suspend provisional DL Adequate basis for suspending ones not exist Order to show cause has been issued DENTON.HR Office of Nuclear Reactor Regulation 80/02/29 2pp
- --8004220422 Decision DD-80-9, granting partial acceptance of AK Horse 790521 petition for issuance of order to suspend provisional DL Adequate basis for suspension does not exist Order to show cause has been issued DENTON H R Office of Nuclear Reactor Regulation 80/02/29 17aa
- --B004220430 Nutice of issuance of Director's Decision DD-80-9, granting partial acceptance of AK Norse petition for issuance of order to suspend provisional DL Adequate basis for suspension does not exist Request handled under 10CFR2 206 DENTUN, H R Office of Nuclear Reactor Regulation 80/02/27 2pp
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OUSSICK: V Office of the Executive Director for Operations B0/04/02 34pp
- BOO4100364 Notifies that issuance of FES will be delayed for approx two wks MCIDHEAD: C P Hearing Branch 3 80/04/03 ip
- 8004210091 Order granting NRC 800313 motion to compel Coulee Region Energy Coalition to respond to NRC 791214 interrogatories, by 800425 Intervenor failed to comply w/ASLB 791130 order setting discovery schedule refull-term DL proceeding BBCHHOEFER.C Atomic Safety and Licensing Board Panel 80/04/04 200
- 8004210174 Order granting extension, until 800415, for Commission to elect whether to review Director's 800227 decision CHILK.S J Office of the Secretary of the Commission 80/04/10

H General correspondence

- 8004170301 Responds to 800126 ltr to HR Denton requesting all future meetings re facility be held in WI & ASLD desision to allow expansion of facility spent fuel storage pool No secrecy involved in NRC activities Documents & meetings accessible DIRCKS,W J Office of the Executive Director for Operations 80/03/28 3pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 9004040261 Forwards certified summary of ACRS Subcommittee on LACBUR 771026 meeting in Washington.DC re proposal to enlarge storage capacity of spent fuel storage pool MCKINLEY, J C ACRS Advisory Committee on Reactor Safeguards 80/02/06 1p
- --8004040267 Certified summary of ACRS Subcommitte on LaCrosse BWR 791026 meeting in Washington.DC re proposal to enlarge capacity of spent fuel storage pool # ACRS Advisory Committee on Reactor Safeguards 80/01/08 22nn
- P Operating license stage documents & correspondence
- 7812060303 Notification of 781207 meeting w/SEP Dwner's Group in Bethesda:MD to discuss plans to address seismic input for use in SEP seismic review LEVIN:H A Systematic Evaluation Programs Branch (Pre 790625) 78/11/24 2pp
- 8004100314 Advises that responses to 751123 ltrs re LWR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors, per typical feel bundle & batch burnups ZIEMANN,D L. Operating Reactors Branch 2 80/02/29 3pp
- 8004080195 Forwards NUREG-0969, "Evaluation of Integrity of SEP Reactor Vessels," completing review of SEP Topic V-4 W/o encl ZIEMANN,D L. Operating Reactors Branch 2 80/03/03 2pp
- 8004020003 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN, D L. Operating Reactors Branch 2 80/03/06 5pp

- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethosda Operations Ctr EISENHUT. D. G. Division of Operating Reactors 80/03/12 Spp
- --B004030118 "Nuclear Data Link Specs " * Division of Operating Reactors 80/02/21 28pp
- 8004070321 Forwards operating instructions 5 characteristics of NRC health physics belephone network Purpose of network is transmission of health physics info during incident or abnormal occurrence at facility
 KEPPLER. J G Region 3. Chicago, Office of the Director 80/03/19
- 8004100114 Requests that uncontrolled set of PDIDs be placed on controlled distribution list to any future revisions. Revisions should be forwarded to attention of Region 3 incident response ctr.

 KEPPLER, J O Region 2, Chicago, Office of the Director. 80/03/20
- 8004210409 "Response to NRC Concerns on Liquefaction Potential " * Dames & Moore 80/03/21 32pp
- 8004090369 Forwards "Safety Evaluation & Compliance w/NRC Staff Positions le LACBUR Emergency Power Sys," App A rø test procedures for annual tests of emergency diesel generators IA & 18 Procedures inadvertently omitted from 800317 ltr LINDER, F Dairyland Power Cooperative 80/03/28 lpp
- ~~8004090376 "Safety Evaluation & Compliance w/NRC Staff Positions re LACβUR Emergency Power Sys." App A re test proceeders for annual tests of emergency diesel generators 1A ½ 18 w Nuclear Energy Service. Inc. 80/03/28 10pp
- 8004170290 Forwards request for add1 info to environ qualification of olectrical equipment ZIEMANN.D L. Operating Reactors Branch 2 80/03/28 14pp
- 8004140312 Requests that Toch Specs 4 2 4 2 5 ½ 5 2 17 5 be amended so that exposure limitation applies only to fuel assemblies in core interior & exposure limit on peripheral assemblies is deleted forwards proposed revision to Tech Specs LINDER, F Dairyland Power Cooperative 80/04/01 4pp
- --8004140314 Proposed revision to Tech Specs 4 2 4 2 5 & 5 2 17 5
 applying exposure limitation only to fuel assemblies in core
 interior & deleting exposure limit on peripheral assemblies
 Supporting documentation encl
 * Dairyland Power Cooperative 80/04/01 lipp
- BD04070303 Forwards corrected Pages 3 % 4 of util response to show cause order & corrected Table 2 % Figures 1-3 of Dames % floore rept which accompanied lesponse HIESTANDIO S florgan, Lewis & Buckius 80/04/03 9pp
- 8004150204 Forwards response to request for add1 info resulting from NRC site review of compliance w/NVREG-0578 Revised pages to 800131 its also encl
 LINDER.F Dairyland Power Cooperative 80/04/09 15pp
- Q Inspection reports, IF Bulletins & correspondence
- 8004100134 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/07 ip
- B00401010B Responds to IF Bulletin 80-02, "Inadequate QA for Nuclear Supplied Equipment " No Marvin Engineering Co equipment installed at facility LINDER, F Dairyland Power Cooperative 80/03/10 2pp
- 8004150170 Forwards It Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER: J G Region 3, Chicago, Office of the Director 80/03/31
- 8004080706 Forwards IE Circular 80-05, "Fmergency Diesel Generator Lubricating Oxl Addition & Onsite Supply "No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/01 ip

- 8004150029 Foluards IF Inc. He 11c 80-11 'GE Type SBM Control Switches Defective CAM Followers 100 specific Section or response KEPPLER J. Region 7 Pricago Ofrie or the Director 80/04/02
- 8004180048 Forwards attachurnt, ou IE Circulai 80-03, "Protection From Toxic Gas Haraids" inad ertaintly omitted from 800306 transmittal REPPER J is Region 3 th, ago. Orrice or the Director 80/04/02
- 8004220135 Forwards IF Into Notice 80-14, "Sarety Suggestions From Employees' No action required KEFPLER, J.G. Region 3 Chicago, Office of the Director 80/04/02
- 8004220357 Forwards It circular 80-07. Problems N/HPCI Turbine Oil Sys "No written response required REPPLER, J.G. Region 3. Chicago Office of the Director 80/04/03
- 8004110035 Forwards 18 buildetin 60-07. PWR Jet Pump Assembly Failure "Written response required
 KEPPLER, J G Region 3 Chicago, Office of the Director 80/04/07
- 8004230199 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/04/07
- 8004220104 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J. G. Region 3, Chicago, Orrice of the Director. 80/04/09
- R Periodic operating reports & related correspondence
- BCO4140365 Forwards monthly operating rept for Mar 1980 LINDER: F Dairyland Power Cooperative 80/04/07 1
- --8004140367 Monthly operating rept for Mar 1980 GOBDMAN.L S Dairyland Power Cooperative
- S Reportable occurrences. LFRs & related correspondence
- B0041504BB RO on B00409 while in shutdown condition, abnormal degradation was discovered in primary reactor containment during periodic. Type B * C surveillance leak rate testing Cause unstited Reapris underway LINDER.F Dairyland Power Cooperative 80/04/10 2pp
- 8004220584 RO 80-01 800410, during periodic Type B leak rate tests, electrical penetrations 3.4 2 5 exceeded permissible rates Caused by abnormal degradation Flectrical penetrations being LINDER, F Dairyland Power Cooperative 80/04/10 2pp
- 8004210200 RD-80-02 on 800415 during periodic Type C surveillance leakage rate testing, leak flow rates determined from exhaust dampers exceeded permissible leak flow rates Repairs to exhaust dampers being accomplished & retests will be made LINDER.F Dairyland Pauer Cooperative 80/04/16 2pp
- 8004270341 RO 80-03 on 800417 during periodic Type C surveillance leakage rate testing on containment bldg heating sys valve, leak flow rates found in ercess or permissible leak flow rates cause unstated Valve repairs 2 adjustments planned LINDER.F Dairyland Power Cooperative 80/04/17 2pp
- 8004300456 Forwards LFR 80-001/01T-0 LINDER:F Dairyland Power Cooperative 80/04/21 Spp
- --8004300463 LER 80-001/0)T-0 on BC0407, during periodic leakage rate testing, electrical penetration units 3.4, & 5 did not meet type B test criteria Gaused by cracked penetration glands Individual penetrations replaced GGODMAN.L B Dairyland Power Cooperative 80/04/21 1p
- U Congressional/Executive Correspondence
- 8004080260 Responds to 800128 ltr concerning Coulee Region Energy Coalition inquity re facility full-term QL proceeding DDE should be contacted for federal funding into Coalition environ evidence will be considered at ASLB hearing DIRCKS: N J Office of the Executive Director for Operations DIRCKS, N J 0: 80/03/10 2pp

- 8004080204 Requests response to encl Coulee Region Energy Coalition ltr refacility rull-term Ol proceeding PROXMIRE,W Senate 80/01/20 App
- 8004140235 Forwards response to Badger Safe Energy Alliance 800126 ltr of concern re facility, in response to 800208 request W/o
 - enci DIRCKS.W J Office of the Executive Director for Operations HD/03/28 in
- --800414023B Requests info on encl Badger Safe Energy Alliance 800126 ltr requesting that future NRC meetings ie facility be held in LaCrosse,WI area REDELMAN,J NELSON,G Senate 89/02/08 2pp
- DOCKET 50-410 NINE MILE POINT RUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8004040031 Advises or issuance of NUREG-0588, "Interim Staff Position on Environ Qualitication of Sarety-Related Electrical Equipment," providing guidance te methods for compliance RUSS.D F Division of Project Management 80/02/05 7pp
- 8004020466 Notification of 800326 & 27 meeting w/representatives from Mark II owners group in San Jose.CA to discuss Mark II Creace Test Program.41 c/o tests & foreign tests ELTAWILA.F Containment Systems Branch 80/03/10 12pp
- 8004030122 Notification of 800326-27 meeting w/Mark II owners group, NRC consultants & GE in San Jose-CA to discuss Mark II Creare test program.4T C/O & foreign tests Topics are proprietary Agonda enci ELTAWILA,F Containment Bystems Branch 80/03/10 12pp
- B004010014 Forwards NRC B00128 \$ 0211 ltrs to GE re mods to DWR control drive sys Mods should not be performed prior to issuance of NUREO-0419 Appropriate sys mods A supporting analyses should be incorporated into FSAR RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/i1 2pp
- 8004100301 Notification of 800403 meeting w/OE in Bethesda, MD to discuss BMR & safety relief valves mfg by Q Dickens & Co & supplied by GE to facilities HEMDERSON. J B Division of Reactor Construction Inspection 80/03/13
- 8004040474 Bummary of 800227 meeting w/Mark II comers group re status of several long-term program tasks.including Tasks A 17 & A 16 & task related to utilization of foreign test data ELTAWILA:F Containment Systems Branch 80/03/18 104pp
- B004100297 Requests addl info re 790809 proposal to use alternative method of splicing reinforcing steel bars than described in facility PSAR Reply must be notarized RUGENSTEIN.L S Light Water Reactors Branch 4 80/03/25 3pp
- 8004300061 Summary of 800326-27 meetings w/Mark II numers group in San Jose,CA re discussion of NRC concerns on data from Grears tests & foreign full-scale test programs & relationships w/ Mark II designs ELTAWILA,F Containment Systems Branch 80/04/14 22pp
- 8004250419 Requests authorization to use ASMC Section III Code Case N-242, "Matis Certification " Code case approved for SNUPPB by OD Parr in 790713 ltr BARLETT, J Niagara Mohawk Power Corp 80/04/21 ip
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act GRIMEB.O K Emergency Preparedness Task Force 80/03/i1 4pp
- B004070034 Forwards copy of NRC 771121 generic 1tr re upgraded emergency plans Document also available in local PDR W/o encl RUBENSTEIN, L S Light Water Reactors Branch 4 80/03/25 1p
- H Ogneral correspondence
- 8004280376 Informs of mgt changes BARTLETT, J. Niagara Mohawk Power Corp. 80/04/22 ip

- G Inspection reports, IE Bulletins : correspondence
- 8004150285 Forwards IE info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/31 1p
- 8004300282 Ack receipt of 800319 ltr informing NRC of steps taken to correct violations noted in IE insp Rept 50-410/80-01 CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 60/03/31 jp
- --8004300290 Responds to NRC 800214 ltr re violations noted in IE Insp. Rept 90-410/80-01 Corrective actions increased training of preventive maint personnel will be instituted, using formal & on-job sessions
 BARTLETT, J. Niagara Mohawk Power Corp. 80/03/19 3pp
- --8004300296 Forwards IE Insp Rept 50-410/80-01 on 800109-11 & notice of violation CARLESUN:R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/14 2pp
- --B004300301 Natice of violation from insp on 800109-11
 * Region 1, Philadelphia, Office of the Director 80/02/08 2pp
- --8004300309 IE Insp Rept 50-410/80-01 on 800109-11 Noncompliance noted failure to perform required equipment maint, to furnish recorded evidence of maint & to control equipment storage MCGAUGHY, R W Region 1. Philadelphia, Reactor Construction & Engineering Support Branch CERNE. A C Region 1. Philadelphia, Office of the Director 80/02/08 7pp
- 8004090077 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required ORIER, DH Region 1, Philadelphia, Office of the Director 80/04/01 ip
- 8004110159 Forwards IE Info Notice BO-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required ORIER, B H. Region i, Philadelphia, Office of the Director BO/04/02 ip
- 8004240330 Forwards 1E Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER, B H Region I, Philadelphia, Office of the Director 80/04/02 ip
- 8004180180 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Dil Bys " No written response required ORIER, D H Region i, Philadelphia, Office of the Director 80/04/03 1p
- 6004110058 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required ORIER.B H Region i, Philadelphia, Office of the Director 80/04/04 lp
- B004230486 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defecte in ASME SA-312, Type 304 Stainless Steel Pipe " Action required ORIER, B H Region I. Philadelphia, Office of the Director 80/04/04 ip
- 8004180205 Forwards IE Bullotin 80-08. "Exam of Containment Liner Penetration Welds " Written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/04/07 tp
- 8 Reportable occurrences, LERs & related correspondence
- 8004100580 Ack receipt of 800205 interim deficiency rept re possible future movement of radwaste bidg geologic feature CARLEBONR T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/21 1p
- 8004220559 Forwards interim deficiency rept re defects in biological shield wall shop welds previously reported 790530 Final rept summarizing test & analyses & identifying possible safety implications will be provided by 800801 TERRY, J H Niagara Mohawk Power Corp 80/04/15 ip
- ---8004220577 Interim deficiency rept re defects in biological shield wall shop welds Cause unstated Defect sizes & locations will be mapped, based on engineering evaluation to determine allowable defects Repairs will be performed as required * Niegara Mohawk Power Corp 80/04/15 25pp

- DOCKET 50-412 BEAVER VALLEY POWER STATION. UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURCG-0588, 'Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance te methods for compliance ROSS, D.F. Division of Project Kinagement 80/02/05 7pp
- 8004070336 Advises that due to studied of electric syc requirements % const expenditure forecasts, ruel load date was deferred from 831231 to 851231 Commercial operation date scheduled for 860531 FSAR & environ rept submittal scheduled for WOOLEVER.E J Duquesne Light Co 80/03/26 tp
- F Security, medical, emergency of ire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Ropts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- Q Inspection reports. IE Bulletins & correspondence
- 7906010118 FOIA request by UCS for all documents re Task Action Plans A-40 & A-41, into on seismic issues prepared for SEP & insp repts for Beaver Valley WEISS,E R Sheldon, Harmon & Weiss 79/03/19 2pp
- 8004280188 Responds to II Bulletin 80-03 Insp of chargoal adsorber cells shall be performed when received WODLEVER.E J Duquesne Light Co 80/03/19 tp
- 8004150266 Forwards 1E Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia. Office of the Director 80/03/34 ip
- 8004090052 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition » Onsite Supply " No written response required GRIER, B # Region 1, Philadelphia, Office of the Director 80/04/01 1p
- 8004110133 Forwards IF info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER, B H Region !, Philadelphia. Office of the Director 80/04/02 | Ip
- B004240303 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required GRIER.II H Region 1. Philadelphia, Office of the Director 80/04/02 Ip
- 8004180192 Forwards IF Circular 80-07, 'Problems W/HPCI Turbine 0:1 Sys " No wistten response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/03 | 1p
- 8004230475 Forwards IE Bulletin 79-03A. "Longitudinal Wald Defects in ABME SA-312, Type 304 Stainless Steel Pipe " Action required ORIER, B H. Region J. Philadelphia. Office of the Director 80/04/04 ip
- 8004180134 Forwards IC Bulletin 80-08, "Txam of Containment Liner Penetration Welds " Writton response required GRIER, B K Region 1. Philadelphia, Office of the Director 80/04/07 ip
- BOO4220483 Responds to NRC BOO313 ltr re unresolved items & allegations noted in IE insp Rept 50-412/HO-02 Corrective actions util initiated QA audits to confirm piping fabricator actions prior to BOO601
 WUDLEYER: J Duquesne Light Co BO/04/16 22pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT, K W Region 2, Atlanta, Office of the Director 77/08/12

- CoUM2230169 Requests extension From BC1413 to O616 for final rept on Significant Deficiency (2-15 record discrepancies in reactor resvel structure in proport More time required for tampling analysis in the Lution or deficiency MCDLEVER to its properties in the second of the control of t
- " Operator Examinations
- 8004070743 Denie, ital 8007 4 request for administering written examination. We are 800910 to delaying oral operating examinations with Jul 179, due to last or reactivity manipulations.

 CCCLLIS F.F. Tiperatur Livensing Smanch 80/03/19 2pp
- BOCKET 50-413 CATAKEM NULLEAR STATION, UPIT 1

 A Application/construction stage documents & correspondence
- #3040406731 Ad ises of issuance or NUREG-0588, "Interin Staff Position on Environ Gualification of Sarety-Related Electrical Equipment, pro iding goldance in methods for compliance ROSS D.F. Division of Project Management 80/02/05 7pp
- E004040017 Submits add1 pridance to NuREG-0588, "Interim Staff Position on Environ Qualification or porety-Related Electrical Equipment ' Requests re seu or equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- BOO4070155 Summary of BOO314 meeting w/utils.Westinghouse & Sargent & Lundy re Westinghouse optimized fuel assembly Comm Ed requested to amend FSAR as soon as possible to show plant will use optimized fuel assembly WINTNER, L L Light Water Reactors Branch 1 80/03/1B 8pp
- 8004170327 'TMI-Plus One Toward a Sefer Nuclear Power Program "

 * Duke Power Co 80/03/26 13pp
- E004140430 Forwards comparison or drart STS w/snubber functional test sampling plan COLLINGS, D M Dute Power Co 83/04/03 11pp
- F Security, medical energency & tire protection plans
- 80040B0077 Advises that submittal date for evacuation time estimates, requested by PRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- Q Inspection reports, 1E Bulletins & correspondence
- B004020019 Discusses completed diesel generator factory test per IE Bulletin 79-23 Voltage & frequency requirements maintained during test & cooling sys functioned within design limits PARVER.W O Duke Power Co B0/03/20 ip
- 8004210164 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std Type 11, Two-Inch. Tray Adsorber Cells " Containment cleanup is only unit using design described in bulletin No sign of sagging screens or other derect that would permit leakage PARKER, W. O. Dute Power Co. 80/03/24 ip
- 8004210234 Ack receipt of IE Insp Repts 50-413/80-03 & 50-414/80-03, on 800214-15 No proprietary info PARKER, N D Duke Power Co 80/03/28 1p
- --B004210242 Forwards 1E Insp Repts 50-413/B0-03 % 50-414/B0-03 on B00214-15 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/03/10 2pp
- --B004210247 IE insp Repts 50-413/80-03 & 50-414/80-03 on 800214-15 No noncompliance noted Major areas inspected indoctrination of new resident inspector for const BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch MCFARLAND.C R Region 2. Atlanta. Office of the Director 80/03/10 4pp
- 8004150511 Forwards IF Info Notice 80-12, "Instrument Failure Causes Opening of FORV & Block Valve ' No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31

- 5004080611 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/04/01
- 8004160116 Ack receipt of IF Insp Repts 50-413/80-02 & 50-414/80-02 on 800212-14 No proprietary info PARKER, W O Duke Power Co 80/04/01 lp
- --8004160118 Forwards IE Insp Repts 50-413/80-02 & 50-414/80-02 on 800212-14 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/12 2pp
- --8004160122 IE Insp Repts SO-413/80-02 & 50-414/80-02 on 800212-14 No noncompliance noted Major areas inspected RCPB piping, safety-related piping, vendor pipe welds w/rejectable indications & safety-related structures HERDT. A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS. N Region 2. Atlanta, Office of the Director 80/03/11 7pp
- 800415007D Forwards IE Info Notice 80-13, "OE Type SDM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director BD/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Bafety Buggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004180326 Forwards IE Circular 80-07, "Problems W/MPCI Turbine Dil Sys " No written response required D'REILLY. J P Region 2. Atlanta. Office of the Director 80/04/03 2pp
- B004230132 Forwards IE Bullevin 79-03A "Longitudinal Weld Defects in ASHE SA-312, Type 304 Stainless Steel Pipe" Action required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04 ip
- B004180358 Forwards IE Bulletin B0-08, "Exam of Containment Liner Penetration Weids " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07
- DOCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits add1 guidance to NUREC-0588. "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compilance ROSS.D F Division of Project Management 80/02/21 Spp
- B004170327 "TMI-Plus One Toward a Safer Nuclear Power Program" * Duke Power Co 80/03/26 13pp
- B004140430 Forwards comparison of draft STS w/snubber functional test sampling plan CULLINOS.D M Duke Power Co 80/04/03 iipp
- F Security, medical, emergency & fire protection plans
- BOO40B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 itr.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- Q Inspection reports: IF Bulletins & correspondence
- 8004020019 Discusses completed diesel generator factory test per IC Bulletin 79-23 Voltage & frequency requirements maintained during test & cooling sys functioned within design limits PARKER, N.O. Duke Power Co. 80/03/20

DOCKETED ITEMS

- 80042j0164 Responds to 1E Bulletin 80~03, "Loss of Charcoal from Std Typs 11.Two-inch.Tray Adsorber Cells " Containment cleanup is only unit using design described in bullotin No sign of sagging screens or other defect that would permit leakags PARKER.W O Duke Power Co 80/03/24 1p
- 8004210234 Ack receipt of IE Insp Repts 50~413/80~03 & 50~414/80~03, on 800214~15 No proprietary into PARKER, W O Duke Power Co 80/03/28 1p
- --8004210242 Forwards IE Insp Repts 50-413/80-03 & 50-414/80-03 on 800214-15 No nancampliance noted BRYANT,J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/10 2pp
- --8004210247 IE Insp Repts 50-413/80-03 % 50-414/80-03 on 800214-15 No noncompliance noted Major areas inspected inductrination of new resident inspector for const BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch MCFARLAND, C R Region 2, Atlanta, Office of the Director 80/03/10 4pp
- 8004i505ii Forwards JE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 200
- 8004080611 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01 200
- 8004160116 Ack receipt of IE Insp Repts 90~413/80~02 & 50~414/80~02 on 800212~14 No proprietary info PARKER,N O Duke Power Co 80/04/01 ip
- --8004160118 Forwards IE lnsp Repts 50-413/80-02 & 50-414/80-02 on 800212-14 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/03/12 2pp
- --8004160122 IE Insp Repts 50-413/80-02 & 50-414/80-02 on 800212-14 No noncompliance noted Major areas inspected RCPB piping, safety-related piping, vendor pipe welds w/rejectable indications & safety-related structures HERDT.AR Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS.N Region 2, Atlanta, Office of the Director 80/03/11 7pp
- 8004150070 Forwards IC Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 200
- 8004240249 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004180326 Forwards 1E Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03 200
- 8004230132 Forwards IE Bulletin 79-03A "Longitudinal Held Defects in ASME SA-312.Tupe 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/04 ip
- B0041B0358 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- DOCKET 50-416 GRAND OULF NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDSE.D F Division of Project Management 80/08/05 7pp

- 800404001/ Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Oudlinication or Carety Related Electrical Equipment 'Requests review or Aquipment qualification documentation to identify degine of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- B004020446 Forwards NRC BN0126 ' v211 ltrs to GE re mods to BWR control rod drive sys ! addl analyses or boiloff rates respectively Further info / guidance to be issued in NUREC-0619
 BAER,R L Light Water Reactors Branch ? 80/03/13 2pp
- 8004100301 Notification or 800403 meeting w/GC in Bethesda.MD to discuss BWR & safety relief valves mfg by G Dickens & Co & supplied by GE to racilities HENDERSON / B Division or Reactor Construction Inspection 80/03/13 | App
- 8004030149 Requests addi into to complete facility environ review Forwards specific list of required info Reply should consist of sequentially numbered revision to final environ rept BALLARD, R L Four commental Projects Branch 1 80/03/14 3pp
- 8004090341 Forwards application for amend of Licenses CPPR-118 & CPPR-119 Also forwards 10CFR50 App L antitrust Info STAMPLEY.N L Mississippi Power & Light Co 80/04/03 2pp
- --8004070345 Application for amend of CPPR 118 % CPPR-119 adding South Mi Electric Fower Association as co-owner Drafts of joint constracquistion % ownership agreement operating agreement % substitute power agreement encl # Mississippi Power % Light Co 80/04/03 240pp
- --8004090350 Annual Financial Rept 1978 Addl financial info attached ≠ Gouth Mississippi Electric Power Association 78/12/31 150pp
- 8004210228 Forwards info per NRC 800214 request supporting confirmatory piping analysis of safety lelief Valve 15 discharge line Revision 6 to piping design Spec 9545-M-220 0 other supporting info 8 drawings available in Central Files only DALE, L.F. Mississippi Power 2 light Co. 80/04/09 4pp
- 8004280084 Forwards Instrumentation & Control Branch request for add1 info re FBAR Sections 7 4 % 7 5 FBAR should be amended to reflect responses to requests BAER.R L Light Water Reactors Branch 2 80/04/09 9pp
- 8004170243 Forwards fee re 740710 request for approval of deletion of stage monitoring requirement in environ protection program DALE, L.F. Mississippi Power & Light Co. 80/04/16. 1p
- C Utility Environmental Report (ER), amends & correspondence
- BOD4220421 Forwards correspondence between util 1 State of MI Natural Heritage Program per Guestian 340 14 on final environ rept DALE, L.F. Mississippi Power & Light Co. 80/04/16 App
- BOO4220289 Forwards Amend 3 to environ rept, consisting of responses to 800122 requests for add1 info STAMPLEY,N L Mississippi Power & Light Co 80/04/18 1p
- --B004220293 Amend 3 to environ rept
 * Mississippi Power % Light Co B0/04/18 40pp
- f Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC /91226 ltm, has been postponed pending OAD clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 App
- B0041005B4 Notification of postponement of 800414-16 meeting w/util. Bechtel % Gage Babcock in Port Oibson, HS to review facility fire protection HDU0HTON, T C Light Water Reactors Branch 2 B0/03/11 2pp
- H General correspondence
- 8004100362 Responds to NRC 780627 ltm by forwarding affidavit of svc redistribution of Amend 37 to CPPR-118 & CPPR-119
 DALE, L F Mississippi Power & Light Co 80/04/07 2pp
- 1 Financial information
- 8004220535 Annual Financial Rept 1979 * Middle South Utilities Inc 79/12/31 40pp

- m (Amilian, family depart of harm) amends
- af ATT of filter metry of application for OL Also forwards piping filtering the trial drawings blockrayal mealings of an interfer of the inter
- 3.0476 'A Figur, ' 1 ().me (3)13m Diagram Reactor Water Cleanup Sys • Partiel (crp. 1846 - 76,12/11 - 1p
- = 827423 FR1 Frend FR + 1 / 2 R variating of responses to NRC questions & minellaneous recipieners or design thin

 Missiasippi Found () ohi / 5 80 04/25 230pp
- M Antiffust corresponden e
- CO34090353 Response to 17 former 200312 ltm to NRC me interconnection agreement Absence on the schools to execution of Gulf States (1011 Countries agreement of interned to be operative Requests resolution became UL stage MCDIAPMID R Countries (UL stage M
- --8004090255 fetition to intervene in proceeding Urges Commission to accept intercornertion, agreement for hilling suspend agreement operation for one day the set issue for immediate conference thearing McDiaRMID.R C. Springel & McDiaRMID.R C. Springel
- 8004150197 Finds antitrust info submitted 800403 acceptable for docketing? distribution TQALSTOR, A Antitrust Indemnity Group 80/04/14 ip
- --8004150205 Forwards antitiust info per application for amend of Licenses CPPR-118 / LPPR-119 STAMPLE/, N.L. Mississippi Power / Light Co. 80/04/03 10pp
- BOG4180283 Forwards info re South MS Electric Power Association, submitted per App L of 10CFPEO or Cormission Rules of Practice info transmitted to orrer opportunity to render advice re findings to be nade by Cormission M/o encl SHAPAR, H w. Orfice of the Ejecutive Legal Director 80/04/16 1p
- G Inspection reports IF Bulletins & correspondence
- 8004070337 Forward: IF Bullinin 80-03. Loss of Charcoal From Std Type
 II. Tun-Inch Tray Adsorber Cells ' Action required
 O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/02/06
 2pp
- 800404084 Forwards IF Irsp Repts 50-416/80-01 & 50-417/80-01 on 800122-24 No noncompliance nored BRYANTJ C Region 2 Atlanta Reactor Construction & Engineering Support Branch 60/02/12 2pp
- --8004040125 IE Insp Repts 50-416/80-01 4 50-417/80-01 on 800122-24 No noncompliance noted Major areas inspected offsite warehouse insp 2 observation or safety-related activities Followup on IE builetin inspector 1 licensee identified items CANFRELL.F 5 Region 2. Atlanta. Reactor Construction & Engineering Support Branch RAUSCH, J K Region 2. Atlanta, Office of the Director 80/02/11 App
- 8004040201 Forwards 1F Repts 50-416/80-06 5 50-417/80-05 on 800129-31 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/15 2pp
- BOO4100045 Forwards IE Insp Rept 50-416/80-03 on 800129-0201 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 2pp

- -800410005) [E insp kept 50 414/80-03 on 800127-0201 No noncompliance noted Major areas insperted protection 3 maint of safety-related electrical equipment, instrumentation work? revises or associated records
 COLON-TE Region 2, Atlanta Reactor Construction 3. Engineering Support Branch RUFF, A E Region 2, Atlanta, Office of the Director 807/02/19 Jpp
- GC042300/O Responds to IE Bulletin RO-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Cells " Insp revealed improvement in design/const or tray type charcoal adsorber cells DALE.L F Mississippi Power * Light Co B0/03/20 2pp
- 8004150491 Forwards IE Inno Notice 80-12, "Instrument Failure Caused Opening of FORV & Block Valve 'No specific action or response necessary O'REILLY, J. P. Region 2, Atlanta, Orfice of the Director 80/03/31
- 8004080587 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 200
- 8004130088 Forwards IC Info Notice 80-13, "GE Type 80M Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240268 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004180268 Forwards IE Circular 80-07. "Problems N/HPC1 Turbine Oil Bys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/03 2pp
- 8004110014 Forwards It Bulletin 80-07. "BWR Jet Pump Assembly Failure "
 No written response required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/04/04
 2pp
- 8004230181 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASKE SA-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180328 Forwards 1E Bulletin 80-08: "Exam of Containment Liner Penetration Helds " Written response required U'REILLY, J.P. Region P. Atlanta, Office of the Director 80/04/07 2pp
- 8004230322 Forwards It insp Rept 50-416/79-34-01 supplemental response clerifying previous response transmitted in BO0414 ltr MCOAUGH7,J Mississippi Power & Light Co BO/04/15 2pp
- S Reportable occurrences. LERs & related correspondence
- 8004090183 PNO-II-80-044 on 800319, site ambulance, en route to hosp w/laborer, heart attack victim, involved in accident Three of four occupants villed Status of laborer unknown HURT.M D. RAUSCH.J K. Region 2. Atlanta, Office of the Director 80/03/19 [p
- 8004170071 Forwards final rept for Potentially Reportable Deficiency 79/12 re Rosemount Model 510 DU master & slave trip units DALE, L. F. Mississippi Power & Light Co. 80/03/21 1p
- --8004170074 Final rept for Potentially Reportable Deficiency 77/12 re
 Model 510 DU master * slave trip units w/max current drain
 in excess of original specified value Deficient power
 supplies being replaced Details found in GE rept
 4 Mississippi Power & Light Co 80/03/21 Ip
- 8004280517 Forwards interim deficiency rept re damaged instrumentation cables under reactor pressure vessel DALE, L. F. Mississippi Power & Light Co. 80/03/31 1p
- --8004280522 Interim deficiency rept re damaged instrumentation cables under reactor pressure vessel During installation of control rod drive assembly housings.insulation on 132 cables was damaged Cause under investigation
 * Mississippi Power & Light Co 80/03/31 1p

- 8004280501 Farwards summary overview of deficiency PRD-80/04 re effects of loss of site power on rod position indication & neutron monitoring indication Util is re-evaluating position on reportability of defficiency Final rept will be issued DALE, L.F. Mississippi Power & Light Co. 80/04/03 3pp
- 8004150548 Forwards history & description of deficiency re to valve manifolds supplied by Dragon Valbe, Inc Deficiency Improperly evaluated Re-evaluation underway, w/determination of potentially reportable deficiency by 800402 DALE, L.F. Mississippi Power & Light Co. 80/04/04 2pp
- B004280484 Confirms B00328 telcon concerning deficiency PRD-B0/02 re defective gloom in control rod drive hydraulic sys Problem does not constitute reportable deficiency Elbow does not adversely affect plant safety Elbow will be replaced DALE.L F Mississippi Power & Light Co B0/04/04 4pp
- 8004280541 Deficiency rept re William Powell valves which may not meet seismic requirements of original purchase order Vendor re-analysis of valve hatural frequencies still in progress final rept will be submitted by 8000613 DALE.L F Mississippi Power & Light Co 80/04/04 ip
- 8004280520 Deficiency rept re malfunctioning Limitorque motor operators Cause of deficiency apparently related to excessive threading of stem protector Investigation continuing Final rept should be submitted by 800728 DALE.L F Mississippi Power & Light Co 80/04/11 1p
- 8004280610 Forwards interim rept for Potentially Reportable Deficiency 80/05 re electrical cable insulation damage sustained during cable pulling process
 DALE.L F Mississippi Power & Light Co 80/04/11 ip
- --8004280618 Interim rept for Potentially Reportable Deficiency 80/05 re cable damage substained during cable pulling process Nature of damage ranges from jacket chafing to insulation cut through to conductor Cables replaced # Mississippi Power & Light Co 80/04/11 1p
- 8004280481 Second interim deficiency rept re faulty GE CR2940-U8203E hand switch in plant svc water sys Buttch returned to GE for failure analysis Final rept will be forwarded on 800618 DALE.L F Mississippi Power & Light Co 80/04/15 19
- 8004280499 Submits status rept for deficiency PRD-80/09 re pipe hanger nonconformances Possibly caused by inadequate training & insp procedures Noncomformances are being evaluated DALE, L. F. Mississippi Power & Light Co. 80/04/18 2pp
- 8004280606 Submits status rept for deficiency PDR-80/10 re unqualified cable insulation repairs in Rockbestos cable Cable splices were not involved Supplier conducting qualification tests on repair matls

 DALE.L F Mississippi Power & Light Co 80/04/18 2pp
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREQ-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re-methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004040017 Bubmits add1 guidance to NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment " Requests review of equipment qualification documentation to identify degree of compliance ROSS, D.F. Division of Project Management 80/02/21 3pp
- 8004020446 Forwards NRC 800128 & 0211 ltrs to 0E re mods to BWR control rod drive sys \$ add1 analyses of boiloff rates respectively Further info & guidance to be issued in NUREO-0619

 BAER.R L Light Water Reactors Branch 2 80/03/13 2pp
- 8004i0030i Notification of 800403 meeting w/OE in Bethesda.MD to discuss BWR 6 safety relief valves mfg by G Dickens & Co & supplied by GE to facilities HENDERSON.J B Division of Reactor Construction Inspection 80/03/13 2pp
- 8004030149 Requests addl info to complete facility environ review Forwards specific list of required info Reply should consist of sequentially numbered revision to final environ rept BALLARD, R. L. Environmental Projects Branch 1 80/03/14 3pp

- 8004090341 Forwards application for anend of Licenses CPPR-118 & CPPR-119 Also forwards LUCFR50 App L antitrust info STAMPLEY.N L Mississippi Power & Light Co 80/04/03 2pp
- --8004090345 Application for amend of CPPR-118 % CPPR-119 adding South MI Electric Power Association as co-owner Diafts of joint const.acquistion & owner, the agreement operating agreement % substitute power agreement encl

 * Mississippi Power * Light Co 80/04/03 240pp
- --8004090353 Annual Financial Rept 1978 Addi +inancial info attached

 * South Mississippi Flectic Power Association 78/12/31 150pp
- B004210228 Forwards info per NRC 800214 request supporting confirmatory piping analysis of safety relier Valve 16.discharge line Revision & to piping design Spec 9645-H-220 O other supporting info & drawings available in Central Files only BALE.L F Mississippi Power & Light Co B0/04/09 App
- 8004280084 Forwards Instrumentation & Control Branch request for add1 info re FSAR Sections 7 4 & 7 5 FSAR should be amended to reflect responses to requests

 BAER.R t. light Water Reactors Branch 2 80/04/09 9pp
- 8004170243 Forwards fee re 790710 request for approval of deletion of stage monitoring requirement in environ protection program DALE.L.F. Mississippi Power & Light Co. 80/04/16 1p
- C Utility Environmental Report (ER), amends & correspondence
- 8004220421 Forwards correspondence between util & State of MI Natural Heritage Program per Question 340 14 on final environ rept DALE.L F Kississippi Power & Light Co 80/04/16 App
- 8004220287 Forwards Amond 3 to environ tept, consisting of responses to 800122 requests for addl info STAMPLEY, N.L. Mississippi Power & Light Co. 80/04/18 [p
- --8004220293 Amend 3 to environ rept * Mississippi Power 5 Light Co 80/04/18 40pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr. has been postponed pending GAO clearance under Federal Repts Act GRIMES. B K Emergency Proparedness Task Force 80/03/11 4pp
- 8004100584 Notification of postponement of 800414-16 meeting w/util. Bechtel & Gage Babcock in Port Gibson.MS to review facility fire protection HDUGHTDM, T.C. Light Water Reactors Branch 2 80/03/11 2pp
- H General correspondence
- 8004100362 Responds to NRC 780627 ltr by forwarding affidavit of svc re distribution of Amend 37 to CPPR-118 & CPPR-119 DALE, L F Kississippi Power & Light Co 80/04/07 2pp
- I Financial information
- Middle South Utilities, Inc 79/12/31 40pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004280365 Forwards Amend 38 to application for QL Also forwards piping & instrumentation diagrams * electrical drawings Electrical drawings not enci LUTKEN.D C Mississipp Power & Light Co 80/04/25 ip
- --8004280371 Amend 38 to application for UL Consists of responses to NRC questions re FSAR & miscellaneous refinements of design info LUTKEN.D C Mississippi Power & Light Co 80/04/21 2pp
- ---8004280381 Amend 38 to FSAR, consisting of responses to NRC questions & miscellaneous refinements of design info
 * Mississippi Power & Light Co 80/04/25 230pp

M. Antifrust correspondence

- 8004090363 Responds to TU Conner 1300312 ltr to NRC reinterconnection agreement Absence of s.c schedule 5 execution of Gulf States Uril Coundicate agreement not intended to be operative Requests resolution before QL stage MCDIARMID. R C = preget / NCDIARMID. R C = preget / NCDI
- --800405036B Petition to infervene in proceeding Urges Commission to accept interconnection agreement for filing, suspend agreement operation for one day / set issue for immediate conference & hearing MCDIARMID.R C Michigan, State of MCDIARMID.R C Spiegel & McDiarmid 8070328B Sps
- 8004150197 Finds antitiust info submitted 800403 acceptable for docketing & distribution TOALETORIA Antitrust & Indemnity Group 80/04/14 ip
- ---8004150200 Forwards antitiust info per application for amend of Licenses CPPR-118 / CPPR-119 BTAMPLEY, N L Mississippi Fower // Light Co 80/04/03 10pp
- 80041R0283 Forwards info ie South MS Electric Power Association, submitted per App L or 10CFR50 of Commission Rules of Practice info transmitted to offer opportunity to render advice re findings to be made by Commission W/o encl SHAPAR.H K Office or the Erecutive Legal Director 80/04/16 1p
- G Inspection reports. [E Bulletins > correspondence
- 8004090339 Forwards IE Bulletin 80~03. "Loss of Charcoal From Std Type II.Two-Inch, Tray Adsorber Cells" Action required O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/02/06
- B0040400B4 Forwards IE Insp Repts 50-416/80-01 ½ 50-417/80-01 on B00122-24 No noncompisance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/02/12 2pp
- --8004040125 IE Insp Repts 50-416/80-01 & 50-417/80-01 on B00122-24 No moncompliance noted Major areas inspected offsite warehouse insp 2 observation of safety-related activities Followup on IE bulletin, inspector 2 licensee identified items CANTRELL,F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch PAUSCH-J K Region 2, Atlanta, Dffice of the Director B0/02/11 App
- 8004040201 Forwards IE Repts 50-416/80-06 & 50-417/80-05 on 800129-31 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --9004040222 IE Insp Repts 50-416/80-06 % 50-417/80-05 on 800129-31 No noncompliance noted Major areas inspected safety-related pipe welding, reactor piessure boundary pipe handling & welding % followup on previously identified items HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch VANDOORN P K Region 2. Atlanta. Office of the Director 80/02/15 app
- 8004230070 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch, Tray Adsorber Cells " Insp revealed improvement in design/const or tray type charcoal adsorber cells DALE.L F Mississippi Power & Light Co 80/03/20 2pp
- 8004150491 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PDRV '> Block Valve " No specific action or response necessary D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080589 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 2pp
- B0041500BB Forwards IE info Notice B0-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/02 2pp
- 8004240268 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2nd

- 8004180268 forwards IC Circular 80~07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 2pp
- 8004110014 Forwards IE Bulletin 80-0/, "BWR Jet Pump Assembly Failure "
 No written response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
 200
- 8004230181 Forwards IE Builetin 74-03A "Longitudinal Held Defects in ASME SA-312 Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/04
- 8004180328 Forwards IC Bulletin 80-08. "Exam of Containment Liner Penetration Walds' Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004230522 Forwards IE Incp Rept 50-416/79-34-01 supplemental response clarifying previous response transmitted in 800414 ltr MCGAUGHY.J Mississippi Power & Light Co 80/04/15 2pp
- S Reportable occurrences. LERs & related correspondence
- 8004090[83 PND-1]-80-044 on 800319, site ambulance, en route to hosp w/laborer, heart attack victim, involved in accident Three of four occupants Xilled Status or laborer unknown HUNT, M D , RAUSCH, J K Region 2, Atlanta, Office of the Director 80/03/19 ip
- 8004170071 Forwards final rept for Potentially Reportable Deficiency 79/12 re Rosemount Model 510 DU master & slave trip units DAUE.L F Mississippi Power & Light Co 80/03/21 1p
- --8004170074 Final rept for Potentially Reportable Deficiency 79/12 re
 Model 510 DU master / slave trip units w/max current drain
 in ercoss of original specified value Deficient power
 supplies being replaced Details found in GE rept
 Mississippi Power & Light Co 80/03/21 ip
- 8004280517 Forwards interim deficiency rept re damaged instrumentation cables under reactor pressure vessel
 DALE, I F Mississippi Power & Light Co 80/03/31 1p
- --B004280522 Interim deficiency rept re damaged instrumentation cables under reactor pressure vessel During installation of control red drive assembly housings, insulation on 132 cables was damaged Cause under investigation # Mississipp: Power % Light Co 80/03/31 1p
- 8004280501 Forwards summary overview of deficiency PRD-B0/04 re effects of loss of site power on rod position indication & neutron monitoring indication Util is re-evaluating position on reportability of deficiency Final rept will be issued DALE, L.F. Hississippi Power & Light Co. 80/04/03 3pp
- 8004i50568 Forwards history & description of deficiency re to valve manifolds supplied by Dragon Valbe, Inc Deficiency improperly evaluated Re-evaluation underway, w/determination of potentially reportable deficiency by 800602 DALE:L F Mississippi Power & Light Co 80/04/04 2pp
- 8004280484 Confirms 800328 telcon concerning deficiency PRD-80/02 re defective elbow in control rod drive hydraulic sys Problem does not constitute reportable deficiency Elbow does not adversely affect plant safety Elbow will be replaced DALE, L. F. Mississippi Power & Light Co. 80/04/04 4pp
- 80042805%1 Deficiency rept re William Powell valves which may not meet seismic requirements of original purchase order Vendor re-analysis of valve natural frequencies still in progress Final rept will be submitted by 800813 DALE.L F Mississippi Power & Light Co 80/04/04 1p
- 8004280520 Deficiency rept re malfunctioning Limitorque motor operators Cause of deficiency apparently related to excessive threading of stem protector investigation continuing final rept should be submitted by 800728 DALE, t. F. Mississippi Power & Light Co. 80/04/11 ip
- 8004280610 Forwards interim rept for Potentially Reportable Deficiency 80/05 re electrical cable insulation damage sustained during cable publing process DALE, L.F. Mississippi Power & Light Co. 80/04/11 ip

- --8004280618 Interim rept for Potentially Reportable Deficiency 80/05 re cable damage substained during cable pulling process Nature of damage ranges from jacket chafing to insulation cut through to conductor Cables replaced * Mississippi Power & Light Co 80/04/11 1p
- 800428048: Second interim deficiency rept re faulty GE CR2940-U9203E hand switch in plant svc water sys Switch returned to GE for failure analysis Final rept will be forwarded on 800418 DALE, L. F. Mississippi Power & Light Co. 80/04/15 1p
- 8004280499 Submits status rept for deficiency PRD-80/07 re pipe hanger nonconformances Possibly caused by inadequate training & insp procedures Noncomformances are being evaluated DALE.L F Mississippi Power & Light Co 80/04/18 2pp
- 8004280606 Submits status rept for deficiency PDR-80/10 re unqualified cable insulation repairs in Rockbestos cable Cable splices were not involved Supplier conducting qualification tests on repair matls

 DALE, L. F. Mississippi Power & Light Co. 80/04/18 2pp
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

 A Application/construction stage documents & correspondence
- BOO4040031 Advises of issuance of NUREO-D58B. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSB.D F Division of Project Management
- 8004230413 Notifies of intent to invoke provision of Code Case N-245 re use of copper alloy castings meg from ASTM 861-76 & 862-76 maths specs for use in ASME III Class 3 component installation COUNSIL, W G , FEE, W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 ip
- F Security, medical, emergency & fire protection plans
- BD04080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004020408 Forwards "Feasibility Rept on Evacuation of Area Around Facility " COUNSIL:N 9 Northeast Utilities 80/03/31 2pp
- --8004020419 "Feasibility Rept on Evacuation of Area Around Facility "
 One oversize drawing enc!
 RDDGERS.L M Affiliation Unknown 80/03/31 58pp

H General correspondence

- 8004210048 Responds to 800307 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 10CFR20 & App 1 to 10CFR30 Environ info available in stated LPDR8 BALLARD, R L Environmental Projects Branch 1 80/04/01 2pp
- I Financial information
- 8004080557 Responds to NRC 800305 ltr re adequacies of cash flows to meet possible retrospective premium payments & forwards 1979 annual repts for CT Light & Power Co, Hartford Electric Light Co & Western MA Electric Co O'GUNNOR, L A Northeast Utilities 80/04/01 ip
- --8004080544 Annual Financial Rept 1979 * Connecticut Light & Power Co 80/03/14 24pp
- --8004080581 Annual Financial Rept 1979 * Hartford Electric Light Co 80/03/14 24pp
- --8004080590 Annual Financial Rept 1979
 * Western Massachusetts Electric Co 80/03/14 2ipp
- 8004150320 Forwards Annual Financial Repts 1979 BIBHOP, R W Northeast Utilities 80/04/02 1

- J. Insurance 4 indemnity information
- 8004160254 Forwards Endorsements 57 % 58 MAELU Policy NF-52 IFFLAND, R R Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 3pp
- O Inspection reports, IE Bulletins & correspondence
- 6004210003 Forwards IE Insp Rept 50-423/60-01 on 600213-15 No noncompliance noted CARLSCIR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 60/03/06 2pp
- --8004210011 IE Insp Rept 50-423/80-01 on 800213-15 No moncompliance noted Major areas inspected velder qualifications weld rod issue controls unresolved item status tours & interviews MCGAUGHY.R & Region 1, Philadelphia. Reactor Construction & Engineering Support Branch CERRE.A C Region 1, Philadelphia. Office of the Director 80/03/05 6pp
- 8004150279 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 | 1p
- 8004090074 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER.B H Region I, Philadelphia. Office of the Director 80/04/01 1p
- BOO4110156 Forwards IE Info Notice BD-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director BOO4002 ip
- BO04240319 Forwards IE Info Notice 80-14, 'Safety Suggestions From Employees' No action required ORIER, II H Region 1. Philadelphia, Office of the Director BO/04/02 1p
- BO041B0231 Forwards IT Circular BO-O7, "Problems W/HPCI Turbine Oil Sys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/04/03 ip
- 8004230433 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME SA-312. Type 304 Stainless Steel Pipe "Action required GRIER. B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 8004180201 Forwards IE Bulletin 80-08, "Fxam of Containment Liner Penetration Welds" Written response required GRIER, BH Region 1, Philadelphia, Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- B004040205 Forwards annual environ operating rept, "Monitoring Marine Environ or Long Island Sound' Requests rept be incorporated into proceedings for Unit 3 COUNSIL.N 9 Northeast Utilities 80/03/30 1p
- --B004040206 "Monitoring Marine Environ of Long Island Sound," annual rept, 1979
 * Northwest Utilities 80/03/31 400pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004100606 Ack receipt of 800225 interim deficiency rept re error in 3/8-inch orifice design Requests that final rept discuss planned or completed corrective actions CARLSON, R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/03/12 ip
- --8004100609 Interim deficiency rept 3/8-inch orifices shown on flow diagram failed to appear on fabrication isometric S&W isometrics also found deficient Couved by transfer of info Drawings will be corrected & orifices added by rework COUNSIL-K O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/02/23 2pp

- BOCKET 50-424 ALVIN W VOLTLE NUCLEAR PLANT, UNIT 1

 A Application on the time stage documents ' correspondence
- BOO4220042 Responds to Alberto memo re structural aspects of as-built foundation defails Enfects or erosion should not be significant re safety-related structures Structures should be analyzed for as-built onditions SCHAUER, F.P. Structural Engineering Branch 80/03/31 ip
- B004140335 Submits info requested by NRC 800327 telcon Descibes mod of acceptance citieria? justification for removal of fines by temporary well point dewatering sys
 DUTTON D Georgia Fower Co B0/04/0/ 2pp
- F Security, medical, emergenry & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Ropts Act GRIMES B K Emergency Preparedness Task Force B0/03/il 4pp
- G Adjudicatory correspondence
- 8004170292 Forwards supplemental Director's decision to 791012 denial of Georgians Against Nuclear Energy petition to reconsider util need for power Following review of submittals. Commission finds no besis for reconsideration BO/03/26 2pp DENTON.H R Gffice of Nuclear Reactor Regulation 80/03/26 2pp
- --8004170276 Supplemental Director's decision under 10CFR2 206
 Supplements 791012 denial of Georgians Against Nuclear
 Energy petition re suspension of CP & re-examination of need
 for power Review finds no basis for reconsiderations
 DENTON-N R Office of Nuclear Reactor Regulation 80/03/26
- 8004240145 Supplemental Director's Decision under 10CFR2 206 denying Georgians Against Nuclear Energy request to suspend licenses & institute new proceeding DENTON:H R Office of Nuclear Reactor Regulation 80/03/26 3pp
- Q Inspection reports. If Builetins & correspondence
- 8004070198 Responds to IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps "
 Supplier taking measures to prevent use of defective switches
 DUTTON D Georgia Power Co 80/01/25 6pp
- 8004040420 Act receipt of 1E Insp Repts 50-424/79-19 & 50-425/79-19 on 791227 No proprietary info DUTTONID Georgia Power Co 80/02/06 ip
- --B004040474 Forwards IE Insp Repts 50-424/79-19 % 50-425/79-19 on 791227 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/01/23 2pp
- ~~8004040430 IE insp Repts 50-424/79-19 & 50-425/79-19 on 791227 No noncompliance noted Major areas inspected soils & concrete lab & const status CONLON: TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch LENAHAN, J J Region 2, Atlanta, Office of the Director 60/01/22 4pp
- 8004090349 Forwards IE Bulletin 80-03, "Loss of Charcoal From 5td Type II. Two-Inch. Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2: Atlanta, Defice of the Director 80/02/06 2pp
- 8004020187 Ack receipt of IE Insp Repts 50-424/80-01 & 50-425/80-01 an 800130-0201 No proprietary info DUTTON.D Georgia Power Co 80/03/11 1p
- --8004020188 Forwards IE Insp Repts 50-424/60-01 & 50-425/80-01 on 800130-0201 No nencompliance nated BRYANT.J C Region 2: Atlanta, Reactor Construction & Engineering Support Branch 80/02/21 2pp

- --8004020194 If Insp Repts 50-424/60-01 / 50-425/80-01 on B00130-0201 No noncompliance noted Major areas inspected erosion of backrill, bldg foundation, concrete embuds, voids in concrete, reactor vessel orfinading / IE bulletins MUNT. If D Region 2. Atlanta, Reactor Construction & Engineering Support Branch MCFARLAND, C.R. Region 2. Atlanta, Office of the Director 80/02/21 5pp
- 8004106348 Responds to 1E Bulletin 80-03 No std Type II tray or drawer adsorber cells will be used Facility adsorber cells are vertical fill type b use perforated metal sheets welded not tiveted to filter casings

 DUTTON.D Georgia Power Co 80/03/20 ip
- 8004150521 Forwards IF Info Notice 80-12. "Instrument Failure Causes Opening of PORV A Block "alve " No specific action or response necessary O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/31
- 8004080624 Forwards IF Circular 80-05, "Emergency Diesel Generator Lubicating Gil Addition & Onsite Supply " No written response required G'REILLY, J.P. Region 2, Atlants, Office of the Director BO/04/01 2pp
- 8004150093 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAN Followers " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02
- 8004240265 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004240344 Ack receipt of IE Insp Repts 50-424/80-04 & 50-425/80-04, on 800311 No proprietary info DUT(ON D Georgia Power Co 80/04/02 ip
- --8004240352 Forwards IE Insp Repts 50-424/80-04 & 50-425/80-04 on 800311 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --8004240360 IE insp Repts 50-424/80-04 & 50-425/80-04 on 800311 No noncompliance noted Major areas inspected underlining of control bidg electrical tunnel 2 foundation, surface & subsurface drainage controls & slope stabilization measures CDLON, J E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch HARRIS, J R Region 2, Atlanta, Office of the Director 80/03/21 3pp
- 8004180903 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 0:1 Sys " No written response required 0'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004230173 Forwards IE Bulletin 79-03A "Longitudinal Held Defects in ASME 8A-312. Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180436 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 200
- S Reportable occurrences, LERs & related correspondence
- 8004020335 Forwards deficiency rept re voids in concrete placements on auxiliary bldg interior walls DUTTON,1) Georgia Power Co BO/03/03 2pp
- --8004020340 Deficiency rept re voids in concrete placements on auxiliary bldg interior walls No cause stated Vojds patched & wat cured for min of three days Tremie placement will be preplanned to allow better concrete flow in congested areas * Georgia Power Co 80/03/03 3pp
- 8004010349 Informs NRC that util is unable to establish definite completion date for final deficiency rept re dewatering & erosion of backfull Addl update & possible date for final rept will be provided by 800415
 BUTTON: D Georgia Power Co 80/03/24 2pp

- 8004020390 Interim deficiency rept re backfill dewatering & erasion No definite completion date established for final rept Addi update will be submitted by 600415 DUTTON.D Georgia Power Co 80/03/24 2pp
- 8004150427 Advises of discrepancy in 800307 deficiency rept re status of corrective action Corrective action had not been completed as of rept date for embed plate assemblies Final rept will be filed by 800530 DUTTON, D Georgia Power Co DUTTON, D Southern Co Services, Inc 80/04/10 2pp
- 8004280491 Significant deficiency rept re discrepancies in 791121 deficiency rept on embed plate assemblies Status of corrective action incorrect Should indicate that corrective action is incomplete Final rept to be submitted 800430 DUTTON, D Georgia Power Co 80/04/10 2pp
- DOCKET 50-425 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0589. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," previding guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004140336 Submits info requested by NRC 800327 telcon Descibes mod of acceptance criteria & justification for removal of fines by temporary well point demactering sys
 DUTTON, D Georgia Power Co 80/04/07 2pp
- F Security, medical, emergency & fire protection plans
- BOO40B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act
 GRIMES, B K Emergency Preparedness Task Force BO/03/11 4pp
- Q Adjudicatory correspondence
- B004170292 Forwards supplemental Director's decision to 791012 denial of Georgians Against Nuclear Energy petition to reconsider util need for pawer Following review of submittals. Commission finds no basis for reconsideration DENTON, HR Office of Nuclear Reactor Regulation 80/03/26 2pp
- --8004170296 Supplemental Director's decision under 10CFR2 206
 Supplements 791012 denial of Georgians Against Nuclear
 Energy petition re suspension of CP & re-examination of need
 for power Review finds no basis for reconsiderations
 DENTON, H R Office of Nuclear Reactor Regulation B0/03/26
 1000
- 8004240145 Supplemental Director's Decision under 10CFR2 206 denying Georgians Against Nuclear Energy request to suspend licenses & institute new proceeding DENION.H R Office of Nuclear Reactor Regulation 80/03/26 Jpp
- G Inspection reports, IE Bulletins & correspondence
- 800407019B Responds to IC Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Tamps " Supplier taking measures to prevent use of defective switches, DUTTON D Georgia Pawer Co 80/01/25 6pp
- 8004040420 Ack receipt of IC Insp Repts 50-424/77-19 & 50-425/79-19 on 791227 No proprietary info DUTTON, D Georgia Power Co 80/02/06 ip
- --8004040424 Forwards IE Insp Repts 50-424/79-19 & 50-425/79-19 on 791227 No noncompliance noted BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/01/23 2pp
- --8004040430 IE Insp Repts 50-424/79-19 % 50-425/79-19 on 791227 No noncompliance noted Major areas inspected soils & concrete lab & const status CONLIDATE Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch LENAHAN.J J Region 2. Atlanta. Office of the Director 80/01/22 4pp
- 8004090349 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II, Two-Inch, Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/04

- 8004020187 Ack receipt of IE Insp Repts 50-424/80-01 \$ 50-425/80-01 on 800130-0201 No proprietary into DUTTON, D. Georgia Power Co. 80,03/11 ip
- --8004020189 Forwards IE Inap Repts 50-424/80-01 % 50-425/80-01 on 800130-0201 No noncompliance noted BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/21 2pp
- --B004020194 IE Insp Repts 50-424/B0-01 ' 50-425/B0-01 on 800130-0201 No noncompliance noted flajor areas inspected erosion of backfill.bldg foundation.concrete embeds, voids in concrete, reactor vessel offloading & IE bulletins
 HUNT, N D Region 2, Atlanta, Reactor Construction & Engineering Support Branch MCFARLAND, C R Region 2, Atlanta, Office of the Director B0/02/21 5pp
- 800410034B Responds to IF Bulletin 80-03 No std Type II tray or drawer adsorber cells will be used Facility adsorber cells are vertical fill type 2 use perforated metal sheets welded, not riveted, to filter casings

 DUTTON.D Georgia Power Co 80/03/20 ip
- 8004;5052; Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REFLLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31 2pg
- 8004080624 Forwards IE Circular 80-05, "Emergency Dipsel Generator Lubricating Oil Addition 2 Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01
- 8004150093 Forwards 1E info Notice 80-13, "GE Type SDM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240265 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2nn
- 8004240344 Ack receipt of IE Insp Repts 50-424/80-04 & 50-425/80-04, on 800311 No proprietary info DUTTON,D Georgia Power Co 80/04/02 ip
- --8004240352 Forwards IE Insp Repts 50-424/80-04 & 50-425/80-04 on BOO311 No noncomptiance noted MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch BO/03/24 2pp
- --8004240360 IE Insp Repts 50-424/80-04 & 50-425/80-04 on 800311 No nancompliance noted Major areas inspected underlining of control bldg electrical tunnel 2 foundation.surface & subsurface of cainage controls & slope stabilization measures COLON. J E Region 2. Atlants. Reactor Construction & Engineering Support Branch HARRIS. J R Region 2. Atlanta. Office of the Director 80/03/21 3pp
- 8004180303 Forwards IE Circular 80-07, "Problems N/HPC1 Turbine Dil Sys " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004230173 Forwards 1E Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/04 ib
- 8004180436 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07
- S Reportable occurrences, LERs & related correspondence
- 8004020335 Forwards deficiency rept re voids in concrete placements on auxiliary bidg interior walls
 DUTTON.D Georgia Pawer Ca 80/03/03 2pp
- --8004020340 Deficiency tepf re voids in concrete placements on auxiliary bldg interior walls No cause stated Voids patched & wet cured for min of three days Tremie placement will be preplanned to allow better concrete flow in congested areas & Georgia Power Co 60/03/03 3pp

- 3004010349 Informs NRC that util is unable to establish definite completion date for final deficiency rept re dewatering terosion of backfull Addl update & possible date for final rept will be provided by 800419
 DUTTON.D Georgia Power Co. 80/03/24 2pp
- 3004020370 Interim deficiency rept re backfill dewatering & erosion No definite completion (ate astablished for final rept Add) update will be submitted by 800415 DUTTON.D Georgia Fower Co 80/03/24 2pp
- ROO4:50421 Deficiency rept re erosion under cable tunnel decumented in IE Insp Rept 50-425/80-05 Repairs completed & backfilling activities resumed Complete rept will be filed by 800430 DUTTON.D Georgia Power Co 80/04/10 2pp
- BOO4150427 Advises of discrepancy in 800307 deficiency rept re status of corrective action Corrective action had not been completed as of rept date for embed plate assemblies Final rept will be filed by 800530 DUTTON, D Georgia Power Co DUTTON, D Southern Co Services, Inc 80/04/10 2pp
- BOO428049i Significant deficiency rept re discrepancies in 791121 deficiency rept on embed plate assemblies Status of corrective action incorrect Should indicate that corrective action is incomplete Final rept to be submitted 800430 DUTTON, D. Georgia Power Co. 80/04/10. Zpp
- JOCKET 50-427 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 4
 - Application/construction stage documents & correspondence
- BOO4220042 Responds to 800206 memo re structural aspects of as-built foundation details Effects of erosion should not be significant re safety-related structures Structures should be analyzed for as-built conditions
 ECHAUER, FP Structural Engineering Branch 80/03/31 1p
- DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR
- Periodic operating reports & related correspondence
- 3004070328 Forwards "Annual Rept of Operations, 1979 "
 KROES,R J Catifornia, Univ o+, Santa Barbara 80/03/31 Ip
- --8004070327 'Annual Rept of Operations, 1977 " PROFIG.A & California, Univ. of, Santa Barbara 80/03/31 App
- DOCKET 50-434 SURRY PONER STATION, UNIT 3
- . Application/construction stage documents & correspondence
- 3004150249 Notification of ACRS Subcommittee on Surry Nuclear Station B00123 meeting in Washington.DC to continue review of steam generator replacement program HOYLE, JC ACRS Advisory Committee on Reactor Safeguards 79/12/20 Spp
- IDCKET 50-495 SURRY PONER STATION, UNIT 4
- , Application/construction stage documents & correspondence
- 3004150249 Notification of ACRS Subcommittee on Surry Nuclear Station 800123 meeting in Washington.DC to continue review of steam generator replacement program HDYLE.J C ACRS Advisory Committee on Reactor Safeguards 79/12/20 3pp
- MICKET STN-50-437 FLOATING NUCLEAR PLANT
 - Application/construction stage documents & correspondence
- 3004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re-methods for compliance ROSS,D F Division of Project Management 80/02/05 7pp

- G Adjudicatory correspondence
- 8004090021 Advises that NRC ½ applicant met w/ACRS to discuss applicant proposed core ladie design Views will be reflected in written ltrs NRC reorganization may affect completion of technical review SOHINKI/S % Hearing Branch 3 80/03/31 2pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK, V Office of the Executive Director for Operations 80/04/02 34pp
- 8004290231 Notice of withdrawl from proceeding Certificate of Svc encl STAENBERG, N R Regulations Division 80/04/25 3pp
- O Inspection reports. IE Bulletina & correspondence
- 8004090360 Forwards IE Bulletin 80~03, 'Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required D'REILLY.∪ P Region 2. Atlanta, Office of the Director 80/02/06 200
- 8004150550 Forwards IE Info Notice 80-12, "instrument Failure Causes Opening of FORV & Block Valve" No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31 2pp
- 8004080&58 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required O'REILLY.JP Region 2, Atlanta, Orfice of the Director 80/04/01 200
- 8004150107 Forwards IE Info Notice 80-13, "GE Type SRM Control Switches Defective CAM Followers" No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240238 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/04/02 to
- 800418D382 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director BO/04/03 ip
- 8004230102 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/04
- 6004180476 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Rogion 2, Atlanta, Office of the Director 80/04/07
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004240201 Forwards License SNM-1865, authorizing receipt possession.
 insp & storage of U-235 fuol assemblies & max of 100 fuel
 rods License also allows packaging & shipping for transfer
 Safety evaluation encl
 PAGE, R G Uranium Recovery Licensing Branch BO/01/30 2pp.
- --8004240207 License SNM-1865, authorizing receipt, possession, insp, storage & transfer of max of 2.110 kg u-235 fuel assemblies & 100 fuel rods Licensee is exempt from matls provisions of 100FR70 24 PAGE, R G Uranium Recovery Licensing Branch 80/01/30 2pp
- --8004240217 Safety evaluation re util application for license to receive max 2.110 kg U-235 fuel assemblies & 100 fuel rods License should be granted w/exemption from 100FR70 24 CROM,N T . DELANEY,J L Uranium Recovery Licensing Branch, 80/01/30 2pp
- 8004040031 Advises of issuance of NUREQ-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance ro methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp

DOCKETED ITEMS

- B004040017 Submits addl guidance to NUREG-OSBB, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- 8004280308 Forwards request for addl info re power sys, for OL application review Requests date that response will be available for review PARR.O D Light Mater Reactors Branch 3 80/03/19 25pp
- 8004110046 Requests addl info on changes & studies proposed in App F of 791203 response to NRC 791025 10CFR50 54 requests redesign adequacy of B&W NSSS utilizing once-through steam generators
 PARR.O D Light Water Reactors Branch 3 80/03/25 5pp
- F Security, medical, emergency & fire protection plans
- BOO40B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 1tr.has been postponed pending GAD clearance under Federal Repts Act
 ORIMES.B K Emergency Preparadness Task Force 80/03/11 4pp
- 8004070052 Forwards request for info re util 790301 safeguards contingency plan & 790901 Revision 1 Encl withheld (ref 10CFR2 790) PARR.O D Light Water Reactors Branch 3 80/03/14 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8004090352 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type 11.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06 200
- 8004090388 Forwards IE lnsp Repts 50-438/80-03 & 50-439/80-03 on 800206-08 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004090392 IE Insp Repts 50-438/80-03 & 50-439/80-03 on 800206-08 No noncompliance noted Major areas inspected containment prestressing GA/GC controls, work performance, const status & quality records CONLON, T.E., LENAHAN, J.J. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 4pp
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC & util in Atlanta, CA to discuss accuracy of written repts provided to IE NRC will provide overall avaluation of util handling of deficiences identified by QA program O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/12 2pp
- 8004070130 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~438/80~01 & 50-439/80~01 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/03/17 2pp
- --8004070158 Forwards IE Insp Repts 50-438/80-01 & 50-439/80-01 on 800108-11 & notice of violation BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/02/11 2pp
- --8004070168 Notice of violation from insp on 800108-11 * Region 2, Atlanta, Office of the Director 80/02/11, 1p
- ---B004070177 IE Insp Repts 50-438/80-01 & 50-439/80-01 on B00108-11 Noncompliance noted failure to follow procedure for visual insp of welds HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch VANDOORN.P K Region 2. Atlanta, Office of the Director B0/02/01 4pp
- 8004210178 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II, Two-Inch. Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS:L M Tennessee Valley Authority 80/03/21 4pp.
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches. At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS.L M Tennessee Valley Authority 80/09/28. 2pp

- 8004150527 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 20p
- 8004080636 Forwards IE Circular 80-08, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 2nn
- 8004150097 Forwards IE Info Notice 80-13, "GE Type SDM Control Switches Defective CAM Followers " No specific action of response required D'REICLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004240274 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- B004180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004230142 Forwards IE Bulletin 77-03A "Longitudinal Wald Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- B004180445 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07 3no
- 8004270379 Requests approval of ASME Code Cases N=234 & N=235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLO, L. M. Tonnessee Valley Authority 80/04/23 3pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004020459 Part 21 rept on 800228, B&W made telephone rept re defect concerning potentially overstressed supports on reactor coolant letdown coolers due to inadequate support design Corrective action redesign of support stand TAYLUR.J H Babcock & Wilcox Co 80/03/03 &pp
- 8004080563 PNO-II-80-045 on 800319, util notified Region 2 of B&W notification re-potential for failure of main steam lines in event of feedwater overflow of steam generators. Region 2 investigating generic aspects WRIOHI, W. CONTRELL.F. S. Region 2, Atlanta, Office of the Director 80/03/19 ip
- BOO4190209 Forwards deficiency mept me support braces for cooling water supply header used for seactor bldg coolers being incongrous w/seismic analysis
 TAYLDR.J H Babcock & Wilcox Co BO/03/24 ip
- TATEDATO II BABCOCK & MITCOL CO BO703724 IP
- ---9004150210 Deficiency rept re support braces for cooling water supply header used for reactor bldg coolers being incongruous \(\psi \) seismic analysis Cause unstated Braces returned to vendor for mod to conform to seismic analysis design \(\psi \) Babcock & Wilcox Co \(\text{BO/O3/24} \) 3pp
- 8004300570 Part 21 rept re support braces for reactor bldg coolers that are nonconservative w/respect to brace design assumed in seismic analysis Support braces are to be modified to conform to seismic design
 TAYLOR, J H Babcock & Wilcox Co 80/03/24 5pp
- 8004020395 Seventh interim deficiency rept re expansion anchors not passing qualification tests Final rept MILLS.L M Tennessee Valley Authority 80/03/25 1p
- 8004010397 Interim deficiency rept re potential overstress condition in letdown cooler supports Nozzle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys HOWELL, B H Consumers Power Co 80/03/27 ip
- r-8004010404 forwards add1 info to Part 21 rept re potentially overstrassed supports on reactor coolant letdown coolers at facilities under const by B&W TAYLOR, J H Babcock & Wilcox Co 80/03/03, App

- BOO4020414 Forwards interin dericiency rept re potential defects in WKM central valves in decay heat cooler outlet Next rept will be submitted by Boo514
 MILLS-L M Tennessee Valley Authority 80/03/27 ip
- --6004020416 Interim deficiency rept ie potential defects in WKM central valves in decay heat cooler outlet B&W has begun investigation to determine extent & cause of defects Tennessee Valley Authority 80/03/27 ip
- 8004020431 Forwards second interim deficiency mept re makeup & purification / decay heat removal pumps u/damaged thermocouple wiring Neit rept will be submitted by 800508 MILLS-L H Tennessee Valley Authority 80/03/27 ip
- --8004020436 Second interim deficiency lept re makeup & purification & decay heat removal pump motors w/damaged thermotouple uiring Neeting planned w/NBW to discuss scheduling of repairs & testing of pump motors * Tennessee Vailey Authority 80/03/27 ip
- 8004040377 Forwards final deficiency rept re makeup & purification letdown cooler supports
 MILLS.L M Tennessee Valley Authority 80/03/27 ip
- --8004040371 Final deficiency rept agreement reached by AE & vendors that combination of AE support platform & cooler support bracket would result in overstressed condition in lowest of three cooler supports Completian of support mode expected 800930

 Tennessee Valley Authority 80/03/27 1p
- 8004020417 Forwards interim deficiency rept re violation of INRYCD field installation procedures Next rept will be submitted by 800618
 - MILLB.L M Tennessee Valley Authority 80/03/28 1p
- --8004020421 Interim deficiency rept re violation of INRYCO field installation procedures Revisions to GC procedures have been recommended & new inspector instructed in following Tennessee Valley Authority 80/03/28 ip
- 8004160291 Forwards final deficiency rept re voids in primary containment dome
 MILLS, L M Tennessee Valley Authority 80/03/31 1p
- --B004160396 Final deficiency rept re voids in primary containment domo Suspect areas result from lack of bond between liner plate & concrete Holes in liner plate repaired MILLS.L M Tennessee Valley Authority 80/03/31 ip
- 8004280432 Forwards second interim deficiency rept re defective seat ring seal welds on Borg-Warner valves Final rept will be submitted by 800428 MILLS.L M Tennessee Valley Authority 80/04/07 ip
- --8004280436 Second intersm deficiency rept re defective seat ring seal welds on Borg-Harner valves Util & manufacturer have established required acceptance criteria for welds Insp of valves is in progress Results will be in final rept # Tennessee Valley Authority 80/04/07 tp
- BOO4220420 Notifies that correct date of initial notification on NRC 1070 was 790928 Repts dtd 791026,1211 2 BOO331 erroneously stated date as 790528 MILLS,L M Tennessee Valley Authority BO/04/15 ip
- BO04220541 Forwards final deficiency rept re Borg-Warner three-inch motor operated gate valves MILLS,L N Tennessee Valley Authority BO/04/16 1p
- --8004220546 Final deficiency rept re Norg-Narner three-inch motor operated gate valves Gate valve failed to close fully when actuated under operating conditions during recent test program Borg-Harner is redesigning std gate valve.

 * Tennessee Valley Authority 80/04/16 ip
- 8004280438 Forwards final deficiency rept re Borg-Warner 3-inch motor operated gate valves
 MILLB.L.M Tennessee Valley Authority 80/04/16 ip
- ~-8004280442 Final deficiency rept re Horg-Warner 3-inch motor operated gate valves Binding will be corrected by mod of valves * Tennessee Valley Authority 80/04/16 ip
- 8004230380 Forwards final deficiency rept re header supports for HILLS, L. H. Tennessee Valley Authority 80/04/17 ip

- --8004230382 Final deficiency rept re header supports for reactor bldg coolers Manufacturer performed seismic analysis & discovered braces fabricated from box cross section tubing Braces returned for mod

 * Tennessee Valley Authority 80/04/17 1p
- B004230503 Forwards first interim deficiency rept re Intl Telaphone & Telegraph actuator for Ruskin dampers Next rept will be submitted by B00813
 MILLS,L M Tennessee Valley Authority 80/04/17 ip
- ---8004230507 First interim deficiency rept re Intl Telephone & Telegraph actuator for Ruskin dampers Upon receipt of Intl Telephone & Telegraph actuator data, Ruskin will provide corrective procedures to util

 * Tennessee Valley Authority 80/04/17 ip
- 8004230527 Forwards first interim deficiency rept re Intl Telephone & Telegraph controls for American Warming & Ventilation dampers Nect rept will be submitted by 800814 MILLS.L M Tennessee Valley Authority 80/04/17 ip
- --8004230529 First interim deficiency rept re Intl Telephone & Telegraph controls for American & Warming & Ventilation dampers Upon receipt of Intl Telephone & Tetegraph actuator data-American Warming & Ventilation will provide corrective procedures * Tennessee Valley Authority 80/04/17 1p
- 8004240384 Forwards first interim deficiency rept re failure of main steam lines MILLS.i M Tennessee Valley Authority 80/04/17 1p
- --8004240389 First interim deficiency rept ro failure of main steam lines Caused by main feedwater overfill Deficiency undergoing evaluation Util 8 B&W working to incorporate mitigative instrumentation into facilities

 * Tennessee Valley Authority 80/04/17 1p
- 8004280516 Forwards first interim deficiency rept re defective springs used in ITT General Control actuators supplied to Ruskin MRLLS,L M Tennessee Valley Authority 80/04/17 ip
- --B0042B0524 First interim deficiency rept re defective springs used in ITT General Control actuators supplied to Ruskin Bpring does not possess designed strength & forco Ruskin uill inform util of corrective actions, pending receipt of accurate data

 * Yennessee Valley Authority B0/04/17 ip
- 8004250380 Forwards final deficiency rept to TPIPE computer user failure to check frequency analysis of piping sys MILLS, L. M. Tennessee Valley Authority 80/04/21 ip
- --8004250384 Final deficiency rept re TPIPE computer user failure to check frequency analysis No erroneous design info has resulted frogram mod to stop any program run when frequency analysis not converging # Tennessee Valley Authority 80/04/21 ip
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D P Division of Project Management
- 8004040017 Submits add1 guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance RDSS.D F Division of Project Management 80/02/21 3pp
- 800428030B Forwards request for add1 info re power sys.for OL application review Requests date that response will be available for review PARR.O D Light Water Reactors Branch 3 80/03/19 25pp
- B004110046 Requests addl info on changes & studies proposed in App F of 791203 response to NRC 791025 10CFR50 54 requests reducing adequacy of BBM NSSS utilizing once-through steam generators PARR.O D Light Water Reactors Branch 3 80/03/25 5pp

- F Security, medical, emergency & fire protection plans
- B004080077 Advises that submittal date for evacuation time estimates requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- B004070052 Forwards request for info re util 770301 safeguards contingency plan & 790901 Revisson 1 Encl withheld (ref 100FR2 790) PARR.O D Light Water Reactors Branch 3 80/03/14 2pp
- Q Inspection reports: IC Bulletins & correspondence
- 8004090352 Forwards IE Bulietin 80-03, "Loss of Charcoal From Std Type II, Two-Inch, Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/04
- 8004090388 Forwards IE Insp Repts 30-438/80-03 & 50-439/80-03 on 800204-08 No nuncompliance noted BRYANT, J C Region 2, Atlante, Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004070392 IE Insp Repts 50-438/80-03 & 50-437/80-03 on 800206-08 No noncompliance noted Major areas inspected containment prestressing GA/GC controls, work performance, const status & quality records CONLON,TE , LENAHAN, J Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 4pp
- BO04090025 Confirms BO0310 telcon arranging B00320 meeting between NRC butil in Atlanta, GA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by GA program CAREILLY, J P Region 2, Atlanta, Office of the Director B0/03/12
- 8004070150 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-01 &
- --8004070158 Forwards IE Insp Ropts 50-438/80-01 & 50-439/80-01 on 800108-11 & notice of violation BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/11 2pp
- --8004070168 Notice of violation from insp on 800108-1: * Region 2, Atlanta, Office of the Director 80/0 80/02/11 ip
- --8004070177 IE Insp Repts 50-438/80-01 & 50-439/80-01 on 800108-11 Noncompilance noted failure to follow procedure for visual insp of welds HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch VANDOURN.P K Region 2. Atlanta, Office of the Director 80/02/01 4pp
- 8004210178 Forwards response to IE Bulletin 80-03. "Loss of Charcoal from Std Type II. Two-Inch. Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists, MILLS.L M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS,L M. Tennessee Valley Authority 80/03/28 2pp
- 8004i50527 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080436 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01
- 8004150097 Forwards IE Info Notice 80-13, "OE Type 98M Control Switches Defective CAM Followers " No specific action or response required
 O'REILLY, J. F. Region 2, Atlanta, Office of the Director 60/04/02

- 8004240274 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required D'REILLY. J P Region 2. Atlanta. Office of the Director 80/04/02 300
- 8004180275 Forwards 1E Circular 80-07. "Problems W/HPCI Turbine Gil Sys " No written response required D'REILLY.J P Region 2, Atlanta, Office of the Director
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME SA-312.Type 304 Stainless Steel Pipe" Action required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/04/0 B0/04/04
- 8004180449 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004270377 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vossels Expeditious approval is necessary for use of code cases in forthcoming preservice insp MILLS, L M Tennessee Valley Authority 60/04/23 3pp
- S Reportable occurrences. LERs & related correspondence
- 8004020457 Part 21 rept on 800228,8&W made telephone rept re defect concerning potentially overstressed supports on reactor coolant latdown coolers due to inadequate support design Corrective action redesign of support stand TAYLOR,J H Babcock & Wilcox Co 80/03/03 6pp
- BO04080563 PNO-II-B0-045 on 800319, util notified Region 2 of B&W notification repotential for failure of main steam lines in event of feedwater overflow of steam generators Region 2 investigating generic aspects
 WRIGHT.R W., CONTRELL.F S Region 2, Atlanta, Office of the investigating
 WRIGHT,R W / CONTRESS
 80/03/19 1 p
- BOO4150209 Forwards deficiency rept re support braces for cooling water supply header used for reactor bldg coolers being incongrous w/seismic analysis
 TAYLOR, J. H. Babcock & Wilcox Co. BD/03/24 lp
- --8004150210 Deficiency rept re support braces for cooling water supply header used for reactor bldg coolers being incongluous w/ seismic analysis Cause unstated Braces returned to vendor for mod to conform to seismic analysis design # Babcock & Wilcox Co 80/03/24 3op
- 8004300370 Part 21 rept re support braces for reactor bldg coolers that are nonconservative w/respect to brace design assumed in seismic analysis Support braces are to be modified to conform to seismic design
 TAYLOR.J H Babcock & Wilcox Co 80/03/24 Spp
- 8004020395 Seventh interim deficiency rept re expansion anchors not passing qualification tests final rept
 MILLS,L M Tennessee Valley Authority 80/03/25 ip
- 8004010397 Interim deficiency tept re potential overstress condition in letdown cooler supports No.11e loads will be analyted for effects on support structure to determine if mods are required to cooler support sys HOWELLIS H Consumers Power Co 80/03/27
- --8004010404 Forwards addi into to Part 21 rept re potentially overstressed supports on reactor coolant letdown coolers a facilities under const by B%H
 TAYLOR, J H Babcock & Wilcox Co 80/03/03 App
- 8004020414 Forwards interim deficiency rept re potential defects in WKM central valyes in decay heat cooler outlet Next rept will be submitted by 800514
 MILLS.L M Tennessee Valley Authority 80/03/27 ip
- --8004020416 Interim deficiency rept re potential defects in WKM central valves in decay heat cooler outlet BMN has begun investigation to determine extent % cause of defects # Tennessee Valley Authority 80/03/27 ip
- 8004020431 Forwards second interim deficiency rept re makeup & purification & decay heat removal pumps w/damaged thermocouple warning Next rept will be submitted by 800508 MILLS,L // Tennessee Valley Authority 80/03/27 ip

- --8004020436 Second site im dericiency Lept Le makeup & purification & decay heat removal pump motors w/damaged thermocouple wiring fleeting planned w/860 to discuss scheduling of repairs & testing of pump motors # Tennessee Valley Authority 80/03/27 ip
- 8004040377 Forwards final deficiency tept re makeup & purification latdoum cooler supports
 MILLS.L M Tennessee Valley Authority 80/03/27 ip
- --8004040391 Final deficiency rept agreement reached by AE & vendors that combination of AE support platform & cooler support bracket would result in overstrassed condition in lowest of three cooler supports Completion of support mods expected 800930 * Tannessee Valley Authority 80/03/27 1p
- 8004020417 Forwards anteriam defactioncy tept re violation of INRYCO field installation procedures Next rept will be submitted by 800618 MILLS, L M Tennessee Valley Authority 80/03/28
- --8004020421 Interim deficiency rept re violation of INRYCO field installation procedures Revisions to QC procedures have been recommended & new inspector instructed in following procedures
 - Tennessee Valley Authority 80/03/28 1p
- 8004280402 Forwards second interim deficiency rept re defective seat ring seal welds on Borg-Warner valves Final rept will be submitted by 800428 MILLS.L M Tennessee Valley Authority 80/04/07 1p
- --8004280436 Second interim deficiency rept re defective seat ring seal welds on Borg-Warner valves Util & manufacturer have established required acceptance criteria for welds insp of valves is in progress Results will be in final rept # Tennessee Valley Authority 80/04/07 ip
- 8004220541 Forwards final deficiency rept re Borg-Harner three-inch motor operated gate valves MILLS.L M Tennessee Valley Authority 80/04/16 ip
- --8004220546 Final deficiency tept re Borg-Warner three-inch motor operated gate valves Gate valve failed to close fully when actuated under operating conditions during recent test program Borg-Warner is redesigning std gate valve # Tennessee Valley Authority 80/04/16 ip
- 8004280438 Forwards final deficiency tept re Borg-Warner 3-inch motor operated gate values
 MILLS.L M Tennessee Valley Authority 80/04/16 ip
- --8004280442 Final deficiency rept re Borg-Warner 3-inch motor operated gate valves Binding will be corrected by mod of valves
 * Tennessee Valley Authority 80/04/16 1p
- 8004230380 Forwards final deficiency rept re header supports for reactor bidg coolers MILLB.L M Tennessee Valley Authority 80/04/17 ip
- --8004230382 Final deficiency rept re header supports for reactor bldg coolers Manufacturer performed seismac analysis & discovered braces fabricated from box cross section tubing Braces returned for mod * Tennessee Valley Authority 80/04/17 1p
- 8004230503 Forwards first interim deficiency rept re Inti Talephone & Telegraph actuator for Ruskin dampers Next rept will be submitted by 800813

 MILLS:L 4 Tennessee Valley Authority 80/04/17 ip
- --8004230507 First interim deficiency rept re Intl Telephone & Telegraph actuator for Ruskin dampers Upon receipt of Intl Telephone & Telegraph actuator data; Ruskin will provide corrective procedures to util # Tennessee Valley Authority 60/04/17 ip
- B004230527 Forwards first interim deficiency rept re Intl Telephone & Telegraph controls for American Warming & Ventilation danpers Nest rept will be submitted by B00014 MILLS:L H Tennessee Valley Authority B0/04/17 ip
- --8004230529 First interim deficiency rept re intl Telephone & Telegraph controls for American & Warming & Ventilation dampers Upon receipt of intl Telephone > Telegraph actuator data, American Warming & Ventilation will provide corrective procedures * Tennessee Vallay Authority 80/04/17 ip

ŕ

- 8004240386 Forwards first interim deficiency rept re failure of main steam lines MILLS:L M - Tennessee Valley Authority - 80/04/17
- --8004240388 First interim deficiency rept re failure of main steam lines Caused by main feedwater overfill Deficiency undergoing evaluation Util 2 88W working to incorporate mitigative instrumentation into facilities * Tennessee Valley Authority 80/04/17 ip
- 8004280516 Forwards first interim deficiency rept re défective springs used in ITT General Control actuators supplied to Ruskin MILLS.L M Tennessee Valley Authority 80/04/17 ip
- --8004280524 First interim deficiency rept re defective springs used in ITT General Control actuators supplied to Ruskin Spring does not possess designed strength & force Ruskin will inform util of corrective actions, pending receipt of accurate data * Tennessee Valley Authority 80/04/17 ip
- 8004250380 Forwards final deficiency rept re TPIPE computer user failure to check frequency analysis of piping sys
 MILLS.L M Tennessee Valley Authority 80/04/21 1p
- --8004250384 Final deficiency rept re TPIPE computer user failure to check frequency analysis No erroneous design info has resulted Program and to stop any program run when frequency analysis not converging

 * Tennessee Valley Authority 80/04/21 ip
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Davision of Project Hanagement 80/02/05 7pp
- 8004070041 Forwards NRC 800128 & 0211 ltrs to GE re mods to BHR control rod drive sys re elimination of clacking in return line nozzle Mods should not be performed until issuance of NUREO-RUBENSTEIN, L. S. Light Water Reactors Branch 4 80/03/11 200
- 8004100301 Notification of 800403 meeting w/GE in Bethesda, MD to discuss BWR & safety relief valves mfg by 0 Dickens & Co & supplied by GE to facilities
 HENDERSON, J B Division of Reactor Construction Inspection 80/03/13 2pp
- F Security, medical, emergency & fire protection plans
- BOO40B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO cleanance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt Improvement in radiological emergency planning & FEMA re pro improvement in radiological emergency planning & preparedness, distributed as Board notification GOSBICK, L V Office of the Elecutive Director for Operations 80/04/02 34pp
- H General correspondence
- BOO4240364 Responds to 791129 ltr requesting review of DD Wilt concerns re licensee const practices & NRC insp approach Const defects must be corrected prior to OL issuance NRC sampling insp program assures compliance w/NRC requirements DIRCKB:N J Office of the Frecutive Director for Operations 80/03/05 3pp Зрр
- G Inspection reports. IE Bulletins & correspondence
- 8004110150 Forwards IE Insp Repts 50-440/80-01 & 50-441/80-01 on 800123-25 & notice of violation FIGRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/26 2pp
- --8004110152 Natice of violation from insp on 800123-25
 * Region 3, Chicago, Office of the Director 80/02/20 ip

- --8004110176 IE Insp Repts 50-440/80-01 & 50-441/80-01 on 800123-25 Noncompliance nated failure to qualify inspector personnel records
 - HILLIAMB,C C , KONKLIN,JE , KEY,W J Region 3, Chicago. Office of the Director 80/02/20 10pp
- 8004100125 Forwards IE Info Notice 80-08. "States Co Silding Link Electrical Terminal Block " No specific action or response KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/07
- 8004150165 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary Region 3. Chicago, Office of the Director BO/03/31
- 8004080698 Forwards IE Circular 80-05, "Emargency Dissel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/0 B0/04/01
- 8004150034 Forwards IE Info Notice 80-13, "GE Type 98M Control Switches Defective CAM Followers " No specific action or response required

 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/02
- 800418003B Forwards attachments to LE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 8003D5 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220118 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220347 Forwards IE Circular 80-07, "Problems W/HPC! Turbine Gil Sys "No written response required. KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/03
- 8004110033 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/04/07
- 8004230201 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07
- 8004220139 Forwards IE Bulletin 80-00, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/09
- 8, Reportable occurrences. LERs & related correspondence
- 8004090167 Ack receipt of 800229 final deficiency rept re omission of Class B fill waterstops
 Class B fill waterstops
 FIGNELLI, O Region 3, Chicago, Reactor Construction & Engineering
 Bupport Branch 80/03/17 ip
- 8004230353 Final deficiency rept re cracks & tears in bottom of steel encls of ITE switchgear caused by seismic environ Holes drilled & welds run along bend line Min of three switchgear frames will be boited together for future shipments
 DAVIDSON, D R Cleveland Electric Illuminating Co 80/04/15 3pp
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588; "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment:" providing guidance re methods for compliance RDS8.D F, Division of Project Management 80/02/05 7pp
- 8004070041 Forwards NRC 800128 & 0211 ltrs to GE re mods to BWR control rod drive sys re elimination of cracking in return line nozzle Mods should not be performed until issuance of NUREQ-RUBENSTEIN.L B Light Water Reactors Branch 4 80/03/11 2pp

- 8004100301 Notification of 800403 meeting w/OE in Bethesda.MD to discuss BMR 4 safety relief valves mrg by G Dickens 2 Co & supplied by GE to facilities Division of Reactor Construction Inspection HENDERSON, J B
- F Security, medical, emergency & rire protection plans
- BOO4080077 Advises that submittel date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- 8004240364 Responds to 791129 ltr requesting review of DD Wilt concerns re licensee const practices \$ NRC insplaymoach Const defects must be corrected prior to OL issuance NRC sampling insp program assures compliance w/NRC requirements DIRCKS:W J Office of the Executive Director for Operations 80/03/05 3pp
- Q Inspection reports, IF Bulletins & correspondence
- 8004110150 Forwards IE Insp Repts 50-440/80-01 & 50-441/80-01 on BO0123-25 & notice of violation
 FIGRELLI.G Region 3. Chicago, Reactor Construction & Engineering
 Support Branch 80/02/26 2pp
- --8004110152 Notice of violation from insp on 800123-25 * Region 3. Chicago, Office of the Director 80/0 80/02/20 10
- --8004110176 IE Insp Repts 50-440/80-01 & 50-441/80-01 on 800123-25 Noncompliance noted failure to qualify inspector personnel records WILLIAMS, C.C., KONKLIN, J.E., KEY, W.J. Region 3, Chicago, Office of the Director 80/02/20 10pp
- 8004100125 Forwards IE Info Notice 80-08: "States Co Sliding Link Electrical Terminal Block " No specific action or response required
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07
- 8004190165 Forwards IF Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/31
- 8004080698 Forwards IE Circular 80-05, "Emergancy Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLERJ G Region 3, Chicago, Office of the Director 80/04/4 R0/04/01
- 8004150034 Forwards IE Info Notice 80-13; "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- BOO4180038 Forwards attachments to IE Circular 80-03, "Protection From Toxic Qas Hazards," inadvertently omitted from 800306 transmittal MEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220118 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required KEPPLER, J & Region 3. Chicago. Office of the Director 80/04/0 80/04/02
- 8004220347 Forwards IE Circular 80-07, "Problems W/HPC! Turbins Dil Sys " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director

- 8004110033 Forwards 1F Bulletin PO-07, "RWR Jet Pump Assembly Failure" No written response required KEPPLER, J.G. Region 3. Chicago, Office of the Director 80/04/07
- 8004230201 Forwards IE Sulletin 79-03A "Longitudinal Weld Defects in ASME 6A-312 Type 303 Signless Steel Pipe " Action required KEPPLER, J. 0 Region 3 Chicago Office of the Director 80/04/07 to
- 8004220139 Forwards IE Bulletin 80-08. 'Exam of Containment Liner Fenetiation Welds Written response required KEPPLER, J.G. Region 3. 'Aicago, Orrice of the Director 80/04/09 to
- 5 Reportable occurrence . (ERs > related correspondence
- 8004090167 Act receipt o+ 800229 final de+iciency rept re omission of Class B fill waterstops FIDRELLIG Region 3. Chirago, Reactor Construction & Engineering Support Branch 80/03/17 ip
- B004230353 Final deviciency rept to cracks & tears in bottom of steel socis of ITE switchyear caused by seismic environ Holes drilled & welds run along bend line Min of three switchgear frames will be bolted together for future shipments DAVIDSON, D.R. Cleveland Electric Illuminating Co. 80/04/15. 3pp
- DOCKET 50-443 SEABROOK NUFLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- BO04040031 Advises of issuance or MUREG-0588, "Inter(m Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance re-methods for compliance ROSS,DF Division of Project Management B0/02/05 7pp
- 8004020124 Advises that steps have been taken to initiate review of G4W-FSD-253G re main steam isolation valve, per 800108 ltr Review will be conducted on schedule consistent w/OL, application review VARGAIS A Assistant Director for Light Water Reactors 80/03/25
- F Security, medical, emergency & fire protection plans
- BO04080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004210316 Submits statement of 800320 meeting re status of city emergency evacuation plan Present plan insufficient to ensure human sarety State 5 federal runding & technical assistance needed to bring plan to required to stds BHERIDAN.C F Affiliation Unknown 80/03/24 1p
- G Adjudicatory correspondence
- B004080364 Discusses 800122 board notification re re-evaluation of 1732 Montreal earthquake % impact on facility NRC conclusion promature % reassessment of seismic experts may be subj to conflict of interest SHELDON, K.P. Sheldon, Harmon % Weiss 80/03/05 4pp
- BO04010472 Notifies that vote of people at annual town meeting supported withholding issuance of CL until safe evacuation plan established No town funds will be spent on evacuation plan tOCKE,E U , FALCONER, J C , EATON, J Affiliation Unknown BO/03/25 2pp
- 8004070045 Order granting extension until 800418 for Commission to consider whether to review ALAB-422 & ALAB-561 CHILK.S J. Office of the Secretary of the Commission 80/03/28 fp.
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Boald notification GOBSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004280165 Order granting extension until 800507 for Commission to consider whether to review ALAB-422 & ALAB-561 CHILKS J Office of the Secretary of the Commission 80/04/17

- H General correspondence
- 7907170211 Requests halt to plant const until util & NRC can devise adequate e-acuation plans
 BATES-A W Affiliation Uninown 79/07/11 ip
- 7907250345 Requests suspension or const pending improved evacuation planeas residence is only 12 miles from proposed plant WILLIAMSON, F. W. Affiliation Unknown 79/07/17)p
- 7907250327 Requests suspension of const pending improved evacuation plan GALLAGHER, V.C. Affiliation Unknown 79/07/18 ip
- 8004110052 Responds to 79071; itr re emorgency planning Will review applicant responses to Commission requirements prior to decision to issue OL Opportunity will be provided for public intervention prior to decision

 VARGA-5 A Assistant Director for Light Water Reactors 80/03/27
- 8004110060 Responds to 790717 note re emergency planning & consequences of Class 9 accidents Will review applicant responses to Commission requirements Opportunity will be provided for public intervention prior to decision to issue OL. VARGA. S. A. Assistant Director for Light Water Reactors 80/03/27 3pp
- 8004110047 Responds to 790718 itr re emergency planning for areas near facility Will review applicant responses to Commission requirements by provide apportunity for public intervention prior to decision to issue CL VARDA. S A Assistant Director for Light Water Reactors 80/03/27 Jpp
- 8004150131 Responds to 740710 ltr re omeigency planning Will review applicant responses to Commission requirements prior to decision to issue OL Opportunity will be provided for public intervention prior to decision VARGA. E. A. Assistant Director for Light Water Reactors 80/03/27 3pp
- 8004240529 Responds to 790407 itr of opposition to plant const Forwards 800211 ltr containing Director's decision not to issue order to show cause NRC will review applicant responses to requirements prior to decision re OL issuence ROSS.D F Division of Project Management 80/04/09 2pp
- ---8004240534 Opposes plant const due to lack of evacuation plan & threat of disaster
 EATON.L. Affiliation Unknown 79/06/07 1p
- I Financial information
- 8004070299 Forwards revised source of funds schedule.omitted from 800314 Suppl 4.Amend 40 request for partial transfer of CPs RITSHER, J A Ropes & Gray 80/03/31 ip
- ---8004070302 Revised source of funds schedulo, omitted from Suppl 4. Amend 40 of OL application for partial transfer of CPs

 * Public Service Co of New Hampshire 80/03/31 2pp
- 8004170263 Forwards request for addl rinancial info NRC requires info to complete evaluation of financial capability of applicants proposing to increase convership participation & evaluation of financial capability of proposed new owners RUBENSTEIN:L S light Water Reactors Branch 4 80/04/02 8pp
- M Antitrust correspondence
- BO04140098 Forwards Attorney General B00317 itr providing addl antitrust advice re CP application Ltr will be published in FR SALTZMAN, J Antitrust & Indemnity Group B0/03/21 1p
- --8004140104 Advisos NRC to CP for power plants per Section 105 of amended Abonic Energy Act of 1954 Antitrust hearing not necessary LITYACK.S M Justice, Dept of, Attorney General's Office 80/03/17 1p
- B004140279 Forwards DDJ B00317 ltr providing addl antitrust advice re CP application Ltr concludes that no basis for antitrust hearing was disclosed during review of info re Bangor ownership of 50 MW share in facility SALTZMAN. J Antitrust & Indemnity Group BD/03/26 2pp

O Inspection reports, IE Bulletins & carrespondence

- 8004090432 Forwards IE Mgt Meeting Repts 50-443/80-02 % 50-444/80-02 on 800206 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/26 ip
- --8004090441 IE Mgt Meeting Repts 50-443/80-02 & 50-444/80-02 on 800206
 Areas discussed & results establishment of onsite ofc to
 place full-time resident inspector
 MCGAUGHY, R W Region 1, Philadelphia. Reactor Construction &
 Engineering Support Branch MCOSCAR.J J. CERNC.A C Region i,
 Philadelphia, Office of the Director 80/02/26 3pp
- 8004070102 Ack receipt of 800201 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-443/79-09 & 50-444/79-09 CARLEON R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/05 2pp
- --8004070104 Responds to NRC 800111 ltr re violations noted in IE Insp Repts 50-443/79-09 & 50-444/79-09 Corrective actions revised Perini Procedure GAP-15-0 to require corrective action determination on each rept DEVINCENTIS.J Public Service Co of New Hampshire 80/02/01
- --8004070109 Forwards IE Insp Repts 30-443/79-09 & 90-444/79-09 on 791113-16 & notice of violation CARLSON:R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/11 2pp
- --8004070110 Notice of violation from insp on 791113-16
 * Region 1. Philadelphia, Office of the Director 80/01/03 ip
- ---B004070111 IE Insp Repts 50-443/79-09 & 50-444/79-09 on 791113-16
 Noncompliance noted failure to prescribe corrective actions
 by Perini & UE&C to preclude placement of concrete until all
 reinforcing steel has been installed
 EBMETER.S D Region I. Philodelphia. Reactor Construction &
 Engineering Bupport Bi anch SAMDERS.W F. VARELA.A A Region I.
 Philadelphia. Office of the Director 80/01/03 Bpp
- 8004100035 Forwards IE Insp Repts 50-443/80-01 & 50-444/80-01 on 800122-25 No noncompliance noted CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/11 2pp
- --8004100040 IE Insp Repts 50-443/80-01 & 50-444/80-01 on 800122-25 No noncompliance noted Major areas inspected QC controls on rebar installation & cadwelding, equipment maint & storage & plant insp tour
 KERNE, A C , VARELA, A A Region 1, Philadelphia, Office of the Director MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/04 9pp
- 8004080355 Forwards IE rept ger CJ Reis 800303 ltr Draws attention to Pages 3 & 4 M/o encl REIS.E J. Hearing Branch 3 80/03/25 lp
- 8004190302 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER.II H Region 1. Philadelphia. Office of the Director 80/03/31 ip
- 8004090103 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 1p
- 8004110511 Forwards IE Info Notice 80-13. "GE Type 88M Control Switches Defective CAM Followers " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/04/02 ip
- 800424034B Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees" No action required QRIER,B H Region 1. Philadelphia. Office of the Director 80/04/02 ip
- 8004180173 Forwards IE Circular 80-07, "Problems M/HPCI Turbine Oil 8ys " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/04/03 ip

- BOO4230502 Forwards IE Bulletin 79 0 PA "Longitudinal Weld Defects in ASIE SA-312. Type 304 Stainless Steel Pipt" Action required ORIER. B H. Region 1. Chiladelphia Orrico of the Director BO/04/04 | 1p
- 8004180284 Forwards 16 No. 11etin 80-08 'Cram of Containment Liner Penetration Welds ' Written esponse required GRIER, B H Region 1. Philadelphia. Office of the Director 80/04/07 1p
- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

 A Application/construction stage documents ' correspondence
- 8004040031 Advises of issuance of NUPEG-098B. "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance ROSS D F Division of Project Management 80/02/05 7pp
- 8004020124 Advises that stops have been taken to initiate review of GHV-F8D-253B re main steam isolation valve, per 800108 ltr Review will be conducted on schedule consistent w/DL application review VARGA.S A Assistant Director for Light Water Reactors 80/03/25
- F Security, medical, emergency fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 App
- 8004210316 Submits statement of 800320 meeting re status of city emergency evacuation plan Present plan insufficient to ensure human safety State 5 rederal funding 5 technical assistance needed to bring plan to required to stds SHERIDAM. C F Affiliation Unknown 80/03/24 ip
- G Adjudicatory correspondence
- 8004080364 Discusses 800122 board notification re re-evaluation of 1732 Montreal earthquake & impact on facility NRC conclusion premature & reassessment of seismic experts may be subj to conflict of interest SHELDON.K P Sheldon, Harmon & Weiss 80/03/09 4pp
- 8004010472 Notifies that vate of prople at annual town meeting supported withholding issuance of CL until safe evacuation plan established No town funds will be spent on evacuation plan LOCKE, E. U., FALCONER, J. C., EATON, J. Affiliation Unknown BO/03/25
- B004070045 Order granting extension until 800418 for Commission to consider whether to review ALAB-122 % ALAB-561 CHILM: S J Office of the Secretary of the Commission 80/03/28 ip
- G004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OUSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004280165 Order granting extension until 800509 for Commission to consider whether to review ALAB-422 & ALAB-561 CHILKS J. Office of the Socretary of the Commission 80/04/17
- If General correspondence
- 7907170211 Requests halt to plant const until util & NRC can devise adequate evacuation plans
 BATES A K Affiliation Unknown 79/07/11 1p
- 7907250345 Requests suspension of const pending improved evacuation plantas residence is only 12 miles from proposed plant WILLIAMSON.P N Affiliation Unknown 79/07/17 1p
- 7907280327 Requests suspension of const pending improved evacuation plan
 OALLACHER, V.C. Affiliation Unknown 79/07/18 tp

- BOO4110052 Responds to """ "1 ltt to emergency planning Will review applicant response. 12 formula ion requirements prior to decision to issue OL Opportoning will be provided for public intervention prior to decision. 2 National Control of the Provided For Public Page 15 Assistant Limitation For Light Water Reactors 80/03/27
- 8004110060 Responds to 750/17 note to emergency planning & consequences of Class 9 accident Will restew applicant itsponses to Commission requirement, appointments will be provided for public intervention prior to decision to issue OL VARQuis A Assistant Director for light Water Reactors 80/03/27
- 8004110067 Responds to 790718 its referency planning for areas hear facility Will review applicant responses to Commission requirements / provide apportunity roll public intervention prior to decision to issue GL VARGANS A Assistant Firector For Light Water Reactors 80/03/27 Jpp
- 8004150131 Responds to 770710 Its se emergency planning Will review applicant responses to Commission requirements prior to decision to 1-sue OL Opportunity will be provided for public intervention prior to decision.

 VARGA.5 A. Assistant Intractor for Light Water Reactors. 80/03/27 3pp.
- 8004240529 Responds to 79060; its or opposition to plant const Forwards 800211 its containing Director s decision not to issue order to show cause NRC will review applicant responses to requirements prior to decision to D. Issuence ROSS.D F. Division of Project Management 80/04/09 2pp
- --8004240534 Opposes plant const due to lack of evacuation plan & threat of disaster EATON: Afriliation Unknown 79/06/07 1p
- l Financial information
- 8004070299 Forwards revised source of runds schedule, omitted from 800314 Suppl 4. Amend 40 request for partial transfer of CPs RITSHER. J A Ropes 6 Gray 80/03/31 1p
- --8004070302 Pevised source of tunds schedule,omitted from Suppl 4,Amend 40 of OL application for partial transfer of CPs 4 Public Service for of New Hampshire 80/03/31 2pp
- 8004170263 Forwards requist for add] financial into NRC requires info to complete evaluation of financial capability of applicants proposing to increase ownership participation 2 evaluation of financial rapability of proposed new owners RUBENSTEINL S Light Water Reactors Branch # 80/04/02 Bpp
- M Antitrus* correspondence
- 800414009B Forwards Attorney General 800317 ltr providing addl antitrust advice re CP application Ltr will be published in FR SALTZKANOJ Antitrust & Indecently Group 80/03/21 1p
- --8004140104 Advises t'RC ie CP foi powei plants per Section 105 of amended Atomic Energy Act of 1954 Antitrust hearing not necessary LITVACK, S M Justice. Dept of, Attoiney General's Office 80/03/17 ip
- 8004140279 Forwards DDJ 860317 ltm providing addl antitrust advice re CP application Ltr concludes that no basis for antitrust hearing las disclosed during review of info re Bangor ownership of 50 MM shale in facility SALTZMAN, J. Antitrust? Indemnity Group 80/03/26 2pp
- Q inspection reports. If Bulletins & carrespondence
- 8004090432 Forwards IE Mgt Meeting Repts 50-443/80-02 & 50-444/80-02 on 800206 CARLSON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/28 1p
- --800409044) IE Mgt Meeting Repts 50-443/80-02 & 50-444/80-02 on 800206 Areas discussed & results establishment of onsite off to place full-time resident inspector MCGAUGHY, R & Region 1. Philadelphia. Reactor Construction & Engineering Support Branch MCOSCAR. J J. CERNE. A C. Region 1. Philadelphia, Office of the Director 80/02/26 Spp

- 8004070102 Ark receipt of 800201 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-443/79-09 ½ 50-444/79-09 CARLSON,R 1 Region 1. Philadelphia, Reactor Construction 2 Engineering Support Branch 80/03/05 2pp
- --BO040/0106 Responds to NRC B00111 itr 10 violations noted in IE Insp Repts 50-441/79-09 / %c-444/79-09 Corrective actions revised Perini Procedure QAP-15-0 to require corrective action determination on each impt DEVINCENTIS, J. Public Service Co. of New Hampshire B0/02/01
- --8004070109 Forwards LE Insp Repts 50-443/79-09 & 50-444/79-09 on 791113-16 * notice of violation CARL SOW, R.T. Region 1, Philadelphia. Reactor Construction & Engineering Support Branch BO/01/11 2pp
- --8004070110 Notice of violation from insp on 791113-16
 * Region 1. Philadelphia: Office of the Director 60/01/03 1p
- --8004070111 JE Insp Repts 50-443/79-09 & 50-444/79-09 on 791113-16 Noncompliance noted failure to prescribe corrective actions by Perini & UEAC to preclude placement of concrete until all reinforcing steel has been installed EDNETER. S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch SAMDERS.W F . VARELA.A A Region 1, Philadelphia, Office of the Director BO/01/03 Spp
- B004100035 Forwards 1E Imap Repts 50-443/80-01 & 50-444/80-01 on 800122-25 No noncompliance noted CARLSON,R T Region 1, Philadelphia. Reactor Construction & Engineering Support Dranch B0/03/11 2pp
- --8004100040 IE Insp Repts 50-443/80-01 & 50-444/80-01 on 800122-25 No noncompliance noted Major areas inspected QC controls on rebar installation & cadwelding.equipment maint & storage & plant insp tout

 KERNELA C. VARELA A. Region 1, Philadelphia, Defice of the Director REGAUCHY.R W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/04 9pp
- 8004080355 Forwards IC rept per FJ Rois 800303 ltr Draws attention to Pages 3 ひ 4 W/o enc! REIS、E J Hearing Branch 3 80/03/25 ip
- 8004150302 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Niock Valve " No specific action or response necessary GRIER. DH Region 1. Philadelphia. Office of the Director 80/03/31 | 1p
- 8004090103 Forwards IC Circular BO-05, "Emorgoncy Diesol Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, BH Region 1, Philadelphia, Office of the Director 80/04/01 1p
- 8004110511 Forwards II. Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No written response required GRIER, B Region 1, Philadelphia, Office of the Director 80/04/02 p
- HOO424GJAB Forwards IF Info Notice 80-14. "Safety Buggestions From Employees " No action required ORIER, B H Region I. Philadelphia. Office of the Director 80/04/02 | p
- 8004180173 Forwards IE Circular 80-0/. "Problems (J/HPCI Turbine Oil Sys " No written response required GRICR, B H. Region J. Philadelphia, Office of the Director BD/04/03 | 1p
- 8004230502 Forwards IF Bulletin 77-03A, "Longitudinal Weld Defects in ASME SA-312,Type 304 Stainless Steel Pipe " Action required GRIER, B H Region i. Philadelphia, Office of the Director 80/04/04 ip
- 8004180284 Forwards IF Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Hritten response lequired CRIER, B H Region 5, Philadelphia, Office of the Director 80/04/07 ip

- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addi guidance to NUREQ-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management B0/02/21 3pp
- 8004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amond to application Submittal schedule should include NRC approval prior to issuance of OL Wienci ROSS:DF Division of Project Management 80/03/10 53pp
- 8004150001 Notifies that IE Insp Repts 50-455/80-04,50-4446/80-04, 50-445/80-05 & 50-446/80-05 contain no proprietary info GARY.R J Teras Utilities Generating Co 80/03/25 ip
- 8004290521 Forwards add1 electrical, instrumentation & control drawings to assist in facility review List of drawing submittals & revision status encl CARY,R J Texas Utilities Generating Co BO/04/18 19pp
- 8004270634 Forwards add1 electrical instrumentation & control drawings to assist in facility review List of drawings & revision status encl Drawing available in Central Files only OARY, R J Texas Utilities Conerating Co 80/04/22 32pp
- 8004300526 Forwards add1 electrica), instrumentation 5 control drawings to assist in facility review List of drawings & revision status oncl
 CARY, R J Texas Utilities Generating Co 80/04/22 2pp
- F Security, medical, emergency * fire protection plans
- 8004080077 Advises that submittel date for evacuation time estimates, requested by NRC 791226 itm, has been postponed pending OAD clearance under Federal Repts Act
 ORIMES.B.K. Emergency Proparedness Task Force 80/03/i1 4pp
- 8004090053 Notification of postponement of 800326 meeting w/util in Bethesda,MD to discuss fire protection criteria for review of facility Heeting will be rescheduled BURWELL.B B Light Water Reactors Branch 2 80/03/14 App
- G Adjudicatory correspondence
- 8004040088 Response in opposition to Citizens for Fair Util Regulation B00219 request for order requiring NRC to provide documents re change of position & for postponement of prohearing Rationale of position undiscoverable W/Certificate of Bvr REYNDLDS,N S Texas Utilities Generating Co REYNDLDS,N S Debevoise & Liberman 80/03/04 Spp
- 8004080221 Response in apposition to Citizens Association for Sound Energy 800225 request for order compelling production of documents & for postponement of prehearing conference Certificate of Syc encl REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 80/03/04 Spp
- B004080726 Forwards NRC statement of position on admissibility of TX Association of Community Organizations for Reform Now contentions, re parties 800317 conference call OM Gay will be contacted on 800404 re applicant & NRC stipulations ROTHSCHILD, M U Hearing Branch 1 80/03/27 1p
- 8004090015 Forwards statement reflecting NRC views on admissibility of Citizens for Fair Util Regulation contentions per 800317 telcon NRC will contact intervenor on 800402 re compliance w/ABLB 800319 order W/o encl ROTHECHILD.M U Hearing Branch 1 80/03/28 2pp
- 800409001B Forwards statement reflecting NRC views on admissibility of Citizens Association for Bound Energy contentions per 800319 telcon NRC will contact intervenor on 800404 re compliance w/ABLB 800319 order W/o encl ROTHCHILD, M U Hearing Branch i 60/03/28 2pp

- B004030026 Memorandom or inderstanding between NRC ? FEMA re prompt improvement in radiological emergency planning * preparedness, distributed at Braid notification GOSSICKL V Office of the Executive Biricctor for Operations B0704702 34pp
- 8004210424 Rept re position on admissibility of intervenors'contentions per ASLB 800319 order scheduling 800430 prehearing conference Notices of SA Treby & SE Turk appearance. LJ Chandler withdrawall & Certificate or Svc encl ROTHSCHILD.M M , TURK.S. E. Hearing Branch (80/04/10 101pp
- BO0425034B Confirms BO040B telcon re Tx Association of Community Organizations for Reform Now position re NRC % applicant proposed stipulation covering intervenor contentions NRC position will address contentions as regotiated ROTHSCHILD. (i. U. Hearing Branch 1 80/04/10 1p
- 8004240421 Notion for approval of 800410 stipulation executed by NRC applicants % Citizens for Fair Util Representation, reintervenor contentions Parties' positions are stated in 800410 repts filed per ABLB 800319 order ROTHSCHILD, () U Hearing Branch 1 80/04/22 2pp
- ---8004240424 Stipulation renumbering / rewording Citizens for Fair Utils Regulation contentions Supersedes * supplements intervenor 790507,0529 % 1031 motions to intervene / suppls Stipulated statement of intervenor contentions end!
 FOUKEIR L Citizens for Fair Utility Regulation ROTHSCHILD, M U Hearing Branch I REYNOLDS, N S Texas Utilities Generating Co 80/04/10 lipp
- --8004240433 Response stating no objection to Citizens Association for Sound Energy 800411 request ror extension until 800411 to file motion for consideration of Contention 8 * to file position on contentions Certificate of Svc encl ROTHSCHILD.M U Hearing Branch 1 80/04/22 2pp
- H General correspondence
- 8004240428 Forwards 800221 ltr from TX Senator R Clower w/encl ltr from constituent MV McNutt Requests pertinent info to answer constituent fears of cancer from low level radiation exposure DEVISENVL Senate 80/03/05 3pp
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8004160239 Forwards Amend 10 to FSAP Affidavit encl GRAY,R J Texas Utilities Generating Co 80/03/31 2pp
- --B004160243 Amend 10 to F5AR Oversize drawings encl * Texas Utilities Generating Co B0/03/31 1400pp
- 8004220426 Forwards affidavit of sic for FSAR Amend 10 GARY,R J Texas Utilities Generating Co 80/04/14 3pp
- M Antitrust correspondence
- 8004020200 Response to Central & South West Corp et al second request for production of documents Stagg Sys Inc workpapers available for insp & copying Documents re transactions already produced Certificate or Svc ancl COPELAND, J G Houston Lighting & Power Co COPELAND, J G Baker & Botts 80/02/25 App
- BOO4040072 Notice of appearance in proceeding Certificate of Svc encl FABRIKANTIR Justice Dept of BO/02/25 4pp
- BOO4110030 Discusses addl request for documents located in Chalker personal files Request is untimely b deficient, failing to specify relevancy to proceeding No obligation to respond to request by BOO227, per Commission Rules of Piactice STANL, D M Isham, Lincoln b Real 80/02/25 2pp
- 8004020149 Forwards DDJ 2 NRC 800228 joint motion for mod of ASLB order re-settlement discussions & for issuance of order to compal production of certain documents & testimony Proposed order encl
 CVPHERT, 8 8 Justice, Dept of CHANANIA, FD Antitrust Division
 80/02/28 4pp
- --BO04020164 Joint motion for mod of ASLB 790416 order re protection of auttlement discussions & fai issuance of older to comptl production of decuments & testimony from Houston Lighting & Power & TX Utils W/Certificate of Svc CYPBERT.S B . DOPSUVIC.D A Justice.Dept of CHANANIA.F D Antitrust Division 60/02/28 120pp

- --8004020175 Oral deposition of EP Scarth re certification of questions Pp 2-8 * Atomic Safety and Lirensing Board Panel SCARTH/E D Affiliation Unknown 60/02/22 7pp
- --- 8004020181 Motion to compel I4 Utils Cos to supplement Apr & Jul 1979 responses to first set or interrogatories & requests for production of documents Urges partormance of current new obligations by 800306 W/Certificate of Sec & proposed order CYPHEGI.S B LUGUE, & Justice, Dept of 80/02/28 7pp
- --B004020190 Motion to compel Houston Lighting & Power to supplement 790111 % 0427 answers to 781122 interrogatoiles Urges fulfillment of current obligations arising from development of new info Certificate of Sc / proposed order enci CYPHERT.S B , LUQUE, N Justice, Dept of B0/02/28 7pp
- --8004020198 Joint application for issuance of subpoens directed to ED Scarth of TX Utils Generating Co.* DF Simmons of Houston Lighting / Power Requests extension until 800402 to depose DE Simmons Draft subpoenss / Certificate of Svc enci CYPHERT.S D. DDPSDVIC.D A. Justice.Dept of BLUHE.M. Antitrust Division 80/02/28 /pp
- BOO402009B Motion for protective order re disclosure of Diamond Shamrock Corp documents, in response to ASLB BO011B subposed duces tecum Documents in question are sub, of contractual obligations Certificate of Svc & proposed order enci CYPHERT.S B Justice.Dept of 80/02/29 10pp
- BOO40B0174 Notifies of change of address for counsel of South TX Electric Cooperative, Inc. & Medina Electric Cooperative, Inc. effective BOO310
 JDBN,D F Akin, Gump, Hauer 'Feld BO/03/04 ip
- 8004100498 Discovery rept for Feb 1980 Southwest TX Electrical Cooperative, Inc & Medina Electric Cooperative, Inc neither initiated nor received any discovery requests Certificate of Core and
 - Svc encl JOHN, D.F. Akin, Gump, Haver J. Feld 80/03/04 4pp
- 8004110574 Confirms 800229 felcon re DDJ subpoens of documents from Gulf States Utils Subpoens covers certain areas also covered in Grownsville Public Utils subpoens Util documents will be available to all parties RADER.R M Connel Moors / Corber 60/03/04 2pp
- 8004080559 Requests pretrial conserence to clarify procedural matters re ASLB 791214 order, filing testimony summaries & designation of trial exhibits
 CYPHERT, S.B. Justice, Dept of CHAMANIA, F.D. Antitrust Division RITE, F.H. Texas-Louisiana Electric Cooperative, Inc. 80/03/05
- 8004090204 Discovery rept for Feb 1980 Deposed W Taylor, M Hebb, DE Simmons 5 El Hatson Participated in depositions noticed by TX-LA Electric Cooperative 5 City of Brownsville, TX Reviewed Diamond Shamrock documents Filed application for subpoems CYPHERT, S B , PARMENTER, F H Justice, Dept of 80/03/05 Spp
- 8004070387 Discovery reg+ for Feb 1980 Participated in A Gerber,M Hebb, E Simmons, V Robertson & GW Beams depositions Attended J Turk. & S Phillips depositions Filed motion for addl time to respond to TX Utils interrogatories W/Certificate of SVC CARNEY,J A Central & Southwest Corp CARNEY,J A Isham, Lincoln & Beals 80/03/05 7pp
- 8004ii0056 Response to Houston Lighting & Power 8002i9 motion to compel interrogatory answers by DGJ re C Stover proposed expert testimony DGJ has no addl info to provide except for facts stated in this response M/Stover ltr & Certificate of Svc CYPHERT, S B Justice. Nept of 80/03/05 8pp
- 8004030344 Comments by Public Utils Board of City of Brownsville.TX on NRC & DOJ motion for mad of ASLB order re protection of settlement discussions ** ro; order to compel documents & testimony Urges clarification of scope U/Certificate of Svc POIRIER.M R Texas. State of 80/03/06 18pp
- 8004080273 Response in apposition to DOJ & NRC joint motion for mod of ASLB order re-settlement discussions & for order to compel production of documents Negotiations for settlement purposes are protected from discovery per case law & per rules SDUKNIOHT, J & Houston Lighting & Power Co + Baker & Botts + Lowenstein, Newman, Reis, Azelrad & Toll NRC 80/03/06 15pp
- --8004080285 Response seeking dismissal of DUJ 800228 motion to campal supplementation of interrogatories, as most Answers were served one day prior to this motion Addl suppl will be filled if further responses are appropriate W/Certificate of Svc FRANKLIN.W J Houston Lighting & Power Co * Bater & Botts * Lowenstein.Newman.Reis.Axelrad & Toll 80/03/06 App

- 8004080360 Response in opposition to DBJ & NRC joint motion for mod of ASLB order re-settlement discussions & for order to compe) production of documents NRC policy favoring settlement is designed to protect sources involved W/Certificate of Svc * Central * Southwest Corp * Isham, Lincoln * Beale 80/03/06 ilpo
- 8004080638 Response in opposition DOJ & NRC 800228 joint motion for mod or ABLB order te settlement discussions & for order to compet production of documents Negotiations must be protected per Rule of Fridence 408 W/Certificate of Svc AHEARN, C D Teras Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/03/06 30pp
- 8004090185 Notice of appearance on behalf of Public Utils Board of City of Brownsville.TX. in consolidated discovery Certificate of Svc encl SPIEGEL.G Texas, State of SPIEGEL.O Spiegel & McDiarmid 80/03/06 4pp
- 8004090434 Discovery rept by Public Utils Board of City of Brownsville, TA.for Feb 1980 Disposed M Borchelt or Central Power & Light Participated in R Edelstein deposition Received documents from Central & South West Corp Certificate of Svc encl PCIRIER.M R Teras, State of PCIRIER.M R Spiegel & McDjarmid 80/03/06 App
- BOO4100218 Notifies that DOJ recoived Houston Lighting & Power Co supplemental answers to Central Power & light Co first interrogatories w/o apps Requests Attachment A to Houston Power & Light Co second set of addi answers to NRC CYPHERT.S D Justice.Dept of 80/03/06 1p
- BOO4100433 Notice of appearance of G Epiegel on behalf of Public Utils Commission of Brownsville.TX Centificate of Svc encl SPIEGEL. G Drownsville.TX SPIEGEL, G Spiegel & McDiarmid BO/03/06 6pp
- 8004100535 Discovery ropt for Jan & Feb.1980.City of Austin has neither initialed nor received any discovery requests BALOUGH.R C Austin, TX 80/03/07 Spp
- 8004080044 Response by Public Utils Board of City of Brownsville, TX, in opposition to Central & Southwest Corp 800222 motion for protective older, re-second set of interrogatories & production of documents W/Certificate of Svc & 800207 ltr PDIRICER M R Texas, State of PDIRIFR.M R Spiegel & McDiarmid 80/03/10 | 12pp
- 8004100514 Forwards notice of taking of deposition of D Springs AMEARN, C D Debevoise & Liberman 80/03/10 ip
- --B004100525 Notice of taking of deposition of D Bprings on B00313-14 in Atlanta, GA Deponent will be examined on matters re bulk power supply & transmission % wheeling svcs in TX Certificate of Svc encl AHEARN, C D Toxas Utilities Generating Co AHEARN, C D Debavoise & Liberman 80/03/10 Spp
- BOO4110169 Notifies that W Scott deposition scheduled for Mar is cancelled Cancellation based on DOV representation that Scott would be called as expert withness BALDHIN. J M. Naker & Botts BO/03/10 Spp
- 8004090018 Updated response to first set of interrogatories & document requests includes info re witnesses, compositive utils, product & geographic market & petitions to intervene Prof qualifications of DA Springs : Certificate of Svc encl BURCHETTEIN Texas-Louisiana Electric Cooperative, Inc BURCHETTEIN H Northcutt Fly 80/03/11 27pp
- 8004090)44 Second supplemental response to first set of interrogatories & document requests Includes info re projected loads, capacity & reserves as of 800215 SLICKER:F K Texas Utilities Co SLICKER:F K Worsham, Forsythe & Sampels 80/03/11 Spp
- 8004090175 Supplemental response to thild set of interrogatories & document requests Supplemental answer to Interrogatory 18 encl (1/0 encl SLICKER, F K Texas Utilities Co SLICKER, F K Worsham, Forsythe & Sampels 80/03/11 3pp
- 8004090180 Supplemental response to first set of interrogatories & document requests Includes info re monthly fuel cost adjustments for 1979
 8LICKER; F. K. Texas Utilities Co. SLICKER; F. K. Worsham, Forsythe & Sampels 80/03/11 4pp

- 8004100084 Forwards DOJ subposes requiring DE Simmons.util vice president to testify 800331-0402 Confirms that Simmons will be available for deposition on 800404-05 instead of dates listed in subposes W/o enci CYPHERT.S B Justice.Dept of 80/03/11 1p
- 8004100221 Fourth supplemental response to first set of interrogatories & document requests Includes info re cities & utils which have explored power alternatives offered by TX Utils Co SLICKER,F K Texas Utilities Co SLICKER,F K Worsham, Forsythe & Sampels 80/03/11 3pp
- 800403025B Response in opposition to schedule proposed by NRC for reply to motion to quash 800221 subpoena directed to R Frame Merit of NRC argument will be better evaluated after Lerner deposition Suggests 800221 for reply W/Certificate of Svc KNDTTS, J B Texas Utilities Generating Co 80/03/12 5pp
- 8004020113 Forwards Houston Lighting & Power 800313 patition for directed certification of ASLB 800307 order re-confidential documents of settlement negotiations
 BOUKNIGHT, J. A. Lowenstein, Newman, Reis, Axelrad & Toil 80/03/13
 2pp
- --8004020119 Patition for directed certification, interim stay & review of ABLB 800307 order requiring Houston Lighting & Power to produce settlement negotiations documents Urges reversal of ruling W/excerpts of 800307 prehearing transcript BOUKNIGHT, J A , GREEN, D O Houston Lighting & Power Co BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13
- ~-9004020122 Order re NRC 790323 motion to compel further answers to Houston Lighting & Power first interrogatories Directs util to furnish list of privileged documents Orders responses to majority of questions W/escerpts of 790601 prehearing MILLER, M E Atomic Bafety and Licensing Board Panel 79/04/16
- 8004080028 Forwards POJ third supplemental response to Houston Lighting & Power Co first set of interrogatories Documents responsive to util 770204 second set of interrogatories encl Documents respond interrogatories not encl CYPHERT, 8 B Justice, Dept of 80/03/13 ip
- --8004080033 Third supplemental response to first set of interrogatories & document requests includes info re QT Taylor testimony re four relevant product markets in proceedings CYPHERT.8 B Justice.Dept of 80/09/13 30pp
- 8004080073 Application for issuance of subposes directed to FG Arey of Webster Engineering Corp. to be deposed & to produce documents re interconnections & interconnected sys Draft subposes & Certificate of Svc encl OREEN.D O Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Azeirad & Toll 80/03/13 13pp
- 8004090439 Ack receipt of & accepts 800312 itr in lieu of interrogatory enswer per 800307 prehearing ruling Ltr does not solve Houston Lighting & Power problems re C Stover deposition DOJ 800311 & 12 itrs & Certificate of Svc encl OREEN.D O Lowenstein, Newman, Reis, Azelrad & Toll 80/03/13 10pp
- B004100545 Response to third set of interrogatories Includes info re electric power & energy delivered to various utils during Dec 1979 Centificate of Svc encl * Taxas Electric Bervice Co B0/03/13 16pp
- 8004080370 Discovery rept for Feb 1980 Deposed J Wilson.GC Campbell & V Robertson et al Attended 80J & NRC depositions Served 800201 first set of interrogatories to NRC Received addl responses to interrogatories Certificate of Svc encl FRANKLIN.W J Houston Lighting & Power Ca * Baker & Botts * Lowenstein.Newman.Reis.Azelrad & Toll 80/03/14 7pp
- BO0404007B Comments by Public Utils Board of City of Brownsville, TX. stating no position re consolidation for trial advised by ABLB during BO0307 prehearing If consolidation ordered-right of cross-examination must be preserved W/Gertificate of svc POIRIER, M R . POIRIER, M R . Texas. State of 80/03/17 7pp
- 8004080153 Statement in apposition to consolidation of proceedings for hearing purposes, per ASLB 800307 prehearing conference request Issues not identical & evidence in South TX Project may not be related to Commanche Peak W/Certificate of Svc STAHL, D M Central & Southwest Corp STAHL, D M Isham, Lincoln & Beale 80/03/17 7pp

- 8004080247 Discovery rep¹ for Feb 1980 Participated in Ammons, Beams, Borchelt, Campbell, A. Yachtorigh depositions. Inspected DOJ documents Received A. opposed Central A. Southwest motion for additime to reply to interrogatories W. Certificate of Svc. AHEARN, C.D. Texas Utilities Co. AHEARN, C.D. Debevoise & Liberman 80/03/17. Upp
- B004080401 Submits TX Utils Generating Co response to ASLR 800307 request reviews on consolidation of proceedings for hearing purposes Urges complete consolidation KNOTTS. J Debevoise 5 Liberman 80/03/17 4pp
- B004080663 Order confirming results of 800307 oral argument NRC & DDJ joint motion; re-mod of order concerning protection of settlement discussions, granted in part Parties may not engage in further discovery re-documents included in motion CLASER, M.L. Atomic Sarety and Licensing Board Panel 80/03/17
- 8004210437 Notice of appearance in proceeding Certificate of Svc encl OLAZIER,K M. Justice-Dept of 80/03/17 App
- 8004090427 Discovery tept for Jan-Feb 1980 Participated in M Olymy deposition No discovery requests initiated Certificate of Svc encl BURCHETIC, W H Texas-Louisiana Electric Cooperative, Inc BURCHETTE, W H Northcutt Ely 80/03/19 3pp
- 8004010517 Order denying NRC 800311 motion to quash subposma of R
 Frame TX Utils Opherating Co-entitled to tost ND Lerner
 credibility by questioning work? documents prepared by
 Frame For Lerner review
 WOLFE,S J Atomic Safety and Licensing Board Panel 80/03/20 2pp
- 8004030347 Response in opposition to TX Utils Generating Co. Houston Lighting & Power Co & South West Corp 800313 petitions for directed centification of order compelling production of documents News article ? Certificate of Syc encl CHANANIA, F D. DLUME, H D. HODGOGN, A P. Antitrust Division 80/03/20 21pp
- 8004100177 Memorandum in opposition to petitions for directed certification filed by TX Utils Generating Co. Houston Lighting & Power Co & Central % South West Corp et al., re ASLB 800307 order Certificate of Svc encl CYPHERT. 6 B , DQP80VIC. D A , GLAZIER. K M Justice. Dept of S0/03/20 26pp
- 8004100534 Response to DGJ first set of interrogatories includes info re TX electric cooperatives & wholesale suppliers Certificate of Svc encl * Texas Electric Service Co 80/03/20 21pp
- BOD4010267 Clarifies NRC updated response to Houston Lighting & Power first set of interrogatories & request for production of documents
 BLWHS, M B Antitrust Division 80/03/21 2pp
- 8004040184 Motion to quash subpoens directed to GM Stagg upon BGJ & NRC joint request Absent evidentiary reliance upon Stagg Sys. Inc work nontestifying outside consultants are not subj to discovery process, per established rule FRANKLIN.W J Houston Lighting & Power Co 80/03/21 4pp
- --B004040198 Advises that Houston Lighting & Power does not intend to rely on Stagg Sys, Inc studies as part of defense in proceeding NRC & Central & Southwest Corp contensions re Stagg study based on misconception W/Certificate of Svc GREEN, D G Lowenstein, Newman, Reis, Axelrad & Toll B0/03/21 7pp
- 8004160111 Responds to NRC & Central & South West Corp comments re consolidation Severance arguments based on belief that util will rely on study by Stagg Sys. Inc as part of defense Util will not rely on Stagg study Certificate of Svc encl GREEN, D G Lowenstein, Newman, Reis, Azelrad & Toll 80/03/21 Opp
- BOO4030360 Response by Public Utils Board of City of Brownsville, TX in opposition to nonconsolidation of proceeding suggested by NRC & Central & South West Corp In event of separation, South TX case should be heard first Centificate of Bvc encl SPIECEL. G Texas, State of B0/03/24 9pp
- 8004290049 Response in opposition to Public Utils Board of City of Brownsville, TX 800317 comments requesting admittance as party in consolidated proceeding Statement of interest untimely & vague Certificate of Svc encl
 AHEARN, C D Texas Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/03/29 7pp

- BOO4100271 flotion to compal projection of documents by Southwest TX Electric Cooperative or subpreha directed to general manager & HcGinnes Requests to tiple M Ginnes 8001221 deposition if documents are not produce NVAIset subpoens b documentation GREEN D.G. Houston Lighting * Power Co. * Baker & Botts * Lowerstein, Newman, Reiser, -lief * 1011 ±0703/26 18pp
- --800410027B Notice to compel production or documents by Midwest Electric Cooperative re-subported professor of general manager.

 P Mettel Request- to this Mettel rescheduled deposition of documents are not produced M subpoeta? Certificate of Svc GREEN.D & Houston Lighting? Power to & Baker & Botts & Lowenstein, Newfami.Rel Apaliab ! Toll 80/03/26 15pp
- 8004080420 Application for issuance or subpoens directed to Gulf States
 Utils Co re settlement documents Documents not produced in
 response to 770779 & 807118 subpoens Urges production to
 extent allowed by ASLAB
 BLUKE.K B Antitiust Division 80703727 2pp
- --8004080424 Subposent directed to Gvlf States Utils Co requesting settlement documents, for this blooping.in Mashington.DC on 800402 Subposent and be quashed or modified upon request Certificate of Svc encl MILLER.M E Atomic Sarety and Licensing Board Panel 80/03/27 6pp
- 8004090126 Order denying Houston Lighting # Power 800321 motion to quash subpoena district to UM Stagg upon DOJ request Prior rulingsine nontestifying outside consultants do not apply in this proceeding due to relevancy of Stagg studies WOLFE.S J Atomic Safety and Licensing Board Panel 80/03/27 3pp
- 8004210386 Forwards Houston Lighting 5 Power 800327 motions to compet production of documents by NRC expert witnesses RH Hartley & NC Lerner Requests 800371 conference call prior to scheduled depositions
 FRANKLIN W J Lowenstein, Neuman, Reis, Axelrad & Tol1 80/03/27 ip
- --8004210392 Motion to compel testimonial questions answered by NRC expert witness RH Hartley Discoverability of questions established on Pages 421-423 of preheating conference transcript re ASLB 800625 order FRANKLIN, W J Houston Lighting & Power Co FRANKLIN, W J Lowenstein, Neuman, Reis, Aightad & Toll * Baker & Botts 80/03/27 4pp
- --B004210374 Submits preparation study for 800220-21 meeting re intraregional interconnections, transmission lines & other pooling matters HARTLEY:R H Affiliation Unknown 80/01/29 25PP
- --8004210397 Forwards RH Hartley 800211 memo to NRC re 800129 answers in preparation for 800220-21 meeting Requests questions to which answers were stated, per rule established in 790601 prehearing conference Pages 421-423 of transcript encl FRANKLIN.W J Lowenstein.Newman, Reis, Axelrad % Toli 80/03/20 Ann
- --B004210400 Motion to compel electric util industry testimonial antitrust analyses prepared by NRC expert economic witness N Lerner re Midland proceeding Urges production per prior rulings, subj to enci protective order W/Certificate of Swc FRANKLIN, W J Houston Lighting & Power Co FRANKLIN, W J Lowenstein, Newman, Reis, Azelrad & Toll * Baker & Botts 80/03/27 14pp
- 8004090123 Order giving parties one white provide addl authority restrictions of settlement privilege Memoranda addressing issue should be received by 800404 & response thereto by 800409 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/28 Rpp
 - 04090456 Protoctive order, in favor of Houston Lighting & Power, reconfidential corporate study produced in response to NRC initial interrogatories Parties may challenge claimed confidentiality by seeking judicial review per FOIA WOLFE, S J Atomic Safety and Licensing Board Panel 80/03/31 4pp
 - 04100243 Order granting in part NRC motion to compel add1 responses by Houston Lighting & Power (HL&P) Accords confidentiality to N Lerner analysis re Midland settlement Grants HL&P motion to compel NRC questions re RH Hartley testimony AULFE,S J Atomic Safety and Licensing Board Panel 80/03/31 3pp
 - 04100429 Public Utils Board of Brownsville motion for leave to file iffidavit as amicus curiae Brownsville is party to proceeding but has not formally appeared in appellate proceeding Certificate of Svc encl pricedly Gertificate of

- --B004100430 Arridavit of RE Roundtree, general manager of Biownsville Public Utils Board re agreement among T/ "IOUs" for const or two de interstate ties of 500 MW 5 250 MW Brownsville prepared to enter settlement negotilations ROUNDTREE, R E Brownsville, TX 80/03/27 3pp
- 8004090172 Updated response to Houston Lighting & Power second set of interrogatories & TY Util, first set of interrogatories Anticipates RE Corder participation as uitness re areas discussed during Corder deposition Certificate of Svc encl CHANANIA.F D. Antitrust Division 80/04/01 5pp
- 8004)00240 Order requesting parties in directed certification proceeding to respond to Utils Board of City of Brownsville, TX 800331 motion by 800409
 BISHOP, C J Atomic Safety and Licensing Appeal Panel B0/04/02
- BOO41BO151 Forwards joint motion for extension of time Motion is joined in by all parties to proceeding except DOJ & City Public Utils Board of BrownsvillerT(
 WhOTTS, J.B. Debevoise / Liberman 80/04/02 ip
- --B004|B0167 Joint motion for 30-day extension for all procedural dates
 Motion is based on progress of meaningful settlement
 negotations which could lead to resolution of part or all of
 proceedings Certificate of Svc encl
 CHANANIA,F D Antitrust Division COPELAND,J Q Houston Lighting
 ₹ Power Co STAHL, D M Central Power ₹ Light Co B0/04/02 Δρρ
- BOO4140007 Third set of addl answers to NRC 790115 initial interrogatories Simmons & Woodson are expected to testify re interconnections
 FRANKLIN, N J Houston Lighting & Power Co & Baker & Botts & Lowenstein, Nowman, Reis, Arelrad & Toll BO/04/03 2pp
- --B00414000B Second supplemental answers to Central Power & Light Co 790223 interrogatories Simmons & Woodson are expected to testing re interconnections Certificate of Svc encl FRANKLINIAU J Houston Lighting & Power Co * Baker & Botts * Lowenstein Rewman, Reis, Azelrad & Toll 80/04/03 6pp
- 8004(50032 Forwards opposition by Brownsville to joint motion for extension of time & request for prehearing conference, miscellaneous atty & ufil correspondence, affidavit & Brownsville rate estimates Certificate of Svc encl
 SPIEOEL.G > POIRIER.M R Spiegel & McDiarmid 80/04/03 19pp
- ~-B004150050 Opposition to joint motion for extension of time & request for prehearing conference Brownsville has been excluded from negotiations on which request for extension is based Certificate or Sv. encl
 SPIEGEL O. POIRIER MR Brownsville, TX SPIEGEL, O Spiegel & McDiarmid 80/04/03 2pp
- B004230066 Forwards Houston Lighting & Power 800403 motion to compet production of documents? JW Wilson testimony by Public Utils Board or City of Brownsville, TX Proposes expedited schedule to permit completion of expert witness discovery GREEN, D & Lowenstein, Newman, Reis, Axelrad & Toll 80/04/03 2pp
- ---8004230074 Motion to compel production of documents & JH Wilson expert testimony by Public Utils Board of City of Brownsville.TX
 If motion not grantod requests order precluding Wilson from hearing W/proposed order ie schedule & Cortificate of Svc
 BALDWIN.J M Houston Lighting & Power Co * Baker & Botts *
 Lowenstein.Newman.Reis.Axelrad & Toll 80/04/03 11pp
- 8004100126 Memorandum in response to ASLAR 800328 order requesting addit authority to recognition of settlement privilege Courts & case law do not recognize existence of privilege Cortificate of Svc entil BLUME.M B , HODODON.A P Antitrust Division 89/04/04 App
- 8004150083 Order setting 600411 conference at NRC Hearing Room.
 Bethesda, MD Oral argument will address NRC & DOJ joint
 motion for 30-day extension & Houston Lighting & Power
 800403 motion to compel Utils Board of Brownsville
 WOLFE, S J Atomic Safoty and Licensing Board Panel 80/04/04
- 8004170312 Memorandum of authorities re discoverability of settlement documents Urges reversal of ASLB 800307 ruling due to privilege recognized per case law 2 federal rules of evidence Supporting documentation & Certificate of Svc encl BOUKNIOHT: J A , GREEN, D G Houston Lighting & Power Co BOUKNIOHT: J A Baker & Botts 80704704 Blpp

- 8004170340 Response stating no position re joint motion for 30-day extension in proceeding, filed by NRC, Central & South West Corp. Houston Lighting & Power, TX Utils Generating Co. City of Austin & other parties Centricate of Soc encl DOPSQVIC.D A , LUQUE.N , PARMENTER, F Justice, Dept of 80/04/04
- 8004220128 Memorandum of authorities in support of settlement privilege Documents prepared in connection w/settlement process should be protected from discovery under work product privilege Certificate of Svc encl STAHL.D Central & Southwest Services. Inc. STAHL.D Isham. Lincoln & Beale 80/04/04 10pp
- B004240043 Consent motion for two-wk extension to respond to Houston Lighting 9 Power Co motion to compel groduction of documents Represents that util consents to extension O'NEILL:R A Bouthwest Texas Electric Cooperative O'NEILL:R A Miller, Balis & O'Neil 80/04/04 3pp
- 8004240045 Certifies syc of consent motions for extension to respond to Hauston Lighting & Power Co motion to compel production of documents from Midwest Electric Cooperative & Southwest TX Electric Cooperative on #00404 D'NEILL.R A Miller, Balis & O'Neil 80/04/04 App
- 8004240053 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compol production of documents Represents util consent to extension O'NEILL: R A Southwest Texas Electric Cooperative O'NEILL: R A Miller: Dalis & O'Neil BO/04/04 3pp
- 80042401/3 Memorandum.per ASLAB 800328 request.stating add1 authorities re directed certification of settlement document issue Treatises & modern trend hald inadmissibility of privileged documents as evidence Cortificate of Svc encl KMOTTS, J B . AHEARN.C D Texas Utilities Generating Co KNOTTS, J B Debavoise & Liberman 80/04/04 22pp
- 8004250106 Advises of arrangement to deliver Houston Lighting & Power pleadings moving to compol documents re E McGinnes & P Wetzel subpoenas Consents to I4-day extension for responses Cortificate of Sec encil GREEN, D G Lowenstein, Newman, Reis, Axelrad & Toll 80/04/04 5pp
- 8004100552 Motion to issue order compelling Southwest TX Electric Cooperative & general manager E McQinnes to produce for insp & copying documents set forth in motion Draft subpoena & Certificate of Svc encl OREEN, D O Mouston Lighting & Power Co ORFEN, D G Baker & Botts 80/04/07 18pp
- --B004100560 Motion to issue order compelling Midwest Electric Cooperative & general manager P Netrol to produce for inap & copying, documents responsive to subpoena served on Wetrol Draft subpoena & Cortificate of Svc encl OREEN.D & Houston Lighting & Power Co OREEN.D & Baker & Botts B0/04/07 15pp
- 8004230154 Motion to preclude DOJ from filing principal brief re ASLAB 800328 order DOJ failed to file principal brief by 800404 DOJ seeks to obtain unfair tactical adventage by untimely filing BOUKNIGHT.J A . OREEN.D O Houston Lighting & Power Co BOUKNIGHT.J A . Baker & Botts BO/04/07 3pp
- --8004230162 Order directing all parties to furnish ASLAB w/addl authority re privilege against discovery of documents Memoranda due on 800404 BIBHDP.C J Atomic Safety and Licensing Appeal Panel 80/03/28
- 8004240061 Motion for ASLB to reconsider extending procedural dates for 30 days Requests 80040B conference call to rule on extention TX Utils Generating Co is only party to be prejudiced by extending dates CHANANIA.F Antitrust Division BOUKNIGHT.J A Houston Lighting & Power Co BURCHETTE.W H Texas-Louisiana Electric Cooperative.Inc 80/04/07 3pp
- --8004240071 Supplemental argument & representations Addl time required by utils to make progress in settlement discussions Discussions began Sept 1977 Parties are optimistic about possibility of reaching quick settlement BURCHETTE, W H Texas-Louisiana Electric Cooperative. Inc KNOTTE, J B Texas Utilities Generating Co 80/04/07 Spp
- 8004210147 Discovery rept for Mar 1980 Deposed JA Bruggeman. JT Wenders, AJ Wood & DA Springs Moved to compel NRC deposition of ND Lerner Responded to DOJ motion to compel supplemental answers to first interrogatories W/Certificate of Svc FRANKLIN.W J Houston Lighting & Power Co FRANKLIN.W J Lowenstein. Neuman. Rois. Axejrad & Toll 80/04/08 App

- 8004150157 Response to Houston Lijhting & Power TX Utils Generating Co & Central & South West for 600404 memoranda of authorities re settlement privilege Higes affilmation of ASLB 800307 order fe production of documents N/Celfilicate of Svc CHANANIA F D . HURGDON', A P Antitiust Division 80/04/09 10pp
- 8004170347 Response to Public Utils Soard of City of Brownsville,TX 800331 motion to file RE Roundtiee afridavit as amicus curiae Disclosure of documents should not affect potential for settlement Certificate or Soc encil CHANANIA:FD Antitiust Division 80/04/09 App
- 8004226021 Response to Public Utils Bhard of City of Brownsville, TX 800331 motion to rile Roundtiec effidavit Requests to file counter-affidavit, re status or setilement, if Roundtree affidavit is accepted by ASLAS Certificate of Svc enc) KNOTTS, J S Texas Utilifies Generating Co 80/04/09 App
- BO04220152 Response to Houston Lighting & Fower B00403 motion to compel production of documents % deposition of Public Utils Board of City of Brownsyille, TX Poes not oppose motion if subj to enci protective order Apparance & Cortificate of Svc enci ROTH, A J. JACOBS, J C. Florida Cities ROTH, A J. Spiegel & HcDiarmid B0/04/07 14pp
- 8004240562 Response in opposition to NRC 800404 memorandum of addl authorities re existence of settlement documents privilege Congress did not intend to rice;e developing law of privilege W/Certificate of Svc KNOTTS, J B , AHEARN, C P Teras Utilities Generating Co KNOTTS, J D Debevoise & Liberman 80/01/09 Spp
- 8004170351 Order granting 30-day entonsion for procedural matters, amending ASLB 791214 order to discovery schedule & directing consolidation of proceedings for pictual & evidentiary hearings Consent motions for extension to 800404 granted MILLER, M E Atomic Safety and Licensing Board Panel 80/04/10 500
- BO04210141 Order denying Houston Lighting * Power motion seeking to preclude DDJ memorandum or add1 authorities filed per ASLAB BO0328 order IIIHOP.C J Atomic Sarety and Licensing Appeal Panel 80/04/10
- 8004230033 Forwards TX Utils Generating Co affidavit of LF Fikar requested during 800409 oral argument KNOTTS.J B Debevoise & Liberman 80/04/10 tp
- --B00423004i Affidavit stating that Contral & South West Corp. Houston Lighting & Power Co & TX Utils Co Sys have reached agreement in principle re interconnection disputes Agreement may form basis for discussions w/other parties W/Cortificate of Svc FIKAR, L F Texas Utilities Generating Co B0/04/10 5pp
- 8004230002 Responds to Public Utils Doard of City of Brownsville, TX opposition to Joint motion for extension of time Objects to alleged refusal to wheel 'submits (IL Borchelt affidavit in response to alleged exclusion from discussions STAHL, D M Central's Southwest Corp STAHL, D M Jeham, Lincoln & Beale 80/04/11 3pp
- ---8004230007 Affidavit responding to Public Utils Board of City of Brownsville,TX allegation that Brownsville has been excluded from discussions re interconnection Clarifies statement made at BOG27 meeting Certificate of Svc encl BORCHELT,M L Carolina Power / Light Co 80/04/f0 10pp
- 8004270227 Discovery rept for Mar-Apr 1780 Participated in FJ Meyer,HH Wandson & GN Stagg depositions Filed opposition to petitions for directed certification & reversal of ABL8 800307 order Joined other parties in moving for procedural extension CHANANIA,F D , BLUME,M B . HGDODON,A P Antitrust Division 80/04/25 3pp
- N Antitrust hearing transcripts
- 8004030346 Pages 690 % 691 ommitted from original transcript * Commission 80/03/07 3pp
- 800415029B Transcript of 800409 hearing in Bethesda, MD Pp 1-140 * Commission 80/04/09 140pp
- Q Inspection reports: IF Bulletins 3 correspondence
- 8004010147 Responds to JE Bulletin 79~28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps" Requests extension until 300331 to inspect safety-related equipment & implement necessary corrective actions GARY, R J Texas Utilities Generating Co 80/01/23 ip

- BOO4290492 Discussor IE Insp Repts 50-445/80-01 & 50-446/80-01 on BOO118 & rollards notice or violation SFIDLE, H C Region 4, Italias, Reactor Construction & Engineering Support Benning ROUGE24 Page
- --8004270498 Notice or violation from insp on 800118 Noncompliance noted procedures for securing Class IE battery chargers inappropriate fillet upids too small due to math thickness a Region 4, Pallas, Reactor Construction & Engineering Support Branch HO 01/2 < 10
- BOO416004: Forwards IF Insp Repts 50-445/80-05 & 59-446/80-05 on BOO214-15 ' 17 21 No narrompliance noted SEIDLE, W.C. Region 4. Pallas, Reactor Construction & Engineering Support Branch 60/02/20 Zpp
- --B004140050 lE Into Repts 50-445/80-05 * 50-446/80-05 on 800214-15 & 19-21 ho noncompliance noted Major areas inspected followup review or Unit 1 RCPB pring welding h of QA/QC records re Unit 2 containment bijg structural concrete installations HALL R C Region 4. Dallas. Reactor Construction & Engineering Support Branch CRESCHANLUA . TAPIA.J I Region 4. Dallas. Office or the Director 80/02/28 5pp
- 8004210175 Forwards II liss Repts 50-445.80-06 / 50-446/80-06 on 800220-21 No noncompliance noted MADSEN G.L. Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/02/29 1p
- --8004210179 IE Insp Repts 50-445/80-06 & 50-446/80-06 on B00220-21 No noncompliance noted Major areas inspected preoperational testing GA & operational staffing WESTERMAN, T.F. SMITH R. Region 4. Dailas, Office of the Director B0/02/29 Spp
- 8004220232 Forwards IE Insp Repts 50~445/80-04 & 50~446/80-04 on 800211-15 No noncompliance noted SEIDLE W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004220244 IE Insp Repts 50-445/80-04 to 50-446/80-04 on 800211-15 No moncompliance noted Major aleas inspected procedures for controlling changes to approved design documents HALE.C J. CPOSSMAN.W A. BRICKLEY.R H. Region 4. Dallas, Vendor Inspection Branch 80/02/28 8pp
- 8004210432 Advises that numbers of inspirepts transmitted by 600229 ltr should be corrected to read 50-445/80-06 & 50-446/80-06 MADSEN G L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/03/10 ip
- --8004210443 Forwards IE Insp Repts 50-445/80-06 ½ 50-446/80-06 on 800220-21 No noncompliance noted MADSEN.G L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/02/29 ip
- --8004210428 IE insp Repts 50-445/80-05 & 50-446/80-05 on 800220-21 No noncompliance noted Major areas inspected preoperational testing. GA 2 operational staffing WESTERMAN. TF Region 4. Dallas, Reactor Operations Nuclear Support Granch SMITH.R Region 4. Dallas, Office of the Director 80/02/29 Spp
- 8004040081 Ack receipt of 600305 ltr informing NRC of steps taken to correct violations noted in LE lnsp Repts 50-445/80-03 & 50-445/80-03 SEIDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/03/11 1p
- --8004040063 Responds to NRC 800207 IE insp Repts 50-445/80-03 & 50-446/80-03 Corrective actions engineering personnel reviewed cable lubrication requirements w/key const personnel involved w/cable pulling OARY.R J Texas Utilities Generating Co 80/03/05 3pp
- 8004040098 Ack receipt of 600220 ltm informing NRC of steps taken to correct violations noted in lE Insp Rept 50-445/79-31 & 50-445/79-29 SEIDLE, W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 60/03/11 lp
- 8004040101 Responds to NPC 800127 IE Insp Repts 50-445/77-31 & 79-446/77-29 Corrective actions tackwelds removed. General Piping & Welding Procedure CP-CPM-6 9 revised by reorganized GARY.R J Texas Utilities Generating Co 80/02/20 3pp
- 8004250079 Forwards IE Investigation Repts 50~445/80~02 & 50~446/80~02 on 800121~0205 No noncompliance noted SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/03/20 2pp

- --8004250093 IE investigation Repts 50-445/80-02 & 50-446/80-02 on 800121-0205 No noncompliance noted Major areas inspected allegations re law 0C procedures, welding problems & weld defects CROSMMI, W A GILBERT, L D . HALL, R E Region 4, Dallas, Office of the Director 80/03/18 7pp
- B004240225 Forwards IE Into Notice 80~14, "Safety Suggestions From Employees" No artion required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/02 in
- BOO4220320 forwards IE Circular 80-07, "Problems N/HPCI Turbine Oil Sys " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/03
- 8004220779 Forwards IE Rulletin 79-03A "Longitudinal Weld Defects in ASME SA 312. Type 304 Stainless Steel Pipe "Action required SEYFRIT.K V Region 4 Dallas, Orrice of the Director 80/04/04 ip
- BOO4220208 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds" Written response required SEYPRIT, X V Region 4. Dailas. Office of the Director BO/04/07 in
- S Reportable occurrences, LERs & related correspondence
- G004010295 Forwards deficiency rept re control board welded connections OARY,R J Texas Utilities Generating Co 80/03/21 ip
- --8004010297 Deficiency rept on 800228, GA inspreaded control board walded connections not meeting seismic design criteria Cause unstated Control board suppliers & AE reviewing as-built wald configurations Rework will be completed by 800501

 > Texas Utilities Conerating Co 80/03/21 2pp
- 8004150199 Forwards deficiency rept re control board welded connections
 GARY,R J Texas Utilities Generating Co 80/03/21 ip
- --8004150202 Deficiency rept re control board welded connections
 Specified 8-inch spacing of welds from end to end was found
 to vary from sixteen to eighteen inches on several panels
 As-built weld configurations under review
 * Texas Utilities Generating Co 80/03/21 2pp
- B004010276 Forwards rept of actions taken to correct deficiencies in mig of discs for svc water control valves Supporting documentation is available at site for inspector review GARV:R J Teras Utilities Generating Co 80/03/25 2pp
- 8004070278 Supplemental RD violation found re piping min wall thickness Cause unstated Engineering review in progress Progress rept will be submitted by 800418 GRY/R J Teras Utilities Generating Co 80/03/28 ip
- 8004220423 Interim deficiency rept re piping min wall thickness Review of weld & base metal repair records is continuing Another progress rept will be submitted by 800620 GARY.R J Texas Utilities Generating CO 80/04/15 ip
- E004270250 Forwards deficiency rept to concrete honeycomb condition encountered in steam generator compartment walls of Unit 2 reactor containment bidg OARY.R J Teras Utilities Generating Co 80/04/21 ip
- --8004290294 Deficiency rept re concrete honeycombing in steam generator compartment walls of Unit 2 reactor containment bldg Consultant survey shound no critical internal defects Util to repair "condition w/dry-pack mortar-grout & concrete # Texas Utilities Generating Co 80/04/21 3pp
- 8004270271 Interim deficiency rept re installation of drilled-in expansion anchors Matter was corrected 770616 by revision to installation procedure Formal rept to be filed by 801215 GARY-R J Texas Utilities Generating Co
- 8004290411 Provides status of interim deficiency rept re installation & insp requirements for Class V non-nuclear safety-related pipting supports Final rept will be forwarded by 800715 OARY-R J Texas Utilities Generating CO B0/04/21 ip
- 8004270430 Forwards interim deficiency rept re installation & insp of welded conduit supports Final rept to be filed by 800801 GARY.R J Texas Utilities Generating Co 80/04/21 1p

- ~~8004290437 Interim deficiency rept re installation & insp of welded conduit supports Major support was fabricated w/o formalized instructions & insp records for number of smaller weided supports were not directly traceable to as-built conditions GARY,R J Texas Utilities Generating Co 80/04/21 1p
- T Hearing transcripts on non-antitrust matters
- 8004210312 Transcript or 800327 hearing in Bethesda, MD Pp 1-127

 * Atomic Safety and Licensing Appeal Panel 80/03/27 130pp
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA .UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safoty-Related Clottrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Rolated Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSB.D F Division of Project Management 80/02/21 Spp
- B00423005B Requests into re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident into should be provided as amend to application Bubmittal schedule should include NRC approval prior to issuance of OL W/encl ROBS.DF Division of Project Management 80/03/10 53pp
- 8004150001 Notifies that IE Insp Repts 50-435/80-04, 50-446/80-04, 50-445/80-05 & 50-446/80-05 contain no proprietary info GARY,R J Texas Utilities Generating Co 80/03/25 1p
- 8004270521 Forwards add) electrical, instrumentation & control drawings to assist in facility review List of drawing submittals & revision status encl
 OARY,R J Texas Utilities Generating Co 80/04/10 17pp
- B004270634 Forwards add! electrical, instrumentation & control drawings to assist in facility review List of drawings & revision status encl Drawing available in Central Files only QARY.R J Texas Utilities Generating Co
- 9004300526 Forwards add1 electrical instrumentation & control drawings to assist in facility review List of drawings & revision status encl
 OARY.R J Texas Utilities Generating Co 80/04/22 2pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 ORIMES, B K Emergency Preparedness Task Force 80/03/i1 4pp
- 8004070053 Notification of postponement of 800326 meeting w/util in Bethesda,MD to discuss fire protection criteria for review of facility Meeting will be rescheduled BURMELL.8 B Light Water Reactors Branch 2 80/03/14 App
- 0 Adjudicatory correspondence
- 8004040088 Response in opposition to Citizens for Fair Util Regulation 800219 request for order requiring NRC to provide documents re change of position & for postponement of prehearing Rationale of position undiscoverable W/Certificate of Svc REYNOLDS,N 8 Texas Utilities Generating Co REYNOLDS,N 9 Debevoise & Liberman 80/03/04 Spp
- 8004080221 Response in opposition to Citizens Association for Sound Energy 800225 request for order compelling production of documents & for postponement of prehearing conference Certificate of Svc encl REYNOLDS.N.S Texas Utilities Generating Co REYNOLDS.N.S Debevoise & Liberman 80/03/04 Spp
- 8004080726 Forwards NRC statement of position on admissibility of TX Association of Community Organizations for Reform Now contentions, re-parties 800319 conference call GM Gay will be contacted on 800404 re-applicant t NRC stipulations. ROTHSCHILD, M U Hearing Branch 1 80/03/27 ip

- 800-4090015 Forwards statement reflecting NRC views on admissibility of Citizens for Fair Util Regulation contentions per 800317 telcon IRC will contact intervenor on 800402 re compliance w/ASLB 800319 order W/o encl ROTHSCHILD, M U Hearing Bianch 1 80/03/28 2pp
- 8004070018 Forwards statement reflecting NRC views on admissibility of Citizens Association for Sound Energy contentions per 800319 telcon NRC will contact intervenor on 800404 re compliance w/ASLD 800319 order W/o enc! ROTHCHILD.M V Hearing Branch 1 80/03/28 2pp
- GOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations BO/04/02 34pp
- 8004210424 Rept re position on admissibility of intervenors'contentions per ASLB 800319 order scheduling 800430 prehearing conference Notices of SA lieby 8 SE Turk appearance. LJ Chandler withdrawal & Certificate of Svc enc) RØTHSCHILD,M M . TURK, S E Hearing Branch 1 80/04/10 101pp
- 8004250348 Confirms 800408 telcon re TX Association of Community Organizations for Reform New position re NRC & applicant proposed stipulation covering intervenor contentions NRC position will address contentions as negotiated ROTHSCHILD.N U Hearing Branch 1 80/04/10 tp
- BOO4240421 Motion for approval of BOO410 stipulation executed by NRC, applicants & Citizens for Fair Util Representation, reintervenor contentions Parties' positions are stated in BOO410 repts filed per ASLB BOO319 order ROTHSCHILD, M. U. Hearing Branch (BO/04/22 2pp
- --8004240424 Stspulation renumbering & fewording Citizens for Fair Utils Regulation contentions Supersedes & supplements intervenor 790507,0527 & 1031 motions to intervene & supple Stipulated statement of intervenor contentions encl FOUXE.R L Citizens for Fair Utility Regulation RDTHSCHILD, M U Hearing Branch 1 REYNDLDS, N S Texas Utilities Generating Co 80/04/10 11pp
- ---8004240433 Response stating no objection to Citizens Association for Bound Energy 800411 request for extension until 800411 to file motion for consideration of Contention 8 & to file poststion on contentions Certificate of Svc encl ROTHSCHILD, M V Hearing Branch (80/04/22 2pp
- H General correspondence
- 8004240428 Forwards 800221 itr from TX Senator R Clower w/encl itr from constituent MN McNutt Requests pertinent info to answer constituent fears of cancer from low level radiation exposure BENTSEN:L. Senate 80/03/05 3pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004160239 Forwards Amend 10 to FSAR Affidavit and QRAY, R J Teras Utilities Generating Co 80/03/31 2pp
- --B004160243 Amend 10 to FSAR Oversize drawings encl * Texas Utilities Generating Co 80/03/31 1400pp
- 8004220426 Forwards affidayit of svc for FSAR Amend 10 GARY.R J Texas Utilities Generating Co 80/04/14 3pp
- M Amiitrust correspondence
- 800402020B Response to Central & South West Corp et al second request for production of documents Stagg Sys Inc workpapers available for insp & copying Documents re transactions already produced Certificate of Svc encl COPELAND. J & Houston Lighting & Power Co COPELAND. J & Baker & Botts 80/02/25 App
- 8004040072 Notice of appearance in proceeding Certificate of Svc encl FABRIKANT,R Justice.Dept of 80/02/25 App
- 8004110030 Discusses addl request for documents located in Chalter personal files Request is untimely & deficient, failing to spacify relevancy to proceeding No obligation to respond to request by 800227, per Commission Rules of Practice STAHL.D M Isham. Lincoln & Beale 80/02/25 2pp

- 8004020149 Forward, FOJ / NAC ENGLES joint motion for mad of ASLB order resettlement discussions for issuance of order to compel production of certain incurents for testimony proposed order encl.

 CYPHERI, S. B. Jultice, Pert of CHANANIA, F.D. Antitrust Division 80/02/28 4pt
- 8004020164 Joint rotion for and or AFLB 790416 order re-protection of settlement discussions? For insuance or order to compel production or incuments, ? restinging from Houseon Lighting & Power 1. Tx Utils & Certificate of Svr CYPBERT, S. D., COPPOVIC F. A. Justice-Dept of CHANANIA, P. D. Antitrust Division 60702/08 120pp
- ~-8004020175 Dial Jeposition of ED Starth re certification of questions Pp 2-8 4 Atomic Safate and Licensing Board Panel SCARTH.E D Affiliation Unknown 80/02/22 9pp
- --800402018) Notion to compel TX UF:13 Cos to supplement Apr & Jul 1979 responses to first set or interrogatories & requests for production of Jocuments Utges performance of current new obligations by 800300 M. Centificate of Svc & proposed order CYPHERT, S B LUQUE, N Justice, Dept of 80/02/28 7pp
- ~8004020190 Motion to compel Houston Lighting © Power to supplement 790111 & 04+7 answers to 70112P interrogatories Urges fulfillment of current abligations arising from development of new into Certificate of Sic & proposed order encl CYPHERT, S.B., LUJUE, N. Justice, Dept of 80/02/28 7pp
- --8004020198 Joint application for issuance of subpoena directed to ED Scarth of TX Utals Generating Co ? DE Simmons of Houston Lighting & Pewer Requests extension until B00402 to depose DE Simmons Draft subpoenas & Certificate of Svc encl CYMERT, 5 B , DUPSOVIC, D A Justice, Dept of BLUME, M Antitrust Division 80/02/28 7pp
- BO0402009B Mation for protective order re disclosure of Diamond Shampack Corp documents in response to ASLB B0011B subposma duces tecum Documents in question are subj of contractual obligations Certificate of Svc / proposed order encl CYPHERT.S B Justice Dept of B0/02/29 lope
- BOO4080174 Notifies of change of address for counsel of South TX Electric Cooperative, Inc & Medina Electric Cooperative, Inc, effective BOO310 JOHN.D F Akin. Gump. Haver & Feld 80/03/04 1p
- 8004100498 Discovery rept for Feb 1980 Southwest TX Electrical Cooperative, Inc & Medina Electric Cooperative, Inc neither initiated nor recoived any discovery requests Certificate of Svc encl JOHN, D.F. Akin, Gump Hauer & Feld 80/03/04 App
- BOO4110974 Confirms BOO279 telcon re DDJ subpoena of documents from Gulf States Utils Subpoena covers certain areas also covered in Brownsville Public Utils subpoena Util documents will be available to all partices
 RADER.R M Couner. Moore ! Corber BO/03/04 2pp
- 8004080559 Requests pretrial conference to clarify procedural matters re ASLB 791214 order filing testimony summaries & designation of trial exhibits CYPHERT.S B Justice. Rept of CHAMANIA.F D Antitrust Division RITTS.F H Texas-Louisiana Electric Cooperative Inc. 80/03/05
- 8004090E04 Discovery rept for Feb 1980 Deposed W Taylor,M Hebb.DE Simmons & FL Watson Participated in depositions noticed by TX-LA Electric Coopitative & City of Brownsville.TX Reviewed Diamond Shamroty documents Filed application for subposenss CYPHERT.S B , PARMENTER F H Justice.Dept of 80/03/05 5pp
 - 04070387 Discovery rept for Feb 1780 Participated in A Gerber M Hebb, E Simmons V Robertson & GN Beams depositions Attended J Turk & S Phillips depositions Filed motion for add1 time to respond to TX Utils interrogatories W/Certificate of Svc JARNEY, J A Central & Southwest Corp CARNEY, J A Isham, Lincoln & Beale 80/03/05 7pp
- 8004110054 Response to Houston Lighting ? Power 800219 motion to compel interrogatory ensuers by DOJ re C Stover proposed expert testimony DOJ has no aids info to provide except for facts stated in this response M/Stover ltm ? Certificate of Bvc CYPHERT(S B Justice Dept of 80/03/05 Spp
- BOO4030344 Comments by Public Utils Board of City of Brownsville.TX on NRC & DOJ motion for mod of ASLB order re protection of settlement discussions & for order to compel documents & testimony Urges clarification of scope M/Certificate of Svc POIRIFR.M R Texas, State or 80/03/04 18pp

- BOOAOBO273 Response in opposition to DOJ to NRC joint motion for mod of ASLB order te settlement discussions & for order to compel production of documents Negotiations for settlement purposes are protected from discovery per case law & per rules BOUNNIGHT J. Housen Lighting 'Power Co. * Baker & Botts * Lovenstein, Neuman, Rois, Arehrad & Toll MRC BO/03/06 15pp
- --B004080285 Response secking dismissal of DOJ B00228 motion to compel supplementation of interlogatories, as moot Answers where served one day prior to this motion Addi suppl will be filed if further responses are appropriate W/Certificate of Svc FRANKLIM, M. J. Houston Lighting & Power Co. * Baker & Botts * Lowensfelm, Newman, Rels. Ascirad & Toll B0/03/06 App
- 8004080360 Response in opposition to DOU % NRC joint motion for mod of ASLB order re-settlement discussions % for order to compel production of documents NRC policy favoring sottlement is designed to protect sources involved M/Certificate of Svc * Central ! Southwest corp * Isham, Lincoln & Beale 80/03/06 lion
- 8004080638 Response in opposition DOJ & NRC 800228 joint motion for mad of ASLB order re-settlement discussions & for order to compel production of documents Negotiations must be protected per Rule of Evidence 408 W/Certificate of Svc AHEARN, C D Texas Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/03/06 30pp
- 8004070185 Notice of appearance on behalf of Public Utils Board of City of Brownsville,TX.in consolidated discovery Certificate of Svc enci SPIEGEL,G Tesas, State of SPIEGEL,O Spiegel & McDiarmid 80/03/06 6pp
- 8004090434 Discovery rept by Public Utils Board of City of Brownsville, TA. for Feb 1980 Deposed M Borchelt of Central Power & Light Participated in R Edelstein deposition Received documents from Central & South West Corp Certificate of Svc encl PDIRIER, N R Texas, State of PDIRIER, N R Spiegel & McDiarmid 80/02/04 App
- 8004100218 Notifies that DOJ received Houston Lighting & Power Co supplemental answers to Central Power & Light Co first interragatories w/o apps Requests Attachment A to Houston Power & Light Co second set of add answers to NRC CYPHERT, S D Justice, Dept of 80/03/06 1p
- B004100433 Notice of appearance of Q Spiegel on behalf of Public Utils Commission of Brownsyille.TX Certificate of Svc encl SPIEGEL.Q Brownsyille.TX SPIEGEL.Q Spiegel & McDiarmid 80/03/06 App
- 8004100535 Discovery rept for Jan & Feb. 1980, City of Austin has neither Initialed nor received any discovery requests BALQUGH, R. C. Austin, TX. 80/03/07 Spp
- 8004080044 Response by Public Utils Board of City of Brownsville, TX, in opposition to Central & Southwest Corp 800222 motion for protective order, re second set of interrogatories & production of documents W/Certificate of Bvc & 800207 Itr PDIRIER, M R Teras, State of PDIRIER, M R Spiegel & McDiarmid 80/03/10 12pp
- BOOM100514 Forwards notice of taking of deposition of D Springs AHEARN.C D Debevoise & Liberman BO/03/10 ip
- --8004100525 Notice of taking of deposition of D Springs on 800313-14 in Atlanta. GA Deponent will be examined on matters re bulk power supply & transmission & wheeling sycs in TX Certificate of Syc encl AMEARN, C D Texas Utilities Generating Co AMEARN, C D Debevoise & Liberman 80/03/10 Spp
- 8004Fi0149 Notifies that W Scott deposition scheduled for Mar is cancelled Cancellation based on DDJ representation that Scott would be called as expert withness BALDNIN.J H Baker S Rotts 80/03/10 3pp
- BOO40BOOIB Updated response to first set of interrogatories & document requests Includes info re winesses, competitive utils, product & geographic market? petitions to intervene Prof qualifications of DA Springs & Certificate of Bvc encl BURCHETIE.W H Texas-Louisiana Electric Cooperative, Inc BURCHETIE.W H Northcutt Ely 80/03/11 29pp
- 8004090164 Second supplemental response to first set of interrogatories & document requests includes info re projected loads, capacity & reserves as of 800215 SLICKER, F K Teras Utilities Co GLICKER, F K Worsham, Forsythe & Sampels 80/03/11 5pp

- 8004090175 Supplemental response to third set of interrogatories & document requests Supplemental answer to Interrogatory 18 encl W/o encl SLICKER, FK Texas Utilities Co SLICKER, FK Worsham, Forsythe & Sampels 80/03/11 3pp
- 8004090180 Supplemental response to first set of interrogatories & document requests Includes info re monthly fuel cost adjustments for 1979
 SLICKER.F K Texas Utilities Co SLICKER.F K Worsham, Forsythe & Sampels 80/03/11 4pp
- 8004100084 Forwards DOJ subpoens requiring DE Simmons, util vice president, to testify 800331-0402 Confirms that Simmons will be available for deposition on 800404-05 instead of dates listed in subpoens W/o encl CYPHERT, S B Justice, Dept of 80/03/11 jp
- 8004100221 Fourth supplemental response to first set of interrogatories & document requests includes info re cities & utils which have explored power alternatives offered by TX Utils Co SLICKER, F K Texas Utilities Co SLICKER, F K Worsham, Forsythe & Sampels 80/03/11 3pp
- 8004030258 Response in opposition to schedule proposed by NRC for reply to motion to quash 800221 subpoena directed to R Frame Merit of NRC argument will be better evaluated after Lerner deposition Suggests 800321 for reply H/Certificate of Syc KNOTTS.J B Texas Utilities Generating Co 80/03/12 Spp
- B004020113 Forwards Houston Lighting & Power B00313 petition for directed certification of ASLB 800307 order re confidential documents of settlement negotiations BCUKNIOHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13
- --B004020119 Petition for directed certification, interim stay & review of ASLO B00307 order requiring Houston Lighting & Power to produce settlement negotiations documents Urges reversal of ruling W/excerpts of B00307 prehearing transcript BOUKNIGHT, J A GREEN, D Q Houston Lighting & Power Co BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13 19pp
- ---8004020122 Order re NRC 790323 motion to compel further answers to Houston Lighting & Power first interrogatories Directs util to furnish list of privileged documents Orders responses to majority of questions W/s:cerpts of 790401 prehearing MILLER.M E Atomic Safety and Licensing Doard Panel 79/04/16
- B0040B002B Forwards DOJ third supplemental response to Houston Lighting & Power Co first set of interrogatories Documents responsive to util 790204 second set of interrogatories encl Documents re second interrogatories not encl CYPHERT, B B Justice, Dept of 80/03/13 ip
- ---B0040B0033 Third supplemental response to first set of interrogatories & document requests includes into re GT Taylor testimony refour relevant product markets in proceedings CYPHERT, 8 B Justice, Dept of B0/03/13 30pp
- 8004080073 Application for issuance of subpoens directed to FG Arey of Webster Enginearing Corp. to be deposed & to produce documents re interconnections & interconnected sys Draft subpoens & Certificate of Syc enc. QREEN, D G Hauston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13 13pp
- 8004090439 Ack receipt of & accepts 800312 ltr in lieu of interrogatory answer per 800307 prehearing ruling Ltr does not solve Houston Lighting & Power problems re C Stover deposition DDJ 800311 & 12 ltrs & Certificate of Svc encl OREEN, D G Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13 10pp
- 800A100545 Response to third set of interrogatories Includes info re electric power & energy delivered to various utils during Dec 1979 Certificate of Svc encl * Texas Electric Service Co 80/03/13 14pp
- 8004080370 Discovery rept for Feb 1980 Deposed J Milson, GC Campbell & V Robertson et al Attended DDJ & NRC depositions Served 800201 first set of interrogatories to NRC Received addites responses to interrogatories Certificate of Svc encl FRANKLIN, W J Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/03/14 7pp
- 8004040078 Comments by Public Utils Board of City of Brownsville,TX, stating no position re consolidation for trial advised by ASLB during 800307 prehearing If consolidation ordered right of cross-examination must be preserved M/Certificate of svc POIRIER,M R . POIRIER,M R Texas, State of 80/03/17 7pp

- 8004080153 Statement in opposition to consolidation of proceedings for hearing purposes, per ASLB 800307 prehearing conference request Issues not identical *h* evidence in South TX Project may not be related to Commanche Peak W/Certificate of Svc STAHL, D II Central / Couthwest Corp STAHL, D M Isham, Lincoln & Beale 80/03/17 9pp
- 8004080247 Discovery rept for Feb 1980 Participated in Ammons Beams.
 Borchelt.Campbell. Yaibiough depositions Inspected DDJ
 documents Received & opposed Central & Southwest motion for
 addl time to imply to interrogatories W/Certificate of SVs
 AHEARN, C D Texas Utilities Co AHEARN, C D Debevoise & Liberman
 BO/03/1/ Spp
- 8004080401 Submits TX Utils Generating Co response to ASLB 800307 request re views on consolidation of proceedings for hearing purposes Urges complete consolidation KNOTTS, J. B. Debevoise & Liberman 80/03/1/ 4pp
- 8004080663 Order confirming results of 800307 oral argument NRC % DOJ joint motion, re-mod of order concerning protection of settlement discussions, glanted in part Parties may not engage in further discovery re-documents included in motion GLASER, M.L. Atomic Safety and Licensing Board Panel B0/03/17 200
- B004210437 Notice of appearance in proceeding Certificate of Svc encl GLAZIER:K M Justice, Dept of B0/03/17 4pp
- 8004090427 Discovery rept for Jan-Feb 1980 Participated in M Drymy deposition No discovery requests instrated Certificate of Svc encl BURCHETTE.N H Texas-Louisiana Electric Cooperative Inc BURCHETTE.N H Northcutt Ely 80/03/19 3pp
- BOO4010517 Order denying NRC 800311 motion to quash subpoons of R Frame TX Utils Generating Co entitled to test ND Lerner credibility by questioning work & documents prepared by Frame for Lerner review WDLFE.S J Atomic Safety and Licensing Board Panel 80/03/20 2pp
- 8004030347 Response in opposition to TX Utils Generating Co.Houston Lighting & Power Co & South West Corp 800313 petitions for directed certification of order compelling production of documents News article ? Certificate of Svc encl CHANANIA.F D. BLUME.M B. HODGDON.A P. Antitrust Division 80/03/20 21pp
- 8004100177 Memorandum in apposition to petitions for directed certification filed by TX Utils Generating Co. Houston Lighting & Power Co. & Central & South Nest Corp et al.re AGLB 800307 order Certificate of Svr encl CYPHERT. S B. DUPBOVIC.D A. GLAZIER.K M. Justice.Dept of 80/03/20 26pp
- BOO4100534 Response to DDJ first set of interrogatories Includes info re TX electric cooperatives & wholesale suppliers Certificate of Svc enc1 + Texas Electric Service Co 80/03/20 21pp
- 8004010262 Clarifies NRC updated response to Houston Lighting & Power first set of interrogatories & request for production of documents BLUME.M B Antitrust Division 80/03/21 2pp
- BOOAO40184 Motion to quash subpoens directed to GN Stagg upon DOJ & NRC joint request Absent evidentiary reliance upon Btagg Sys. Inc work montestifying outside consultants are not subj to discovery pincess, per established rule FRANKLIN:N J Houston Lighting & Power Co 80/03/21 4pp
- --8004040198 Advises that Houston Lighting & Power does not intend to rely on Stagg Sys, Inc studies as part of defense in proceeding NRC & Central & Southwest Corp contensions re Stagg study based on misconception W/Certificate of Svc OREEN, D O Lowenstein, Newman, Reis, Arelrad & Toil 80/03/21 7pp
- 8004160111 Responds to NRC & Central & South West Corp comments re consolidation Severance arguments based on belief that util will rely on study by Stagg Sys.Inc as part of defense Util will not rely on Stagg study Certificate of Svc encl OREEN,D G Lowenstein, Newman, Rois, Axelrad & Toll 80/03/21 App
- 8004030360 Response by Public Utils Board of City of Brownsville,TX in opposition to nonconsolidation of proceeding suggested by NRC & Central & Bouth West Corp In event of separation. South TX case should be heard first Certificate of Svc encl SPIEGEL,0 Texas, State of 80/03/24 9pp

- 8004250049 Response in apposition to Public Utils Board of City of Brownsville TY 800317 comments requesting admittance as party in consolidated profeeding Statement of Interest untimely 8 vague Certificate or Svc encl AHEARM C D Teas Utilities Cenerating Co AMEARM C D Debevoise & Liberran 80/03/25 Tpp
- 8004:00271 Motion to compel production of documents by Southwest TX Electric Cooperative me subpoend directed to general manager E McGinnes Requests to strike McGinnes 800:221 deposition if documents are not produce! Wilraft subpoend & documentation GREEN.D O Housion Lighting & Power Co # Baker & Botts * Lowenstein.Newman.Reis Aleirad & Toll 80/03/26 18pp
- --B004100278 Motion to compel production of documents by Midwest Electric Cooperative re subpoens directed to general manager. P. Wetiel Requests to strike Wetiel rescheduled deposition if documents are not produced Wisubpoens & Certificate of Svc. GREEN.D.G. Houston Lighting & Power Co. * Baker & Botts. * Lowenstein.Newman.Ress.Aielrad & Toll. 80/03/26. 15pp
- 8004080420 Application for issuance of subpoens directed to Gulf States Utils Co re settlement documents Documents not produced in response to 790709 J 80018 subpoens Urges production to extent allowed by ASLAS BLUME, M B Antitust Division 80/03/27 2pp
- --8004080424 Subpoena directed to Gulf States Utils Co requesting settlement documents for insp & copying in Washington, DC on 800402 Subpoena may be quashed or modified upon request Certificate of Svc encl HILLER.M E Atomic Safety and Licensing Board Panel 80/03/27
- 8004090126 Order denying Houston Lighting & Power 800321 motion to quash subpoena directed to GW Stagg upon DOJ request Prior rulings,re nontestifying outside consultants.do not apply in this proceeding due to relevancy of Stagg studies WOLFE,S J Atomic Safety and Licensing Board Panel 80/03/27 3pp
- 8004210386 Forwards Houston Lighting & Power 800327 mptions to compet production of documents by NRC expert witnesses RH Hartley & NC Lerner Requests 800331 conference call prior to scheduled depositions
 FRANKLIN.H J Lowenstein, Newman, Reis, Axelrad & Toll 80/03/27 ip
- --8004210392 Motion to compet testimonial questions answered by NRC expert witness RM Hartley Discoverability of questions established on Pages 421-423 of prehearing conference transcript re ASLB 800625 order FRANKLIN,W J Houston Lighting & Power Co FRANKLIN,W J Lowenstein Neuman, Reis, Axeirad & Toll * Baker & Botts 80/03/27 App
- --8004210394 Submits preparation study for 800220-21 meeting re intraregional interconnections transmission lines & other pooling matters HARTLEY.R H Affiliation Unknown 80/01/29 25PP
- --8004210397 Forwards RH Hartley 800211 memo to NRC re 800129 answers in preparation for 800220-21 meeting Requests quastions to which answers were stated per rule established in 790601 prehearing conference Pages 421-423 of transcript encl FRANKLIN.W J Lowenstein.Newman.Reis.Axelrad & Toll 80/03/20
- --B004210400 Hotion to compel electric util industry testimonial antitrust analyses prepared by NRC expert economic witness N Lerner re Hidland proceeding Urges production per prior rulings, subj to encl protective order W/Certificate of Svc FRANKLIN, W J Houston Lighting & Power Co FRANKLIN, W J Lowenstein, Newman, Reis, Axelrad & Toll e Baker & Botts B0/03/27 14pp
- 3004090123 Order giving parties one with o provide addit authority re existence of settlement privilege Memoranda addressing issue should be received by 800404 & response thereto by 800409 BISMOP.C J Atomic Gafety and Licensing Appeal Panel 80/03/28 2pp
- 8004090456 Protective order, in favor of Houston Lighting & Power, reconfidential corporate study produced in response to NRC initial interrogatories Parties may challenge claimed confidentiality by seeking judicial review per FDIA WOLFE, S.J. Atomic Safety and Licensing Board Panel 80/03/31 4pp
- 8004100243 Order granting in part NRC motion to compel add1 responses by Houston Lighting & Power (MLSP) Accords confidentiality to N Lerner analysis re Midland settlement Grants HL&P motion to compel NRC questions re RH Hartley testimony WOLFE.S J Atomic Safety and Licensing Board Panel 80/03/31 3pp

- 8004100428 Public Utils Board of Brownsville motion for leave to file affidavit as amicus curiae Brownsville is party to proceeding but has not formally appeared in appellate proceeding Certificate of Sv. encl SPIEGEL, O Brownsville, TX SPIEGEL, O Spiegel & McDiarmid 80/03/31 Bpp
- ---B004100430 Affidavit of RE Roundtree general manager of Brownsville
 Public Utils Board is agreement among TX "10Us" for
 const of two dc interstate ties of 500 HM & 250 MM
 Brownsville prepared to enter settlement negotilations
 ROUNDTREE.R E Brownsville.TX B0/03/27 3pp
- 8004080172 Updated response to Houston Lighting & Power second set of interrogatories & TX Utils first set of interrogatories Anticipates RE Corder participation as witness re areas discussed during Conder deposition Cestificate of Svc encl CHANANIA.F D. Antitrust Division 80/04/01 5pp
- 8004100240 Order requesting parties in directed certification proceeding to respond to Utils Board of City of Brownsville, TX 800331 motion by 800409
 BISHOP, C.J. Aromic Safety and Licensing Appeal Panel 80/04/02
- BOO4180151 Forwards joint motion for extension of time Motion is joined in by all parties to proceeding except DOJ & City Public Utils Board of Brownsville, TA WKOTTS, J B Debevoise & Liberman BO/04/02 ip
- --8004180167 Joint motion for 30-day extension for all procedural dates
 Motion is based on progress of meaningful settlement
 negotations which could lead to resolution of part or all of
 proceedings Certificate of Bvc encl
 CHANANIA.F D Antitrust Division COPELAND.J Q Houston Lighting
 & Power Co STAHL.D M Central Power & Light Co 80/04/02 App
- 8004140003 Third set of addl answers to NRC 790115 initial interrogatories Simmons & Woodson are expected to testify reinterconnections
 FRANKLIN, W J Houston Lighting & Power Co * Baker & Botts
 Lowenstein, Newman, Reis, Areirad & Tail 80/04/03 2pp
- --9004:1000B Second supplemental answers to Central Power & Light Co 790223 interrogatories Simmons & Woodson are expected to testify re interconnections Certificate of Svc encl FRANKLIN.N J Houston Lighting & Power Co * Baker & Botts * Lowenstein. Newman. Reis, Azelrad & Toll 80/04/03 &pp
- 8004150032 Forwards opposition by Brownsville to joint motion for estension of time & request for prehearing conference, miscellaneous atty & util currespondence affidavit & Brownsvijle rate estimates Certificate of Suc encl
 SPIEOEL.O, POIRICE, M.R. Spiegel & McDiarmid 80/04/03 19pp
- --8004150050 Opposition to joint motion for extension of time & request for prehearing conference Brownsville has been excluded from negotiations on which request for extension is based Cartificate of Svc encl SPIECEL.9 . POIRIER.M R Brownsville.TX BPIECEL.0 Spiecel & McDiarmid 80/04/03 2pp
- 8004230366 Forwards Houston Lighting & Power 800403 motion to compel production of documents & JW Wilson testimony by Public Utils Board of City of Brownsville, TX Proposes expedited schedule to permit completion of expert witness discovery GREEN.D & Lowenstein.Newman.Reis.Axelrad & Toll 80/04/03 2pp
- --B004230074 Motion to compel production of documents & JW Wilson expert testimony by Public Utils Board of City of Brownsville, TX
 If motion not granted requests order precluding Wilson from hearing W/proposed order re schedule & Certificate of Svc
 BALDMIN.JM Houston Lighting & Power Co * Baker & Botts *
 Lowenstein, Newman, Reis. Axelrad & Toll 80/04/03 11pp.
- 8004100126 Memorandum in response to ASLAB 800328 order requesting add1 authority re recognition of settlement privilege Courts 3 case law do not recognize existence of privilege Certificate of 8vc encil BLUME. H B . HODODON. A P Antitrust Division 80/04/04 App
- 8004150083 Order setting 800411 conference at NRC Hearing Room, Bethesda,MD Oral argument will address NRC & DDJ goint motion for 30-day extension > Houston Lighting & Power 800403 motion to compel Utils Board of Brownsville HOLFE,B J Atomic Safety and Licensing Board Panel 80/04/04 2p

- 8004170312 Memorandum of authorities re discoverability or settlement documents Urges reversal of ASLB 800307 ruling due to privilege recognized per case law & federal rules of evidence Supporting documentation & Certificate of Svc encl BOUKNIGHT, J A . GREEN, D G . Houston Lighting & Power Co BOUKNIGHT, J A . Daker & Botts 80/04/04 Bipp
- 8004170340 Response stating no position re joint motion for 30-day extension in proceeding filed by NRC.Central & South West Corp.Houston Lighting & Power, TX Utils Generating Co. City of Austin & Other parties Certificate of Syc encl DDPSOVIC, D A , LUGUE, N , PARMENTER, F Justice. Dept of 80/04/04
- B004220128 Memorandum of authorities in support of settlement privilege Documents prepared in connection w/settlement process should be protected from discovery under work product privilege Certificate of Svc encl STAHL, D Central & Southwest Services. Inc STAHL, D Isham. Lincoln & Beale 80/04/04 10pp
- 8004240043 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents that wtil consents to extension O'NEILL, R A Southwest Texas Ejectric Comperative O'NEILL, R A Miller, Balis & O'Neil 80/04/04 3pp
- 8004240045 Certifies svc of consent motions for extension to respond to Houston Lighting & Power Co motion to compel production of documents from Midwest Electric Cooperative & Southwest TX Electric Cooperative, on 800404

 O'NEILL, R A Miller, Balis & O'Neil 80/04/04 4pp
- 8004240053 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents Util consent to extension O'NEILL, R A Southwest Texas Electric Cooperative O'NEILL, R A Miller, Balis & O'Neil BO/04/04 3pp
- 8004240173 Memorandum.per ASLAB 800328 request, stating add1 authorities re directed certification of settlement document issue Treatises & modern trend hold inadmissibility of privileged documents as evidence Cartificate of Bvc encl KNOTTB.J B . AMEARN.C D Texas Utilities Generating Co KNDTTB,J B Debevoise & Liberman 80/04/04 22pp
- 8004290106 Advises of arrangement to deliver Houston Lighting & Power pleadings moving to compel documents re E McGinnes & P Wetzel subpoenas Consents to 14-day extension for responses Certificate of Suc encil OREEN, D & Lowenstein, Neuman, Reis, Axelrad & Toll 80/04/04 Spp
- 8004100552 Motion to issue order compelling Southwest TX Electric Cooperative & general manager E McGinnes to produce for insp & copying, documents set forth in motion Draft subpoena & Certificate of Svc encl OREEN.D.O Houston Lighting & Power Co OREEN.D.O Baker & Botts 80/04/07 1980
- --8004100860 Motion to issue order compelling Midwest Electric Cooperative & general manager P Wettel to produce, for insp & copying, documents responsive to subpoena served on Wetzel Draft subpoena & Certificate of Svc encl OREEN, D O Houston Lighting & Power Co GREEN, D Q Baker & Botts 80/04/07 15pp
- 8004230154 Motion to practude DOJ from filing principal brief re ASLAD 800328 order DOJ failed to file principal brief by 800404 DOJ seeks to obtain unfair tactical advantage by untimely filing DOJKNIGHT, J A . GREEN, D G Houston Lighting & Power Co BOUKNIGHT, J A . Baker & Botts 80/04/07 3pp
- --8004230162 Order directing all parties to furnish ASLAB w/addl authority re privilege against discovery of documents Memoranda due on 800404 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/28 ópp.
- 8004240061 Motion for ASLB to reconsider extending procedural dates for 30 days. Requests 800408 conference call to rule on extention TX Utils Oenerating Co is only party to be prejudiced by extending dates CHANANIA:F Antitrust Division BOUKNIGHT. J A Houston Lighting & Power Co BURCHETTE. H H Texas-Louisiana Electric Cooperative, Inc 80/04/07 3pp
- --8004240071 Supplemental argument & representations Addl time required by utils to make progress in settlement discussions.

 Discussions began Sept 1979 Parties are optimistic about possibility of reaching quick settlement BURCHETTE, W H Texas-Louisians Electric Cooperative, Inc KNOTTS, J B Texas Utilities Generating Co 80/04/07 5pp

- 8004210147 Discovery rept for Mar 1980 Deposed JA Bruggeman, JT Wenders, AJ Wood & DA Springs Moved to compel NRC deposition of ND Lerner Responded to DOJ motion to compel supplemental answers to first interrogatories W/Certificate of Svc FRANKLIN.W J Houston Lighting > Power Co FRANKLIN.W J Lowenstein, Nowman, Reis, Aielrad & Toll 80/04/08 App
- 8004190157 Response to Houston Lighting > Power.TX Utils Generating Co & Central & South West Cos 800404 memoranda of authorities re spttlement privilege Urges affirmation of ASLB 800307 order re production of documents W/Certificate of Svc CHANANIA.F D. HODODON.A P Antitrust Division 80/04/09 10pp
- 8004170347 Response to Public Utils Board of City of Brownsville,TX 800331 motion to file RE Roundtree affidavit as amicus curlae Disclasure of documents should not affect potential for settlement Certificate of Sic encl CHANANIA.F D Antitiust Division 80/04/09 6pp
- G004220021 Response to Public Utils Board of City of Brownsville,TX 800331 motion to file Roundtree affidavit Requests to file counter-affidavit re status or settlement if Roundtree affidavit is accepted by ASIAB Certificate of Svc anci KNDITS,J 8 Toxas Utilities Generating Co 60/04/09 App
- B004220132 Response to Houston Lighting & Power 800403 motion to compel production of documents & deposition of Public Utils Board of City of Brownsville.TX Does not appose motion if subj to encl protective order Appearance & Certificate of Svc encl ROTH.A J , JACOBS, J C Florida Cities ROTH.A J Spiegel & McDiarmid 80/04/09 14pp
- B004240562 Response in opposition to NRC 800404 memorandum of addl authorities re existence of settlement documents privilege Congress did not intend to freeze developing law of privilege W/Certificate of Svc KNOTTS, J B , AHCARN.C D Teras Utilities Generating Co KNOTTS, J D Debevoise & Liberman 80/04/09 Bpp
- 8004170351 Order granting 30-day extension for procedural matters, amending ASLB 791214 order to discovery schedule & directing consolidation of proceedings for pretrial & evidentiary hearings Consent motions for extension to 800404 granted MILLER.N E Atomic Safety and Licensing Board Panel 80/04/10
- 8004210141 Order denying Houston Lighting & Power motion seeking to preclude DOJ memorandum of addl authorities filed per ASLAB 800328 order BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/04/10
- 8004230033 Forwards TX Utils Generating Co affidavit of LF Filar requested during 800409 oral argument KNQTTS, J B Debeyoise & Liberman 80/04/10 Ip
- --8004230041 Affidavit stating that Central & South West Corp. Houston Lighting & Power Co & TX Utils Co Sys have reached agreement in principle re interconnection disputes Agreement may form basis for discussions w/other parties M/Certificate of Bvc FIKAR.L F Tevas Utilities Generating Co 80/04/10 Spp
- 8004230002 Responds to Public Utils Board of City of Brownsville,TX opposition to joint motion for extension of time Objects to alleged refusal to wheel & submits ML Borchelt affidavit in response to alleged exclusion from discussions STAHL.D M Central & Gouthwest Corp STAHL.D M Isham, Lincoln & Beale 8D/04/11 3pp
- --8004230007 Affidavit responding to Public Utils Board of City of Brownsville,TX allegation that Brownsville has been excluded from discussions re interconnection Clarifies statement made at 800327 meeting Cerulificate of Svc encl BORCHELT.M L Carolina Power & Light Co 80/04/10 iOpp
- 8004290227 Discovery rept for Mar-Apr 1980 Participated in FJ Meyer, HH Moodson & GN Stagg depositions Filed opposition to petitions for directed certification & reversal of ASLB 800307 order Joined other parties in moving for procedural extension CHANANIA: F D. BLUME, M B. HODDON, A P Antitrust Division 80/04/25 3pp
- N Antitrust hearing transcripts
- 8004030346 Pages 690 \$ 691 ommitted from original transcript * Commission 80/03/07 3pp
- BO04150298 Transcript of 800409 hearing in Bethesda, MD Pp 1-140 * Commission 80/04/09 140pp

- Q Inspection reports. IF fulletins ? correspondence
- 8004010147 Responds to IE (ulletin 79-28, "Possible Malfunction of NAMCO Model £4180 timp" ,witches at Elevated Temps "
 Requests extension until 800331 to inspect safety-related equipment 5 inspect no essay corrective actions
 OARY, R. J. Teras Utilitie, Generating Co. 80/01/23 Ip
- 8004290492 Discusses IE Insp Rept, 59-445/80-01 & 50-446/80-01 on 800118 ? forwards notice of violation SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/01/23 2pp
- --8004290498 Notice of violation from insp on 800118 Noncompliance noted procedures for securing Class IE battery chargers inappropriate Fillet welds too small due to natl thickness * Region 4 Dallas, Reactor Construction & Engineering Support Branch 80/01/23 Ip
- 8004140044 Forwards IF Insp Repts 50-445/80-05 % 50-446/80-05 on B00214-15 % 19-21 No mancompliance noted SEIDLE-W C Region 4. Dallas, Reactor Construction & Engineering Support Draich 80/02/2/ 2pp
- --8004160050 IE Insp Repts 50-445/80-05 % 50-446/80-05 on 800214-15 & 19-21 No noncompliance noted Major areas inspected followup review of Unit I RCPB piping welding & of GA/GC records re Unit 2 containment bldg structural concrete installations HALL.R C Region 4. Dallas. Reactor Construction & Engineering Support Branch CROSSMAN.W A. TAPIA.J I Region 4. Dallas. Office of the Director 80/02/28 5pp
- 8004210175 Forwards IE Insp Pepts 50-445/80-06 & 50-446/80-06 on B00220-21 No noncompliance noted MADSEN O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/29 ip
- --BO04210179 IE Insp Repts 50-445/B0-06 / 50-446/B0-06 on 800220-21 No nuncompliance noted Major areas inspected preoperational testing GA > operational staffing WESIERMAN.TF . SMITH.R Region 4. Dallas. Office of the Director B0/02/29 5pp
- 8004220232 Forwards IE Insp Repts 50-445/80-04 & 50-446/80-04 on 800211-15 No noncompliance noted SEIDLE W C Region 4. Pallas, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- -8004220244 [E Insp Repts 50-445/80-04 & 50-446/80-04 on 800211-15 No nancompliance noted Major areas inspected procedures for controlling changes to approved design documents HALE,C J . CROSSMAN,W A . DRICKLEY,R H Region 4. Dallas, Vendor Inspection Branch 80/02/28 Bpp
- 8004210432 Advises that numbers of insp repts transmitted by 800229 ltr should be corrected to read 50-445/80-06 % 50-446/80-06 MADSEN,G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 60/03/10 ip
- --8004210443 Forwards IE Insp Repts 50-445/80-06 & 50-446/80-06 on 800220-21 No noncompliance noted MADSEN.G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/29 ip
- --8004210438 IE insp Repts 50-445/80-05 % 50-446/80-05 an 800220-21 No noncompliance noted Major areas inspected preoperational testing QA & operational staffing WESTERFAN.T F Region 4. Dallas, Reactor Operations Nuclear Support Branch SMITH.R Region 4. Dallas. Office of the Director 80/02/29 5pp
- 8004040081 Act receipt or 800305 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-03 \$ 50-446/80-03 SEIBLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/03/11 1p
 - 3004040083 Responds to NRC 600207 IE Insp Repts 50-449/80-03 & 50-446/80-03 Catrective actions engineering personnel reviewed cable Jubrication requirements w/key const personnel involved w/cable pulling GARY.R J Texas Utilities Generating Co 60/03/05 3pp
 - J404009B Ack receipt of B00220 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-445/79-31 & 50-446/79-29 SEIDLE.N C Region 4, Dallas, Reactor Construction & Engineering Support Branch B0/03/11 ip

- --8004040101 Responds to HRC 800127 IE Insp Repts 50-445/79-31 & 79-446/79-29 Corrective actions tackwelds removed General Piping & Welding Procedure CP-CPH-6 9 revised & reorganized OAR's R J Teras Utilities Generating Co 80/02/20 3pp
- 8004250079 Forwards IF Investigation Repts 50-445/80-02 \$ 50-446/80-02 on B00121-0205 No noncompliance noted SCIDLE:W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/03/20 2pp
- 8004240225 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required SEYFRIT, X V Region 4. Dallas, Office of the Director 80/04/02 by
- 8004220320 Forwards 1E Circular 80-07, "Problems W/HPCI Turbine 0:1 Eys " No written response required SEYFRIT, K V Region A. Dallas, Office of the Director 80/04/03 to
- 80042207/9 Forwards IC Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe" Action required SEYFRIT, K. V. Region 4. Dellas, Office of the Director 80/04/04 in
- 8004220208 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Panetration Welds " Written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/07
- S Reportable accurrences, LERs & related correspondence
- 8004010275 Forwards deficiency rept re control board welded connections
 OARY, R J Texas Utilities Generating Co 80/03/21 ip
- --8004010279 Deficiency rept on 800228. GA inspressed control board welded connections not meeting seismic design criteria Cause unstated Control board suppliers & AE reviewing as-built weld configurations Rework will be completed by 800501 * Texas Utilities Generating Co 80/03/21 2pp
- 8004150199 Forwards deficiency rept re control board welded connections GARY,R J Texas Utilities Opnerating Co 80/03/21 ip
- --B004150202 Deficiency rept re control board welded connections
 Specified 0-inch spacing of welds from end to end was found
 to vary from sixteen to eighteen inches on several panels
 As-built weld configurations under review

 Texas Utilities Generating Co 80/03/21 2pp
- 8004010296 Forwards rept of actions taken to correct deficiencies in mfg of discs for svc water control valves Supporting documentation is available at site for inspector review GARY.R J Teras Utilities Concreting Co 80/03/25 2pp
- 8004070278 Supplemental RO violation found re piping min wall thickness Cause unstated Engineering review in progress Progress rept will be submitted by 800418 GARY.R J Texas Utilities Generating Co 80/03/28 lp
- 9004220423 Interim deficiency rept re piping min wall thickness Review of weld & base metal repair records is continuing Another progress rept will be submitted by \$000620 OARY.R J Texas Utilities Generating Co 80/04/15 ip
- 8004290250 Forwards deficiency rept is concrete honeycomb condition encountered in steam generator compartment walls of Unit 2 reactor containment bldg GARY.R J Texas Utilities Generating Co 50/04/21 ip
- --8004270254 Deficiency rept re concrete honeycombing in steam generator compartment walls of Unit 2 reactor containment bldg Consultant survey showed no critical internal defects Util to repair condition w/dry-pack mortar, grout & concrete * Teras Utilities Generating Co 80/04/21 3pp
- 8004290271 Interim deficiency rept re installation of drilled-in expansion anchors Matter was corrected 790616 by revision to installation procedure Formal rept to be filed by 801215 OARY.R J Teras Utilities Generating Co

DOCKETED ITEMS

- 80042904ii Provides status of interim deficiency rept re installation & insp requirements for Class V non-nuclear safety-related pising supports Final rept will be forwarded by 800715 GARY.R J Teras Utilities Generating Co 80/04/21 ip
- 8004290430 Forwards interim deficiency rapt re installation & insp of whiled conduit supports Final rept to be filed by 800801 GARY.R J Texas Utilities Generating Co. 80/04/21 1p
- ~~6004270437 Interim deficiency rept re installation & insp of welded conduit supports Major support was fabricated w/o formalized instructions & insp records for number of smaller welded supports were not directly traceable to as-built conditions GARY,R J Texas Utilities Generating Co 80/04/21 ip
- T Hearing transcripts on non-antitiust matters
- 8004210312 Transcript of 800327 hearing in Bethesda. MD Pp 1-127

 * Atomic Bafety and Licensing Appeal Panel 80/03/27 130pp

DOCKET 50-448 DOUGLAS FOINT NUCLEAR STATION, UNIT 1

- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emorgency planning & preparedness distributed as Board notification OOSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp

M Antitrust correspondence

8004170340 Response stating no position re joint motion for 30-day extension in proceeding, filed by NRC, Central & South West Corp, Houston Lighting & Power, TX Utils Generating Co. City of Austin & other parties Certificate of Syc encl DDP80VIC, D A , LUGUE, N , PARMENTER, F Justice, Dept of 80/04/04

DOCKET 50-449 DOUGLAS PUINT NUCLEAR STATION, UNIT 2

- O Adjudicatory correspondence
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 00951CKL V Office of the Executive Director for Operations 90/04/02 34pp
- ## Antitrust correspondence
- 8004040072 Notice of appearance in proceeding Certificate of Svc encl FABRIKANT, R Justice Dept of 80/02/25 4pp
- 8004080557 Requests pratiial conforence to clarify procedural matters pt ASLB 791214 order.filing testimony summaries & designation exhibits CYPHERT.8 B Justice.Dept of MILLER.M J Central & Southwest Cap 80/03/05 2pp
- 8004090204 Discovery rept for Feb 1980 Deposed W Taylor, M Hebb.DE Simmons & EL Matson Participated in depositions noticed by TX LA Electric Cooperative & City of Brownsville, TX Reviewed Diamond Shamrock documents Filed application for subposnas CYPHERT, 6 B Justice, Dept of 60/03/05 Spp
- 8004170351 Order granting 30-day extension for procedural matters, amending ASLB 791214 order re discovery schedule & directing consolidation of proceedings for pretrial & evidentiary hearings Consent motions for extension to 800404 granted MILLER, M E Atomic Safety and Licensing Board Panel 80/04/10 500

DOCKET 90-452 GREENWOOD ENERGY CENTER, UNIT 2

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management

- G Adjudicatory correspondence
- 8004030026 Remorandum of understanding between RRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET 50-453 GREENWOOD CHERG, CENTER, UNIT 3
- A Application/construction stage documents & correspondence
- B004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance te methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OCSBICK, L V Office of the Ejecutive Director for Operations 80/04/02 34pp
- DOCKET 50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSB, D.F. Division of Project Hanagement 80/02/05 7pp
- 8004040017 Submits addl guidance to KURFG-0588. "Interim Staff Position on Environ Qualification of bafety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS, D.F. Division of Project Management B0/02/21 3pp
- 80001230058 Requests info to auxiliary feedwater sys per Builetins & Orders Task Force review of TMI-2 accident info should be provided as amond to application Submittal schedule should include MRC approval prior to issuance or DL Wrenci ROSS: DF Division of Project Management 80/03/10 53pp
- B004090155 Summary of 800311 meeting w/utils, Hostinghouse & Sargent & Lundy re Westinghouse optimized fuel assembly Comm Ed requested to amend FSAR as soon as possible to show plant will use optimized fuel assembly KINTNER, L. L. Light Water Reactors Branch 1 80/03/18 8pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A, GA program Revisions reflect recent organization title changes NAUGHTON, W.F. Commonwealth Edison Co. 80/04/02 1p
- --8004150328 Revised pages constituting Revision 13 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co

F

- 8004020033 First interrogatories directed to NRC includes request for specific description of deliation, honconformity or change occurring after CP issuance Proof of 5vc encl. CHERRY, M M. League or Women Voters of Rockford, IL. CHERRY, M M. Cherry, Fight ? Manter 80/03/12 10pp
- 8004080429 Forwards League of Momen Votets of Rockford, IL interrogatories * motion sceling ASLB authorization W/o interrogatories CHERRY, M.M. Cherry, M. N. / Cherry, Flynn & Kanter 80/03/12 to
- --8004080435 Motion urging presiding officer to issue order requesting NRC to answer intervenor 800342 interrogatories Proof of Svc enci CHERRY, N. M. League of Nomen Voters of Rockford, IL. CHERRY, M. M. Cherry, M. M. Zoberry, Flynn & Kanter 80/03/12 App
- 8004090177 First sot of interrogatories includes questions to intervenors' revised contentions? deviations occurring since issuance of CP Proof of svc each CHERRY,M M League of Wimmi Voters of Rockford,il CHERRY,M & Cherry, M M /Cherry, Flynn & Kanter 80/03/12 10pp
- 8004100322 Objects to intervenor League of Women Voters of Rockford.IL 800312 first set of interrogatories ASLS has not ruled on admissibility of proposed contentions to which interrogatories refer Certificate of Svc encl MURPHY.P M Commonwealth Edison Co MURPHY.P M Isham, Lincoln & Beale 80/03/19 3pp
- BOOAGBOA2B Mution for order setting BOOAGB for applicant & BOOA25 for NRC to respond to Roctford League of Women Voters revised contentions Time is needed to perform preliminary evaluation re possible stipulation Certificate of Svc encl MURPHY.P M Commonwealth Edison Co MURPHY.P M Isham, Lincoin & Beale BO/O3/20 App
- 8004090448 Order setting 800418 for Comm Ed to respond to League of Homen Voters of Rockford revised contentions
 MILLER, M.E. Atomic Safety and Licensing Board Panel 80/03/26 ip
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification 005510k/L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004290217 Response to intervenor Roctford League of Homen Voters 800310 revised contentions Recommends acceptance of 19 separate contentions 5 two consolidation contentions Centificate of Svc encl KARMAN.N., CODDARD.R J. Hearing Dranch 2 80/04/25 23pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004080397 Forwards affidavit stating that distribution of Amend 25 to FSAR has been made in accordance w/RS Boyd 791020 1tr NAUGHTON.W F Commonwealth Edison Co 80/04/01 2pp
- a inspection reports. If Bulleting & correspondence
- 8004280066 Forwards 16 Insp Repts 50-454/80-02 & 50-455/80-02 on 800207-08 No moncompliance noted FIDRELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/06 2pp
- --8004280074 IE Insp Repts 50-454/80-02 t 50-455/80-02 on 800207-08 No noncompliance noted Major at ear inspected licensee corrective actions on previous insp findings & storage of safety-related mechanical t electrical matts & components HILLIAMS.C C . KONKLINJ E , JONES.C E Region G. Chicago. Office of the Director 60/03/04 lipp
- 04100118 Forwards IE Info Notice 80-08, "States Co Sliding Link lectrical Terminal Block " No specific action or response quired PPLES. I & Region 7. Chicago Desires of the Diseases. 200000
- quired
 PPLER.J G Region 3. Chicago, Office of the Director 80/03/07
 ,
- 4280031 Forwards 1E Insp Repts 50-454/80-03 & 50-455/80-03 on 300220.21 & 27 No moncompliance mated FIDRELLIA Region 3. Chicago. Reactor Construction & Engineering Support Branch 60/03/12 2pp
- --8004280039 lE Insp Repts 50-454/80-03 \$ 50-455/80-03 on 800220,21 & 27 No noncompliance noted Major areas inspected RCPB piping work activities welding & procedures DANIELSON.D H Region 3, Chicago, Reactor Construction & Engineering Support Branch LEE,E W Region 3, Chicago, Office of the Director 80/03/10 app

- 8004)40119 Forwards response to IF Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escaps PEOPLES,D L Commonwealth Edison Co 80/03/20 5pp
- 8004150159 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block "alve " No specific action or response necessary KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/03/31
- 8004080686 Forwards IE Cirrular 80-05, "Emergency Diesel Generator Lubricating Dil Addition % Onsite Supply " No written response required KEPPLER.J G Region 3. Chicago, Offica of the Director 80/04/01
- 8004150014 Forwards IE Info Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- GOO4180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," (nadvertently emitted from 800306 transmittal KEPPLER, J. G. Region 3, Chicago, Office of the Director 60/04/02
- BO04220093 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER.J G Region 3, Chicago, Office of the Director B0/04/02 to
- 8004220324 Forwards IE Corcular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J. G. Region 3, Chicago, Opfice of the Director 80/04/03 in
- 8004220069 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Helds " Hritten response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/09 to
- BD04230224 Forwards IE Bullotin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director BO/04/07 to
- S Reportable occurrences. LERs & related correspondence
- 8004070228 Ack receipt of 800227 second interim rept re failure of post-tensioning tendon field anchor heads Rescheduled date of 800515 for submittal of final rept is acceptable FIDRELLI.9 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/19 ip
- DOCKET 50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREQ-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re-methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re Auriliary feedwater sys par Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application. Submittal schedule should include NRC approval prior to issuance of Ot. W/encil ROSS.DF Division of Project Management 80/03/10 53pp
- BDD4150316 Forwards revised pages constituting Revision 13 to CE-1-A, GA program Revisions reflect recent organization title changes.

 NAUOHYUN, W F Commonwealth Edison Co 80/04/02 1p
- --B004150328 Revised pages constituting Revision 13 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-1-A R13 80/04/04 7pp

- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 771226 Itr.has been postponed pending OAO clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11
- BOO4140118 Forwards request for add1 info consisting of fifth set of round one questions re safeguards contingency plan Encl withheld (ref 10CFR2 790)
 RUBENSTEIN,L B Light Water Reactors Branch 4 80/03/28 2pp

@ Adjudicatory correspondence

- B004100027 Notice of appearance in proceeding Certificate of Svc encl LEVIN.K F DeKalb Area Alliance for Responsible Energy LEVIN.K F Sinmissippi Alliance for the Environment (SAFE) LEVIN.K F Beatty, Levin: Holland, Dasofin & Barsany B0/02/27 Jpp
- B004090411 Discusses League of Homen Votors of Rockford B00213 motion re admissibility of contentions Requests ASLB to vacate 800221 order & permit filing of revised contentions on 800310 Proposes schedule for briefing MURPHY.P M Isham, Lincoln & Beale B0/03/05 App
- 8004020033 First interrogatories directed to NRC Includes request for specific description of deviation, nonconformity or change occurring after CP issuance Proof of Svc encl CHERRY, M M League of Women Voters of Rockford, IL CHERRY, M M Cherry, M M /Cherry, Flynn & Kanter 80/03/12 10pp
- 8004080429 Forwards League of Women Voters of Rockford, IL interrogatories & motion seeking ASLB authorization W/o interrogatories Cherry, M M /Cherry, Flynn & Kanter 80/03/12 1p
- ~-8004080435 Motion urging presiding officer to issue order requesting NRC to answer intervenor 800312 interrogatories Proof of Svc encl 8vc enc: CHERRY,M M. League of Women Voters of Rockford,IL Cherry, M. M./Cherry, Flynn & Kanter B0/03/12 4 CHERRY, M M 4pp
- 8004090177 First set of interrogatories includes questions re intervenors' revised contentions & deviations occurring since issuance of CP Proof of svc encl CHERRY, M M League of Women Voters of Rockford, IL CHERRY, Cherry, M M /Cherry, Flynn & Kanter 80/03/12 10pp CHERRY, M M
- 8004100322 Objects to intervenor League of Women Voters of Rockford.IL 800312 first set of interrogatories ASLO has not ruled on admissibility of proposed contentions to which interrogatories refer Certificate of Svc encl MURPHY.P M Commonwealth Edison Co MURPHY.P M Isham, Lincoln & Beale 80/03/19 3pp
- 8004080428 Motion for order setting 800418 for applicant & 800425 for NRC to respond to Rockford League of Women Voters revised contentions Time is needed to perform pre-liminary avaluation re-possible stipulation Certificate of Svc encl MURPHY.P M Commonwealth Edison Co MURPHY.P M Isham, Lincoln & Beale 80/03/20 4pp
- 8004090448 Order setting 800418 for Comm Ed to respond to League of Women Voters of Rockford revised contentions MILLER, M E Atomic Bafety and Licensing Board Panel 80/03/26 ip
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSBIGK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004290217 Response to intervenor Rockford League of Women Voters 800310 revised contentions Recommends acceptance of 19 separate contentions & two consolidation contentions. Certificate of Svc enc1 KARMAN, M., GODDARD, R.J., Hearing Branch 2, 80/04/25 23pp
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8004080397 Forwards affidavit stating that distribution of Amend 25 to FBAR has been made in accordance w/RB Boyd 791020 ltr NAUOHTUN.W F Commonwealth Edison Co BO/04/01 2pp

- Q Inspection reports, If Bulletins / correspondence
- 8004280066 Forwards IF Inop Repts 50-454/80-02 \$ 50-455/80-02 on #BOO207-08 No nancompliance noted
 #IORELLI, G Region 3, (bicago, Reactor Construction & Engineering
 Support Branch 80/03/06 2pp
- --8004280074 [E Insp Repts 50-454/80-02 \$ 50-455/80-02 on 800207-08 No noncompliance noted Major areas inspected licensee corrective actions on previous insp findings & storage of safety-related mechanical & electrical matls / components WILLIAMS, C C , KONKLIN. J E , JONES. C E Region 3, Chicago. Office of the Director 60/03/04 llpp
- 8004100118 Forwards IE Info Notice 80-06, "States Co Stiding Link Electrical Terminal Block' No specific action or response KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/03/07
- 8004280031 Forwards If Insp Repts 50-454/80-03 & 50-455/80-03 on 800220.21 & 27 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/12 App
- --8004280037 IE Insp Repts 50-454/80-03 & 50-455/80-03 on 800220,21 & 27 No noncompliance noted Hajar areas inspected RCPB piping work activities:weldsing & procedures DANIELSON.D H Region 3. Chicago, Reactor Construction & Engineering Support Branch (EE,E W Region 3, Chicago, Office of the Director 80/03/10 App
- 8004140119 Forwards response to IE Bulletin 80-03, 'Loss of Charcoal from 8td Type II.Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal grainule escape
 PEOPLES.D L. Commonwealth Edison Co 80/03/20 Spp
- 8004150159 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV ? Block Valve " No specific action or response necessary Repelet. J Q Region 3. Chicago, Office of the Director 80/03/31 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/03/31
- BD04080686 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written rasponse required Region 3, Chicago, Office of the Director 80/04/01 KEPPLER, J G
- 8004150014 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180030 Forwards attachments to IE Circular 80-03. "Protection From Toxic Gas Haiards." inadvertently omitted from 800305 transmittal KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004220093 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/04/02
- B004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER. J 0 Region 3. Chicago, Office of the Director B0/D4/03
- 8004220069 Forwards IC Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/04/09
- 8004230224 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Action required KEPPLER. J G Region 3. Chicago. Office of the Director 80/04/07
- 8 Reportable occurrences, LERs & related correspondence
- 8004070228 Ack receipt of 800229 second interim rept re failure of post-tensioning tendon field anchor heads Rescheduled date of 800515 for submittal of final rept is acceptable FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 60/03/19 ip

- DOCKET 50-455 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURLG-0588. "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment." providing guidance to methods for compliance ROSS. D.P. Division of Project Management. 80/02/05 7pp
- B004040017 Submits addl guidance to RUREG-0588, "Interin Staff Position on Environ Qualification of Safety Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance ROS8.D F Division or Piuject Management 80/02/21 Jpp
- 8004230058 Requests info ie auriliary feedwater sys per Bulletins & Orders Task Force review of FMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC apploval prior to issuance of OL Wienci ROSS.DF Division of Project Management 80/03/10 53pp
- 8004(4044) Forwards GA plan implemented during Sept 1979 to Feb 1980 const suspension in response to NRC 800303 request Plan will prevent degradation of quality of safety-related equipment, components & structures
 PEOPLES
- --8004140447 OA Plan during estended const delay CASARD,R . FARR,R J , MARCUS,G F Commonwealth Edison Co 79/10/24 Zipp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. GA program Revisions reflect recent organization title changes NAUGHTON.W F Commonwealth Edison Co 80/04/02 ip
- --B004150328 Revised pages constituting Revision 13 to GA program Revisions reflect recent diganizational title changes • Commonwealth Edison Co CE-1-A R13 80/04/04 7pp
- F Security, medical, emergency & tire protection plans
- 8004090077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending OAO clearance under Federal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004140115 Forwards request for add1 into consisting of fifth set of round one questions re safeguards contingency plan Encl withheld (ref 10CFR2 790)
 RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/28 2pp
- G Adjudicatory correspondence
- 8004030024 Memorendum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OOSSICK, L V Office of the Crecutive Director for Operations 80/04/02 34pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004080397 Forwards affidavit stating that distribution of Amend 25 to FSAR has been made in accordance w/RS Boyd 791020 ltr NAUGHTON, W F Commonwealth Edison Co 80/04/01 29p
- 1 Inspection reports, IE Bulletins & correspondence
- 04110284 Forwards IE lnsp Repts 50-486/80-01 & 50-457/80-01 on 000116-17 & notice of violation TiORELLI, G. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/29 2pp
- -8004110271 Notice of violation from insp on 800115-17 * NRC Regional Offices 80/02/27 ip
- --8004110300 IE Insp Repts 50-456/80-01 % 56-457/80-01 on B00116-17 No noncompliance noted failure to property store QA records WILLIAMS, C C NRC Regional Offices SCHWEIBINZ, E R. Region 3, Chicago, Office of the Director B0/02/27 4pp
- 8004100118 Forwards IE info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEFPLER, J G Region 3, Chicago, Office of the Director 80/03/07 in

- 8004140119 Forward, response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES.D t. Commonwealth Edison Co. 80/03/20 5pp
- 8004150159 Forwards IF Into Notice 80-12. "Instrument Failure Causes Opening or PORV & Block Valve "No specific action or response necessary

 KEPPLER, J. G. Region 3. Chicago, Office of the Director BO/03/31

 Ip
- 8004080686 forwards [E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/01
- 8004150014 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02 to
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02 ip
- 8004220093 Forwards IF info Notice 80-14, "Safety Buggestions From Employees " No action required KEPPLCR.J O Region 3, Chicago, Orfice of the Director 80/04/02
- 8004220324 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Oil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03 to
- B004220069 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director B0/04/09
- 8004230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/07
- DOCKET 50-457 BRAIDWOOD STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-DSBB, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS,D F Division of Project Management 80/02/08 7pp
- B004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Clectrical Equipment "Requests review of equipment qualification documents to Identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info is auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of OL W/zenl ROSS,D F Division of Project Management 80/03/10 93pp
- 8004140441 Forwards QA plan implemented during Sept 1979 to Feb 1980 const suspension in response to NRC 800303 request Plan will prevent degradation of quality of safety-related equipment, components & structures
 PEOPLES.D L Commonwealth Edison Co 80/03/25 2pp
- --8004140449 QA Plan during extended const delay CASARO.R , FARR.R J , MARCUS.O F Commonwealth Edison Co 79/10/24 21pp
- 8004159316 Forwards revised pages constituting Revision 13 to CE-1-A, GA program Revisions reflect recent organization title changes NAUGHTON, W.F. Commonwealth Edison Co. BO/04/02 ip
- --8004i50328 Revised pages constituting Revision i3 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-1-A RI3 80/04/04 7pp

- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending GAD clearance under Federal Repts Act Emergency Preparedness Task Force BO/03/11 4pp GRIMES, B K
- BOO4140115 Forwards request for add1 info consisting of fifth set of round one questions re safeguards contingency plan Encl withhold (ref 10CFR2 790)
 RUBENSTEIN, L S Light Water Reactors Branch 4 80/03/28 2pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA ve prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations GO/04/02 34pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004080397 Forwards affidavit stating that distribution of Amend 25 to FBAR has been made in accordance w/RS Boyd 791020 ltr NAUGHTON,W F Commonwealth Edison Co 80/04/01 2pp
- G Inspection reports, 1E Bulletins & correspondence
- B004110284 Forwards IE Insp Repts 50-456/80-01 & 50-457/80-01 on 800116-17 & notice of violation FIGRELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/29 2pp
- ---8004110291 Notice of violation from insp on 800116-17
 * NRC Regional Offices 80/02/27 ip
- --8004110300 IE Insp Repts 50-456/80-01 & 50-457/80-01 on 800116-17 No noncompliance noted failure to properly store GA records WILLIAMS.C C. NRC Regional Offices SCHWEIBINZ.E R. Region G. Chicago, Office of the Director 80/02/27 4pp
- 9004100119 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required
 KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/07
- 8004140119 Forwards response to IE Bulletin 80-03. "Loss of Charcoal from 8td Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEGPLES.D L. Commonwealth Edison Co. 80/03/20 Spp
- 8004190157 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J G Region G. Chicago. Office of the Director 80/03/31
- 8004080686 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/0
- 8004150014 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/02
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Qas Mazards," inadvertently omitted from 800306 transmittal KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220093 Forwards IE Info Natice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/04/02
- 8004220324 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Gil Bys "No written response required
 KEPPLER, J G. Region 3, Chicago, Office of the Director 80/04/03

- BOO4220069 Forwards IF Bulletin Bir-OB 'Exam or Containment Liner Penetration Welds " Written response required KEPPLER, J.G. Region 3, Chicago Office of the Director BO/04/09
- 8004230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Derects in ASME SA-312.1ype 304 Stainless Steel Pipe " Action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/07
- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A Application/constitution stage documents & correspondence
- 8004040335 Forwards 3-month test results of Pittsburgh Test Lab Repts 800985 & 800986. "Rept of Potential Aliali Reactivity, ASTM C227 & C-289 " Results within limits for 3 & 6-month test criteria WEIOAND.J G - Gulf States Utilities Co - BO/O1/22 - 1p
- ~~8004040345 "Rept of Potential Alvali Reactivity, ASTM C227 & C-289 "

 ★ Pittsburgh Testing Laboratory 80/01/15 ip
- --8004040356 "Rept of Potential Alkai Reactivity, ASIM C227 % C-289 " * Pittsbuigh festing Laboratory E0/01/15 ip
- 8004040363 Forwards 3-month test results of Pittsburgh Test Lab Repts 800985 & 800986. "Rept or Potential Alkali Reactivity. ASTM C227" Results within limits for 3 & 6-month tests WEIGAND, J G Oulf States Utilities Co 80/01/30 ip
- --8004040364 "Rept of Potential Alkali Reactivity, ASIM C227 "

 * Pittsburgh Testing Laboratory 80/01/23 ip
- --8004040367 "Rept of Potential Alkali Reactivity.ASTM C227 "
 # Pittsburgh Testing Laboratory 60/01/23 ip
- GOO4040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 60/02/05 7pp
- 8004040370 Forwards 4-month results of Pittsburgh Testing Lab Repts 800985 & 800986, "Rept of Potential Alkali Reactivity, ASTM C227 & C289 " Results within limits for 3 & 6 Month test durations
 WEIGAND, J G Oulf States Utilities Co 80/02/22 to
- --8004040372 "Rept of Potential Alkali Reactivity, ASTM C227 & C289 " Pittsburgh Testing Laboratory 80/02/12
- --8004040373 "Rept of Potential Alka]1 Reactivity, ASTH C227 & C289 "
 * Pittsburgh Testing Laboratory 60/02/12 1p
- BOO404027B Forwards four-month results of Pittsburgh Testing Lab Repts BOO985 & BOO986, "Rept of Potential Alkali Reactivity. ABTM C227 " Results within limits for 3 & 6-month test durations WEIGAND, J Q Gulf States Utilities Co 80/02/28 ip
- --8004040384 "Rept of Potential Alkali Reactivity.ASTM C227 "
 * Pittsburgh Testing Laboratory 80/02/20 ip
- --8004040386 "Rept of Potential Alkali Reactivity, ASIM C227 "
 Pittsburgh Testing Laboratory 80/02/20 Ip
- 800.4180102 Notifies NRC that shop mods are being made to reactor pressure vessel Work involves plugging control rod driveling return noizle & replacement of safe-ends or feedwater & recirculation noizles
 MEIGAND.J G Gulf States Utilities Co 80/03/14 ip
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending GAO clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11 4pp

6 Adjudicatory correspondence

8604030026 Memorandum of understanding between NRC & FEHA is prompt improvement in radiological emergency planning \(\hbar \) preparedness, distributed as Soard notification GOSSICK/L \(\hbar \) Office or the Elecutive Director for Operations 80/04/0≥ 34pp

1 Financial information

8004210182 Forwards Annual Financial Rept 1979 WEIGAND, J.G. Gulf States Utilities Co. 80/04/14 ip

--8004210185 Annual Financial Rept 1979
* Gulf States Utilities Co 80/04/14 35pg

M Antitrust correspondence

8004230466 Comments on antitrust review re Cajun Electric Power Cooperative, Inc. ownership interest in facility, on behalf of the Consumer League, Inc. Commission should lequest add) info & hold hearings to determine it antitrust implications exist IRVING.S II Public Law Utilities Group 80/04/18 13pp

O Inspection reports, IF Builetins & correspondence

8004040106 Confirms 800215 telcon advising that no proprietary info contained in 1E lnsp Rept 50 450/79-08 WEIGAND, J G Gulf States Utilities Co 80/02/15 ip

8004010018 Responds to IE Bulletin 79-28, "Possible Maifunction of NAMCO Model EA180 Limit Switches at Elevated Temps " No suitches purchased or intended to be purchased for use at facilities WEIGANID, J G Gulf States Utilities Co 80/02/28 ip

8004010023 Responds to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys " No relays referred to in bulletin are to be used in facility WEIGAND. J Q Gulf States Utilities Co 80/02/28 ip

8004010041 Responds to IE Builetin 79-02. Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "Concrete block walls in seismic Category 1 % 2 structures shall not be designed to support pipes or sys WEIGAND, J G Gulf States Utilities Ca 80/02/28 2pp

8004140046 Forwards IF Investigation Rept 50-458/80-03 on 800212-15 No noncompliance noted SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/02/28 2pp

--8004140049 IE Investigation Rept 50-458/80-03 on 800212-15 No noncompliance noted Major areas inspected allegations re conflict between const cost & nuclear safety CROSSMAN, W. A. OBERG. C. R. Region 4. Dallas. Office of the Director 80/02/26 8pp

8004220204 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/02 in

8004220288 Forwards IE Circular E0-07, "Problems W/HPCI Turbine Dil Sys " No written response required SEYFRIT.X V Region 4, Dallas, Office of the Director 80/04/03

1004220770 Forwards IE Bulletin 77-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/04 p

8004220237 Forwards IF Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/07

R Periodic operating teports & related correspondence

8004280537 Forwards "1977 Groundwater Usage & Industrial Growth Burvey " Rept constitutes third submitted in fulfillment of PSAR commitment WEIOAND.J G Guif States Utilities Co 80/04/21 ip

- --8004280543 "1979 Groundwater Usage & Industrial Growth Survey " WEIGAND.J G Gulf States Utilities Co 80/04/21 23pp
- S Reportable occurrence. LERs & related correspondence

8004040056 Advises of commitment to rework questionable wald areas as final resolution of reportable deficiency re mfg of containment to embedment-plate T-welds StW & Graver Energy Sys.lnc assessments of deficiency encl WEIGAND. J G Gulf States Utilities Co 80/02/01 1p

--8004040057 Interim deficiency rept re subsurface defects in containment corner junction T-welds Caused by undestrable weld nugget or bead shape deposited at roof Resultant cavity areas will rewelded KIRKEBO, J. A. Stone & Webster Engineering Corp. 80/01/14 54pp

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREC-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance remethods for compliance ROSS,D F Division of Project Management 80/02/05 7pp

- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending QAO clearance under Federal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/ii 4pp
- Q Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 0D88ICK.L V Office of the Executive Director for Operations 80/04/02 34pp

I Financial information

8004210182 Forwards Annual Financial Rept 1979 WEIGAND.J C Oulf States Utilities Co 80/04/14 1p

--8004210185 Annual Financial Rept 1979
Gulf States Utilities Co 80/04/14 35pp

Q Inspection reports, IF Bulletins & correspondence

8004010018 Responds to IE Bulletin 79-28, "Possible Malfunction of MAMCO Model EAIBO Limit Switches at Elevated Temps " No switches purchased or intended to be purchased for use at facilities HEIOAND.J O Gulf States Utilities Co 80/02/28 in

8004010023 Responds to IF Bulletin 79-25, "Failures of Westinghouse BFD Relays in Bafoty-Related Gys" No relays referred to in bulletin are to be used in facility WEIOAND, J G Gulf States Utilities Co 80/02/28 ip

80040i004f Responds to IF. Bulletin 79-02. Revision 2. "Pipe Support Base Plate Designs Using Concrete Espansion Anchor Bolts "Concrete block walls in seismic Category 1 & 2 structures shall not be designed to support pipes or sys WEIGAND, J G Gulf States Utilities Co 80/02/28 2pp

8004220206 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/02 ip.

80042202BB Forwards IE Circular BO-07, "Problems W/HPCI Turbine Dii Sys " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director BO/04/03 ip

8004220770 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required SEYFRIT, K V Region 4, Dallas, Office of the Director B0/04/04 ip

- 8004220237 Forwards 1E Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required SEYFRITIK V Region 4, Dallas, Office of the Director 80/04/07
- R Periodic operating reports & related correspondence
- B004280539 Forwards "1979 Groundwater Usage & Industrial Growth Survey " Rept constitutes third submittal in fulfillment of PSAR commitment MEIGAND.J G Gulf States Utilities Co B0/04/21 1p
- --8004280543 "1979 Groundwater Usage & Industrial Growth Survey " WEIGAND, J. G. Gulf States Utilities Co. 80/04/21 23pp
- S Reportable occurrences. LERs & related correspondence
- BD04040056 Advises of commitment to rework questionable weld areas as final resolution of reportable deficiency re mfg of containment to embedment-plate T-welds S&W & Oraver Energy Sys. Inc assessments of deficiency encl
- --8004040057 Interim deficioncy rept re subsurface defects in containment corner junction T-welds Caused by undesirable weld nugget or bead shape deposited at roof Resultant cavity areas will rewelded KIRKEBO.J A Stone & Webster Engineering Corp. 80/01/14 54pg
- DOCKET 50-460 WPP68 NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS D F Division of Project Management 80/02/05 7pp
- 8004210408 Requests addl info re changes & studies proposed in App F of 791203 reply to NRC 791025 10CFR50 54 requests concerning design adequacy of D&W N988 utilizing once-through steam generators
 PARR.O D Light Water Reactors Branch 3 80/03/25 6pp
- 8004280619 Advises that 791220 request for approval of alternative test method to verify max moisture in low hydrogen electrode coating is accepted Requests that notarized version of request be sent in addition to specific sites for use RUBENSTEIN.L S Light Water Reactors Branch 4 80/04/04 5pp
- BOO4160285 Advises of fundamental misstatement in BOO402 minutes of BOO104 meeting w/util re QA program unionization Requests correction to reflect that fact had no influence on Local 598 election REYNDLDS,N 8 Debevoise & Liberman 80/04/10 ip
- 8004210285 Responds to 800221 itr re-schedule for completing review of qualification of safety-related electrical equipment Schedule for completion of review will be provided after final issuance of NUREO-0588 RENBERGER, D L. Washington Public Power Bupply System 80/04/11 to
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791224 ltr.has been postponed pending GAO clearance under Federal Repts Act ORINES.B K Emergency Preparedness Task Force 80/03/11 4pp
- Q Adjudicatory correspondence
- BOO4030026 Hemorendum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OBSECKL V Office of the Executive Director for Operations BO/04/02 34pp
- G Inspection reports: IE Bulletins & correspondence
- B004280083 Forwards IE Insp Rapts 50-460/80-02 & 50-513/80-02 on B00211-15 No noncompliance noted BPENCER 0 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/03/19 2pp

- --8004280094 IE Insp Repts 50-460/80-02 & 50-513/80-02 on 8002i1-15 No noncompliance noted Major aleas inspected safety-related components, safety-related piping installation, welder training & weld filler matl control
 DODDS, R T Region 5. Sam Francisco, Reactor Construction & Engineering Support Dranch McGNER, W J , HAIST, D P Region 5. San Francisco, Office of the Director 80/03/18 Bpp
- 8004150220 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENDELKEN.R H Region 5, San Francisco, Office of the Director 80/03/31 1p
- 8004100107 Forwards IE Circulai 80-05, 'Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENGELKEU.R H Region 5, San Francisco. Office of the Director 80/04/01 lp
- 8004110119 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required ENGELMEN.R H Region 5, San Francisco, Office of the Director BD/04/02 16
- 8004220052 Forwards IF info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN.R H Region 9, San Francisco, Office of the Director BD/04/02 ip
- BOO4180139 Forwards 1E Circular 80-07. "Problems N/HPCI Turbine Oil Sys " No written tesponse required ENGELKEN, R H Region 5. San Francisco. Office of the Director BO/04/03 lp
- BOO4230370 Forwards IE Bulletin 79-03A. "Longitudinal Held Defects in ABME 8A-312, Type 304 Stainless Steel Pipe" Action required EMOCLKEN, R H Region 5, San Francisco, Office of the Director BO/04/04 1p
- 8004220201 Forwards IE Dulletin 80-08, "Exam of Containment Liner Pemetration Helds" Written lesponse required ENGELKEII.R H Region 5, San Francisco, Office of the Director 80/04/07 ip
- 8004230239 Ack receipt of 800318 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-460/79-13 & SO-513/79-13 SPENCER.O S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/04/08 1p
- --B004230248 Responds to NRC B00228 ltr re violations noted in [E Insp Repts 50-460/79-13 & 50-513/79-13 Corrective actions identified & described nature A extent of referenced administrative & security controls RENBERGER.D L Washington Public Power Supply System 80/03/18

- OCCRET 50-461 CLIMION POWER STATION, UNIT 1

 A Application/construction stage focuments & correspondence
- 8004040631 Advises of issuance of NUREC-0088, "Interim Staff Position on Environ Qualification of Rarety-Related Electrical Equipment," providing gradumer to nothers for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004150225 Forwards I.R. 800118 1 0211 lins to GE discussing analysis of boil off rates mods to BWR control rod drive return line noirles to prevent cracking Hods should not be performed before issuance of NARE-0617 or w/o NRC guidance STOLY, J.F. Light Water Reactors Branch 1 80/03/07 2pp
- BOO4130301 Notification of BOO403 reating w/GE in Bethasda.HD to discuss BHR 6 safety relief valves mfg by G Dickens & Co & supplied by GE to facilities HENDERSCRIJ B Division of Reactor Construction Inspection BO/03/13 2pp
- 8004010249 Forwards comments on NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," in response to NRC 800205 ltr Certain sections need revision 2 clarification WULLER, Q E Illinois Power Co 80/03/24 App
- F Security, medical, emongency / fire protection plans
- 80040800/7 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending QAO clearance under Federal Repts Act GRIMES.B K Emergency Proparedness Task Force 80/03/11 4pp
- 8004010328 Submits evacuation time estimates in response to NRC 800226 1tr Map of area encl WULLER, G E Illinois Power Co 80/03/24 App
- G Adjudicatory correspondence
- 8004030024 Memorandum of understanding between NRC & FEMA Te prompt improvement in radiological emergency planning & preparedness distributed as Brand notification GOSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- Q Inspection reports, IF Bulletins & correspondence
- 8004100139 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block "No specific action or response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/03/07
- BOO4140109 Responds to IE Bulletin 79-09. "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " GE type AK-2 circuit breakers will not be used with any safety-related sycs at facility WULLER.G E Illinois Power Co 80/03/24 tp
- 8004;50190 Responds to IF Bulletin 80-03 re charcoal adsorber cells Liscensee does not use adsorber trays discussed in bulletin but uses vertical gasketless adsorbers mfg by American Air Filter Co MULLER, Q E Illinois Power Co 80/03/24 fp
- 8004150175 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLERIJ & Region 3. Chicago. Office of the Director 80/03/31
- 8004080714 Forwards IE Circulai 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER J G Region G. Chicago, Office of the Director 80/04/01
- 8004150045 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02

- 8004180052 Forwards attachments to IE Circular 80-03, "Protection From Tour Gas Hazards, inidventently omitted from 800306 transmittal VEPPLER.J U Region 3. Chicago, Office of the Director 80/04/02 in
- B004220142 Farwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/04/02
- 8004220368 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/03
- 8004110042 Forwards IF Bulletin 80-0/, "BWR Jet Pump Assembly Fallure " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/04/07
- 8004230266 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required KEPPLER. J.O. Region 3, Chicago, Office of the Director BO/04/07 10
- 8004220144 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penatration Welds " Written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/09
- 8 Reportable occurrences, LFRs & related correspondence
- 8004040039 PND-1J1-80-033 on 900318 pipefitter working on turbine bldg roof drain piping fell from 65 ft scaffolding.hitting crane support girder & was killed WESCOTT.H , KKDP.R C . FIORELLI.O Region 3. Chicago, Office of the Director 80/03/19 ip
- 8004300048 Act receipt of 800331 interim deficiency rept re incorrect soil characteristic value FIGRELLI, 9 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/14 1p
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Cleatrical Equipment." providing guidance re methods for compliance RDSs.D F Division of Project Hanagement 80/02/05 7pp
- 8004150225 Forwards NRC 800128 / 0211 ltrs to GE discussing analysis of boil off rates mods to BWR control rod drive return ling nozzles to prevent cracking Mods should not be performed before issuance of NUREG-0619 or w/o NRC guidance STOLZ.J F Light Water Reactors Dranch 1 80/03/07 2pp
- 8004100301 Notification of 800403 meeting w/GE in BethesdarMD to discuss BWR 6 safety relief valves mfg by G Dickens & Co & supplied by GE to facilities HENDERSON.J B Division of Reactor Construction Inspection 80/03/13 2pp
- 8004010249 Forwards comments on NUREC-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," in response to NRC 800205 ltr Certain sections need revision & Clarification WULLER, O E Illinois Power Co 80/03/24 App
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act
 ORIMES.B K Emergency Preparedness Task Force 80/03/11 App
- B00401032B Submits evacuation time estimates, in response to NRC 800226 ltr Map of area encl KULLER:0 E | 111mois Power Co | 80/03/24 | App

- 9 Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning % proparedness distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- G Inspection reports, IE Bulletins & correspondence
- 800410013B Forwards IE Info Notice 80-08. "States Co S)iding Link Electrical Terminal Block "No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/07
- 8004140107 Responds to IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys" QE type AK-2 circuit breakers will not be used with any safety-related sycs at facility
 WULLER, Q E Illinois Power Co 80/03/24 1p
- B004i50i90 Responds to IE Bulletin 80-03 re charcoal adsorber cells Liscensee does not use adsorber trays discussed in bulletin but uses vertical gasketless adsorbers mfg by American Air Filter Co WULLER.O E Illinois Power Co 80/03/24 1p
- 8004i50i75 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J O Region 3, Chicago. Office of the Director 80/03/31
- 8004080714 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/04/01
- 8004130045 Forwards IE Info Notice 80-13, "OE Type 88M Control Switches Defective CAM Followers " No specific action or response required KEPPLERIJ O Region 3, Chicago, Office of the Director 80/04/02
- 8004180092 Forwards attachments to IE Circular 80-03, "Protection From Toxic Cas Hazards," inadvertently emitted from 800306 transmittal KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220142 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/04/02
- B00422036B Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Bys " No written response required KEPPLER, J O Region 3, Chicago, Défice of the Director 80/04/03
- 8004110042 Forwards IE Bulletin 80-0/, "BMR Jet Pump Assembly Failure " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07 io
- 8004230246 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07 ip
- 8004220144 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/04/09
- DOCKET 50-443 FULTON GENERATING STATION, UNIT 1
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 90881CKL V Office of the Executive Director for Operations 80/04/02 34pp

- DOCKET 50~464 FULTON GENERATING STATION, UNIT 2
 G Adjudicatory correspondence
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning ** preparedness distributed as Board notification GOSSICK, L V Diffice of the Executive Director for Operations 80/04/02 34pp
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT I

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance ie methods for compliance RUSS, D.F. Division of Project Management 80/02/05 7pp
- 8004010242 Forwards "Environ Assessment & Responses to NRC Questions Transportation of Reactor Pressure Vessel," prepared by Dames & Moore MCGUIRE.W F Houston Lighting & Power Co 80/03/26 App
- --B004010250 "Environ Assessment & Responses to NRC Guestions Transportation of Reactor Pressure Vessel" * Dames & Hoore 4490-057-12 80/03/31 70pp
- 8004210405 Summary of 800328 meeting w/near-term CP applicants in Bathesda.MD re evaluation of progress made to date establishing proposed requirements stemming from TIII-2 accident
 THOMAS, C.O. Standardization Branch 80/04/03 63pp
- 8004300074 Summary of 800317 meeting w/neat-term CP applicants in Bethesda, MD re resumption of CP application review activities associated w/TMI-2 accidents THOMAS.C D Standardization Dranch 80/04/03 12pp
- 8004240557 Summary of 800402 meeting w/Near-Term CP Applicants Group in Bethosda.MD re-progress made establishing proposed requirements stemming from TMT-2 accident Proposed requirement category assignments end TMOMAS.C II Light Water Reactors Branch 1 80/04/07 47pp
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- BD04150076 Forwards assessment of impact of proposed facility on endangered species residing or migrating throughout site Project will not affect endangered species & no further assessment is necessary BALLARD, R L Environmental Projects Branch 1 B0/04/02 3pp
- G Adjudicatory correspondence
- 8004080244 Requests that Public Utils Board provide full & complete answers to incomplete interrogatories COPELAND.J G Baker & Botts 80/02/07 2pp
- 8004020232 Response to JF Daherty twolfth request for production of documents NEDO 23, 785; NEDO 21, 778; APED 5750. 1 & 2 & NEDO 20, 355A available for insp & copying Remaining documents not available Certificate of Svc encl
 BIDDLE, C T . NEWMAN. J R Houston Lighting & Power Co BIDDLE, C T Baker & Botts 80/02/28 App
- 8004140281 Response by State of TX to fourth set of interrogatories Includes info re availability of natural gas & impact of air quality on fue) switching Cortificate of Svc encl LOWERRE.R W Teras. State of 80/02/28 7pp
- 8004100078 Responds to seventh set of interrogatories includes info re MSIVs, feedwater pumps & possible hydrogen explosion in TMI-2 containment during accident Notice of appearance of D Hancock on behalf of util & Certificate of Svc encol HANCOCK, D Houston Lighting & Power Co HANCOCK, D Baker & Botts 80/03/03 2ipp
- BD04090100 Requests to make limited appearance statement at next public meeting on behalf of Citizens Antinuclear Info Team
 BISHOP, M Affiliation Unknown 80/03/05 ip

- 8004140415 Answers to intervenor of Doheity second request for admissions includes questions ie authenticity of certain documents & info concerning GF diesel generators Certificate of 5 of encl.
 BIDDLE. C T Houston Lighting & Power Co BIDDLE. C T Baker & Botts 80703707 9pp
- 8004100532 Response to eighth set of interrogatories Includes inforce control room displays for values to other manually operated, renotely controlled instruments Certificate of Svc encl
 HANCOCK, D. Houston Lighting & Power Co. HANCOCK, D. Baker & Botts
 80/03/10 19pp
- 80040806B7 Response to this teenth set of interrogatories includes infore weight of thermal shielding & insulation in drywell & in containment bldg Certificate of Svc encl BIDDLE.C T Houston Lighting & Power Co BIDDLE.C T Baker & Botts 80/03/11 26pp
- 8004110551 Intervenor Contention 47 Applicant main generator turbine is not designed sufficiently to prevent turbine missiles from damaging critical components of sys Certificate of Svc encl DOMERTY. JF Affiliation Unknown 80/03/12 2pp
- 8004210153 Notice of appeal from ASLB 800310 order rejecting WJ Schuessier Contentions 1,2,3 % 5-13 Requests extension.until 800325 to file amend to appeal re admissibility of contentions SCHUESSLER.W. J. Affiliation Uningwn 80/03/20 1g
- BOO4100557 Response to intervenor JF Daherty fifteenth request for documents tists documents available for insp & copying at applicant Energy Development Complex in Houston, TX Certificate of Svc encl
 BIDDLE, C T Houston Lighting > Power Co BIDDLE, C T Baker & Botts 80/03/21 5pp
- B004230024 Notice of intent to appeal ASLB 800310 order rejecting B Baler 790918 Contention 2 re cost/benefit analysis BAKER/B Affiliation Unknown 80/03/21 4pp
- 8004240548 Requests reversal of ASLB 800311 denial of FH Potthoff petition to intervene Latitude should be granted to layperson authoring legal document Supports admittance of contention re marine biomass energy production DDHERTY, J F Doherty, J F 80/03/21 3pp
- ---8004240555 Submits Contention 5 re need for power & contention re biomass production operating marine biomass farm would be environmentally preferable to nuclear plant ASLB should deny CP under NCPA POTITHOFF.F H Affiliation Unknown 77/06/01 2pp
- 8004030076 Menorandum / order dismissing MJ Schuessler appeal re ASLG 800310 order rejecting majority of intervenor contentions Rules of practice do not permit interlocutory appeal unless petition is denied in entirety 8
- 800424018B Response in opposition to JF Doherty motion seeking applicant admission of Contentions 20.25.26,30.31,40,41,43 & 44 Motion is w/o substance re timely request Relevance to FOIA requests not clear W/Certificate of Svc COPELAND. J O , NEWMAN. J R Houston Lighting & Power Co COPELAND I O Bater & Botts 80/03/26 7pp

- BOO4230022 Response in opposition to intervenor JF Doherty second motion to compel further responses to interrogatories Clarifies previous objections & urges ASLB to deny motion to compel for being deficient Certificate of Svc encl BIDDLE.C T. NEWMAN.J R. Houston Lighting & Power Co. BIDDLE.C Y Baker & Botts. BO/03/31 10pp
- 8004230035 Response in support of R Potthoff appeal re denial of petition to intervene Potthorf contention should be regarded as allegation that EIS did not address biomass conversion W/Certificate of Svc SCOTT. J Teras Public Interest Research Gloup 80/03/31 3p
- 8004080016 Response in opposition to JF Doherty 800312 Contention 47 returbine design inadequacies NRC safety evaluation concluded likelihood of resultant radioactive release sufficiently small W/Certificate of Svc SDHINKI.S M Hearing Branch 3 80/04/01 4pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OCSSICK, V Office of the Executive Director for Operations CAMM; F Federal Emergency Management Agency 80/04/02 34pp
- BOO424053B Motion for issuance of protective order re TX PIRO request for public disclosure of util Jan 1980 rept, "South TX Nuclear Project, GA & QC, Mgt Assossment Survey for Brown & Rook, Inc. "Draft protective order & Certificate of Svc encl BIDDLE, C Y Houston Lighting & Power Co 80/04/02 9pp
- B004150181 Discusses JF Doherty B00321 appeal on behalf of FH Potthoff Pro se intervenor has no standing to assert rights of another party per Project Myl Corp case Doherty appeal should be treated as brief in support of Potthoff appeal SCHINKI.S Hearing Branch 3 80/04/07 2pp
- 8004170307 Brief in opposition to FH Potthoff 800326 appeal Urges affirmation of ASLB 800310 order denying petition to intervene Contention is economic in nature & need not be considered per 1978 ALAP-458 Certificate of Svc encl SOHINKI, 8 M Hearing Branch 3 80/04/07 10pp
- 8004100474 Appeals ASLAB 800320 decision to deny standing on Contention 6 re environ preferability of biomass farm to nuclear plant Biomass farm would release less radioactivity to environ & would alter landscape less
 POTTHOFF.F H Affiliation Unknown 80/04/08 2pp
- 8004230055 Order directing that discovery re intervenor J Doherty Contention 47 be initiated & completed in 120 days after svc on ASLB 800310 order TX PIRO 800314 motion recansolidation granted J Doherty 800318 motion denied WDLFG.8 J . LINENBERGER.G Atomic Safety and Licensing Board Penel 80/04/10 5pp
- 8004230094 Order advising intervenor J Doherty to reply to NRC & applicant answers to Doherty 800408 motion re Contentions 48 & 49, within 10 days of answers ASLB should be immediately notified if replies are not to be filed WOLFE.8 J Atomic Safety and Licensing Board Panel 80/04/14 tp
- BOO4300403 Response to JF Doherty BO0407 new Contentions 48 & 49 & amend to Contention 17 Urges admittance of Contention 48 & denial of both Contention 49 & amend to Contention 17 Certificate of Svc encl WOODHEAD, C.P. Hearing Branch 3 BO/04/28 17pp

DOCKET STN-50-470 CESSAR SYSTEM BO

- A Application/construction stage documents & correspondence
- 8004110522 Advises of docketing of facility FSAR Forwards FR notice of receipt of standardized FSAR KANELM F Standardizetion Brench 80/03/04 1p
- OCCKET 80-471 PILORIM NUCLEAR POWER STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Owalification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RUSS, D.F., Division of Project Management 80/02/05 7pp
- 8004280167 Forwards video tape of fuel assemblies in fuel pool provided by util on 800321 for NRC review W/o encl ORIER,8 H Region i, Philadelphia: Office of the Director, 80/03/31 ip

- B004210405 Summary of 800328 meeting w/near-term CP applicants in Bethesda.MD re evaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident THOMAS.C O Standardization Branch 80/04/03 43pp
- B004300074 Summary of B00319 meeting w/near-term CP applicants in Bethesda,MD re resumption of CP application review activities associated w/TMI-2 accidents
 THOMAS.C 0 Standardization Branch 80/04/03 12pp
- 8004240557 Summary of B00402 meeting w/Near-Term CP Applicants Group in Bethesda:MD re progress made establishing proposed requirements stemming from Trij-2 accident Proposed requirement category assignments encl THOMAB,C O Light Water Reactors Branch 1 80/04/07 47pp

G Adjudicatory correspondence

- 8004090412 Order re review of statements filed in response to ASLS 800117 order re emergency planning hearing Directs parties to advise ASLS within 30 days re filing time of testimony & eshibits in preparation for hearings 0000H0PE, A C Atomic Safety and Licensing Board Panel 80/03/27 200
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification COSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004270237 Provides info in response to ASLB 800327 order re emergency planning testimony NRC is awaiting evacuation time estimates for future nuclear plant areas in order to perform analysis No specific schedule can presently be made QUDDARD, R J Hearing Branch 2 80/04/25 2pp

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance, ROS8,DF Division of Project Management
- 8004040016 Forwards request for add1 info to complete review of QA program PARR: D Light Water Reactors Branch 3 80/03/20 App
- 8004110577 Advises that tendered application for OL is being sent under separate cover Due to TMI priorities.acceptance review will be performed in late spring or early summer SOUDER.J L Division of Rules and Records 80/03/26 ip
- 8004i80352 Forwards add1 info re std plant QA programs for design & const.in response to NRC 800122 request Util commits to Reg Ouide I 94 w/exception of requirements re structural bolt tightening & number of threads exposed beyond nut BEIKEN.8 J Standardized Nuclear Unit Power Plant System 80/04/i4
- 8004280463 Updates 800401 meeting w/util & NRC re OL applications Bubmits program for start of NRC review, including initial meeting w/util project manager Applicants exploring other steps to aid NRC review PETRICK, N A Standardised Nuclear Unit Power Plant System BO/04/23 2pp
- F Security, medical, emergency & fire protection plans
- 80040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending GAO cleanance under Federal Repts Act ORIMES.B K. Emergency Preparedness Task Force 80/03/11 4pp
- Q Adjudicatory correspondence
- 8004040268 Order granting extension until 800321 for Commission to elect whether to review director's 800131 decision denying relief under 10CFR2 204 CHILM, 8, J. Office of the Secretary of the Commission 80/03/14

8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning */
preparedness.distributed as Board notification
GDSBICK.L V Office of the Executive Director for Operations
80/04/02 34pp

I Financial information

- BO040904B2 Annual Financial Rept 1979

 General Public Utilities GPU Service Corp 80/04/03 44pp
- --8004090483 "Proposal to Conduct Analysis of Strategic Options for JCP&L ' * Arthur Young & Co 80/02/29 125pp
- B004220730 Forwards Annual Financial Repts 1979 Certificate of Svc encl KDESTER, G L Kansas Gas / Flectric Co B0/04/15 19pp
- ---8004220747 Annual Financial Rept 1979 * Kansas Gas & Electric Co 80/03/03 36pp
- --8004220759 Annual Financial Rept 1979 * Kansas Gas & Electric Co 80/02/13 32pp

M Antitrust correspondence

- BOO4030207 Informs that review of available info has disclosed no basis for conclusion that antitrust hearing is necessary re KB Cas & Electric ownership of 195 MMT hare in Unit 1
 LITVACK.S M Justice.Dept of. Attorney Ceneral's Office BO/03/28
- 8004110121 Forwards DOJ Atty General 800328 ltr providing addl antitrust advice per Atomic Energy Act, re CP application Advice in question has been transmitted to FR for publication TOALBTON.A Antitrust & Indemnity Group 80/04/02 ip
- --8004110139 Submits add1 antitrust advice per Atomic Energy Act, rs CP application Licensee agreement to accept license conditions made antitrust hearing unnecessary LITVACK, S M Justice, Dapt of 80/03/28 ip

G Inspection reports: IE Bullotins & correspondence

- 8004010030 Supplements util 771108 response to IE Bulletin 77-02, "Potential Failure Mechanism in Certain Mestinghouse AR Relays "Relays not used in safety-related applications KOEBTER. G L. Kansas Oas & Electric Co. 80/02/12 lp
- 8004100280 Responds to IE Bulletin 79-28 Investigation re planned use of NAMCO EA180 switches, identification in SNUPPS design & development of plans for corrective action requires more time than anticipated Will forward response later PETRICK.N A Standardized Nuclear Unit Power Plant System 80/03/06 ip
- 8004240218 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required 8EYFRIT.K V Region 4, Dallas, Office of the Director 80/04/02 in
- BOO4220257 Forwards IE Circular BO-07, "Problems W/HPCI Turbine Oil Bys " No written response required BEYFRIT, K V Region 4, Dallas, Office of the Director BO/04/03 to
- 8004230392 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME 84-312, Type 304 Stainless Steel Pipe " Action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 800422024i Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/07

S Reportable occurrences, LERs & related correspondence

8004040269 Forwards supplemental rept on potential deficiency re qualification of control sys discussed in util 790928 ltr No unnesolved safety concerns re pressure controllers & main steam line atmospheric relief valve PETRICK:N A Standardized Nuclear Unit Power Plant System. 80/02/05 2pp

- B004040264 Discusses incorrect testing at concrete test cylinders on Tinsus-Olson test machine Twelve-Inch head was used when head no longer than 30-inches should have been used Indicated strength was probably not significantly affected KOESTER.O L Kansas Gis "Electric Co 80/02/08 ip
- 8004100533 Ack receipt of 800205 intorin deficiency rept re qualification of control sys CARLSOMR T Region 1, Philadelphia, Reactor Construction & Engineering Support Granch 80/02/21 ip
- 8004090127 Ack receipt or 800215 final deficiency rept re flookin Mfg Co fire dampers CARLSONR T Region (Philadelphia, Office of the Director 80/03/04 ip
- 8004010034 Interim deficiency rept re out-of-tolerance threads for NSSS support anchor bolt nots Analytical b empirical test data will be correlated to establish more precise methods for determining strength of threads on not KOESTER.G L Kansas Gas * Electric Co 80/03/05 2pp
- 8004170172 Followup deficiency reptile broken actuator shaft of NAMCO furnished limit switch installed on anchor Darling main steam isolation valve Fillore attributed to excessive force applied during shipping/handling No generic deficiency KOESTER.G ! Pansas Gas * Electric Co 80/03/13 1p
- BOD4150179 Discusses undetectable railure in engineered safety features actuation sys Utils are investigating hardware changes that may preclude further testing provided that changes are feasible Otherwise, tests will continue PETHICK.N A Standardized Nuclear Unit Power Plant System BO/03/20 ip
- 8004070292 Third interim deficiency rept re fibod damaged equipment Many valves & pumps cleaned & inspected Rework of electrical items & preassembled piping formations will continue through 1980 KOESTER.G L. Pansas Gas & Electric Co. 80/03/31 2pp
- B004150367 Interim deficiency rept re vertical fire dampers furnished by Ruskin Mfg Co Addl problems identified requiring new design mods Mods being developed & will be described in rept to be issued by B00515 PETRICK.II A Standardized Muclear Unit Power Plant System B0/04/03 2pp
- DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS.DF Division of Project Management 80/02/05 7pp
- 8004070189 Forwards request for add1 info to complete review of OA grogram PARR.D D Light Water Reactors Branch 3 80/03/20 App
- BOO4180352 Forwards add1 info re std plant QA programs for design & const, in response to NRC 800122 request Util commits to Reg Quide 1 94 w/exception of requirements re structural boilt tightening & number of threads exposed beyond nut SEIKEN.8 J Standardized Nuclear Unit Fower Plant System 80/04/14
- 8004280463 Updates 800401 meeting w/util 8 NRC re DL applications Submits program for start of NRC review including initial meeting w/util project manager Applicants exploring other steps to aid MRC review PETRICK-N A Standardized Nuclear Unit Power Plant System 80/04/23 2pp
- F Security, medical, emergency t fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 itr. has been postponed pending GAO clearance under Federal Repts Act ORIMES.B K Emergency Preparedness Task Force 80/03/ii 4pp
- H General correspondence
- 8004070070 Discusses NRC program of upgrading emergency preparedness in anvirons of nuclear power plants in response to 800102 ltr. Bys for alerting public must be demonstrated effective prior to OL issuance.

 DENTON, H.R. Office of Nuclear Reactor Regulation. 80/03/17 ip

- --8004070071 Expresses concern re proposed evacuation plan for facility Alerting fairworkers to emergency within required time would be difficult UELL.6 M Affiliation Unknown 80/01/02 lp
- G. Inspection reports, 18 Bulletins & correspondence
- B004040060 Forwards IF Insp Rept 50-483/79-16 on 791203-21 & notice of violation FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/02/12 2pp
- --8004040061 Notice of violation from insp on 791203-21

 * Region 3, Chicago, Office of the Director 80/02/07 ip
- --8004040062 IE Insp Rept 50-483/79-16 on 791203-21 Noncompliance noted railure to follow prescribed procedure re measurement of purge flow rate during welding of root pass HAMSERI, W H, KNOP, R C Region 3, Chicago, Office of the Director 80/02/07 5pp
- BOO4070167 Forwards IE Insp Rept 50-4B3/BO-02 on BO0123-25 & notice of violation FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch BO/02/15 2pp
- --8004070171 Notice of /iolation from insp on 800123-25
 * Region 3. Chicago, Office of the Director 80/02/11 ip
- --8004070173 IE lnsp Rept 50-483/80-02 on 800123-25 Noncompliance noted failure to maintain low hydrogen electrodes in heated containers when welder was not working in inaccessible area DANIELSON.D H. Region G. Chicago, Reactor Construction & Engineering Support Branch CORDERON.Z. LEE.E W.K. Region G. Chicago, Office of the Director 80/02/11 Spp
- 8004100280 Responds to IF Builetin 79-28 Investigation re planned use of NAMCO EA180 switches, identification in SNUPPS design & development of plans for corrective action requires more time than anticipated Will forward response later PETRICK, N A Standardized Nuclear Unit Power Plant System 80/03/04 ip
- 800410014B Forwards IC Info Notice 80-0B, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07 ip
- BO04040064 Forwards 1E Insp Rept 50-483/80-06 on 800227-29 & notice of violation FIGRELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004040071 Notice of violation from insp on 800227-29
 * Region 9. Chicago, Office of the Director 80/03/12 ip
- --8004040077 1E Insp Rept 50-483/80-06 on 800227-27 Noncompliance noted failure to follow site procedures re poor vibration practices HAYES, D W. Region 3. Chicago, Reactor Construction & Engineering Support Branch SCHAPER, J.F., LANDSMAN, R.B. Region 3. Chicago, Office of the Director 80/03/12 5pp
- 8004150192 Forwards IE Info Notice 90-12, "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/31 ip
- BOO4080725 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/04/01 tp
- 8004110318 Ack receipt of 800314 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-483/80-02 FIORELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/01 ip
- --8004110329 Responds to NRC 800215 ltr re violation noted in IE (nsp Rept 50-483/80-02 Corrective actions work procedure WP-503 has been revised to reflect OA manual requirements allowing electrodes to be taken from portable heaters for 4-h BRYAN. J K Union Electric Co 80/03/14 3pp

- 8004150057 Forwards IE Info Notice BO-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required
 KEPPLER, J G Region 3, Chicago, Ofrice of the Director 80/04/02
- 8004180063 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER J G Region 3, Chicago. Orfice of the Director 80/04/02
- 8004220153 Forwards IE info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220388 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Gil Sys "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 8004230282 Forwards IE Bulletin /9-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J. O. Ragion 3, Chicago, Office of the Director 80/04/07
- 8004220098 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Whitten response required XEPPLER, J O Region 3, Chicago, Office of the Director 80/04/09
- 8004300166 Notification of 800423 meeting in Fulton, MD to discuss resident inspector program KEPPLER, J G Region 3, Chicago, Office of the Director BO/04/14
- --8004300178 Notification of 800423 meeting in Culton, MO to discuss resident inspector program
 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/14
- --8004300184 Natification of 800423 meeting in Fulton,MQ to discuss resident inspector program KEPPLER.J Q Region 3, Chicago, Office of the Director 80/04/14
- --8004300189 Notification of 800423 meeting in Fulton, MD to discuss resident inspector program KEPPLER, J O Region 3, Chicago, Office of the Director BO/04/14
- --B004300194 Notification of 800423 meeting in Fulton, MO to discuss resident inspector program Agenda encl KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/14
- S Reportable occurrences, LERs & related correspondence
- 8004040269 Forwards supplemental rept on potential deficiency re qualification of control sys discussed in util 790928 ltr No unresolved safety concerns re pressure controllers & main steam line atmospheric relief valve PETRICK, N A Standardized Nuclear Unit Power Plant System PETRICK, N A S 80/02/05 2pp
- 8004100533 Ack receipt of 800205 interim deficiency rept re qualification of control sys CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/21 ip
- 8004090127 Ack receipt of 800219 final deficiency rept re Ruskin Mfg Co fire dampers CARLSON, R T Region 1. Philadelphia, Office of the Director 80/03/04 ip
- BOO4140156 Supplemental Part 21 rept re failed engine thrust bearing Insp of crankshaft thrust bearings installed on two PC-2 5 generator sets indicate plugs properly installed & free of reported potential defect Load during shop tests too light MCRIARTY.J M Colt Industries, Inc., Fairbanks Morse Engine Div BO/03/05 3pp
- 8004070230 Ack receipt of 800229 interim rept re NBSS lateral support anchor bolt nuts NRC will review final rept upon receipt FIGRELLI,0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/19 ip

- 8004080672 Ack receipt or NOO2.7 timal deficiency rept re undersize socket welds NRC will camplete review or matter during tuture insp FIDRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/19 ip
- 8004150179 Discusses undritectable failure in engineered safety features actuation sys Utils are investigating hardware changes that may preclude further testing provided that changes are feasible Otherwise tests will continue PETRICK N.A. Standardised Nuclear Unit Power Plant System 80/03/20 1p
- 800403020B Interim deficiency rept to electrical penetration assembly wire terminations Initiated Dunker-Ramo insp to determine cause Final rept will be submitted by 800430 BRYAN, J K Union Electric Co 80/03/26 ip
- 8004040362 Forwards final deficiency rept re potentially defective GE induction disc-type relays BRYAN, J.K. Union Electric Co. 80/03/27 1p
- --8004040368 Final deficiency rept investigation in response to IE Circular 80-01 revealed GE induction disc-type relays w/ higher than normal pickup voltage Caused by petroleum jelly lubricant Airangements made for GE replacement or mods + Union Electric Co 80/03/27 ip
- 8004(80486 Ack receipt of 800229 final deficiency rept re undersized field welds on small piping installed at plant NRC will complete review of matter during future insp FIORELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/01 ip
- 8004190369 Interim deficiency rept re-vertical fire dampers furnished by Ruskin Mfg Co Addl problems identified requiring new design mods Mods being developed & will be described in rept to be issued by 800515 PETRICKIN A Standardized Nuclear Unit Power Plant System PETRICK, N A :
- 8004290050 Ack recespt of 800326 interim deficiency rept re apparent crimping of terminal lugs for containment electrical penetration assemblies FIDRELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/14 ip
- 8004300060 Ack receipt of 800327 final rept re GE protective relay svc advice FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/14 ip
- DOCKET STN-50-484 TYRONE ENERGY PARK, UNIT 1 G Adjudicatory correspondence
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK, U Office of the Executive Director for Operations BO/04/02 34pp
- DOCKET STN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT 1 A Application/construction stage documents & correspondence
- B004040031 Advises of issuance of NUREC-0589. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSB, D.F. Division of Project Management B0/02/05 7pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 771226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- Q Adjudicatory correspondence
- 8004090192 Explains circumstances involving 800222 svc of BNNL draft rept re measurements of underground mining radon releases & NRC testimony of RM Wilde re same rept Missing enc i Page 6 onci BORDENICK.B M Hearing Branch 4 80/03/05 4pp

- NU4030726 Memilandin or interstanting between ARC 5 FEMA re prompt improvement in reducing all energetry planning % prepareduals distributed as Dear motifs ation (CCSTM to theire or the Executive Director for Operations 20/04/02 14pp
- I Financial information
- #8034153502 Ann al Firancial Fept 1979
 Rochester Gas ! Electric Comp #80703714 | 35pp
- 4 Inspection reports is rulleting a correspondence
- FOC4:00200 Responds to 16 Dulletin 79-28 Investigation re planned use of RAMOD EA13) suitches identification in SNUPPS design & development of plans for corrective action requires more time than anticipated Will forward response later PETRICK I. A Standardized Nuclear Unit Pouer Plant System 80/03/05 1p
- 8004150300 Forwards IE Into Notice 80-12 Instrument Failure Causes Opening or F09V & Block Valve 'No specific action or response necessary GRIER B H Region 1 Philadelphia. Orfice of the Director 80/03-31 to
- 8004070105 Forwards IE Circilar 20-05. 'Emergency Diesel Generator Lubricating Oil Addition's Onsite Supply No written response required GRIER B H Region 1 Philadelphia, Office of the Director BO/04/01 1p
- 8004110512 Forwards IE Into Notice 80-13 'GE Type SBM Control Switches Defective CAM Followers No written response required GRIER.B M. Region | Philadelphia, Office of the Director 80704702 | 19
- 8004240351 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees No action required GRIER, B H Region 1 Philadelphia, Office of the Director 80704702 1p
- 9004180243 Forwards IE Circular 80-67, 'Problems W/HPCI Turbine Oil Sys ' No written response required GRIER.0 H Region i. Philadelphia. Office of the Director 80/04/03 ip
- 8004230472 Forwards IE Bulletin 79-03A "Longitudinal Held Defects in ASME 5A-312 Type 304 Stainless Steel Pipe" Action required GRIER: B H Region i. Philadelphia Office of the Director 80/04/04 tp
- 8004186271 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Penetration Welds " Written response required GRIER.8 H Region 1. Philadelphia. Office of the Director 80/04/07 1p
- S Reportable occurrences, LERs & related correspondence
- 8004040267 Forwards supplemental rept on potential deficiency requalification of control sys discussed in util 790928 ltr No unresolved safety concerns re pressure controllers & main steam line atmospheric relief valve
 PETRICK.N A Standardized Nuclear Unit Power Plant System 80/02/05 2pp
- BGO4100533 Act receipt of BO0205 interim deficiency rept re qualification of control sys CARLSGN.R T Region 1 Philadelphia, Reactor Construction & Engineering Support Branch BO/02/21 1p
- 6004150179 Discusses undetectable failure in engineered safety features actuation sys Utils are investigating hardware changes that may preclude further testing provided that changes are feasible Otherwise, tests will continue PETRICK, N A Standardized Nuclear Unit Power Plant System 80/03/20 ip
- DOCKET STN-50-484 CALLOWAY PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- BOO4040031 Advises of issuance of NUREC-058B. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS.D F Division of Project Hanagement BO/02/05 7pp

- 8004070189 Forwards request for add) into to complete review of GA program PARR, D D | light Water Reactors Branch 3 80/03/20 App
- 8004180352 Forwards addl info re std plant QA programs for design & const. In response to NRC 800122 request Util commits to Reg Guide i 94 w/exception of requirements re structural bolt tightening & number of threads exposed beyond nut SEIKEN S J Standardized Nuclear Unit Power Plant System 80/04/14
- 8004280463 Updates 800401 meeting w/util & NRC ro OL applications Submits program for start of NRC review including initial meeting w/util project manager Applicants exploring other steps to aid NRC review PETRICK.N A Standardized Nuclear Unit Power Plant System 80/04/23 2pp
- F Security, medical, emergency & fire protection plans
- B0040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr. has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force B0/03/11 4pp
- Q Adjudicatory correspondence
- 8004210165 Order granting extension, until 800416, for Commission to elect whether to review Director's 800310 decision per 10CFR2 206
 CHILK 8 J Office of the Secretary of the Commission 80/04/10 is
- H Ceneral correspondence
- 8004070070 Discusses NRC program of upgrading emergency preparedness in environs of nuclear power plants in response to 800102 ltr Sys for alerting public must be demonstrated effective prior to QL issuance DENTON: HR Office of Nuclear Reactor Regulation 80/03/17 lp
- --800407007: Expresses concern re proposed evacuation plan for facility Alerting farmworkers to emergency within required time Uauld be difficult WEILL, 8 M Affiliation Unknown 80/01/02 1p
- G. Inspection reports. IE Bulletins & correspondence
- 8004100280 Responds to IF Bulletin 79-28 Investigation re planned use of NAMCO EA180 switches, identification in SNUPPS design & development of plans for corrective action requires mora time than anticipated Hill forward response later PETRICK.N A Standardised Nuclear Unit Power Plant System 80/03/06 Ip
- 800410014B Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director BO/03/07 1p
- B004150192 Forwards IE Info Notice B0-12, "Instrument Failure Causes Opening of PORV & Black Valve " No specific action or response necessary KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/31. Ip
- 8004080725 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Bupply " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/01
- 8004150057 Forwards IE Info Notice 80-13, "QE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/02 ip
- 8004180063 Forwards attachments to 1E Circular 80-03, "Protection From Toxic Gas Harards," inadvertently omitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02 1p
- 8004220153 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J G Region 3, Chicago, Office of the Director, 80/04/02 ip

- 8004220388 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/03 to
- 8004230282 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312:Type 304 Stainless Steel Pipe" Action required KEPPLER.J O Region 3: Chicago: Office of the Director 80/04/07 is
- 8004220098 Forwards IE Bulletin 80-08, "Exam of Containment Liner Panetration Welds " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/09
- 8004300144 Notification of 800423 meeting in Fulton,MD to discuss resident inspector program
 KEPPLER,J G Region 3. Chicago, Office of the Director 80/04/14
- --8004300178 Notification of 800423 meeting in Fulton.MD to discuss resident inspector program
 KEPPLER.J 0 Region 3, Chicago, Office of the Director 80/04/14
- --B004300184 Notification of 800423 meeting in Fulton,MD to discuss resident inspector program KEPPLER,J G Region 3, Chicago, Office of the Director 80/04/14 in
- --B804300189 Notification of 800423 meeting in Fulton.MD to discuss resident inspector program
 KEPPLER.J G Region 3, Chicago, Office of the Director B0/04/14
- --8004300194 Notification of 800423 meeting in Fulton,MD to discuss resident inspector program Agenda encl KEPPLER,J G Region 3. Chicago, Office of the Director 80/04/14
- S Reportable occurrences, LERs & related correspondence
- 8004040267 Forwards supplemental rept on potential deficiency re qualification of control sys discussed in util 770928 ltr No unresolved safety concerns re pressure controllers & main steam line atmospheric relief valve PETRICK: N A Standardized Nuclear Unit Power Plant Bystem 80/02/05, 2pp
- 8004100533 Ack receipt of 800205 interim deficiency rept re qualification of control sys CARLSON,R T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/21 ip
- B004090127 Ack receipt of B00215 final deficiency rept re Ruskin Mfg Co fire dampers CARLSON,R T Region i, Philadelphia, Office of the Director B0/03/04 ip
- 8004130177 Discusses undetectable failure in engineered safety features actuation sys Utils are investigating hardware changes that may preclude further testing provided that changes are feasible Otherwise, tests will continue PETRICK.N A Standardized Nuclear Unit Power Plant System 80/03/20 ip
- 8004180486 Ack receipt of 800227 final deficiency rept re undersized field welds on small piping installed at plant NRC will complete review of matter during future insp FIDRELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/01 ip
- 8004130367 Interim deficiency rept re vertical fire dampers furnished by Ruskin Mfg Co Addl problems identified requiring new design mods Mods being developed & will be described in rept to be issued by 800515 PETRICK.N A Standardized Nuclear Unit Power Plant System 80/04/03 2pp
- 8004300060 Ack receipt of 800327 final rept ra GE protective relay svc advice FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/04/14 1p

- DOCKET SIN-50-489 PERKINS NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004170327 "TMI-Plus One Toward a Sarær Nuclear Power Program "

 * Duke Power Co 60/03/26 13pp
- G004140430 Forwards companison of draft STS w/snubber functional test sampling plan COLLINGS.D M. Duke Power Co. 80/04/03 line
- 8004210405 Summary of 600328 meeting w/near-term CP applicants in Bethesda, MD re evaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident
 THOMAS, C O Standardization Branch 80/04/03 43pp
- 8004300074 Summary of 800319 meeting w/near-term CP applicants in Bethesda MD re resumption of CP application review activities associated w/TMI-2 accidents THDMAS.C O Standardization Blanch 80/04/03 12pp
- BD04240557 Summary of B00402 meeting w/Near-Term CP Applicants Group in Bethesda,MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl THOMAB.C D Light Water Reactors Branch i 80/04/07 47pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GUSSICK, U Office of the Executive Director for Operations 60/04/02 34pp
- G Inspection reports, JE Bulletins & correspondence
- 8004230085 Submits response to IE Bulletin 80~03 Review revealed that no charcoal adsorber cells have been received from manufacturers

 DAIL. L C Duke Power Co 80/03/19 ip
- 8004150305 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/03/31 2no
- 8004080604 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 2pp
- B004i30075 Forwards IE Info Notice 80-i3, "GE Type 98M Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240254 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004180375 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Bys " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/03 2pp
- 8004230122 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004180351 Forwards IE Builetin 80-08, "Exam of Containment Liner Penetration Helds " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/07

- I was gift " 48) comp to John Station Unit 2
- . . . pli aris construction arage documents & correspondence
- the 131 MJ/Ises of issiance of NIREC-0588. Interin Staff Position is priar in Publification in seri-Related Electrical Equipment of 13103, journette nethods for compliance with LT Invision of image. Kanagement 80/02/05. 7pp
- Ta, 1927 TM, files (e fourto a Earer Nuclear Power Program "
 Diversuer Chill (1937) To 1355
- 1734t40430 Figures impaire or draft STB u/snubber functional test
 dampling plan
 CLIPE DM DM Pare Folger Ch 60/04/03 lipp
- C0242104D5 Ourhany of C0 23 ceeting U/near-term CP applicants in Befreeda.HD relevaluation of progress made to date eshablishing proposed requirements stemming from TMI-2 accident THUMAS CO Ctandardization Shanch 80/04/03 63pp
- "TU4D00074 Simmary or 3U J19 meeting withear-Term CP Applicants Group in Bethesia MU ne matters related to resumption of CP application relieu arti ities associated w/TMI-2 accidents TMOM/3 C Q Otandardication Granch B0/04/03 (22p)
- G (14240557 Simmany or Mildia meeting u/Near-Term CP Applicants Group in Bathasia M5 re-progress hade establishing proposed requirements sherising from FMT-2 accident Proposed requirement category assignments end! Thirds F G Light Mater Reactors Branch 1 80/04/07 47pp
- > Adjudscatory correspondence
- #2504030526 Memoranium of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GDEBICHILLY Office of the Executive Director for Operations 90/04/62 34pp
- Inspection reports, If Bulletins & correspondence
- CC04233035 Submits response to IE Bulletin 80-03 Review revealed that no charcoal adsorber cells have been received from manufacturers

 [CAIL C Dute Power Co 80/03/19 ip
- BCC4150505 Forwards IE Into Notice 80-12, "Instrument Failure Causes Deeming of PORV 5 Block Valve No specific action or response nocessary O REILLY, J.P. Region 2 Atlanta Office of the Director 80/03/31
- EC04080604 Forwards IE Circular 80-05, "Emergency Diesel Generator Inbritating 0:1 Addition & Onsite Supply "No written response required O REILLY J.P. Region 2. Atlanta, Office of the Director 80/04/01 2pp
- G304150075 Forwards IE Info Notice B0-13, "GE Type SBM Control Switches Defective CAM Followers ho specific action or response required O'REILLY J.P. Region 2 Atlanta, Office of the Director 80/04/02 Zpp
- ©304240254 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required D REILLY J.P. Region 2, Atlanta. Office of the Director 80/04/02 Rep
- BGO4180375 Forwards IE Circular 80-07. 'Problems W/HPCI Turbine Oil Sqs " No written response required O'REILLY J.P. Region 2 Atlanta Office of the Director BO/04/03 289
- 8004230122 Forwards IE Bulletin 79-03A 'Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY/JP Region 2: Atlanta: Office of the Director 80/04/04 ip
- BO04180351 Forwards IE Suiletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required D'REILLY. J.P. Region 2. Atlanta, Office of the Director 80/04/07 2pp

- DOCKET STR-50-190 FERKINS NUCLEAR STATION. UNIT 3
- A Application/construction stage documents & correspondence
- 2004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D F Division of Project Management 80/02/05 7pp
- 8004170327 "TMI-Plus One Toward a Safer Nuclear Power Program "
 * Dute Power Co 80/03/26 13pp
- 8004210405 Summary of 800328 meeting w/near-term CP applicants in Bethesda. MD re evaluation of progress made to date establishing proposed requirements stemming from TM1-2 accident
 THOMAS. C O Standardization Branch 80/04/03 63pp
- 8004300D71 Summary of 800319 meeting w/Near-Torm CP Applicants Ordup in Bethesda. HD re matters related to resumption of CP application review activities associated w/YMI-2 accidents THOMAS. C O Standardization Bronch 80/04/03 12pp
- BO04240557 Summary of BO0402 meeting w/Near-Term CP Applicants Group in Bethesda MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl THOMAS.C O Light Water Reactors Branch 1 BO/04/07 47pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GDSBICK.L V Office of the Executive Director for Operations BO/04/02 34pp
- P Operating license stage documents & correspondence
- 8004140430 Forwards comparison of draft STS w/snubber functional test sampling plan COLLINGS,D M Duke Fower Co 80/04/03 11pp
- G Inspection reports, IE Bulletins & correspondence
- 8004230085 Submits response to IE Builetin 80-03 Review revealed that no charcoal adsorber cells have been received from manufacturers DAIL.L C Duke Power Co 80/03/19 1p
- 8004150505 Forwards IE Info Notice 80~12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary D'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 2pp
- 8004080604 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01 2pp
- 8004150075 Forwards If Info Notice 80-13, "GE Type 8DM Control Bwitches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 200
- 8004240254 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02 2pp
- 8004180375 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Sys "No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/03 2pp
- 8004230122 Forwards 1E Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY. J P Region 2. Atlanta, Office of the Director B0/04/04 is
- 8004i8035i Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/04/07 2pp

DOCKETED ITEMS

- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project hanagement 80/02/05 7pp
- 8004170327 "TMI-Plus One Toward a Safer Nuclear Power Program " # Duke Power Co 80/03/26 13pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSICK,L V Office of the Executive Director for Operations 80/04/02 34pp
- P Operating license stage documents & correspondence
- B004140430 Forwards comparison of draft STS w/snubber functional test sampling plan CDLLINGS,D M Dute Power Co B0/04/03 lipp
- G Inspection reports, IE Bulletins & correspondence
- 8004230085 Submits response to IE Bulletin 80~03 Review revealed that no charcoal adsorber cells have been received from manufacturers

 DAIL, C Duke Power Co 80/03/19 ip
- 8004220105 Ack receipt of IE Insp Repts 50-491/80-02,50-492/80-02 & 50-493/80-02 an 800224-29 No proprietary info 80/03/28 lp
- --8004220117 Forwards IE Insp Repts 50-491/80-02.50-492/80-02 & 50-493/80-02 on 800226-29 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --B004220134 IC Insp Repts 50-471/B0-02.50-492/B0-02 & 50-493/B0-02 on B00226-27 No noncompliance noted Major areas inspected QA program implementation.const program changes & QA audits MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch RAUSCH.J K Region 2. Atlanta, Office of the Director 80/03/24 3pp
- 8004240426 Ack receipt of IE Insp Repts 50-491/80-03,50-492/80-03 & 50-493/80-03 on 800303-05 No proprietary info DAIL, L C Duke Power Co 80/03/28 ip
- --8004240430 Forwards IE Insp Repts 90-491/80-03,50-492/80-03 & 80-493/80-03 on 800303-03 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004240434 IE Insp Repts 50-491/80-03.50-492/80-03 & 50-493/80-03 on BOO303-05 No noncompliance noted Major areas inspected structural concrete & steel GA & GC.settlement monitoring program CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch LENAHAN.J J Region 2. Atlanta. Office of the Director 80/03/19 5pp
- 8004190505 Forwards IC Info Notice 80-12, "Instrument Failure Gauses Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080604 Forwards IE Circular 80-05, "Emergancy Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01

- 8004190075 Forwards IC Into Notice 80-13, "CE Type SBM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2 Atlanta Office of the Director 80/04/02 200
- B004240254 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180375 Forwards 1E Circulat 80-07, "Problems W/HPC! Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004230122 Forwards IE Rulletin 79-03A 'Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Ortice of the Director 80/04/04 in
- 8004180351 Forwards JE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director BD/04/07
- DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 800404003i Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Ejectrical Equipment." providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004170327 "TMI-Plus One Toward a Safer Nuclear Power Program " * Duke Power Co 80/03/26 13pp
- 8004140430 Forwards comparison or draft STS w/snubber functional test sampling plan CQLLINGS.D M. Duke Power Co. 80/04/03 11pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates. requested by NRC 791226 ltr.has been postponed pending GAQ clearance under Federal Repts Act GRIMES:B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC > FEMA re prompt improvement in redicingical emergency planning > preparedness, distributed as Board notification GUSSICKL V Office of the Executive Director for Operations BO/04/02 34pp
- 9 Inspection reports, IF Bulletins & correspondence
- 8004230085 Submits response to IE Bulletin 80-03 Review revealed that no charcoal adsorber cells have been received from manufacturers
 DAILL C Dute Power Co 80/03/19 1p
- 8004220105 Ack receipt of IC Insp Repts 50 491/80-02,50-492/80-02 & 50-493/80-02 on 800226-29 No proprietary info DAIL, L C Duke Power Co 80/03/28 ip
- --8004220119 Forwards IC Insp Repts 50-491/80-02.50-492/80-02 & 50-493/80-02 on 800226-29 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --8004220134 IE Insp Repts 50-491/80-02, 50-492/80-02 & 50-493/80-02 on 800226-29 No noncompitance noted Major areas inspected QA program implementation, const program changes & QA audits MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch RAUSCH, J K Region 2, Atlanta, Office of the Director 80/03/24 3pp
- 8004240426 Ack receipt of IE Insp Repts 50-491/80-03, 50-492/80-03 & 50-493/80-03 on 800303-05 No proprietary info DAIL, L C Duke Fower Co 80/03/28 ip

- india will Figure victors Fepts 50-171/80-03:50-492/80-03 & " will victor victor in from compliance mated "Pay Till swap rice vil the Pearton Construction & Engineering approximation to The way with the results of the way
- Fig. 434 % 164 here, 1 471/20-03 50 492/80-03 & 50-493/80-03 on CO has replay enoted Major areas inspected are right and reset on 1 92 settlement monitoring program Co to The Figure 2 Artantal Reactor Construction & Engineering
- program

 Contribution Figure 2 orlands Reactor Construction & Engineering

 Appart Frame Forth of the Pegion 2 Atlanta, Office of the

 Director 2 5 1/2 Sp.
- ET 4150105 Forwards IE Info hitice Bu-12 "Instrument Failure Causes Opening or Pint's Place of e. No specific action or response recessory (FREILLY F) Region at Arlanta Office of the Director 80/03/31 App.
- ' 14070'-04 F rushas IE Circular ED 05 Emergency Diesel Generator Lutri ating Oil Addition ' Onsite Supply ' No unitten response required O RELIE: 1 P Region Atlanta Office of the Director 80/04/01 259
- 6734152 75 Forwards IE Inno Notice 80-13 'GE Type SBM Control Switches Lefective TAM Followers no specific action or response required O REILLY J.F. Region 2 Arlanta Orfice of the Director 80/04/02 2pp
- CC4Z40_54 Forwards IE (nfo Notice 80-14, "Safety Suggestions From Employees" No action required O FEISLY J.P. Region P. Atlanta Orfice of the Director BD/04/02 2pp
- GC041803/5 Forwards IC Circular 80-07, 'Problems W/HPCI Turbine Oil Sys ' No written response required O REICLY J.F. Ragion 2. Atlanta, Office of the Director 80/04/03 2pp
- 8504230122 Forward: IE Bulletin 79-03A 'Longitudinal Held Defects in ASME SA-312 Type 324 Stainless Steel Pipe " Action required D REILLY, J P Region 7 Atlanta, Office of the Director 80/04/04 ip
- 2304(8005) Forwards IE Bulletin 80-08 "Exam of Containment Liner Penetration Helds" Written response required O'REILLY J.P. Region 2. Atlanta, Office of the Director 80/04/07 2pp
- COCKET 3IN-50-473 CHERG/EE NUCLEAR STATION, UNIT 3

 A Application/ronstruction stage documents & correspondence
- GC04040031 Advises of issuance of NUREC-058B. "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment, providing guidance re-methods for compliance FCSS.D F Division of Project Management 80/02/05 7pp
- 6304170327 "TMI-Plus One Toward a Safer Nuclear Power Program " • Duke Power Co 60/03/26 13pp
- 8004140430 Forwards comparison of draft STS w/snubber functional test tampling plan COLLINOS.D H Dute Power Co 80/04/03 11pp
- F Security, medical emergency b fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by IRC 791926 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Roard notification GUSSICK, L V Office of the Executive Director for Operations

- @ Inspection reports, IE Pulletins & correspondence
- 2004230085 Submits response to 1E Bulletin 80-03 Review revealed that no chaicoal adsorber cells have been received from manufacturers DAIL,L C Dute Power Co 80/03/19 1p
- 8004220105 Ack receipt of 1E Insp Repts 50-491/80-02,50-492/80-02 & 50-493/80-02 on 800226-29 No proprietary info DAIL, L C Duke Power Co 80/03/28 1p
- --8004220117 Forwards IE Insp Repts 50-491/80-02,50-492/80-02 & 50-493/80-02 on 800226-27 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --B004220134 IE Insp Repts 50-491/B0-02.50-492/B0-02 & 50-493/B0-02 on B00226-27 No noncompliance noted Major areas inspected GA program implementation.const program changes & GA audits MARPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch RAUSCH, K Region 2. Atlanta. Office of the Director B0/03/24 3pp
- 8004240426 Ack receipt of IE Insp Repts 50-491/80-03,50-492/80-03 & 50-493/80-03 on 800303-05 No proprietary info DAIL, L C Duke Power Co 80/03/28 ip
- --8004240430 Forwards IE Insp Repts 50-491/80-03.50-492/80-03 & 50-493/80-03 on 800303-05 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/03/20 2pp
- --8004240434 IE Insp. Repts 50-491/80-03,50-492/80-03 & 50-493/80-03 on 800303-05 No noncompliance noted Major areas inspected structural concrete & steel QA & GC; settlement monitoring program CONLON,TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch LENAHAN,J J Region 2, Atlanta, Office of the Director 80/03/19 5pp
- BO04150505 Forwards 1E Info Notice 80-12. "Instrument Failure Causes Opening of FORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta, Office of the Director BO/03/31
- BOD40B0604 Forwards IE Circular 80-03, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written 'response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01
- 8004150075 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240254 Farwards 1E Info Notice 80-14, "Bafety Suggestions From Employees" No action required O'REILLY, J P Region 2, Atlanta, Office of the Director BO/04/02 200
- 8004180375 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Sys " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03, 2pp
- 8004230122 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 6A-312. Type 304 Stainless Steel Pips" Action required. O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/04 ip
- 800418035; Forwards IF Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/07 2pp

DOCKET STN -50-495 SWESSAR-P1

- A Application/construction stage documents & correspondence
- 8004280065 Responds to 800128 request for info re testimony before Public Utils Commission & forwards LER 78-53/01T-0.781206 backup rept & list of documents on dockets for Oct 1978-Mar 1979 Mar 1979-May 1979 Request list encl RUBBELL, ## T Technical & Administrative Support Branch 80/02/05 2pp

~-8004260098 Forwards QA Program Insp Rept 99900507/79-03 on 790501-04 & notices of violation & deviation Summarizes background info on related enforcement issue REINMUTH, G W Division of Reactor Construction Inspection 79/08/10 Jpp

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION. UNIT 1

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREC-0388. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSB.D F Division of Project Hanagement 80/02/05 7pp

I Financial information

8004180320 Forwards Annual Financial Repts 1979 BISHOP, R W Northeast Utilities 80/04/02 ip

J Insurance & indemnity information

8004160254 Forwards Endorsements 57 & 58 MAELU Policy MF-52 IFFLAND, R R Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 3pp

DOCKET 90-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSB, D F Division of Project Management

I Financial information

8004150320 Forwards Annual Financial Repts 1979 BISHOP,R W Northeast Utilities 80/04/02 1

J Insurance & indemnity information

8004160254 Forwards Endorsements 57 & 58 MAELU Policy MF-52 IFFLAND,R R Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 App

DOCKET STN-80-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp

8004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROS8,D F Division of Project Management 80/02/21 Spp

8004040240 Updates nine point action program re QA program identified in util 791228 ltr & 800125 status rept Actions 1-3 & 5-8 have been implemented Proposes to begin placement of safety-related complex concrete on 800303 OPREA:O W Houston Lighting & Power Co 80/02/28 3pp

B00423005B Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident info should be provided as amend to application Bubmittal schadule should include NRC approval prior to issuance of OL W/encl ROSB, D. F Division of Project Management B0/03/10 53pp

8004180128 Forwards request for add1 info concerning review of facility FBAR PARR:0 D. Light Water Reactors Branch 3 80/03/18 5pp

8004010377 Advises that instrumentation & control diagrams for review of FBAR Chapter 7 have been transmitted to OW Burte of ORNL in response to NRC request
BARKERID, G. Houston Lighting & Power Co 80/03/28 3pp

8004140463 Forwards Lower CO River Authority data re South TX Interconnected Sys interchange for 1979 Data should provide index re types & magnitude of member interchange within South TX Interconnected Sys WEST.NE Teras, State of 80/04/07 14pp

F Security, medical, emergency / rire protection plans

8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
GRIMES B K Emergency Preparedness Task Force 80/03/11 4pp

G Adjudicatory correspondence

8004100274 No objection to intervenor Citizens Concerned About Nuclear Power, Inc 800302 motion for extension to answer applicant second set of interrogatories Objects to mischarecterizations made in motion Certificate of Svc encl BIDDLE.C T Houston Lighting 9 Power Co BIDDLE.C T Baker & Botts 80/03/06 Spp

8004020136 Response to ASLB 800310 memorandum inviting views re feasibility of early hearing Concurs w/ASLB suggestions & desires to participate in hearing within memorandum conditions Certificate of Svc encl CULP,R H, SCRUARZIM D Houston Lighting & Power Co CULP,R H Lowenstein, Newman, Reis, Aiglind & Toll 80/03/19 4pp

8004280047 Response to ASLB 800310 memorandum re hearing to consider issues on alleged const & QA/QC deficiencies Early hearing may foreclose possibility of raising similar issues at later time Certificate of Bvc encl
SINKIN.L Citizens Concerned About Nuclear Power, Inc 80/03/24
4pp

B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GUSBICK.L V Office of the Executive Director for Operations 80/04/02 Jup

8004210414 Response to ASLB 800310 memorandum inviting views re feasibility of separating admitted contentions Views will be submitted when IE investigation re assessment of GA/GC effectiveness is completed W/Certificate of Svc TREBY.S A Hearing Branch 1 60/04/10 2pp

K Utility Final Bafety Analysis Report (FSAR) & amends

8004220743 Forwards Amend 10 to FSAR.consisting of responses to first round review questions concerning initial startup testing Affidavit encl TURNER.E A Houston Lighting & Power Co 80/04/21 3pp

--8004220769 Amend 10 to FSAR

* Hauston Lighting & Power Co 80/04/21 125pp

M Antitrust correspondence

BOO402020B Response to Central & South West Corp et al second request for production of documents Stags Sys Inc workpapers available for insp & copying Documents re transactions already produced Certificate of Svc encl COPELAND, J Q Houston Lighting & Power Co COPELAND, J Q Baker & Botts 80/02/23 4pp

B004040072 Notice of appearance in proceeding Certificate of Syc encl FABRIKANT,R Justice:Dept of 80/02/25 App

8004110030 Discusses add) request for documents located in Chalker personal files Request is untimely & deficient, failing to specify relevancy to proceeding No obligation to respond to request by 800227, per Commission Rules of Practice STAHL.D M Isham, Lincoln & Beale 80/02/25 2pp

8004020147 Forwards DDJ & NRC 800228 joint motion for mod of ASLB erdar re settlement discussions & for issuance of order to compel production of certain documents & testimony Proposed order encl CYPHERT, S.B. Justice, Dept of CHANANIA, F.D. Antitrust Division .

--B004020164 Joint motion for mod of ASLB 790416 order re-protection of settlement discussions & for issuance of order to compel production of documents & testimony from Houston Lighting & Power & TX Utils W/Certificate of Evc CYPBERTIS B , DDPSDVIC.D A Justice.Dept of CHANANIA.F D Antitrust Division B0/02/2B 120pp

- 1004620175 Oral 1803514100 of ED Branch to contification of questions Pp 2-8

 A Atomic Savety and Licensing Board Panel SCARTH/E D

 Aftilisation Unknown 10 Cd 2d Spp
- -3034CFURN Manna to check It Utils Cos to supplement Apr & Jul 1979 response, to first set at interrogatories & requests for production at facurers Lijes performance of current new colligations & ECGRAP Manufesticate of Svc & proposed order CYFLERT S B (USUF): Justice Dept at 86/02/28 7pp
- --6004620170 Mation to compel Houston Lighting & Power to supplement 790111 / 0427 ensuers to 701122 interrogatories Urges Fulfillment of current abligations arising from development of neu into Lettificate on Soc / proposed order enci CYPHERT, 3 B . LUGUE B Justice Dept of 80/02/28 7pp
- --BOD40E0193 Joint application for issuance of subpoend directed to ED Scarth of TX Utils Generating Co // DE Simmons of Houston Lighting // Power Requests entension until BOD402 to depose DE Simons Draft subpoends // Certificate of Svc encl CYPHERT 5 B DDP50VIC.D A Justice, Dept of BLUME, M Antitrust Division BO/02/EB 7pp
- GOO4020098 Motion for protective order the disclosure of Diamond Shannock Corp documents in response to ASLB BOOHB subpoena duces tecum Documents in question are subj or contractual obligations Certificate of Suc 5 proposed order encl CYPHERT, S.B. Justice Dept. or GO/02/29 10pp
- 8004030174 Notifies of change of address for counsel of South TX Electric Cooperative, Inc.* Medina Electric Cooperative, Inc. effective 800310 JDRN D F Akin, Gump. Hauer & Feld 80/03/04 1p Akin, Gump, Hauer & Feld B0/03/04 1p
- 8004100498 Discovery rept for Feb 1980 Southwest TX Electrical Cooperative, Inc / Medina Electric Cooperative, Inc neither initiated nor received any discovery requests Certificate of Sve encl JOHN, D F Akin Gump. Hauer / Feld BO/03/04 4pp
- 8004110574 Confirms 800779 telcon re DOJ subpoens of documents from Golf States Utils Subpoens covers certain areas also covered in Brownsville Public Utils subpoens Util documents will be available to all parties
 RADER R M Conner, Moore & Corber 80/03/04 2pp
- 8004080557 Requests pretrial conference to clarify procedural matters re ASLS 791214 order filing testimony summaries % designation of trial exhibits
 CYPHERT, S. B. Justice, Dept of CHANANIA, F. D. Antitrust Division RITIS, F. H. Teyas-Louisiana Electric Cooperative, Inc. 60/03/05
 2pp
- 8004090204 Discovery rept for Feb 1980 Deposed M Taylor, M Hebb, DE Simmons A. EL Matson Participated in depositions noticed by TX-LA Electric Cooperative 5. City of Brownsville. TX Reviewed Diamond Shamioci documents Filed application for subpoenas CYPHERT, S. B. PARKENTER, F. H. Justice. Dept of 80/03/05 5pp
- 8004090387 Discovery rept for Feb 1980 Participated in A Gerber, M Hebb, E Simmons. V Robertson & GW Beams depositions Attended J Turk. & S Philips depositions Filed motion for addl time to respond to TX Utils interrogatories W/Certificate of Svc CARNEY, J A Central & Southwest Corp CARNEY, J A [sham, Lincoln & Beale 83/03/05 7pp
- 8004090421 Discovery tept for Feb 1980 No discovery requests received nor initiated Certificate of Svc encl MOOD, J C San Antonio, TX HODD, J C Matthews, Nowlin, Macfarlane & Barrett 80/03/05 4pp
- 8004110024 Discovery rept for Feb. 1980 City of San Antonio, acting by & through City Public Svc Board of San Antonio, neither initiated nor received any discovery requests Certificate of Soc and Svc encl WOOD.JC San Antonio. TX 80/03/05 4pp
- 8004110056 Response to Houston Lighting & Power 800219 motion to compel interrogatory answers by DOJ re C Stover proposed expert testimony DOJ has no add1 info to provide except for facts stated in this response W/Stover Itr & Certificate of Svc CYPMERT. 8 B Justice, Dept of 80/03/05 Spp
- 8004030344 Comments by Public Utils Board of City of Brownsville, TX on MRC & DOJ motion for mod of ASLB order to protection of settlement discussions & for order to compel documents & testimony Urges clarification of scope W/Certificate of Svc POIRIER, MR Texas, State of B0/03/06 18pp

- 8004080273 Response in opposition to DOJ / NRC joint motion for mod of ASLB order re-settlement discussions & for order to compel production of documents Negotiations for settlement purposes are protected from discovery per case law & per rules
 SOUNNIGHT. J A Houston Lighting & Power Co * Baker
 Lowenstein, Neuman, Reis, Axeliad & Toll NRC 80/03/06
- --8004080285 Response seeking dismissal of DOJ 800228 motion to compel UUQQUOCHD RESPONSE SEEFING DISMISSAI OF DUD GOVERN METER AS EXPERIENTATION OF INTERCEPT OF METER AND ANSWERS WERE SERVED ON THE TESPONSES A RE APPROPRIATE W/Certificate of Syc FRANKLIN.W J Houston Lighting & Power Co & Baker & Botts Lowenstein, Newman, Reis, Axelrad & Toll 80/03/04 App
- 8004080360 Response in opposition to DOJ % NRC joint motion for mod of ASLB order re-settlement discussions & for order to cumpel production of documents NRC policy avoring settlement is designed to protect sources involved W/Certificate of Svc * Central / Southwest Corp * Isham, Lincoln & Beale DO/03/06
- 8004080638 Response in opposition DOJ & NRC 800228 joint motion for mod of ASLB order re-settlement discussions & for order to compel production of documents Negotiations must be protected per Rule of Evidence 408 W/Cortificate of Svc AHEARN, C D Teras Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/03/04 30pp
- 80040701B5 Notice of appearance on behalf of Public Utils Board of City of Brownsville,TX,in consolidated discovery Certificate of Svc encl
 Svice encl
 SPIEGEL.6 Texas, State of SPIEGEL.G Spiegel & McDiarmid 80/03/06 6pp
- 8004090434 Discovery rept by Public Utils Board of City of Brownsville, TX, for Feb 1980 Doposed M Borchelt of Central Power & Light Participated in R Edelstein deposition Received documents from Central & South West Corp Certificate of Svc encl POIRIER, M R Texas, State of POIRIER, M R Bpiegel & McDiarmid 80/03/04 App
- GOO4100218 Notifies that DOJ received Houston Lighting & Power Co supplemental answers to Control Power & Light Co first interrogatories w/o apps Requests Attachment A to Houston Power & Light Co second set of addl answers to NRC CYPHERT, S B Justice, Dept of 80/03/06 1p
- 8004100433 Notice of appearance of O Spiegel on behalf of Public Utils Commission of Brownsville.TX Certificate of Svc encl SPIEGEL, O Brownsville.TX SPIEGEL, O Spiegel & McDiarmid 80/03/0b épp
- BOD4100535 Discovery rept for Jan & Feb.1780.City of Austin has neither initialed nor received any discovery requests 9ACDUGHR C Austin, TX BO/03/07 5pp
- 8004080044 Response by Public Utils Board of City of Brownsville.TX, in opposition to Central & Southwest Corp 800222 motion for protective order re second set of interrogatories & production of documents W/Certificate of Svc & 800207 itr POIRIER,M R Teras, State of POIRIER,M R Spiegel & McDiarmid 80/03/10 12pp
- BOO4100514 Forwards notice of taking of deposition of D Springs AHEARN.C D Debevoise & Liberman BO/03/10 tp
- 8004110169 Notifies that W Scott deposition scheduled for Mar is cancelled Cancellation based on DOJ representation that Scott would be called as expert withness BALDWIN, J M Baker 2 Botts BO/OG/10 5pp
- B00408001B Updated response to first set of interrogatories & document requests includes info re untresses competitive utils, product & geographic market & petitions to intervene Prop qualifications of DA Springs & Certificate of Bvc ancl BURCHETTE.W H Texas-Louistana Electric Cooperative, Inc BURCHETTE,W H Northcutt Ely 80/03/11 27pp.
- 8004090164 Second supplemental response to first set of interrogatories & document requests includes info re projected leads. capacity & reserves as of 800215 SLICKER.F K Texas Utilities Co SLICKER.F K Worsham, Forsythe & Sampels 80/03/11 5pp

- 8004090175 Supplemental response to third set of interrogatories & document requests Supplemental answer to Interrogatory 18 encl W/o encl SLICKER.F K Texas Utilities Co SLICKER.F K Worsham, Forsythe & Sampels 80/03/11 3pp
- 8004090180 Supplemental response to first set of interrogatories & document requests includes info re monthly fuel cost adjustments for 1979
 SLICKER.F K Texas Utilities Co SLICKER.F K Worsham, Forsythe & Sampels 80/03/11 4pp
- 8004100084 Forwards DOJ subpoens requiring DE Simmons, util vice president, to testify 800331-0402 Confirms that Simmons will be available for deposition on 800404-05 instead of dates listed in subpoens W/o encl CYPHERT, S. B. Justice, Dept of 80/03/11 1p
- 800410022I Fourth supplemental response to first set of interrogatories & document requests Includes info re cities & utils which have explored power alternatives offered by TX Utils Co SLICKER, F K Texas Utilities Co SLICKER, F K Horsham, Forsythe & Sampels 80/03/ii 3pp
- 8004030258 Response in opposition to schedule proposed by NRC for reply to motion to quash 800221 subpoens directed to R Frame Merit of NRC argument will be better evaluated after Lerner deposition 80ggests 800321 for reply W/Certificate of Svc KNOTTB, J B Teras Utilities Generating Co 80/03/12 5pp
- 8004020113 Forwards Houston Lighting & Power 800313 petition for directed certification of ASLE 800307 order re confidential documents of settlement negotiations BOUKNIGHT, J A Lowenstein, Newman, Ress, Axelrad & Toll 80/03/13
- --8004020119 Petition for directed certification, interim stay & review of ASLS 800307 order requiring Houston Lighting & Power to produce settlement negatiations documents Urges reversal of ruling M/excerpts of 800307 prehearing transcript BOUKNIGHT.J A . GREEN, D & Houston Lighting & Power Co BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13 19pp
- --8004020122 Order re NRC 790323 motion to compel further answers to Houston Lighting & Power first interrogatories Directs util to furnish list of privileged documents Orders responses to majority of questions W/excerpts of 790601 prohearing HILLER.M E Atomic Safety and Licensing Board Panel 79/04/16 San
- 8004080028 Forwards DDJ third supplemental response to Houston Lighting & Power Co first set of interrogatories Documents responsive to util 790204 second set of interrogatories encl Documents re second interrogatories not encl CYPHERT.8 B Justice.Dopt of 80/03/13 ip
- --8004080033 Third supplemental response to first set of interrogatories & document requests Includes info re GT Taylor testimony refour relevant product markets in proceedings
 CYPHERT.8 0 Justice.Dept of 80/03/13 30pp
- 8004080073 Application for issuance of subpoena directed to FG Arey of Mebster Engineering Corp. to be deposed & to produce documents re interconnections by interconnected sys Draft subpoena & Cartificate of Svc encl OREEN.D O Houston Lighting & Power Go * Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13 13pp
- 8004090439 Ack receipt of & accepts 800312 ltr in lieu of interrogatory answer per 800307 prohearing ruling Ltr does not solve Houston Lighting & Power problems re C Stover deposition DOJ 800311 & 12 ltrs & Certificate of Svc encl OREEN,D O Lowenstein, Nawman, Reis, Azelrad & Toll 80/03/13 10pp
- 8004100345 Response to third set of interrogatories Includes info re electric power & energy delivered to various utils during Dec 1979 Certificate of Svc enc! * Texas Electric Service Co 60/03/13 15pp
- 8004080370 Discovery rept for Feb 1980 Deposed J Wilson, CC Campbell & V Robertson et al Attended DOJ & NRC depositions, Served 800201 first set of interrogatories to NRC Received additesponses to interrogatories Certificate of Svc encl FRANKLIN.W J Houston Lighting & Fower Co # Baker & Botts # Lowenstein, Newman, Reis, Axelrad & Toll 80/03/14 7pp
- 800404007B Comments by Public Utils Board of City of Brownsville.TX, stating no position re consolidation for trial advised by ABLB during 800307 prehearing If consolidation ordered right of cross-examination must be preserved W/Certificate of syc POIRIER.M R , POIRIER.M R. Texas. State of 80/03/17 7pp.

- 8004080153 Statement in opposition to consolidation of proceedings for hearing purposes, per ACLB 800307 prehearing conference request Issues not identical ! evidence in South TX Project may not be related to Commanche Peak M/Certificate of Svc STAHL, D M Central & Southwest Corp STAHL, D M Isham, Lincoln & Beale 80/03/17 9pp
- 8004080247 Discovery rept for Feb 1980 Participated in Ammons, Beams, Borchelt. Campbell, 5 Yashrough depositions Inspected DDJ documents Received 5 opposed Central & Southwest motion for additime to reply to interrogatories W/Certificate of Svc AHEARN, C D Teras Utilities Co AHEARN, C D Debevoise & Liberman BD/03/17 5pp
- 8004080401 Submits TX Utils Generating Co response to ASLB 800307 request re views on consolidation or proceedings for hearing pulposes Urges complete consolidation KKOTTS.J B Debevoise 5 Liberman B0/03/17 4pp
- 8004080663 Order confirming results of 800307 oral argument NRC & DDJ joint motion, re-mod of order concerning protection of settlyment discussions, granted in part Parties may not engage in further discovery re-documents included in motion GLABER! M. L. Atomic Safety and Licensing Board Panel 80/03/17 200
- 8004070427 Discovery rept for Jan-Feb 1980 Participated in M Diymy deposition No discovery requests initiated Certificate of Svc encl BURCHETTE, W H Texas-Louisiana Electric Cooperative Inc BURCHETTE, W H Northcutt Ely 80/03/19 3pp
- 80040105;7 Order dunying RRC 8003;1 motion to quash subpoems of R Frame TX Utils Generating Co entitled to test ND Lerner credibility by questioning work & documents prepared by Frame for Lerner review WOLFE,S J Atomic Safety and Licensing Board Pane; 80/03/20 2pp
- 8004030347 Response in opposition to TX Utils Generating Co-Houston Lighting & Power Co & South West Corp 800313 petitions for directed certification of order compelling production of documents News article & Certificate of Svc encl CHANANIA:F D , BLUNE:M B , HODODON,A P Antitrust Division 80/03/20 2198
- 8004100177 Memorandum in opposition to petitions for directed certification filed by TX Utils Generating Co.Houston Lighting & Power Co & Central & South West Corp et al.re ASLB 800307 order Certificate of Svc encl CYPHERT. S B , DOPSGVIC, D A , GLA71FR, K M Justice, Dept of 80/03/20 26pp
- 8004100442 Supplemental response to first set of interrogatories & request for production of documents Includes info re utils which purchased caal-fired economy energy from City Public Svc Board of San Antonio HILSON. HR Matthews, Nowlin, MacParlane & Barrett 80/03/20 12pp
- ---8004130444 Supplemental response to first set of interrogatories & requests for production of documents Includes info re San Antonio refusal to transmit or receive interstate electrical power. Exhibits responsive to interrogatories encl HILSQI.W R San Antonio. TX WILSQN.W R Matthews. Nowlin. Macfarlane & Darrett 80/03/20 16pp
- --8004100447 Supplemental response to Brownsville Public Util Board initial interrogatories "first request for production of documents includes info re joint action contemplated by members of TX Interconnected Bys Certificate of Svc encl WILSDN, W R San Antonio, TX WILSDN, W R Matthews, Nowlin, Macfarlane & Barrett 80/03/20 66pp
- 8004100534 Response to DDJ First set of interrogatories includes info re TX electric comperatives & wholesale suppliers Certificate of Svc encl * Teras Electric Service Co 80/03/20 2ipp
- 8004010262 Clarifies NRC updated response to Houston Lighting & Power first set of interrogatories & request for production of documents BLUME.M B Antitrust Division 80/03/21 2pp
- 8004040184 Motion to quash subpoena directed to GN Stagg upon DDJ \$
 NRC joint request Absent evidentiary reliance upon Stagg
 Sys. Inc work:nontestifying outside consultants are not subj
 to discovery process; per established rule
 FRANKLIN:NJ J Houston Lighting \$ Power Co 80/03/21 4pp

- G004040168 Advises that Houston Lighting & Power does not intend to rely on Stage Dys In. studies as part of defense in proceeding NRC * Central & Bouthwest Corp contensions restraight study based on misconception M/Centricate of Svc GREEN.D G Lowerstein Neuron Reis Arelrad & Toll 80/03/21 7pp
- Cu04160111 Responds to NRC ¹ Central ² South West Corp comments reconsolidation Severance arguments based on belief that util util rely on study by 3tag; Sys. Inc. as part of defense Util util not rely on Etag study Certificate of Syc encl
 GREEN D.G. Lovenstein, Neuman Reis Arelrad ² Yoll 80/03/21 App
- E004030360 Response by Public Utils Board of City of Brownsville,TX in opposition to nonconsolidation or proceeding suggested by NRC / Central & South West Corp In event of separation.
 South TX case should be heard first Certificate of Svc encl SPIEGFL.G Telas, State of 80/03/24 9pp
- GG04250049 Response in opposition to Public Utils Board of City of Brownsville.TX GG0317 corrents requesting admittance as party in consolidated proceeding Statement of interest untimely & vague Centificate of Svc encl
 AKEARN.C D Tesas Utilities Generating Co AHEARN.C D Debayoise & Liberman 80/03/25 7pp
- 8004100271 Hotion to compel production of documents by Southwest TX Electric Cooperative re subpoens directed to general manager E McGinnes Requests to strike McGinnes 8001221 deposition if documents are not produced M/draft subpoens & documentation GREEN D G Houston Lighting & Power Co « Baker & Botts » Lowenstein. New-an, Reis Azelrad & Toll 80/03/26 18pp
- --E004100278 Motion to compel production of documents by Midwest Electric Cooperative re subpoena directed to general manager P Metrel Requests to strike Metrel rescheduled deposition if documents are not produced Wisubpoena & Certificate of Svc GREEN D G Houston Lighting & Power Co * Baker & Botts * Lowenstein, Neuman, Reis, Azefrad & Toll 80/03/26 15pp
- 8004080420 Application for issuance of subpoena directed to Gulf States Utils Co re settlement documents Documents not produced in response to 790709 & 800118 subpoenas Urges production to attent allowed by ASLAB

 BLUME, M B Antitrust Division 80/03/27 2gp
- --8004080424 Subpoend directed to Gulf States Utils Co requesting settlement documents, for insp & copying, in Mashington, DC on 800402 Subpoend may be quashed or modified upon request Certificate of Svc enc!

 MILLER, M E Atomic Safety and Licensing Board Panel 80/03/27 6pp
- 8004090126 Order denying Houston Lighting & Power 800321 motion to quash subpoens directed to GW Stagg upon DDJ request Prior rulings re nontestifying outside consultants, do not apply in this proceeding due to relevancy of Stagg studies MOLFERS J Atomic Safety and Licensing Board Panel 80/03/27 3pp
- 8004210384 Forwards Houston Lighting & Power 800327 motions to compel production of documents by NRC expert witnesses RH Hartley & NC Lerner Requests 800331 conference call prior to scheduled depositions
 FRAMKLIN.W J Lowenstein, Newman, Reis, Azelrad & Toll 80/03/27 1p
- ~-8004210392 Motion to compel testimonial questions answered by NRC expert witness RH Hartley Discoverability of questions established on Pages 421-423 of prehearing conference transcript re ASLB 800420 order FRANKLIN, W J Houston Lighting & Power Co FRANKLIN, W J Lowestein, Newman, Reis, Atelrad & Toll * Bater & Botts 80/03/27 App
- --B004210394 Submits preparation study for B00220-21 meeting re intraregional interconnections, transmission lines & other pooling matters HARTLEY,R H Affiliation Unknown B0/01/29 23PP
- --8004210397 Forwards RH Hartley 800211 memo to NRC re 800129 answers in preparation for 800220-21 meeting Requests questions to which answers were stated, per rule established in 790401 prehearing conference Pages 421-423 of transcript enci FRANKLIN.H J Lowenstein.Newman.Reis.Azelrad & Toll 80/03/20 4pp
- --8004210400 Motion to compel electric util industry testimonial antitrust analyses prepared by NRC expert economic witness N Lerner re Midland proceeding Urges production per prior ruings, subj to encl protective order W/Certificate of Byc FRANKLIN,W J Houston Lighting & Power Co FRANKLIN,W J Lowenstein, Newman, Reis, Axelrad & Toll * Baker & Botts B0/03/27 14pp

- 8004090123 Order giving parties one whito provide add1 authority resistence of settlement privilege Mamoranda addressing issue should be received by 800404 / response thereto by 800409 BISHOP.C J Atomic Sarety and Licensing Appeal Panel 80/03/28 2pp
- 8004090456 Protective order, in favor of Houston Lighting & Power, reconfidential corporate study produced in response to NRC initial interrogatories Parties may challenge claimed confidentiality by seeing judicial review per FOIA HOLFE.S J Atomic Bafety and Licensing Board Panel 80/03/31 4p
- 8004100243 Order granting in part NRC motion to compel addl responses by Houston Lighting & Power (HL&P) Accords confidentiality to N Lerner analysis re Midland settlement Grants HL&P motion to compel NRC questions re RH Hartley testimony WOLFE.S J Atomic Safety and Licensing Board Panel 80/03/31 3pp
- 8004100428 Public Utils Board of Brownsville motion for leave to file affidavit as amicus curiae Brownsville is party to proceeding but has not formally appeared in appellate proceeding Certificate of Svc encl SPIEGEL. O Brownsville, TX SPIEGEL. G Spiegel & McDiarmid 80/03/31 Spp
- ---BOO4100430 Affidavit of RE Roundtree, general manager of Brownsville
 Public Utils Board re agroement among TX "IQUs" for
 const of two dc interstate ties of 500 MW & 250 MW
 Brownsville prepared to enter settlement negotiations
 ROUNDTREE, R E Brownsville, TX 80/03/27 3pp
- 80040B0172 Updated response to Houston Lighting & Power second set of interrogatories & TX Utils first set of interrogatories Anticipates RE Corder participation as witness re areas discussed during Corder deposition Centrificate of Svc encl CHANANIA,F D Antitrust Division 80/04/01 5pp
- 8004100240 Order requesting parties in directed certification proceeding, to respond to Utils Board of City of Brownsville, TX 800331 motion, by 800409 BISHOP.C J Atomic Safety and Licensing Appeal Panel BO/04/02 2pp
- 8004180151 Forwards joint motion for extension of time Motion is joined in by all parties to proceeding except DOJ & City Public Utils Board of Brownsville, TX KNOTTS-J B Debevoise & Liberman BO/04/02 is
- --BOD4180167 Joint motion for 30-day extension for all procedural dates
 Motion is based on progress of meaningful settlement
 negotations which could lead to resolution of part or all of
 proceedings Certificate of Svc encl
 CHANANIA:F D Antitrust Division COPELAND. J. Q Houston Lighting
 & Power Co STAHL. D H Central Power & Light Co BO/04/02 Gpp
- 8004140003 Third set of addt answers to NRC 790115 initial interrogatories Simmons & Woodson are expected to testify reinterconnections FRANKLIN.W J Houston Lighting & Power Co * Baker & Botts * Lowenstein.Neuman.Reis.Axelrad & Toll 80/04/03 2pp
- 8004150032 Forwards opposition by Brownsville to joint motion for extension of time & request for prehearing conference, miscellaneous atty & util correspondence, affidavit & Brownsville rate estimates Certificate of Svc encl SPIEGEL, O , POIRIER, M R Spiegel & McDiarmid 80/04/03 19pp
- --B004150050 Opposition to joint motion for extension of time & request for prehearing conference Brownsville has been excluded from negotiations on which request for extension is based Certificate of Svc encl SPIECEL, 0, PDIRIER, MR Brownsville, TX BPIECEL, 0 Bpiegel & McDiarmid B0/04/03 2pp
- B004230066 Forwards Houston Lighting & Power B00403 metion to compet graduction of decoments & JW Wilson testimony by Public Utils Board of City of Brownsville, TX Proposes expedited schedule to permit completion of expert witness discovery GREEN, D G Lowenstein, Newman, Reis, Axelrad & Toll 80/04/03 2pp
- --8004230074 Motion to compel production of documents & UH Wilson expert testimony by Public Utils Board of City of Brownsville, TX If motion not granted requests order precluding Wilson from hearing W/proposed order re schedule & Certificate of Evc BALDNIN. J M Houston Lighting & Power Co * Daker & Botts & Lowenstein, Newman, Reis, Azelrad & Toll 80/04/03 lipp
- B004100126 Memorandum in response to ABLAB B003RB order requesting add1 authority re recognition of settlement privilege Courts & case law do not recognize existence of privilege Certificate of Svc encl BLUME, M B , HDDGDDN, A P Antitrust Division 80/04/04, 6pp

- BO041500B3 Order setting B004[1 conference at NRC Hearing Room, Bethesda.MD Oral argument will address NRC & DOJ joint motion for 30-day extension & Houston Lighting & Power B00403 motion to compel Utils Board of Brownsville WOLFE.S J Atomic Safety and Licensing Board Panel B0/04/04 2p;
- 8004170312 Memorandum of authorities re discoverability of settlement documents Urges reversal of ABLB 800307 ruling due to privilege recognized per case law & foderal rules of evidence Supporting documentation & Certificate of Svc encl 80UxMIGHT, J A , GREEN, D & Houston Lighting & Power Co BOUKNIGHT, J A Jaker & Botts 60/04/04 8ipp
- 8004220128 Memorandum of authorities in support of settlement privilege Documents prepared in connection w/settlement process should be protected from discovery under work product privilege Certificate of Svc encl 8TAHL.D Central & Southwest Services, Inc STAHL.D Isham, Lincoln & Beale 80/04/04 10pp
- 8004240043 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compal production of documents Represents that util consents to extension O'NEILL: A Bouthwest Teras Electric Cooperative O'NEILL: R A Miller, Balis & O'Neil 80/04/04 3pp
- 8004240045 Certifies svc of consent motions for extension to respond to Houston Lighting & Pawer Co motion to compel production of documents from Midwest Electric Cooperative & Bouthwest TX Electric Cooperative, on 800404

 O'NEILL, R A Miller, Dalis & O'Neil 80/04/04 App
- 8004240053 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents util consent to extension O'NEILL.R A Bouthwest Texas Electric Cooperative O'NEILL.R A Miller.Balis & O'Neil 80/04/04 3pp
- 8004240173 Memorandum, per ASLAB 800328 request, stating add1 authorities re directed certification of settlement document issue Treatises & modern trend hold inadmissibility of privileged documents as evidence Certificate of Svc encl KNDTTB, J B , AHEARN, C D Texas Utilities Generating Co KNOTTB, J B Debevoise & Liberman 80/04/04 22pp
- BOO4250104 Advises of arrangement to deliver Houston Lighting & Pawer pleadings moving to compel documents re E McGinnes & P Wetrel subpoenss Consents to 14-day extension for responses Certificate of Byc encl OREEN, D O Lowenstein, Newman, Reis, Azelrad & Toll BO/04/04 Spp
- 8004100552 Motion to issue order compelling Southwest TX Electric Cooperative & general manager E McGinnes to produce, for insp & copying, documents set forth in motion Draft subpoena & Certificate of Svc encl OREEN, D O Houston Lighting & Power Co OREEN, D G Baker & Botts 80/04/07 18pp
- --8004100560 Motion to issue order compelling Midwest Electric Cooperative & general manager P Metrel to produce for insp & copying, documents responsive to subpoens served on Wetrel Draft subpoens & Certificate of Svc encl GREEN.D G Mouston Lighting & Power Co GREEN,D G Baker & Botts 80/04/07 15pp
- 8004230154 Motion to preclude DDJ from filing principal brisf re ASLAB 800328 order DDJ failed to file principal brisf by 800404 DDJ seeks to obtain unfair tactical advantage by untimely filing BDUKNIOHT, J A., OREEN, D G. Houston Lighting & Power Co BDUKNIOHT, J A. Baker & Botts 80/04/07 3pp
- --8004230162 Order directing all parties to furnish ABLAB w/addl authority re-privilege against discovery of documents, Memoranda due on 800404 BIBHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/03/28 4pp
- 8004240041 Motion for ASLB to reconsider extending procedural dates for 30 days. Requests 800408 conference call to rule on extention TX Utils Generating Co is only party to be prejudiced by extending dates CHANANIA.F Antitrust Division BOUKNIGHT, J A Houston Lighting & Power Co. BURCHETTE, W H Texas-Louisiana Electric Cooperative, Inc. 80/04/07 3pp.
- --8004240071 Supplemental argument & representations Addl time required by utils to make progress in settlement discussions Discussions began Sept 1979 Parties are optimistic about possibility of reaching quick settlement BURCHETTE.W H Taxas-Louisiana Electric Cooperative, Inc. KNOTTS, J B. Texas Utilities Generating Co 80/04/07 Spp

- B004210147 Discovery cept for Mar 1980 Deposed JA Bruggeman, JT Wenders, AJ Wood & DA Springs Moved to compel NRC deposition of ND Lerner Responded to DOJ motion to compel supplemental answers to first interrogatories W/Certificate of Svc FRANKLIN, N J Houston Cighting / Power Co FRANKLIN, N J Lowenstein, Neuman, Reis, Azelrad & Tail B0/04/08 6pp
- BOO4150197 Response to Houston Lighting & Power, TX Utils Generating Co & Central & South West Cos 800404 memoranda of authorities re settlement privilege Urgos affirmation of ASLB 800307 order ie production of documents W/Certiricate of Byc CHANANIA, F. D., HONGDON, A. P. Antitrust Division 80/04/09 10pp
- 8004170347 Response to Public Utils Board of City of Brownsville.TX 800331 motion to file RE Roundtree affidavit as amicus curlae Disclusure of documents should not affect potential for sottlement Certificate of Svc encl CHANANIA,F D Antitrust Division 80/04/09 App
- 8004220021 Response to Public Utils Board of City of Brownsville.TX B00331 motion to file Roundtree affidavit Requests to file counter-affidavit,re status of settlement if Roundtree affidavit is accepted by ASLAB Certificate of Boc encl KNOTTS.J B Teras Utilities Generating Co B0/04/09 App
- 8004220152 Response to Houston Lighting & Power 800403 motion to compel production of documents & deposition of Public Utils Board of City of Brownsyllle. TX Does not appose motion if subj to encl protective order Appearance & Certificate of Svc encl ROTH, A J. JACOBS, J C. Florida Cities ROTH, A J. Spiegel & McDiarmid 80/04/09 14pp
- 8004240562 Response in opposition to NRC 800404 memorandum of addl authorities re-existence of settlement documents privilege Congress did not intend to freeze developing law of privilege WCertificate of Svc KNOTTS.J B , AHEARN.C D Teras Utilities Generating Co KNOTTS.J D Debevoise & Liberman 80/04/09 8pp
- 8004170351 Order granting 30-day extension for procedural matters, amending ASLB 791214 order re discovery schedule & directing consolidation of proceedings for pretrial & evidentiary hearings Consent motions for extension to 800404 granted MILLER.M E Atomic Safety and Licensing Board Panel 80/04/10 800
- 8004210141 Order denying Houston Lighting & Power motion seeking to preclude BDJ memorandum of add) authorities filed per ASLAB 800328 order BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/04/10
- 8004230033 Forwards TX Utils Generating Co affidavit of LF Fikar requested during 800409 oral argument KNOTTS, J B Debevoise & Liberman 80/04/10 ip
- ~~8004230041 Affidavit stating that Control & South West Corp. Houston
 Lighting & Power Co & TX Utils Co Sys have reached agreement
 in principle re interconnection disputes Agreement may form
 basis for discussions w/other partics W/Cortificate of Byc
 FIKAR.L F Texas Utilities Generating Co 80/04/10 5pp
- 8004230002 Responds to Public Utils Board of City of Brownsville, TX opposition to joint motion for extension of time Objects to alleged refusal to wheel & submits ML Borchelt affidavit in response to alleged exclusion from discussions STAHL, D M Central & Southwest Corp STAHL, D M Isham, Lincoln & Beale 80/04/11 3pp
- --8004230007 Affidavit responding to Public Utils Board of City of Brownsville-IX allegation that Brownsville has been excluded from discussions re interconnection Ciarlifies statement made at 800327 meeting Certificate of Svc encl
 BORCHELT.M L. Carolina Power & Light Co 80/04/10 iOpp
- BOO4290227 Discovery rept for Mar-Apr 1980 Participated in FJ Meyer.HH Woodson & CM Stagg depositions Filed apposition to petitions for directed certification & reversal of ASLB BOO307 order Juined other parties in moving for procedural extension CHANANIA:F D. BLUME.M B . HDDCDDN.A P Antitrust Division 80/04/25 3pp
- N Antitrust hearing transcripts
- BOO4150298 Transcript of 800407 hearing in Bethesda,MD Pp 1-140 * Commission BO/04/09 140pp

- . Inspection reports of dilletins tearrespondence
- FD340706+3 Re poids to JF 3-lietin 79-28 "Possible Malfunction of NAFOO Model FAI2+ Limit Louis nes at Elevated Temps " Util Libit progress (LFF) to Standard limit switch impart on hold life is at Today Intervalls
 TURNER F A Housen Lip ring & Power to 80/02/01 Ip
- GC04189714 Forwards IE Insp Repts 50-449/80-02 & 50-499/80-02 on 360205 G3 No Honocompliance increding EID E N & Pepson 4 Callas Reactor Construction & Engineering Support Brainin (ROYOP/E) Zap
- --0034180218 IE insp Repcs 55-498/86-02 % 50-499/80-02 on 800205-08 No noncepliance notes Major areas inspected const activities re relieu of procedures observation of work re reactor coulant psping i licensee actions on previous insp findings HALL R E TOTLINSON D P Region 4. Dallas, Reactor Construction & Engineering Support Franch (ROSSMAN, M A Region 4, Dallas, Office of the Director 80,02/20 ipp
- 8104010126 Responds to IE Bulletii 79-28. "Possible Malfunction of NAMCO Mudel EAlby Limit Emitches at Elevated Temps." Updates 800201 response to NRC Fisher Controls initiated corrective action. Westinghouse suithes not affected IURNER E. A. Houston Lighting & Power Co. 80/02/27. Opp
- EDG4140107 Corrects typographical error in util response (ET-ML-AE-417) to NRC Insp Repti 50-488,79-19 \$ 50-489,79-19 TURNER E A Houston Lighting & Power Co 80/02/28 1p
- 8004076057 Ack receipt or 79;113 & 800212 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-499/79-15 & 50-499/79-15 & 50-499/79-15 & SEIDLE W C Region 4, Dalias, Reactor Construction & Engineering Support Branch 80/03/11 lp
- ~-8004070060 Responds to NRC B00124 ltr re violation noted in IE Insp Repts 50-498/79-15 & 50-499/79-15 Corrective actions concrete placement was revibrated satisfactorily Vibrator operators will be retrained every 90 days TURNER.E A Houston Lighting & Power Co 60/02/12 2pp
- 8004303028 Forwards IE Insp Repts 50-498/80-03 & \$0-499/80-03 on 800226-29 No incrempliance noted Efible: Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/03/11 2pp
- --BOD4300035 IE Insp Repts 50-498/80-03 / 50-499/80-03 on 800226-29 No noncompliance noted Major areas inspected site tour, reactor welding & other safety-related welding, records review & procedures for piping fabrication MALL.R & CROSSMAN.W A . GILBERT.L D Region 4, Dallas, Office of the Director 60/03/11 4pp
- 8004300514 Act receipt of 800226 5 79;102 ltrs informing NRC of steps taken to correct violations noted in IE Jusp Repts 50-498/79-13 5 50-499/79-19 SEIDLE, W C Region 4, Dailas, Reactor Construction & Engineering Support Branch 80/03/21 ip
- --8004300523 Responds to ARC 800131 ltr requesting add1 info re violations noted in IE lusp Repts 50-498/79-13 & 50-499/79-13 Corrective actions Pittsburgh-Des Moines QA manual revised adding info re QA coordinator authority TURNER E A Houston Lighting & Power Co 80/02/26 2pp
- 8004240216 Forwards lE Info Nutice 80-14. "Safety Suggestions From Employees." No action required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/02 ip
- 8004220260 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required EEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/03
- 8004220777 Forwards IE Bulletin 79-03A "Longitudinal Wold Defects in ASME 5A-312. Type 304 Stainless Steel Pipe " Action required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/04 p
- 8004220233 Forwards IE Bulletin 80-08, "Eram of Containment Liner Fenetration Welds " Written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/07 19

- S Reportable occurrences, LERs & related correspondence
- 8004010332 Disrusses possible reportable deficiency re backfill matl Extent of nonconforming backfill compaction has not been fully defined Initial testing indicates that nonconformances are focalized incident will be reviewed further TURNER, E. A. Houston Lighting & Power Co. 90/03/21. Spp
- 8004040374 Forwards first interim deficiency rept consisting of schematic drawing of logic for liner plate bulgo repair OPREA:0 W Houston Lighting & Power Co 80/03/24 3pp
- --8004040409 First interim deficiency rept consisting of schematic drawing of lagic for liner plate bulge repair # Hauston Lighting & Power Co 80/03/24 Ip
- 800A040390 Advises that potential deficiency reported on 800224 involving main feedline rupture w/assumed failure in steam generator blowdown sys does not constitute safety concern Considers matter closed OPREA/Q W Houston Lighting & Power Co 60/03/27 3pp
- 8004180384 Final deficiency rept is voids detected under crossover leg embed plates Evaluation shows that condition would not affect safety of plant therefore not reportable per 10CFR50 55(e)
 TURNER.E.A. Houston Lighting & Power Co. 800/04/07 3pp
- 8004180423 Interim deficiency rept re wolds in essential cooling water sys Methods to verify integrity of weld joints are being evaluated Second interim rept will be submitted by 800613 Oversize drawing indicating weld locations encl TURNER, E. A. Houston Lighting & Power Co. 60/04/10 4pp
- 8004180421 Deficiency rept re unqualified mata; operator for trip & throttle valve of turbine driven auxiliary foodwate; pump Defective motor operators will be replaced w/IE qualified pumps off by Terry corp.prior to plant startup TURNER.E A Houston Lighting & Power Co GO/04/11 4pp
- 8004270398 Interim deficiency rept re-broken tie-down studs in Unit 1 polar trane rail Caused by wolding w/low range parameters Encl plan issued for insp & testing of selected studs & associated plates Failures examined by stud supplies TURNER, E.A. Houston Lighting & Power Co. 80/04/16, 10pp
- T Hearing transcripts on non-antitrust matters
- 8004210312 Transcript of D00327 hearing in Bethesda MD Pp 1-127 * Atomic Safety and Licensing Appeal Panel 80/03/2/ 13Dpj
- DOCKET SYN-50-499 SOUTH TEXAS PROJECT. UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREQ-0588, "Interim Btaff Position on Environ Qualification of Bafety-Related flectrical Equipment," providing guidance re methods for compliance ROSS, D. F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits addi guidance to NUREG-0988, "Interim Staff Position on Environ Qualification of Safety-Related Liectrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management BO/02/21 3pp
- 8004040240 Updates hine point action program to OA program identified in util 791828 ltr & 800125 status rept Actions 1-3 & 5-0 have been implemented Proposes to begin platement of safety-related complex concrete on 800303 UPREA.O W Houston Lighting & Power Co 80/02/20 Upp
- 800423005B Requests info re auxiliary feedwater sysper Bulletins & Orders Task Force review of TMI-2 accident info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of OL Wiencl ROSS, D.F. Division of Project Management 80/03/10 53pp
- 8004150128 Forwards request for add1 info concerning review of facility FSAR PARR.O D tight Water Reactors Dranch 3 80/01/10 5pg
- 800A010377 Advises that instrumentation & control diagrams for review of FBAR Chapter 7 have been transmitted to ON Burks of ORNL in response to NRC request BARKER.D G Houston Lighting & Power Co 80/03/28 3pp

- 8004140463 Forwards Lower CO River Authority data re South TX Interconnected Sys interchange for 1979 Data should provide index re types & magnitude of member interchange within South TX Interconnected Sys WEST,W E Texas, State of 80/04/07 14pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 itr has been postponed pending OAD clearance under Federal Repts Act
 ORIMES, B K Emergency Preparedness Task Force 80/03/11 4pp

G Adjudicatory correspondence

- 8004080360 Response in apposition to DUJ & NRC joint motion for mod of ASLB order re-settlement discussions & for order to compel production of documents NRC policy favoring settlement is designed to protect sources involved W/Certificate of Svc * Central & Southwest Corp 80/03/06 lipp
- 8004100274 No objection to intervenor Citizens Concerned About Nuclear Pawer. Inc 800302 motion for extension to answer applicant second set of interrogatories Objects to mischaracterizations made in motion Certificate of Bvc encl BIDDLE, C T Houston Lighting & Pawer Co BIDDLE, C T Baker & Botts 80/03/06 5pp
- B004020136 Response to ABLB 800310 memorandum inviting views re feasibility of early hearing Concurs w/ASLB suggestions & desires to participate in hearing within memorandum conditions Certificate of Svc enci CULP.R H . SCHWARZ, M D Houston Lighting & Power Co CULP.R Lowenstein, Newman, Reis, Azelrad & Toll B0/03/19 App CULP, R H
- B004280069 Response to ASLB 800310 memorandum re hearing to consider issues on alleged const & QA/QC deficiencies Early hearing may foreclose possibility of raising similar issues at later time Certificate of Byc encl
 BINKIN, L Citizens Concerned About Nuclear Power, Inc 80/03/24
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification dOSSIGK, L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004210414 Response to ASLB 800310 memorandum inviting views re feasibility of separating admitted contentions Views will be submitted when IE investigation re assessment of GA/GC effectiveness; is completed W/Certificate of Svc TREBY.S A Hearing Branch i 80/04/10 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004220743 Forwards Amend 10 to FBAR consisting of responses to first round review questions concerning initial startup testing Affidavit encl
 TURNER E A Houston Lighting & Power Co 80/04/21 3pp Houston Lighting & Power Co 80/04/21 3pp
- --8004220769 Amend 10 to FBAR * Houston Lighting & Power Co 80/04/21 125pp

M Antitrust correspondence

- 8004020208 Response to Central & South West Corp et al second request for production of documents Stage Bys Inc workpapers available for insp & copying Documents re transactions already produced Certificate of Svc encl
 COPELAND, J O Houston Lighting & Power Co 80/02/25 6pp
- BOO4110030 Discusses addl request for documents located in Chalker personal files Request is untimely & deficient, failing to specify relevancy to proceeding No obligation to respond to request by BOO277, per Commission Rules of Practice STAHL, D M Isham, Lincoln & Beala BO/02/25 2pp
- 8004020149 Forwards DOJ & NRC 800228 Joint motion for mod of ASLB order re-settlement discussions & for issuance of order to compet production of certain documents & testimony, Proposed order CYPHERT, 8.B Justice, Dept of 80/02/28 4pp
- ---8004020164 Joint motion for mod of ABLB 790416 order re protection of settlement discussions & for issuance of order to compel production of documents & testimony from Houston Lighting & Fower & TX Utils W/Certificate of Svc CYPBERT, B B Justice, Dept of 80/02/28 120pp

- -- 8004020175 Oral deposition of ED Scarth is certification of questions Pp 2-8

 * Atomic Safety and Licensing Board Panel 80/02/22 9pp
- --8004020181 Motion to compel TX Utils Cos to supplement Apr & Jul 1979 responses to first set of interrogatories & requests for production of documents Urges performance of current new obligations by 800306 W/Certificate of five / proposed order CYPHERTS B Justice Dept of 80/02/28 /pp
- --8004020190 Motion to compel Houston Lighting & Power to supplement 790111 > 0427 answers to 791122 interrogatories Urges fulfiliment of current obligations arising from development of new info Certificate of Svc & proposed order encl CYPHERT,S B Justice,Dept of 80/07/28 7pp
- --8004020198 Joint application for issuance of subpoema directed to ED Scarth of TX Utila Gonerating Co & DE Simmons of Houston Lighting & Power Requests extension until 800402 to depose DE Biomons Draft subpoemas > Certificate of Svc encl CYPHERT.S B Justice.Dept of CHANANIA.F Antitrust Division 80/02/28 /pp
- BOO402007B Motion for protective order re disclosure of Diamond Shamrock Corp documents.in response to ASLB 800118 subpoena duces tecum Documents in question are subjust contractual obligations Certificate of Suc & proposed order encl CYPHERT.B B Justice.Dept of 80/02/29 tOpp
- BOO4080174 Notifies of change of address for counsel of South TY Electric Cooperative, Inc. / Hedina Flectric Cooperative, Inc. effective ROO310 JOHN:D F Akin: Oump. Hauer & Feld 80/03/04 1p
- 8004100498 Discovery rept for Feb 1980 Southwest TX Electrical Cooperative Inc & Medina Flectric Cooperative Inc neither initiated nor received any discovery requests Cortificate of Svc encl JOHN,D F Akin, Gump, Hauer & Feld 80/03/04
- 8004110574 Confirms G00229 tolcon re DBJ subpoces of documents from Ouif States Utils Subpoces covers certain areas also covered in Brownsville Public Utils subpoces Gulf States documents will be available to all parties RADER.R M Conner, Moore & Corber G0/03/04 2pp
- BOD4090387 Discovery rept for feb 1980 Participated in A Gerber, M Hobb, E Simmons, V Robertson & GW Beams depositions Attended J Turk, & 8 Phillips depositions Filed motion for addl time to respond to IX Utils interrogatories W/Certificate of 9/c GARNEY, J A Central & Southwest Corp 90/03/03 7pp
- 8004090421 Discovery rept for Feb 1980 No discovery requests received nor initiated Certificate of Svc encl MODD.J C San Antonio. TX MODD.J C Matthows, Mawlin, Macfarland & Barrett 80/03/05 App
- 8004110024 Discovery rept for Feb. 1980 City of Ban Antonio, acting by & through City Public 8vc Board of San Antonio, neither initiated nor received any discovery requests Certificate of Syc encil WODD, J C San Antonio, TX 80/03/05 4pp

- PID ACT HIS POISE IN 1915 STAIN EQUIT NAC 600228 joint notion for mod or ACLP order reservice entities years for order to compel projection of 10 invents Negotiations not be protected for Rule of Evidence 403 McCertaricate of Svc AHEARN (C. Tesas Unities Generating Co. 80/03/06. 30pp
- 60:4070185 Nursee of appearance un behalf of Public Utils Board of City of Drownsville To in consultrated discovery Certificate of Greensville is an Smith Second Greens of GO, U3/Ob Gpp

- E10409G434 Discovery rept by Public Utils Board of City of Brownsville. Ti for Feb 1980 Deposed M Borchelt of Central Power & Light Participates in R Edelstein Jeposition Received documents from Central 1 South West Corp Lertificate or Syc encl POIRIER. II R Texas. State or E0/03/05 App
- EU0410021B Nutifies that DOJ received Houston Lighting & Power Co supplemental answers to Central Power & Light Co first interrogationies u/o apps Requests Attachment A to Houston Power & Light Co second set of add answers to NRC CYPHERT.S B Justice.Dept of 80/03/06 tp
- 8604103433 Nitice of appearance of C Spiegel on behalf of Public Utils Commission of Brownsville.Tr Certificate of Svc encl SPIEUEL G Brownsville.Tr 80 03/06 App
- 8004100535 Discovery rept for Jan / Feb. 1980. City of Austin has neither initialed nor reveived any discovery requests BALDUGH R C Austin, Tx 80/03/07 5pp
- BOO40BJ044 Response by Public Utils Board of City of Brownsyslle, TX, in apposition to Central & Southwest Corp BO0222 metion for profective order, re-second set of interlogatories & production or documents MCSTrificate of Svc & B00207 ltr PDIRIER, NR P Telas. State of B0/03/10 12pp
- B004100514 Forwards notice of taking of deposition of D Springs AMEARN.C D Debevoise & Liberman B0/03/10 ip
- --B004100525 Natice of taking of deposition of D Springs on B00313-14 in Atlanta.GA Deponent will be examined on matters re bulk power supply & transmission h wheeling svcs in TX Certificate of Svc encl AHEARN.C D Texas Utilities Generating Co B0/03/10 5pp
- BCO4110169 Notifies that W Scott Jeposition scheduled for Mar is cancelled Cancellation based on DOJ representation that Scott would be called as expert withness BALDWIN.J M Bater & Botts BO/03/10 5pp
- 8004080018 Updated response to first set of interrogatories & document requests includes info re witnesses, competitive utils, product & geographic market & petitions to intervene Prof qualifications of DA Springs & Certificate of Svc encl BURCHETTE.W H Telas-Louisians Electric Cooperative, Inc. 80/03/11
- 8004090164 Second supplemental response to first set of interrogatories & document requests Includes 1880 re projected loads, capacity & reserves as of 800215
 SLICKER,F K Teras Utilities Co 80/03/11 5pp
- BOO4090175 Supplemental response to third set of interrogatories 3 document requests Supplemental answer to Interrogatory 18 encl W/o encl SLICKER.F K Taxas Utilities Co 80/03/11 3pp
- 8004090180 Supplemental response to first set of interrogatories & document requests includes into re monthly fuel cost adjustments for 1979

 BLICKER,F K Teras Utilities Co 80/03/11 4pp
- 8004100084 Forwards DDJ subpoena requiring DE Simmons, util vice president to testify 800331-0402 Confirms that Simmons will be available for deposition on 800404-05 instead of dates listed in subpoena W/s encl CYPHERT.S B Justice. Dept of 80/03/11 1p
- BOO410022I Fourth supplemental response to first set of interrogatories & document requests includes into re cities & utils which have explored power alternatives offered by TX Utils Co SLICKER, F K Texas Utilities Co BO/03/II 3pp
- BO0403025B Response in opposition to schedule proposed by NRC for reply to motion to quash 800221 subpoens directed to R Frame Merit of NRC argument will be better evaluated after Lenner deposition Suggests 800321 for reply W/Certificate of Svc KNOTTS, J B Texas Utilities Generating Co 80/03/12 5pp

- B004020113 Forwards Houston Lighting * Power B00313 petition for directed certification of ASLB B00307 order re confidential documents of settlement negotiations
 B00kN16H7, J A Lowenstein Newman, Reis, Arelrad & Toll B0/03/13
- --8004020119 Petition for directed certification, interim stay & review of ASLB 800307 order requiring Houston Lighting & Power to produce settlement negotiations documents Urges reversal of ruling M/excepts of 800307 prehearing transcript BOUKNIOHT, J A Houston Lighting & Power Co 80/03/13 19pp
- --B004020122 Grder re NRC 790323 motion to compel further answers to Houston Lighting & Power first interrogatories Directs util to furnish list of privileged documents Orders responses to majority of questions Westerpts of 790001 prehearing MILLER,M E Atomic Safety and Licensing Board Panel 77/04/16
- B0040B002B Forwards DOJ third supplemental response to Houston Lighting & Power Co first set of interrogatories Documents responsive to util 770204 second set of interrogatories encl Documents resecond interrogatories not encl

 CYPHERT, S B Justice, Dept of B0/03/13 1p
- --B004080033 Third supplemental response to first set of interrogatories & document requests Includes in force GT Taylor testimony re four relevant product markets iπ proceedings CYPHERT.S D Justice, Dopt of 80/03/13 30pp
- B0040B0073 Application for issuance of subpoena directed to FG Arey of Webster Engineering Corp. to be deposed & to produce documents re interconnections & interconnected sys Draft subpoena & Certificate of Svc enc S GREEN, D.G. Houston Lighting & Power Co 80/03/13 13pp
- 8004090439 Ack receipt of & accepts 800312 ltr in lieu of interrogatory answer per 800307 prehearing ruling Ltr does not solve Houston Lighting & Power problems are C Stover deposition DDJ 800311 & 12 ltr & Certificate of Svc ent GREEN, D G Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13 10pp
- 8004100545 Response to third set of interrogetories includes info re electric power & energy delivered to various utils during Dec 1979 Certificate of Svc encl * Texas Electric Service Co 80/03/13 16pp
- 8004080370 Discovery rept for Feb 1980 Deposed J Wilson, GC Campbell & V Robertson et al Attended DOJ & NRC depositions, Served 800201 first set of intorrogatories to NRC Received add1 responses to intorrogatories Certificate of Svc ent. FRANKLIN.M J Houston Lighting & Power Co 60/03/14 7pp.
- 8004040078 Comments by Public Utils Board of City of Drownsville, TX, stating no position re-consulidation for trial advised by ASLB during B00307 prehearing If consolidation ordered, right of cross-examination must be proserved W/Certificate of svc POIRIER, M R Toxas, State of 80/03/17 7pp
- 8004080153 Statement in opposition to consolidation of proceedings for hearing purposes, per ASLB 800307 prehearing conference request Issues not identical & evidence in South TX Project may not be related Commanche Peak Certificate of Svc encl. STAHL, D M Central & Southwest Corp 80/03/17 9pp
- 8004080247 Discovery rept for Feb 1980 Participated in Ammons, Neams, Borchelt, Campbell, & Yambrough depositions Inspected DDJ documents Received & opposed Central & Southwest motion for addlitime to reply to interrogatories W/Certificate of Svc AHEARN, C D Texas Utilities Co BD/03/17 5pp
- B004080401 Submits TX Utils Generating Co response to ABLB 800307 request re views on consolidation of proceedings for hearing purposes Urges complete consolidation KNOTTS.J B Debevoise & Liberman 80/03/17 4pp
- 8004080663 Order confirming results of 800307 oral argument NRC & DOJ joint motion, re mod of older concerning protection of settlement discussions, granted in part Parties may not engage in further discovery re documents included in motion CLASER, M.L. Atomic Safoty and Licensing Board Panel 80/03/17
- 8004210437 Notice of appearance in proceeding. Certificate of Svc encl OLAZIER, K.M. Justice, Dept. of. 80/03/17 4pp
- 8004070427 Discovery rept for Jan-Feb 1980 Participated in H Drymy deposition No discovery requests initiated Certificate of BURCHETTE, W H Texas-Louisiana Electric Cooperative, Inc 80/03/19

- 8004010517 Order denying NRC 800311 motion to quash subpoena of R Frame TX Utils Generating Co entitled to test ND Lerner credibility by questioning work & documents prepared by Frame for Lenner review WOLFE.S J Atomic Safety and Licensing Board Panel 80/03/20 2pp
- 8004030347 Response in opposition to TX Utils Generating Co. Houston Lighting & Power Co & South West Corp 800313 petitions for directed certification of order compelling production of documents News article & Certificate of Svc encl CHANANIA: FD Antitrust Division 80/03/20 21pp
- 8004100177 Memorandum in opposition to patitions for directed certification filed by TX Utils Generating Co.Houston Lighting & Power Co & Central & South West Corp et al.re ABL\$ 800307 order Certificate of Syc encl CYPHERT,S B Justice,Dept of 80/03/20 26pp
- 8004100442 Supplemental response to first set of interregatories & request for production of documents Includes info re utils which purchased coal-fired economy energy from City Public Svc Board of San Antonio HILBON.W R San Antonio, TX WILBON.W R Matthews, Nowlin, MacAarlane & Barrett 80/03/20 12pp
- --B004100444 Supplemental response to first set of interrogatories & requests for production of documents Includes info re San Antonio refusal to transmit or receive interstate electrical power Exhibits responsive to interrogatories encl WILSON,W R Ban Antonio, TX WILSON,W R Matthews. Nowlin, Macfarlane & Barrett 80/03/20 16pp
- --8004100447 Supplemental response to Brownsville Public Util Board initial interrogatories & first request for production of documents Includes info re joint action contemplated by members of TX Interconnected Sys Certificate of Syc encl WILBON, W R San Antonio, TX WILBON, W R Matthews, Nowlin, Macfarlane & Barrett 80/03/20 66pp
- 8004100534 Response to DOJ first set of interrogatories includes info re TX electric cooperatives & wholesale suppliers Certificate of Svc encl * Texas Electric Service Co 80/03/21 2ipp
- 8004010262 Clarifies NRC updated response to Houston Lighting & Power first set of interrogatories & request for production of documents
 BLUME: M B Antitrust Division 80/03/21 2pp
- BOD4040184 Motion to quash subpoens directed to GM Stagg upon DOJ & NRC joint request Absent evidentiary reliance upon Btagg work, nontestifying outside consultants are not subj to discovery process, per established rule FRANKLIN, W J Houston Lighting & Power Co BO/03/21 4pp
- --8004040198 Advises that Houston Lighting & Power does not intend to rely on Stagg Bys.Inc studies as part of defense in proceeding NRC & Central & Southwest Corp contentions re Stagg study based on misconception W/Certificate of Svc OREEN.D O Lowenstein.Newman.Reis.Axelrad & Toll 80/03/21 7pp
- 8004160111 Responds to NRC & Central & Southwest Corp comments reconsolidation Severance arguments based on belief that util will rely on study by Stagg Sys. Inc as part of defense Util will not rely on Stagg study Certificate of Syc encl GREEN.D O Lowenstein.Newman.Reis.Axelrad & Toll 80/03/21 6pp
- 8004030360 Response by Public Utils Board of City of Brownsville,TX in opposition to nonconsolidation of proceeding suggested by NRC & Central & South West Corp In event of separation, Bouth TX case should be heard first Certificate of Svc encl SPIEOEL,O Texas, State of 80/03/24 9pp
- 8004250047 Response in opposition to Public Utils Board of City of Brownsville.TX 800317 comments requesting admittance as party in consolidated proceeding Statement of interest untimely & vague Certificate of Svc encl
 AMEARN.C D Texas Utilities Generating Co. 80/03/25 7pp.
- 8004100271 Motion to compel production of documents by Bouthwest TX Electric Cooperative re subpoens directed to general manager E McGinnes Requests to strike McGinnes 8001221 deposition if documents are not produced M/draft subpoens & documentation OREEN,D G Houston Lighting & Power Co 80/03/26 18pp
- --8004100278 Motion to compel production of documents by Midwest Electric Cooperative re subpoens directed to general manager P Hetzel Requests to strike Hetzel rescheduled deposition if documents are not produced W/subpoens & Certificate of Byc OREEN,D Q Houston Lighting & Power Co 80/03/26 18pp

- 8004080420 Application to issuance of subpoena directed to Gulf States
 Utils Co re settlement documents Documents not produced in
 response to 790707 & BOOI18 subpoenas Urges production to
 extent allowed by ASLAB
 BLUMER, M B Antitrost Division BO/03/27 2pp
- ~-8004080424 Subpoeno directed to Gulf States Utils Cos requesting 800402 availability of settlement documents for insp & copying, in Washington.DC Subpoena may be quashed or modified upon request Certificate of Svc enc!

 MILLER,M E Atomic Safety and Licensing Board Panel 80/03/27 600
- 8004090126 Order denying Houston Lighting & Power 800321 motion to quash subposes directed to GN Stagg upon DQJ request Prior rulings.re nontestifying outside consultants.do not apply in this proceeding due to relevancy of Stagg studies WQLFE.8 J Atomic Safoty and Licensing Board Panel 80/03/27 3pp
- 8004210386 Forwards Housion Lighting 9 Power 800327 motions to compel production of documents by NRC expert witnesses RH Hartley & NC Lerner Requests 800331 conference call prior to scheduled depositions
 FRANKLIN.H J Lowenstein, Newman, Reis, Axelrad & Toll 80/03/27 ip
- --8004210392 Motion to compel testimonial questions answered by NRC expert witness RH Hartley Discoverability of questions established on Pages 421-423 of prehearing conference transcript re ASLB 800625 order FRANKLIN, W
- --8004210394 Submits preparation study for 800220-21 meeting re intraregional interconnections transmission lines & other pooling matters HARTLEY,R H Affiliation Unknown 80/01/29 25PP
- --B004210397 Forwards RH Hartley B00211 memo to NRC re 800129 answers in preparation for B00220-21 meeting Requests questions to which answers were stated, per rule established in 770601 prehearing conference Pages 421-423 of transcript encl FRANKLIN, W. J. Lowenstein, Neuman, Reis, Axelrad & Toll B0/03/20
- --8004210400 Motion to compel electric util industry testimonial antitrust analyses prepared by NRC expert economic utiness N Lerner re Midland proceeding Urges production per prior rulings. subj to encl protective arder M/Certificate of Svc FRANKLIN.W J Houston Lighting & Power Ca 80/03/27 14pp
- 8004090123 Order giving parties one wk to provide add1 authority re existence of settlement privilege Memoranda addressing issue should be received by 800404 & response thereto by 800409 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/28 200
- 8004090456 Protective order, in favor of Houston Lighting & Power, re confidential corporate study produced in response to NRC initial interrogatories Parties may challenge claimed confidentiality by seeking judicial review per FOIA WQLFE, 8 J Atomic Safety and Licensing Board Panel 80/03/31 4pp
- 8004100243 Order granting in part NRC motion to compel addit responses by Houston Lighting & Power (HL&P) Accords confidentiality to N Lerner analysis re Midland settlement Grants HL&P motion to compel NRC questions; a RH Hartley testimony WOLFE.S J Atomic Bafety and Licensing Board Panel 80/03/31 3pp
- 8004100428 Public Utils Board of Brownsville motion for leave to file affidavit as amicus curiae Brownsville is party to proceeding but has not formally appeared in appellate proceeding Certificate of Evc enci
 SPIEGEL. 6 Brownsville TX 80/03/31 8pp
- --BOO4100430 Affidavit of Ro Roundtree, general manager of Brownsville Public Utils Board re agreement among TX "IOUs" for const of two dc interstate ties of 500 MN & 250 MN Brownsville prepared to enter settlement negotiations RGUNDTREE.R E Brownsville.TX BO/03/27 3pp
- BOO4080172 Updated response to Houston Lighting & Power second set of interrogatories & TX Utils first set of interrogatories Anticipates RE Corder participation as witness re areas discussed during Corder deposition Certificate of Bvc encl CHANANIA,F D Antitrust Division 80/04/01 5pp
- 8004100240 Order requesting parties in directed certification proceeding to respond to Utils Board of City of Brownsville, TX 800331 motion by 800409 BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/04/02 200

- BOO4180151 Forwards joint motion for extension of time Motion is joined in by all parties to picceeding except DOJ & City Public Utils Board of Brownsville, 1X FROTTS, JB Debevoise & Liberman BO/04/02 lp
- --8004180167 Joint motion for 30-day extension for all procedural dates
 Motion is based on progress of meaningful settlement
 negotations which could lead to resolution of part or all of
 proceedings Certificate of Svc encl
 CHANANIA,FD Antitrust Division 80/04/02 App
- 8004140003 Third set of add1 answers to NRC 790113 initial interrogatailes Simmons & Woodson are expected to testify reinterconnections
 FRANKLIN.17 J Houston Lighting & Power Co. 80/04/03. 2pp
- --800414000B Second supplemental answers to Central Power & Light Co 790223 interrogatories Simmons ! Modson are expected to testify re interconnections Certificate of Svc enci FRANKLIN.W J Houston Lighting & Power Co 80/04/03 6pp
- 8004150032 Forwards opposition by brownsville to jount motion for extension of time & request for preheating conference, miscellaneous atty & util correspondence, affidavit & Brownsville rate estimates Certificate of Suc enci SPIEGEL.6 Spiegel & McDearmid 80/04/03 19pp
- --8004150050 Opposition to joint motion for extension of time & request for prehearing conference Brounsville has been excluded from negotiations on which request for extension is based Certificate of Svc encl
 SPIECEL C Brownsville, TX POIRIER, MR Spiegel & McDiarmid B0/04/03 24pp
- 8004230066 Forwards Houston Lighting & Power 800403 motion to compel production of documents & JW Wilson testimony by Public Utils Board of City of Brownsville, TX Proposes expedited schedule to permit completion of expert uitness discovery QREEN, D G Lowenstein, Neuman, Reis, Axelrad & Toll 80/04/03 2pp
- --8004230074 Motion to compel production of documents & JN Wilson expert testimony by Public Utils Board of City of Brownsville,TX If motion not granted requests order precluding Wilson from hearing W/proposed order re schedule & Certificate of Svc BALDWIN.J M Houston Lighting & Power Co 80/04/03 11pp
- B004100126 Memorandum in response to ASLAB 800328 order requesting add1 authority re recognition of settlement privilege Courts & case law do not recognize existence of privilege Certificate of Svc encl BLUME, M B Antitrust Division 80/04/04 App
- 8004150083 Order setting 800411 conference at NRC Hearing Room, Bethesda.MD Oral argument will address NRC 2 DOJ joint motion for 30-day extension A Houston Lighting & Power 800403 motion to compel Utils Board of Brownsville WOLFE.S J Atomic Safety and Licensing Board Panel 80/04/04 2
- 8004170312 Memorandum of authorities re discoverability of settlement documents Urges reversal of ASLB 800307 ruling due to privilege recognized per case law 2 federal rules of evidence Supporting documentation 3 Certificate of Svc encl BOUKNIGHT. J A Houston Lighting 8 Power Co 60/04/04 81pp
- 8004170340 Response stating no position re joint motion for 30-day extension in proceeding filed by NRC, Central & South West Corp. Houston Lighting & Power, TX Utils Generating Co, City of Austin & other parties Certificate of GVC encl DOPSOVIC.D A Justice, Dept of 80/04/04 5pp
- 8004220128 Memorandum of authorities in support of settlement privilege Documents prepared in connection w/settlement process should be protected from discovery under work product privilege Certificate of Suc encl
 STAML.D Central & Southwest Services, Inc. 80/04/04 10pp
- 8004240043 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents that util consents to extension O'NEILL.R A Southwest Texas Electric Cooperative 80/04/04 3pp
- B004240045 Certifies svc of consent motions for extension to respond to Houston Lighting & Power Co motion to compel production of documents from Midwest Electric Cooperative & Bouthwest TX Electric Cooperative; or B00404 O'NEILL, R A Miller, Balis & O'Neil B0/04/04 4pp
- B004240053 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents util consent to extension G'NEILL, R A Gouthwest Texas Electric Cooperative 80/04/04 3pp

- 8004240173 Memorandum.per ASLAB 800328 request.stating add1 authorities redirected certification of settlement document issue Treatises & modern frend hold inadmissibility of privileged documents as evidence Certificate of Svc encl KNOTTB, J B Teras Utilities Generating Co AMEARN.C D Dubovoise & Liberman 80/04/04 2278
- B004250106 Advises of arrangement to deliver Houston Lighting & Power pleadings moving to compel documents re E McGinnes & P Wetzel subpoens Consents to 14-day extension for responses Certificate of Svc encl GREEN, D Q Lowerstein, Newman, Reis, Axeliad & Toll B0/04/04 Spp
- 8004100552 Motion to issue order compelling Southwest TX Electric Cooperative & general manager E McGinnes to produce, for insp & copying, documents set forth in motion Draft subpoena & Certificate of Svc enc! GREEN,D G Houston Lighting & Power Co 80/04/07 18pp
- --8004100540 Motion to issue order compelling Midwest Electric Cooperative & general manager P Wetzel to produce, for insp & copying documents responsive to subpoena served on Wetzel Draft subpoena & Certificate of Svc encl GREEN, D G Houston Lighting & Power Co 80/04/07 15pp
- 8004230154 Motion to preclude DDJ from filing principal brief re ASLAB 800328 order DDJ failed to file principal brief by 800404 DDJ seeks to obtain unfair tectical advantage by untimely filing BOUKNIGHT, J A Houston Lighting & Power Co GREEN, D O Baker & Botts 80/04/07 3pp
- --B004230162 Order directing all parties to furnish ABLAD w/add1 authority re-privilege against discovery of documents Memoranda are due on 800404 B16HDP/C J Atomic Bafety and Licensing Appeal Panel 80/03/28 App
- 800424006t Motion for ASLB to reconsider extending procedural dates for 30 days Requests 800408 conference call to rule on extention TX Utils Generating Co is only party to be prejudiced by extending dates CHANANIA,F Antitiest Division 80/04/07 3pp
- --8004240071 Supplemental argument & representations Add1 time required by utils to make progress in settlement discussions. Discussions began Sept 1979 Parties are optimistic about possibility of reaching quick settlement.

 BURCHETTE.W H Texas-Louisiana Electric Cooperative, Inc. 80/04/07 5na.
- 8004210147 Discovery rept for Mar 1980 Deposed JA Bruggeman, JT Wenders, AJ Wood & DA Springs Moved to compel NRC deposition of ND Lerner Responded to DDJ motion to compel supplemental answers to first interiogatories W/Certificate of Bvc FRANKLIN,W J Houston Lighting & Power Co 80/04/08 6pp
- BO04150157 Response to Houston Lighting & Power, TX Utils Openerating Co & Central & Bouth West Cos B00404 memoranda of authorities re settlement privilege Urgas affirmation of ABLB B00307 order re production of documents UrCortificate of Boc CHANANIA, F D Antitrust Division B0/04/09 10pp
- BOO417034/ Response to Public Utils Board of City of Brownsville,TX BOO331 motion to file RE Roundtree affidavit as amicus curiae Disclosure of documents should not affect potential for settlement Cortificate of Svc encl CHANANIA,F A Antitrust Division 80/04/09 6pp
- 8004220021 Response to Public Utils Board of City of Brownsville, TX 800331 motion to file Roundtree affidavit Requests to file counter-affidavit re status of settlement. If Roundtree affidavit is accepted by ASLAB Certificate of Byc encl KNOTTS, J B Texas Utilities Generating Co 80/04/09 6pp
- 8004220152 Response to Houston Lighting & Power 800403 motion to compel production of documents & deposition of Public Utils Board of City of Brownsville, TX Does not oppose motion if subj to encl protective order Appearance & Certificate of Svc encl ROTH, A J Florida Cities JACOBS, J C Fivin, Varn, Jacobs, Odom & Kitchen 80/04/07 14pp
- 8004240562 Response in opposition to NRC 800404 memorandum of add1 authorities re existence of settlement documents privilege Congress did not intend to freete developing law of privilege W/Certificate of Svc KNOTTS, J B Texas Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/04/09 8pp

- 80042:0141 Order denying Houston Lighting & Power motion seeking to preclude DDJ memorandum of addl authorities filed per ASLAD 800328 order Atomic Safety and Licensing Appeal Panel 80/04/10
 - BIGHOP,C J
- 8004230033 Forwards TX Utils Generating Co affidavit of LF Fikar requested during 800407 oral argument KNOTS: J B Debevoise & Liberman 80/04/10 ip
- --B004230041 Affidavit stating that Central & South West Corp. Houston Lighting & Power Co & TX Utils Co Sys have reached agreement in principle re interconnection disputes Agreement may form basis for discussions widther parties W/Certificate of Svc FIKAR.L F Texas Utilities Generating Co 80/04/10 Spp
- BO04230002 Responds to Public Utils Board of City of Brownsville.TX opposition to joint motion for extension of time Objects to alleged refusal to wheel & submits ML Borchelt affidavt in response to alleged exclusion from discussions STAHL.D if Central & Southwest Corp B0/04/11 3pp
- --8004230007 Affidavit responding to Public Utils Board of City of Brownsyille,TX allegation that Brownsyille has been excluded from discussions re interconnection Clarifies statement made at 800327 meeting Certificate of Svc encl BORCHELT,M L Carolina Power & Light Co 80/04/10 10pp
- 8004290227 Discovery rept for Mar-Apr 1980 Participated in FJ Meyer, HN Woodson & GM Stagg depositions Filed opposition to patitions for directed certification & reversal of ASLB 800307 order Joined other parties in moving for procedural extension CHANANIA, FD Antitrust Division 80/04/25 3pp

N Antitrust hearing transcripts

- 8004150298 Transcript of 800409 hearing in Bethesda, MD Pp 1-140 * Commission 80/04/09 140pp
- @ Inspection reports, IE Bullatins & correspondence
- 8004070062 Responds to IE Bulletin 79-28. "Possible Maifunction of NAMCO Model EA180 Limit Switches at Elevated Temps " Util will submit progress repts re stem-mounted limit switch impact on facilities at 30-day intervals TURNER, E A Houston Lighting & Power Co 80/02/01 ip
- BO04180214 Forwards 1E Insp Repts 50-498/80-02 & 50-499/80-02 on 800205-08 No mancompliance noted BEIDLE.H C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/02/21 2pp
- --8004180218 IE Insp Repts 50-498/80-02 & 50-499/80-02 on 800205-08 No OUTIONIE IN THE TOTAL TO THE SOCIETY SOCIETY AND THE OUTCOME AND THE TOTAL THE SOCIETY OF THE SO
- 8004010126 Responds to IE Bulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " Updatos 800201 response to NRC Fisher Controls initiated corrective action & Westinghouse switches not affected TURNER, E A Houston Lighting & Power Co 80/02/27 3pp
- 8004140107 Corrects typographical error in util response (ST-HL-AE-417) to NRC Insp Repts 50-498/79-19 & 50-499/79-19 TURNER, E A Houston Lighting & Power Co 90/02/28, ip
- 8004070057 Ack receipt of 791113 & 800212 ltrs informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-498/79-13 & 50-499/79-15 & SCINES, W.C. Region 4, Datlas, Reactor Construction & Enylneering Support Branch. 80/03/11 ip
- --B004070060 Responds to NRC B00124 ltr re violation noted in IE Insp Repts 50-498/79-15 & 50-499/79-15 Corrective actions concrete placement was revibrated satisfactorily Vibrator operators will be retrained every 90 days TURNER, E A Houston Lighting & Power Co 80/02/12 2pp
- 8004300028 Forwards IE Insp Repts 50-498/80-03 & 50-499/80-03 on 800226-29 No noncompliance noted BEIDLE:W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/03/11 2pp

- -8004300035 IE Insp Repts 50-498/80-03 5 50-499/80-03 on 800226-29 No 204300035 IE Insp Repts 50-498/80-03 50-499/80-03 on 800226-29 No noncompliance noted Major aleas inspected sits tour, reactor welding & other safety-ielsted welding, records teview & procedures for piping rabrication HALLIR E. CROSSMAN.W.A., GILBERT.L.D. Region 4. Dallas, Office of the Director 80/03/11 4pp
- 8004300514 Ack receipt of 800226 & 791102 ltrs informing NRC of steps taken to correct violations noted in IE Imap Repts 50-498/79-13 & 50-499/79-13 SEIDLE.W C Region 4, Pallas, Reactor Construction & Engineering Support Branch 80/03/21 19
- --8004300523 Responds to NRC B00131 ltr requesting addl info re violations noted in IE lnsp Repts 50-498/79-13 & 50-499/79-13 Corrective actions Pittsburgh-Des Moines OA manual revised adding info re OA coordinator authority TURNER.E A Houston Lighting & Power Co 80/02/26 2pp
- 8004240216 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees "No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/02
- 8004220260 Forwards IE Circular 80-07. 'Problems W/HPCJ Turbine Oil Sys " No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/03
- 8004220777 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME 5A-312.Type 304 Stainless Steel Pipe " Action required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/04
- 8004220233 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/07
- S Reportable occurrences, LFRs & related correspondence
- 8004010332 Discusses possible reportable deficiency re backfill matl Extent of nonconforming backfill compaction has not been fully defined initial testing indicabos that nonconformances are localized Incident will be reviewed further TURNER, E.A. Houston Lighting & Power Co. 80/03/21 Spp
- 8004040394 Forwards first interim deficiency rept consisting of schematic drawing of logic for liner plate bulge repair OPREA,6 W Houston Lighting & Power Co 80/03/24 3pp
- --8004040409 First interim deficiency rept consisting of schematic drawing of logic for liner plate bulge repair

 * Houston Lighting & Power Co = 80/03/24 1p
- 8004040390 Advises that potential deficiency reported on 800224 involving main feedling rupture w/assumed failure in steam generator blowdows sys does not constitute safety concern Considers matter closed OPREA.G W Houston Lighting & Power Co 80/03/27 3pp
- 8004180384 Final deficiency rept ie voids detected under cros leg embed plates Evaluation shows that condition would not affect safety of plant, therefore not reportable per iOCFRSO 55(e) Hauston Lighting & Power Co 80/04/09 3pp
- 8004180423 Interim deficiency rept re welds in essential cooling water sys Methods to verify integrity of weld joints are being evaluated Socond interim rept will be submitted by 800613 Oversize drawing indicating weld locations end!

 TURNER, E. A. Houston Lighting & Power Co. 80/04/10 4pp
- 8004180421 Deficiency rept re unqualified motor operator for trip & throttle valve of turbine driven auxiliary feedwater pump Defective motor operators unil be replaced w/IF qualified pumps mfg by Terry corp.prior to plant startup TURNER, E A Houston Lighting & Power Co 80/04/11 4pp
- B004290398 Interim deficiency rept re broten tie-down studs in Unit 1 polar crane rail Caused by welding w/low range parameters Encl plan issued for insp & testing of selected studs & associated plates Failures examined by stud supplier TURNER.£ A Houston Lighting & Power Co B0/04/16 16pp
- T Hearing transcripts on non-antitrust matters
- 8004210312 Transcript of 800327 hearing in Bothesda.MD Pp 1-127

 * Atomic Safety and Licensing Appeal Panel 80/03/27 130p

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION. UNIT 2

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NURFG-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance to nethods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp

G Adjudicatory correspondence

8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning % preparedness, distributed as Board notification QUSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp

0 Inspection reports: 1E Bulletins & correspondence

8004040145 Forwards IE Insp Repts 50-500/80-01 & 50-501/80-01 on 800206 No noncompliance noted FIORELLI. C Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/29 2pp

--B004040149 IE Insp Repts 50-500/B0-01 ; 50-501/B0-01 on B00206 No noncompliance noted Major areas inspected condition of site const re limited work authorization HILLIAMS.C C , JONES.C E , GRANT, W B Region 3, Chicago, Office of the Director B0/02/26 4pp

DOCKET 50-501 DAVIS-BESSE NUCLFAR POWER STATION. UNIT 3

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance is methods for compliance ROSS, D F Division of Project Management 80702709 7pp

G Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSBICK. V Office or the Executive Director for Operations B0/04/02 34pp

Q Inspection reports, IE Bulletins & correspondence

8004040145 Forwards IE Insp Repts 50-500/80-01 & 50-501/80-01 on 800204 No noncompliance nated FIORELLI-Q Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/02/29 2pp

--8004040149 IE Insp Repts 50-500/60-01 & 30-501/80-01 on B00206 No noncompliance noted Major areas inspected condition of site const re limited work authorization WILLIAMS, C C . JONES. C E . GRANT, W B Region 3, Chicago

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDSS, D F Division of Project Management 80/02/05 7pp
- 8004010340 Forwards mod to NPDES Permit WA-002496-1 Mod does not involve adverse environ impact of safety issues & does not require mod to CP RENDERCER.D L. Washington Public Power Supply System 80/03/21
- --8004010345 Mod to NPDES Permit WA-002496-1, issued to WA Public Power Supply Sys LEWIS.N D Environmental Protection Agency 76/10/27 11pp
- 8004280619 Advises that /91220 request for approval of alternative test method to verify max moisture in low hydrogen electrode coating is accepted Requests that notarized version of request test on the specific sites for use RUBENSTEIN, L & Light Water Reactors Branch 4 80/04/04 5pp

8004160285 Advises of fundamental misstatement in B00402 minutes of B00104 meeting w/util re GA program unionization Requests correction to reflect that fact had no influence on Local 598 election REYMOLDS: N S Debouise & Liberman B0/04/10 ip

8004150443 Requests concurrence in use of ABME. Section III. Code Case N-242 re maths contification to resolve apparent conflicts in ABME interpretations of certification of code maths RENDERGER.D L Washington Public Power Supply System 80/04/11

8004210285 Responds to B00221 ltm re schedule for completing review of qualification of safety-rolated electrical equipment Schedule for completion of review will be provided after final issuance of NURES-0588 RENBERGER.D L. Washington Public Power Supply System 80/04/11 ip

F Security, medical, emergency & fire protection plans

8004080077 Advises that submittal date for evacuation time estimates, requested by NIC 791226 ltr. has been postponed pending CAO clearance under Federal Repts Act
QRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp

Q Inspection reports, IE Bulletins & correspondence

8004150220 Forwards IE Info Natico 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELKEN.R H Region 5, Ban Francisco, Office of the Director 80/03/31 ip

8004100109 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director, 80/04/01 ip

8004110119 Forwards IF Info Notice 80-13, "OE Type 8BM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN.R H Region 5, San Francisco, Office of the Director. 80/04/02 ip

8004220052 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees" No action required ENGELKEN,R H Region S. Ban Francisco, Office of the Director 80/04/02 ip

B004180137 Forwards IE Circular 80-07, "Problems H/HPCI Turbine Oil Bys " No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/04/03 1s

8004230370 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME 8A-312.Type 304 Stainless Steel Pipe " Action required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/04/04 ip

- 8004220201 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds " Hritten response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/07 1p
- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Bafety-Related Electrical Equipment," providing guidance re methods for compliance ROSB.D F Division of Project Management
- 8004010340 Forwards mod to NPDES Permit WA-002496-1 Mod does not involve adverse environ impact or safety issues & does not require mod to GP RENBEROER, D L Washington Public Power Supply System 80/03/21
- --8004010345 Mod to NPDES Permit WA-002496-1, issued to WA Public Power Supply Bys LEWIS.N D Environmental Protection Agency 76/10/27 11pp
- 8004280619 Advises that 791220 request for approval of alternative test method to verify max moisture in low hydrogen electrode coating is accepted Requests that notarized version of request be sent in addition to specific sites for use RUBENSTEIN.L B Light Water Reactors Branch A 80/04/04 5pp
- 8004160285 Advises of fundamental misstatement in 800402 minutes of 800104 menting w/util re GA program unionization Requests correction to reflect that util had no influence on Local 578 election REYMOLOS N 8 Debevoise & Liberman 80/04/10 ip
- 8004150443 Requests concurrence in use of ASME. Section III. Code Case N-242 re matis certification, to resolve apparent conflicts in ASME interpretations of certification of code matis RENBERGER. D.L. Washington Public Power Supply System 80/04/11
- 8004210285 Responds to 800221 itr re-schedule for completing review of qualification of safety-related electrical equipment Behedule for completion of review will be provided after final issuance of NVREO-0588 RENBEROER.D.L Washington Public Power Supply System 80/04/11
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, raquested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp.
- 9 Inspection reports. IE Bulletins & correspondence
- 8004150220 Forwards IE Info Notice 80-12, "Instrument Feilure Causes Opening of FORV & Block Valve " No specific action or response necessary ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/31 ip
- 8004100109 Forwards IE Circular B0-05, "Emergency Diesel Generator Lubricating Gii Addition & Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/01 1p
- 8004110119 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required ENGELKEN, R.H. Region 5, San Francisco, Office of the Director 80/04/02 in
- 8004220052 forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required ENGELKEN, R H Region 5, San Francisco. Office of the Director 80/04/02 ip
- 8004180139 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gii 8ys " No written response required ENOELKEN,R H Region 5, San Francisco. Office of the Director 80/04/03 ip

- BOO4220201 Forwards IE Bulletin BO-OB, "Exam of Containment Liner Penetration Welds" Written response required ENGELKEN,R H Region 5. San Francisco. Office of the Director BO/O4/O7 ip
- 8004230370 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/04/04 | Ip
- DOCKET 50-510 BLUE HILLS STATION UNIT 1

 G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OCSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET 50-511 BLUE HILLS STATION, UNIT 2
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification QCSEICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET 50-513 WPPSS NUCLEAR PROJECT. UNIT 4

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSB, D.F. Division of Project Management 80/02/05 7pp
- 8004210408 Requests add1 info re changes & studies proposed in App F of 791203 reply to NRC 791025 100FR50 54 requests concerning design adequacy of BNN NSSS utilizing once-through steam generators
 PARR: 0 D Light Water Reactors Branch 3 80/03/25 App
- 8004280619 Advises that 791920 request for approval of alternative test method to verify may moisture in low hydrogen electrode coating is accepted Requests that notarized version of request be sent in addition to specific sites for use RUBENSTCIN.L B Light Water Reactors Branch 4 80/04/04 5pp
- BOO4160285 Advises of fundamental misstatement in GOO402 minutes of BOO104 meeting w/util no OA program unionization Requests correction to reflect that util had no influence on Local 398 election REYNOLDS. N B Debevoise & Liberman 80/04/10 ip
- 8004210285 Responds to 800221 ltr re-schedule for completing review of qualification of safety-related electrical equipment

- --8004250074 If In-p Rept. 50-160,60-02 % 50-513/80-02 on 800211-15 No moncompliance noted Major areas inspected safety-related components sarety related piping installation, welder training % weld filler matl control DODDS PT Pegion 5 for Francisco, Reactor Construction & Engineering Support Unanch UndCHER W J. MAIST, D.P. Region 5, Ban Francisco Orrice of the Director 80/03/18 8pp
- 8004150220 Forwards IT Irro Notice 80-12. 'Instrument Failure Causes Opening or FORY' Block Valve fo specific action or response nerossary EUGELMEN, R. H. Region 5. Dan Francisco. Office of the Director 80/03/31 16
- 80041400109 Forwards IF Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENGELMENAR H Region 5, San Francisco, Office of the Director 80/04/01 1p
- 8004110119 Forwards IE Into Notice 80-13, 'GE Type SBM Control Switches Defective CAM Followers ' No specific action or response required EMGELMEILR H Region 5, San Francisco, Office of the Director 80/04/02 in
- 80/04220052 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required ENGELKEN, RH Region 5. San Francisco, Office of the Director 80/04/02 1p
- BOO4180139 Forwards IE Circular BO-07, 'Problems W/HPCI Turbine Oil Sys " No written response required ENGELKENIR H Region 5. San Francisco, Office of the Director BO/04/03 1p
- 8004220201 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Hritten response required ENGELMENTRY H Region 5. San Francisco, Office of the Director 80/04/07 1p
- 8004230370 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required ENGELKER,R H Region 5. San Francisco. Office of the Director 80/04/04 ip
- 8004230239 Ack receipt or 800318 ltr informing NRC of steps taten to correct violations noted in IE lnsp Repts 50-460/79-13 & 50-513/79-13 PERCERIO S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 83/04/08 ip
- ~-8004230248 Responds to NRC 800228 ltr re violations noted in IE Insp Repts 50-460/79-13 % 50-513/79-13 Corrective actions identified % described nature & extent of referenced administrative & security controls RENSERGER, D. L. Washington Public Power Supply System 80/03/18 2pp
- --8004230253 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/79-13 & 50-513/79-13 Requests info re nature & extent of referenced administrative & security controls
 SPENCER.C S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/02/28 ip
 - 'I Responds to NRC 800116 itr re violations noted in IE Insp D-460/79-13 t 50-513/79-13 Corrective actions ted accessive weld weave identified as infraction i provisions to control access to Level C storage IR.D L Washington Public Power Supply System 80/02/19
 - E Insp Repts 50-460/79-13 & 50-513/79-13 on of violation & deviation n 5. San Francisco, Fuel Facility & Materials D1/16 2pg
- # Region 5. San Francisco, Office of the Director 80/01/15 ip
- ---8004230287 Notice of deviation from insp on 791201-31
 Region 5, San Francisco, Office of the Director BO/01/15 ip
- --8004230290 IE insp Repts 50-440/79-13 \$ 50-513/79-13 on 791201-31
 Noncompliance noted excessive weld weave & absence of specific access controls for Level C Items
 DUDDS.R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch TOTH.A D Region 5. San Francisco, Office of the Director BO/01/15 7pp

- DOCKET 50 514 PEBBLC SPRINGS NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents 2 carrespondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment, 'providing guidance re methods for compliance ROSS,D F Division of Project Management 80/02/05 7pp
- 8004210405 Summary of 800328 meeting w/near-term CP applicants in Bethesda,MD re-evaluation of progress made to date establishing proposed requirements stemming from TM1-2 accident
 THOMAS, C. G. Standardization Branch 80/04/03 63pp
- 8004300074 Summary of 800319 meeting w/Near-Term CP Applicants Group in Bethesda. MD is matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAS, C D Standardization Branch 80/04/03 12pp
- B004240557 Summary of B00402 meeting u/Neai-Term CP Applicants Group in Bethesda.MD re progress made establishing proposed requirement stemming from TMI-2 accident Proposed requirement category assignments encl THCMAS.C D Light Hater Reactors Braπch 1 80/04/0/ 4/pp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8004280112 Forwards Final Suppl 1 to FES, NUREG-79/02% & related FR notice BALLARD, R L Environmental Projects Branch 1 80/04/10 2pp
- --8004280114 Notice of availability of final Suppl 1 to FCG, NURFQ-75/025 BALLARD, R L Environmental Projects Branch 1 60/04/09 2pp
- --8004280118 Final Suppl i to FES # Office of Nuclear Reactor Regulation NUREO-/5/025 100/04/30 80pp Available at NTIS
- 8004290500 Informs that NRC project notice was assigned file title & number "Final Suppl to Final Pebble Springs [16, " & Number 8004 4 760 Thirty-day review began 800422 # Gregon, State of 80/04/22 ip
- F Security, modical, emergency & fire protection plans
- BOO4180359 Responds to NRC 791226 request for info re evacuation time estimates around future plants Forwards summary rept, "Evacuation Time Estimates For Oilliam & Morrow Counties, CR & Kickitat County-MA"

 LINDBALD, N J Portland General Electric Co BO/04/04 ip
- --8004180364 "Evacuation limo Estimatos for Oilliam & Morrow Counties, OR & Klickitat County.WA" * Portland General Electric Co 80/03/31 21pp
- 8004180364 "Evacuation Time Estimates for Qilliam & Morrow Counties, OR & Klickitat County.UA " s Portland General Electric Co 80/03/31 21pp
- G Adjudicatory correspondence
- 8004080439 Updates 800310 ltr submitted to ABtII Final suppl to FLB real alternative sites will be issued 15 days after 8003331 BORDENICK, B M Hearing Branch 4 80703724 1p
- 8004250375 Forwards State of OR Energy Facility Biting Council 800014 order suspending further proceedings in site certificate application until 810701 Certificate of 8vc encl 8AMDVIK.R M Justice.Dept of 80/03/26 Spp
- 00040B0597 Order re util 800215 announcement that facility completion will be delayed until 1970s Grants parties 10 days, from receipt of order, to respond to NRC 000310 suggestions to proceed w/site suitability matters
 BOMERS, E.S. Atomic Safety and Licensing Board Panel 80/03/27
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSSICK,L V Office of the Executive Director for Operations 80/04/02 34pp

- 8004150072 Order ie OR Energy Facility Siting Council 800314 order suspending proceeding until 810701 Directs parties to inform ASLB re effects of suspension on site suitability NGWERG, E. G. Atomic Bafety and Licensing Board Panel 80/04/03 ip
- 8004190243 Response to ASLB 800403 order re State of DR Energy Facility Siting Council 800314 order suspending proceeding until 810701 Council action does not affect NRC position re continuance on site suitability Certificate of Svc encl BURDENICK, B M Heating Branch 4 80/04/11 4pp
- DOCKET 50-815 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- EB094040031 Advises of issuance of NUREG-0988, "Interim Btaff Position on Environ Qualification of Safety-Related Ejectrical Edvipment," providing guidance re-methods for compliance ROSS, D. F. Division of Project Hanagement E0/02/05 7pp
- BOO4210405 Summary of BOO328 meeting winear-term CP applicants in Bethesda, MD no evaluation of progress made to date astablishing proposed requirements stemming from TMI-2 accident TMMAS, C D. Standardization Branch 80/04/03 ASpp
- BDO4300074 Summary of BD0319 meeting w/Near-Term CP Applicants Group in Betheeda, MD re matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAS, C D Standardization Branch BO/04/03 12pp
- 8004240597 Bummary of G00402 meeting w/Near-Tarm CP Applicants Group in Bethesda, MD re-progress made astablishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments end TMI-2 Accident G0/04/07 47pp
- D NRC Draft// inal Environmental Statements, supple & correspondence
- OCCAPRO112 Forwards Final Suppl 1 to FEG.NUREQ-75/025 & related FR notice
 DALAMB.R L Environmental Projects Branch 1 00/04/10 2pp
- -- HOO4220114 Notice of availability of Final Buppl 1 to FER.NURGO-75/020 DALLARD.R L Environmental Projects Branch 1 80/04/09 2pp
- (3004270500 Informs that NIC project natice was assigned file title & number "Final Cuppl to Final Pebbie Springs FIB." & Number 5004 4 760 Thirty-day review began 600422 e Oregon, State of 60704722 ip
- F Security, medical, emergency & fire protection plane
- GOGA180359 Responds to NRC 791226 request for info re evacuation time estimates around future plants Forwards summary rept.
 "Fivacuation Time Estimates For Gilliam & Morrow Counties, OR & Klickitat County, MA"
 LINDBALD, W.J. Portland General Electric Co. 60/04/04 ip
- B004180364 "Evacuation Time Estimates for Gilliam & Horrow Counties. UR & Klickitat County, WA" * Portland Opneral Flectric Co. 80/03/31 2ipp
- O Adjudicatory correspondence
- 80004080439 Updates 800010 ltr submitted to ABLD Final suppl to FES re alternative sites will be issued 15 days after 800331 BORDENICK: D.M. Hearing Branch 4 80/03/24 ip
- E004250375 Forwards State of CR Energy Facility Siting Council 800314 order suspending further proceedings in site certificate application until 810701 Certificate of Svc encl SANDVIK.R H Justice.Dept of 80/03/26 bp
- GOO4080597 Drder re util 800215 announcement that facility completion will be delayed until 1990s Crants parties to days from receipt of order to respond to NRC 800310 suggestions to proceed w/site suitability matters

 BOMERBLE 8 Atomic Sefety and Licensing Board Panel 80/03/27
 2pp

- 8004030626 Memorandum of Understanding between NRC & FEMA re-prompt improvement in radiological emergency planning between the restributed as Board notification GOSSICK, L. V. Office of the Executive Director for Operations BO/04/02 44pp
- 8004150092 Order to DR Energy Facility Siting Council 800314 order susponding proceeding until 810701 Directs parties to inform ASEB re-effects of suspension on, site suitability BOWERB, E. 6. Atomic Safety and Licensing Board Panel 80/04/0J 1p
- GOO4150243 Response to ASLR HOU403 order se State of UR Energy Facility Siting Council HOU314 order suspending proceeding until BLO701 Council action does not arrect NRC position re continuance on site sustability Certificate of Svc ancl BURDENICK, U.M. Hearing Branch 4 GO/O4/11 App
- NOCKET 6TN-50-516 JANESPORT NUCLEAR STATION, UNIT I

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURLG-OUFIB, "Interim Staff Position on Environ Qualification of Sarety Rolated Electrical Equipment," providing guidance re methods for compliance RDSS, D.F. Olvision of Project Management 80/02/05 7pp
- F Bucusity, medical, emergency & fire protection plans
- 90040000// Advises that submittal date for evacuation time estimates, requested by NRC /71776 ltr.ha. Even postponed pending GAG clearance under Feieral Repts Act GRIMES, B.K. Emergetty Proparedness Task Force GD/03/11 4pp
- Q Adjudicatory correspondence
- 8004030026 Nemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GCSBICKL V Office of the Executive Director for Operations GO/04/02 14pp
- 8004150312 Tenth status cept por ASLAB /70607 indefinite extension for NRC to respond to Buffalk County motion to file supplemental brief lask action plan underway Na written decision on coal plant issued by NY Board on Flectric Coneration Ditring BORDENICK.B M Healing Branch 4 80/04/11 "pp
- Q Inspection reports, If Bulletins & correspondence
- 80041502/4 Forwards IE Info Notice BO 12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIFF, B H Region 1. Philadelphia, Office of the Director 80/03/31 ip
- 8004090063 Forwards It Circular 80-05, "Emergency Diseal Generator Lubricating 011 Addition & Onsite Supply " No written response required GRICR B H Region 1, Philadelphia, Office of the Director 80/04/01 1p
- BOO4110140 Forwards II Info Natice BO-13, "GE Type BBM Control Buildnes Defective CAM Followers" No written response required ORIER, B H Region L. Philadelphia, Office of the Director BO/04/02 ip
- 8004240313 Forwards IF Info Notice 80-14, "Safety Buggestions from Employees" No action required GRIER, B H Region 1. Philadelphia, Office of the Director 80/04/02 1p
- 8004180179 Forwards IE Circular GO-O7. 'Problems W/HPCI Turbine Dil Bys " No written response required CRIER.B 14 Region 1. Philadelphia, Office of the Director BD/04/03 1p

- 8204230471 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ASME 5A-312 Type 304 Stainless Steel Pipe " Action required CRIER.B H Region 1, Philadelphia, Office of the Director 80704701 | Ip
- 3004180161 Forwards IF Nulletin 80-08, 'Eram of Containment Liner Penetration Welds "Written response required GRIER.B H Pegion 1, Thiladelphia, Office of the Director 80/04/07 is
- T Hearing transcripts on non-antitrust matters
- 8004100450 Testimony before NY State Board on Electric Generation Siting & Environ re proposed Jamesport facilities KLEIN, J V Suffolk County, NY 79/07/10 App
- --8004100160 Testimony before NY State Board on Electric Generation Siting & Environ re-proposed Jamesport facilities Prof qualitications encl GEISELMAN, J. N. Suffolk County, NY 79/06/29 6pp
- --G004100472 Testimony before NY State Board on Electric Generation Siting b Environ re proposed Jamesport facilities Related diagrams.ref & prof qualifications enci GIARDINA.P A Suffolk County, NY 79/06/29 25pp
- DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-058B. "Interim Staff Position on Environ Gualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GDSSICKL V Office of the Executive Director for Operations
- 8004150312 Tenth status rept per ASLAB 790607 indefinite extension for NRC to respond to Suffolk County motion to file supplemental brief Task action plan underway No written decision on coal plant issued by IV Board on Electric Generation Siting BORDENICK. 8 M Hearing Branch 4 80/04/11 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004220036 Responds to IF Bulletin 80-03 Charcoal adsorber cells have not been purchased PLASKON.R E Long Island Lighting Co 80/03/19 ip
- 8004150274 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response mecessary GRIER B H Region 1, Philadelphia, Office of the Director 80/03/31 1p
- 8004090063 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 | 1p
- 8004110140 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director [p
- BOOA240313 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required GRIER, BH Region 1, Philadelphia, Office of the Director 10

- 8004180179 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Gil Sys " No written response required GRIER.B H Region I. Philadelphia. Office of the Director 80/04/03 Ip
- 8004230471 Forwards 1E Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required GRIER, B H. Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 8004180161 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required GRIER.B H. Region I. Philadelphia. Office of the Director 80704/07 ip
- T Hearing transcripts on non-antitrust matters
- 8004100450 Testimony before NY State Board on Electric Generation Siting & Environ re proposed Jamesport facilities KLEIN, J V Suffelk County, NY 79/07/10 Spp
- --8004100460 Testimony before NY State Board on Electric Generation Siting : Environ re proposed Jamasport facilities Prof qualifications encl GEISELMAN.J N Suffolk County, NY 79/06/29 App
- --8004100472 Testimony before NY State Board on Clectric Generation Siting & Environ re proposed Jamesport facilities Related diagrams: ref & prof qualifications encl GIARDINA,P A Suffol County, NY 79/06/27 25pp
- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0598, "Interim Staff Position on Environ Qualification of Safety-Related Clectrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC /91226 ltr.has been postponed punding QAU clearance under Federal Repts Act ORIMES, D K Emergency Preparedness Task Force 80/03/11 4pp
- O Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GDBBICKL V Office of the Executive Director for Operations
- Q Inspection reports: IE Bulletins & correspondence
- 8004090352 Forwards IF Bulletin 80-03, "Loss of Charcoal from fitd Type II, Two-Inch, Tray Adsorber Celis" Action required D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/02/06 200
- 8004090384 Forwards IE Insp Repts 50-518/80-03,50-519/80-03, 50-320/80-03 % 50-521/80-03 on 800103-18 % 25 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 200
- --8004090400 IE Insp Repts 30-518/80 03, 30-519/80-03, 30-520/80-03 & 30-521/80-03 on 800103-18 & 25 No noncompliance noted Major areas inspected GA program review structural concrete & licenses const organization changes
 EMAN.W B Repion 2. Atlanta, Office of the Director CANTRELL, C S Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/02/19 3pp
- 8004090025 Canfirms 800310 teicon arranging 800320 meeting between NRC & util in Atlanta, OA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by OA program O'REILLY, J.P. Region 2, Atlanta, Office of the Director 00/03/12

- 800421017B Forwards response to IE Builetin 80-03, "Loss of Charcoal from 8td Type 11.Two-Inch.Tray Adsorber Colls" Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS,L M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement paskets have been ordered MILLG.L M Tennessee Valley Authority 80/03/28 2pp
- 3004150527 Forwards IE Info Notice 80-12, "Instrument Failure Gauses Opening of PORV & Block Valve " No specific action or response necessary U'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 1004080636 Forwards IE Circular 80-05, "Emorgency Diesel Generator Lubricating Dil Addition & Unsite Supply " No whitten response required G'RELLY, J P Region 2, Atlanta, Office of the Director 80/04/01
- 300415009/ Forwards IE Info Notice 80-13. "GE Type BBM Control Switches Defective CAM Followers " No specific action or response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 00/04/02
- 1004240274 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees," No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 3pp
- 1004180275 Forwards If Circular 80 0/, "Problems W/HPCI Turbine 0:1 Bys " No written response required O'MEILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/03 2pp
- 004110017 Forwards IE Bulletin 60-07, 'DWR Jet Pump Assembly Failure " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Disector B0/04/04 200
- 004230142 Forwards It. Bulletin 79-03A "Longitudinal Weld Defects in ABMC BA-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04 in
- 004180440 Forwards IE Dulletin 80-00, "fram of Containment Liner Penetration Helds " Hritten response required O'RELLLY, J.P. Region 2, Atlanta, Office of the Director B0/04/07 366
- 004290379 Requests approval of AGME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp. HILLS, L. M. Tennesses Valley Authority 80/04/23 3pp
- Reportable occurrences, LFRs & related correspondence
- 304160216 Forwards revised corrective actions to 800215 final deficiency rept HILLB: I M Tennessee Valley Authority 80/03/31 ip
- *B00416021B Revised corrective actions to 800213 final deficiency rept Buttered edges on reactor pressure vessel pedestal examined & repaired Vendor film quality sufficient to produce repair overlays * Tennessee Valley Authority 80/03/31 ip
- 204150414 Forwards suppl to final deficiency rept re unacceptable GA documentation for Olajer steel matl MILLB,L M lennessee Valley Authority 80/04/03 ip
- 8004150417 Suppl to final deficiency rept re unacceptable GA documentation for Glazer steel math All questionable math has been tested Blightly excessive sulfur content is caused by chemical differences & not QA sys defects

 # Tennessee Valley Authority 80/04/03 ip
- 04290066 Part 21 rept to insp of generator control panels for emergency dissel generators Results determined defects could degrade emergency dissel unit to unsafe performance Corrective action includes in-depth insps & training FALTER.M.H PHR Bystem Div PA/PI 80/04/07 4pp

- 8004220724 Forwards interim deficiency rept re incorrect root face on skewed cadweld sleeves MILLS.L.M. Tonnessee Valley Authority 80/04/14 in
- ---8004220764 Interim deficiency topt re incorrect root face on skewed cadweld sleeves Root face on stowed cadweld sleeve 18 varies from 3/32 to 1/2 inch Design based on assumed 1/16inch toot face Sleeves will undergo destructive pull tests * Tennessoo Valley Authority 83/04/14 2pp
- 8004280503 Forwards +irst interim deficiency rept re cracks in reactor pressure vessel shield wall MILLS.C M Tennessee Valley Authority 80/04/14 1p
- --8004280505 First interim deficiency rept re cracks in reactor prossure vessel shield wall Three base metal cracks were found in shield wall inner shell plates Cause to be determined pending results of Singleton analysis
 MILLS:L M Tennessee Valley Authority 80/04/14 ip
- 8004300390 Forwards flist intorim ropt of deficiency ro wiring in HPCS metal clad switchgear MILLS.L.M Tonnessoc Valley Authority 80/04/24 ip
- --8004300377 First interim deficiency ropt ro wiring in HPCS motal clad switchgear QE has been notified of wiring diagram & labeling discrepancies missing wires & billing problems Phipps Bend mgt investigating discrepancies

 * Tennossee Valley Authority 80/04/24 lp
- DOCKET STN-90-919 HARTSVILLE NUCLEAR FLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,() F Division of Project Management 80/02/05 7pp
- f Becurity, modical, emergency & fire protection plans
- 00040800// Advises that submittal date for avacuation time estimates/ requested by NRC /91226 ltr.has been postposed pending QAO clearance under Federal Repts Act QRIMIG.B K Emergency Proparedness Task Force BO/03/it 4pp
- Q Inspection reports, If Bulletins & carrespondence
- 8004090792 Forwards IP Bulletin 80-03 "loss of Charcoal from 8td Type 11.Two-Inch.Tray Adsorber Colls " Action required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/06 20a
- 8004070384 Forwards IE Insp Repts 50 518/80 03,50-519/80-03, 50-520/80-03 & 50-521/80-03 on 800103-18 & 25 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/02/20 2pp
- --H004070400 IE Insp Repts 50-518/80-03.50 519/80-03.50-520/80-03 & 50 521/80 03 un B0010J 18 & 25 No nancompliance noted Major areas inspected QA program review, structural concrete & licensee Const organization changes
 GHAN.W 8 Region 2. Atlanta. Office of the Director CANTRELL / 8 Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/17 5pp
- BO04090025 Confirms B00310 teleon arranging B00320 meeting between NRC to vtil in Atlanta. OA to discuss accuracy of written repts provided to If NRC will provide overall evaluation of util handling of deficiences identified by QA program D'REILLY. J P Region P. Atlanta. Office of the Director 80/03/12 2pp
- 8004210178 Forwards response to IE Bulletin 80-03, "loss of Charcoal from Btd Type II.Two-Inch.Tray Adapter Cells " Enct lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L.M Tennessee Valley Authority 80/03/21 4pp
- 8004i80i06 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model CAIBO limit suitches At facilities where applicable limit switches are identified, replacement gastets have been prodered MILLG, LM Tennessee Valley Authority 80/03/28 2pp

- 800415057 Forwards IE Inro Notice 80-12. "Instrument Failure Causes Opening or PORV & Block Value " No specific action or response necessary O'REILLY, J.P. Region = Atlanta, Office of the Director 80/03/31
- 8004080636 Forwards If Circulat 80-05, "Emergency Diesel Generator Lubricating Ui) Addition? Onside Supply "No unitten response required O'REILLI, J.P. Region P. Atlanta, Office or the Director 80/04/01
- GOO415009/ Forwards IE Info Notice 80-13, "GE Type SBM Contro) Switches
 Defective CAM Followers No spacific action or response
 required
 O'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/04/02
- 8004240274 Forwards IE Info Notice 80-14, 'Safety Suggestions From Employees " No action required D'REILLI, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180275 Forwards IE Circular 80-07, 'Problems H/HPCI Turbine Oil Sys " No written response required O'REILLI, J P Region 2, Atlanta, Orfice of the Director 80/04/03
- 8004(£0017 Forwards IE Bulletin 80-07, "BUR Jet Pump Assembly Failure " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04 200
- 8004230142 Forwards IE Rulletin 79-03A 'Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Action required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004)80445 Forwards IE Bulletin 80-08, "Eram of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07 3bc
- 8004290377 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLG. L. M. Tennesser Valley Authority 80/04/23 3pp
- S Reportable occurrences, LERs & related correspondence
- 8004150414 Forwards suppl to final deficiency rept re unacceptable OA documentation for Claier steel matl MILLS.L M. Tennessee Valley Authority 80/04/03 ip
- --8004150417 Suppl to final deficiency rept re unacceptable QA documentation for Glazer steel matl All questionable matl has been tested Slightly excessive sulfur content is caused by chemical differences * not OA sys defects * Tennessee Valley Authority 80/04/03 lp
- 8004270066 Part 2: rept re insp of generator control panels for emergency diesel generators Results determined defects could degrade emergency diesel unit to unsafe performance Corrective action includes in-depth insps & training FALTER, H N PWR System Div PA/PI 80/04/07 App
- 8004220724 Forwards interim deficiency rept re incorrect root face on skewed cadweld sleeves MILLS.L M Tennessee Vailey Authority 80/04/14 lp
- --B004220764 Interim deficiency rept no incorrect root face on skewed cadweld sleeves Root face on stewed cadweld sleeve 10 varies from 3/32 to 1/2 inch Dosign based on assumed 1/16-inch root face Sleeves will undergo destructive puil tests a Tennessee Valley Authority 80/04/14 2pp
- 8004300390 Forwards first interim rept of deficiency re wiring in HPCS metal clad switchgear MILLS, L M Tennessee Valley Authority 80/04/24 (p
- --8004300397 First interim deficiency rept re wiring in HPCS metal classwitchgear OE has been notified of wiring diagram & labeling discrepancies, missing wires & billing problems Phipps Bend mgt investigating discrepancies

 * Tennessee Valley Authority 80/04/24 lp

- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance te nethods for compliance ROSS,D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- BOD4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAQ clearance under Federal Repts Act GRIMES.B K Energency Prepaiedness Task Force BO/03/11 4pp
- G Adjudicatory correspondence
- 8004030626 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification CDSSICK,L V Office of the Executive Director for Operations 80/04/02 34pp
- G Inspection reports, IE Bulletins & correspondence
- 8004070352 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06 200
- 8004090384 Forwards IE Insp Repts 50-518/80-03,50-519/80-03, 50-520/80-03 & 50-521/80-03 on 800103-18 & 25 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --B004090400 IF Insp Repts 90-518/80-03,50-519/80-03,50-520/80-03 & 50-521/80-03 on 800103-18 & 25 No noncompliance noted Major areas inspected GA program review, structural concrete & licensee const organization changes BMAN,N B Region 2, Atlanta, Office of the Director CANTRELL,F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/19 5pp
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC total an Atlanta, GA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/12 200
- 8004210178 Forwards response to 1E Bulletin 80-03, "Loss of Charcoal from 8td Type 11. Two-Inch. Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLG.L M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to 12 Bulletin 79-28 re possible malfunction of NAMCO Model FAISO limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS, LM Tennessee Valley Authority 80/03/28 2pp
- 8004150527 Forwards IF Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31, 2pp
- 8004080636 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Bil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01
- 8004150097 Forwards 1E Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers" No spotific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 20s
- 8004240274 Forwards 1E Info Notice 80-14, "Bafety Buggestions From Employees" No action required d'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 3pp

- 8004180279 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004110017 Forwards IE Bulletin 80-07, "BWR Jot Pump Assembly Failure" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004230142 Forwards IC Bulletin 79-03A "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainloss Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-08, "Exam of Containment Lines Penetration Welds " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 356
- 8004270377 Requests approval of ASMC Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp. MILLS, L.M. Tennessee Valley Authority 80/04/23 3pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004190414 Forwards suppl to final deficiency rept re unacceptable QA documentation for Olaser steel mat!
 MILLS.L II Tennessee Valley Authority B0/04/03 ip
- --8004150417 Buppl to final deficiency mept re unacceptable GA documentation for Olayer steel mati All questionable mati has been tested Blightly excessive sulfur content is caused by chemical differences & not OA sys defects * Tennessee Valley Authority 80704703 ip
- 8004270066 Part 21 rept re insp of generator control panels for emergency diesel generators Results determined defects could degrade emergency diesel unit to unsofo performance Corrective action includes in-depth insps & training FALTER, H N PUR System Div PA/PI 50/04/07 4pp
- 8004220724 Forwards interim deficiency rept to incorrect root face on skewed cadweld sleeves MILLS,L M Tennessee Valley Authority BO/04/14 ip
- --8004220/64 Interim deficiency rept re incorrect root face on skawed cadweld sleeves Root face on skawed cadweld sleeves 18 varies from 3/32 to 1/2 inch, Design based on assumed 1/16-inch root face Gleeves will undergo destructive pull tests * Tennessee Valley Authority 60/04/14 2pp
- 8004300390 Forwards first interim rept of deficiency re wiring in HPCB metal clad switchpoar MILLS.L M Tennessee Valley Authority, 80/04/24 ip
- --8004300377 First interim deficienty rept re wiring in HPCB metal clad multchgear OE has been notified of wiring diagram & labeling discrepancies missing wives & billing problems, Phipps Bend mgt investigating discrepancies * Tennesse Valley Authority 80/04/24 ip
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREQ-058B, "Interim Btaff Position on Environ Qualification of Bafety-Related Electrical Equipment," providing guidance re-methods for compilance ROSB, D F Division of Project Management 80/02/05 7pp
- F Becurity, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791826 ltr.has been postponed pending OAO clearance under Federal Repts Act GRIMEG.B.K Emergency Preparedness Task Force 80/03/11 App
- Q Adjudicatory correspondence
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board natification ODSEICK-L V. Office of the Executive Director for Operations 80/04/02. 34pp

- G Inspection reports. If Bulletins & correspondence
- 8004090384 Forwards If Insp Repts 50-518/80-03,50-519/80-03, 50-520/80-03 & 50-521/80-03 on 800103-18 & 25 No noncompliance noted BRYANT J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 Ppp
- --8004070400 IE lasp Repts 90-518/80-03.50 519/80-03.50-520/80-03 & 50-521/80-03 on 800101-18 t 25 No noncompliance noted Major areas inspected & program review, structural concrete & licensees const organization changes BHAN, N B Region 7. Atlanta. Office of the Director 80/02/19
- 8004090025 Confirms 800310 felican arranging 800320 meeting between NRC 5 util in Atlanta. OA to discuss accuracy of written repts provided to IE NRC will provide eventall evaluation of util handling of deficiences identified by GA program C'REILLY. J.P. Region 2. Atlanta, Office of the Director 80703/12 206
- 8004210178 Forwards response to 1F Bulletsh 80-03, "toss of Charcoal from Std Type II, Two-lich Tray Advertor Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS: I M Tennessee Valley Authority 80/03/21 App
- 8004180106 Forwards response to 1C Bulletin 79 28 re possible malfunction of NAMCO Model EA180 limit switches At Facilities where applicable limit surtches are identified, replacement gaskets have been oldered MILLS.L 21 Tennessee Valley Authority 80/03/28 2pp
- 800415052/ Forwards IE Info Notice 80-12. 'Instrument Failure Causes Opening of PORV & Block Valve "No specific action or response notessary O'REHLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 000400636 Forwards It Circular 60-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Gupply "No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/04/01
- 6004150097 Forwards IT Info Notice 80-19, "GE Type 63M Control Gwitches Defective CAM Followers " No specific action or response required O'RERLY, J.P. Region 2: Atlanta. Office of the Director 60/04/02
- 8004240274 forwards IF Info Notice 80-t4. "Safety Buggestions from Employees" No action required 0.4ETHLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02
- 80041B0279 forwards IL Circulai 80-07, "Problems W/MPCI Turbine Dil 8ys " No written response required D'RESLLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 20p
- 8004|10017 Forwards If Suljetin 80-07. "RWR Jot Pump Assembly Failure "No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004230142 Forwards If Builetin /9-03A 'Longitudinal Weld Defects in ASME GA 312. Type 304 Stainless Steel Pipe " Action required D'REILLY, J.P. Region 2. Atlanta. Office of the Director R0/04/04 tp
- 8004180445 forwards IE Bulletin BO-OG, "Crem of Containment Liner Penetration Welds " Writton response required O'MEJLLY, J.P. Region 2. Atlanta, Office of the Director B0/04/07
- 8004270777 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Espeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLE, L. M. Tennessee Valley Authority 80/04/23 3pp
- S Reportable occurrences, LFRs & related correspondence
- B0041304i4 Forwards suppl to final deficiency rept re unacceptable QA documentation for Glozer steel mat! MILLS-I M Tennessee Valley Authority B0/04/03 ip

- --800415C417 Suppl to rins) deficiency rept re unacceptable QA documentation for Glajer steel nafl All questionable math has been tested Slightly excessive sulfur content is caused by chemical differences 'not QA sys defects * Tennessee Valley Authority 80/04/03 ip
- 8004290066 Part 21 teptine inspirof generator control panels for emergency diesel generators Results determined defects could degrade emergency diesel unit to unsare performance. Corrective action includes indepth inspir
- 8004220724 Forwards interim deficiency rept re incorrect root face on steward cadweld sleeves MILLS.L M Tennessee Valley Authority 80/04/14 tp
- --8004220764 Interim deficiency lept re incorrect root face on skewed cadweld sleeve IB varies from 3/32 to 1/2 inch Design based on assumed 1/16-inch root face Sleeves will undergo destructive pull tests * Tennessee Valley Authority 83/04/14 2pp
- 8004300390 Forwards first interim rept of deficiency re wiring in HPC8 metal clad switchgear MILLS.L M Tennessee Yailey Authority 80/04/24 lp
- --8004300397 First interim deficiency rept re wiring in HPCS metal clad switchgear QE has been notified of wiring diagram & labeling discrepancies missing wires 5 billing problems Phipps Bend ngt investigating discrepancies *

 * Tennessee Valley Authority 80/04/24 ip
- DOCKET STN-50-522 SAAGIT NUCLEAR POWER PROJECT, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment." providing guidence re methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8004070237 Discusses status of Geosciences Branch review effort Concurs on lecommendation to withhold application until applicant performs extensive studies Branch should be informed of util meeting re-proposed site relocation STGLZ.JF Light Water Reactors Branch 1 80/03/20 1p
- 8004100489 Responds to 800129 request for info re composition of piping in cooling sys & data concerning chemical loadings in sys Stainless steel will be used for condensor tubes in place of Admirally metal originally specified BLACK.R L. Hearing Brench 1 80/03/31 2pp
- 9004210405 Summary of B00328 meeting w/near-term CP applicants in Bethesda, MD re evaluation of progress made to date establishing proposed requirements atemning from TMI-2 accident
 THDMAS.C O Standardization Branch 80/04/03 63pp
- B004300074 Summary of 600319 meeting w/Near-Term CP Applicants Group in Bethesda. MD re matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAS. C D Standardiistion Branch B0/04/03 12pp
- 3004240557 Summary of 800402 meeting w/Near-Term CP Applicants Group in Bethesda. MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl
 THOMAS.C O Light Water Reactors Branch 1 80/04/07 47pp
- Adjudicatory correspondence
- 3004020468 Responds to 800219 itr requesting reanalysis of A-6 aircraft accident rate in light of recent developments Potential hazara needs not be reanalyzed at present, but info is being monitored for future possibility BLACK, R. L. Hearing Branch 1 80/03/20 ip
- -8004020474 Comments recent A6 accident published in 800212 Seattle Times Accident does not increase risk of crash at facility site due to military nature of Accident Analysis Branch 80/03/18 ip
- OO4080017 Order denying Skagitonians Concerned About Nuclear Power motion to compel applicants' answers to interrogatories re San Juan Islands seismic profiles Issue does not relate to matters in controversy identified by Commission or ASLB DEALE,V B Atomic Safety and Licensing Board Panel B0/03/21 3pp

- 8004030026 Memorandum or understanding between NRC & FEMA re prompt improvement in tadiological emergency planning & preparedness, distributed as Boald notification COSSICK, L. V. Orfice of the Executive Director for Operations 80/04/02 34pp
- 6004170245 Submits progress rept in response to ASLB 800304, "Conference of 800122 Background, Purpose & Results," re resolution of USOB/NRC requests for add1 info Hearing dates on geology & seismology not yet known Will submit status by 800530 SHANSON, D T Hearing Branch 1 80/04/15 2pp
- U Congressional/Executive Correspondence
- 8004140286 Responds to 791011 ltr re-setsmalagical review of proposed facility USGS & other experts contracted to review site conservative assumptions are incorporated into structural & sys designs to compensate for setsmalagical uncertainties DIRCKS.H J Orfice of the Frecutive Director for Operations 80/03/18 2pp
- DOCKET STN-50-523 SKAGIT NUCLEAR POWER PROJECT. UNIT 2

 A Application/constitution stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D F Division of Project Management 80/02/09 7pp
- B004070237 Discusses status of Geosciences Branch review effort Concurs in recommendation to withhold application until applicant performs extensive studies Branch should be informed of util meeting reproposed site relocation STOLI, J.F. Light Water Reactors Branch (80/03/20 ip
- 8004100489 Responds to 800129 request for info re composition of piping in cooling sys & data concerning chemical loadings in sys Btainless steel will be used for condensor tubes in place of Admiralty metal originally specified BLACK-R L. Hearing Branch i 80/03/31 2pp
- B004210405 Summary of B00328 meeting w/near-term CP applicants in Bethesda MP re evaluation of progress made to date establishing proposed requirements stemming from TMI~2 accident THOMAS.C O Standardization Branch 80/04/03 63pp
- 8004300074 Summary of 800319 meeting w/Near-Term CP Applicants Group in BetherdarMD re-matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAS.C O Standardization Branch 80/04/03 12pp
- BO04240557 Summary of B00402 meeting w/Near-Term CP Applicants Group in Bethesda.MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl
 THOMAS.C O Light Water Reactors Branch 1 B0/04/07 47pp
- G Adjudicatory correspondence
- B00402046B Responds to B00215 itr requesting reanalysis of A-6 aircraft accident rate in light of recent developments Potential hazard needs not be reanalyzed at present but info is being monitored for future possibility

 BLACK, R. L. Hearing Branch i 50/03/20 ip
- ~-8004020474 Comments recent A6 accident published in 800212 Seattle Times Accident does not increase risk of crash at facility site due to military nature of A6 READ, J Accident Analysis Branch 80/03/18 ip
- 8004080017 Order denying Skagitonians Concerned About Nuclear Power motion to compel applicants' enswers to interragatories to San Juan Islands seismic profiles Issue does not relate to matters in controversy identified by Commission or ASLE DEALE.V B Atomic Safety and Licensing Board Panel. 80/03/21 3pp.
- 8004030026 Memorandum of Understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSSICK. V Office of the Executive Director for Operations
- 8004170245 Submits progress rept in response to ASLB 800306, "Conference of 800122 Background. Purpose & Results." re resolution of USOS/NRC requests for addl info Hearing dates on geology & seismology not yet known Will submit status by 800530 SNANSON, D T Hearing Branch I 80/04/15 2pp

U Congressional/Executive Correspondence

8004140286 Responds to 791011 itr re seismological review of proposed facility USGS & other experts contracted to review situ Conservative assumptions are incorporated into structural & sys designs to compensate for seismological uncertainties DIRCKS.N J Office of the Executive Director for Operations 80/03/18 2pp

DOCKET 50-524 BARTON, UNIT 1 O Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OOBSIGKL V Office of the Executive Director for Operations 80/04/02 34pp

DOCKET 50-525 BARTON, UNIT 2

- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp

DOCKET 50-526 BARTON, UNIT 3

Q Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSBICKL V Office of the Executive Director for Operations

DOCKET 50-527 BARTON, UNIT 4

9 Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GUSSICKL V Office of the Executive Director for Operations 80/04/02 34pp

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D F. Division of Project Management
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal data for evacuation time estimates; requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES:B K. Emergency Preparedness Task Force 80/03/11 4pp
- B004180866 Responds to NRC 791121 & 1226 requests for evacuation time estimates & revised emergency plan, respectively Delay will render AZ state plan incomplete Info will be provided in Dec 1980, VAN BRUNT, E E Arizona Public Service Co B0/04/01 4pp
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8004010244 Forwards Amend 1 to FSAR
 VAN BRUNT, E E Arizona Public Service Co 80/03/31, ip
- --8004010247 Amend 1 to FSAR

 * Arizona Public Service Co 80/03/31 155pp

- Q Inspection reports: IF Bulletins & correspondence
- 8004300117 Forwards IE Insp Repts 50-528/77-10,50-529/77-10 & 50-530/79-06 on 791101-30 No noncompliance noted SPENCER,C S Region 3. San Francisco, Reactor Construction & Engineering Support Branch 60/01/31 2pp
- --8004300121 [E Insp Repts 50-528/79-10.50-529/79-10 & 50-530/79-06 on 791101-30 No noncompliance noted Major areas inspected const activities, including pipe hanger welds, reactor cooling postweld heat treatment & spray pond pump steel DDDDS,R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch VORDERGRUEGGEN Region 5, San Francisco, Office of the Director 80/01/30 6pp
- 8004020152 Ack receipt of 800228 itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-528/79-09, 50-529/79-09 & 50-530/79-05
 SPENCER, 0 B Region 5, San Francisco, Reactor Construction & Engineering Support Branch GD/03/17 ip
- --8004020162 Responds to NRC 800129 ltr re violation noted in IE Insp Repts 50-528/79-09, 50-529/79-09 & 50-520/79-09 Corrective actions inspected piping for cleanliness & instituted formal training for employees VAN BRUNT, E E Aritona Public Sprvice Co 80/02/28 3pp
- --8004020168 Forwards IE Insp Repts 50-528/79-09.50-529/79-09 & 50-530/79-05 on 791129-30 & notice of violation BPENCER, G S Region 5, San Francisco, Office of the Director 80/01/29 2pp
- --8004020171 Notice of violation from insp on 791129-30 * Region 5, San Francisco, Office of the Director 80/01/28 ig
- --8004020180 IE Insp Repts 50-528/79-09.50-529/79-09 & 50-530/79-05 on 791129-30 Noncompliance noted failure to use temporary cleanliness pipe caps on safety-related piping DDDDS:R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch NARBUT,P P, ECKHARDT,J H Region 5. San Francisco, Office of the Director 80/01/28 7pp
- 8004150203 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response mecessary ENGELKEN.R H Region 5, Ban Francisco. Office of the Director 80/03/31 ip
- 8004100077 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/01 ip
- 8004110107 Forwards IE info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers" No specific action or response required ENGELKEN.R H Region 5, San Francisco, Office of the Director
- 8004220031 Forwards IE info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELHEN, R H Region S, San Francisco, Office of the Director 80/04/02 ip
- 8004180146 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil 8µs " No written response required CMGELKEN.R H Region 3, San Francisco, Office of the Director 80/04/03 ip
- 8004230373 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312.Type 304 Stainless Steel Pipe " Action required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/04 ip
- 8004220170 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ENGELKEN.R H Region S. San Francisco, Office of the Director 80/04/07 Ip
- 8004240493 Ack receipt of 800326 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/80-01; 50-529/80-01 & 50-530/80-01 BPENCER, 0 & Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/04/08 lp

- --8004240501 Responds to NRC 800227 Itr re violations noted in IE Insp Repts 50-528/80-01,50-529/80-01 % 50-530/80-01 Corrective actions Bochtel field ranst manager issued 800201 memo emphasizing compliance w/drawing confrol sys VAN BRUNITE E Arizona Public Service Co 80/03/26 5pp
- -8004240508 Forwards IE Insp Repts 50-528/80-01,50-529/80-01 & 50-530/80-01 on 800121-29 & notice of violation SPENCER.G S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004240516 Notice of violation from insp on 800121-25
 * Region 5. San Francisco. Office of the Director 80/02/26
 200
- --8004240522 IF Insp Repts 50-528/80-01.50-529/80-01 to 50-530/80-01 on 800121-25 Noncompliance noted failure to stamp drawings for proper identification ECKHARD.T, KIRSCH.D F Region 5, San Francisco, Office of the Director HAYNES.R C Region 5, San Francisco, Reactor Constituction & Engineering Support Branch 80/02/26 11pp
- S Reportable occurrences. LERs & related correspondence
- B004070251 Ack receipt of B00305 final rept re deficient welds on safety-related pipe hanger assemblies Util rept will be reviewed & evaluated by NRC ENGELMEN.R H. Region 5. San Francisco, Office of the Director B0/03/12
- --8004070255 Forwards final rept re deficient welds on safety-related pipe hanger assemblies
 VAN DRUNT,E E Arizona Public Service Co 80/03/06 lp
- --B004070258 Final rept re deficient welds on safety-related (Quality Class Q) pipe hanger assemblies Of 47 pipe hangers installed & inspected, 17 had fillet welds that were too small Welds are being repaired per design criteria * Arziona Public Service Co 80/03/05 3pp
- B004010330 Forwards interim deficiency rept re Rockbestos Co 600 volt copper power cable delivered > partially installed at facility Results of qualification testing are required before final corrective action can be taken VAN DRUNT, E E Arirona Public Service Co 80/03/24 2pp
- --8004010358 Interim deficiency rept re partially installed Rockbestos
 Co 600 voit copper power cables having nonsequential footage
 markings Investigation revealed factory repair of conductor,
 insulation 5 jacket unacceptable Stop work order issued
 4 Arizona Public Service Co 80/03/18 Spp
- SCO4170045 Forwards interim deficiency rept re visual insp of circumferential weld joints on ASME Section III, Class 3 piping sys between 2-4 inches in diameter VAN BRUNT.E E Arizona Public Service Co BO/04/10 pp
- --B004170051 Interim deficiency mept re visual insp of circumferential weld joints on ASME Section III.Class 3 piping sys between 2-4 inches in diameter Caused by incorrect info on Drawing 13-P226-011 Welds will be re-inspected # Arizona Public Service Co 80/04/09 2pp
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance R088,D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp.
- 8004150566 Responds to NRC 791121 & 1226 requests for evacuation time estimates & revised emergency plan, respectively Dalay will render AZ state plan incomplete info will be provided in Dec 1980
 VAN DRUNT, E.E. Arizona Public Service Co. 80/04/01 4pp

- V Utility Final Safety Analysis Report (FSAR) & amends
- 8004010244 Forwards Amend I to FSAR VAN BRUNT, E E Arizona Public Service Co 80/03/31 ip
- --8004010247 Amend 1 to FSAR * Arizona Public Service Co 80/03/31 195pp
- G Inspection reports, IE Bulletins / correspondence
- 8004300117 Forwards IE Insp Repts 50-528/79-10.50-529/79-10 & 50-530/79-06 on 791101-30 No noncompliance noted SPENCER.G S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/01/31 2pp
- --8004300121 IE Insp Repts 50-528/79-10,50-529/79-10 & 50-530/79-04 pn 791101-30 No noncompliance noted Major areas inspected constactivities, including pipe hanger welds, reactor cooling postweld heat treatment & spray pond pump steel DODDS,R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch VURDERBRUEGGEN Region 5, San Francisco, Office of the Director GO/01/30 App
- 8004020152 Ack receipt of 800228 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-528/79-09, 50-529/79-09 & 50-530/79-05 SPENCERO S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/03/17 ip
- ---8004020162 Responds to NRC 800129 ltr re violation noted in IE Insp Repts 50-528/79-09, 50-529/79-09 & 50-530/79-03 Corrective actions inspected piping for clearliness & instituted formal training for employees VAN BRUNT.E E Arisona Public Service Co 80/02/20 3pp
- --800402016B Forwards IE Insp Repts 50-528/79-07, 50-529/79-07 & 50-530/79-08 on 791129-30 & notice of violation SPENCER(0 S Region 5, San Francisco, Office of the Director 60/01/29 200
- --8004020180 IE Insp Repts 90-528//9-09.50-529/79-09 & 50-530/79-08 on 791129-30 Noncompliance noted failure to use temporary cleanliness pipe caps on safety-related piping DODDS.R T Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch NARBUT.P P. ECKHARDT.J H Region 5, Ban Francisco, Office of the Director 80/01/28 7pp
- B004150203 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/03/31 tp
- 8004100097 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating dil Addition & Onsite Supply " No written response required ENGELECT, R H Region 5, San Francisco, Office of the Director 80/04/01 ip
- 8004110107 Forwards IE Info Notice 80-13, "GE Type SUM Control Switches Defective CAM Followers " No specific action or response required ENGELMEN.R H Region 5. San Francisco. Office of the Director 80/04/02 in
- 8004220031 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees " No action required ENGELKER,R H Region 5, San Francisco. Office of the Director 80/04/02 ip
- 8004180146 Forwards IE Circular 80-07, "Problems W/HPCl Turbine Oil Sys " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/03 ip
- BO04230373 Forwards IC Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312 Type 304 Stainless Steel Pipe" Action required. ENGELKEN, R H Region 5. San Francisco. Office of the Director B0/04/04 ip
- 8004220170 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required ENGELMENTR H Region S, San Francisco. Office of the Director 80/04/07 1p

- 8004240493 Ack recuipt of 800326 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-528/80-01, 50-527/80-01 & 50-530/80-01
 8PENCER: 0 & Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/04/03 lp
- ---8004240501 Responds to NRC 800227 ltr re violations noted in IE Insp Repts 50-528/80-01,50-529/80-01 & 50-530/80-01 Corrective actions Bechtel field const manager issued 800201 memo emphasizing compliance w/drawing control sys VAN BRUNT, E E Arizona Public Service Co 80/03/26 5pp
- --B004240508 Forwards IC Insp Repts 50-328/80-01,50-529/80-01 & 50-330/80-01 an 800121-29 & notice of violation SPENCER,0 B Region 7, Ban Francisco, Reactor Construction & Engineering Support Branch 80/02/2/ 2pp
- --8004240516 Notice of violation from insp on 800121-25

 * Region 5. Ban Francisco, Office of the Director 80/02/26
- --8004240522 IC Inep Repts 90-528/80-01, 90-529/80-01 & 50-530/80-01 on 800121-20 Noncompliance noted failure to stamp diawings for proper identification ECKHARD.T. KIRSCH.D F Region 5, Ban Francisco, Office of the Director HAYNES, R Region 5, Ban Francisco, Reactor Construction & Engineering Gupport Branch G0/02/26 11pp
- 8 Reportable occurrences, LCRs & related correspondence
- (1004170049 Forwards interim deficiency rept re visual insp of circumferential weld joints on ASMC Section III.Class 3 piping sys between 2-4 inches in diameter VAN BRUNT, E. Artiona Public Service Co. 80/04/10 pp
- --8004170051 Interim deficiency nept re visual insp of circumferential weld joints on ABMT Section III.Class 3 piping sys between 2-4 inches in diameter Caused by incorrect info on Drawing 13-P226-011 Welds will be re-inspected Arisona Public Service Co BD/04/09 2pp
- DOCKET GTN-50-530 PALO VERDE NUCLEAR GTATION, UNIT 3

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURTO-050B, "Interim Btaff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSE, D f Division of Project Management
- F. Security, medical, emergency & fire protection plans
- BD040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAU clearance under Federal Repts Act
 ORIMEG.B K Emergency Preparedness Task Force 80/03/11 4pp
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8004010244 Forwards Amend 1 to FBAR VAN BRUNTLE E Aritona Public Service Co 80/03/31 ip
- Q Inspection reports, IE Bulletins & correspondence
- GOO4300117 Forwards IC Insp Repts 30-520/79-10.50-529/79-10 & 50-530/79-06 on 791101-30 No noncompliance noted BPENCER, 0 B. Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/01/31 2pp
- --B004300121 IE Insp Repts 50-528/77 10:50-529/77-10 & 50-530/77-06 on 771101-30 No noncompliance noted Major areas inspected const activities, including pipe hanger welds, reactor cooling postweld heat treatment & spray pond pump steel DODDB, R Y. Region 5. San Francisco, Reactor Construction & Engineering Bupport Branch VORDERBRUZGEN Region 5. San Francisco, Office of the Director B0/01/30 App
- BO04020152 Ack receipt of B00228 itr informing NRC of steps taken to correct violation noted in IF Insp Repts 50-528/79-09.
 50-529/779-09 & 50-530/79-05
 SPENCER.O S Region 5. San Francisco. Reactor Construction & Engineering Support Drauch 60/03/17 ip

- ---8004020162 Responds to NRC 800129 its re-violation noted in IE Imap Repts 50-529/79 09.50 529/79-09 & 50-530/79-05 Corrective actions inspected pipting for cleanliness & instituted formal training for employees VAN BRUNIT C 6 Artions Public Service Co 80/02/28 3pp
- --8004020168 Forwards IL Insp Repts 50-528/79-09,50-529/79-09 % 50-530/79-05 on 791179 30 % notice of violation SPENCER 6 S Region 5, wan Francisco. Office of the Director 80/01/29 200
- --8004020171 Notice of violation from insp on 79(129-30 * Region 5, San Francisco, Uffice of the Director 80/01/28
- ---8004020180 IC Insp Repts 50-528/79-09.50-529//9-09 & 50-530/79-05 on 791129-30 Noncompliance noted failure to use temporary cleanliness pipe capi on sarety-related piping DDDDS.R T Region 5. San Fiancisco. Reactor Construction & Engineering Support Branch NARBUTP P. ECKHARDT.J H Region 5. Gan Francisco, Office of the Director BO/01/28 7pp
- 8004150203 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/03/31 1p
- 8004100077 Forwards IE Circular BO-05, "Emergency Diesel Generator Lubricating Dil Addition & Unsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director BO/04/01 ip
- 800411010/ Forwards IL Info Notice 80-13, "GE Type SDM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN,R H Region 5, San Francisco. Office of the Director 90/04/02 in
- 8004220031 Forwards If Info Notice 80-14. "Safety Buggestions From Emplayers" No action required ENGELKEN.R H Region 5. San Francisco: Office of the Director 80/04/02 ip
- DDD41B0146 Forwards IE Circular B0-0/, "Problems W/HPC! Turbine **Gi1**Sys " No written response required
 ENGELKEN, H Region 9, Jan Francisco, Office of the Director
 80/04/03 lp
- 8004230373 Forwards IE Bulletin 77-03A, "Longitudinal Held Defects in ASME BA-312, Type 304 Stainless Steel Pipe " Action required ENGELKEN, R H Region 5, Ban Francisco Office of the Director 80/04/04 in
- 8004220170 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds" Written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/07 10
- 8004240493 Ack receipt of 800325 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/80-01. 50-529/80-01 & 50-530/80-01 BPENCER.0 9 Region 5. Ban Francisco, Reactor Construction & Engineering Bupport Branch 80/04/08 1p
- --B004240301 Responds to NRC 800227 ltr re violations noted in IE Insp Repts 50-528/80-01.50-529/80-01 & 50-530/80-01 Corrective actions Bechtel field const manager issued 800201 memo emphasizing compliance w/drawing control sys VAN BRUNY.E E Artiona Public Service Co. 80/03/26 5pp
- --B00424090B Forwards IE insp Repts 50-528/80-01,50-529/80-01 & 50-530/80-01 on 800121-25 & notice of violation SPENCER,0 B Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004240516 Notice of violation from insp on 800121-25 * Region 5. San Francisco. Office of the Director E0/02/26 2pp
- --B004240522 IE Insp Repts 80-928/80-01.50-527/80-01 & 50-930/80-01 on B00121-25 Noncompliance noted failure to stamp drawings for proper identification ECKHARD, T . KIRSCH, D F Region 9. San Francisco, Office of the Director HAYNES, R C Region 9. Ban Francisco, Reactor Construction & Engineering Support Branch B0/02/26 ilpp

DOCKET 50-534 WOLSUNG 1

- F Security, medical, emergency & fire protection plans
- 8004150546 Responds to NRC 791121 5 122a requests for evacuation time estimates 5 revised emergency plan, respectively Delay will render AZ state plan incomplete Info will be provided in Dec 1980
 VAN SRUNT, E E Arriona Public Service Co 80/04/01 4pp
- OCCKET 50-537 CLINCH RIVER BREEDER REACTOR

 A Application/construction stage documents & correspondence
- 3004040031 Advises of issuance of NUREO-058B, "Interim Staff Position on Environ Gualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 3004270364 Forwards "Final Rept on Base Matls Tests for Cell Liner Steels " COPELAND.R L Energy, Dept of, Clinch River Breeder Reactor Plant BO/04/04 ip
- --BO04290371 "Final Rept on Base Matis Tests for Cell Liner Steels "CDW01LL;M G . GOWDA;B C . THOMAS;K C Wastinghouse Electric Corp WARD-D-0252 G0/01/31 300pp
- BO04150473 Forwards Revision 1 to MARD-D-0218, "Structural Response of Scale Models to Simulated Hypothetical Core Disruptive Accident"

 COPELAND.R L Energy, Dept of, Clinch River Breeder Reactor Plant BO/04/11 1p
- --800450480 "Structural Rasponse of Scale Models to Simulated Hypothetical Core Disruptive Accident " Revision 1 * Westinghouse Electric Corp HARD-D-0218 R1 79/10/31 18pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending OAO clearance under Federal Repts Act ORIMES B K Emergency Preparedness Task Force 80/03/11 4pp
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0598. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance RQSS,D F Division of Project Mahagement 80/02/05 7pp
- 8004170193 Forwards documentation of util over capacity Current reserves are greater that 50% & predictions for 1980 show reserves of 70% No urgency to resume const HAUCK/F Affiliation Unknown 80/03/06 [p
- BO04080671 Notification of B00314 meeting among Ofc of Nuclear Reactor Regulation/IE Region 3 % Ofc of IE Div of Reactor Const Inspin Betherda-MD to discuss util submittals & answer to current order
 SHEMMAKER: R F Division of Reactor Construction Inspection
 B0703707 2pp
- 8004080160 Forwards util 800305 request that NRC allow resumption of first phase of safety-related work POPE, J R Public Service Co of Indiana. Inc 80/03/11 1p
- --8004090168 Discusses NRC 790815 order confirming suspension of safety-related const at facilities Submits plan for resuming receipt insp of safety category matls & components Requests NRC approval of resumption or safety-related activities SHIELDS, S W Public Service Co of Indiana, Inc 80/03/05 Opp
- 8004230184 Forwards request for add1 info re util GA program NRC needs info to complete review of revised GA program submitted in response to NRC 790815 order confirming suspension of const Requests consolidation of present GA program RUBENSTEIN.L S Light Water Reactors Branch 4 B0/04/01 9pp
- 8004180370 Notification of 800411 meeting w/util in Bethesda, MD re revised QA program description WILSON, J.N. Light Water Reactors Branch 4 80/04/02 5pp

- 8004290426 Interms of intention to use ANSI N45 2 9-1979 "Requirements for Collection.Storage % Maint of GA Records for Nuclear Power Plants" for two design parameters re wind loadings & 2-h fire rating SHIELDS-S W Public Service Co of Indiana, Inc. 80/04/21 ip
- 8004300348 Forwards 'Consolidated Description OA Program "
 SHIELDS S W Public Service Co of Indiana, Inc. 80/04/28 ip
- --8004300350 "Consolidated Description GA Program"

 * Public Service Co. of Indiana, Inc. 80/04/28 96pp
- F Security, medical, emergency & rire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending OAD clearance under Federal Repts Act ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004180223 Forwards util "Description of Licensee Activities Addressing Order Confirming Suspension of Const" POPE. J. R. Public Service Co. of Indiana. Inc. 80/03/04 2pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICKL V Office of the Executive Director for Operations
- H General correspondence
- 8004020490 Awaits reply to 791210 request for hearing re-order for suspension of const-Appeal protested regulation & sys which can so easily dismiss final administrative appeal w/o reason or explanation FREY.D G Sassafras Audubon Society 80/03/02 ip
- 8004210275 Forwards excelpt from President Carter's "Becond Natl Energy Plan." transmitted to Congress on 790507, in response to ltr to DDE referred to NRC on 800122 Plan promotes expanded use of nuclear & coal power DENTON H R Defice of Nuclear Reactor Regulation 80/03/03 15pp
- --80042102B2 Forwards, for NRC response, Boyles ltr urging expediting const of coal & nuclear power plants
 RATHKOPF, C.L. Energy, Dopt of 80/01/22 3pp
- BOO4070364 Responds to 790916 request that LPDR be established in Indianapolis. IN NRC establishes LPDR in immediate vicinity of proposed & operating commercial nuclear power plants Applicable LPDR locations & hours of operation encl BOUDER, J L Division of Rules and Records 80/03/13 3pp.
- ---8004070373 Requests establishment of LPDR in Indianapolis, IN Believes that LPDR would be appreciated & well-used by citizens of Indianapolis BENNETT, C.L. Affiliation Unknown 79/09/16 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 80040400043 Forwards IE lnsp Repts 50-546/80-02 & 50-547/80-02 on 800117-18. No noncompliance noted FIGRELLI. G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/15 2pp
- ---BO04040046 IE Insp Repts SO-546/BO-02 & 30-547/BO-02 on B00117-18 No noncompliance noted Major areas inspected followup on previously identified insp findings & review of PBI rept re 790627 immediate action Itr HAYEB.D W Region 3. Chicago. Reactor Construction & Engineering Support Brench HAKKINS.F C Region 3. Chicago. Office of the Director 80/02/11 5pp
- 80040414 Forwards IE Insp Repts 50-546/80-05 & 50-547/80-05 on B00121 No noncompliance noted KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/16 2pg
- --B004040418 IE insp Repts 50-546/80-05 & 50-547/80-05 on B00121 No noncompliance noted Major areas inspected development of licensee response to order confirming suspension of const. FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch SCHWEIBINZ, E.R., HAWKINS, F.C. Region 3, Chicago, Office of the birector B0/02/19 Spp

- B004i00144 Forwards IE Info Notice 80-08. "States Co Bliding Link Electrical Terminal filock "No specific action or response required KEPPLER, J.G. Ragion 3. Chicago, Office of the Director 80/03/07 is
- 8004210131 Forwards will 800305 lir to V Stello requesting that util be allowed to resume receipt insp at facility SHIELDS, S.W. Public Service Co. of Indiana, Inc. 80/03/07 ip
- B004100371 Responds to IF Builetin 80-03 Charcoal adsorber cells purchased for facility have not been delivered to site SHIELDS,5 W Public Service Co of Indiana, Inc. 80/03/19 ip
- 8004300525 Forwards 1E Insp Repts 50-546/80-03 & 50-547/80-03 on 800107-31 & natice of violation KEPPLER, J Q Region 3, Chicago, Office of the Director 80/03/21
- --8004300528 Notice of violation from insp an 800107-31 * Region 3, Chicago, Office of the Director 80/03/18 6pp
- --8004300536 IE Insp Repts 80-546/80-03 & 50-547/80-03 on 800107-31
 Noncompliance noted failure to include quality requirements in procurement documents, to prescribe quality activity in documented procedure & to implement insp program WILLIAMS, C C . HARRISENJ J Region 3, Chicago, Office of the Director 80/03/18 8pp
- 8004090141 Ack receipt of 800310 its informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-25 & 50-547/79-25 FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 807/03/24 ip
- --8004090146 Responds to NRC 800115 ltr w/add1 info re violations noted in IE Insp Repts 80-546/79-25 & 50-547/79-25 Corrective actions custody of neutron positioning device was changed & proper purge maint was performed SHIELDB, B. W. Public Service Co. of Indiana, Inc. 80/03/10 4pp
- 8004110548 Ack receipt of 800306 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 80-546/79-07 & 50-547/79-09 FIORELLI, G. Region G. Chicago, Reactor Construction & Engineering Support Branch
- --8004110896 Responds to NRC 791002 itr reviolations noted in IE Insp. Repts 50-546/79-09 & 50-847/79-09 Corrective actions contaminant removed from reinforcing steel, joint reprepared to mest Spec Y-27222 Dection 4ii & feathersdge sliminated SHIELDS.8 W Public Service Co of Indiana. Inc. 00/03/06 10pp
- 8004100287 Ack receipt of 800306 itr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-346/79-11 t 50-347/79-11. FIORELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch. 80/03/31 ip
- --8004100291 Supplements 79:101 ltr re violations noted in IE Insp Repts 50-546/79-11 & 50-547/79-11 Corrective actions all const work stopped Util retained consultant to perform mgt analysis of site QA program revised SHIELDS, S.W. Public Service Co. of Indiana, Inc. 80/03/06 7pp
- B004130186 Forwards IF Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Diock Valve " No specific action or response necessary KEPPLER.J Q Region 3. Chicago. Office of the Director 80/03/31
- 8004080721 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Bupply " No written response required KEPPLER.J G Region O. Chicago, Office of the Director 80/04/01 is
- 8004150054 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers" No specific action or response required. KEPPLER, J G. Region 3, Chicago, Office of the Director 80/04/02 ip
- 8004180059 Forwards attachments to IE Circular 80-03, "Protection From Toxic Cas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J. G. Ragion 3. Chicago, Office of the Director 80/04/02

- 8004220150 Forwards IE Info Natice 80 14, "Safety Suggestions From Employees " No action required KEPPLER. J G Region 3, Chicago. Office of the Director 90/04/02 ip
- 8004220398 Forwards IF Circular 80-07. "Problems W/HPCI Turbino Dil Sys " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/03 to
- 8004230250 Forwards 1E Bulletin /9-03A. "Longitudinal Held Defects in ASME SA-312. Type 304 Blainless Steel Pipe" Action required KEPPLER, J. 0 Region 3. Chicago. Office of the Director 80/04/67 to
- 8004220094 Forwards IF Bullatin 80-08. "Exam of Containment Liner Penetration Welds " United response required KEPPLER, J. G. Region J. Chicago, Office of the Director 80/04/09
- S Reportable occurrences, IERs & related correspondence
- 8004070201 Ack receipt of 800305 interim deficiency rept te noncode mat1 & certain Catagory I components final rept will be reviewed upon receipt FIURELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/17 ip
- 8004070197 Ack receipt of 800719 interim deficiency rept re tear in outside flange of uppermast containment liner stiffener Review will commence upon receipt of final rept FIORELLIG Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/03/18 1p
- 8004170249 Ack receipt of 800317 interim deficiency rept to potential for reduced steam generator cooling during certain feedwater line break scenarios NRC will review final rept upon receipt FIDRELLIO Region 3. Chicago. Reactor Construction & Fingineering Support Branch 80/04/01 [p
- 8004240122 Ack receipt of final deficiency tept re interaction of nonsafety-grade sys w/steam supply equipment NRC will complete review of matter during future insp FIDRELLIO Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/04/01 lp
- DOCKET STN-50-547 MARBLE HELL NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURLG OSED. "Interim Btaff Position on Environ Qualification of Bafety-Related Hiertrical Equipment." providing guidance re methods for compliance ROSB,D F Division of Project Hanagement 80/02/05 /pp
- 8004170193 Forwards documentation of util over capacity Current reserves at a greater that 50% & predictions for 1980 show reserves of 70% No urgency to resume const HAUCK, F Affiliation Unknown 20/03/06 ip
- 8004080671 Notification of 800314 meeting among Ofc of Nuclear Reactor Regulation, IE Region 3 & Ofc of IL Div of Reactor Const. Insp. in Bethesda, MD to discuss util submittals & answer to current order.

 BHEMMAKER R. E. Division of Reactor Constitution Inspection 80/03/07 2pp.
- 8004080160 Forwards util 800305 request that NRC allow resumption of first phase of safety-related work POPE, J.R. Public Service Co. of Indiana, Inc. BO/03/11 ip
- ~-8004080168 Discusses NRC /90815 order confirming suspension of eafetyrelated const at facilities Bubmits plan for resuming recelpt insp of safety category matts & components Requests NRC approval of resumption of safety-related activities BHICLOS, B. W. Public Service Co. of Indiana, Inc. 60/03/05 Opp
- BO04230186 Forwards request for add1 info re util QA program NRC needs info to complete review of revised QA program submitted in response to NRC 790815 order confirming suspension of const Requests consolidation of present QA program RUBENSTEIN, L S Light Water Reactors Branch 4 D0/04/01 9pp
- B004180370 Notification of 800411 meeting w/util in Bethesda.MD re revised OA program description HILSON, J N Light Hater Reactors Branch 4 B0/04/02 Spp

- BUU4270420 Invorms of intential to use ANSI N45 2 9-1979 "Requirements for collection/Storage! Maint of UA Records for Nuclear Pouer Plants for two "esign parameters re wind loadings & 2-h fire raing EMIECES 5 W Public Service Co. of Indiana. Inc. 80/04/21 1p
- 6304305348 Furwards Consolidated Description GA Program **
 SHIELES S W Public Service Co or Indiana, Inc. 80/04/28 ip
- ~-8004350350 'Consolidated Description (A Program " * Public Serice Co of Indiana, Inc. 80/04/28 96pp
- F. Security medical, emergency & rice protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltt.has been postponed pending GAD clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Tast Force 80/03/11 4pp
- G Adjudicatory correspondence
- ECO41B022) Forwards util 'Description of Licensee Activities Addressing Order Constraing Suspension or Const' POPE J R Public Service Co of Indiana, Inc. 80/03/04 2pp
- 8004030025 Memorandum or understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GUSSICK.L V Ofrice of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- BO04020490 Abaits reply to 791210 request for hearing re order for suspension of const Appeal protested regulation & sys which can so easily dismiss final administrative appeal w/o reason or explanation
 FREY, D G Sassafras Audubon Society BO/03/02 ip
- BOO4070364 Responds to 790916 request that LPDR be established in Indianapolis. IN NRC establishes LPDR in immediate vicinity of proposed & operating commercial nuclear power plants Applicable LPDR locations & hours of operation encl SOUDER.J L Division of Rules and Records 80/03/13 3pp
- --8004070373 Requests establishment of LPDR in Indianapolis.IN Believes that LPDR would be appreciated & well-used by citizens of Indianapolis BENNETT.C L Affiliation Unknown 79/09/16 2pp
- G Inspection reports. IF Bulletins & correspondence
- 8004040043 Forwards IE Insp Repts 50-546/80-02 & 50-547/80-02 on B00117-18 No noncompliance nated FIORELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --8004040046 [E Insp Repts 50-546/80-02 & 50-547/80-02 on 800117-18 No noncompliance noted Major areas inspected followup on previously identified insp findings & review of PSI rept re 770627 immediate action ltr HAYES, D W. Region 3, Chicago, Reactor Construction & Engineering Support Branch HAKHINS, F C. Region 3, Chicago, Office of the ctor 80/02/11 Spp
 - Torwards IE Insp Repts 50-546/80-05 & 50-547/80-05 on noncompliance nated 7 Region 3, Chicago, Difice of the Director 80/02/16
 - epts 50-546/80-05 % 50-547/80-05 on 800121 No dayor areas inspected development of licensee response to order confirming suspension of const FIGRELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch SCHWEIBINZ.E.R., HAMKINS.F.C Region 3, Chicago, Office of the Director 80/02/13 2pp
- 8004100144 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/03/07 18
- BOO4210131 Forwards util BOO305 Itr to V Stello requesting that util be allowed to resume receipt insp at facility SHIELDS,S N Public Service Co of Indiana, Inc 80/03/07 ip

- 8004100371 Responds to 1E Bullotin 80-03 Charcoal adsorber cells purchased for facility have not been delivared to site SHIELDS.S W Public Service Co of Indiana, Inc 80/03/19 1p
- 8004300525 Forwards IF Insp Rept* 50-946/80-03 & 50-947/80-03 on B00107-31 & notice of violation KEPPLER, J G Region 3. Chicago, Office of the Director B0/03/21 Zap
- --8004300528 Notice of violation from insp on 800107-31 * Region 3, Chicago, Office of the Director 80/03/18 4pp
- ~-8004300536 IE Insp Repts 50-546/80-03 % 50-547/80-03 on 800107-31 Moncompliance noted failure to include quality requirements in procurement documents, to prescribe quality activity in documented procedure 1 to implement insp program HILLIAMS, C C . HARRISCON. J Region 3, Chicago, Office of the Director 80/03/18 8pp
- 8004090141 Ack receipt or 800310 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-25 & 50-547/79-25 FIDRELLI.6 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/24 ip
- --8004090146 Responds to NRC 800115 ltr w/addl info re violations noted in IE Insp Repts 50~546/79-25 / 50~547/79-25 Corrective actions custody of neutron positioning device was changed & proper purge maint was performed SMIELDS,S W Public Service Co of Indiana, Inc 80/03/10 4pp
- 8004110548 Ack receipt of 800306 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 30-546/79-09 & 50-547/79-09 FIGRELLIA Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/24 ip
- --8004110556 Responds to NRC 791002 ltr re violations noted in IE Inap Repts 50-546/79-09 & 90-547/79-09 Corrective actions contaminant removed from reinforcing steel, joint reprepared to meet Spec Y-2722, Section 411 & featheredge eliminated SHIELDS, S W Public Service Co of Indiana. Inc 60/03/04 10pp
- 8004100287 Ack receipt of 800306 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-546/79-11 & 50-547/79-11 & FlORELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/31 Ip
- --8004100291 Supplements 791101 ltr re violations noted in IF Insp Repts 50-546/79-11 & 50-549//9-11 Corrective actions all const work stopped Util relatined consultant to perform mgt analysis of site GA program revised SHIELDS, S.W. Public Service Co. of Indiana, Inc. 60/03/06 7pp
- 8004150186 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of MORV & Block Valve " No specific action or response necessary KEPPLER.J G Region 3, Chicago, Office of the Director, 80/03/31
- BO0408072! Forwards It Circular 80-05, "Emergency Diesel Conerator Lubricating Dii Addition & Chaite Supply " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director BO/04/01, 10
- BOOH190054 Forwards IF Info Notice BO-13, "GE Type SDM Control Buitches Defective CAM Followers " No specific action or response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02 tp
- B004180059 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards." inadvertently omitted from 800306 transmittal KEPPLER. J O Region 3. Chicago, Dffice of the Director 80/04/02 ip
- 8004220150 Forwards IE Info Notice BO-14, "Safety Buggestions From Employees" No action required KEPPLER, J O Region 3, Chicago, Office of the Director BO/04/02.
- 8004220378 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil 8ys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director, 80/04/03

- B004230250 Forwards 1E Bulletin 79-03A. "Longitudinal Weld Defects in ABME BA-312. Type 304 Stainless Steel Pipe" Action required KEPPLER. J O Region 3. Chicago. Diffice of the Director 80/04/07
- B004220094 Forwards IE Builetin 80-08, "Exam of Containment Liner Penetration Wolds " Writton response required KEPPLER, J O Region 3, Chicago, Office of the Director B0/04/09
- 8 Reportable occurrences. LERs & related correspondence
- 8004070201 Ack receipt of 800305 interim deficiency rept re noncode mat1 & certain Category 1 components Final rept will be reviewed upon receipt FIURELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/17 ip Bupport Branch
- 8004070197 Ack receipt of 800219 interim deficiency rept re tear in outside flange of uppermost containment liner stiffener Review will commonce upon receipt of final rept FICRELIT, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/18 ip
- 8004170249 Ack recoipt of 800319 interim deficiency rept re-patential for reduced steam generator cooling during costain feedwater line break acemarics NRC will review final sept upon
 - FIGNELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/01 ip
- GOOARADIRE Ack receipt of final deficiency rept re interaction of nonsefety-grade sys w/steam supply equipment NRC will complete review of matter during future insp FIDARLIL, O Region 3, Chicage, Reactor Construction & Engineering Support Branch 80/04/01 ip

DOCKET 50-948 FORT CALHOUR STATION, UNIT 2

- O Adjudicatory correspondence
- 80040300%6 Memorandum of understanding between NRC & FEMA re grompt represent in radiological emergency planning & preparedness, distributed as Doard notification GOSBICK, L. V. Office of the Executive Director for Operations 80/04/02 34pp.
- DOCKET 50-949 ORFENE COUNTY NUCLEAR POWER PLANT A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURTO 0588, "Interim Staff Position on Environ Gualification of Bafety-Related Cleatrical Equipment," providing guidance re methods for compliance RGSB.D C Division of Project Management 80/02/09 7pp
- Q Adjudicatory correspondence
- B0040300R6 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning a preparadness, distributed as Board notification OBSECKI, V. Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET BIN-50-550 GEBBAR-238-ROP INTERFACE
- A Application/construction stage documents & correspondence
- 1004280422 Forwards excerpts, submitted to NRC on 800331, which define low-low set relief function of nuclear boiler sys in 3NR info is provided to facilitate NRC review & is unchanged from matt presented at 800428 meeting w/NRC GUJRK, J F General Electric Co 80/04/21 i3pp
- DOCKET STN-SO-953 PRIPPS BEND NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of Issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSB, D.P. Division of Project Management 80/02/05 7pp

- 8004080723 Forwards NRC 8001247 (21) line to GE remode to BWR control rod diren sys % addl analysis of boil-off lates, respectively further info * guidance to be issued in NUREG-BAER.R & Light Water Reactors Branch ? 80/03/13 2pp
- B004020154 Forwards addl info re shorthose sturgeon in Delaware River Concludes that continued operation of Unit 1. future operation of Unit 2° const completion of Hope Creek units will not joopardise existence of shorthose sturgeon REGAN, H. H. Assistant Director for Environmental Projects 80/03/14
- --8004020163 "Assessment of Impacts of Salem & Hope Greek Stations on Shorthose Stungoon, Acipenser Brownostrum Lesuer" HASNIK, M.T., WILSON, J.H. (Office of Nuclear Reactor Regulation 00/03/03 110pp
- 800402019.1 Forwards documentation of compliance w/Natl Historic Preservation Act 1 maps of corridors / corridor segments Review of transmission line corridors shows no potential for adverse environ impact to structures or acheological sites MILLS.L M Tennessee Valley Authority 80/03/24 18pp
 - -800402017/ "Transmission Line Vicinity (lap " Gheet 1 of 3 * Tennessee Valley Authority 78/12/01 1p
- ~~B004020203 "Transmission Line Vicinity Map " Sheet 2 of 3 * Tannessee Valley Authority 78/12/01 Ip
- ~8004020204 "Transmission time Vicinity Map " Shoet 3 of 3 * Temposee Valley Authority /8/12/01 ip
- --B004020207 "Transmission Line Vicinity Map " Sheet 1A * Tennessee Vailey Authority 60/01/07 1p
- BOO4080953 Forwards "Fault Zone in Rock Foundation For Essential Gyc Water Pumping Station," providing dotailed description of newly discovered addl fault discussed in 800314 tolcon w/8 Wastler fault not considered capable MILLS.L M Tennessor Valley Authority 80/04/01 4pp
- 8004300021 Discusses faulting in Unit 1 feW pumping station & Unit 2 turbing bldg area NRC considers fault Zones 15 & 16 to be associated w/deformational activity rolated to early geologic history of region Util (80071) # //1024 ltrs encl JACKBON, R. F. Geosciences Branch BO/04/08 ip
- 8004180296 Forwards "Geologic Foundation Rept Descriptions of Faults 11-18," Revision i MILL8,L M Tennessee Vallay Authorsty 80/04/14 ip
- -8004180264 "Geologic Foundation Rept Descriptions of Faults 11-18." Revision 1 AVCL, A.P. Tennossee Valley Authority 80/03/31 Spp
- f Becurity, medical, emorgoncy & fire protection plans
- EIO0408007/ Advises that submittal date for evacuation time estimates, requested by NRC /91226 ltr.has been postponed pending OAD clearance under Federal Repts Act ORIMES.B K Emergency Preparedness Task Force 80/03/11 App
- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re-prompt improvement in ladiological emergency planning & preparedness distributed as Board notification QUSSICK.1 V Office of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by IOCFR20 & App 1 to 10CFR50 Environ info available in stated LPIRG BALLARD.R L. Environmental Projects Branch 1 80/04/01 2pp
- Q Inspection reports, If Bulietins & correspondence
- 8004090352 Forwards IX Bulletin 80-03, "Loss of Charcoal From 8td Tupe 11, Two-Inch, Tray Adsorber Cells" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06

- 8004160057 Forwards IE Insp Repts 50-553/80-01 & 50-554/80-01 on 800212-14 No noncompliance noted BRYANT. U.C. Region 2. whlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --B004160062 IE Insp Repts 50-553/B0-01 1 50-554/B0-01 on B00212-14 No noncompliance noted Major areas inspected const status, project organization, receiving insp. storage 2 preventive & licensee action on previous insp findings CANTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch BURDETTE.T E . WRIGHT,R W Region 2. Atlanta, Office or the Director B0/02/27 App
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC 3 util in Atlanta GA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/03/12
- 8004210178 Forwards response to IE Bulletin 80-03. "Loss of Charcoal from Std Type [[,Two-Inch,Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority 80/03/21 4pp
- 8004180196 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit suitches At facilities where applicable limit suitches are identified, replacement gaskets have been ordered MILLS.L # Tennessee Valley Authority 60/03/28 2pp
- 8004;50527 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31 2bp
- 8004080636 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/01
- 8004150097 Forwards IE info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 200
- 6004240274 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 3pp
- 8004180275 Forwards IE Circulai 80-07, 'Problems M/HPCI Turbine Gil Sys "No written response required O'REILLY, J.P. Region P. Ablanta, Office of the Director BO/04/03 2pp
- 8004210183 Ark receipt of 800314 ltr informing NRC of steps taken to correct violations noted in 1E lnsg Repts 90-553/79-17 & 50-554/79-16
 MVRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/03 ip
 - 'B Responds to NRC 800110 ltr re violations noted in IE Insp 9-17 t 50-554/79-16 Corrective actions craft quality inspectors instructed to conform to tions pending nnessee Valley Authority 80/03/14 3pp
 - s IF Bulletin 80-07. 'BWR Jet Pump Assembly Failure "nse required spine 2, Atlanta, Office of the Director 80/04/04
 - s (E Builetin 79-03A "Longitudinal Weld Defects in 304 Stainless Steel Pipe " Action required egion 2. Atlanta. Office of the Director B0/04/04
 - s IE Bulletin 80-08. "Exam of Containment Liner s " Written response required egion 2. Atlanta, Office of the Director 80/04/07

- 8004230347 Forwards supplement to 790924 response re IE Insp Rept 50-553/79-12 & noncompliance item 553/79-12-01.per NRC 800325 request Rockwell Intl notified that future work performed using insp procedures wypropen signature affixed MILLS.L M Tennessee Valley Authority 80/04/15 2pp
- 8004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp. MILLS, L.M. Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- BOO4150392 Forwards, "Const Effects Monitoring Rept.781019-791018 " EL-ASHRY,M T Tennessee Valley Authority 80/04/11 1p
- --8004150396 "Const Effects Monitoring Annual Rept 781019-791018 "
 ROBERTSON,E B . CLEH.H . WEBB.D H Tennessee Valley Authority
 WR-50-10-80 02 79/04/30 95pp
- S Reportable accurrences. LERs & related correspondence
- 8004160216 Forwards revised corrective actions to 800215 final deficiency rept MILLS.L M Tennessee Valley Authority 80/03/31 ip
- --B004160218 Revised corrective actions to 800213 final deficiency rept Buttered edges on reactor pressure vessel pedestal examined & repaired Vendor film quality sufficient to produce repair overlays > Tennessee Valley Authority B0/03/31 ip
- 8004150485 Forwards final deficiency rept re max weave width exceeded on containment shell welds
 MICLS, L M Tennessee Valley Authority 80/04/03 ip
- ~-8004150494 Final deficiency rept re max weave width exceeded on containment shell welds Weld metal deposited in excess of 5/8-inch max weave width will be removed by thermal air arc grouping All work will be completed by 800930

 Tennessee Valley Authority 80/04/03 ip
- 8004290066 Part 21 rept to insp of generator control panels for emergency diesel generators Results determined defects could degrade emergency diesel unit to unsafe performance Corrective action includes indepth insps & training program FALTER.HW PNR System Div PA/PI 80/04/07 4pp
- 8004220724 Forwards interim deficiency rept re incorrect root face on stewed cadweld sleeves MILLS, L H Tennessee Valley Authority 80/04/14 ip
- --8004220764 Interim deficiency rept re incorrect root face on skewed cadweld sieeves floot face on skewed cadweld sleeve 18 varies from 3/32 to 1/2 inch Design based on assumed 1/16-inch root face Sleeves will undergo destructive pull tests
 Tennessee Valley Authority 80/04/14 2pp
- DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing quidance re-methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 80040807R3 Forwards NRC 800128 & 0211 ltrs to GE re mods to BWR control rod driven sys & addl analyses of boil-off rates; respectively further info & guidance to be issued in NUREG-0619

 BAER, R L Light Water Reactors Branch 2 80/03/13 2pp
- 8004020154 Forwards add1 info re shortnose sturgeon in Delaware River Concludes that continued operation of Unit 1, future operation of Unit 2 t const completion of Roge Creek units will not propardize existence of shortnose sturgeon, REGANN W H Assistant Director for Environmental Projects 80/03/14 2pp
- 8004020193 Forwards documentation of compliance w/Natl Historic Preservation Act & maps of corridors & corridor segments Review of transmission line corridors shows no potential for adverse environ impact to structures or archeological sites MILLG.E. M. Tonnessee Valley Authority 80/03/24 18pp

- ---8004020197 "Transmission Line Vicinity Map " Sheet 1 of 3 * Tennessee Valley Authority 78/12/01 1p
- --8004020203 "Transmission Line Vicinity Map" Sheet 2 of 3
 * Tennéssee Valley Authority 78/12/01 ip
- --8004020204 "Transmission Line Vicinity Map " Sheet 3 of 3 * Tennessee Valley Authority 78/12/01 1p
- --8004020207 "Transmission Line Vicinity Map " Sheet 1A * Tennessee Valley Authority 80/01/07 ip
- 8004080553 Forwards "Fault Zone in Rock Foundation For Essential Svc Hater Pumping Station," providing detailed description of newly discovered addl fault discussed in 800314 telcon w/5 Wastler Fault not considered capable MILLS,L M Tonnessee Valley Authority 80/04/01 4pp
- 8004300021 Discusses faulting in Unit 1 FSW pumping station 1 Unit 2 turbine bldg area NRC considers Fault Zones 15 ½ 16 to be associated w/deformational activity related to early geologic history of region Util 800219 ½ 791024 ltrs encl JACKBON,R E Geosciences Branch 80/04/08 1p
- 8004180256 Forwards "Geologic Foundation Rept Descriptions of Faults i1-18:" Revision 1 HILLS: LM Tennessee Valley Authority 80/04/14 ip
- --8004180264 "Geologic Foundation Rept Descriptions of Faults 11-18," Revision 1 AVEL:AP Tennessee Valley Authority 80/03/31 Spp
- F Becurity, medical, emergency & fire protection plans
- B0040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending QAO clearance under Federal Repts Act
 ORIMES,B K Emergency Preparedness Task Force 80/03/ii 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification COSBICK,L V Office of the Executive Director for Operations 80/04/02 34pp
- H Qeneral correspondence
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 10CFR20 & App i to 10CFR50 Environ info available in stated LPDR8

 BALLARD.R L Environmental Projects Branch i 80/04/01 2pp
- Q Inspection reports: IE Bulletins & correspondence
- 8004090382 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06
- 8004160057 Forwards IE Insp Repts 50-553/80-01 & 50-554/80-01 on 800212-14 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactos Construction & Engineering Support Branch 80/02/27 2pp
- --8004160062 IE Insp Repts 50-553/80-01 & 50-554/80-01 on 800212-14 No noncompliance noted Major areas inspected const status, project organization, receiving inspectorage & preventive & licensee action on previous insp findings CANTRELL,F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch BURDETTE.T E. WRIONT,R W Region 2, Atlanta, Office of the Director 80/02/27 App
- B004090025 Confirms 800310 telcon arranging 800320 meeting between NRC & util in Atlanta, OA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by OA program G'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/12
- 8004210178 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch, Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority 80/03/21 App

- 8004180106 Forwards response to IE Bulletin 77-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS.L M Termessee Valley Authority 80/03/28 2pp
- 8004150527 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening or PDRV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2: Atlanta, Orfice of the Director 80/03/31
- 8004080636 Forwards IE Circular 80-05, "Fmergency Diesol Generator Lubricating Oil Addition 5 Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/01
- B004150097 Forwards IE Info Notice 80-13, "GE Type SDM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/04/02
- B004240274 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 300
- 8004180275 Forwards IE Circular 80-07, 'Problems W/MPCI Turbine Gil Sys " No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004210183 Ack receipt of 800314 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/79-17 & 90-554/79-16 MURPHY-C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/03 ip
- --8004210188 Responds to NRC 800110 ltr re violations nated in IE Insp. Repts 50-553/79-17 & 90-554/79-16 Corrective actions craft supervisors & quality inspectors instructed to conform to specs Other actions pending MILLS.L M Temnessee Valley Authority 80/03/14 3pp
- B004110017 Forwards IE Bulletin 80-07, 'BNR Jet Pump Assembly Failure "
 No written response required
 O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
 2pp
- 8004230142 Forwards IF Bulletin 79-03A "Longitudina) Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004190445 Forwards IE Bulletin 80-09, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/07 Son
- B004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp. MILLS, L.M. Ter

- CUCACRONDO Part 21 rept -- imap of generator control panels for energen y diesel generators Hesolts determined defects could ingrare energency diesel unit trousable performance corrective action includes indepth insist training program FALTER HOU POR Lyster Div PAPP SO/04/07 App
- 8004220724 Forwards interim dericiency tept re incorrect root face on skeued cadeld sleeves.
 MILLOI II Tennessec "alley Authority 80/04/14 lp
- -80342.43/64 Interim deficiency rept re incorrect root face on skewed caduald sleeve 18 aries area 3/32 to 1.2 inch Design based on assumed 1/16-inch root face Sleeve 111 undergo destructive pull tests e Tannessee Valley authority 80/04/14 2pp
- EOCKET STR-50-556 BLACK Fire STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 6004040031 Advises of issuance of NUREG-0588. "Interin Staff Position on Environ wealtrication of Sarety-Related Electrical Equipment "providing jourdance remethods for compliance FDSS D F Division of Project Management 80/02/05 7pp
- 8004210405 Carmany of 800.325 meeting u/near-term CP applicants in Bathesda. The evaluation of progress made to date establishing proposed requirements steaming from TMI-2 accident THOMAS C O Standardivation Branch 80/04/03 63pp
- 8004300074 Surnary of 800319 meeting u/Near-Term CP Applicants Group in Bethesda.MD re-natters related to resumption of CP application review activities associated u/TMI-2 accidents THOMAS C Q Standardization Branch 80/04/03 12pp
- 8004240557 Summary of 800402 meeting u/Near-Term CP Applicants Group in Bethesda, MD re-progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl
 TMOMAS.C O Light Water Reactors Branch 1 80/04/07 47pp
- G Adjudicatory correspondince
- 8004070149 Requests NRC permission to address meltdown issue during hearings affecting const 3 operation of facility Questions should be fully answered 5 thoroughly researched OK citizens have right to be heard HILLHITE S Citizens Action For Safe Energy 80/02/21 1p
- BOO4100995 Forwards intervenor response to applicant motion to strike response of DK attoiney genera! to ALAB-573 & intervenor motion to strike applicant motion to dismiss Class 9 accident inquiry FARRIS.JR Feldman, Hali, Franden, Reed & Woodward 80/02/26 ip
- --8004100605 Intervenor response to applicant motion to strike response of DK attorney general to ASLAB-573 State of DK response contains important 3 substantive comments & should be adopted to ALAB-573 Certificate of Svc encl FARRIS, J R Citizens Action For Safe Energy FARRIS, J R Feldman. Hall, Franden. Reed 3 Woodward 80/02/26 3pp
- ~-8004100610 Intervenor motion to strike applicant motion to dismiss Class 9 accident inquiry & notion to strike response of OK attorney general to ALAB-573 Proceeding should be judged on merits & not technicalisties Certificate of Svc enci FARRIS, J.R. Citizens Action For Safe Energy FARRIS, J.R. Feldman, Hall. Franden, Reed & Woodward 80/02/26 App
- 8004160161 Notice of change of address for Washington ofc of Isham, Lincoln & Beale Certificate or Svc encl GALLO.J Fublic Service Co of Oklahoma GALLO,J Isham, Lincoln & Beale 83/03/14 App
- 8004040266 Suggests local self-reliant, self-sufficient communities are solution to present problems Opposes all forms of nuclear power kin amount of energy from coal 2 gas should be needed for mfg useful tools, bicycles & efficient tractors
 MEEKS:M Affiliation Unknown 80/03/15 2pp
- 8004070108 Expresses concern re NRC refusal to address meltdown issue at hearings Class 9 accident is distinct possibility & should be thoroughly examined Environ & site suitablity hearings should be reopened BUTTHEAD.B J Affiliation Unknown 80/03/15 19

- 8004100235 Response in opposition to joint intervenors' 800226 motion to strike applicants' 800211 pleadings re Class 9 accident inquiry Striking instant pleadings on grounds of untimeliness is not warranted under case law DAVIS.L D Hearing Branch 4 80/03/17 8pp
- 8004280030 Submits additinfo in support of 600206 request for extension to review ALAR-573 Class 9 accident issue Lack of NRC opposition to OA laquest 2 lecent proliferation of info support extension CARTWRIGHT. J E., ROGERS. C S. Oklahoma, State of 80/03/18 3pp
- 8004070143 Hemorandum & order to ASLAB 791207 decision.ALAB-573 Issue of Class 9 accidents varated & remanded to ASLAB for addl action Related motions moot Commission shall be informed of related cases Commissioners Gilinsky & Bradford dissented CHILK.S J Office of the Societary or the Commission GO/03/21 4pp
- 8004180027 Forwards licensee supplemental brief re motion for directed certification % for stay Pendency of Class 7 issue before Commission noted in Licensee motion for directed certification % for stay Discussed on Pages /-10
 WETTERHAHN,M J Conner, Moore % Carber 80/03/24 2pp
- ---8004150043 Memorandum ? order vacating portion of ΛLΛΟ 573 captioned "Consideration of Class 9 Accidents" & remanding to ΛSLΛΟ for further consideration Certificate of Svc encl CHILK.5 J Office of the Secretary of the Commission 80/03/21 600
- 8004080562 Memorandum % order re ALAB-573 concerning individual cases of Class 9 accidents Directs ASLB to address radiological health % safety proceedings in manner consistent w/ABLAB opinion. ALAB-587 % Commission momorandum CLI-80-08
 BISHOP.C J Atomic Safety and Licensing Appeal Panel 60/03/28
- 8004250003 Forwards Commission order to consideration of environ consequences of Class 9 accidents at land-based reactors SHAPAR, H. Office of the Executive Legal Director 80/03/31 ip
- --8004250011 Order vacating portion of ALAB-573 re Class 7 accidents & remanding that portion to ASLAB for further consideration CHILK-5 J Office of the Secretary of the Commission 80/03/31
- 8004230082 Statements of position re-certified question of App 1 of 10CFR50 concerning litigation of health effects of routing radioactive emissions Uiges dismissal of inquiry Cortificate of Svc encl
 DALTON, A T Dalton, A T 00/04/01 7pp
- 8004030026 Memorandum of understanding between NRC & FEMA re-prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK, V Office of the Executive Director for Operations 80/04/02 34pp
- 8004290372 Forwards Corp Commission of State of OK 800403 order denying request for approval to sell bonds PBC of OK presently reviewing order w/view of filing appeal w/OK Bupreme Court OALLO.J Isham, Lincoln & Beale 80/04/04 4pp
- 800415009B Brief on question certified by ABLAN re App I of 10CFR2 785 (d) concerning litigation of health effects Issue is litigable in context of striking overall NEPA cost-benefit balance Appeal must be denied W/Certificate of Svc encl DAVIS, L D . SCINTO, J Hearing Branch 4 80/04/07 28pp
- BOD4220334 Memorandum stating views re question certified in ALAN-573 Consideration of health effects from emission within App I limits is central & controlling factor Certificate of Byc ancl Research I and MURPHY.P M Public Service Co of Oklahoma MILLER,M I sham, Lincoln & Deale BO/04/07 33pp
- 8004280189 Brief amicus curiao re certified question of whether littigation of health effects of normal radioactive releases is barred as matter of law Issue is procluded in absence of special circumstances W.Certificate of Svc REYNOLDS, N.S. PHILIPS, M.H. Teras Utilities Generating Co REYNOLDS, N.S. Debevoise & Liberman 80/04/07 21pp
- H General correspondence
- BO04030337 Requests open hearings on facility re possibility of major accidents, health effects & evacuation NRC & utils have moral responsibility to insure safety People have right to know ansuers to problems

 FARRELL, D., FARRELL, S. Affiliation Unknown BO/02/14 1p

- 8004070124 Requests that NRC reopen environ 5 site suitability hearings Meltdown issue should be fully explored + Affiliation Unknown 80/02/15 1p
- B004040238 Requests that NRC reopen environ & site suitability hearings to consider possible moltdown & related emergencies associated w/nulcear power plants GIBBS.C F Affiliation Unknown 80/02/19 ip
- 8004070116 Requests that NRC reopen environ & site switability hearings to fully explore meltdown possibilities at facility Const should stop until problems re nuclear waste disposel & safety are resolved
 TIBETTS.L Affiliation Unknown 80/02/24 1p
- 8004040228 Suggests hearings on const of reactor did not address meltdown issues Tulsa should not be made site for potential nuclear mistake Utils should build plants away from populated areas Requests reopening of hearings BMITH.M Affiliation Unknown 80/03/15 ip
- BO04040241 Requests that NRC hold meetings in Tulsa,CK re emergency evacuation zone around nuclear plants Plans should be more thorough to protect people if meltdown should accur HEMPLEREE,R Affiliation Unknown BO/03/15 ip
- B004090260 Responds to 1t: to President Carter inquiring why work has stopped on facility Provides info re NRC rules & regulations involved in building & licensing nuclear plants CPs must be issued to util before work can be resumed on facility STDLZ.J F Light Water Reactors Branch 1 B0/03/20 1p
- --8004070267 Forwards F Friend ltr to President Carter inquiring why work has stopped on facility Requests comments
 RATHKOPF.C L Energy, Dept of 60/01/22 4pp
- B004290175 Forwards D Plant B00214 ltr expressing concern re possible meltdown at facilities Requests response BYNAR.II House of Rep. 80/03/26 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004250431 Forwards first intorim deficiency rept re defective concrete pour in auxiliary bldg Next rept will be submitted by 800613.
 MILLE-L M Tonnessee Valley Authority 80/04/21 ip
- --8004250432 First interim deficiency rept re defective concrete pour in auxiliary bldg Concrete samples have been sent to Bingleton Lab for testing * Tennessee Valley Authority 80/04/21 App
- DOCKET BIN-90-557 BLACK FOX BIATION, UNIT 2
- B004160161 Notice of change of address for Washington of of Isham, Lincoln & Beale Certificate of Svc encl OALLO, J Public Bervica Ca of Oklahoma OALLO, J Isham, Lincoln & Beale B0/03/14 4pp
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREQ-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance RQSS, D f Division of Project Management 80/02/05 7pp
- 8004210405 Summary of 800328 meeting w/near-term CP applicants in Bethasda,MD re evaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident THOMAS.C O Standardization Branch 80/04/03 63pp
- 8004300074 Summary of 800319 meeting w/Near-Term CP Applicants Group in Bethasda, MD re matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAG.C O Standardization Branch 80/04/03 12pp
- BOO4240587 Summary of BOO402 meeting w/Near-Term CP Applicants Group in Dethesda.MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl
 THOMAS.C O Light Water Reactors Branch i BO/04/07 47pp

- G Adjudicatory correspondence
- 8004070149 Requests NRC permission to address moltdown issue during hearings affecting constit operation of racility Questions should be fully answered by thoroughly researched DK citizens have right to be heard WILLMITE, S. Citizens Action For Safe (nergy 80/02/21 p.
- BOO4100595 Forwards intervenor response to applicant motion to strike response of CK attorney general to ALAB-5/3 % intervenor motion to strike applicant motion to dismiss Class 9 accident inquiry FARRIS, J. R. Feldman, Hall, Franden, Reed * Noodward BO/02/26 ip
- ~-8004100605 Intervenor response to applicant motion to strike response of OK attorney general to AbLAB-573 State of OK response contains important ; substantive comments & should be adopted to ALAB-577 Certificate of Svc encl FARRIS, J R Citizens Action For Safe Energy FARRIS, J R Feldman, Hall, Franden, Reed / Waodward 80/02/26 3pp
- --8004100610 Intervenor motion to strike applicant motion to dismiss Class 9 accident inquiry & motion to strike response of CK attorney general to ALAR-5/3 Proceeding should be judged on merits & not technicalities Certificate of Svc encl FARRIS, J R Citizens Action for Safe Energy FARRIS, J R Feldman, Hall, Franden, Reed & Woodward 80/02/24 App
- 8004040266 Suggests local self-reliant, self-sufficient communities are solution to present problems Opposes all foims of nuclear power Min amount of energy from coal 1 gas should be needed for mfg useful tools, bicycles / efficient tractors MEEKS.M Affiliation Unknown 80/03/15 2pp
- 8004070109 Expresses concein to NRC refusal to address meltdown issue at hearings Class 9 accident is distinct possibility & should be thoroughly examined Environ & site suitablity hearings should be reopened BUTTHEAD, S J Affiliation Unknown 80/03/15 1p
- 8004;00235 Response in opposition to joint intervenors' 800226 motion to strike applicants' 800211 pleadings re Class 9 accident inquiry 5triking instant pleadings on grounds of untimpliness is not warranted under case law DAVIS:L D Hearing Branch 4 80/03/17 8pp
- 8004280030 Submits add) info in support of 800206 request for extension to review ALAB-573 Class 9 accident issue Lack of NRC opposition to UK request / recent proliferation of info support extension CARTARIOHT.J F / ROCERS.C S Otjahuma, State of BO/03/18 3pp
- 8004070143 Memorandum & order re ASLAB 791207 decision. ALAB-573 Issue of Class 9 Accidents vacated & remanded to ASLAB for addlaction Related metions most Commission shall be informed of related cases Commissioners Olisusky & Bradford dissented CHILK.S J Office of the Secretary of the Commission 80/03/21 Abb
- 8004150027 Forwards licensee supplemental brief to motion for directed certification & for stay Pendency of Class 9 issue before Commission noted in Licensee motion for directed certification & for stay Discussed on Pages 7-10 HETTERHAMN, II J Conner, Muole & Corber 80/03/24 2pp
- --8004150043 Memorandum & order vacating portion of ALAB 573 captioned "Consideration of Class 9 Accidents" > remanding to ASLAB for further consideration Certificate of Svt encl CHILK,S J Office of the Secretary of the Commission 80/03/21 App
- 8004080562 Memorandum & order re ALAB-573 concerning individual cases of Class 9 accidents Directs ASLB fo address radiological health & safety proceedings in manner consistent w/ASLAB upinion.ALAB-987 & Commission memorandum CLI-80-08 BISHOP.C J Atomic Sefety and Licensing Appeal Panel 80/03/28 40s
- 8004250003 Forwards Commission order to consideration of environ consequences of Class 9 accidents at land-based reactors SHAPAR, N Office of the Executive Legal Director 80/03/31 ip
- --8004250011 Order vacating portion of ALAB-573 re Class 9 accidents & remanding that portion to ASLAB for further consideration.

 CHILK.8 J. Office or the Secretary of the Commission 80/03/31 4pp

- through distriction of particles relatively question of App 1 of 1006652 non-energiality with the relative effects of routine radical to a white the relative of the architects of Svelection of App 1 of the svelection of App 1 of 1006652 non-energy and 1
- ingro enert in radius in a templanding between NRC & FEMA ne prompt ingro enert in radius/just energency planning & preparedness distributed as 5 and notification (COSSEVELL 11 Above of the Exerctive Director for Operations 80704707 Talpy
- 890425137/ Furuards vorp ornivation or State of OK 800403 order denying request for approval to well monta PSU of OK presently reviewing order utries or righting appeal L/OK Supreme Court OALLO U Tahan time of Beale 80704704 App
- F304157678 Brief on question centimied by ASLAB re App I of 100FR2 785 (3) rendering litigation of health effects Issue is litigable in contest of skiriling overall NEPA cost-benefit balance Appeal must be series Wifertisicate of Svc encl BAVIS L D SUINTO Hearing Branch 4 80/04/07 38pp
- 6004220334 Memorandum stating views re question certified in ALAB-573 Consideration or health erre to recommission within App 1 limits is rentral 5 confecting ractor Certificate of Second HILLER II I MARPHY, P. M. Public Service Co. of Oklahoma MILLER, II I sham Lincoln Seele 80/04/07 33pp
- 8304280187 Stier anicus uijav te cetlified question of whether litigation of health erreits or normal radioactive releases is barred as matter of lau lesue is precluded in absence of special circumstances & cetlificate or Svc REMBLOS N S PHILIPS. II H Teras Utilities Generating Co RESNULDS.N S Debeccise Liberran 80.04/07 21pp ,

H General correspondence

- 8004030339 Requests open learings on racility is possibility of major accidents, health effects & evacuation NRC & utils have moral responsibility to insure safety People have right to know answers to problems

 FARRELL.D FARRELL, S Affiliation Unknown 80/02/14 ip
- 8004070124 Requests that NHC reopen environ & site suitability hearings Heltdoun issue should be fully explored • Affiliation Unknown 80/02 15 1p
- 800404023B Requests that NRC reopen environ % site suitability hearings to consider possible meltdown % related emergencies associated u/nulcear price plants
 GIBSS.C.F. Affiliation Uninoun 80/02/17 1p
- BO0407011& Requests that NRC reopen environ 5 site suitability hearings to fully explore meltdown possibilities at facility Const should stop until problems re nuclear waste disposal & safety are resolved
 TIBETTS, L. Affiliation Uninown 80/02/24 1p
- BOO4040228 Suggests hearings on const of reactor did not address meltdown issues Tulsa should not be made site for potential nuclear mistate Utils should build plants away from populated areas Requests reopening of hearings BMITH.M Affiliation Unknown E0/03/15 ip
- 8004040241 Requests that IRC hold meetings in Tulsa, DK re emergency evacuation ione around nuclear plants Plans should be more thorough to protect people if meltdown should occur HEMPLEREE, R Aefiliation Uninown 80/03/15
- 8004090260 Responds to 1t1 to President Carter inquiring why work has stopped on facility Provides info re NRC rules E regulations involved in building & licensing nuclear plants CPs must be issued to util before work can be resumed on facility STOLZ, J.F. Light Water Reactors Branch 1 80/03/20 1p
- --8004090269 Forwards E Friend itr to President Carter inquiring why work has stopped on facility Requests comments RATHAOFF,C L Energy Dept or BD/01/22 4pp
- 8004290175 Forwards D Plant 800214 ltr expressing concern re possible meltdown at facilities Requests response SYHAR.M House of Rep 80/03/26 2pp

- S. Reportable occurrences, LERs / related correspondence
- 8004250431 Forwards first interim deficiency tept re defective concrete pour in auxiliary bldg Nert rept will be submitted by 800413
 MILLS, L M Tennessee Valley Authority 80/04/21 ip
- --8004250432 First interim deficiency rept to defective concrete pour in auxiliary bidg Concrete samples have been sent to Singleton Lab for testing * Tennessee Valley Authority 80/04/21 4pp
- DOCKET 50-464 NUCLEAR FULLS RECOVERY & RECYCLE CENTER
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0888, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for cumpliance ROSS, D F Division of Project Management
- F Security, medical, emergancy & fire protection plans
- B0040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 Itr.has been postponed pending GAO clearance under Federal Repts Act GRIMES B K Emergency Preparedness Task Force B0/03/11 4pp
- @ Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSSICK.L. V. Office of the Executive Director for Operations 80/04/02 34pp
- Q inspection reports: IE Dulletins & correspondence
- B0041004B1 Ack receipt of 800123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts B0-986/79-18 & S0-987/79-18 & BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2ρp
- --8004100495 Responds to NRC 791228 ltr re violations noted in IC Insp Repts 50-566/79-18 & 50-567/79-18 Corrective actions chemical & vol control sys charging pumps relocated from storage to area w/power supply Heaters connected HILLS.L H Tennessee Valley Authority 60/01/23 2pp
- --8004100503 Forwards 1E Insp Repts 50-566//9-18 & 50-567/79-18 on 791211-14 > notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/12/28 2pp
- --8004100505 Notice of violation from insp on /91211-14
 * Region 2. Atlanta, Office of the Director 79/12/27 1p
- --B004100506 IE Insp Repts 50-566/79-18 & 50-367/79-18 on 791211-14. Noncompliance noted failure to provide space heaters for safety-related pumps in storage CANTRELL,F S. Region 2. Atlanta, Reactor Construction & Engineering Support Branch GOUGE,M J. Region 2. Atlanta, Office of the Director 79/12/27 Jpp
- 8004090352 Forwards IF Builetin 80-03, "Loss of Charcoal From 8td Type II, Two-Inch, Tray Adsorber Calls " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/02/06 2pp
- 8004040203 Forwards IE Insp Repts 90-966/80-02 & 50-967/80-02 on B00123-29 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/13 Ppp

- --8004040208 IE Insp Repts 50-566/80-02 \$ 50-567/80-02 on 800123-25 No noncompliance noted Major areas inspected preservice insp of major components
 HERDY, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch CROKLEY, B.R. Region 2, Atlanta, Office of the Director 80/02/12 7pp
- 8004210116 Forwards IE lnsp Repts 50-566/80-04 & 50-567/80-04 on 800219-22 No noncompliance noted BRYANT, J C Region 2: Atlanta, Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004210121 IE Insp Repts 50-566/80-04 % 50-567/80-04 on 800219-22 No noncompliance noted Major areas inspected licensee action on previous insp findings. insp followup items. IE bulletins & circulars & warchouse storage CANTRELL, F 8 Region 2. Atlanta, Reactor Construction & Engineering Support Branch THOMAG. H., GDURGE. N. J. Region 2. Atlanta, Office of the Director 80/03/03 Spp
- 8004070025 Confirms 800310 teleon arranging 800320 meeting between NRC & util in Atlanta. OA to discuss accuracy of written repts provided to IC NRC will provide everal evaluation of util handling of deficiences identified by RA program C'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/12 20s
- 800421017B Forwards response to IE Bulletin 80~03, "Loss of Charcoal from Btd Type II, Two-Inch, Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLG,L,M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IT Bulletis 79-20 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLB,L M Tennessee Valley Authority 80/03/28 2pp
- 8004190527 Forwards II Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080636 Forwards IE Circular 80-03, "Emergency Diesel Generator Lubricating Oil Addition & Unsite Supply "No written response required O'RFILLY, P Region 2, Atlanta, Office of the Director 80/04/01
- 0004150097 Forwards IF Info Notice 80-13, "OF Type 80M Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240274 forwards IC Info Nutice 80-14, "Bafety Suggestions From Employees " No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004100275 Forwards II. Circular 80-07, "Problems H/HPCI Turbine Gil Bys " No written response required O'REILLY.J !" Region 2. Atlanta. Office of the Director 80/04/03 280
- 6004230142 Forwards IE Dulletin 77-03A "Longitudinal Hald Defects in ABME 8A-312. Type 304 Stainless Steel Pips " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04 is
- 8004180445 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penatration Helds " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 3pp
- 8004300090 Ack receipt of 800324 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/80-03 & 00-567/80-03 MRP NRPPLY CE Region 2. Atlanta. Reactor Construction & Engineering Support Branch
- --8004300096 Responds to NRC 600228 itr re violations noted in IE Insp Repts 50-566/80-03 & 50-567/80-03 Corrective actions all radiographs w/unacceptable shim placement will be reshot HILBEL H Tennesses Valley Authority. 80/03/24 2pp

- --B004300100 Forwards IF Insp Repts 50-566/80-03 & 50-56//B0-03 on B00203-08 % notice of violation BRYANT, J C Region 2, Aflanta, Reactor Construction & Engineering Support Branch B0/02/29 2pp
- --8004300103 Notice of violation from insp on 800205-08 * Region 2. Atlanta. Office of the Director 80/02/27 lp
- --8004300108 If Insp Repts 50-546/80-03 b 50-547/80-03 on 800205-08
 Noncompliance noted failure to establish adequate measures
 to control radiographic exam procedures for welds
 KLEINSORGE, W.P. Region 2. Atlanta, Office of the Director
 HERDTAR Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch 80/07/2/ Spp
- 8004250405 Notifies that revised response to violations noted in IC Insp Repts 50-566/80-03 t 50-567/80-03 re failure to establish adequate measures to control radiography, will be submitted by ROUNTE MILLS.L.M. Tennessee Valley Authority 80/04/21 ip
- 8004290379 Requests approval of AGME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLS.C. II Tennossee Valley Authority GO/04/23 3pp
- R Periodic operating reports / related correspondence
- 8004280508 Forwards YCNP-SMR 3. 'Socioeconimic Munitoring & Mitigation Rept." For Jan-June 1979 HILLS-L N Tennessee Valley Authority 80/04/15 lp
- --8004280510 "Socioeconumic Henitoring & Hittigation Rept," for Jan-June 1977
 - * Tennessee Valley Authority YCNP-SMR 3 80/03/31 31pp
- 8 Reportable occurrences, 1FRs & related correspondence
- G004250374 Forwards first into im deficiency ropt re improper documentation 5 utilization of computer program INERTIA Next rept will be submitted by G00801 MILLS.L M Tonnessee Valley Authority G0/04/21 ip
- --B0042503/9 first interim deficiency rept to improper documentation & utilization of computer program INERTIA Program documentation being revised to restrict use to closed sections only a Tennesse Valley Authority B0/04/21 ip
 - b (buildaged and red intoling and alter the
- DOCKET STN-90 967 YI'LLOH CREEK NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURCO-0580. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance to methods for compliance RDS9.0 F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 [Lr.hos been postponed pending GAO clearance under Fedoral Repts Act
 ORIMES.B K Emergency Preparedness Task Force 80/03/i1 4pp
- O Adjudicatory correspondence
- BOO4030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations GO/04/07 34pp
- Q Inspection reports. If Bulletins & correspondence
- 8004100481 Ack receipt of 800123 ltr informing NRC of steps taken to correct vialations noted in It. Insp Repts 50-556/79-18 % 50-567/79-18 % BRYANT.J.C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp

- 302+103475 merpang, in 181 7/12/3 lts ie loletions noted in [E Insp. Repts 1: '6- 7/12/3 lts ie loletions actions chemical in lountral sys in ging purps relocated from statinge to a early over supply Meaters connected MILLS L M. Tenrosse "alle, authority 80/01/23 2pp
- --8004|00033 forwards IE inspirests 50-556/79-18 & 50-56/79-18 on 79|211-14 finiting on Tableton Munifori F. R-jack V. Affenta Reactor Construction & Engineering Support Diane. 7/12 272 259
- --EOD410FPD IE Insp Rept. 97 550 79-18 % 50-567/79-18 on 791211-14 Moncropliance united tablance to provide space heaters for savety-relaised pumps in storage CA 'TRELL F.S. Pegion & Atlanta. Reactor Construction & Engineering Support Limited GOUGE M.J. Region 2. Atlanta. Office of the Director 9-12 d7 Spp
- 2004070352 Forward | If Bullitin Bu-03 | Loss of Chancoal From Std Type II. Two-inch Trag Advance: Cells | Action required D'REILLI, J.F. Region (, atlants, Drice of the Director | 80/02/06 | 200
- 8004046203 Forwards If Insp Repts 50-566/80-02 & 50-567/80-02 on 800123-75 No noncorpliance noted BRYANT, J C Pagion 2 Atlanta, Reactor Construction & Engineering Support Branch 80/62/13 2pp
- --8004040208 IE insp Repts 50-564/80-02 \$ 50-567/80-02 on 800123-25 No noncompliance noted Major areas inspected preservice insp of major components

 HERDT.A R Region 7. Atlanta. Reactor Construction & Engineering Support Branch LRONLEY B R Region 2. Atlanta, Office of the Director 80/02/12 7pp
- 8004210116 Forwards IE Insp Repts 50-566/80-04 & 50-567/80-04 on 800219-22 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004210121 IE Insp Repts 50-566,80-04 ? 50-567/80-04 on 800219-22 No noncompliance noted Major areas inspected licensee action on previous insp findings, insp rollowup items. IE builetins & circulars ? warehouse storage CANTRELL,F 9 Region 2, Aflanta, Reactor Construction & Engineering Support Bianch THOMASIM, GOUNGEM J Region 2, Atlanta, Office of the Director 80/03/03 Spp
- 8004090025 Confirms B0G310 felron arranging B00320 meeting between NRC 5 util in Atlanta. GA to discuss accuracy of written repts provided to IF NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILL: J.P. Region 2 Atlanta, Office of the Director B0/03/12 2pp
- 8004210178 Forwards response to IF Bulletin 80-03, "Loss of Charcoal from 5kd Type II.Two-lnrh.Tray Adsorber Cells" Encl lists results of insps at farilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L II Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS, L M Tennassee Valley Authority 80/03/28 2pp
- 8004150527 Forwards IE Into Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Value " No specific action or response necessary O'REILLY.J P Region 2. Atlanta, Office of the Director 80/03/31 2pp
- 8004080o36 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 2pp
- 8004150097 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response required O'REILLY.J P Region 2, Atlanta, Orfice of the Director 80/04/02 2pp

- 8004240274 Forwards II Into Notice 80-14. "Safety Suggestions From Employees' No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02 300
- 8004180275 Forwards If Circular 80-07, 'Problems W/HPCI Turbine Dil Sys "No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/04 in
- 8004180445 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Penetration Welds " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004300090 Ack receipt or 800324 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/80-03 & 50-567/80-03 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/09 Zpp
- --8004900076 Responds to NRC 800228 Ith re violations nated in IE Imap Repts 50-566/80-03 5 90-557/80-03 Corrective actions all radiographs w/unacceptable shim placement will be reshot MILLS:L M Tennessee Valley Authority 80/03/24 2pp
- --8004300100 Forwards IE Insp Repts 50-564/80-03 & 80-567/80-03 on 800205-08 notice of violation BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8004300103 Notice of violation from insp on 800205-08
 * Region 2, Atlanta, Office of the Director B0/02/27 ip
- --8004300108 IE Insp Repts 50-566/80-03 2 50-567/80-03 on B00205-08 Noncompliance noted railure to establish adoquate measures to control radiographic exam procedures for welds KLEINSORGE.W P Region 2. Atlanta, Office of the Director HERDT, A Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 Gpp
- 8004250405 Notifies that revised response to violations noted in IC Insp Repts 50-566/80-03 & 50-567/80-03 re failure to establish adequate measures to control radingraphy, will be submitted by 800428 MILLS, L.M. Tennesses Valley Authority 80/04/21 ip
- 8004290377 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 KILLS.L M. Tennessee Valley Authority 80/04/23 3pp.
- R Periodic operating reports & related correspondence
- 8004280508 Furwards YCNP-9MR 3. "Goctoeconimic Monitoring & Mitigation Rept," for Jan-June 1979 MILLS,L II Tennessee Valley Authority 80/04/15 1p
- --8004280510 "Boctoeconomic Monitoring & Mitigation Rept." for Jan-June 1979 * Tennessee Valley Authority YCNP-6MR 3 80/03/31 3ipp
- S Reportable occurrences, LERs & related correspondence
- 8004230374 Forwards first interim deficiency rept re improper documentation & utilization of computer program INCRTIA Next rept will be submitted by 800801 MILLS.L M Tennessee Valley Authority 80/04/21 ip
- -8004250379 First interim deficiency rept re improper documentation & utilization of computer program INERTIA Program documentation being revised to restrict use to closed sections only # Tennessee Valley Authority 80/04/21 ip

```
DOCKET STN-50-568 NEP NUCLEAR, UNIT 1
                                                                                                                                                                    DOCKET SIN-50 500 LRIC HOLLEAR PLANT, UNIT 1
A Application/construction stage documents & correspondence
7811300053 Forwards review of the Preliminary Draft Environ Statement
Finds PDES unnecessarily wordy Believes impact sections
should only focus on real putential of probable areas
SAMWORTH.R B Environmental Specialists Branch 78/11/17 13pp
8004140012 Responds to 771217 withdrawal of CP application to recovery of review costs Ofc of Controller notified to issue invoice for balance due
    MILLER, W.O. License Fee Management Branch 80/03/24
Q Adjudicatory correspondence
8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radialogical emergency planning & preparedness distributed as Noard notification QOBSICK.L. V Uffice of the Executive Director for Operations
    80/04/02
                         34pp
DOCKET BIN-50-969 NEP NUCLEAR, UNIT 2
A Application/construction stage documents & correspondence
7811300093 Forwards review of the Proliminary Draft Environ Statement Finds PDEB unnecessarily wordy Believes impact sections should only focus on real petential or probable areas SAMMORTILR R Fovironmental Specialists Branch 78/11/17 13pp
1004140012 Responds to 791217 withdrawal of CP application re-recovery of raylow costs Ofc of Controller notified to issue invoice
    for balance due
MILLER.W O License Fee Management Branch 80/03/24 ip
9 Adjudicatory correspondence
0004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification 008BICKIL V. Office of the Executive Director for Operations
                          74pp
    00/04/02
DUCKET STN-50-574 BAGNAG NUGLEAR PONUR PROJECT
A Application/construction stage documents & correspondence
8004070148 Recommends issuance of license to export reactor & associated components to Philippines Proposed export would not be inimical to VS common defense & security No further action required on SECY-79-100
SHEA.J R Dffice of International Programs SECY-80-142 80/03/14
--8004070180 Discusses deaths of two energy activists & physical security of proposed reactor Continued repression creates highly unstable environ "Mother Jones" Dec 1777 article re state of civil war in Philippines enci PERLABIN Philippine Movement for Unvironmental Protection 80/01/27
O Adjudicatory correspondence
```

8004080697 Discusses judicial review on behalf of Ctr for Development Policy & Movement for free Philippines Urges delay of export license issuance for seven working days after Commission apinion; in order to avoid hasty litigation ABHCR.T R Asher.T R PC 00/03/21 2pp

0004280036 Submits Westinghouse response to TR Asher 800321 ltr on behalf of Ctr for Development Policy & Movement for Free Philippines Urges Commission to promptly grant applications renuclear reactor export to Philippines COMAN.B Z. DAUGHERTY.T M. Eckert, Beamans, Cherin & Hellott 80/03/27 App

BOOAIBDIOI Motion to stay effectiveness of final order pending appeal & judicial review re-nuclear reactor export to Philippines Delay in shipment will not injure interests of exporter or parties Certificate of Svc enci SCHERR. B. J. Natural Resources Defense Council MIIBBLE R. Union of Concerned Scientists DOUDHERTY. J. Philippine Movement for Environmental Protection. 80/04/03. 6pp

```
A Application/construction stoge documents / correspondence
8004040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Sarety-Rolated Electrical Equipment," providing guidance re methods for compliance ROSS DF Division of Project Management 80/02/05 7pp
Q Adjudicatory correspondence
8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OBSICKI V Office or the Executive Director for Operations 80/04/02 34pp
DOCKET STH 50-501 ERIE NUCLEAR PLANT, UNIT 2
A Application/construction stage documents & correspondence
8004040031 Advises of issuance of NUREG-0588, "Interim Btaff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance ie methods for compliance ROSS D F Division of Project Management 80/02/05 7pp
O Adjudicatory correspondence
8004030026 Memorandum of understanding between NRC & FEMA is prompt improvement in ladialogical emergency planning & preparadices, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
DOCKET 50 -582 BUNDESERT, UNIT I
G Adjudicatory correspondence
8004030026 Memorandum of understanding between NRC & FEMA re prompt
    improvement in radiological emergency planning & preparedness distributed as Board motification (OSBICK, L.V. Office of the Executive Director for Operations (OO/O4/O2 34pp
DOCKET SO SOR BUNDESERT, UNIT 2
O Adjudicatory correspondence
8004030076 Hematandom of understanding between NRC & FEMA to prompt improvement in tadiological emotioning & preparodness, distributed as Board notification OCSBICK.t V Office of the Executive Director for Operations 80704702 34pp
DUCKET 50-585 TRIGA MARK II
A Application/construction stage documents & correspondence
1004170360 Bubmits application to amend export license, changing contractual & delivery dates, increasing reactor power level & increasing reactor costs Also applies for SNM
    HOWRY. W R Quieral Atamic Co (subs of Quif Dil Ca ) B0/03/20
 DOCKET GTH-50 592 PALO VERDE NUCLEAR STATION, UNIT 4
Q Adjudicatory correspondence
8004030026 Memorandum of understanding between NRC & FEMA re prompt
improvement in radiological emergency planning &
preparedness, distributed as Board motification
QBBICK.L.V. Office of the Executive Director for Operations
     80/04/02
                         3400
```

CHICKET STIL 90-578 PALL TERRE INCLEAR STATION, UNIT 5

G. Adjudicatory correspondence

5004030020 Menoratic or understanding between NRC & FEMA re-prompt improvement in regularization and general planning & preparedness distributed as Grand notification GOSSICP. I "Orrice or the Elecutive Director for Operations GO/04/02 34pp

DOTHET STR-50-596 NEW HAVEN UNIT 1

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of FUREC-0588, "Interim Staff Position on Environ Gualification of Sarety-Related Electrical Equipment, providing juidance to nethods for compliance ROSS.D F Division of Project Management 80/02/05 7pp

Adjudicatory correspondence

800403u025 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as 30ard notification GOSSICK L V Office of the Esseutive Director for Operations 80/04/02 34pp

DOCKET STH-50 597 NEW HAVEN, UNIT 2

A Application/construction stage documents & correspondence

BOO4040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Eafety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management BO/02/05 7pp

G Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OUSSICK.L V Office or the Executive Director for Operations 80/04/02 34pp

DOCKET 50-599 CARROLL FACILITY I

A Application/construction stage documents & correspondence

8004020177 Requests add1 45 days to submit responses to 800206 ltr restte suitability environ & sarety repts
NAUCHTON, W.F. Commonwealth Edison Co. 80/03/28 1p

G Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification COBBICK.L V Office or the Executive Director for Operations 80/04/02 34pp

DOCKET 50-600 CARROLL FACILITY 11

A Application/construction stage documents & correspondence

B004020177 Requests addl 45 days to submit responses to B00206 ltr re site suitability environ A safety repts NAUOHTON,W F Commonwealth Edison Co B0/03/28 1p

O Adjudicatory correspondence

B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

8004160002 Responds to 790906 & 20 ltrs requesting approved route
Alternate route plan proposed in 790920 ltr has been
approved Enc) data is airangements & approved route withheld
(ref 10CFR2 790)
MCCORKLE.O K Physical Security Licensing Branch 80/02/08 2pp

8004220059 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/04/04 to

DOCKET 70-0025 ROCKWFLL INTERNATIONAL CORP

8004100053 Forwards IE Insp Rept /0-0025/79-06 on 790821-24 No noncompliance noted BOOK.HE Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/10/02 2pp

--8004100056 IE Insp Rept 70-0025/79-06 on 790821-24 No noncompliants noted Major areas inspected facility changes & mode, safety committee activities, operations review, radiation protection & raduaste mgt 800K-N E Region 5, San Francisco, Fuel Facility & Materials Safety Branch COULTY, N J Region 5, San Francisco, Office of the Director 79/10/01 7pp

8004020230 Forwards IE Insp Rept 70-0025/80-03 on 800211-13 No noncompliance noted Encl withheld (ref 10CFR2 790) NORDERHAUO, L R Region S. San Francisco. Safeguards Dranch 80/03/10 2pp

8004100174 Forwards IE Insp Rept 70-0025/80-01 on 800107-11 & notice of violation Encls withheld (ref 10CFR2 790)
NORDERHAUG, L R Region 5. San Francisco, Bafeguards Branch 80/03/10 2pp

6004040457 Ack receipt of 800307 ltr informing NRC of steps taken to correct violations noted in 800215 notice of violation NURDERHAUG.L R Region 5, San Francisco, Safeguards Branch, 80703712 ip

8004220009 Forwards IE Info Notice 80-14. "Safety Suggestions From Enployees " No action required ENCELKEN.R H Region 5, San Francisco, Office of the Director 80/04/02 lp

8004170278 Forwards IE Insp Rept 70-0025/80-5 on 800303-07 No noncompliance noted Encl withheld (ref 10CFR2 790) NORDERHAUG.L R Region 5. San Francisco: Safeguards Branch 80/04/03 2na

DOCKET 70-0027 BABCOCK & WILCOX CO

8004070153 Application for amend to SNM-42 to provide for proposed revisions to plant liquid effluent lines re use of flow meters & proportional automatic samplers Diagram, specs & fee encl CGRDANI, R A Babcock & Wilcor Co , Naval Nuclear Fuel Div 80/01/18 7no

8004040130 Ack receipt of 800121 ltr informing NRC of eteps taken to correct violations noted in IE Insp Rept 70-0027/79-15 STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Bafsty Branch 80/02/06 lp

---8004040137 Responds to NRC 791226 ltr re violations noted in IE Insp Rept 70-00R7/79-15 Corrective actions sampling sys was cleaned & repaired Frequent monitoring will establish needed insp schedule EMINO, J. F. Babcock & Wilcox Co. 80/01/21 2pp.

--8004040144 Forwards 1E Insp Rept 70-002//79-15 on 791126-30 & notice of SUTHERLAND.J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/12/26 2pp

--8004040148 Notice of violation from insp on 791126-30 * Region 2, Atlanta, Office of the Director 79/12/21 |p

- --8004040156 IE Insp Rept 70-0027/79-15 on 791126-30 Noncompliance noted improper sampling of incinerator stack OIBSOLA F Region 2, Atlanta, Fuel Facility & Materials Safety Branch MILLGAP, W J Region 2, Atlanta, Office of the Director 79/12/21 7pp
- B004140476 Ack receipt of fee & B00319 ltr transmitting protection plan for BNM of moderate & low strategic significance Request classified in fee Category IA, LOCFRITO 31 AddI payment should be remitted Any overcharges will be refunded WEIBB, D License Fee Management Branch 80/03/28 ip
- B004210106 Revises safeguards Amend MPP-1 to License ENM-27 by granting extension until B00404 for completion of limit of error calculation for Jan-Feb 1980 matl balance period PARTLON J O Material Control Licensing Branch
- 8004240227 Forwards IE info Notice 80 14. "Gafety Suggestions From Employees" No action required GrEILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/02 to

DOCKET 70-0033 TEXAS INSTRUMENTS: INC

- 8004100185 Ack receipt of 800218 itr informing NRC of steps taken to correct violations noted in IC Insp Rept 70-0033/79-13 Ltr will be withheld (ref 1007R2 790) MARTININ O Region 1. Philadelphia, Safeguards Branch 80/03/17 ip
- --8004100189 Forwards IC Insp Rept 70 0033/79-13 on /91217-20 & notice of violation Notice of violation withheld (ref 10CFR2 /90)
 HARTIN V O Region 1, Philadelphia, Bafeguards Branch 80/02/08
 200
- --B004100191 IC Insp Rept /0-0033//9-13 on 791217-20 Noncompliance noted BNM protection Details withheld (ref 10CFR2 790) DEVLIN.J W Region I. Philadelphia, Safeguards Branch BAILEY:R J Region I. Philadelphia, Office of the Director 80/02/07 ip.
- DOCKET 70-0047 NATIONAL AERONAUTICS & SPACE ADMINISTRATION
- 8004090122 Discusses IC Insp Repts 30-4338/80-01.30-6927/80-01 & 70-0047/80-01 on 800110 Noncompliance noted MCCLINTOCK, R O Region i. Philadelphia. Office of the Director 80/02/04 ip

DOCKET 70-0082 NUCLLAR METALB, INC

- B004040207 Documents NRC actions to retire docket file in response to Nuclear Metals. Inc 790408 & 0724 requeste re License ENN-65 Readings from 791125 tabular rept showed radiation level below guidelines Docket should be retired DELANCY, J. C., CROW, W. T. Uranium Fuel Licensing Branch 80/02/15 to

DOCKET 70-0078 TOLEDO, UNIV OF

- 8004020477 Forwards notice of violation from IE insp of Licenses 34-10247-06.8UD-815 & SNN-915 on 800219-20 DAVIS:A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/03/24 2pp
- --B004020492 Notice of violation from insp on B00219-20 Noncompliance noted food consumed in room & stored in refrigerator w/ radioactive isotopes, no neutron survey meter available for monitoring & no leak test records available for 1978 * Region 3, Chicago, Office of the Director B0/03/24, lp

- DOCKET 70-0135 BABCOCK & WILCOK CO
- 8004240028 Discusses B*W /00119 ltm me temporary measures to be taken during phase-out of high enviched U operations Withdraws request for changes of ten specific pages moferenced in itr Plan will be kept current w/normal processing WILLIAMS, R A Babcocy & Wilco, Co., Nuclear Material Div 78/03/06 lp
- --8004240038 forwards addendum to ref plan for safeguarding residual SNM during cleanout of high enriched U facilities Addendum will make plan totally acceptable Addendum withheld WILLIAMS, A M. Babcock / Wilcor Co , Nuclear Material Div 78/09/08 Cpp
- ---8004240046 Formards revised plan for sofeguarding residual SNM during cloanout of enriched U facilities Addresses all areas agreed to at 760721 meeting w//RC flow diagram of scrap recovery processes attached Plan withheld WILLIAMS,R A. Babcock & Wilcox Co., Nuclear Material Div 78/08/18 2pp
- --8004240056 Submits description of upcoming change to D&W matl control & accounting program info withheld (ref 10CFR2 /90) WILLIAMS R A Babcock & Wilcox Co , Nuclear Material Div 77/12/22 lp
- -- 4004240073 forwards projection of expected LEMUF & LEMUF limits for Mar, May 2 Jul 1978 inventories of high enriched U plant in response to NRC request Demonstrates need for exception to required LEMUF limit W/o LEMUF projection WILLIAMS, R A Babcock & Wilcox Co , Nuclear Material Div 78/04/10 1p
- --B0042400B4 Updatos NRC /70826 memo re B&W plans to terminate highly enriched U operations at facilitos Outlines key points in D&W phase-out schedule Phase-out plan is generally acceptable Parts of schedule withheld (ref 1007R2 790) EMITH Office of Nuclear Material Safety & Saroguards 77/11/29 3pp
- --8004240999 (valuates BAW rundamontal nuclear matt control plan & proposed changes Plan should be separated into two parts, one for Pu operations 5 one for low enriched U operations Some plant operations are not described. Into withheld THURMAN.D G. Material Control Licensing Branch. 79/07/30. 2pp
- --8004240104 Notifies that NEW is not able to maintain sys of control required by code requirements for high enriched U plant Code requirements criteria re-scrap recovery operation are no longer applicable info mitchhald
 THURMAN D G Material Control Licensing Branch 78/09/15 2pp
- -8004240110 Discusses 760821-23 trip to 86W sites to discuss portions of measurement control plan 3 to clarify activities retermination of high entitled U operations at Apollo site Info withheld including partion of BNN memorandum THURMAN.D 8 Material Control Licensing Branch 78/09/11 13pp
- --8004240127 Provides followup info to J Partiow 780104 notes re possible strike No hostility exists between mgt & labor inventory of SNM at facilities is being reduced to absolute min Ail processing operations will cease MCCOMRLE.0 Physical Security Licensing Branch 79/01/05 2pp
- --- GOOA240137 Provides add1 info re possible strike All facilities will be shut down All accessble highly enriched U at facilities will be maved to Leechburg vautt PARTLOW, J Material Control Licensing Branch 79/01/04 ip
- --8004240150 Notifies Commission of status of termination of high enriched U operations Unly wet & dry scrap recovery at Apollo & cleanup/dismantling activites at Leechburg have not been shutdown Info withheld (ref 10CFR2 770) EMITH.C V Office of Nuclear Material Bafety & Bafaguards BECY-78-322 78/06/16 2pp
- --8004240185 Forwards preliminary amend fee & revised plan for safeguarding residual SNM during cleanout of enriched U facility Requests that 780626 safeguards plan be withdrawn M/o encis
 WILLIAMS.R A Dabcock & Wilcox Cp . Nuclear Material Div 78/08/18 in

- --9064_40170 (histories of diministroning plans for facilities B&W will replace progretary interior of App I w/nonproprietary version All prodrietary dath changed to homproprietary form Add lines for proprietary flatsification encl LEWIS (in father) will on the Middlean Material Div 78/05/17 Sec.
- 8034_101/7 be_comming than Arp I Cost & Other Commercial Data "

 Patruck & Wilson or Modern Material Div 78/02/17 16pp
- --8004740163 forwards Revision 4 to decommissioning plan Plans have been revised to reflect NAC ownerts during 780215 presentation DZICMISC, J S. Babrock * Wilcox Co., Nuclear Material Div 78.72.17 ty
- --8004_40187 Derchmissioning plan Revision 4

 + Rabcock / Wilcor to Nuclear Material Div 78/02/15 9pp
- 8004220016 Forwards replacement page for conditions section of application for Amend 4 to License SIM-145 omitted from 791221 ltr Sarety e aluation also enc) CROW, N T. Uranium Fuel Licensing Branch 79/12/28 2pp
- ---B004220026 Sarety evaluation supporting administrative amend to License SNM-145 Continued operation or processing equipment should be beneticial **valuable na*l would be recovered for reuse rather than discarded as waste NIYOR.W A Uranium Fuel Licensing Branch 79/12/21 1p
- 8004210081 Application to amend Licenses NM-145 & SNM-264 for redefinition of waste mati AUSTIM M A Babcock & Wilton Co , fuclear Material Div 80/01/16
- ~B004210053 Requests fer for amend of Licenses SNM 145 & SNM-364 NEISS.D License Fee Management Branch B0/02/11 lp
- --8004210026 Forwards fee for amend of Licenses SNM 145 & SNM-364 AUSTIN:N A Babcock & Wilco: Co , Nuclear Material Div 80/02/19
- BOO4020069 "Safeguards Case Study of Nuclear Matls & Equipment Corp V Processing Plant-Apollo-PA (U)." App A ALTMAN, NOCKERT, J. GUINN. E. Division of Bafeguards NUREC-0627 APP A 80/01/31 130pp Available at NTIS
- 8004080197 "Bafeguards Case Study of Nuclear Matls & Equipment Corp U Processing Plant: Appollu-PA ' ALTHAN: W. HDCKERT, J., QUINNE, Division of Safeguards NUREG-0627 80/01/31 12pp
- 80040805B0 Forwards IE Insp Repts 70-0135/79-23 & 70-0364/79-29 on 791105-800104 No noncompliance noted Rept details withheld fref 10CFR2 790! MARTIN.U G Region 1. Philadelphia. Safeguards Branch 80/02/04 200
- --8004080733 IE Insp Rept 70-0135/7y-23 & 79-0364/79-29 on 791105-800104 No noncompliance noted Major areas inspected material control & accounting.physical security.health & industrial security Details withheld (ref 10CFR2 790) KUSHMER, W. L. Region I. Philadelphia. Office of the Director KUSHMER, W. L. Region I. Philadelphia. Office of the 01rector SUSHMER, W. L. Region I. Philadelphia. Safeguards Branch 80/01/30
- 8004070280 Forwards IE Insp Rept 70-0135/79-26 bn 791217-21 No honcompliance noted Details withheld (ref 10CFR2 790) MARTIN N G Region 1. Philadelphia. Safeguards Branch 80/02/04 2pp
- --B004070285 IE Insp Rept 70-0135/79-26 on 791217-21 No noncompliance noted Major areas inspected low enriched U heraflouride receipts, storage, internal control, measurement & statistical controls Details withheld (ref 10CFR2 790) ZIBULSXY,H, SUMMERS,R, MARTIN,W Q Region i, Philadelphia, Safeguards Branch 80/01/30 lp
- 8004100550 Forwards IE Insp Repts 70-0135/79-17 & 70-0364/79-25 on 799904-28 No montompliance noted Sections withheld (ref 100FR2 790)
 MARTIN-U 0 Region 1, Philadelphia, Safeguards Branch 80/02/05 200
- --8004100555 IE Insp Repts 70-0135/79-17 & 70-0364/79-25 on 790904-28
 No noncompliance noted Major areas inspected mati control & accounting physical security health & industrial safety
 Sections withheld fref 10CFR2 790)
 KUSHMER.W L Region J. Philadelphia, Office of the Director
 JOYNER.J H Region J. Philadelphia, Safeguards Branch 80/01/31
 900

- 8004070211 Forward: IE Insp Repts 70-0135/80-02 & 70-0364/80-02 on 300115-18 No noncompliance noted MARTINIU G Region 1, Philadelphia, Safeguards Branch 80/02/07
- --B004070217 IE insp Repts 70-0135/80-02 / 70-0344/80-02 on 800115-18
 No noncompliance noted Major areas inspected physical
 security, health // sarety // en/iron programs
 SMITH G L Region I, Philadelphia, Office of the Director
 JONNER, J H Region 1, Philadelphia, Safeguards Branch 80/02/01
 4pp
- 8004240550 Forwards Amend 7 to License SNM-145 revising Bpecs 1-4,re organization () 1-5,on Tech Specs) control sys,replacement pages for license & NRC sifety evaluation supporting amend PAGE,R G Uranium Fuel Licensing Branch 80/03/06 1p
- --8034240554 Amend 7 to License SNM-145 revising Specs I-4, re organisation & J-5, on Tech Specs & control sys Replacement pages for license encl PAGE, R G Uranium Fuel Licensing Branch 80/03/05 34pp
- BO04090393 Ack receipt of BO0225 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-27 & 70-0364/79-31 Response to be withhold (ref 10GFR2 790) MARTIN.N G Region 1. Philadelphia. Safeguards Branch B0/03/13
- --8004090405 Forwards IE Insp Repts 70-0135/79-27 & 70-0364/79-31 on 791226-800104 & notice of violation Notice of violation uithheld (ref 10CFR2 790)
 MARTIN.H G Region J. Philadelphia, Safeguards Branch 80/02/06
- --8004090419 IE Insp Repts 70-0135/79-27 & 70-0364/79-31 on 791226-800104 Noncompliance noted failure to apply tamper-safing devices to insure integrity of previously made measurements Details withheld (ref 10CFR2 790)

 JOYNER J H Region 1, Philadelphia, Safeguards Branch BMITH, 0 C Region 1, Philadelphia, Office of the Director 80/01/31 1p
- 8004100197 Ack receipt of 800228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-15 & 70-0364/79-19 Ltr will be withheld (ref iOCFR2 790) MARTIN N G Region 1, Philadelphia, Safeguards Branch 80/03/13 ip
- --8004100201 Forwards IE Insp Repts 70-0139/79-15 & 70-0364/79-19 on 790702-0803 & notice of violation MARTIN.W O Region I. Philadelphia, Safeguards Branch 80/02/06
- --8004100204 Notice of violation from insp on 790702-0803
 * Region 1, Philadelphia, Office of the Director 80/01/30 1p
- --8004100209 IE Insp Repts 70~0135/79~15 & 70~0364/79~19 on 790702~0803

 Noncompliance noted various sources containing small amounts of source math SNM & byproduct mail located in unauthorized areas Details withheld (ref (OCFR2 790)

 JDYNER.J H Region 1. Philadelphia, Safeguards Branch KUSHNER.W L Region 1. Philadelphia, Office of the Director 80/01/30
- 8004180626 Forwards proposed PA operations security plan for safeguarding SNM of low strategic significance W/o encl AUSTIN.M A Babcock & Wilcox Co GO/03/13 1p
- 8004080334 Ack receipt of 800222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-16 & 70-0364/79-20 Ltr Withheld (ref 10CFR2 790) MARTIN.N G Region 1. Philadelphia, Safeguards Branch 80/03/14 pp
- --8004080343 Forwards [E Insp Repts 70-0135/79-16 & 70-0364/79-20 on 790806-31 & notice of violation MARTIN W G Region 1, Philadelphia, Safeguards Branch 80/02/14 2nn
- --80040B0346 Notice of violation from insp on 790806~31
 * Region i, Philadelphia, Office of the Director B0/01/31 ip
- --8004080354 IF Insp Regis 70-0135/79-16 % 70-0364/79-20 on 790806-31 Noncompliance noted Pu fuel pins transferred from matl balance area to item control area w/delayed completion of documents Portions withheld (ref 10CFR2 790) JOYNER, J H Region 1. Philadelphia, Safeguards Branch WUSHNER, W. Region 1. Philadelphia, Office of the Director 80/01/30

- 8004210203 Ack receipt of 800221 itr informing NRC of steps taken to correct violations noted in IC Insp Rept 70-0135/79-25 ORIER.8 H Region 1, Philadelphia. Office of the Director 80/03/19 1p
- ---8004210207 Responds to NRC 800120 ltr re violations noted in IE Insp Rept 70-0135/79-25 Corrective actions CPVC pipe was replaced w/borositicate raschig rings, drums have been labeled & documents posted AUSTIN.M A Babcock & Walcox Co 80/02/21 3pp
- --804210214 Forwards IE Insp Rept 70-0135/79-25 on 791127-30 & notice of violation BMITH O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/01/29 2pp
- --8004210216 Notice of violation from insp on 791127-30 * Region 1. Philadelphia. Office of the Director 80/01/28 2pp
- --8004210222 IE Insp Rept 70-0135/79-25 on 791127-30 Noncompliance noted failure to follow procedures re storage & labeling of GNM containers & to maintain chlorine content of CPVC pipes CROCKER,H H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch ROTH,J Region 1, Philadelphia, Office of the Director 90/01/29 11pp
- 8004270061 Advises that use of Hodel HA-10 will be discontinued & company will not renew Certificate of Compliance 4824 AUSTIN.M A Babcock & Wilcox Co., Nuclear Material Div 80/03/25 lp
- 8004160027 Notifies that Source Matls License SMB-502 is terminated Activities authorized under license were incorporated into Source Matls License SNM-145 PAGE.R 0 Uranium Fuel Licensing Branch 80/03/27 lp

DOCKET 70-0143 NUCLEAR FUEL GERVICES, INC

- 80042200B1 Informs that vender will revise 770415 Fundamental Nuclear Control Plan.Section 1 O.Ravision 7.to include duties & responsibilities in Attachments 1,11.III & IV Attachments withheld (ref 10CFR2 770)
 HINBLEY.K D Nuclear Fuel Services, Inc (subs of Oetty Gil Co) 80/01/15 ip
- 8004300089 Forwards upgrading measurement sys change to fundamental nuclear mati control plan. Section 3. Revision 9 Change withheld (ref 10CFR2 790)
 HENSLEY. R D Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)
 80/01/17 1p
- 8004180482 Forwards supplemental info re iE Insp Rept 70-0143/79-40, Item C Revised corrective action health & safety procedure for contamination control, NFB-0H-1. Revision 1, will be revised by 800131 re requirement for survey of hands. MANBER, W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) 80/01/23 2pp
- 8004180143 Responds to 1E Insp Rept 70-0143/79-47 on 800107 No proprietary info MANBER.W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/01/24 ip
- 8004220133 Requests temporary amend to License SNM-124 to permit discharges to unlined ponds until 800831 Continuance required while storage facility is being designed & instelled Administrative fee encl MICHEL.C J Nuclear Fuel Services. Inc (subs of Getty Gil Co) 80/02/01 19
- 8004040037 Ack receipt of 800125 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-0143/79-46 KENNA.W B Region 2. Atlanta. Safeguards Branch 80/02/08 ip
- --8004040041 Responds to NRC 800104 ltr re violations noted in IE Insp Rept 70-0143/79-46 Corrective actions withheld (ref 10CFR2 790) MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/01/25. ip
- --8004040044 Forwards IE Insp Rept 70-0143/79-46 on 791126-30 & notice of violation withheld (ref 10CFR2 790) KENNA, W B Region 2. Atlanta. Safeguards Branch 80/01/04 2pp

- --8004040047 IF Inso Rept *0 0143/77~46 on 791126-30 Noncompliance noted person not employed by licensee was improperly escorted in protected area Detail: withheld (ref 100FR2 790) PERNY,C D. CHRISTOFFER,G. Region 2 Atlanta, Office of the Director TOBIN,N J. Region 2. Atlanta, Safeguards Branch 80/01/03
- 8004100538 Requests undertaking study of facility // fuel making process utilized to identify mafl control // accountability improvements which could be implemented w/o degrading quality of product as rollowup to INRC 800121 order AMEARNE. J F Commission 80/02/20 2pp
- 8004070422 Forwards Revision 17 to physical protection plan Fees not applicable Revision withheld (rev 10CFR2 790) INCHEL, C J Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/02/25 1p
- 8004300003 Forwards "Erfluent Monitoring Rept." Jul-Dec 1979 MICHEL.C J Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/02/26 ip
- --800430024 "Ff+luent Monstoring Pept," Jul-Dec 1979
 * Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/02/26
 ip
- BOO4070046 Ack receipt or BOO211 ltr informing NRC of steps taken to correct violations noted in IE insp Ropt 70-0143/79-44 LONG.F J Region 2. Atlanta, Office of the Director BO/03/03 ip
- --B004070049 Responds to NRC 800123 ltr re violations in IE Insp Rept 70-0143/79-44 Corrective actions withheld (ref 10CFR2 790) MANSER,W C Nuclear fue) Services, Inc (subs of Getty Oil Co) 80/02/11 lp
- --8004070054 Forwards 1E Insp Rept 70-0143/79-44 on 790918-1130 & notice of violation Notice of violation withheld (ref 10CFR2,790)
 KENNA,W B Region 2, Atlanta, Safeguards Branch 80/01/23 2pp
- --B004070059 IE Insp Rept 70-0143/79-44 on 790918-1130 Noncompliance noted failure to measure all SNA at time of physical inventory & failure to maintain identity & quality records Details withheld (ref 10CFR2 790) OILLESPIE.F P Region 2. Atlanta. Safeguards Branch 80/01/23 1a
- BOO4140448 Provides Subcommittem on Nuclear Regulation U/response to 791101 inquiry re sarequards adequacy NRC insp plans for NFS Erwin investigation encl AHEARKE.J F Commission BO/03/05 33pp
- ----B004140469 Forwards questions re safeguards adequacy includes math accounting sys.physical protection sys.? specific responses to facility inventory differences

 HART, G Senate, Environment ? Public Horks 79/11/01 7pp
- BOO4180213 Forwards supplemental info re operating criteria for U hexaficuride scrubber requested during D Joy BO0225 visit Details withheld (ref 10CFR2 770) HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty D:1 Co) BO/03/ii lp
- 8004220219 Forwards request for amend to License SNM-124 Encl withheld (ref 10CFR2 790) Administrative amend fee also encl HENGLEY,K D Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/03/il 1p
- BOO4040113 Forwards IE Insp Rept 70-0143/80-02 on 800115-0207 No noncompliance noted KENNA, W B Region 2, Atlanta, Safeguards Branch 80/03/12 2pp
- --8004040117 IE Insp Rept 70-0143/80-02 on 800115-0207 No noncompliance noted Major areas inspected facility organization & operation, mgt of matis control, storage & internal control Details withheld (ref 10CFR2 790)
 OILLEEPIE: F P Region 2. Atlanta, Safeguards Branch MODRE, D.E., CLAY, E.L. Region 2. Atlanta, Office of the Director 80/03/10
- 8004090232 Ack receipt of 800304 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 70-0143/79-36 & 70-0143/79-37 KENNAW B Region 2. Atlanta. Safeguards Branch 80/03/13 ip
- --B004070235 Responds to NRC 791005 ltr w/add1 info re violations noted in IE Insp Repts 70-0143/79-36 & 70-0143/79-37 Corrective actions withheld (ref 10CFR2 790)
 MANSER.W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
 B0/03/04 1p

- COSADJOTO Prescribe to the Tripus line re violations noted in IE insp. Repts 10 (144/16-75) 10 UTWO/TO TV Corrective actions withheld intel 10-FP2 100 PROSERVE Historical Services Inc. (subs. of Getty Dil Co.) 79/10/25 1p.
- COD40 rC.40 Entuaris It Irap Repts 70-0143/79-36 & 70-0143/79-37 on 790710-11 / notice or i lation Notice of violation withheld feet 10178/ 770)
 PERMAN B Region 2 Arlanta Safeguards Branch 79/10/05 2pp
- 8004090244 It Insp Repris TO-0143/79-36 & 70-0143/79-37 on 790910-14 Noncomplian a noted relibration to establish NDA procedures Datails withfeld (rev. ID: FRZ 790) GILLESPIE F.P. CLAr. (L. Region 2, Atlanta, Safeguards Branch 79/10/02 1p
- 9064070351 Notifies that vendon 800222 submittal re operating criteria for U herarluoride scruto-r is acceptable. & that NRC is revising License Conditions 2 24 1-A.2 24 5-A. 2 24 6-A 1 3 2 Encls withheld (ref 1006R2 790) PARTLOW, J G. Material Control Licensing Branch 80/03/14 2pp
- 8C04210352 FOIA request for all documents re facility from 800117 to date COCHEAN, T B Matural Resources December Council 80/03/14 ip
- 8004100259 Notice or appearance in proceeding Certificate of Svc and WEISS.E R Matural Resources Devense Council WEISS.E R Sheldon. Marmon i Weiss 80/03/18 Zop
- BOON070419 Responds to RNU311 request for esception from 10CFR70 5B(e) requirements re small U herafluoride receipt Notifies of issuance of license condition, errective immediately, to amend MPP-1 to License SNM-124 PARTLOW U G Material Control Licensing Branch BO/03/19 1p
- E004080565 Advises that License SNM-124.Condition 49 is amended, per 800201 application Amend 4 limits use of lined ponds to discharges from waste water treatment facilities PAGE/R G Uranium Fuel Licensing Branch 80/03/19 ip
- ---B0040B0570 Safety evaluation supporting Amend 4 to License SNM-124, Condition 49, limiting use of unlined ponds to discharges from waste water treatment racillty DELANEY, J C Urenium Fuel Licensing Branch 80/03/19 2pp
- 8004090356 Forwards IE insp Rept 70-0143/80-03 on 800226-28 No noncompliance noted Details withheld (ref 10CFR2 790) KENNA.W B Region 2. Atlanta, Safeguards Branch 80/03/19 ip
- -- 8004090361 IE Insp Rept 70-0143/60-03 on 800226-28 No noncompliance noted Major areas inspected organization; physical barriers, access controls, detection and 5 festing Details withheld (ref 1005R2 790)
 KENNAU R Region 2. Atlanta, Sareguards Branch TOBIN/U J
 Region 2. Atlanta, Office of the Director 80/03/19 ip
- ≅004240153 Approves Amend 4 to License SNM-124 re continued use of Unlined ponds for discharges from waste water treatment facility PAGE.R G Uranium Fuel Licensing Branch 80/03/19 ip
- --B004240159 Safety evaluation supporting Amend 4 to License SNM-124 DELANEY, J. C., CROW, W. T., Uranium Fuel Licensing Branch 80/03/19
- BOO4210198 Responds to NRC 800229 ltr by advising that no Model 6400 packages are cured to no shipment of package has been made since 780228 MICHELIC J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/03/21 ip
- #004160107 Responds to 800718 ltr transmitting site security plan for low enriched math Request has been classifed as major safeguards amend for license requiring safeguards amend fee WEISS.D J License Fee Management Branch 80/03/31 ip
- ❷○○4240235 Forwards IE Info Notice 80~14. "Safety Suggestions From Employees " No action required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/02 tp
- EACO4210350 Partial response to FOIA request for all documents re facility Forwards documents listed in App A JF Ahearne draft itr to G Hart anti FELTON.J M Division of Rules and Records 80/04/07 13pp

- -8004210357 Afradavit of nJ Whittle re restart of facility operations in accordance w/NRC 500117 decision Facility restart is essential to natl detense WHITTLE:A J Navy.Dept of 80/01/18 3pp
- --8004210359 Arradavit of W Bateman or NF6 Erwin plant shutdown Costs incurred by govt are accumulating at engineous rate as facility remains idle
 BATEMAN, W Energy, Dept of 80/01/18 2pp

DOCKET 70-0190 CATHOLIC UNIV

- 8004070089 Ack receipt of 800226 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 30-00638/80-01, 40-6329/80-01 & 70-0190/80-01 MCCLINTOCK, R O Region 1. Philadelphia, Office of the Director
- --80040/0099 Responds to FRC 800204 ltr re violations noted in IE Insp Rept 30--00538/80--01,40-6329/80--01 & 70-0190/80--01 Corrective actions separate eating space provided for dept of biology & technicians reinstructed re malls rules NUESBE.C J Catholic Univ 80/02/26 2pp
- --8004070104 Forwards IE Insp Repts 30-00638/80-01,40-6329/80-01 & 70-0190/80-01 on 800116 & notice of violation MCCLINTOCK,R Q Region 1. Philadelphia, Office of the Director 80/02/04 200
- --8004070107 Notice of violation from insp on B00116 Noncompliance noted failure to instruct technicians working in lab on procedures for handling radioactive matls Failure to wear protective gloves 3 having food in restricted area e Region 1, Philadelphia, Office of the Director 80/02/04 ip
- DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO
- 8004240028 Discusses 86W 780119 ltr no temporary measures to be taken during phase-out of high enriched U operations Withdraws request ror changes of ten specific pages referenced in ltr Plan will be vept current w/normal processing WILLIAMS.R A Babcock & Wilcox Co , Nuclear Material Div 78/03/06 in
- --8004240046 Forwards revised plan for safeguarding residual ANM during cleanout of enriched U facilities Addresses all areas agreed to at 780721 meeting w/NRC Flow diagram of scrap recovery processes attached Plan withheld WILLIAMS:R A Babcock / Wilcox Co / Nuclear Material Div 78/08/18 2pp
- --8004240073 Forwards projection of expected LEMUF & LEMUF limits for Mar.May & Jul 1978 inventories of high enriched U plant, in response to NRC request Demonstrates need for exception to required LEMUF limit W/o LEMUF projection HILLIAMS,R A Babcock & Wilcox Co , Nuclear Material Div 78/04/10 fp
- --8004240084 Updates NRC 770826 memo re B&W plans to terminate highly enriched U operations at facilites Outlines key points in B&W phase-out schedule Phase-out plan is generally acceptable Parts of schedule withheld (ref 10CFR2 790) SMITH Office of Nuclear Material Safety & Safeguards 77/11/29 3pp
- --8004240095 Evaluates B&W fundamental nuclear matl control plan & proposed changes Plan should be separated into two parts, one for Pu operations & one for low enriched U operations Some plant operations are not described Info withheld THURMAN.D S Material Control Licensing Branch 79/07/30 2pp
- --8004240iiO Discusses 78082i-23 trip to B&W sites to discuss portions of measurement control plan & to clarify activities retermination of high enriched U operations at Apollo site Info withheld including portion of BNL memorandum THURMAN.D S Material Control Licensing Branch. 78/09/11 13pp
- --8004240114 Forwards notes re possible strike, in response to request In event of strike.NRC would have forwarded license condition to formalize provisions for strike period, W/o encl
 MCCORKLE. Q W Physical Security Licensing Branch 79/01/15 ip
- --8004240127 Provides followup info to J Partiow 780104 notes re possible strike No hostility exists between mgt & labor Inventory of SNM at facilities is being reduced to absolute min All processing operations will cease
 MCCDRKLE, G Physical Security Licensing Branch 79/01/05 2pp.

- --8004240137 Provides addl info re possible strike All facilities will be shut down All accessble highly enriched U at facilities will be moved to Leechburg vault PARTLOWJ Material Control Licensing Branch 79/01/04 ip
- --8004240150 Notifies Commission of status of termination of high enriched U operations Only wet 3 dry scrap recovery at Apoilo & cleanup/dismantling activites at Leechburg have not been shutdown Info withheld (ref 10CFR2 790) SMITH.C V Office of Nuclear Material Safety & Safeguards SECY-78-322 78/06/16 2pp
- --8004240170 Discusses decommissioning plans for facilities B&W will replace proprietary version of App I w/nonproprietary version All proprietary data changed to nonproprietary form Addi info re proprietary classification encl
 LEWIS.JR Babcock & Wilcox Co , Nuclear Material Div 78/05/17
- --8004240177 Decommissioning plan App I, "Cost & Other Commercial Data" * Babcock & Wilcox Co , Nuclear Material Div 78/02/17 16pp
- --8004240183 Forwards Revision 4 to decommissioning plan Plans have been revised to reflect NRC comments during 780215 presentation DZIEHIBZ.J S Babcock & Wilcox Co , Nuclear Material Div 78/02/17 lp
- ---8004240187 Decommissioning plan.Revision 4

 * Babcock & Wilcox Co , Nuclear Material Div 78/02/15 9gp
- B004140006 Summary of 780620 meeting w/NRC to acquaint latest group of NRC consultants w/Pu facility, specifically ventilation sys & fire protection
 ARTHAN.K L. Babcock & Wilcox Co , Nuclear Material Div 78/06/21
- 8004210081 Application to amend Licenses NM-145 & SNM-364 for redefinition of waste mat! AUSTIN.M A Babcock & Wilcox Co., Nuclear Material Div BO/01/16
- --8004210083 Requests fee for amend of Licenses SNM 145 & SNM-364 WEISB.D License Fee Management Branch 80/02/11 1p
- --8004210086 Forwards fee for amend of Licenses SNM 145 & SNM-364 AUSTIN:M A Babcock & Wilcox Co . Nuclear Material Div 80/02/19 ip
- 8004080580 Forwards IE Insp Repts 70-0135/79-23 & 70-0364/79-29 on 791105-800104 No noncompliance noted Rept details withheld (ref 10CFR2 790) MARTIN.W Q Region 1, Philadelphia, Safeguards Branch 80/02/04 2pp
- --8004080733 IE Insp Rept 70-0135/79-23 & 79-0364/79-29 on 791105-800104
 No noncompliance noted Major areas inspected material
 control & accounting physical security, health & industrial
 security Details withheld (ref 10CFRZ 790)
 KUSHNER: W.L. Region i. Philadelphia. Office of the Director
 KUSHNER; W.L. Region i. Philadelphia. Safeguards Branch 80/01/30
- 8004080593 Forwards IE Insp Rept 70-0364/79-17 on 790709-0802 No noncompliance noted Rept details withheld (ref 10CFR2 790) MARTIN-W O Region 1, Philadelphia, Safeguards Branch 80/02/05 2pp
- --80040B0599 IE Insp Rept 70-0364/79-17 on 790709-0802 No noncompliance noted Major areas inspected independent assessment of Parks Township Type II process facility U-235 holdup Details withheld (ref 10CfR2 790) SHAUB, E T, BIBSETT, P H, JOYNER, J, H Region i, Philadelphia, Safeguards Branch 80/01/31 ip
- 8004100550 Forwards IE Insp Repts 70-0135/79-17 & 70-0364/79-25 on 790904-28 No noncompliance noted Sections withheld (ref 10CFR2 790)
 MARTIN.W O Region 1, Philadelphia, Bafeguards Branch 80/02/05
- --8004100855 IE Insp Repts 70-0135/79-17 & 70-0364/79-25 on 790904-28
 No noncompliance noted Major areas inspected metl control & accounting, physical security, health & industrial safety
 Bections withheld (ref 10CR2 790)
 KUBHNER, W. L. Region 1. Philadelphia, Office of the Director
 JOYNER, J. H. Region 1. Philadelphia, Safeguards Branch 80/01/31
 79p

- 8004070211 Forwards IF Insp Repts 70-0135/80-02 & 70-0364/80-02 on 800115-18 No noncompliance noted MARTIN,N G Region 1, Philadelphia, Safeguards Branch 80/02/07 2pg
- --8004070217 IE Insp Repts 70-0135/80-02 % 70-0364/80-02 on 800115-18
 No noncompliance noted Major areas inspected physical
 sacurity, health % safety / environ pingrams
 SMITH.G C Region I. Philadelphia. Office of the Director
 JOYNER.J H Region I. Philadelphia. Safeguards Branch 80/02/01
 4pp
- 8004270105 Application for amend of License SNM-414 to authorize storage of SNM-contaminated waste in designated locations Proposed Revision (to OL enc)
 AUSTINIM A Babcock & Wilcor Co , Nuclear Material Div 80/02/12
- B004100080 Forwards IE lnsp Rept 70-0364/80-05 on 800124-25 No noncompliance noted MARTIN.W O Region 1, Philadelphia, Safeguards Branch 80/02/13 2pp
- ---8004100092 IE Insp Rept 70-0364/80-05 on 800124-25 No noncompliance noted Major areas inspected sampling of mixed oxide pellets & licensee labs JUNNER.J H. DELLA RATTA.A , ZIBULSKY.H Region 1, Philadelphia. Office of the Director 80/02/06 2pp
- 8004180099 Forwards fundamental nuclear math control plan for License SNM-414 W/g encl (ref 10CFR9 5 & 9 12) Plan does not decrease effectiveness of math control b accountability program AUSTIN.M A Babcock & Wilcox Co 80/02/25 ip
- 8004180533 Forwards supplemental info to application by B&W re storage of weste
 AUSTILM A Babcock & Wilcox Co 80/02/26 ip
- 8004070383 Ack receipt of 800205 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0364/79-30

 BMITH, 0 H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/27 ip
- --B0040703BB Responds to NRC B00114 ltr re violations noted in 1E Insp Rept 70-0364/79-30 Corrective actions importance of wearing proper dosimbty re-emphasized & new survey procedures for box gloves begun AUSTIN.M A Babcock & Hilcox Co B0/02/05 3pp
- --8004070392 Forwards IE insp Rept 70-0364/79-30 o violation SMITH.O H Region 1. Philadelphia, Fuel Facilii Safety Branch BO/01/14 2c-

~-£10

- 8004240550 Forwards Amend 7 to License SNM-145 revising Specs 1-4;re arganization & I-5;on Tech Specs & control sys;replacement pages for license & NRC safety evaluation supporting amend PAGE,R G Uranium Fuel Licensing Branch 80/03/06 1p
- BOO4070373 Ack receipt of 800225 ltr informing NRC of steps taken to correct violations noted in 1E Insp. Repts 70-0135/79-27 & 70-0364/79-31 Response to be withheld (ref 100CR2 790) MARTIN, W O Region 1, Philadelphia, Safeguards Branch BO/03/13 lb
- --B004090406 Forwards IE Insp Repts 70-0135/79-27 & 70-0364/79-31 on 791226-B00104 & notice of violation Notice of violation withheld (ref 10CFR2 790) MARTIN.W G Region 1. Philadelphia, Safeguards Branch 80/02/06 2pp
- ---B004090419 IE lnsp Repts 70-0135/79-27 & 70-0364/79-31 on 791226-B00104 Noncompliance noted failure to apply tamper-safing devices to insure integrity of previously made measurements Details withheld (ref 10CFR2 790) JOYNER,J H Region 1, Philadelphia, Safeguards Branch SMITH,O C Region 1, Philadelphia, Office of the Director B0/01/31 1p

- m 4717 1 2
- 41) If carry IF In pinguts C-0135/79-15 / 70-0364/79-19 on think the pinguts of carry III in a carry III in the carry II in the carry III in the carry II in the
- 61341C...14 ** *ic* c* inlation from insplan 790702-0803 * Region 1 Philatelphia Office of the Director Br B0/01/30 1p
- 1-1 241032 7 16 Irap fepts (N-0135/79-15 * 70-0364/79-19 on 770702-0803 famorphiance noted arrays sources containing small amounts of so rice math 258 * supproduct math located in unauthorized areas (erails withheld fref 10,582 790)

 JuffP J H. Megium 1. Philadelphia, Sareguards Branch PUT N-R W. C. Feyion 1. Philadelphia, Orfice of the Director Application.
- © 3046803144 Art receipt of Fru202 ltd informing NRC of steps taken to correct italiation, noted in HE Insp Repts 70-0135/79-16 & 70-0244/77-01 for withheld free 100FRZ /900 MARTIN N G Region 1 Friladelphia Sareguards Branch 80/03/14
- - SGC4CE2347 For Jards IE Insp Repts 70-0135779-16 & 70-0364/79-20 on 790804-31 i notice of violation MARTIN W ... Region 1 Philadelphia, Sateguards Branch 80/02/14
- -- 5004CE0345 Nutice of violation from insp on 790806-31
 Region 1 Philadelphia Office of the Director 80/01/31 1p
- 40040Eu35* IE Insp Rapts 70-0135/79-16 & 70-0364/79-20 on 790806-31 Manco-plaince noted Fu fuel pins transferred from matl balance area to iten control area widelayed completion of documents Portions withheld free footpop of Janker J H Region I Philadelphia. Safeguards Branch MUSH.ER W E Region I. Philadelphia Office of the Director 83/01/33 10pp
- 교육이 418.634 Provides monthly status rept for Mar 1980 re Pu ventilation Upgrading All tack ordered matts received on site Several electrical equipment pieces checked for motor rotation & Control furction Dab-ock & Wilcon Co Nuclear Material Div 80/03/14
- EDG4270Col Advises that use of Model HA-10 will be discontinued & corpany will not renew certificate of Compliance 4824
 ANSTER A Pabcock F Wilcon Co Nuclear Material Div 80/03/25
- EDICHET 70-0371 UNITED NUCLEAR CORP
- 感にひ4150187 Forwards IE Insp Rept 70-0371/79-24 on 791218-21 No PONCOppliance noted
 PARTIN N G Region ! Philadelphia Safeguards Branch 80/02/28 MARTIN N G
- © 00 4090154 Responds to NRC 791114 ltr re reporting requirements for rol 2 accounting program Forwards revised Chapter theid (ref 100FR2 790)
 - United Nuclear Corp , Naval Products Div 80/02/29

- 8004210104 IF Insp Rept 70-03/1/80-02 on 800115-17 No noncompliance noted Major areas inspected shipper-receiver differences, neasurements / statisfical controls records & repts Details neasurements / Statistical controls records of the betaling uithheld (ref 10CFR2 /90) MARTIN M G Region 1, Philadelphia, Safeguards Bianch HOLODY, D J C. C. C. C. C. Region 1, Philadelphia, Office of the Director 80/02/21 ip
- 6004220025 Forwards IC Insp Rept 70-0371/80-02 on 800211-15 No noncompliance noted MARTIN,W G Region L. Philadelphia. Safeguards Pranch 80/03/06
- --8004220041 IE Insp Rept 70-0371/80-02 on 800211-15 No noncompliance OUMEROUM: IE insp kept 70-0371/80-02 on 800211-15 No honcompli noted Majot areas inspected measurement control programs, records 5 repts Details withheld (ref 100FR2 /90) JOYNER, J. H., ZIBULGKY, H., UOLTHER, E. Region 1, Philadelphia, Bafeguards Branch 80/03/03 ip
- 8004210063 Forwards pages of revised emergency plan KIRK, W F United Nuclear Corp , Naval Products Div 80/03/14 ip
- -8004210057 Pages of revised emergency plan KIRK.N F United Nuclear Corp Naval Products Div 80/03/14
- 8004290062 Advises that revised rundamental nuclear math control plan submitted w/600125 for should not be incorporated as condition of license until deficiencies listed in enci are corrected Enc.) withheld (ref IOCFR2 770) Material Control Licensing Branch 80/03/27 1p PARTLOW, J G
- DOCKET 70-0398 COMMERCE, DEPT OF
- 8004070115 Forwards IE Insp Rept 70-0398/80-01 on 800116-18 No noncompliance noted Details withheld (ref 10cFR2 770) MARTIP: N G Region 1. Philadelphia, Safeguards Dranch
- --8004070119 IE Insp Rept 70-0398/80-01 on 800116-18 No noncompliance noted Major areas inspected facility organization & operation, storage & internal control & physical inventory petalls withheld (ref 10CFR2 790)
 SUMMERS, R Region i. Philadelphia, Office of the Director SHAUB, E. MARTIN, W. G. Region 1, Philadelphia, Bafeguards Branch 80/02/04 ip
- DOCKET 70-0572 MONSANTO RESCARCH CORP
- 8004080612 Requests fee for 800312 application for amend to License WEISS, J. D. License Fee Management Branch 80/03/19
- 8004220059 Forwards IE Info Notice 80-14, "Safety Suggestions from Employees "No action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/04
- DOCKET 70-0687 UNION CARBIDE CORP.
- B004180042 Application to amend License SNM-639 VOTH, H Union Carbide Corp 79/12/28 17 1700
- B004020101 Advises that request for amend to License BNM-639.re U recovery from waste products has been additionally classified as requiring safeguards amend Add1 amend fee will WEISS, J.D. License Foe Management Branch 80/03/17 19
- DOCKET 70-0496 GENERAL SERVICES ADMINISTRATION
- 8004180511 Notifies of expired matl/byproduct license Statement required explaining method of disposal of matls, matls involved & to whom matl was shipped within 3 days MCCLINTOCK, R D Region I, Philadelphia, Office of the Director 78/10/04
- DOCKET 70-0734 GENERAL ATOMIC CO
- B004220015 Forwards IE Info Notice B0-14, "Safety Suggestions From Enployees " No action required ENGELNEUR H Region 5, San Francisco, Office of the Director B0/04/02 ip

- DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO
- 8004100423 "Effluent Monitoring & Environ Surveillance Programs Annual Summary,1979 " BROZ,R E General Electric Co NEDD-24780 80/01/31 82pp
- 8004300505 Forwards SAR for GE spent fuel shipping cast Model 700.in support of Certificate of Compliance 5742 Drawings available in Central Files only BRUGGER.R M. Missouri, Univ. of. Columbia. 80/03/20 2pp
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSIGNL V Office of the Executive Director for Operations
- 8004220022 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required ENGELKENIR H. Region 5, San Francisco: Office of the Director 80/04/02 ip

DOCKET 70-0820 UNITED NUCLEAR CORP

- 8004180372 Forwards revision to Section 5 4 of fundamental nuclear metl control plan OREOO,R J United Nuclear Corp , UNC Recovery Systems Div 80/01/17 2pp
- 8004180046 Forwards corrected page of revision to Section 5 4 of fundamental nuclear matl control plan GREGO,R J. United Nuclear Corp., UNG Recovery Systems Div 80/01/21 3pp
- 8004230533 Bubmits response to 800102 ltr concerning procedure used to satisfy License Condition / 8 is waste compaction sys Procedures for waste compaction currently being revised to require spacific mode of operation BOHERS C E United Nuclear Corp , UNC Recovery Systems Div 80/01/24 2pp
- B004170321 Summary of B00129 meeting w/United Nuclear Corp in Silver Spring. Hd re proposed amend to License SNM-777 to authorize mods in procedures for processing of process wastes including wastes stored in onsite lagoons STEVENSON.R L Uranium Fuel Licensing Branch B0/02/12 Rpp
- 8004240160 Requests that deadline for full compliance w/approved emergency plan be extended to May 1980 Fee entl BOMERS.C E United Nuclear Corp., UNC Recovery Bystems Div 80/02/18 2pp
- 8004100026 Forwards IE Insp Rept 70-0820/80-01 on 800129-31 No noncompliance noted MARTIN, N O Region 1, Philadolphia, Safeguards Branch 80/02/19
- --B004100030 IE Insp Rept 70-0820/80-01 on B00129-31 No noncompliance noted Major areas inspected physical inventory & records & repts Details withheld (ref 10CFR2 790)
 COHEN, I: WOLTNER, E Region I, Philadelphia, Office of the Director JUYNER, J H Region I, Philadelphia, Bafeguards Branch B0/02/15 ip
- BOO4220177 Requests NRC guidance re processing & decontamination of lagoons to release limits by B20701 per 790115 Amend 6. Condition 26 to License BNM-777 Unable to meet deadline Possible alternatives are beyond power of facility BOWERS: C E United Nuclear Corp., UNC Recovery Systems Div BO/02/19 ip
- B0041B0020 Forwards modified Sections 5 12 & 6 1 of fundamental nuclear matl control plan clarifying that "book record" includes total facility & subsidiary matl control areas OREOO,R J United Nuclear Corp , UNC Recovery Systems Div 80/03/07 4pp
- B004150300 Informs of issuance of Amend 12 to License GNM-777 changing effective date for instituting emergency plan to B00501 PAGE,R,Q Uranium Fuel Licensing Branch 80/03/17 ip
- --8004150305 Bafety evaluation supporting Amend 12 to SNM-777 changing effective date for instituting emergency plan to 800501. STEVENSON,R L., CRON,W T Uranium Fuel Licensing Branch 80/03/17. 2pp

- B004080072 Discusses deficiencies in math control & accounting program & submits NRC position on appropriate corrective actions
 Insufficient sample control records exist to properly control amount of math going to & coming from lab
 PARTLOW.J G Material Control Licensing Branch B0/03/19 3pp
- 8004150178 Advises that no response received to encl 800220 fee request for change of address for License SNM-777 Requests payment within 15 days W/o encl WEISS.D License Fee Management Branch 80/03/28 ip

DOCKET 70-0824 BABCOCK & WILLOK CO

- B004240236 Forwards replacement pages for License SNM-778 & replacement pages for renewal application re Dec 1978 request for Amend 11 to license OLBENIA F Babrook & Wilcox Co B0/02/28 21pp
- GO04070065 Disapproves primary route for transport of spent reactor fuel & approves alternate route submitted w/791205 ltr Primary route passes through heavily populated areas & does not meet requirements Encl withheld (ref 100FR2 790) MCCORKLE.0 W Physical Security Licensing Branch B0/03/12 2pp
- 8004150182 Ack receipt of 800320 ltr u/fee transmitting protection plan for SNM of low strategic significance Request classified as major safeguards amend for License SNM-778, requiring addl payment WEISS,D License Fee Management Branch 80/03/28 ip
- 8004240227 Forwards IC Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/02

DOCKET 70-0827 THE DEFIANCE COLLEGE

- 8004140007 Advises no response received to enci 800211 fee request for renewal of License SNM-758 Requests payment within 15 days W/o enci
 WEISS,D License Fee Management Branch 80/03/28 ip
- DOCKET 70-0925 CIMMARON FACILITY, KERR-MCGEE CORP
- 8004230138 Forwards IE Insp Repts 70-0925/80-01 & 70-1193/80-01 on 800206-07 & notice of violation DAVIS.A.B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/03/04 2pp
- ---8004230146 Notice of violation from insp on 800206-07

 * Region 3, Chicago, Office of the Director 80/02/28 ip
- --B004230i57 IE Insp Repts 70-0925/80-01 % 70-1193/B0-01 on B00206-07 Noncompliance noted possession of SNM w/enrichment greater than authorized by license FISHER:W L Region 3, Chicago, Fuel Facility & Materials Safety Branch DUBRY,N E Region 3, Chicago, Office of the Director B0/02/28 9pp
- 8004110563 Advises that Ofc of Controller has been notified to initiate proceedings for refunding difference between fee paid & actual manpower expenditures for 790918 request to use facility for bench-scale coal liquefaction development SHELLY, W J License Fee Management Branch 80/03/28 ip
- B004220070 Forwards IE Info Notice B0-14, "Safety Suggestions From Employees" No action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/04

DOCKET 70-0984 PACIFIC NORTHWEST LAB

8004180502 Forwards IE Info Notice 80-14. "Hafety Suggestions From Employees" No action required ENGELKEN, R H Region 5. San Francisco. Office of the Director 80/04/02 Ip

- CONST. 1 OF SHEAR ELECTRIC CO
- r lights entured application for American Each Centificate of Camplia enture for all EU-7 Supporting documentation assaults recent in the American Conformation Energy Products Division (4) Align Conformation (4) Align Conformatio

 - JA1' End Apply its nor he isson 3 to Certificate of Compliance ulr revising from spens / authorized content
 Demand Electric on hear Energy Products Div 80/03/14
- Fundiging Application to amend License SNM-54 to authorize transport of Pritin Models (0-, 1 Pril 7 as described in Mod 23 to App C Tulk-sort A U General Electric Co 74/05/24 10pp
- 174220 27 Futuards IF Info Notice 80-14, "Sarety Suggestions From Englishes to action sequend ENJFLARM R M. Region 9. Jan Francisco, Office of the Director 60704702.
- 1 DOKET 10 THAN ELCATOR UNIO DE
- 2014200213 Informs FRC or upgrading or physical security requirements of univ Changing location of ruel storage area will regult in significant improvements inquires whether license amend DiALIN U Florida Univ of Gainesville 80/03/03 ip
- COCKET 70-1089 PERRISTLVANIA COMMONWEALTH DE
- E054150163 Discusses IE Insp Rept 70-1059/80-01 on 800213 No noncompliance noted Major areas inspected radiation safety & compliance w/Complession rules & regulations MCCLINIOCK R O Region 1. Philadelphia, Office of the Director 87/107/74 10 80/02/26
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC.
- EC04070105 Firwards IE Insp Rept 70-1100/79-12 on 791212-14 No Prontong Forwards in 1939 Rept For House File on Francis Filence noted

 EMITH G H Region 1, Philadelphia, Fuel Facility & Haterials Safety

 Branch 80/02/07 2pp
- -- 2004070112 IF Insp Rept 70-1100/79-12, on 791212-14 No noncompliance noted Pajor areas inspected energency planning, environ manstoring & confirmatory neasuraments, including equipment insp & raint, training, five protection & radwaste mpt IEEC.16 M. Edwild DEON DE Pegion 1. Philadelphia, Office of the Director EDREG R J. Region 1. Philadelphia, Fyel Facility & Materials Safety Branch 80/02/01 Bpp
- 8304070203 Forwards IE Insp Rept 70-1100/79-11 on 791211-13 No noncompliance noted Details withheld (ref 10CFR2 790) MARTIN N G Region I Philadelphia, Safeguards Branch 80/02/07
- -- GOD4070207 JE Juse Regt 70-1100/77-11 on 791211-13 No noncompliance noted Major areas inspected records, repts & physical inventory procedures Details withheld (ref 10CFR2 790) CDMEN I. SMITH G. Region I. Philadelphia. Office of the Director JOMER, J. H. Region I. Philadelphia. Safeguards Branch. B0/01/3; in
- BOO4020153 Bafety evaluation re C-E 791221 application for limitation of mar enrichment of U to less than 207 U-235 C-E is presently authorized to possess U-235 of any enrichment Recommends issuance of license amend METZLACH, W , CRUM, W Y Uransum Fuel Licensing Branch 80/02/25
- BOO4240169 Requests that sampling data be used to set higher quarterly action L reporting level of JuC: which will allow operation of fuel labrication facility under normal conditions & Lichiemperger C-E Power Systems 80/02/28 ip
- 8004210027 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted BMITH 6 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 1p

- --8004210034 Waste Packaging Rept 77-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination & package external feature requirements PDTTER. J. P. PEERV. M. W. WOODRUFF. R. L. Region I, Philadelphia. Fuel Facility & Materials Safety Branch 80/01/10 78p
- 8004210126 Ack receipt of 800300 ltr informing NRC of steps taken to correct violations noted in 15 lnsp Rept 70-1100/79-09 SMITH-Q Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 80/03/16 ip
- --8004210130 Responds to NRC 800214 ltrire violations noted in 1E insp Rept 70-1100/79-09 Corrective actions signs replaced & personnel reminded of importance of keeping all work stations posted w/clear & legible signs LICHTERRECEPTH C-E Power Systems 80/03/03 2pp
- --8004210133 Forwards Page 3 of App A to 791113 ltr rp 1E Inop Rept 70-1100/79-09 Requests written statement in reply to 1tem E within 20 days SMITH.0 H Region i. Philadelphia, Fuel Facility & Platerials Safety Branch 80/02/14 2pp
- --8004210135 Act receipt of 771205 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1100/19-09 SMITH, 6 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/01 lp
- --G09421013B Responds to NRC 791113 itr re violations noted in 1E insp.
 Rept 70-1100/79-09 Corrective actions formal procedure
 written for knockdown operation including safety limits &
 controls nacessary to assure protection
 LICHTENDERGER.H. C-E Power Bystems 79/12/05 3pp
- ~-8004210139 Forwards IE Insp Rept 70-1100/79-09 on 791009-12 & notice of Original Control of the Control of t
- ~-8004210143 Notice of violation from insp on 791009-12 * Region 1, Philadelphia, Office of the Director 79/11/09 3pp
- --8004210145 IE insp Rept 70-1100/77-09 on 791009-12 Noncompliance noted inadequate or improper posting of work station failure to teep stored rod bux covered when not attended & failure to supply procedures
 ROTH.J Region I. Philadelphia. Office of the Director
 CROCKER, H W Region I. Philadelphia. Fuel Facility & Materials
 Safety Branch 79/11/09 16pp

DOCKET 70-1113 GENERAL ELECTRIC CO

- 800415005B Forwards notice of teccipt of applications t intent to prepare environ assessments re amends of License BMM-1077 PAGE.R G Uranium Fuel Licensing Branch 80/02/13 ip.
- --8004130068 Notice of receipt of applications & intent to prepare environ assessments re amends of License SNM-1097 PAGE, R O Uransum Fuel Licensing Branch B0/02/13, 3pp
- B004230143 Discusses concern raised during 800121-25 inspire presence of area manager qualification requirements in Section 4 i of license App A Qualifications are difficult to interpret. Hill propose changes to manager qualifications. KAPLAN.A L. General Electric Co., Nuclear Energy Products Div 80/00/25 2pp
- 8004180121 Forwards "Bemiannual Effluent Rept for Jul-Dec 1979 " KAPLAN.A L General Electric Co , Nuclear Energy Products Div 80/02/29 jp
- --8004180124 "Semiannual Effluent Rept for Jul-Dec 1979 "
 KAPLAN, A L General Electric Co . Nuclear Energy Products Div.
- 8004140075 Recommends approval of GE 800117 Application for authority to obtain 5 use up to 1 q U exidencentaining U enriched up to 93% in U-235, in form of NBS std ref met!

 STEVENSON, R L Uranium Recovery Licensing Branch 80/03/05 2pp
- 8004150289 Informs of issuance of Amend 12 to License 8NM-1079 adding Conditions 6 F.7 F & 8 F PAGE.R C Uranium Fuel Licensing Branch 80/03/05 1p

- 8004090149 Requests Amend S-18 of License SNM-1097 authorizing GE to retain certain scrap matis in excess of one yr period, through 800509 Attached details withheld (ref 10CFR2 790) Fee entl KAPLAN, A L G B0/03/07 2pp General Electric Co , Nuclear Energy Products Div
- 8004100593 Bubmits contract costs incurred & man-h used in reviewing 800117 application for amend of License SNM-1097 BTEVENBON, R L . PAGE, R O Uranium Fuel Licensing Branch 80/03/12
- BOO4100095 Informs vendor of fee overpayment re Amend 12 to SNM-1097 Refund will be forwarded MILLER, W.O. License Fee Management Branch 80/03/25 1p
- 8004210155 Ack receipt of 800227 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-1113/80-01 KENNA.H B Region 2, Atlanta. Safeguards Branch 80/03/28 ip
- --8004210162 Responds to NRC B00205 ltr re violations noted in IE Insp Rept 70-1113/B0-01 Corrective actions operators & foremen responsible for transporting storing & using U hexafluoride cylinders reinstricted in handling procedures KAPLAN,A L. General Electric Co B0/02/29 3pp
- --8004210167 Forwards IE Insp Rept 70-1113/80-01 on 800121-25 & notice of KENNA, W B Region 2, Atlanta, Bafeguards Branch 80/02/05 2pp
- --8004210171 Notice of violation from insp on 800121-25 * Region 2, Atlanta, Office of the Director 80/0 80/02/05 lp
- -8004210176 IE Insp Rept 70-1113/80-01 on B00121-25 Noncompliance noted ten 2 5 ton U hexafluoride cylinders discovered lying in driveway adjacent to raised dock Five cylinders were full, w/no vaive protectors installed KAHLE.J B . BTEELE, P W Region 2, Atlanta, Safeguards Branch B0/02/04 6pp
- 8004240233 Forwards IE Info Notice 80-14. "Safety Buggestions From Employees" No action required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/02

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

- 8004220054 Forwards IE Insp Rept /0-1143/79-09 on 790518 No noncompliance noted MARTIN,W Q Region 1, Philadelphia, Safeguards Branch 79/11/14
- -- 000422006B IE Insp Rept 70-1143//9-09 on 7905iB No noncompliance noted Major areas inspected licenses plans for coping w/strikes Dotails withheld (ref 100FR2 790) JCHMERJ H. KYBINER, W.L. Region 1, Philadelphia, Safeguards Branch 79/11/07, 1p
- B004210084 Forwards IC Insp Rept 70-1143/80-02 on B00204-05 No ncompliance noted 1714:0 H. Region i, Philadelphia, Fuel Facility & Materials Safety -anch 80/02/28 2pp Branch
- -8004210089 IE Insp Rept 70-1143/80-02 on 800204-05 No noncompliance noted Major areas inspected exposure info.survey data: chronology events & regulatory requirements CRUCKER, W. Region I, Philadelphia, Fuel Facility & Materials Safety Branch CLEMON.P., Region I, Philadelphia, Office of the Director 80/02/25 5pp
- 8004220379 Forwards Waste Packaging Insp Rept 79-07A No noncompliance BWITH'O H notes. BMITH.Q H Region (, Philadelphia, Fuel Facility & Materials Safety Branch. 80/03/05 2pp
- --B004220402 Waste Packaging lnsp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected review of shipping papers radiation survey of vehicles contamination surveys a radiation level surveys of packages POTTER, J P. PEERY, W W. WOODRUFF, R L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch B0/01/18 7pp
- B004030006 Forwards feeder rept for Region 5 coverage of transportation insp of BBNM from Westinghouse.Cheswich.PA to Exxon Nuclear Co.Richiand Wal. B00219-21.W/o enci NDRDERHAUQ.L R Region 5, San Francisco, Safaguards Branch NORDERHAUG, L R 80/03/11 1p.

- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP
- 8004040080 Forwards IF Insp Rept 70-1151/80-02 on 800124-25 & notice Region 2, Atlanta, Sareguards Branch 80/02/08 2pp
- --8004040093 Notice of violation from insp on 800124-25
 * Region 2, Atlanta, Office of the Director 80/0
- --8004040097 IE Insp Rept 70-1151 on 800124-25 Noncompliance noted low level radioactive mat1 shipped in improperly sealed packages packages CORYELL.G P Region 2. Atlanta, Office of the Director KAHLE.J B Region 2. Atlanta, Safeguards Branch 80/02/08
- 8004080049 Submits reptile release or radionuclides to unrestricted areas Jui-Dec 1979 Gaseous results were obtained from point source analysis of stack gas effluent Liquid values were obtained by compositing proportional sample GOODWIN.W.L. Westinghouse Electric Corp. 80/02/14 2pp
- 8004020090 Ack receipt of 800129 ltr re const & use of bldg & equipment for water delonization Environ impact of proposed action is covered by existing environ rept Amend to License SNM-1107 not required CROW, W.T. Uranium Fuel Licensing Branch 80/03/07 ip
- B004140104 Responds to B00129 itr re const 2 use of bldg & equipment for water deionization Environ impact of proposed action, which does not involve radioactive math is covered under stisting environ rept License amend unnecessary CROM, W T Uranium Fuel Licensing Branch 80/03/07 ip
- 8004110015 Ack receipt of IE Insp Rept 70-1151/80-03 on 800204-08 Expresses appreciation for radiation protection program ODDDWIN. If L. Hestinghouse Electric Corp. 80/03/12 1p
- --8004110018 Forwards IE lnsp Rept 70-1151/80-03 on 800204-08 STOHR:J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/02/26 2pp
- --8004110027 IE Insp 70-1;51/80-03 on 800204-08 No noncompliance noted Major areas inspected radiation protection instrumentation, external \$\frac{1}{2}\$ internal exposure control, posting \$\frac{1}{2}\$ labeling notifications \$\frac{1}{2}\$ repts \$\frac{1}{2}\$ installation of new ventilation sys TROUP.0 L. Region 2, Atlanta, \$Office of the Director GIBSON, A Fraction 2, Atlanta, Fuel Focility \$\frac{1}{2}\$ Materials Safety Branch 80/02/25 \$\frac{1}{2}\$\$
- 8004100456 Ack receipt of 800306 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1151/80-01 Awaiting rept on inventory difference KENNA, W B Region 2. Atlanta, Office of the Director 80/03/14
- --B004i00463 Responds to NRC 800213 ltr re violation noted in IE Insp Rept 70-[151/80-01 Corrective actions withheld (ref 10CFR2 770) D'AMOREM , GOODWIN.W L Westinghouse Electric Corp 80/03/06
- --8004100470 Forwards lE insp Rept 70-1151/80-01 on 800114-18 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNA, W B Region 2, Atlanta, Safeguards Branch 80/02/13 2pp
- --B0041004B2 IE Insp Rept /0-ii51/80-01 on 800114-18 Noncompliance noted incorrect calculation re limit of error associated W/inventory difference Details withheld (ref 10CFR2 790) OILLESPIE, F. P. Region 2, Atlanta, Safeguards Branch JONES, D. W. Region 2, Atlanta, Office of the Director B0/02/13 ip
- 8004240237 Forwards IE Info Notics 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP
- 8004230138 Forwards lE Insp Repts 70-0725/80-01 % 70-1193/80-01 on 800206-07 % notice of violation DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/04 2pp
- ---8004230144 Notice of violation from insp on 800206-07

 * Region 3. Chicago, Office of the Director 80/0 80/02/28 1p

- -50042 with it into Paper 70-0-25/60-01 ; 70-1193/80-01 on 800204-07 honcompliante matel passession of SMM w/emichment greater than authorizer ty license FISHER I't Region 1 history Fuel Facility & Materials Safety Bean b Dubber I'f Ecgion 3 Philosoph Office of the Director 83/02/28 7pp
- B004220973 Forwards IE Into Notice 80-14 Sarety Suggestions From Employees No action required AEFFLER. J. G. Region 3. Philago Office of the Director B0/04/04 to
- DOCKEY 70-1201 OF 6 CONVERSION FAUILITY, BABCOCK & WILCOX CO
- 8004240078 Discusses 3/W /80115 ltm re temporary measures to be taken during phase-out or high enriched U operations Withdraus request for changes of ten specific pages referenced in ltm Plan will be kept Current w/normal processing WILLIAMS R A Babcock & Wilson Co . Nuclear Material Div 78/03/06
- --8004240170 Discusses do comissioning plans for facilities BAW uill replace proprietary version or App I w/nonproprietary version All proprietary data changed to nonproprietary form Addl into re proprietary classification encl LEWIS.J R Babcoly & Wilco, Co . Nuclear Material Div 78/05/17
 - BC04240177 Decommissioning plan App I. "Cost & Other Commercial Data "
 Babcock & Milcol Co , Nuclear Material Div 78/02/17 16pp
 - --8004240183 Forwards Revision 4 to decommissioning plan Plans have been revised to reflect NRC comments during 780215 presentation DZIENISI J S Habcock & Wilcox Co , Nuclear Material Div 78/02/17 ip
 - --8004240187 Decommissioning plan.Revision 4 * Babcock & Wilcoi Co , Nuclear Material Div 78/02/15 9pp
 - BOO4010157 Amend Application 79-3 for License SNM-1168 Revision index & revised license pages encl ZEFF,D N Babcock & Wilcox Co BO/01/09 35pp
 - BOO4220169 Requests extension of due date for booking SNM physical inventory results Added load at analytical lab caused delay Preliminary results indicate difference within regulatory limits
 ZEFF.D W Babcock & Wilcos Co BO/02/05 1p
 - 8004090296 Forwards IF Insp Rept 70-1201,80-01 on 800114-18 No noncompliance noted STORR JP Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/21 2pp
 - --8004090302 IE Insp Rept 70-1201/80-01 on 800114-18 No noncompliance noted Major areas inspected radioactive airborne effluents, liquid effluents, procedures, lab instruments & effluent repts
 GIBSON.A F Region 2. Atlanta Fuel Facility & Materials Safety Branch MILLSAP, H J Region 2. Atlanta, Office of the Director 80/02/15
 - 8004280237 Forwards "Effluent Monstoring Results, Jul-Dec 1979 "
 ZEFF, D W Babcock & Hilcox Co , Naval Nuclear Fuel Div 80/02/28
 - --8004280243 "Effluent Monitoring Results, Jul-Dec 1979 "
 ZEFF, D W Babcock & Wilcor Co . Naval Nuclear Fuel Div 80/02/28
- 8004040012 Act receipt of 800307 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1201/80-02 KENNA,W B Region 2. Atlanta, Safeguards Branch 80/03/13 1p
- --8004040015 Responds to ARC 800225 ltr re violations noted in IE Insp Rept 70-1201/80-02 Corrective actions withheld (ref 10CFR2 790) REFF, D H Babcock & Wilcox Co 80/03/07 1p
- ~-8004040018 Forwards IE Insp Rept 70-1201/80-02 on 800109-11 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNA,W B Region 2, Atlanta, Safeguards Branch 80/02/25 2pp

- --8004040021 IF Insp Rept 70-1201/80-02 on 800109-11 Noncompliance noted failure to maintain procedures for tamper-safing Details withheld (ref 10CFR2 /90) GILLESPIE:FF Region 2. Atlanta, Safeguards Branch JONES, D.W., TODO, Q.A. Region 2. Atlanta, Office of the Director 80/02/25
- 8004240231 Forwards If Info Notice 80-14, "Safety Suggestions From Employees " No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 90/04/02 to
- 8004290048 Re-ponds to 800401 telecopy requesting exemption from requirement of completing Form NRC-741 for transfer of empty U oxide pouder cans Request granted * license amended Telecopy contains info of type specified in 10CFR2 790 PARTLOW, J G Material Control & Accountability Development Branch 80/04/02 1p

DOCKET 70~1222 MISSOURI, UNIV OF

8004300505 Forwards SAR for GE spent ruel shipping cask Model 700, in support of Certificate of Compliance 5942 Drawings available in Central Files only BRUGGER,R M Missouri, Univ of, Columbia 80/03/20 Epp

DOCKET 70-1227 ERIE HINING CO

8004180072 Forwards revised responses to Question 8 of community & questions, re License Amend Application 18, raised in NRC 800124 ltr ESTEY.H P Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/03/12 14pp

DOCKET 70-1251 ALBRIGHT COLLEGE

- 8004160098 Ack receipt of 800313 ltr informing NRC of stops taken to correct violations noted in IE lnsp Rept 70-1251/80-01 CRCCKER.H W Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/24 Ip
- --8004140151 Responds to NRC 800227 ltr re violations noted in 1E Insp Rept 70-1251/80-01 Disputes noncompliance Supportive documentation encl KREMSER T R Albright Collège 80/03/13 App
- --8004160156 Discusses It Insp Rept 70-1251/80-01 & forwards notice of violation MCCLINTOCK, R O Region 1. Philadelphia, Office of the Director 80/02/27 2pp
- --8004160159 Notice of violation from insp on 800220 Noncompliance noted records of leak tests conducted on Pu-beryllium neutron sources were not available for insp
 * Region 1. Philadelphia, Office of the Director 80/02/27 ip
- DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, CXXON NUCLEAR CD , INC
- BOO4150119 Advises of issuance of Amend 21 to License BNM-1227 re temporary increase in Pu possession limit CROM.W T Uranium Fuel Licensing Bransh 79/12/10 ip
- --B004150118 Safety evaluation re 791022 amend application for License SNM-1227, temporarily increasing Pu possession limit Recommends approval No EIA, negative doclaration or environ appraisal needed CROW, N T . STEVENSON, R L Uranium Fuel Licensing Branch 79/12/10 2pp
- 8004090370 Forwards response to 800124 comments & quostions raised by NRC on License Amend Application 18
 EBTEY,H P Exxon Nuclear Co , Inc (subs of Exxon Corp)
 B0/02/21 11pp
- --8004070378 Proposed Amend 18 to Licenso BNM-1227 Sections I-5, 2 2 4 & II-4 & I3 re-concentration control * Exton Nuclear Co., Inc. (subs. of Exton Corp.) 79/12/19 6pp
- 8004140458 Forwards response to NRC 791208 ltr re questions raised about renewal of License SNM-1227 Respective pages of encl application have been amended & several new organization changes (ncorporated ESTEY, H P Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/02/22 50pp

- --8004140464 Revised application for amond of License SNM-1227 incorporating organization changes Replaces Apr 1979 version in entirity *_Exxon Nuclear Co. Inc. (subs. of Exxon Corp.) 79/04/30 250pρ
- 8004020238 Forwards IE Insp Rept 70-1257/80-03 on 800221-24 No noncompliance noted Encl withheld (ref 10CFR2 790) NORDERHAUD, L R Region 5. San Francisco, Safeguards Branch 01150108
- B004030006 Forwards feeder rept for Region 5 coverage of transportation insp of SSNM from Westinghouse Cheswich PA to Exxon Nuclear Co.Richland WA. 800217-21 W/o encl NORDERHAUG.L R Region 5, San Francisco, Bafeguards Branch
- 8004100066 Forwards Endorsement 19 to MAELU Policy MF-94 for License SNM-1227 NILSON:R Exxon Nuclear Co. Inc (subs of Exxon Corp.) 80/03/11
- 8004090102 Forwards corrections to Revision 1 renewal application for License SNM-1227 Site plan Figure D-3-2 & Attachment P updated ESTEY.HP Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/03/13 10
- --B00409010B Corrections to Revision 1 of renewal application for License BNM-1227 Corrections include editorial changes addition of scale to site plan Figure D-3-2 & incorporation of add1 refinfo Attachment P
 - Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/03/13 6pp
- --8004090112 Bubmits update of descriptive info for Horn Rapids fuel fabrication plant Includes info re ofc bldg complex addition.new process chemical waste storage lagoon & maint facility Diagrams oncl # Exxon Nuclear Co . Inc (subs of Exxon Corp) 79/11/12 Spp
- 8004080609 Advises that 791119 request for amend to authorize operation of three add1 facilities has been add1thonally classified as safeguards amend & requires add1 fee MEISS.J D License Fee Management Branch 80/03/19 ip
- 8004180443 Forwards IE Insp Rept 70-1257/80-02 on 800127-31 & notice of violation Notice of violation withheld (ref 10CFR2 770)
 NORDERHAUGLE Region 5, San Francisco, Safeguards Branch BD/03/19
- 8004100073 Forwards Endorsement 43 to NELIA Policy NF-193 for License SNM-1227 NILSON,R Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 80/03/20
- 8004100105 Advises that License Condition 2 7 2 has been added to Amend MPP-2 to License SNM-1227.per 800303 request for exemption re-requirements to perform receivers measurement on some fuel rods Util 1tr to be withheld (ref 10CFR2 790) PARTLOW.JQ Material Control Licensing Branch 80/03/24 1p
- 8004110540 Advises that Ofc of Controller has been notified to refund difference between foe paid for 791108 & 14 applications for amend to License SNN-1227 & actual review fee based on manpower expenditures

 MILLER.W O License Fee Management Branch 80/03/28 ip
- 8004160018 Notifies that Div of Fuel Cycle & Matl Bafety has been authorized to complete review of now operations prior to startup Includes laundry facility, waste U recovery facility & addl conversion capacity PARTLOW.J O Material Control Licensing Branch 80/03/31 ip
- 8004220013 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required ENGELMEN.R.H Region 5. San Francisco. Office of the Director 80/04/02 1p
- DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO
- 8004240247 Application for amend of Mat1/Byproduct License SNM-1245, authorizing deletion of references to Series A revisions of NEDD-21324 & substitution of references to Series C revisions.

 DAWSON, D.M. General Electric Co. 60/01/23 Spp.
- --8004240277 Forwards fee for amend of License SNM-1268 DAWSON, D. M. General Electric Co. 80/03/12 1p

- --8004240488 Act rereipt of EGO124 ltr re ree for amend to License SMK-1265 Requests mino: safety 2 environ amend fee Forwards NEDO-21326 Vols (V.2 "Consolidated SAR" WEIS9.D License Fee Hanagement Branch 80/03/04 jp
- --8004240274 "Consolidated SAR" Vols 1 t 2 * General Electric Co NFDO-21924 80701/31 11pp
- G004150127 Opposes choice of Moiris. IL as dumping site for nuclear waste Suggests that waste disposal be part of nuclear plant site JAK.M Affiliation Unknown 80/02/20 2pp
- B004180133 Submits info confirming 800219 telcon LI/J Kesman Describes rail attachment for cash crane & attachment for basin crane DAMSON.D M General Electric Co., Nuclear Energy Products Div 80/02/27 2pp
- 8004140078 Forwards GE 800247 ltl re info for ORNL re crane details ROONEY,M A Mayer, Brown № Platt 80/03/03 ip
- --8004140082 Confirms 18fo futnished to ORNL re crane details Cask crane rail is US Steel (35% rail & 1s in contact w/inverted 18-inch steel thannel Busin crane tail is 40% rail & is clipped to top of contrete wall w/steel rail base clips DA/SDM:D M Genetal Electric Co , Nuclear Energy Products Div 80/02/27 4pp
- 8004090040 Ack receipt of 791219 ltr re changes to physical security plan Changes acceptable Encl to ltr withheld (ref 10CFR2 790) MCCORKLEO W Physical Security Licensing Branch 80/03/07 1p
- 8004080679 Requests addition of E.J Guigley to svc list GUIGLEY, E.J. Affiliation Unknown 80/03/12 ip
- BOD4140060 Forwards GL BOO311 / 12 ltrs re NEDM-20682, "Sabotage Analysis for Fuel Storage at Moiris," 5 amend fee ROONEY M A Hayer, Brown & Platt B0/03/17 Ip
- --8004140070 forwards reprint of NEDM-20682. "Sabotage Analysis for Fuel Storage at Morris." in response to NRC request Reprint contains errata previously submitted as separate documents on 741217 W/o encl ROGERS, H A G. 80/03/11 2pp General Flectice Co , Nuclear Energy Products Div
- -8004140073 Forwards GC Check 866881 to be applied to amend of Matls License SNM-1245 as requested in GF 800123 ltr Ack receipt of GE Check 858832 (I/o encl DAMSON.D M General Flectric Co., Nuclear Fnergy Products Div 80/03/12 2pp

33

_

Ę

- BOO421014** Second set in any low conventions Unges ASUB to vacate BOO225 religious denting tark or it motion to stay proceeding, pending cour logation in regulations to away from storage reactor i entities to a could SEKULLR, I improve the could see the court of the second second
- BOD4090445 Furuaris Numburula Sept 1775 re NRC practice & procedure digest Contains referred veh 31 78034 decisions interpreting rules of practice H o encl ROTHECHILD, M in matter of fulls since BO203/31 1p
- 8004190026 Responds to appeal re-folk request for all records re-sabbtage analyses for spent ruel storage at Morris operation in Morris IL info withheld (ref FOIA Exemption 4) Release of info would be contrary to public interest DIRCKS.W J Office of the Exerctive Director for Operations 80/04/03 2pp
- 8004170167 Advises of contrarge for amend review fee NAC Ofc of Controller motified to refund difference MILLER U.O. (icerse Fee Management Branch 80/04/03 ip
- 8004100151 Response in opposition to State of IL amended Contentions 1(r), 2, 6(c) 7(a)(b) / 10 Supports Contention 7(c) Position re admissibility of other contentions renains unchanged Urges denial of reconsideration re
- 8004220063 Forwards IE Info Notice 80-14 "Safety Suggestions From Employees" No action sequired MEPPLER. J. G. Region 3, Chicago, Orfice of the Director 80/04/04
- 8004280305 Response to State or IL second set of amended contentions & motion to stay proceedings (L ri)ing is deliberate effort to delay proceeding IL sefuses to inform ASLB,NRC & GE relissues for litigation Certificate of Svc encl SZWAJKONSKI, R General Electric Co SZWAJKONSKI, R Mayer, Brown & Platt 80/04/04 GBpp
- 8004170251 Advises of intention to respond to EJ Walsh 800319 petition to intervene served on NRC on 800403 ROTHSCHILD.M U. Hearing Branch 1 80/04/15 ip
- 8004230206 Corrects typographical errors in NRC 800404 responses to State of IL second set of amended contentions & Romem, et al remaineded contentions
 RDTHSCHILD.M V Hearing Branch 1 80/04/[7 2pp
- 8004220377 Response in opposition to E Halsh 800319 untimely petition to intervene Petitioner failed to state good contention, demonstrate standing bestablish good cause for untimeliness Certificate of Svc encl
 ROTHSCHILD, M U Hearing Branch (80/04/18 20pp
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GDSSICK, L. V. Office of the Executive Director for Operations BO/04/02 34pp

DOCKET 70-1319 U.S. NUCLEAR INC.

- 8004280247 Forwards IF Insp Rept 70-1319/80-01 on 800206-07 No moncompliance noted STDHR, J P Region 2. Atlanta: Fuel Facility & Materials Safety Branch 80/03/10 2pp
- --8004280255 IE Insp Rept 70-1319/80-DI on 800206-07 No noncompliance moked Major areas inspected confirmatory survey activities & status of activities to be completed prior to decommissioning GIDSON. A F Region 2. Atlanta. Fuel Facility & Haterials Safety Branch DAVIS.J H. KAHLE.B Region 2. Atlanta. Office of the Director 80/03/07 4pp

DOCKET 70-1426 TRANSHUCLEAR, INC

004180093 Forwards security plans re transportation of GNM of moderate & low strategic significance 4/o encl MANQUEL, J Transnuclear, Inc 80/03/11 1p

- NOO4070380 Ack receipt or 800311 ltr transmitting security plan for transportation or SNM of moderate strategic significance Fee to be assessed per licensing review WEISS.D Office of Administration 80/03/20 lp
- DOCKET 70-1729 FUEL REC % STOR STA , ALLIED GENERAL NUCLEAR SERVICES
- BO04030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board nutirication GOSSICKL V Dffice of the Executive Director for Operations 80/04/02 34pp
- DOCKET 70-1739 TRI STATE MOTOR TRANSIT CO
- 8004230197 Responds to 800130 ltr requesting temporary amend to SNM Security Transportation Plan II Request has been reviewed & found acceptable MCCORKLE, G W Physical Security Licensing Branch 80/02/13 ip
- 8004220062 Discusses 8002P5 Safeguards Physical Security Licensing Branch memo advising of three reviews & approvals reported under one project control number Ofc of Controller notified on 800317 to invoice licensee License Fee Management Branch 80/03/28 Ip
- DOCKET 70-2554 NEW ENGLAND MEDICAL CENTER BOSTON, MA
- 8004080199 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE insp. Repts 30-01868/80-01, 30-00240/80-01, 30-15064/80-01, 50-2254/80-01
 MCCLINIOCK, R. O. Region 1. Philadelphia, Office of the Director
- --8004080213 Responds to NRC 800222 ltr re violations noted in IE Inap Repts 30-01868/80-01.30-00240/80-01.30-15064/80-01 & 70-2254/80-01 Corrective actions necessary monitoring reinstituted on 800207 TRULL, D New England Medical Center Boston, MA 80/03/03 lp
- --8004080230 Forwards 1E Insp Repts 30-01848/80-01,30-00240/80-01, 30-15064/80-01 & 70-2254/80-01 on 800205-07 & notice of violation MCCLINTOCK,R O Region 1, Philadelphia, Office of the Director
- --8004080248 Notice of violation from insp on 800205-07 Noncompliance noted failure to make surveys of airborne radioactivity 791214-800207 & failure to perform routine thyroid monitoring

 Region i, Philadelphia, Office of the Director 80/02/22, 1p

DOCKET 70-2322 EDLOW INTERNATIONAL CO

- B004160003 Approves route through Portsmouth, VA for import of irradiated reactor fuel No practical alternatives exist that are not located in heavily populated areas MCCORKLE.0 W Physical Security Liconsing Branch 80/03/12 ip
- 8004040473 Approves increase in number of routes authorized by NRC 791219 route approval as requested in 800222 ltr MCCORKLE.Q W Physical Security Licensing Branch 80/03/13 ip
- DOCKET 70-2362 BROCKTON HOSP BROCKTON, MA
- 8004210012 Discusses IE insp of Licenses 20-03333-02 & SNM-1664 on 800221 No noncompliance noted Major areas inspected selective exams of procedures & representative records; interviews w/personnel.measurements & observations MCCLINTOCK, R D Region i, Philadelphia, Office of the Director 80/02/28 ip
- DOCKET 70-2478 TRANSNUCLEAR: INC.
- 8004030323 Forwards IF Insp Rept 70-2478/80-01 on 800226-27 No noncompliance noted KENNA, W B Region 2, Atlanta, Bafeguards Branch 80/03/11 2pp

- --8004030362 IE Insp Rept 70-2478/80-01 on 800226-27 No noncompliance noted Major areas inspected physical protection requirement for irradiated fuel in transit Dotails withheld (ref 10CFR2 790)
 TOBIN, N J Region 2, Atlanta, Safeguards Branch PE
 Region 2, Atlanta, Office of the Director 80/03/10 PERNY, C D
- 8004240247 Approves route through Portsmouth.VA for imports of irradiated reactor fuel No practical alternatives exist that are not located in heavily populated areas MCCORKLE,OW Physical Security Licensing Branch 80/03/12 ip
- 8004210075 Forwards Amend 3 to license for Transnuclear, Inc to import 643 058 kg U.containing 459 507 kg U-235 & 2 406 kg Pu.from France
- France STONEBURNER,W Transnuclear, Inc 80/03/14 1p
- --8004210077 Amend 3 to license for Transnuclear, Inc to import 643 058 kg U containing 459 507 kg U-235 & 2 406 kg Pu from France PETERSON,M R Office of International Programs 79/09/25 ip
- --B004210078 Amend 1 to license for Transnuclear, Inc to increase quantity of matl authorized for import SHEA, J R Office of International Programs 78/05/26 1p
- --8004210080 License for Transnuclear, Inc. to import 121 708 kg U containing 96 607 kg U-235 & 666 g Pu QUHIN,M A Assistant Director for Export/Import & International Safeguards 77/07/18 2pp

DOCKET 70-2479 TRANSNUCLEAR, INC.

- 8004240247 Approves route through Portsmouth.VA for imports of irradiated reactor fuel No practical alternatives exist that are not located in heavily populated areas MCCORKLE,O W Physical Security Licensing Branch 80/03/12 ip
- 8004110345 Forwards IE Insp Rept 70-2479/80-03 on 600305-06 No noncompliance noted KENNA:W B Region 2: Atlanta, Safeguards Branch 80/03/25 2pp
- --8004110549 IE Insp Rept /0-2479/80-03 on 800308-04 No noncompliance noted Major areas inspected physical protection of irradiated fuel in transit Details withheld (ref 10CFR2 790)
 TOBIN,N J Region 2, Atlanta, Safeguards Branch MODRE,D E Region 2, Atlanta, Office of the Director 80/03/25 ip
- DOCKET 70-2623 MCQUIRE SPENT FUEL POOL. DUKE POWER CO
- BOO4220303 Protests proposed shipment of nuclear waste from facility in SC to facility in NC Nuclear plants should be required to neutralize radioactive matl rather than transport it SPARGOLL L Affiliation Unknown 80/03/09 2pp
- --8004220315 Discusses Gaston County,NC resolution re transportation of spent nuclear fuel through county Requests opportunity to present resolution at NRC 800428 hearing in Charlotte NC HUNSCHER,D G Affiliation Unknown 80/03/19 1p
- --8004220324 Favors transport of nuclear maste through Mount Holly.NC Other dangerous shipments routinely pass through city SETIER B R Affiliation Unknown 80/03/20 1p
- --800422033; Favors shipment of nuclear waste through Denver.NC & storage of waste at nearby nuclear plant
 KENNERLY,F M Affiliation Unknown 80/03/17 1p
- --8004220342 Opposes transport of nuclear waste through Mount Holly,NC, Route is extremely hazardous due to presence of high-speed intersection & frequency of accidents HCINTOBH.W O Affilation Unknown 80/03/18 ip
- --8004220353 Opposes transport of nuclear waste through Lincolnton,NC Questions necessity of transporting safe mati from plant ROBINGON,F 8 Affiliation Unknown 80/03/11 ip
- --8004220362 Notifies that Gaston Taxpayers Association opposes transport of nuclear waste from Gaston NC facility
 SUTHERLAND, R Affiliation Unknown 80/03/07 ip
- 8004030326 Serves routing info re spent fuel transportation & storage, per Commission 800229 order denying NRC petition Forwards RD Olenn & CV Hodge testimonies evaluating route changes per EIA W/o encl HOEFLINO,R K Hearing Branch 4 50/03/07 2pp

- 8004080372 Forwards June 1919 Fhy.i.al Protection of Shipments of Irradiated Reactor Fuel, Interior Cuidance, "NUREG-0561 W/o enc) KETCHEN, C.G. Hearing Branch 4 BO/03/21 ip
- 8004110193 Motion to deny Carolina En. Hon Study Group request to introduce add1 evidence re cask drop issue Introduction of alleged scale-model test or cask tipping incident is inconsistent wheyolations & rolling M/Certificate of Svc MCGARRY, J M Dute Power Co MCGARRY, J M Debevoise & Liberman agB
- 80042300/8 Forwards 800328 SECY-80-166 requesting amend to irradiated roactor ruel in-transit physical protection requirements If amend approved effect on IRC case re spent fuel transportation 9 storage will be provided HOEFLING, R k. Hearing Branch 4 80/04/01 1p
- 8004030626 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board mutification GOSSIGK, L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004230012 Motion requesting ASLB consideration of proposed primary route Applicant does not deny availability of alternate routes Pertinent NRC regulation based on Sandia Labs study Study envisions highly unlikely sabotage event MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 80/04/04 7pp
- 8004180432 Forwards NRC 800403 lts w/encl commercial newspaper advertisement re resumption of evidentiary hearings NRC wishes to notify public officials of counties in which proposed alternate routes are located KETCHEN, E. G. Hearing Branch 4 BO/04/08 Ip
- --B0041B0441 Notifies of resumption of evidentiary hearings re amend of License SNM-1773 Proposed action is to transport up to 300 spent fuel assemblies from Oconee nuclear facility to McGure nuclear facility Commercial newspaper notice encl ROUSE, L C Advanced Fuel & Spent Fuel Cicensing Branch B0/04/03
- BOO4160197 Forwards BS Spitalny, JN Donohew, CR Marotta & E Lantz prefiled testimonies re amend to License BNN-1773 for Ocohee spent fuel transportation % storage at McGuire KETCHEN, E. G. Hearing Branch & BO/04/11 2pp
- --8004160197 Prefiled testimony re 800428 hearing Updates license amend record re spent fuel handling 3 storage alternatives, status of NRC spent fuel cask review & pin compaction application SPITALNY, B S Advanced Fuel & Spent Fuel Licensing Branch 80/04/61 Spp
- --8004160210 Supplemental NRC rept "Spent Fue) Storage of Geomee Spent Fuel at McGuire Nuclear Station Unit 1" * Commission 80/04/11 Ppp

- --8004160235 Afridavit ne or upational doses caused by Oconee spent fuel assembly rupture at 2.0 days in age, when stoned in McGuire spent fuel pool Completes NAC response to ASLB 791031 order Supporting Jocumentation en
- --8004160240 Afridavit re occupational doses caused by Doonee spent fuel assembly rupture, at 40 days in age, when stored in McGuire spent fuel pool Completes NRC response to ASLB 771031 order Supporting documentation encl
 DDNDHEW, J.N. Environmental Evaluation Branch 80/04/10 Bpp
- --BCO4160244 Affidavit modifying JN Donohew 800111 affidavit.Table 2.Page 10 & Table 3.Page 11 DDNMHEW.J N Environmental Evaluation Branch 80/04/11 3pp
- 8004160265 Response requesting deferral of ASLB consideration of applicant 800405 motion proposing primary route of spent fuel shipments Urges ASLB to hold motion in abeyance pending Commission action re security issue M/Certificate of Svc HQEFLING.R K Hearing Branch 4 80/04/11 9pp
- BOO4230210 Response in support or Duke Power Co 800401 motion to deny Carolina Environ Study Group introduction of add1 evidence re cask drop issue Good cause for reopening record not demonstrated N/Certificate of Svc XETCHEN, F.G. Hearing Branch 4 80/04/21 Bpp
- 800410055B Further supplemental testimony of RN Bostian re spent fuel storage High density relacking discussed Pp 1-3 Certificate of Syc encl BOSTIAN-R W Duke Power Co 80/03/17 Spp
- DOCKET 70-2786 GENERAL ELECTRIC CO
- 8004070136 Forwards info requesting route approval for shipment of irradiated reactor fuel Encl withheld (ref (OCFR2 790) CARRIER.M J General Flectric Co 80/01/29 ip
- 8004020147 Responds to 791205.800127 & 0213 requests for approved spent fuel route Route & law enforcement info moets NRC requirements & approval Route & law enforcement info withheld (ref10CFR2 790) MCCORKLE.G W Physical Security Licensing Branch 80/02/22 ip
- DOCKET 70-2805 NISSHO-IUAL AMERICAN CORP
- 8004240181 Forwards Frecutive Branch response on pending application for license to export highly enriched U to Japan Requests identification of issues to include in analysis
 SHEA, J.R. Office of International Programs SECY-80-120 80/03/03
- ~~8004240190 Application by Wissho-Twai American Corp for license to export 39 185 kg U-235 contained in 42 kg U to Japan KAWAHARA:8 Nissho-Twai American Corp 78/02/08 2pp
- --8004240202 Forwards Nissho-Twal American Corp application for license to export 39 186 kg U-235 to Japan & end use statement End use statement only encl
 TSUJIM Nassho-Twal American Corp 78/02/08 6pp
- DOCKET 70-2845 TRANSMUCLEAR, INC
 - 51 Forwards Elecutive Branch position on 800121 applications tenses to export highly enviched U to Belgium West p.France & the Netherlands Requests comments & BO/01/24
- --9004010081 Forwards application by Transnuclear, Inc for license to export 23 058 kg U in form of U hexaflouride enriched to max 93 3% U-235, to West Germany MATSON, V Transnuclear, Inc 78/03/27 (p
- --9004010071 Application by Transnuclear Inc for license to export 23 058 kg U.in form of U heraflouride enriched to max 93 3% U-235 to West Oermany End use statement & checklist encl MATSON.V Transnuclear, Inc 78/03/27 3pp

- DOCKET 70-2872 REUTER-STOKES
- 8004170108 Act receipt of 800317 ltr transmitting plan for protect of SNM Amend to License SMM-1826 will be upon issued upon plan approval Fee required WEISS.D License Fee Minagement Branch 80/03/26 lp
- DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP POWER SYSTEMS
- 8004180090 Responds to request for name of thief executive of municipality or county mentioned in environ rept submitted in support of 791231 license application re nuclear fuel fabrication plant planned for AL CELLIER.F Westinghouse Flectric Coip 80/02/20 1p
- 8004150104 Forwards distillution list.FR notice & news release TQ issuance of bN4 license for +acility PAGE,R G Uranium Fuel Licensing Branch 80/02/27 4pp
- -8004150107 Notice of opportunity for hearing, availability of envere to intent to prepare DES re issuance of SMM license for facility PAGE.R G Uranium Fuel Licensing Branch 80/02/24 8pp
- B004180098 Transcript of t1S 800327 scoping meeting in Prattville, Pp 1-66 GRAY, C M Affiliation Unknown CROW, W , SHUM, E Y Uranium Fue Licensing Branch 80/03/27 67pp
- 8004240257 Transcript of 800327 EIS scoping meeting in Prattville. re proposed vendor fuel fabrication plant * Commission 80/03/27 67pp
- 8004170282 Confirms 800325 telcon ie establishment of Prattville Fa Library as official NRC IPDR for fabrication plant matl NRC representatives will visit for briefing re matl filing & retrieval procedures CARRIER, W B Division of Rules and Records 80/04/01 ip
- 8004250064 Mation for extension of time to make comments on scope proposed EIS re Kestinghouse SNM application NRC statement at 800327 scoping modeling that proposed 800703 & 07 deadlines were incorrect & created confusion ARANCV.R Affiliation Unknown MCPHILLIPS.J Affiliation Unknown B0704703 3pp
- 8004300366 Response in support of RH Campbell.A Toledo.RE Ely.JA Johnson.MF Butler.CO Butler.R Aronov.LO Moore & SN Draut petitions to intervene Urges presentation of common interest by single spokeman subj. to filing of one contention TURK.S.E. Hearing Branch 1 80/04/28 11pp
- ---8004300371 Response in support of DL Alired 800407 petition to intervene Petitioner demonstrated interest & adequately identified relevant aspects of proceeding Urges admission of petitioner subj to filling of one admissible contention TURK.S E Hearing Branch 1 80/04/28 8pp
- --8004300378 Response in support of State of AL participation as interested state in proceeding TURK.S E Hearing Branch 1 80/04/28 1p
- --B0043003B1 Requests participation in possible hearing, as interess state per 10CFR2 715(c) Notice of SE Turk appearance & Certificate of Svc encl MYERS,I L. Alabama. State of 80/03/21 4pp
- DOCKET 70-2917 TENNESSEE VALLEY AUTHORITY
- 8004240201 Forwards License SNM-1865, authorizing receipt, possessicaling to storage of U-235 fuel assemblies & max of 100 fuel rods License also allows packaging & shipping for transfer Safety evaluation encl
 PAGE, R. O. Uranium Recovery Licensing Branch 80/01/30 2pp
- --B004240207 License SNM-1869, authorizing receipt, possession, Inspite transfer of max of 2,110 kg u-235 fuel assemblies & 100 fuel rods Licensee is exempt from matts provisions of 10CFR70 24 PAGE, R O Uranium Recovery Licensing Branch B0/01/30 2pp J
- --8004240217 Safety evaluation is util application for license to receive max 2.110 kg U-235 fuel assemblies & 100 fuel rods License should be granted w/exemption from 100FR70 24 CROM-H T , DELANEY, J L Utanium Recovery Licensing Branch 80/01/30 2p

DOCKET 70-2920 ALABAMA POWER CD

- 8004020473 Forwards License BNM-1868 for util, authorizing receipt, possession & storage of U enriched in U-235 isotope & Pu License also authorizes packaging of fuel assemblies for delivery to carrier Safety evaluation encl 80/03/12 2pp
- --80040204B1 License SNM-1868 for util, authorizing receipt, possession, insp & storage of U enriched in U-235 isotope in fuel assemblies & fission counters. & Pu in encapsulated Puberyllium neutron sources & alpha sources PAGE,R O Uranium Fuel Licensing Branch 80/03/12 2pp
- --8004020485 Safety evaluation supporting 790918 application for license for fuel & accessories Licensee should be granted exemption from 10CFR70 24 requirements DELANEY.J C Uranium Fuel Licensing Branch 80/03/12 2pp

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0005 MAGNAFLUX CORP

8004290495 Understands GA program description will be submitted by B00417 MACDDNALD, C E Transportation Branch 80/03/04 ip

DOCKET 71-0009 ISOMEDIX, INC

- BO04090220 Advises that vendor is in process of transferring mfg activity to AECL Target date for resolving transfer details is BO0430 At that time, vendor will advise of last date to ship matis or submit revised GA program
 DIETZ, Q R Isomediz, Inc (subs of Maesfield Enterprises, Inc)
 B0/03/17 1p
- ---B004090225 Advises that NRC 790730 Itr requesting add1 info re QA program on timely basis has not received response Provides format, previous correspondence & franked envelope for immediate response
 MACDUNALD, C E Transportation Branch B0/03/04 1p

DOCKET 71-0013 NAVY, DEPT OF

- 9004020373 Forwards QA program approval for radioactive mat1 package MACDONALD.C E Transportation Branch 80/03/05 ip
- --8004020380 GA program approval for radioactive matl package 0013, Revision 1 MACDONALD,C E Transportation Branch 80/03/05 ip

DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP

- 8004090234 Requests amend to GA Program Approval 0024 Revision O, changing program implementation date from 800301 to 800322 ROME.B B Hittman Nuclear & Development Corp (subs Hittman Corp), 80/03/03 ip
- BOO4070147 Forwards QA program approval for radioactive matl package MACDONALD.C E Transportation Branch G0/03/13 ip
- --8004070152 GA program approval for radioactive matl package 0024, Revision MACDONALD, G E Transportation Branch 80/03/13 ip

DOCKET 71-0035 ROCKWELL INTERNATIONAL

- 8004040399 Forwards QA program for packaging licensed radioactive matl for shipment in response to NRC 800123 request for revisions to program MCDERMOTT.R J Rockwell International Corp 80/03/10 ip
- --8004040403 GA program for packaging licensed radioactive matl for shipment JOSEPH,R L , QLABS,D N , MCDERMOTT,R J Rockwell International Corp 80/03/07 24pp

DOCKET 71-0049 NAVY CEPT IIF

- 8004150272 Forwards 9A program for receipt, handling, storage & transfer of special form radicaltive malt in response to NRC 800304 ltr
 - GROVES, R L. Ha-y, Dept or, Na. al Nuclear Power Unit 80/03/13 1p
- --8004150278 Forwards GA program for receipt handling, storage & transfer of special form radioactive math WARD.C E. Navy.Dept of 79/11/12 ip
- --8004150284 QA program for receipt, handling, storage % transfer of special form indicactive mail * Navy, Dept of 79/11/12 App
- B004100239 Forwards GA program approval for radioactive matl package MACDDNALD,C E Transportation Branch 80/03/27 ip
- --8004100242 OA program approved for radioactive matt package 0049. Revision O MACDOMALD.C E Transportation Branch 80/03/27 1p

DOCKET 71-0096 PAN AMERICAN WORLD AIRWAYS

- BOO4180062 Forwards revised GA plan for transportation packages for normal/special fulm radioactive matl DUNN,N M Pan American World Airways, Inc. 80/03/19 1p
- --8004180069 Revised QA plan for transportation packages for normal/special form radioactive matl DUNN,N M Pan American Would Arrways, Inc. 80/03/19 8pp
- 8004100231 Forwards GA program approval for radioactive matl package MACDONALD, C C Transportation Branch 80/04/01 1p
- --8004100236 GA program approval for radioactive matl package 0096. Revision O MACDINALD.C E. Transportation Branch 80/04/01 1p

DUCKET 71-009/ NONDESTRUCTIVE TESTING SERVICE

- 8004150132 Forwards GA Program for industrial radiography licensees HAULDREN, H M Nondostructive Inspection Service 80/03/18 tp
- --8004150133 GA program for industrial radiography licensees
 * Nondestructive Inspection Service 80/03/18 3pp
- 8004100225 Forwards GA program approval for radioactive mati package MACDONALD.C E Transportation Branch 80/04/01 1p
- --8004100229 0A program approval for radicactive package 0097, Revision O MACDUNALD, C E Transportation Branch 80/04/01 ip

DOCKET 71-0102 SOURCE PROD \$ £.QUIP CO . INC

8004080099 Ack receipt of NRC 800304 ltr requesting info Project was turned over to consultant R Parker several months ago Advises that request will be forwarded DICHARRY.R F Bource Production & Equipment Co., inc. 80/03/14 [p.

DOCKET 71-0107 NAVY, DEPT OF

- 8004240314 Forwards revised QA program for industrial radiography, in response to NRC /90813 ltr QROVES,K L Navy, Dept of, Naval Auclear Power Unit 80/02/28 ip
- --8004240322 Forwards sevised QA program for industrial radiography GLENN, T D Navy, Dept of, Naval Nuclear Power Unit 80/02/07 ip
- --8004240331 GA program for industrial radiography
 GLENN, Y D Navy, Dept of, Naval Nuclear Power Unit 80/02/07

```
4 1 4
                                                                                                                 and the state of t
                       (A) p
                                                                                                                        , 1, % it - - Let Unit E0/03/19 1p
                                                                                • •
                                                                                                                                          r sour firling storage & transfer
                                                                                                                                                        ed: Fiver Unit 60/03/07 1p
                                                                                                                             . 41
                     50-411-12
                             * it is a man of all in madicactive mail package

really really 19400 is
                    • r i ilioa *i e hatl package Q116,
                                                                 r I'm ++1 Eta + 80/04/01 1p
          Di MET I ( ) III
          DUTHER TO STORY PROJECTS OF
        neu-arid iga, k. wards tet is ear affl anes to complete review of QA
                EDOMET 71 Give . - EFFT
      C D4CF) Zz = F reside thA p cyram approval for radioactive mati package MACDutA D + F = 0.502 (ration brane) = 80/03/21 = ip
      Review of Development of States 60/03/21 ip
      LOUBET 71 117 Tilled ele THIT CO
    ECO430005. Forward Restance 1 to the program CO4416.7 (44 to Ce et al r'ours 6 Nuclear Energy Products Div 80/04/6" to
   --- GET AL A ST JEST TO SET THE SET OF SET O
                                                                                                           #f-1 R1 +0.03/31 33pp
    DOCKET 71 618 HARTFURD GTEAM DUILER CO
  E004070137 Regresta influre status or response to 790413 ltm
MACDETALP | E Traiso italian pranch 65/03/14 lp
  DOCKET 21 OIGH FRE 11.
  8004070021 F rwands the program Addit appendices included to cover addit
          mediterents
GTRINGFIELD (* 68- 1- D) G3/10 3p
 --8004670022 GA program
 DECKET AL OBS. MINNESSE ANTIES ANTHORITY
8004290513 Forwards GA program Revision 1
BILLS, L % Tennessee Valley Authority 80/04/10 tp
```

```
DOCKET 71-0230 BABCOCK * WILCOK CO
     8004040374 Forwards requirt for addl info to complete review of QA
        program
MACDONALD,C E Fransportation Branch 80/03/14 tp
     DOCKET 71-0249 NUCLEAR FUEL SERVICES, INC.
    8004140024 Forwards QA Program to shipping packages for radioactive math Program includes info requested in NRC B00116 ltr MICHEL.C J. Nuclear Fuel Gervices, Inc. (subs. of Quity Dil Co.) 80/03/17 lp
    --8004140027 QA Program Revision 2 for shipping packages for radioactive
         mati

• Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 80/03/17
    DUCKET 71-0250 TRANSNUCLEAR, INC.
   8004020360 Forwards GA program approval for radioactive matl package MACDGNALD,C E Transportation Branch 80/03/09 ip
    --8004020364 0A program approval for radioactive matt package 0250.
        Revision O
MACDONALD.C E liansportation Branch 80/03/09 ip
   DOCKET 71-0252 DAYTON X-RAY CO
   8004180400 Forwards request for addl info to complete review of OA
     program
MACDONALD, C.E. Transportation Branch 80/03/28 3pp
   DOCKET 71-0273 NAVY, DEPT OF
  8004150079 Forwards supplemental info per NRC 800020 request re QA
    program
GROVES,K L. Navy,Dept of, Naval Nuclear Power Unit 80/03/19 lp
  ~~8004150102 Forwards GA program for radingraphic operation
ALLEN.J E Navy, Dept of, Navat Nuclear Power Unit 60
                                                                         80/02/20 1p
  --8004150108 dA program for radiological operation,
ALLEN, J E. Navy, Dept. of, Navel Nuclear Power Unit. 60/02/20
 8004100329 Forwards QA program approval for radioactive mat1 package MACDONALD,C E Transportation Branch 80/04/01 Ip
 ~-B004100332 QA program approval for radioactive mati package 0273,
      Revision 0
MACDONALD,C E Transportation Blanch 80/04/01 1p
 DOCKET 71-0367 NAVY, DEPT OF
 8004150112 Forwards supplemental info per NRC 800115 request re OA
   program
GRDVES,K L Navy.Dept of, Naval Nuclear Power Unit 80/03/19 ip
--B004150117 Forwards revised Page 3 & new Page 4 to GA program
BISEK, D G Navy, Dept of, Naval Nuclear Power Unit 80/03/13 ip
--8004150121 Revised Page 3 & new Page 4 to GA program
* Navy,Dept of, Naval Nuclear Power Unit 60/03/13 2pp
8004100346 Forwards QA program approval for radioactive mat1 package MACDGNALD, C & Transportation Branch 80/04/Oi ip.
--8004100347 QA program approval for radioactive mati package 0367.
    MACDONALD, C E Transportation Branch B0/04/01 ip
```

DOCKET 71-0370 AMERSHAM CORP

8004040388 Forwards request for addl info to complete review of QA MACDONALD.C E Transportation Branch 80/03/14 12pp

DOCKET 71-0372 BDEING CO

- 8004090214 Forwards GA program approval for radioactive metl package MACDDNALD, C.E. Transportation Branch 80/03/21 ip
- --- 8004090218 GA program approval for radioactive mat1 package 0372, MACDONALD, C E Transportation Branch 80/03/21 1p
- DOCKET 71-00373 NAVY, DEPT OF, NAVAL EXPLOSIVE ORDN DISPOSAL FACIL
- 8004090201 Forwards GA program approval for radioactive matl package MACDONALD,C E Transportation Branch 80/03/21 1p
- --8004090203 GA program approval for radioactive mat1 package 0373, Revision O MACDONALD, C.E. Transportation Branch BD/03/21 1p

DOCKET 71-0375 CALIFORNIA, UNIV OF

- 8004090222 Forwards GA program approval for radioactive matl package MACDONALD,C E Transportation Branch 80/03/21 1p
- --8004090226 GA program approval for radioactive matl package 0375. Revision 0
 MACDONALD.C E Transportation Branch 80/03/21 1p

DOCKET 71-0377 INDIANA & MICHIGAN ELECTRIC CO

- 8004090270 Forwards QA program approval for radioactive matl package MACDDNALD, C E Transportation Branch 80/03/27 ip
- --8004090273 GA program approval for radioactive matl package 0377, Revision 0 MACDONALD,C E Transportation Dranch 80/03/27 ip

DOCKET 71-0378 WISCONSIN ELECTRIC POWER CO

8004040123 Notifies that description of GA program is App H to final description & SAR FAY, G W Wisconsin Electric Power Co 80/02/25 2pp

DOCKET 71-0379 HITTMAN CORP . HITTMAN MATL & MEDICAL COMPONENTS, INC

- B004020274 Responds to B00226 request for approval of OA program Item 3 should be revised to require that all radioactive matl shipping packages procured since 790101 are designed & mfg under NRC-approved OA program MACDONALD. C E Transportation Branch 80/03/20 1p
- 8004220043 Forwards revised Operating Procedure OP-168, constituting "GA Program for Use of DOT 6M Drums in Shipping Special Form Pu-238," DIBALVO Hittman Corp 80/03/25 1p
- --8004220055 Revised Operating Procedure OP-168 constituting" GA Program for use of DOT 6M Drums in Shipping Special Form Pu-238 " DIGALVO Hittman Corp 80/03/28 2pp

DOCKET 71-0380 GENERAL ELECTRIC CO

- 8004070398 Advises that NEDO-11209-04A, Revision 1, "Nuclear Energy Div BWR GA Program Description," outlines GA program vendor uill use for packaging activities re application for registration as user of Model 589 shipping package. CUNNINGHAM, G E General Electric Co 80/03/10 ip
- 8004070014 Forwards GA program approval for rainactive matl package MACDONALD, C. E. Transportation Branch 80/03/31 1p

- --8004090017 9A program approval for matter matt package 0380, Revision C MACMINAL D. C. E. Transportation Branch B0/03/31 lp
- DOCKET 71-0381 C L CONWITT . CO
- 8004210066 Requests approval or entl GA program for transportation o licensed matts
 COPPER.UE E L Conwell & Co BO/03/24 ip
- --80042100/3 GA program for transportation of licensed matts Organizational chart for industrial radiography encl # E | Conwell * to 100/03/21 'pp
- DOCKET 71-0383 HODEL HET TYP LWT CASK, BE INDUSTRIES, INC.
- B004300079 Requests registration as user of Model NLI 1/2 LHT Cask LIPPOLD:N J Dallimore Gas * Electric Co 80/04/03 Ip
- DUCKET 71-4824 MUDIL HA 10. BABCOCK & UILCOX CO
- B004290061 Advises that one of Nodel HA ID will be discontinued & company will not renow Curtificate of Compliance 4824
 AUSTIN-M A Babcock & Wilcox Co., Nuclear Material Div 80/03/25
- DOCKET 71 5375 MODEL CC. WESTINGHOUSE ILECTRIC CORP
- 800428030/ Furwards Revision 5 to Costificate of Compliance 5395 for MACDONALD, C.F. Transportation Branch 80/04/02
- --B0042B0314 Centificate of templiance 5395, Revision 5, for Model CC MACDUNALD, C. E. Transportation Branch B0/04/02 3pp
- DOCKET 71 9607 HODEL GE 3-2, GENERAL ELECTRIC CO.
- BDO40400B2 Notifies of prination of Centificate of Compliance 9607 for Model GL T-6 to continue using package should submit consolidated application diamings & innewal fee MACDONALD.C T. Transportation Branch (BO/07/14 tp

- #20402012V Submits renewal tis for Centificate of Compliance 5939 re GE Model (Submits renewal) interior Packaging description & Vallectes Nuclear Off Pictor (Not enc) CONNINGMAN & C. Genzial a astrology BOY02/21 (5pp
- --8004020137 Forwards percorring to drawings on remaining containers designating jackst hindown bolts re GE models 1500 \$ 700 flods to applications as inding modified drawings forthcoming KIRS WH. General witching to 69.02/20 12pp
- 80040404c2 Notification of registration as user or Model 6400 & GE 1500 in response to request MACCOMALD-C & Transportation Branch 80/03/14 ip
- DOCKET 71 5942 MUDEL GE 700 GENERAL ELECTRIC CO
- 8004300505 Forwards SAR +nr GE, spent fuel shipping cask Model 700 in support of Leithricate or Compliance 5942 Drawings available in Central Files only BRUGGER R M Missour Mnr. of Columbia 80/09/20 2pp
- DOCKET 71 5971 MODEL GE-100, GENERAL ELECTRIC CO
- 8004250084 Requests that certificate of Compliance 5971 for GE Model 200 shipping container be renewed w/minor changes Forwards drawings indicating changes made to cask drawing list Drawings available in Centrol Files only Amend fee encl CUNNINGHAM.G E General Electric Co 80/02/20 16pp
- DOCKET 71-5979 HODEL 5977, ALPHA-OMEGA SERVICES.INC
- BOO4040197 Notifies of expiration of Certificate of Compliance 3979 for Model 5979 To continue using package, should submit consolidated application. 9 drawings MACDONALD.C E Transportation Branch 80/03/17 1p
- DOCKET 71-5998 MODEL GE-400, GENERAL ELECTRIC CO
- 8004070053 Notifies of expitation of Certificate of Compliance 5978 for Model GE-400 To continue using package, should submit renewal application % fee MACDUNALD, C. Transportation Granch 80/03/14 ip
- DOCKET 71-6078 MODEL 927 AT % C1, COMBUSTION ENGINEERING, INC.
- 8004100259 Forwards Revision & to Certificate of Compliance 6078 for Models 92741 & 92741 MACPUNALD, C.E. Transportation Branch 80/03/28 ip
- --8004100262 Certificate of Compliance 60/8, Revision 6 for Models 927A1 & 927C1 HACDDNALD, C E Transportation Branch 80/03/28 3pp
- DOCKET 71-6144 MODEL 6144, HUCLEAR ENGINEERING CO
- 8004110125 Ack receipt of HGO201 request re registration as package user Approved GA program required prior to legistration MACDONALD.C E Transportation Branch 80/03/04 ip
- 8004250502 Requests registration as user of Models CSN-4-101 & CBN-15-1600 CBN-15-1600 CGDNEY/M J Philadelphia Electric Co 80/03/28 Ip
- DOCKET 71-6272 MODEL POLY PANTHER, TELEDYNE ENERGY SYSTEMS
- 8004100212 Forwards Revision 3 to Certificate of Compliance 6272 for Model Polly Panther MACDGNALD.C E Transportation Branch 80/03/28 2pp
- --8004100216 Certificate of Compliance 6272 Revision 3.for Model 6272
 MACDENALD.C E Transportation Branch 80/03/28 200
- DOCKET 71-6375 MODEL PR-1, CHEM-NUCLEAR SYSTEMS, INC
- 800404045 Requests registration as user of Model PB-1 SMITH R L. Vermont Yankee Muclear Power Corp. 80/03/04 1p

- 8004040450 Notification of registration as user of Model CNB 4-45 in response to request MACDOWALD.C E. Transportation Branch 80/03/17 ip
- BOO421041B Forward, request for add1 info re 791126 consolidated application for renewal of Certificate of Compliance 6375 for Model CN5 4-45 (PB-1) Info should be provided within 60 days MACDUNALD.C E. Transportation Granch BO/04/02 Epp
- DOCKET 71-4987 MODEL 60, BATTELLE MEMORIAL INSTITUTE
- B004020055 Forwards Certificate of Compliance 6387 Revision 2 & safety evaluation for HEDL Model 60
 ROSS.D M Energy.Dept of 80/01/21 6pp
- --8004020059 Certificate of Compliance 6387 Revision 2 for HEDL Model 60 TERNARI H W Energy Dept of 79/05/07 7pp
- BOO40404/B Notifies of expiration of Certificate of Compliance A387 for Model &O To continue using package, should submit consolidated application & drawings MACDDNALD.CE Transportation Branch 80/03/17 ip
- DOCKET 71-6400 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP
- 8004040462 Notification of registration as user of Model 6400 & GE 1500 in response to request MACDONALD.C E Transportation Branch 80/03/14 ip
- BOO4220127 Responds to NRC 800229 itr forwarding Revision B to Certificate o+ Compliance 6400 In response to Guestion 2. Lynchburg Research Ctr has used overpacks L-1 & Units 1 & 2 Guestions 1 & 3 do not apply GLSEN, A F Babcock & Wilcox Co 80/03/14 tp
- 8004150119 Responds to request for info re Certificate of Compliance 6400, Revision 8 Util does not own any Model 6400 package & never possessed package to perform insp Model not used since 780228

 LINDER, F Dairyland Power Cooperative 80/03/18 ip
- 8004280061 Responds to 800227 ltr re Certificate of Compliance 6400. Revision & Licensee does not own DDT USA/6400/D() F packages Licensee has not used packages from other vendors since 780228 REMLEY, M & Rockwell International Corp , Energy Systems Div 80/03/18 ip
- 8004210198 Responds to NRC 800229 litr by advising that no Model 6400 packages are owned & no shipment of package has been made since 780228 MICHEL.C J Nuclear Fue) Services, Inc. (subs. of Oetty Dil Co.) 8004321 | lo
- DOCKET 71-6574 HODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8004220274 Forwards response to NRC 791221 request for add1 info re SAR for Mode! HM 200 G-loads under top-corner impact conditions re-ovaluated to consider peak conditions Proposed revised pages to SAR enc1
 MALLORY Fittman Nuclear 5 Development Corp (subs Hittman Corp) 08/03/20 17pp
- 8004100220 Forwards Revision 5 to Certificate of Compliance 6574 for Model NN-200 McCDNALD, C E Transportation Branch 80/03/28 3pp
- ~~8004100224 Certificate of Compliance 6574, Revision 5, for Model HN~200 MACDONALD, C E Transportation Branch 80/03/28 3pp
- DOCKET 71-6679 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO
- 8004100198 Forwards Revision 3 to Certificate of Compliance 6679 for Model 1/2 Super Tiger MACDONALD, C E Transportation Branch 80/03/31 2pp
- --8004100600 Certificate of Compliance 6679 Revision 3.for Model 1/2 Super Tiger MACDONALD.C E Transportation Branch 80/03/31 4pp

- DOCKET 71-6698 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC
- 8004040395 Requests authorization, under Certificate of Compliance 6698, Revision 9 for Model NFS-4, to ship reconstituted PWR U oride fuel assembles containing more or less than design number of fuel rods Fee encl JOHNSON, C R Nuclear Assurance Corp 80/03/03 2pp

DOCKET 71-6717 MODEL 6717 B

- 8004210037 Requests revision to Certificate of Compliance 6717 for Model 6717B deleting references to use of asbestos as thermal insulator in package design Requests that words asbestos free, appear in description paragraph RICHARDSON, H D Gamma Corp 80/02/26 7sp
- ---8004210042 Requests payment of minor amend fee re 800224 request for amend to Certificate of Compliance 6717 for Model 6717B WEISB, J D License Fee Management Branch 80/03/05 ip
- DOCKET 71-9006 MODEL 500 SU, ARGONNE NATIONAL LABORATORY
- B004010001 Notification of registration as user of Models 500-SU & 520 MACDONALD, C E Transportation Branch 80/03/07 ip
- DOCKET 71-9007 MODEL 520, ARGONNE NATIONAL LABORATORY
- BOO4010001 Notification of registration as user of Models 500-80 & 520 MACDDNALD, C E Transportation Branch BO/03/07 1p
- 80040403B1 Notifies of expiration of Certificate of Compliance 9007 for Model 520 To continue using package should submit consolidated application & drawings MACCONALD.C E Transportation Branch 80/03/17 ip
- DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO
- 8004070216 Requests registration as user of Model FL 10-1 package HANBEN.L E Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/02/27 ip
- 8004090046 Submits application for amend of Certificate of Compliance 9009 for FL-10-1 shipping container.
 DIPIAZZA,R F Westinghouse Electric Corp 80/03/11 2pp
- 8004100250 Forwards Revision 6 to Certificate of Compliance 9009 for Model FL 10-1 MACDENALD.C E Transportation Branch 80/03/28 2pp
- --8004100254 Certificate of Compliance 9009, Ravisian 6 for Model FL 10-1 MACDONALD, C E Transportation Branch 80/03/28 ip

DOCKET 71-9010 MODEL NL1-1/2, NL INDUSTRIES, INC

- 8004220225 Requests that Certifificate of Compliance 9010 be revised to provide option for method of capping off neutron shield espansion tank Certificate available in Central Files only Fee encl WILLIAMB.C E NL Industries. NL Nuclear Div 80/02/21 2pp
- 8004280166 Requests renewal of Certificate of Compliance 9010 for Model NLI-1/2 Forwards drawings & "BAR, MLI-1/2 Spent Fuel Shipping Cask " Drawings & rept available in Central Files only HILLIAMS, C.E. NL Industries, NL Nuclear Div 80/03/07 6pp
- 8004040121 Forwards Revision & to Certificate of Compliance 9010 for Model NLI-1/2 HACDDNALD.C.E Transportation Branch 80/03/24 2pp
- --8004040124 Certificate of Compliance 9010.Revision 6 for Model NLI-1/2 MACDDNALD.C E Transportation Branch 80/03/26 6pp

- DOCKET /1-9011 MODEL (-MEH 00-00004, TRANSPORTATION, DEPT OF
- 8004100270 Ack BOC127 request for Type B(U) certification for Models 181375, 181361 % E-NFH-00 00704 shipping containers Review concludes packages authorized by certificates of Compliance 5796 % 9011 meet IAFA requirements for Type B(U) packages MACDONALD, C.E. Transportation Branch 80/03/25 ip
- DOCKET 71-9015 MODEL TH-8. TRANSNUCLEAR, INC
- 8004030104 Notifies of expiration of Certificate of Compliance 9015 for Model TR B To continue using package should submit renewal application 5 fee MACDONALD.C C. Transportation 3ranch 80/03/14 ip
- DOCKET 71-9016 MODEL TN-9 , TRANSNUELFAR, INC
- B004030100 Notifies of expiration of Certificate of Compliance 9016 or Model TN 9 To continue using package, should submit renewal application % fee MACDOMALD.C E Transportation Branch 80/03/14 ip
- DOCKET 71-9017 MODEL BU-7, GENERAL ELECTRIC CO
- B004070076 Requests listing as user of Model BU-6 PENNEY, J A Brookhaven National Laboratory B0/03/06 1
- 8004020143 Forwards amend request to NRC for revision of Certificate of Compliance 9019 re authorized contents & specs for outer 55-gallon drum & inner la-gallon drum used to construct BU-7 package W/o encl KAPLAN,A L General F)ectric Co , Nucleai Energy Products Div 80/03/10 ip
- 8004180515 Forwards application for Amend T-8 to Certificate of Compliance 9019 for Model RU 7 Supporting documentation attached Fee encl
 KAPLAN.A L. General Electric Co., Nuclear Energy Products Div 80/03/14 41pp
- --8004180522 Application for Revision 3 to Certificate of Compliance 9019, revising drum specs & authorized content * General Electric Co , Nuclear Energy Products Div 80/03/14
- --BOD4180925 Application to amend ficense GNM-54 to authorize transport of SNM in Mode)s BU-6 % BU-7 as described in Mod 23 to App D
 TSCHAECHE, A N General Electric Co 74/05/24 10pp
- BO04220789 Forwards revised pages constituting Mod 1 to application for Amend T=8 for certificate of compliance for Model BU-7 KAPLAN.A L General Electric Co., Nuclear Energy Products Div BO/03/17 App
- --8004220770 Revised pages constituting flod 1 to application for Amend T-8 for certificate of compliance for Model BU-7 KAPLAN, A L Oeneral Flectric Co . Nuclear Energy Products Div 80/03/17 Spp
- B0040B0093 Forwards Revision 4 to Certificate of Compliance 9019 for Model BU-7
 MACDOMALO, C. E. Transportation Branch B0/03/IB 2pp
- --8004080097 Certificate of Compliance 9019 Revision 4.for Model 8U-7 MACDONALD C E Transportation Branch 80/03/18 4pp
- DOCKET 71-9020 MODEL SL-10-1, NUCLEAR CONTAINERS, INC
- 8004100036 Forwards Revision 3 to Certificate of Compliance 9020 for Model SL-10-1 MACDDNALD,C E Transportation Branch 80/03/28 1p
- --800410003B Certificate of Compliance 9020 Revision 3 for Model SL-10-1 MACDONALD C E Transportation Branch 80/03/28 4pp

DOCKET /1 9029 MODEL 674 TECHTICAL OPERATIONS, INC.

800408090' Requests ragi fination as user of Models 476 & 676E D'ROURKE Color Alanco Disentifi, Laboratory 80/02/29 1

DOCKET 71 7036 HODLE | U 1 SQUINCE PRODUCTION EQUIPMENT CO

8004030)4T Notifies or expiration or Certificate of Compliance 9036 for Model of 1 To continue using package, should submit consolidates application refused number of drawings showing only significant safety features I renewal fee MACDUNALDICE Transportation Branch 80703717 ip

DOCKET 71-9039 MODEL 715 TECHNICAL OPERATIONS, INC.

8004280129 Forwards application for renewal of Certificate of Compliance 7039 for Model 715 MUNRO.J J Fechips (Technical Operations, Inc.) 80/04/11 ip

-8004280133 Application for renewal of Certificate of Compliance 9039 ror Model 715 * Tech/Ops (Technical Operations: Inc.) 80/04/11 34pp

DOCKET 71-9043 MODEL NNEU, MAVY, DEPT OF

800407006B Notifies or expiration of Centificate of Compliance 9043 for Model NiPU To continue using package should submit renewal application MACDUNALD.C E Transportation Branch B0/03/17 ip

8004300082 Responds to 800317 ltr Requests discontinuation as user of Model NIPU
GROVES, K. L. Navy Dept or 80/04/04 ip

DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO

8004250303 Requests registration as user of Models CNS-1-13C & CNS-1-13C ONS-1-13C ONS

DOCKET 71-9045 POPEL GE-1000, GENERAL ELECTRIC CO

8004020300 Notifies of expiration of Certificate of Compliance 9045 for Model GE-1000 Continued use requires submittal of renewal application % ree MACDUNALD.C E Transportation Branch 80/03/14 1p

DOCKET 71-9046 MODEL GE-1100, GENERAL ELECTRIC CO

8004030009 Notifies or eparation of Certificate of Compliance 9046 for Model GE-f100 To continue using package, should submit renewal application & fee MACDONALD. CE Transportation Branch 80/03/14 ip

DOCKET 71-9049 MODEL GF-500. GENERAL ELECTRIC CO

B004010061 Requests renewal of Certificate of Compliance 9049 for GE Model 500 shipping container Forwards consolidated application for certification supporting tenewal request Updated drawings submitted to NRC on 800208 CUNNINGHAM.C F General Electric Co 80/02/21 jp

--8004010065 "GE Shield Container, Model 300 " * General Electric Co 80/02/21 13pp

8004020304 Notifies of expiration of Certificate of Compliance 9049 for Model GE-500 Continued use requires submittal of renewal application & fee MACDONALD, C.E. Transportation Branch 80/03/14 ip

DOCKET 71-9050 MODEL GE-900, GENERAL FLECTRIC CO

8004030114 Notifies of espiration of Certificate of Compliance 9050 for Model 0E-900 To continue using package, should submit consolidated application, drawings & renewal fee MACDONALD.CE Transportation Branch 80/03/14 ip

DOCKET /1-906/ MODEL BCL -3

8004070389 Requests registration as user of Model BCL-3 package FIT2SINMONS.T R Fnergy, bept of 80/03/13 tp

DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF

8004040092 Responds to 791112 ltr re registration for Model N-55 packaging Must have approved GA program prior to registration as user of package Vendor ref to approved GA program is not acceptable MACDONALD.C E Transportation Branch 80/03/07 ip

DOCKET 71-9072 HODEL GAHC-1. GENERAL ATOMIC CO

8004040C05 Notifies of expiration of Certificate of Compliance 9072 for Kodel GAHC-1 To continue using package, should submit consolidated application drawings 2 renewal fee MACDONALD.C E Fransportation Branch 80/03/14 1p

DOCKET 71-9073 MODEL OH-142, NUCLEAR PACKAGING, INC

8004100228 Forwards Revision 2 to Certificate of Compliance 9073 for Model GH-142 MACDONALD.C E Transportation Branch 80/03/28 2pp

--8004100230 Certificate of Compliance 9073, Revision 2. for Model OH-142
MACDONALD, C E Transportation Branch 80/03/28 4pp

DOCKET 71-9079 MODEL HN-100 SERIES 2, HITTMAN NUCLEAR & DEVELOPMENT

8004070010 Forwards Revision 4 to Certificate of Compliance 9079 for Model HN-100.Series 2 MACDONALD, C E Transportation Branch 80/03/17 2pp

--8004070014 Certificate of Compliance 9079, Revision 4, for Model AN-100, Series 2 MACDUNALD, C.E. Transportation Branch 80/03/17 3pp

DOCKET 71-9080 MODEL HN-600. HITTMAN NUCLEAR & DEVELOPMENT CORP

8004040276 Requests registration as user of Model HN-600 TRIMBLE.D C Arkansas Power & Light Co 80/02/19 ip

8004070018 Forwards Revision 3 to Certificate of Compliance 7080 for Model HN-600 MACDONALD C E Transportation Branch 80/03/17 2pp

--80040/0020 Certificate of Compliance 9080, Revision 3, for Model HN-400 MACDONALD, C E Transportation Branch 80/03/17 3pp

DOCKET 71-9081 MODEL CNS(-1600, CHEM-NUCLEAR BYSTEMB, INC

8004250303 Requests registration as user of Models CNS-1-13C & CNS-1-130 TRIMBLE D C Artansas Power & Light Co 80/03/24 1p

DOCKET 71-9089 MODEL NH-100 S. HITTMAN NUCLEAR & DEVELOPMENT CORP

BOD40B0107 Forwards Revision 2 to Certificate of Compliance 9089 for Model HN-100S ' MACDONALD.C E Transportation Branch B0/03/18 2pp

--8004080112 Certificate of Compliance 9089, Revision 2, for Model HN-1008 MACDONALD, C E Transportation Branch 80/03/18, 2pp

DOCKET 71-9094 MODEL CHSI-14-195-H, CHEM-NUCLEAR SYSTEMS, INC.

8004210415 Advises that facilities will be using Models CN6-80A,7-100, CNSI-21-300 & CNSI-14-195-H for shipment of radioactive matls

DOLAN-J E Indiana & Michigan Electric Co. 80/03/17 ip

- DOCKET 71-9096 MODEL CNS1-21-300, CHEM-NUCLEAR SYSTEMS. INC
- B004210415 Advises that facilities will be using Models CN6-80A,7-100, CNSI-21-300 & CNSI-14-195-H for shipment of radioactive
- matls DDLAN, J E Indiana & Michigaπ Electric Co 80/03/17
- DOCKET 71-9105 MODEL RAD-WASTE CR I, CHEM-NUCLEAR SYSTEMS, INC
- 8004250302 Requests registration as user of Models CSN-6-101 & CSN-15-160B
- COONEY, M J Philadelphia Electric Co 80/03/28 1p
- DOCKET 71-9111 MODEL CN4-80A, CHEM-NUCLEAR, INC.
- 8004210415 Advises that facilities will be using Models CN6-80A.7-100, CNSI-21-300 & CNSI-14-195-H for shipment of radioactive
 - DOLAN, J E Indiana & Michigan Electric Co 80/03/17 ip
- DUCKET 71-9113 MODEL 7-100, CHEM-NUCLEAR SYSTEMS, INC
- 8004210415 Advises that facilities will be using Models CN6-80A.7-100. CN5I-21-300 & CNSI-14-195-H for shipment of radioactive
 - DDLAN, J E Indiana & Michigan Electric Co 80/03/17 1p
- DOCKET 71-9122 MODEL 18-450, CHEM-NUCLEAR SYSTEMS, INC
- 8004070254 Notifies that response to 800129 ltr re Certificate of Compliance 9122 will be transmitted by 800315 REYNOLDB.L E Chem-Nuclear Systems, Inc 80/02/29 lp
- 8004090091 Submits results of review of use of Model 18-450 in response to NRC 800127 ltr Container has not been used for shipment of radioactive matis requiring NRC approval during 1979 & cannot be used during forseeable future REYNOLDE.L E Chem-Nuclear Systems. Inc 80/03/04 2pp
- DOCKET 71-9130 MODEL NP-50-XXL, NUCLEAR PACKAGING, INC
- 8004220184 Forwards Drawing X-20-200D in support of Revision 2 amends to SAR for Model NP 50 Describes application of optional const math configurations
 HAELBIG, R J Nuclear Packaging, Inc. 80/02/25 Spp

- --8004220189 "Transportation Shield Type A.Models 50-1 5L.50-2 5L, 30 & 50-4-0L " Sheet 1 of 2 * Nuclear Packaging. Inc 78/08/09 ip
- ~-8004220193 "Transportation Shield Type A.Models 50-1 5L,90-2 5L,90-% 50-4 GL " Sheet 2 of 2 # Nuclear Packaging, Inc. 78/08/09 1p
- DOCKET 71-9132 MODEL 1-3, NUCLEAR PACKAGING, INC
- 8004080205 Ack receipt of complete application for Model T-3 package Based on vendor 800125 ltr.NRC believes that all outstanding issues have been resolved NRC is preparing approval & safety evaluation for package MACDDNALD, C E Trensportation Branch 80/03/20 1p
- DOCKET 71-9135 HODEL CENTURY, GAMMA INDUSTRIES
- 8004020025 Forwards items for insertion into application for NRC certificate of compliance for Century model devices mfg by Gamma Industries App C detailed drawings 2 revisions for Pages 0 2,7 74 7 78 encl RIGHARDSON: H D Nuclear Systems, Gamma Industries Div 80/02/27
- DOCKET 71-9142 MODEL 2526. MONSANTO RESEARCH CORP
- 8004030354 Requests approval to ship Pu~23B in quantities greater than 20 but no greater than 100 Ci in DDT Spec 20 SC-4 shipping containers Pu~23B sources will be at least double—encapsulated in metal containers & will be leak tested TAYLOR, R R Monsanto Research Corp 80/03/05 ip
- --8004030357 "Model 2526 Shipping Container * Mansanto Research Corp 80/03/05
- 8004210019 Forwards Revision O to Certificate of Compliance 9142 for Model MRC-20WC MACDONALD, C.E. Transportation Branch 80/04/03 19
- ~-8004210021 Certificate of Compliance 7142 Revision O for Model MRC-2 MACDONALD, C.E. Transportation Branch 80/04/03 2pp
- DOCKET 71-9853 MODEL ORNL BNL NBS UN FUEL CONTAINER, ENERGY.
- 8004070247 Forwards recommended changes to NBB unitradiated shipping containers for approval per Certificate of Compliance 9853 TRAVIS.N H Energy, Dept of 80/02/21 2pp

--8004100431 SECY-80-146

- COMMISSION MEETING RECORDS 8004010016 Transcript of 800319 meeting in Washington, DC re NRC enforcement program Pp 1-59 * Commission 80/03/19 59pp --8004010017 SECY-B0-139 Describes various types of enforcement actions re request for Commission approval of general statement of enforcement policy policy STELLO.V Diffice of Inspection & Enforcement, Office of the Director 80/03/13 39pp --8004010021 Endorses objective re development of strong, explicit enforcement program Requests mod of coordination statement to include benefits, costs & Commission guidance requirements
 HALLER.N M Office of Management and Program Analysis BO/03/10 200 8004020022 Transcript of 800319 Affirmation Session 80-11 in Washington, DC Pp 1-5 * Commission 80/03/19 3pp 8004020024 Transcript of 800319 hydrogen control meeting in Washington, DC Pp 1-92 * Atomic Safety and Licensing Board Panel 80/03/19 92pp --8004020028 SECY-80-107 (FRN)
 Establishes technical bases re interim hydrogen control requirements for small containments Technical discussions DENTON, H R Dffice of Nuclear Reactor Regulation 80/02/22 8004020091 Transcript of 800321 meeting w/citizen group on TMI cleanup in Washington, DC Pages 1-94 * Commission 80/03/21 56pp 8004090098 Transcript of 800321 Affirmation Session 80-12 in Washington DC Pp 1-2 * Commission 80/03/21 2pp 8004090179 Transcript of 800324 meeting in Washington, DC re briefing on policy issues in emergency planning rule Pp 1-70 * Commission 80/03/24 71pp 8004090261 Transcript of 800331 meeting in Bethesda, MD re-briefing on two approaches to treatment of inventory differences in nuclear mati accounting Pp 1-52 Viewpraphs encl * Commission 80703/31 55pp 8004100033 Transcript of 800313 Affirmation Session 80-10 in Washington.DC Pp 1-5 * Commission 80/03/13 5pp --8004100039 SECY-80-095 Recommends NRC approval of FR publication of enci notice of denial of petition for rulemaking 2-5 BHAPAR:H K Office of the Executive Legal Director. 80/02/14 8004100429 Transcript of 800331 meeting in Bethasda,MD re physical protection of irradiated reactor fuel in transit Pp 1-33 * Commission 80/03/31 33pp
- JO4100431 SECY-80-166
 Recommends NRC approval of amends to IOCFR73 for immediately effective requirements re physical protection of irradiated fuel in transit for publication in final form Draft FR notice encl
 DIRCKS, W J Office of Nuclear Material Safety & Safeguards 800A170345 Transcript of AIF 800402 briefing in Washington, DC Pg 1-53 * Commission 80/04/02 54pp --9004170350 Forwards "Rept to AIF Policy Committee on Followup to TMI Accident," re draft NUREO-0660 Large number of requirements proposed by plan can & should be reduced LEG.B Atomic Industrial Forum 80/02/22 3pp --8004170352 "Rept to AIF Policy Committee on Followup to TMI Accident, by Working Oroup on Action Plan Priorities & Resources * Atomic Industrial Forum 80/02/29 100pp 8004180137 Transcript of 800410 briefing on waste mgt technical regulations in Bethesda.MD Pp 1-28 * Commission 80/04/10 29pp 8004240471 Transcript of 800414 meeting in Washington.DC to discuss 8ECY-80-139 & SECY-80-130A Pp 1-59
 * Commission 80/04/14 60pp 8004240476 Transcript of Commission & ACRS 800411 joint meeting in Hashington, DC Pp 1-43 * Commission * ACRS - Advisory Committee on Reactor Bafeguards 80/04/11 43pp 8004250276 Transcript of 800415 briefing in Bethesda: MD on status of environ qualification review for electrical components at operating power reactors Pg 1-78
 * Commission 80/04/15 79pp 8004250344 Transcript of 800410 affirmation session in Bethesda.HD re 8ECY-79-6-18 # Gommission. 80/04/10 App ADVISORY COMMITTEE ON REACTOR BAFEQUARDS ACRE
- 8004020111 Certified summary of ACRB Site Evaluation Subcommittee 791220 meeting in Washington.DC re recent policy changes & implementation in area of siting & emergency planning * ACRS Advisory Committee on Reactor Bafeguards 80/02/09 13pp.
- --8004020114 Discusses conflicts in guidance & interpretation re offeit emergency plans per review of NUREO-0376, NUREO-0388 & draft NUREO-0410 QDDWIN, A V. Alabama, State of 79/11/14 25pp
- --8004020120 Forwards comments on "Basis for Emergency Action Levels for Nuclear Power Facilities." Minor events having no effect on public health is safety do not warrant consideration of public officials or agencies

 JURGENSEN,R W American Electric Power Co , Inc 79/11/30 4pp
- --8004020123 Comments on NUREO-0610 recommends four classes of emergence action levels implant occurrence emergency alert, site smergency & general emergency WARD, J E Atomic Industrial Forum. 79/11/28 14pp.
- ---8004020128 Comments on NUREC-0610 draft estimate too low Experience indicates that, using draft examples of initiating condition, fraquency would be six to ten times per yr rather than once or twice or the Director 79/11/27.

- --BQ04080661 Forwards comments on proposed Reg Guide I 97.Revision 2 format of Table 2 % 3 should be reversed so that purpose appears first Variable types D & E should be deleted from scope TAYLUR, J H Babcock & Wiltox Co 79/11/06 6pp
- 8004100392 Summary of 234th ACRS 791004-05 meeting in Washington, DC w/table of contents & Apps 1-16

 * ACRS Advisory Committee on Reactor Safeguards 79/12/04
 140on
- 8004100554 Discusses reactor siting criteria & response capabilities for potential accidents Prompt info on accident releases & likelihood of releases is important Suggests postulating accidents at listed sites to compare potential hazards WILSON,R Plant Systems Branch 79/12/20 3pp
- BOD4110147 Comments on proposed rule 10CFR90 language is ambiguous in places More clarification & numerous editorial changes suggested GRENDON. I Affiliation Unknown 79/12/29 4pp
- 8004140030 "On History of Evolution of LWR Bafety in US " OKRENT,D ACRS - Advisory Committee on Reactor Bafeguards 80/04/10 950pp
- 8004140035 Draft natification of ACRB 800207 meeting in Washington DC to discuss annual rept to Congress on NRC safety research program & proposed NRC plans for study of addl safety features for Zion Units i & 2 & Indian Point Units 2 & 3 HOYLE, J C ACRB Advisory Committee on Reactor Safeguards 80/03/12 5pp
- 8004140042 Summary of ACRB Subcommittee 791104-07 meeting repreparation of annual rept on reactor safety research Related matis & list of attendees encl 4 ACRB Advisory Committee on Reactor Safeguards 79/12/04 2ipp
- 8004140053 Notification of ACRS Subcommittee on B&W Water Reactors B00304 meeting in Washington.DC to continue discussion of transients of once-through steam generators Portions of meeting may be closed to protect proprietary info MCYLE.J C ACRS Advisory Committee on Reactor Safeguards 80/02/ii 3pp
- 8004140056 Notification of ACRB Subcommittee on LERs 800123 meeting w/NRC Ofc of Analysis & Evaluation of Operational Data in Washington.DC to discuss evaluation of LER info HOYLE, J C ACRB Advisory Committee on Reactor Safeguards 79/12/20 ip
- 8004140063 Notification of postponement of ACRS Subcommittee on LERs 800123 meeting HOYLE,J C ACRS - Advisory Committee on Reactor Befeguards 80/01/11 ip
- 8004140089 Notice of ACRB Subcommittee on ATWS 800125 open meeting in Washington, DC to discuss proposed resolution of ATWS HOYLE, J C ACRB Advisory Committee on Reactor Bafeguards 79/12/20 ip
- 8004140121 Comments re ACRB Site Evaluation Subcommittee 771220 meeting on emergency planning Research required to define magnitude of activity releases in reactor accidents & realistic distances for emergency planning rones ORTH, D A E I du Pont de Nemours & Co , Inc. 80/01/10 4pp
- BOO4140466 Summarizes evaluation & questions stemming from 791113 visit to OETR site Believes greatest need is for tectonic syntheses, both local & regional THOMPSON, O.A. Affiliation Unknown 79/12/12 2pp
- 8004i50002 Notification of ACRS Ad Hoc Subcommittee on TMJ-2 Accident Action Plan 800305 meeting in Washington, DC to consider Draft 3 of NRC plans for implementing recommendations of President's Commission HDYLE, J C. ACRS - Advisory Committee on Reactor Safeguards 80/02/13 3pp
- B004150005 Notification that ACRS Ad Hoc Subcommittee on TMI-2 Bulletins & Orders B00303 meeting is recheduled until B00304 ACRS Subcommittee on B&W Hater Reactors B00304 meeting has been postponed indefinitely HOYLE, J C ACRS Advisory Committee on Reactor Safeguards B0/02/19 ip

- 8004150006 Responds to recommendations of NRC Special Inquiry Group re ACRB activities Agrees w/recommendation to retain ACRB in strengthened, modified role & concurs w/some criticism Addresses specific criticisms PLESSET.M S ACRB - Advisory Committee on Reactor Safeguards 80/03/12 2pp
- B004150010 Requests that memorandum identifying safety research needs for use of Ofc by Nuclear Regulatory Research & other groups be automatically sent to ACRS Research requests re TMI-2 accidents should be reviewed in broad perspective PLESSET.N S ACRS Advisory Committee on Reactor Safeguards B0/01/15 1p
- 8004150016 Summarizes review of near-term OL items from Draft 3 of NUREO-0660. "NRC Action Plans Developed as Result of TMI-2 Accident " Near-term OL items provide satsfactory basis for resumption of licensing PLEGET.M S ACRS Advisory Committee on Reactor Safeguards 80/03/11 Spp
- 8004150017 Notification of ACRS Subcommittee open 800107 meeting in Washington DC to discuss procedures for conduct of ACRS activities & strengthening ACRS role in regulatory process HOYLE, J C ACRS Advisory Committee on Reactor Safeguards 79/12/17 1P
- 8004150046 Recommends verification testing of dacay heat removal under upset conditions in near-term OL plant test programs PLESSET, M S ACRS Advisory Committee on Reactor Bafeguards 80/03/11 1p
- 8004190077 Notification of ACRS Bubcommittee 800109 meeting in Washington DC to continue discussion re preparation of ACRS Annual Rept to Congress on NRC Reactor Safety Research Program HOYLE, J C ACRS Advisory Committee on Reactor Bafeguards 79/12/17 2pp
- 8004150iii Notification of ACRS Bubcommittee on D&W Water Reactors 800i08 menting in Washington.DC to discuss sensitivity to transients of once-through steam generator & other features of D&W designed nuclear plants HDYLE.J C ACRS Advisory Committee on Reactor Safeguards 79/12/17 3pp
- B004190114 Nutification of AGRS Ad Hot Subcommittee on YMI-2 Actident Action Plan B00107 meeting in Washington, DC to discuss NRC "Draft Action Plan for Implementing Recommendations of President's Commission & Other Studies of TMI-Accident "HOYLC, J C AGRS Advisory Committee on Reactor Bafeguards 79/12/17 3pp
- B004150122 Comments on proposed rule 10CFRBO requirements for local & state approval of licensee emergency plans can result in subversion of entire open licensing process by small group of individuals

 STEINDLER.M J Argonne National Laboratory 80/01/02 3pp
- 8004150208 Summarises comments resulting from ACRS 239th meeting review of NRC Task Force on Bulletins & Orders recommedations of TMI-2 & generic evaluations of loss of feedwater transients & small break LUCAB PLESSET, MS ACRS Advisory Committee on Reactor Safeguards, 80/03/11. 3oc
- 8004150212 Notification of AGRS 800110-12 meeting in Washington.DC to discuss proposed recommendations to Congress on NRC safety Research Program, NRC action plans to implement THI-2 accident studies & proposed changes in siting criteria. HOYLE.J C AGRS Advisory Committee on Reactor Bafeguards 79/12/20 6pp
- B004i50222 Notification of ACRS Subcommittee on Metal Components U00123-24 meeting in Washington.DC to review status of unresolved generic safety items involving pressure vessels, steam generators & other pressure boundary components HOYLE, J. C ACRS Advisory Committee on Reactor Safeguards 77/12/20 ip
- 8004130228 Notification of ACRS Subcommittee on ECCS 800326 meeting in Washington.DC to discuss analysis of small break LDCAs on Washinghouse upper head injection reactors Portions of meeting may be closed to protect proprietary info HDYLE,J C ACRB Advisory Committee on Reactor Safeguards 80/03/05 3pp
- 8004i90230 Discusses ACR8 79iii5 meeting re extreme external phenomena Subcommittee Technical quality of Seismic Bafety Margins Research Program seems high Determining strain rate should be major objective THOMPSON.O A Affiliation Unknown, 79/12/14 ip

- 8004150232 Notification of ACRS Subcommittee on Concrete & Concrete Structures 800325-26 meeting in Washington,DC to review user needs in structural engineering HOYLE,J C ACRS Advisory Committee on Reactor Safeguards 80
- 8004150236 Notification of ACRS Subcommittee on ATHS 800326 meeting in Washington,DC to continue discussion on proposed resolution of ATHS Portions of meeting may be closed to protect or AND rottions or meeting may be closed to protect proprietary info HOVLE,J C ACRB - Advisory Committee on Reactor Bafeguards 80/03/05 3pp
- 8004150240 Notification of ACRS Ad Hoc Subcommittee on Natural Circulation Heat Removal 800325 meeting in Washington DC to review info on natural circulation & bleed & feed heat removal sys & determine areas where info is inadequate HOYLE.J C ACRS Advisory Committee on Reactor Safeguards 80/03/05 3pp
- 8004150241 Notification of proposed ACRS subcommittee, working group & full committee meetings 800103-0306 HOYLE.J C ACRS Advisory Committee on Reactor Safeguards 79/12/17 4pp
- 8004130244 Notification of proposed ACRS subcommittee,working group & full committee meetings 800123-0412
 HOYLE, J C ACRS Advisory Committee on Reactor Safeguards BO/01/17 4pp
- 8004150245 Notification of ACRS 800306-08 meeting in Washington, DC to discuss implementation of NRC "Action Plans for Recommendations of Presidents' Commission" & other studies of TNI-2 accident HOYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/02/19 6pp
- 8004150249 Addition to agenda for ACRS Ad Hoc Subcommittee on TMI-2 Accident Implications 800305 meeting to consider addl engineered safety features, including installation of molten core crucibles under reactors HOYLE_J.C. ACRS Advisory Committee on Reactor Safeguards 80/02/2: 19
- 8004150254 Notification of ACRS Subcommittee on TMI-2 Accident Implications 800305 meeting in Washington, DC re installation of molten core crucibles at Indian Point Units 2 & 3 & Zion Units 1 & 2, HOYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/02/13 3pp
- 8004150292 Transcript of ACRS Subcommittee on Reactor Safety Research 800409 meeting in Washington, DC Pp 1-80, * ACRS Advisory Committee on Reactor Safeguards 80/04/09 80pp
- 8004150306 Transcript of ACRS Subcommittee on Power & Electrical Sys 800409 meeting in Washington, DC Pp 1-B5 * ACRS Advisory Committee on Reactor Safaguards 80/04/09 85pp
- 8004150321 Transcript of ACRS Subcommittee on Regulatory Activities 800409 meeting in Washington.DC Pp 1-133 * ACRS Advisory Committee on Reactor Safeguards 80/04/09
- 8004i60046 Evaluates 7911i9-16 BSMRP meeting re nuclear plants seismic safety. Repts indicate progress & accomplishment Majority of personnel presentations were of high quality. Development of sup for overall assessments doubtful WHITE: M P. White: M P Consulting Engineer 79/12/24 ip
- 8004170320 Transcript of ACRS Subcommittee on B&H Water Reactors 80040B weeting in Mashington.DC re sensitivity of vendor sys to feedwater transients Pp 1-194 e ACRS, Advisory Committee on Reactor Safeguards 80/04/08
- 8004170358 Detailed schedule & outline for discussion re 237th ACRS meeting on 800306-08 in Washington.DC # ACRS Advisory Committee on Reactor Safeguards 80/02/28 3pp
- 8004170361 Apps to minutes of 236th ACRS meeting on 791206-08 in Washington, DC ACRS - Advisory Committee on Reactor Safeguards. 79/12/08 13000
- 8004180003 Comments on ACRS Subcommittee on ECCS/S&D B00103-04 meeting Measured parameters other than pressure are gross indicators of increasing void fraction within pressurized sys Reduced pump speed is alternative to delayed pump tip ACOSTA; A. California Institute of Technology 80/01/08 2pp

- B0041B0017 Schedule & outline for discussion re 238th ACRS meeting on B00207-09 in Washington.DC

 * ACRS Advisory Committee on Reactor Safeguards 80/01/28 4pp
- 8004180025 Notice of receipt of addl info for ACRS Subcommittee on TMI-1 Nuclear Power Plant 800131-0201 meeting in Middletown. PA Designated federal employee is R Muller Also corrects first word in last paragraph HDYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/01/18 ip
- 8004180032 Notice of change in agenda for ACRS Subcommittee on ATMS 800125 meeting Meeting will include matters involving proprietary info Portion of meeting may be closed to protect proprietary info POULE.J C ACRS Advisory Committee on Reactor Safeguards 8000145 200
- B004iB0036 Notification of ACRS Subcommittee on THI-1.B00i31-0201 meeting w/util & public in Middletown.PA Portions of meeting may be closed to protect proprietary info HOYLE,J C ACRB Advisory Committee on Reactor Bafeguards B0/01/11 3pp
- BOO4180044 Natification of ACRS Subcommittee on Reliability & Probabilistic Assessment BOO206 meeting in Washington. DC to discuss consistency of component failure experience w/WASK-1400 projection HOYLE, J C ACRS Advisory Committee on Reactor Safeguards BO/01/14 ip
- 8004180049 Notification of proposed ACRS subcommittee & working group meetings
 HDYLE.J.C ACRS - Advisory Committee on Reactor Safeguards
 80/01/19 4pp
- B004180074 Summary of 238th ACRS meeting on B00207-09 in Washington, DC Includes items tentatively scheduled for consideration at 239th ACRS meeting on B00306-08
 PLESSET.H B ACRS ~ Advisory Committee on Reactor Safeguards 80/02/22 2pp
- 8004180079 Summary of 237th ACRS meeting on 800110-12 in Washington, DC Includes items tentatively scheduled for 238th ACRS meeting on 800207-09 PLESSET, M S ACRS Advisory Committee on Reactor Safeguards 80/01/24 2pp
- 8004180085 Notification of ACRS Ad Noc Subcommittee on TMI-2 Accident Action Plan 800401-02 meeting in Washington DC to discuss Draft 3 of NUREG-0640 Portions of meeting may be closed to protect proprietary info
 HOYLE, J C ACRS - Advisory Committee on Reactor Safeguards
 80/03/10 3pp
- 8004180190 Transcript of 240th ACRS 800411 general meeting in Washington,DC Pp 1-247 * ACRS ~ Advisory Committee on Reactor Safeguards 80/04/11 254pp
- 8004180406 Notification of ACRS Subcommittee on ECCS & Reactor Fuels
- 8004180481 Comments re ACRS Site Evaluation Subcommittee 791220 meeting on proposed rule 10CFRSO. "Emergency Planning " Efforts to complete plans as early as possible may result in unrealistic deadlines & unnecessary plant shutdowns FOSTER.R F Affiliation Unknown 80/01/12 3pp
- 8004180498 Notification of ACRS Subcommittee on Plant Arrangements 104:180490 Notification of ALRO Bubcommittee on Plant Arrange 800220-21 meeting w/Bandia Labs in Washington, DC to discuss "Final Rept (draft) on Phase I of Generic Task A-17, Bys Interaction in Nuclear Power Plants" & Items re LWRs HOYLE, J C ACRB — Advisory Committee on Reactor Bafeguards HOYLE, J C ACI
- 8004180506 Notification of ACRS Ad Hor Subcommittee on TMI-2 Accident Bulletins & Orders 800303 meeting in Washington, DC to continue consideration of IE bulletins & NRC orders pertaining to TMI-2 accident HOYLE, J.C. ACRS Advisory Committee on Reactor Bafeguards 80/02/11. 3pp
- 8004210001 Transcript of 240th ACRS general meeting in Washington DC on 800410, Pages 1-263 * ACRS Advisory Committee on Reactor Bafeguards 80/04/10, 263pp

- 8004210311 Transcript of Ad Hoc Subcommittee 800326 meeting re natural circulation heat removal in Washington DC Pp 1-269
 * ACRS Advisory Committee on Reactor Bafeguards 80/03/26
 27000
- 8004210313 Transcript of Subcommittee on ATMS 800326 meeting in Mashington, DC Pp 1-215

 * ACRS Advisory Committee on Reactor Safeguards 80/03/26
- 8004220785 Responds to NSSS vendors presentations at ATMS 800125 meeting re Alternative 3A & 4A mods Vendor cost estimates are inflated Both alternative mods should be imposed on all plants
 SAUNDERS S C ACRS Advisory Committee on Reactor Safeguards
- 8004240476 Transcript of Commission & ACRS 800411 joint meeting in Washington, DC Pp 1-43 + Commission + ACRS - Advisory Committee on Reactor Bafeguards 80/04/11 45pp
- 8004290290 Transcript of 800422 subcommittee meeting in Washington, DC re LERs Pp 1-138 * ACRS Advisory Committee on Reactor Safeguards 80/04/22

COMMISSION NRC COMMISSIONERS

- 790B140243 Ack receipt of 790509 Itr to Hendrie re establishment of new safety position in facilities to improve emergency response Discusses review of reactor operator qualifications Invites further suggestions Forwards info re operator bicensing DENTON, H R Office of Nuclear Reactor Regulation 79/07/02 2pp
- --790B140247 Suggests NRC & utils jointly create new safety position in facilities Outlines qualifications & duties STAUDT.H R Bunker-Ramo Corp , Amphenol North America Div 79/05/09 4pp
- 8004020173 Responds to 800210 ltr re device for dispensing iodine in water as thyroid blocking agent NRC looks forward to FDA review of new technique DENTON, H R Office of Nuclear Reactor Regulation 80/03/06 ip
- --8004020179 Discusses nowly designed fodine device used as alternative to potassium oxide for emergency source of thyroid blocking agent in event of accident w/radicactive indine release to atmosphero Device has unlimited storage life POLLEY,R D Omnidine Corp 80/02/15 2pp
- 8004020175 Ack receipt of yearly invitation to speak at ALI-ABA course on atomic energy licensing & regulation in Bept Requests tentative status due to prior commitments HENDRIEJ II Commission 80/03/03 ip
- --8004020199 Extends invitation to Commissioner at luncheon speaker at ALI-ABA course on atomic energy licensing & regulations on 800925
 GREEN,H P Fried, Frank, Harris, Shriver & Kampelman, 80/02/19
- B004030335 Discusses results of encl rept. "NRC Environ Analysis of Nuclear Accidents Is It Adequate " Typical EIS fails to analyse Class 9 accidents despits potential for greatest environ harm & public concern SPETH.0 President of US & Executive Offices B0/03/20 iipp
- --8004030340 "NRC Environ Analysis of Nuclear Accidents Is It Adequate " ENTWISLE,E , WEXLER,D Environmental Law Institute, 80/02/04 200pp
- 8004080037 Provides Subcommittee on Energy & Environ w/updated info ra NRC need for power determinations, in response to 790801 request Electricity demand forecasting techniques are being improved. Supporting documentation encl AHEARNE. J F Commission 80/03/11 App
- --8004080048 Forwards response to 780530 inquiry re NRC need for power determination procedures Need for power determinations made by NRC are part of NEPA reviews required prior to CP or OL issuance
 HENDRIE, J M Commission 78/07/19 10pp
- --8004080059 Forwards excerpts from decisions re need for power MANN.M M Atomic Bafety and Licensing Board Panel 78/06/29 Bon

- --B004080063 Requests info re NRC need for power determination procedures, per NRC 780522 testimony on Nuclear Siting & Licensing Act
 WEAVER, J House of Rep , Interior & Insular Affairs 78/05/30
 3pp
- --8004080066 Asks specific questions re NRC need for power determination, based on J Weaver 780530 inquiry
 UDALL,M K House of Rep , Interior & Insular Affairs 79/08/01
- 8004080070 Summary of 238th ACRS meeting in Washington.DC on 800207-09 PLESECT.M S ACRB - Advisory Committee on Reactor Safeguards 80/02/22 2pp
- 8004080091 Commonts on GAO rept, "NRC More Aggressive Leadership Noeded " Steps are being taken to improve Commission leadership in GAO recommended areas AHEARNE, F Commission 80/03/14 3pp
- ---B0040B010B Comments on OAO rept. "NRC More Agressive Leadership Needed" Steps are being taken to improve Commission leadership in GAO recommended areas Response to rept recommendations enel AHEARNE, J.F. Commission 80/03/14 26pp
- 8004080223 Provides Bubcommittee on Public Works w/info re proposed changes to NRC FYBO base table Carryover funds from FY79 would be applied to priority unfunded tasks identified during post-TMI investigations
 AHEARNE. J F Commission 80/03/07 1p
- --8004080227 Provides Subcommittee on Energy & Environ w/info re proposed changes to NRC FYBO base table Carryover funds from FY79 would be applied to priority unfunded tasks identified during post-TMI investigations AMCARNE.JF Commission 80/03/07 1p
- --B0040B0227 Provides Subcommittee on Nuclear Regulation w/info re proposed changes to NRC FYRO base table Carryover funds from FY77 would be applied to priority unfunded tasks identified during post-THI investigations A
- ~~8004080231 Provides Subcommittee on Energy & Power w/info re proposed changes to NRC FY80 base table Carryover funds from FY77 would be applied to priority unfunded tasks identified during post-TMI investigations AHEARNE.J F Commission 80/03/07 ip
- --8004080234 Provides Bubcommittee on Energy & Water Development w/infore proposed changes to NRC FY80 base table Carryover funds from FY79 would be applied to priority unfunded tasks identified during post-TMI investigations

 AHEARNE, J.F. Commission 80/03/07 4pp
- 8004080243 Provides Subcommittee on Nuclear Regulation w/response to 800213 inquiry concerning NRC actions re federal nuclear waste mgt program
 ANEARNE J F Commission 80/03/06 7pp
- --8004080250 Requests addi info re federal waste mpt program, to clarify NRC testimony at 800123 hearing before Bubcommittee on Nuclear Regulation HART, O Senata, Environment & Public Works 80/02/13 2pp
- 800408026B Forwards list of reactor sites to which FEMA should give priority in making independent estimates of evacuation times, per 800114 memorandum of understanding List includes addl sites not previously discussed.

 AHEARNE, J F Commission 80/03/04 2pp
- G0040B0317 Responds to B00221 inquiry re basis for Commission concurrence in amended agreement between UB & IAEA re mails safeguards. Amend maintains UB nonproliferation policy stds to promote peaceful nuclear cooperation AHEARNE, J.F. Commission 80/03/14 2pp
- --8004080323 Requests views on besis for Commission concurrence in amended agreement between US & IAEA re matls safeguards, Also requests views on Commission expectations re responsibility for supply agreements under amended US & IAEA agreement GHURCH, F Senate, Foreign Relations Committee 80/02/21 5pp.
- 8004090066 Weekly info rept for wk ending 800314 REHM. TA Diffice of the Executive Director for Operations. 80/03/14 29p.

- 8004100507 Discusses priorities re safety, resumption of licensing nuclear power plants & issuing CPs in response to 791121 lit Priority will continue to be given to operating plants as opposed to plants aussiting CPs
 AHEARNE, J F Commission 80/02/12 ip
- --B004100513 Discusses balancing of priorities re licensing & implementation of post-TMI safety recommendations Equally intensive effort should be focused on plants in need of OLs & CPs

 MCCOLLAM, W Edison Electric Institute 79/12/21 2pp
- 8004100592 Heetly info rept for wt ending 800321 REHM.T A Office of the Executive Director for Operations 80/03/25 24pp
- BOD4140392 Provides add1 comments re BO0226 discussion on advanced reactor research program Decision re continuation of NRC advanced reactor safety research program should be separable from DDE development programs
 MENDRIE, J M Commission BO/03/18 ip
- 8004140457 Heekly info rept for week ending 800328 REHM.T.A Office of the Executive Director for Operations 80/04/04 556pp
- BOO4150137 Notifies of reappointment to ACRS for four-yr term beginning BO0401 AHEARNE, J.F. Commission B0/03/11 Ip
- 8004150317 Notifies of re appointment to ACRS for four-yr term beginning 800402 AHEARNE, J. F. Commission 80/03/11 1p
- _ 8004160024 Ack receipt of Recommendation 79-5, re hybrid rulemaking procedures of FTC Indicates that recommendation & encl rept should prove helpful to NRC AMEARNE, JF Commission 80/03/10 2pp
- --B004160030 Forwards Recommendation 79-5, re hybrid rulemaking procedures of FTC Requests NRC support & cooperation re implementation BABCOCK, B L Administrative Conference of the U B 80/01/08 to
- 80041601B6 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415.FR notice encl AMEARNE.JF Commission 80/03/12 ip
- --B004160170 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE.J F Commission 80/03/12 2pp
- --8004160193 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl
 AHEARNE.J F Commission 80/03/12 2pp
- --B004140176 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE, J. F. Commission 80/03/12 2pp
- --8004160200 Requests comments on proposed rulemaking concerning disposal of raddwastes produced by nuclear facilities Comments due by 800415 FR hotice encl AMEARNE, J. F. Commission 80/03/12 2pp
- --8004160202 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by BO0415 FR notice and AHEARNE, J F Commission B0/03/12 2pp.
- --8004160203 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415.FR notice encl
 AHEARNE.J F. Commission 80/03/12 2pp
- --8004160206 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl.

 AHEARNE, J. F. Commission 80/03/12 2pp
- --8004160207 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415.FR notice enci AHEARNE, JF Commission. 80/03/12 2pp

- ~-8004160212 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE, J F Commission 80/03/12 2pp
- --8004160215 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE, J F Commission 80/03/12 2pp
- --B004160220 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by B00415 FR natice encl AMEARNE. J F Commission BD/03/12 Spp
- 8004170112 Accepts invitation to speak to New York Patent Law Association in May HENDRIE, J M Commission 80/02/27 ip
- --B004170117 Extends invitation to be guest speaker in May.at annual dinner meeting for New York Patent Law Association STRASSER, J A Hill & Knowlton, Inc 80/02/18 2pp
- 8004180008 Provides Subcommittee on Nuclear Regulation w/response to 791207 ltr, Question 2 d concerning H R 5809 & 5819 re low level radwaste disposal States should approach waste disposal problem on regional basis AHEARNE, J F Commission 80/03/31 6pp
- --8004180016 Requests response to questions re low level radwaste disposal, for related 800124 & 25 hearings H R 5807 & 5819 encl HART, G Benate, Environment & Public Works 79/12/07 lipp
- B0041B0023 Discusses NRC actions taken in response to recommendations in OAO rept, "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established to verify that serious violations are corrected AHEARNE, J F Commission B0/03/31 4pp
- --BOD4iBO07B Forwards position paper supporting Agreement State program Paper includes comments on advantages of Agreement State vs NRC administering radiation health & safety program TEDFORD.C F Arizona. State of BO/01/23 opp
- ---8004180082 Discusses NRC actions taken in response to recommendations in GAO rept, "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established to verify that serious violations are corrected AKEARNE, J F Commission 80/03/31 4pp
- --BOD41800B6 Provides Subcommittee on Nuclear Regulation w/NRC response to recommendations in GAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established AMEARNE, J F Commission BO/03/31 4pp
- --B004180095 Provides Bubcommittee on Energy & Environ w/NRC response to recommendations in OAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established AHEARNE, J.F. Commission 80/03/31 4pp
- --B004180097 Provides Bubcommittee on Energy & Power w/NRC response to recommendations in GAO rept. "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established AHEARNE, J. F. Commission 80/03/31 4pp
- --BOO41BO100 Provides Bubcommittee on Environ Energy & Natural Resources w/NRC response to recommendations in GAO rept, "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established AMEARNE, J F Commission 80/03/31 4pp
- --B004iB0i0i Discusses NRC actions taken in response to recommendations in OAD rept. "Radistion Control Programs Provide Limited Protection" Insp followup procedures will be established to verify that serious violations are corrected AHEARNE. J F Commission B0/03/31 4pp
- --8004180103 Discusses NRC actions taken in response to recommendations in QAO rept. "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established to verify that serious violations are corrected AHEARNE.J F Commission 80/03/31 4pp

- 8004180128 Provides Subcommittee on Energy & Water Development w/ "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bill for FY79 W/o encl AHEARNE, J F Commission 80/03/25 2pp
- --8004180142 Provides Bubcommittee on Energy & Environ w/"Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bili for FY79 W/o encl AHEARNE, J F Commission B0/03/25 2pp
- --B0041B0153 Provides Subcommittee on Energy & Water Development w/ "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization B111 for FY79 W/o encl AHEARNELJ F Commission 80/03/25 2pp
- --8004180164 Provides Subcommittee on Energy & Power w/ "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bill for FY79 AHEARNE, J F Commission 80/03/25 2pp
- ~~8004180175 Provides Subcommittee on Nuclear Regulation w/ "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization 3ill for FY79 W/o enci AHEARNE, J F Commission 80/03/25 2pp
- --8004180185 Forwards "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bill for FY79 W/o encl
 AMERNE.JF Commission 80/03/25 2pp
- --8004180193 Provides Gubcommittee on Environ, Energy, & Natural Resources ω/ "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bill for FY79 AHEARNE. J F Commission 80/03/25 2pp
- --8004180197 "Rept to Congress on Resident Inspector Program "
 OREHER: E Office of Inspection & Enforcement, Office of the Director THOMPSON, S. R., SLIDER, J. E. Teknekron, Inc. 80/03/31
- 8004:80211 Responds to 800128 itr re NRC emphasis on emergency planning for nuclear accidents NRC & FEMA cooperate in devaloping emergency planning rules & related state guidance AHEARNE, J F Commission 80/03/16 ip
- --8004180220 Comments on proposed rule re emergency planning more emphasis should be placed on planning for probability of catastrophic nuclear accident in context of potential danger from nuclear weapons & other possible diasters
 WYDLER.J W House of Rep 80/01/28 ip
- B004180240 Provides Subcommittee on Energy & Environ w/response to B00311 questions for record of subcommittee hearing on FY81 budget request AMEARNE.J F Commission B0/03/28 26pp
- 8004180279 Forwards response to 791206 inquiry re NRC Agreement States program & Church Rock dam failure RI submittal satisfied Atomic Energy Act. Section 274 requirements for admission as Agreement State
 AHEARNE, J F Commission 80/03/17 10pp
- ---B0041B029B Advises that Environ Improvement Board will promulgate implementation of proposed revisions to regulations re health & environ aspects of radiation BACA-T E New Mexico, State of 79/10/18 ip
- 8004180304 Responds to 791120 ltr re certain aspects of NRC proposed new 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories: Procedural Aspects " Need for in altu testing & exploration supported by USOSIN
- ---B0041B0311 Responds to 791120 ltr re certain aspects of NRC proposed new 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories:Procedural Aspects " Need for in situ testing & exploration supported by UBOB, NAB & earth science community AMEARNE, J F Commission B0/03/18 Spp
- --8004180319 Comments on Proposed Rule 10CFR60 multiple geologic testing & exploration unnecessary & costly NRC should support DOE repository development program WYDLER.J W House of Rep., Science & Technology 80/01/20 2pp

- 8004230095 Responds to 800118 ltr re concern & dissatisfaction w/Region 1 workshop on proposed changes in NRC rules on emergency preparedness Memo providing summary of results of four workshops encl Apologites for inconvenience AHEARNE.JF Commission 80/03/21 2pp
- ~~8004230110 Discusses four workshops re proposed emergency planning rule changes held on 800115,17,22 & 24 Rept will be prepared summarizing lessons learned from series of workshops re conduct of public meetings Agenda enci OOLLER,K R Division of Siting, Health & Safeguards Standards 80/01/28 7pp
- ---B004230118 Informs NRC of deep concern & dissatisfaction w/Region I workshop on emergency planning held B00115 Meeting accomplished next to nothing Suggests NRC undertake extensive measures to recover valuable comments & input VANDENBURGH.D E Yankee Atomic Electric Co B0/01/18 2pp
- 8004240528 Forwards point-by-point response to ACRB 800311 rept re near-term OL items from Draft 3 of NUREG-0660 Criteria used in near-term OL reviews are not suitable for all licensees DIRCKS, W J Office of Nuclear Material Safety & Bafeguards 80/04/01 ilpp
- 8004250046 Weekly info rept for wk ending 800404 REHM,T A Office of the Executive Director for Operations 80/04/09 30pp
- 8004280446 Ack receipt of paper, "Practical Development of Safety Requirements " Forwards Rogovin rept W/o encl KENNEDY, R T Commission 80/01/31 ip
- 8004280448 Ack receipt of 800110 telegram Will be unable to attend 15th Intl Nuclear Energy Symposium KENNEDY,R T Commission 80/02/04 ip
- 8004280450 Forwards summary of MIT meeting re Beabrook licensing proceedings W/o encl KENNEDY,R T Commission 80/02/06 ip
- 8004280485 Ack receipt of 800123 ltr re agreement state program Proposals contained in ltr will be helpful in promoting better relationships between NRC & states KENNEDY, R T Commission 80/02/08 ip
- ---8004280459 Discusses need to reaffirm agreement state program Details specific areas where program improvements are required. TELFORD: C F Aprizona. State of. 80/01/23 6pm.
- BOO42B0464 Supports comments contained in ltr published in BOO220 Washington Post Encourages efforts to correct editorial imbalance re nuclear industry KENNEDY,R T Commission BO/02/20 1p
- 8004280468 Ack receipt of rept of Governor's Commission on TMI Will forward Special Task Force Rept on TMI in near future KENNEDY,R T Commission 80/03/05 ip
- BO0428047i Forwards papers W/o encl KENNEDY, R T Commission 79/12/21 ip
- 8004280485 Ack receipt of comments on recent visit to US Shares conclusion that intl cooperation is of increasing importance KENNEDY, R. T. Commission 79/12/21 1p
- --8004280488 Discusses impressions from recent tour of US Necessity of intl cooperation in energy field is of upmost importance HAKANSBON, K Sweden 79/12/11 1p
- 8004290126 Withdraws as speaker at 15th Intl Nuclear Energy Symposium, due to extensive safety reviews following TMI KENNEDY, R T Commission 79/12/28 1p
- 8004290i3i Offers congratulations on reappointment as acting chairman of Japan Atomic Energy Commission KENNEDY,R T Commission 80/01/02 ip
- 8004290134 Extends thanks for copy of proceedings of symposium on "Energy What Now"
 KENNEDY, R T Commission 80/01/29 1p
- 8004290144 Forwards Ragovin Rept W/o encl KENNEDY, R T Commission 80/01/31 ip.

- 8004300231 Extends appreciation for rept. "Intelligence Requirements for the 1980's Elements of Intelligence" KENNEDY,R T Commission 80/01/04 ip
- 8004300233 Ack receipt of T Ipponmatsu paper KENNEDY, R T Commission 79/12/28 ip
- BOO4300591 Responds to invitation to attend lecture on BOO205 Other commitments prevent attendance KENNEDY, R T Commission BO/01/30 1P
- BG04300597 Buggests B00414-17 as best dates for meeting in AZ KENNEDY, R T Commission 79/12/27 ip
- B004300601 Responds to B00312 ltr re NRC research involving human subjects Forwards FYBO program briefs for three projects involving human subject research
 BUDNITZ.R J Division of Reactor Safety Research FIN B-2283
 80/04/15 4pp
- --B004300606 Requests info re NRC research projects involving human subjects Forwards PL 95-622 establishing commission for study of ethical problems in research programs HISHKIN.B President's Comm for Study of Ethical Prob in Med & Bioms & Behav Research B0/03/12 Bpp
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- 8004010002 Notification of contract execution Mod 5 to "Evaluation of Thorium Content of Human Tissues From Grand Junction.Co " Contractor NY Univ Medical Ctr HADEY.H Research Contracts Branch FIN B-5756 NRC-04-76-358 80
- ~~8004010009 Hod 5.extending period of performance & increasing funds to "Evaluation of Thorium Content of Human Tissues From Grand Junction Co"
 HORTON K V Research Contracts Branch POTTER, J P New York
 Univ FIN B-5756 NRC-04-76-358 80/02/25 4pp
- 8004020205 Notification of contract execution Mod 6 to "Bubble Behavior in LMFBR Core Disruptive Accidents " Contractor Univ of VA JACOBS: A Research Contracts Dranch FIN 8-5616 NRC-04-75-316 807/02/15 ip
- --B004020215 Mod å, adding funds, extending term through 800930 & providing addl scope, to "Bubble Behavior in LMFBR Core Disruptive Accidents"

 MORTON.K V Division of Contracts MUNGER, P L Virginia, Univ of FIN 8-5616 NRC-04-75-316 80/02/15 4PP
- 8004030011 Natification of contract execution.Mod 4 to "Mobile Lab " Contractor Hobile Sys MIOOINS.E Administrative Contracts Branch NRC-05-79-257 B0/03/26 tp
- --8004030014 Mod 4, extending delivery schedule for Items E 2 & E 3, to "Mobile Lab"

 MATTIA: M J Administrative Contracts Branch KIMMEL, J J Mobile Bystems. NRC-05-79-257 80/03/26 ip
- B004030020 Notification of contract execution Mod 3 to "Pioneer Uravan Mill Tailings Evaluation " Contractor FC Hart Associates.
 E0gENDATH.P J Technical Assistance Contracts Branch FIN B-6923-9 NRC-02-79-051 B0/03/19 ip
- --8004030023 Mod 3.extending period of performance, to "Pioneer Urayan Mill Tailings Evaluation " DUOHERTY,D J Technical Assistance Contracts Branch FIN B-6923-9 NRC-02-79-051 80/03/19 ip
- 8004030032 Notification of contract execution Hod 2 to "Advanced Process Control " Contractor Science Applications, Inc FOSTER, J M Technical Assistance Contracts Branch FIN B-6930-9 NRC-02-79-043, 80/03/17 jp
- --8004030037 Mod 2, revising statement of work, changing project officer, adding Article 9 to schedule & extending performance period to "Advanced Process Control" DOUGHERTY, D J Technical Assistance Contracts Branch, TREVING, T, Beience Applications, Inc FIN 8-4930-9, NRC-02-79-043-1 80/03/17. 3pp

- B004030040 Notification of contract execution "Lease 10 Class III Sedans"
 FLYNN.M Administrative Contracts Branch NRC-10-80-371 80/05/05
- --8004030044 Contract "Lease 10 Class III Sedans," awarded to We Try Harder, Inc HATTIA:M J Administrative Contracts Branch NRC-10-80~371 80/05/05 6Jpp
- 8004040116 Notification of contract execution, Mod 1 to "Auxiliary & Emergency Feedwater Pump Reliability " Contractor Franklin Research Ctr HOYLE.A Administrative Contracts Branch FIN D-6819 NRC-03-79-161 E0/02/20 1p
- --8004040120 Mod 1.extending performance period to 800630, to "Auxiliary & Emergency Feedwater Pump Reliability "
 PERLMAN. J Division of Contracts ABHTON, A M Franklin
 Institute/Franklin Research Center FIN 8-6819 NRC-03-79-16;
 80/02/20 ip
- B004040154 Notification of contract execution. Mod 2 to "Enhancement of Nuclear Matis Mgt & Bafaguards Sys " Contractor Boeing Computer Sycs Co FOBTER, J M Technical Assistance Contracts Branch FIN B-6902-9 NRC 02-79-050 B0/03/17 Ip
- ~-8004040162 Mod 2,adding Article 9 re utilization of small business concerns & disadvantaged ownership & control.to "Enhancement of Nuclear Matis Mgt & Bafeguards Bys "
 DDUOHERTY,D J Technical Assistance Contracts Branch
 HOPKINS.H R Boeing Computer Services, Inc (subs of Boeing Co)
 FIN B-6902-9 NRC-02-79-050 80/03/17 2pp
- 8004040180 Notification of contract execution, Mod 1 to "Bynthesis of Physical Security & Matl Control & Accounting Assessment Results" Contractor Science Applications Inc FOSTER, J M Technical Assistance Contracts Branch FIN 8-6412-9 NRC-02-79-029 80/03/21 1p
- ~-8004040i86 Mod i,adding Article 9 re utilization of small business concerns & disadvantaged individual ownership & control to "Bynthesis of Physical Security & Matl Control & Accounting Assessment Results "
 DOUGHERTY,D J Technical Assistance Contracts Dranch TREVING,T Science Applications, Inc FIN 8-6412-9 NRC-02-79-029 80/03/21 2pp
- 8004040197 Mod 2.extending performance period.to "Licensing Assistance/ Tailings Mgt Program Technical Evaluation Exxon Highland U Mill " BOUGHERTY.D J Technical Assistance Contracts Branch FIN D-6446-9 NRC-02-79-031 BD/02/29 ip
- 8004040212 Notification of contract execution. Mod 3 to "Cyprus Mines Corp. Hansen Project Hill Tailings Evaluation " Contractor FC Hart Associates EDDEMORTH. P. J. Technical Assistance Contracts Branch FIN B-6927-9 NRC-02-79-056 80/03/19 ip
- --8004040217 Mod 3.extending period of performance to "Cyprus Mines Corp. Hansen Project Mill Tailings Evaluation" DOUGHERTY.D J Technical Assistance Contracts Branch FIN B-6927-9 NRC-02-79-056 B0/03/17 ip
- 8004040435 Notification of contract execution, Mod 2 to "Util Mgt & Technical Resources "Contractor Teknekron Research, Inc MENCZER, W B Technical Assistance Contracts Branch FIN 8-6824 NRC-03-80-105 80/03/07 ip
- --B004040454 Mod 2 changing Article 1 description of work re info to be collected from licensees, to "Util Mgt & Technical Resources" DDUGHERTY, D J Technical Assistance Contracts Branch FIN B-6824 NRC-03-80-105 B0/03/07 6pp
- --8004040464 Forwards eddl info needed to evaluate mgt & technical resources available to licensees Representative of Teknekron will contact licensees by telephone to obtain data

 DENTON H R Diffice of Nuclear Reactor Regulation 80/02/28 9pp
- B004070003 Notification of contract execution, Mod 1, to "Evaluation of Mat1 Interactions for Advanced Reactor Sys " Contractor Aerospace Corp MENCZER, B., Technical Assistance Contracts Branch NRC-03-79-126-80/03/07 ip

;

ļ

- --B004070007 Mod 1.extending period of performance to 800304-0507.to "Evaluation of Matl Interactions for Advanced Reactor Bys "
 DDU0HERTY.D J Administrative Contracts Branch NRC-03-79-126
 80/03/07 ip
- BO04070006 Notification of contract execution, Mod 6 to "Safety Analysis & Experiments for Alternative Reactor Concepts " Contractor Northwestern Univ HAGEY, H Research Contracts Branch FIN A-4064 NRC-04-75-199 BD/03/14 1p

- --B004070009 Hod 6.extending period of performance to two years w/funding.to "Safety Analysis & Experiments for Alternative Reactor Concepts"
 HORTON,K V Research Contracts Branch MINTZER,D Northwestern Univ FIN A-4064 NRC-04-75-199 B0/09/14 App
- BOO4070025 Notification of contract execution Mod 3 to "Study of Consumer Products Containing Radioactive Matl " Contractor Beisnes Applications Inc EDDEMORTH, P.J. Technical Assistance Contracts Branch FIN 0-0280 EDGEWORTH, P J Technical NRC-02-78-045 80/03/20
- --8004070032 Mpd Gradding new task under Article 1.8ection 2 O re assessment of current criteria & regulatory policy for consumer products to "Study of Consumer Products Containing Radioactive Matl" DOUGHERTY, D J Division of Contracts FIN 8-0280 NRC-02-78-043 80/03/20 2pp
- BO04070096 Notification of contract execution.Mod 2 to "Sealing Rock Masses" Contractor Univ of AZ HAGEY.H Research Contracts Branch FIN D-6627 NRC-04-78-271 80/02/22 1p
- --8004070100 Mod 2, adding no cost extension, to "Bealing Rock Masses MORTON, K V Research Contracts Branch CARR, B E Arizona, Un of FIN 8-6627 NRC-04-78-271 80/02/22 2pp. Arizona, Univ 2րր.
- 8004070125 Notification of contract execution "Licensing Assistance/ Socioeconomic Impacts Evaluations," awarded to Bocial Research & Applications EDDEWORTH,P J Technical Assistance Contracts Branch NRC-02-80-032-02 80/02/25 ip
- --8004070140 Contract "Licensing Assistance/Bocioeconomic Impacts Evaluations," awarded to Bocial Research & Applications DDUDGHERTY,D J Technical Assistance Contracts Branch STERLING,A W Social Research Applications Corp
- 8004080105 Notification of contract execution Mod 1 to "Photographic Svcs" Contractor MD Color Photo WIGGINS.E Administrative Contracts Branch NRC-10-80-668 80/03/10 ip
- -8004080127 Mod 1, replacing Wage Determination 74-65, Revision 4 w/Wage Determination 80-17, to "Photographic 8vcs " MATTIA, M J Division of Contracts NRC-10-80-668 B0/03/10
- 8004080237 Notification of contract execution Mod 3 to "Bys Maint Programming " Contractor Intl Business Bucs HAGAN.T F Administrative Contracts Branch NRC-10-79-372 80/03/18 2pp
- --- 8004080241 Mad 3. extending period of performance to "Sys Maint Programming "
 MATTIA.M J Administrative Contracts Branch FLETCHER, O W
 HATTIA.M J Administrative Contracts TUNGTALL, J E Small
 Business Administration NRC-10-79-372 80/03/18 3pp
- 8004080326 Notification of contract execution "Economic Assistance Related to Antitrust Hearings For South TX Antitrust & Commanche Park Antitrust Proceedings," awarded to Transcomm, GLAGGLA.A F Administrative Contracts Branch FIN B-6593 NRC-03-80-129 80/01/14 1p CLACCILA, A F
- --8004080340 Contract "Economic Assistance Related to Antitrust Hearings for South TX Antitrust & Commanche Peak Antitrust Proceedings," awarded to Transcomm, Inc DDUGHERTY, DJ Division of Contracts LERNER.N C Transcomm, Inc FIN B-6593 NRC-03-80-129 80/01/14 5pp
- B0040B0603 Notification of contract execution "Shuttle Bus Syc," awarded to Beltway Limousine Syc, Inc WIGOINB.E Administrative Contracts Branch NRC-10-B0-372 B0/03/28 1p

- --8004060610 Contract "Shuttle Bus Svc." awarded to Beltway Limousine Svc. Inc MATTIA.M J Administrative Contracts Branch ROBERTSON, J Beltway Limousine Service, Inc. NRC-10-80-372 80/04/01
- 80040806i8 Submits Jan 1980 rept on NRC-03-80-105. "Util Mgt & Technical Resources " Efforts concentrated on review & evaluation of licenses submittals Extended contract may be necessary unless utils respond promptly to encl NRC ltr POWERS, J A Teknekron Research, Inc NRC-03-80-105 80/02/6
- BOO4090263 Notification of contract execution, Mod 1 to "Advanced Process Control " Contractor NUSAC, Inc FOBTER, J M Technical Assistance Contracts Branch FIN 8-6437-9 NRC-02-79-043-2 BO/03/17 Ip
- --00040704B5 Mod 1.revising statement of work & extending period of performance to 80070B.to "Advanced Process Control"

 DUDWHTERY.D T Technical Assistance Controls Branch NUBAG, Inc FIN 8-6437-9 & RC-02-79-043-2 80/03/17 3pp LUMB, R F
- 8004100020 Notification of contract execution "Licensing Assistance/ Tailings Mgt Program Technical Evaluation," awarded to JH Kleinfelder & Associates EDOEMORTH.P Technical Assistance Contracts Branch NRC-02-79-031-05 80/03/07 ip
- ~-8004100023 Contract "Licensing Assistance/Tailings Hgt Program Technical Evaluation," awarded to JH Kleinfelder & Associates DOUGHERTV.D J Technical Assistance Contracts Branch J H Kleinfelder & Associates NRC-02-79-031-05 BO MCRAE, C. H 80/03/07
- 8004100187 Notification of contract execution Mod 8 to "Oft of Mgt & Program Analysis Mgt Info Bys Maint Bupport Bycs "Contractor Buall Business Adminstration Subcontractor Logical Technical Bycs Corp HAGAN.T F Administrative Contracts Branch NRC-07-77-178 B0/03/24 1p
- --8004100194 Had B. revising delivery schedule for project status repts.
 to "Ofc of Mpt & Program Analysis Hgt Info Bya Maint Support TO "OFC OF MRY & Program Analysis ngt into Bys Haint Support Bycs" MATTIA: M J Division of Contracts GUIOLEY, J R Bmail Busin Administration ORCENLES, E A Logical Technical Bervice Corp NRC-07-77-178 80/03/24 2pp Small Business
- 8004100339 Notification of contract execution, Mod 4 to "NRC/TMI 810 Rept 8vcs" Contractor JF Holman & Co Inc HAOAN, T.F., Administrative Contracts Branch NRC-10-79-660 80/03/27 Ip
- --8004100342 Mod 4, revising delivery schedule & extending period of performance, to "NRC/TMI BIO Rept Bycs "
 MATTIA:M J Administrative Contracts Branch HOLMAN, J F John F Holman & Co , Inc NRC-10-79-660 80/03/27 2pp
- 8004100354 Notification of contract execution, Mod 1 to "Engineering Assistance Related to Hearings for Bouth TX Antitrust & Commanche Peak Antitrust Proceedings " Contractor RW Beck & Associates
 OLAGOLA-A F Technical Assistance Contracts Branch FIN 8-6523,
 NRC-072-08-0120 PC -- -

--B

- 8004100360 Notification of contract execution, Mod 10 to "Performance Testing for Personnel Dosimatry " Contractor Univ of MI. QUBTAVE, R P Research Contracts Branch FIN B-10490 NRC-01-77-180 80/03/24 ip
- -8004100363 Mod 10.extending period of performance & adding addl work & funding to "Performance Testing for Personnel Dominstry"
 MORTON:K V Research Contracts Branch MULDER, H J Minnesote,
 Univ of, Minneapolis FIN D-10490 NRC-01-77-180 80/03/24
- 8004100366 Notification of contract execution, Mod 3 to "Characterization & Classification of Geologic Faults & Fractures in Appalachian Foldbeit " Contractor FL State Univ GUSTAUF, P. P. QUSTAVE, R P Research Contracts Branch. FIN 8-10539 NRC-01-78-004 80/03/17 ip

- --B004100369 Mod 3, extending period of performance w/no increase in funds.to "Characterization & Classification of Geologic Faults & Fractures in Appalachian Foldbelt"
 MORTON.K V Research Contracts Branch JOHNSON,R M Florida Btate Univ FIN B-10539 NRC-01-7B-004 80/03/17 ip
- BOD4100523 Notification of contract execution. Mod 9 to "Flood Protection " Contractor US Army Coastal Engineering Research Ctr MENCZER, W B Technical Assistance Contracts Branch FIN B-5075 NRC-03-77-006 80/03/20 1p
- --8004100524 Mod 5, increasing funds to "Flood Protection"

 DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-5075

 NRC-03-77-006 80/03/20 ip
- BOO4100829 Notification of contract execution. Mod 1 to "Geotechnical Engineering Case Reviews " Contractor UE Army Corps of Engineers MENCZER. H B Technical Assistance Contracts Branch FIN B-6826 NRC-03-79-167 B0/03/20 ip
- 8004100572 Notification of contract execution.Mod 7 to "Design of IFMIS" Contractor Small Business Administration Bubcontractor Technassociates.Inc HAQAN.T F Administrative Contracts Branch FIN 8-5131 NRC-10-80-395 80/03/i8 ip
- --8004100576 Mod 7, revising delivery schedule of Task 2a, 2b & 3 & extending performance period through 800915, to "Design of IFMIS"

 MATTIA: M J Administrative Contracts Branch TUNBTALL. J E Bmal Business Administration YTHIER, P. Technassociates, Inc FIN B-5131 NRC-10-80-395 80/03/18 2pp
- 8004100996 Notification of contract execution Mod 3 to "Reactor Vessel Irradiation Damage " Contractor Naval Research Lab OLAGOLÁA F Tachnical Assistance Contracts Branch FIN 9-6809 NRC-03-79-148 80/03/28 ip
- --B004100600 Mod 3.ertending period of performance through 800530, to "Reactor Vessel Irradiation Damage" DDUGHERTY, D J Administrative Contracts Branch FIN 8-6809 NRC-03-79-148 80/03/28 1p
- 8004:50166 Notification of contract execution Mod 4 to "Kinetics of Chlorine-Ammonia in Sea Water " Contractor Univ of NC JACOBS, A Research Contracts Branch FIN B-6248 NRC-04-77-119 80/03/13 ip
- --B004150171 Mod 4.extending period of performance for add1 14 months at no extra cost, to "Kinetics of Chlorine-Ammonia in Bea Water"

 HORTON, K Research Contracts Branch HOLCOMB. G R. North Carolina, Univ of FIN 8-6248 NRC-04-77-119 80/03/13 2pp
- 8004210117 Notification of contract execution. Mod 5 to "Programming in Bupport of Payroll Sys Development " Contractor Small Business Adminstration Subcontractor Technassociates, Inc. HAGEN. T.F. Administrative Contracts Branch NRC-10-79-373 883-4-0-8(A)-79. 80/03/18 ip
- --8004210119 Mod 5.changing wording of Articles I & III & extending period of performance through 800530 to "Programming in Support of Payroll Bys Development "
 MATTIA.M J Administrative Contracts Branch TUNBTALL.JE Bmall Business Administration YTHIER.P Tachnessociates, Inc NRC-10-79-373 883-4-0-8(A)-79, 80/03/18 3pp
- 8004230523 Notification of contract execution.Mod 2 to "Subsurface Radar Profiling Study of Maxey Flats.KY, Waste Disposal Region." Contractor Geo-Centers.Inc WDLLETT.B A Research Contracts Branch FIN B-6349 NRC-04-79-190 80/04/02 ip
- --8004230528 Mod 2. extending terms of contract, to "Bubsurface Radar Profiling Study of Maxey Flats. KY. Waste Disposal Region " MORTON. K V. Research Contracts Branch BEERB. R H Geo-Centers, Inc. FIN 8-6349, NRC-04-79-190 80/04/02, 5pp
- 8004240009 Notification of contract execution, Mod 4 to "Thermal Hydraulic Stability Analysis Relating to LUR." Contractor Renssalar Polytechnic Inst JACOBS, A Research Contracts Branch. FIN 8-7230 NRC-03-78-128 80/04/07.

- --8004240015 Mod 4,increasing funds,to "Thermal Hydraulic Stability Analysis Relating to LWR" MORTON,K V Research Contracts Branch FIN B-7230 NRC-03-78-128 80/04/07 ip
- 8004240033 Notification of contract execution, Mod 9 to "Consulting Svcs (AE) Related to Evaluation of Facility Concepts, Cost Estimates & Schedules for Experimental Facilities "Contractor Burns & Roe, Inc MORTON, K V Research Contracts Branch FIN 8-6220 NRC-04-77-097 80/01/09 1pp
- --B004240041 Mod 9, extending terms of contract to "Consulting Sycs (AE)
 Related to Evaluation of Facility Concepts, Cost Estimates &
 Bichedules for Experimental Facilities"
 HORTON, K V Research Contracts Branch PUCILLO, A C Burns & Roe
 Co FIN B-6220 NRC-04-77-097 B0/01/09 ipp
- 8004240047 Notification of contract execution, Mod 4 to "Regional Tectonics & Beismicity of KS " Contractor Univ of KS JACOBS A Research Contracts Branch FIN D-6172 NRC-04-77-017 BD/04/03 1p
- ---B004240051 Mod 4.extending terms of contract, to "Regional Tectonics & Seismicity of KB" MORTON, K V Research Contracts Branch HORWITZ, F D Kansas, Univ of FIN B-6172 NRC-04-77-017 B0/04/03 App
- 8004240535 Notification of contract esecution Mod 3 to "Assessing Capability of Existing Pu Facilities to Withstand Natural Phenomena "Contractor NM Newmark CLAGGLA: A F Technical Assistance Contracts Branch FIN B-6150-9
- --8004240542 Mod 3, extending period of performance w/no add1 funding to "Assessing Capability of Existing Pu Facilities to Withstand Natural Phenomena"

 BUOWERTY, D J Technical Assistance Contracts Branch FIN B-6150-9 NRC-03-78-150 80/03/31 1p
- 8004240546 Notification of contract execution, Mod 5 to "Review & Evaluation of Piling Foundation Proposed for Category I Structers at Bailly Generating Station " Contractor NH Newmark OLAGOLALA F Technical Assistance Contracts Branch NRC-03-78-150 80/04/02 ip
- --8004240553 Mod S, extending period of performance w/no add1 funding to "Review & Evaluation of Piling Foundation Proposed for Category I Structures at Bailly Generating Station " DUUGHERTY, D J Technical Assistance Contracts Branch NRC-03-78-150 80/04/02 1p
- 8004250014 Notification of contract execution, Mod 2 to "Fire Protection Research Program " Contractor Underwriters Labs WALLETT, 6 A Research Contracts Branch FIN 8-6197 NRC-04-77-122 80/04/04 1p
- --8004250022 Mod 2.providing 1-yr.no-cost extension to."Fire Protection Research Program "
 MORTON,K V Research Contracts Branch BARTON,R D Underwriters Laboratory FIN B-6197 NRG-04-77-122 80/04/04 1p
- 8004250035 Notification of contract execution, Mod 1 to "Bafety Assessment of Concrete Nuclear Structures" Contractor MIT HAGEY, H Research Contracts Branch FIN B-6618 NRC-04-79-181 80/03/31 1p
- ---B004280043 Mod i.extending period of performance & including addl workscope w/addl funds.to "Bafety Assessment of Concrete Nuclear Btructures" MORTON.K V Research Contracts Branch DUMMER.O H Massachusetts Institute of Technology FIN B-6618 NRC-04-79-181 B0/03/31
- B004290109 Notification of contract execution: "Orievance Review Examiner," awarded to PJ La Macchia TRA0ESER, C M Administrative Contracts Branch NRC-10-80-488 80/03/20 ip
- ---B004290113 Contract "Orievance Review Examiner," awardad to PJ LaMacchia PERLMAN, J Administrative Contracts Branch LAMACCHIA,P J LaMacchia, P J. NRC-10-80-688 80/03/20 6pp
- 8004270507 Notification of contract execution "Environ Monitoring Program W/State of ME," awarded to State of ME BAISDEN.L Research Contracts Branch FIN B-5113 NRC-05-80-274 80/01/01 ip

- --8004290514 Contract "Environ Montoring Program W/State of ME,"
 awarded to State of ME
 MORTON, K V Research Contracts Branch PETIT, M R Maine, State
 of FIN B-5113 NRC-05-80-274 B0/01/01 14pp
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 7812120219 Responds to 780316 FDIA request for SECY77-268, SECY77-268A.
 SECY77-268D. SECY77-268C & OPE memo Portions of documents
 Withheld (ref IOCFR9 15 & 2 790)
 FELTON.J M Division of Rules and Records 78/12/05 3pp
- 7906010118 FOIA request by UCS for all documents re Task Action Plans A-40 & A-41.info on seismic issues prepared for SEP & insp repts for Beaver Valley WEISB.E R Sheldon, Harmon & Weiss 79/03/19 2pp
- 800422023B Forwards IE Bulletin 79-09. "Failures of GE-Type Ak-2 Circuit Breaker in Bafaty-Related Sys " Bulletin should be sent on 790417 to all power reactor facilities w/OL or CP Draft itr to licensees enci Bulletin not encl MOSELEY,N C Division of Reactor Operations Inspections 79/04/16
- --8004220245 Forwards draft IE circular, "Uncontrolled Speed Increase of Reactor Recirculation M9 Bet Resulting in Rapid Power Increase " Requests comments Distribution sheets for IE Bulletin 78-14 encl URDAN.E L Division of Reactor Operations Inspections 79/03/01
- --B004220253 Forwards IE Bulletin 78-06, "Defective Cutler-Hammer, Type M Relays w/dc Colis " Bulletin should be sent to all facilities w/DL or CP Draft ltr to licensees encl THORNBURG, H D Division of Reactor Operations Inspections 78/05/26 2pp
- 7909050241 IE Bulletin 78-06. "Defective Cutler-Hammer.Type M Relays w/DC Coils"

 + Office of Inspection & Enforcement, Office of the Director 790934 4 40
- 7909290207 IE Insp Rept 30-05982/79-01 on 790614 No noncompliance noted Major areas inspected air & water samples, CAMPHELL,M , MCGINNESS, J , MCCLINTOCK,R O Region i, Philadelphia, Office of the Director 79/06/20 3pp
- 7911140251 Requests amend of Matl/Byproduct License 34-01055-03 authorizing addition of CK Yin as user of Cc-60 source Amend fee encl STEARNEC B Riverside Methodist Hosp Columbus OH 01610 79/10/11 Bpp
- 7911200274 Mati/Duproduct License 34-01055 03 for Riverside Methodist Hosp is amended per 791004 ltr. Amend 14 changes Condition 12 authorizing C Yin. J Dohorques. BM Rahman & OC Taylor as users VACCA. P C Licensing Management Branch. 79/10/31 1p
- 8003310090 Responds to FOIA requests for documents re glant safety identified by accession & rept number, author, description & number of pages Forwards documents listed in App A Documents 5 & 26 partially withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 80/03/03 8pp
- 8004010033 Responds to FOIA request for winning proposal in response to RFP-R8-NRR-80-102, "Energetic Thermal Interactions, Recriticality & HTOR Accident & Transient Coolant Flow "Contractor notified to decide whether rept is proprietory FELTON.) M Division of Rules and Records 80/03/19 ip
- 8004010038 FOIA request for Purdue Research Foundation winning technical proposal submitted in response to RFP-RS-MRR-80-102. "Energetic Thermal Interactions, Recriticality & HTGR Accident & Transient Coolant Flow "RAUNER, L M Affiliation Unknown. 80/02/29 ip
- 8004010049 Responds to FOIA request for document entitled, "Director FBI Communication 10112Z Apr 1979 " Forwards requested document FBI director Apr 1979 memo to White House Bituation Room re TMI enci FELTON, J M Division of Rules and Records 80/03/19 3pp
- BOO4010054 FOIA request for document forwarded by RJ Brady entitled. "Director FBI Communication 102112Z Apr 1979 "POWER.D F. Affiliation Unknown BO/03/07 1p

- BOO4010056 Responds to FOIA request for documents re NRC comments on DEB written by ORNL or ANL re location, design, capacity or const of cooling water intake structures Forwards documents listed in App A Draft site study encl FELTON. J M Division of Rules and Records BO/03/19 22pp
- 8004010060 F01A request for documents re NRC commments on DEB written by DRNL or ANL re location, design, capacity or const of cooling water intake structures

 HARKAWIK, D P LeBosuf, Lamb, Leiby & MacRae 80/02/27 2pp
- 8004010163 Responds to FOIA request for seven documents related to earlier request under FOIA-79-520 Forwards documents listed in App A Bafeguards manual NEDD-14502, withheld (ref FOIA Exemption 4)
 FELTON, J H Division of Rules and Records 80/03/18 3pp
- BO04010171 FDIA request for info missing from matls sent under FDIA-79-520 on B00130 Info includes GE 741129 ltr to NRC.Safeguards Manual NEDD-14502 & 14502-1 & NEDP-10173-9, GE 720705 ltr to NRC & NEDD-10178 GUIGO.C Pollution & Covironmental Problems, Inc B0/02/20 1p
- BOO40102B1 Responds to FOIA request for NRC document. "Proposed Interim Hydrogen Controls Required for Small Containments." SECY-BO-107 Forwards requested document W/o encl FELTON.J M Division of Roies and Records BO/03/24 1p
- 8004010282 FOIA request for NRC document, "Proposed Interim Hydrogen Controls Required for Small Containments," SECY-80-107 KOWKABANY, B M Durns & Roe Co 80/03/06 ip
- 8004020192 FOIA request for Education & Human Development, Inc winning technical proposal submitted in response to RFP R8-EDD-80-502, "Study & Review of Issues Concerning Equal Employment Opportunity at NRC "
 RAUNER, L M Advanced Technology, Inc 80/02/29 lp
- BOO40202BB Responds to FDIA request for NUREO/CR-1263 Rept is free to participants in ongoing NRC hearings only Document may be purchased from NRC FELTON, J H Division of Rules and Records BD/03/27 ip
- 8004020290 FOIA request for NUREO/CR-1263. MUFFLER.R T FOI Bervice B0/03/11 1
- 8004030302 FOIA request for info re thorium residuals in West Chicago, IL. RAPKIN, A Illinois, State of 80/03/04 2pp
- 800403030B "Aerial Radiological Survey of West Chicago, IL." BOYNS, P.K., FRANKHAUSER, M., HENDRICKB, T.J. EG & Q. Inc. E00-1183-1730 78/08/31 20pp
- --8004030312 Forwards miscellaneous memos & minutes on Reed-Keppler Park Advisory Committee meeting including minutes. JA Pagliara trip repts & recommendations for departmental action to IL Health Dept ALLAN.J.M Region 3, Chicago, Fuel Facility & Materials Safety Branch 77/06/15 lipp
- --8004030316 Summary of Reed-Keppler Park Committee 770322 meeting at ANL PAGLIARD, J A Region 3, Chicago, Office of the Director 77/04/18 14pp
- ---B0D4030319 Summary of Reed-Keppier Advisory Panel 770511 meeting at ANL PAGLIARO, J A Region 3. Chicago. Office of the Director 77/05/20 14pp.
- --B004030321 Requests that position re NRC jurisdictional responsibility concerning licenses issued to Lindsey in late 1740's be developed due to situation visibility & interest of State of IL IE will be unable to develop further info in matter THORNBURG, H D Office of Inspection & Enforcement, Office of the Director 76/10/12, 2pp
- ---8004030324 Discusses source matl (thorium) in Reed-Keppler Park & West Chicago sewage treatment plant. NRC does not have jurisdiction over Kerr-McGee Corp to require decontamination BECKER, J M Office of the Executive Legal Director. 76/10/12.
- --8004030327 IE Investigation Rept 76-01 re thorium residue found in uncontrolled locations. West Chicago, IL, for 760709, 12-16, 22 & 30 JORGENSEN, B. L., JANUSKA, A. G., PAGLIARO, J. A. Region S, Chicago, Defice of the Director 76/08/20

- --8004030328 "Environ Assessment re Kerr-McGes Chemical Corp.West Chicago Chemacterization of Geohydrology & Subsurface Chemistry " # Argonne National Laboratory 78/06/30 33pp
- 8004030304 Responds to FOIA request for document, "Environ Aspects of Commercial Radwaste Mgt.US DOE Info Rept SECY-79-264.US/NRC " NRC has been unsuccessful in locating rept NRC rept. SECY-79-264 does not pertain to radwaste mgt FELTON.J M Division of Rules and Records 80/03/28 ip
- 8004030307 FOIA request for document. "Environ Aspects of Commerical Radwaste Mgt.US DDE Info Rept.SECY-79~264.UB/NRC " LYNXH.J X Montana, Univ of 80/01/29 ip
- 8004030310 Responds to FOIA request for NUREO-0610. "Basis for Emergency Action Level Ouidelines." & NUREO-0578. "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations." Forwards requested documents K/o encl FELTON.J M Division of Rules and Records 80/03/28 ip
- 8004030314 FOIA request for NUREO-0610, "Basis for Emergency Action Level Guidelines," & NUREO-0578, "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations " ARP.D Affillation Unknown 80/03/20 ip
- 8004040422 Forwards application for source matt license involving storage only Fee encl PODHURST,B W Edlow International Co 14864 79/11/29 ip
- --8004040427 Application for source matl license, authorizing storage of 1.643,400 kgs U in form of UF-6 & 762,300 kgs U in form of U-308 EDLOW, J Edlow International Co 14864 79/12/04 25pp
- --8004040432 Responds to 791129 application for authorization to store U in East St Louis. It. Requests handling, emergency radiation safety, survey & program auditing procedures Application review will continue upon receipt of info BASSIN.N Licensing Management Branch 80/02/06 2pp
- --B004040437 Responds to B00206 request for info re application for authorization to store source matl in East Bt Louis, IL Forwards handling radiation safety, emergency & survey procedures Lists actions to be taken if contamination found PODHURBT, BW Ediow International Co B0/02/11 26pp
- --8004040442 Forwards revised procedures re storage of source matl in response to NRC 800211 request Procedures address areas considered deficient by NRC PODHURBT: BW Ediow International Co 15459, 80/02/13 35pp
- 8004070001 Responds to FOIA request for info re radioactive effluents, esposures, decommissioning & future plans concerning CYTR in Pharr.8C Forwards documents listed in App A. Documents 17 & 41 partially withheld (ref FOIA Exemption 6) W/o encl. FELTON.J M Division of Rules and Records 80/03/28 6pp
- 8004070002 FOIA request for info re radioactive effluents exposures, decommissioning & future plans concerning CVTR in Pharr. SC Facility is in state of limited decommissioning BURGEY.B Grass Roots Organizing Workshop 80/01/25, 1p
- 8004070004 Responds to FOIA request for info re violations of federal law concerning storage of radioactive mati on St Petersburg properties NRC has no documents concerning request State of FL should be contacted FELTON.J M Division of Rules and Records. B0/03/28, 1p
- 8004070008 FOIA request for info re violations of federal law concerning storage of radioactive matl on St Petersburg properties ROBERTS.O.W. Cone, Owen, Wagner, Nugent, Johnson, Hazouri & Roth. 80/03/20. ip
- B004070012 Forwards response to FOIA request for NUREQ-0550, Revision 1. "Std Distribution for Unclassified US NRC Publications." FELTON, J M Division of Rules and Records 80/03/28 ip
- 8004070016 FOIA request for NUREO-0550, Revision 1, "Btd Distribution for Unclassified UB NRC Publications" COFFIN.J. Resources Publishing Co 80/03/20 1p
- 8004080046 Responds to FOIA request for documents re extraordinary nuclear occurrence concept, including proposed rulemaking, regulations & rules adopted by AEC Forwards documents listed in App A FELTON.J.M. Division of Rules and Records 80/03/18 5pp.

- -8004080060 Forwards draft Dfc of General Counsel paper recommending adoption of rule re waivers of defenses & extraordinary nuclear occurrences Lists changes to rule resulting from public comments & consultation windustry W/o enci PRICE.E R Atomic Energy Commission 48/10/03 2pp
- --B0040B0076 Forwards exchange of correspondence between AEC & CK State Univ.OH State Univ & RI AEC to ability to waive defenses in indomnity agreements in view of state immunity from public liability
 PRICE, E R Atomic Energy Commission 69/09/16
- --8004080080 Ack receipt of 690808 ltr re Amend 4 to Indemnity Agraement E-9 Provides conditions & exceptions to Amends 4 & 5 Legal opinion re state immunity from public liability encl KAMM.R B Oxlahoma State Univ 69/08/22 4pp
- ---8004080084 Provides info to assist in resolution of 690822 questions re proposed Amend 4 to Indemnity Agreement E-9 Requests legal opinion from state legal official re DK State Univ governmental immunity & legal disability to effect waiver PRICE, E R Atomic Energy Commission 69/08/08 3pp
- --8004080095 Ack receipt of ltr re proposed Amend 2 to Indemnity Agreement E-43 Provides explanation re application of Article II.Paragraph 2 (b) to basic indemnity agreement Requests legal opinion PRICE, E.R. Atomic Energy Commission 69/06/17 2pp
- --8004080098 Ack receipt of ltr re proposed Amend 2 to Indemnity Agreement E-8 Provides explanation re application of Article II Paragraph 2 (b) to basic indemnity agreement Requests legal opinion Atomic Energy Commission 69/06/23 2pp
- ---8004080110 Draft ltr responding to 680703 comments re publication of proposed amends re financial protection requirements to indemnity agreements DOT concerns have been resolved by adding language clarifying effective rule PRICE ER Atomic Energy Commission 69/07/18 1p
- ---B0040B0115 Confirms &B1231 telcon re walver of defenses endorsement Halver endorsements described in amends will be effective to all financial protection policies on 681030 FIBHER,R J Hartford Insurance Group &B/12/31 ip
- --8004080117 Forwards sample endorsement to be used by nuclear liability pools to waive defenses in accordance w/AEC regulations Endorsement will be effective 681030 Two forwarding ltrs enc l MARRONE, J Nuclear Energy Liability Insurance Association 68/12/12 5pp
- --8004080120 Summary of 481021 Meeting 2350 re amend to code concerning criteria for determination of extraordinary nuclear occurrence & waivers of defenses General Counsel has been designated to take appropriate action
 MCCOOL:W B Atomic Energy Commission 48/10/23 2pp
- --B004080123 Summary of AEC/industry 780611 conference re Price-Anderson indemnity waivers of defenses List of attendees encl HOLLOWAY, C J Atomic Energy Commission 68/06/11 14pp
- ---8004080124 Statement re amend to indemnity regulations presented at AEC/industry &80&11 conference ZARIN.M S Power Authority of the State of New York 68/06/11
- --8004080130 Comments on regulations implementing 1966 Price-Anderson amends Commission should rescind approval of insurance policy forms containing 2-yr discovery provision XAHN:R D Affiliation Unknown 67/04/06. 3pp
- --8004080133 Forwards complaints from state educational institutions re regulations concerning indemnity agreements Submits revision of waiver portion of regulation W/o encl SLOSS.C 8 Atomic Energy Commission 69/11/20 2pp
- --8004080134 Comments on proposed regulations concerning financial protection requirements & indemnity agreements re criteria for determination of extraordinary nuclear occurrence Requests deletion of nuclear exclusion clause from policy LEVINSON, C.F. Affiliation Unknown 68/06/07 ip
- ---8004080136 Rept of Price-Anderson Committee. Drafting Subcommittee re criteria for extraordinary nuclear occurrence & texts of waivers of defenses
 - Atomic Industrial Forum 68/06/05 9pp

- ---B0040B0142 Forwards formal statement presented by M Zarin at AEC/industry 4B0611 conference 3 Natl Lead Co 6B0612 ltr commenting on proposed amend to indemnity regulations Ltr only Bnci PRICE, E R Atomic Energy Commission 6B/06/19 1p
- --B0040B014B Discusses 680611 meeting re proposed amend of indemnity regulations AEC regulations afford reasonable protection No different claims are foreseeable in event of extraordinary nucloar occurrence
 BNOWN.B H NL Industries, Inc. 68/06/12 2pp
- ---B0040B0173 Forwards diaft ltr inviting participation in 680611 industry moeting to review new waiver of defenses amends & tentative list of invitees No agenda has been developed SALTIMAN.J Atomic Energy Commission 68/05/07 7pp
- --8004080179 Summarizes ACC 680429 info meeting re proposed amend for extraordinery nuclear occurrence Commission approved publication of proposed amend MCCOOL.N B Atomic Energy Commission 68/05/01 lp
- --8004080184 Forwards &80423 memo is proposed amend to code requirements concerning extraordinary nuclear occurrences Ltrs should be circulated for Commission consideration at early info meeting MCCOOL.W B Atomic Energy Commission AEC 785/101 &8/04/24
- ---8004080188 Submits three changes to proposed amend for code requirements re extraordinary nuclear occurrences Requests meeting w/Commission to approve notice of proposed rulemaking for FR publication SCHUR.3 H Atomic Energy Commission 68/04/23 3pp
- --8004080192 Responds to AEC 680412 ltr re two proposed changes in draft amend re extraordinary nuclear occurrences Proposed amends are acceptable Memo route slip encl
 TAYLOR, 0 H AFL-CIO 68/04/17 2pp
- --8004080196 Forwards two 670117 drafts of criteria for determination of extraordinary nuclear occurrence Drafts dtd 661207 & 08, 670113,16 & 19 enc1 NESTERN.P Atomic Energy Commission 67/01/17 61pp
- ---8004080202 Forwards draft of criteria for determination of extraordinary nuclear occurrence Draft is proliminary & intended for use at 670119 meeting Lists positions to be incorporated in preparation of proposed Draft I VALLERIO.J Atomic Energy Commission 67/01/18 12pp
- ---8004080204 Discusses insurance liability in event of extraordinary nuclear occurrence High radiation levels will result in injury to people & in loss of use of property Draft criteria for human radiation offects encl
 PATTERSON.E Atomic Energy Commission 67/01/27 5pp
- ---8004080208 Summary of 680219 meeting re proposed amend concerning extraordinary nuclear occurrence Commission requested that personnel discuss proposed amend w/labor representatives Two drafts of criteria for waiver encl
 MCCOOL.W B Atomic Energy Commission 68/02/27 App
- --B0040B0211 Forwards 670310 draft of proposed criteria for Price-Anderson waiver of defenses Basic objective is to establish & maintain good public relations Draft dtd 670321 encl
 DUNNINGO M Atomic Energy Commission 67/03/14 14pp
- --8004080216 Draft memo discussing criteria for extraordinary nuclear occurrence Forwards six draft repts re-criteria WESTERN,F Atomic Energy Commission 67/03/31 39pp
- --8004080222 Discusses drafts on waiver of defense Agrees to discuss changes in 670403 draft & need for special category for transportation DUNIING.0 M Atomic Energy Commission 67/04/25 ip
- 8004080052 FOIA request for documents re extraordinary nuclear occurrence concept including proposed rulemaking regulations & rules adopted by AEC OVERDORFF.J S Affiliation Unknown 80/02/12 1p
- 8004080709 Responds to FOIA request for Science Applications Inc rept re safety of ionization (radioactive) smoke detectors NUREO/CR-1156. "Environ Assessment of Ionization Chamber 8moke Detectors Containing Am-241." is available in PDR FELTON.J M Division of Rules and Records 80/03/31 ip

- 8004080713 FDIA request for Science Application Inc rept re safety of ionization (radioactive) smoke detectors CASEY.T E Minnesota, Univ of, Minnespolis 80/03/19 ip
- 8004090023 Partial response to FDIA request for safety/accident repts for Rockwwell Intl Energy Sys Group & safety/accident rates in radioactive matis handling at Rockwell Intl Belence Ctr Forwards NRC insp rept in App A W/o encl FELTON.J M Division of Rules and Records 80/04/01 2pp
- B004090026 FOIA request for safety/accident repts for Rockwell Intl Enorgy Bys 8 safety/accident rates in radioactive matls handling at Rockwell Intl Science Ctr TROY, M Affiliation Unknown B0/03/06 2pp
- 8004090044 Partial response to FOIA request for NRC license issued to US Radium Corp, license application & insps conducted within last three yrs Forwards documents listed in App A Insp info will be forwarded FELTON, J M Division of Rules and Records 80/03/31 2pp
- B004090050 FD1A request for NRC license issued to US Radium Corp of Bloomsburg.PA.license application & insps conducted within last three yrs
 TDMKING.D Affiliation Unknown 80/02/27 ip
- 8004090129 FOIA request for access to entire contents of each issue of weekly highlights printed by NRC or AEC during 1974-1976 POWER, D.F. Affiliation Unknown 80/03/08 ip
- 8004090136 Responds to FDIA request for access to contents of each issue of weekly highlights printed by NRC or AEC during 1974-1976 No 1974 & 1975 repts exist All 1976 repts discharged No records are available subj to request FELTON.J M Division of Rules and Records 80/03/27 1p
- B004090144 FOIA request for written interpretations by NRC general counsel re NRC regulations,10CFR40 4(h),10CFR40 4(k) 5 10CFR40 13(h) 0IRQUARD,P R Affiliation Unknown 80/03/05 2pp
- 8004090150 Responds to FOIA request for written interpretations by NRC general counsel re NRC regulations, 10CFR40 4(h), 10CFR40 4(k) & 10CFR40 13(b) No written general counsel interpretations or Commission authorizations exist FELTON.J M Division of Rules and Records 80/03/27 1p
- B004090353 Responds to FGIA request & 800331 telcon for license application & license issued to Pharmatopes. Inc License has not been issued Request should be resubmitted in approx 30 days FELTON, J M Division of Rules and Records 80/04/01 ip.
- BOO4090362 FOIA request for radioactive matts license application & license issued to Pharmatopes, Inc. MCDDNALD, D. D. Nuclear Pharmacy, Inc. 80/03/21 ip
- 8004070425 Forwards Rogovin Rept in response to FOIA request W/o encl Becond vol of rept will be published in Apr FELTON, J M Division of Rules and Records 80/03/27 ip.
- 8D04090486 FOIA request for Rogovin Rept SHILDBDD, D S. Affiliation Unknown 80/03/05 Ip.
- 8004100048 Responds to FOIA request for 8 Fishkin 800124 FOIA request & NRC response re violation of NRC policy by Equibb employee Forwards 8 Fishkin FOIA request (FOIA-80-44) & NRC response H/o encl FELTON.J M Division of Rules and Records 80/04/01 1p
- 8004100052 FOIA request for B Fishkin 800126 FOIA request & NRC response re violation of NRC policy by Bquibb employee MUFFLER, R T FOI Service 80/03/26, 1p
- B004140102 PNO-111-76-075 255 patients received radiation overdoses between Man 1975-Jan 1976 Caused by malfunctioning of cobait therapy unit IE plans to initiate investigation Medical consultant has been contacted for assistance, MHITT.K W Region 3, Chicago, Office of the Director 76/04/19 to
- BOOA140106 PNO-III-76-027 255 patients received radiation overdoses between Mar 1975-Jan 1976 Caused by malfunctioning of cobalt therapy unit IE plans to initiate investigation. Medical consultant has been contacted for assistance ALLAN, J M Region 3, Chicago, Office of the Director 76/04/19 20s

- 8004140110 PNO-III-76-031 new info was received re overstposure of 255 patients from improperly calibr teletherapy mathine Caused by human error, rather than progressive instrument deterioration IE will complete investigation LONERQAN, C T , ALLAN, J M Region 3, Chicago, Office of the Director 76/03/07 ip
- 8004140124 Discusses FR natice for public comment re proposed rulemaking on waiver of defenses Requests responses to announcement of ABO611 industry conference re amends SALTZMAN, J Atomic Energy Commission 68/05/20 ip
- --8004140131 Comments on proposed rulemaking submitted by NY City Bar Association supports AEC intention to withdraw 2-ur discovery clause Supports exclusion re claimants w/ abnormally sensitive activities AXELRAD, M Affiliation Unknown 69/01/20 5pp
- 8004150013 Responds to FOIA request for records described in 12 broad subj categories Request does not meet FOIA requirement of reasonable specificity Forwards documents listed in Apps A & B H/o encil FELTON, J M Division of Rules and Records 80/04/03 8pp
- 8004150018 FOIA request for records described in 12 broad subj categories, including laws by which NRC derives authority & all safe methods for disposing of radwaste OANNIS.S Affiliation Unknown 80/01/20 ip
- 8004150026 Responds to appeal re FOIA request for all records re sabotage analyses for spent fuel storage at Morris operation in Morris, IL Info withheld (ref FOIA Exemption 4) Release of info would be contrary to public interest DIRCKS-H J Office of the Executive Director for Operations, 8000A/03 200
- 8004150201 Responds to FOIA request for strip charts re transport of SNM & documents identifying safe havens & law enforcement response capabilities Request terminated due to lack of specificity
 FELTON-J M Division of Rules and Records 80/04/04 ip
- B004150206 FOIA request for strip charts re transport of SNM & documents identifying safe havens & law enforcement response capabilities

 D0U0HERTY, J 8 Dougherty, J B 77/11/16 ip
- BOO4150213 Responds to FOIA request for "Critical Items List" mentioned on Page III-B-6 of Public Bvc of IN description of licensee activities in response to order confirming const suspension List not get submitted FELTON-J M Division of Rules and Records BO/04/03 1p
- 8004150219 FOIA request for "Critical Items List" mentioned on Page III-8-6 of Public Svc of IN description of licensee activities in response to order confirming const suspension LAUDIO.8 Laudig 8 80/03/24 ip
- BOO4170131 FOIA responds to request for winning technical proposals subsitted in response to RFP RB-05D-79-002 & RFP-08D-79-003 Forwards nonproprietary versions of proposals W/o encls FELTON, J M Division of Rules and Records BO/04/08 ip
- 8004170139 FOIA request for winning technical proposals submitted in response to RFF-RS-OSD-79-002 & RFP-RS-OSD-79-003 RIINA, J R. Personnel Assessment & Selection Service, Inc. 80/02/29 in
- 80042:00:3 Responds to FDIA request for documents re Atomic Energy Commission of Canada Request should have been for documents re AECL Forwards documents listed in App A FELTON.J M Division of Rules and Records 80/04/08 2pp
 - 22 IE insp rept on 770826 Noncompliance noted no end-window counter available for insp & licenses representatives t weering hand film badges hicago. Office of the Director 77/08/26

- --8004210033 IE Insp Rept 30-06870/79-01 on 790420 No noncompliance noted Major areas inspected assembly for installation of teletherapy unit MCCLINTOCK,R Region 3, Chicago, Office of the Director 79/06/25 3pp
- 8004210017 FOIA request for ducuments re Atamic Energy Commission of Canada MUFFLERR T FOI Service 000878 80/03/05 1p
- BOO421003B Responds to FOIA request for certain proposals under RFP-RS-NMS 80-024, "Development of Advanced Matl Accounting Sys Simulation Model " No contract has been awarded Nonproprietary proposals will be made available upon award FELTON, J M Division of Rules and Records 80/04/07 ip
- 8004210041 FOIA request for sufficient proposals submitted in response to RFP-RB-MMS 80-024, "Development of Advanced Matl Accounting 8ys Simulation Model "
 EBELP E Allied General Nuclear Services 80/03/18 ip
- 8004210047 Add1 response to FOIA request for NRC license issued to US Radium Corp.application & insps conducted within last three yrs Forwards documents listed in App A FELTON:J M Division of Rules and Records 80/04/08 2pp
- --8004210052 IE Insp Rept 30-05982/77-01 on 770314 No noncompliance noted Major areas inspected organization & administration equipment, facilities, contamination control, liquid waste & stack releases
 8L080DIEN.M J. MCCLINTOCK.H O Region 1, Philadelphia, Office of the Director 77/04/01 5pp
- --8004210057 Draft IE Insp Rept 30-05980/79-01 on 790626-27 No items of noncompliance noted Major areas inspected decontamination activities including tour of grounds review of records & examination of licensee plans for decontamination GLENN.J. COBTELLO, F. MCCLINTOCK, R.O. Region I. Philadelphia, Office of the Director 79/08/28 3pp
- --8004210062 Discusses contamination of package & vehicle in transporting radioactive matl Carrier was responsible for decontamination levels were not high enough to require removal of truck from svc GLENN-J Region i, Philadelphia, Office of the Director 79/10/09 2pp
- --8004210065 Discusses well water sample analysis Samples from test wells were analysed for Ra-226.8r-90 & tritium Results confirm significant levels of Sr-90 in groundwater close to waste tanks Licensee is planning extensive monitoring & cleanup OLENN, J. Region i. Philadelphia. Office of the Director 77/11/01 Spp
- 8004210075 Addi response to FOIA request for info re Pakistani const of gas centrifuge enrichment plant & negotiations concerning efforts to acquire nuclear weapons Two CIA & one Defense Intelligence Agency documents have been located FELTON.J M Division of Rules and Records 80/04/07 ip
- 8004220002 FOIA request for all documents re Riverside Methodist Hosp License 34-10155-03 GERLACH,F T Gerlach,F T 80/02/20 2pp
- 8004220020 Forwards response to FDIA request for all documents re Riverside Methodist Hosp Portions of App B & C partially withheld (ref FDIA Exemption 6 & 5), App C documents withheld (ref FDIA Exemption 5) FELTON J M Division of Rules and Records 80/04/03 10pp
- --B004220028 Forwards Citizen-Journal 750419 article re therapy unit malfunction at Riverside Methodist Hosp ODLAUG, M HEW.Dept of, Food & Drug Administration 75/04/19 2pp
- --9004220033 Forwards PNO-76-027 re reported medical therapy overexposures to 255 patients at Riverside Methodist Hosp ALLAN.J M Region 3, Chicago, Fuel Facility & Materials Safety Branch 76/04/21 ip
- --8004220037 Bummarizes 760421 trip to Riversida Methodist Hosp to investigate melfunctioning cobalt therapy unit Optical distance measuring sys on unit was accurate MCGUNNACLE.H. Region 3, Chicago, Office of the Director 76/04/22 lp

- --8004220044 Discusses 760421 investigation of Co-60 teletherapy radiation overexposure incident at Riverside Methodist Hosp Provides brief description of investigation events, persons interviewed & followup procedures SAENGER, E. L. Cincinnati General Hosp Cincinnati, OH 76/04/23
- --B004220051 Confirms NRC request for info re activities authorized by License 34-01055-03 to complete preliminary evaluation of overexposure incident Lists specific info requested KEPPLER, J O Region 3, Chicago, Office of the Director 76/04/28
- --8004220056 Requests written confirmation of 760428 commitments recalibr teletherapy machine GW Callendine 760430 ltr to clients & JR Flynn 760419 statement encl KEPPLER, J G Region 3. Chicago, Office of the Director 76/04/29
- --BO04220075 Notifies that hose will comply withree stipulations conveyed in NRC 76042B itr re use of 0.66 thimble chamber model & teletherapy machine FLYNN.JR Riverside Methodist Hosp Columbus.GH 76/05/04 ip
- --B0042200B0 Forwards PNO-74-031 providing recent info re reported medical therapy overexposure to 255 pattents ALLAN.J M Region 3. Chicago: Fuel Facility & Materials Safety Branch 74/05/10 ip
- --B004220072 Forwards form itr sent to all physicians having patients involved in radiation overdose at Riverside Methodist Hosp FLYNN.J R Riverside Methodist Hosp Columbus.Oli 76/05/24 2pp
- --8004220097 Discusses 760524 telcon re Riverside Methodist Hosp list of patients receiving 10% or more radiation above recorded dose Deceased list was in error due to computational or typing error

 BAENGER, E. L. Cincinnati General Hosp Cincinnati, OH 76/03/24
- --8004220101 Summarizes medical investigations re Co-60 overexposure incident at Riverside Methodist Hosp Provides description of incident events to date Requests comments re investigation proceedings NSS 740328 lir to FDA enci BAENDER, E.L. Cincinnati, Univ. of, Medical School 76/05/24, App.
- --B004220107 Discusses repts to public re deaths resulting from teletherapy incident at hosp Coordination between interested parties is necessary to avoid duplicative efforts & to avoid violating rights of patients & hosp FLYNN.JR Riverside Methodist Hosp Columbus.OH 76/05/28 2pp
- --8004220120 Informs NRC of need to establish appropriate criteria re radiation injury to patients at Riverside Methodist Hosp Pathologist should aid in development of criteria SAENGER: E.L. Cincinnati, Univ of, Medical School 76/05/28 ip
- --8004220125 Responds to 760927 request for definition of NRC medical consultant role in investigation of radiation exposure incident Consultant will conduct independent investigation & render prof opinion

 KEPPLER, J G Region 3, Chicago, Office of the Director 76/06/02
 200
- --8004220130 Forwards 760609 document, "Rept to Riverside Methodist Hosp, Columbus,OH, Concerning Overtreatment of Patients W/Co-60 Radiation " W/o encl RJ Bhalek 760609 ltrs to J Eckler & EL Baenger encl, BHALEK,R J Texas,Univ. of, Cancer Center 76/06/09 3pp
- ~~8004220132 Authorizes EL Saenger to send coroner NRC evaluation of Riverside Methodist Hosp overexposure incident VOLGENAU.E Office of Inspection & Enforcement, Office of the Director. 76/06/10 ip
- --8004220137 Forwards FR Handrickson 760406 ltr re investigation of overesposure incident at hosp Ltr can be used for relevant info but cannot become part of NRC rept on radiation problem at Riverside Methodist Hosp ECKLER. J Brickler. Evatt. Barton & Eckler 76/06/15 ip
- --B004220164 Discusses IE insp of License 34-01055-03 on 760512 & forwards notice of violation KEPPLER, J. 9 Region 3. Chicago, Office of the Director 76/06/15, 2no

- --8004220167 Notice of violation from insp on 760512 Noncompliance noted 760512 hyproduct & matl inventory included 40 mCi Co-60 sealed caller source not authorized by license & medical use of hyproduct matl by unauthorized person # Region 3, Chicago, Office of the Director 76/06/15 ip
- --9004220174 Discusses request for license amend to add enother physician as authorized user on license No objection if NRC decides to remove present physician as authorized user EL Saenger 760617 ltr re patient oversxposure and METZOER, J R Office of inspection & Enforcement, Office of the Director 76/06/16 7pp
- --8004220178 Forwards physician consultant 740406 rept & 740615 ltr to assist NRC medical consultant in investigation of overexposure incident W/a encl PHILLIP, G A Region 3, Chicago, Office of the Director 74/06/18 ip
- --8004220180 Requests on behalf of JC Kirkham, results of NRC investigation re overexposure incident at Riverside Methodist Hosp MIRMAN, J H Topper, Alloway, Goodman, DaLeone & Duffey 76/05/22, in
- --8004220186 IE Insp Rept 30-00398/76-01 on 760420-22 & 0512-13
 Nøncompliance noted licensed mati was used under supervision
 of unauthorized individual & no leak test was performed from
 730713-740803
 LÜNERGAN, G T , SCHULTZ, W H , FOSTER, J E Region 3, Chicago, Office
 of the Director 76/06/23 24pp
- --B004220176 IE Insp Rept 30-00378/76-02 on 760421-22 Noncompliance noted unspecified individual was permitted to supervise use of Co-Oo teletherapy unit, no record of test results available & no leek test performed from 730713-740803 LONEROAN, O.T., PHILLIP, O.A., FOSTER, J.E. Region 3, Chicago, Office of the Director 76/06/23 37pp
- ---B004220202 Summarizes 760622 telcon re overesposure incident possible approcement actions.

 ALLAN.J H Region 3. Chicago. Office of the Director 76/06/24.

 25p
- --B004220207 Discusses possible svcs of C Lushbaugh as pathologist assisting NRC medical consultant in radiation overexposure incident Provides brise background of C Lushbaugh GREHER.E A Office of Inspection & Enforcement, Difice of the Director 76/06/25 is
- --8004220212 Responds to NRC 760613 ltr re violations noted in IE insp of License 34-01095-03 on 760512 Corrective actions 40 mC1 of Co-60 is therapy source, rather than calibr source Cobatt unit will be used under supervision of Fahey
 TAYLOR O C Riverside Nathodist Hosp Columbia DR 76/06/25

--6

- ---8004220216 Responds to 760622 request for NRC investigation rept on radiation overexposure at Riverside Methodiat Hosp. Rept will be forwarded upon completion.

 BYRASMA, J. Region 3, Chicago, Office of the Director 76/06/30 ip
- --8004220229 Forwards revisions to IE Investigation Rept 30-0398/79-01
 Revisions were result of Ofc of Executive Legal Director
 opinion that investigation rept should not contain hosp
 consultant rept.
 KEPPLER. J G Region 3, Chicago, Office of the Director. 76/07/02
 17pp.
- --B004220231 Forwards draft rept re Riverside Methodist Hosp overexposure incident Rept has not been released to public. W/o encl KEPPLER, J O Region 3, Chicago, Office of the Director 76/07/02
- --B004220236 Forwards PND-76-04 re radiation overexposure incident at Riverside Methodist Hosp.W/a encl.
 ALLAN.J M Region 3. Chicago. Fuel Facility & Materials Safety Branch 76/07/02 ip.
- --8004220242 Forwards two lists of deceased Riverwide Hosp patients to be included w/original list,List 1 contains 28 names that were inadvertently omitted List 2 contains 20 names to complete deceased list of patients treated 750301-76030, FLYNN,J R Cincinnati General Hosp Cincinnati,CH. 76/07/08 ip

- --8004220246 Forwards Riverside Rethodist Hosp consultants repts re overtreatment of patients w/co-60 radiation W/o encl EL Saenger 760709 itr to 0fc of Franklin County Corner encl KEPPLER, J O Region 3, Chicago, Office of the Director 76/07/08 200
- --8004220231 Act receipt of 740425 ltr informing NRC of steps taken to correct violations noted in IE insp rept Corrective actions will be examined during future insp
 KEPPLER, J Q Region 3, Chicago, Office of the Director 76/07/19
- --8004220252 Discusses IE insp of License 34-01055-03 on 760421-22 & forwards notice of violation THOMPSON, D Defice of Inspection & Enforcement, Office of the Director. 76/07/21 2pp
- --B004220255 Notice of violation from insp on 740421-22 Noncompliance noted licenses math was used under supervision of unauthorized individual & Co-60 teletherapy source leak test was not performed from 730713-740803 # Office of Inspection & Enforcement, Office of the Director 76/07/21, 2pp
- --8004220259 Discusses JE insp of License 34-01055-03 on 760420-22 & 0512-13 Rept furnished at 760802 meeting identifies insp & investigation basis Rept will be placed in PDR KEPPLER, J Q Region 3, Chicago, Office of the Director 76/08/02
- --B004220263 Summarizes 760802 briefing on radiation overesposure incident at Riverside Nethodist Hosp Action should be taken to identify & remedy human consequences of dosage errors STRAUSS, P. L. Office of the General Course) 76/08/05 2pp
- ---8004220267 Forwards advance copy of Riverside Hethodist Hosp overexposure incident investigation rept Rept was given to hose for proprietary review on 760802 & is not get in PDR H/o encl KEPPLER.J O Region 3, Chicago, Office of the Director 76/08/04
- --B004220276 Forwards revision to AO 76-7. "Patient Exposures Above Prescribed Amounts During Cobait Teletherapy " HIGGINBUTHAM, L. Office of Inspection & Enforcement, Office of the Director 76/08/06. App
- --8004220282 Forwards draft info re overexposure incident at Riverside Methodist Hosp Requests comments by 760806 W/o encl DAVIS.-J G Office of Nuclear Haterial Bafety & Bafeguards 76/08/06. 1p
- --8004220286 Substitutes info for Conclusion 2.Page 2 of NRC investigation rept re radiation therapy overexposure incident Requests acceptance FLYNN:J R. Riverside Methodist Hosp Columbus.CH 76/08/11 in
- --B004220294 Notifies of 760813 training session to discuss NRC investigation of teletherapy overexposure incident at Riverside Methodist Hosp & related studies NRRELUSICE Region 3, Chicago, Office of the Director 76/08/11 1p.
- --8004220314 Recommends acceptance of Riverside Methodist Hosp 760811 request for change of Conclusion 2,Page 2 to NRC rept EL Basnger 760817 ltr to R Zipf encl. KEPPLER.J. 9 Region 3, Chicago, Office of the Director 76/08/16 300
- --8004220319 Forwards revised Pages 2.5.6 & 10 of NRC investigation rept re Riverside Methodist Hosp teletherapy overexposure incident & draft ltr to hosp Ltr only encl KEPPLER, J © Region 3. Chicago, Office of the Director, 76/08/17 lp.
- ---8004220323 Submits revisions to NRC investigation rept re Riverside Methodist Hosp teletherapy radiation ovarexposure incident Forwards revised investigation rept Rept will be released to public on 760818 W/o encl KEPPLER.J @ Region 3. Chicago, Office of the Director, 76/08/17
- --8004220327 Forwards Riverside Methodist Hosp teletherapy overexposure incident investigation rept & NRC 760817 ltr to hosp. H/o encis
 PHILLIP. C. A Commission 76/08/18 tp
- --8004220329 Forwards NRC investigation rapt re teletherapy radiation overexposure incident at Riverside Methodist Hosp, W/o encl KEPPLER, J. G. Region 3. Chicago, Office of the Director 76/08/20 in

- --8004220330 Provides OH Dept of Health w/NRC investigation rept re teletherapy radiation overexposure incident at Riverside Hathodist Hosp W/o encl KEPPLER. J O Region 3. Chicago, Office of the Director 76/08/20 in
- --8004220337 Forwards NRC investigation rept re Riverside Methodist Hosp radiation therapy overexposure incident W/a encl KEPPLER, J O Region 3, Chicago, Office of the Director 76/08/20 to
- --8004220341 Bubmits questions re teletherapy overesposure incident at Riversida Methodist Hosp Requests response WHITMAN,F M Affiliation Unknown 76/08/20 ip
- --8004220346 Forwards response to Items 1.2.4 & 5 required by NRC 760721 notice of violation FLYNNJ R Riverside Methodist Hosp Columbus.CH 76/08/20 5pp
- --800422035i Forwards final investigation rept re Riverside Methodist Hosp teletherapy overexposure incident W/o encl KEPPLER, J. Ø. Region 3. Chicago, Office of the Director 76/08/23
- --8004220355 Requests NRC investigation rept re Riverside Methodist Hosp telatherapy overexposure incident Forwards NY Timos 760811 article re cobalt radiation overdoses & testimony before Subcommittee on Health & Environ KOCH:E I House of Rep 76/08/24 16pp
- --B004220361 Forwards summary of current status of NRC activities re teletherapy overexposure at Riverside Methodist Hosp Requests concurrence EL Saenger 760910 ltr to county coroner encl THOMPSON, D Diffice of Inspection & Enforcement, Office of the Director 76/09/08 7pp
- --8004220366 Forwards EL Søenger rept re EO Valentine, deceased patient of Riverside Methodist Hosp Death was caused by acute radiation pneumonitis KEPPLER, J O Region 3. Chicago, Office of the Director 77/07/29
- ~~8004220370 Bubmits distribution procedures for NRC medical consultant repts re Riverside Methodist Hosp teletherapy incident ALLAN,J M Region 3, Chicago, Fuel Facility & Materials Bafety Branch 77/07/29 ip
- --B004220374 Discusses consultants' repts concerning cause of deaths at Riverside Methodist Hosp Repts will not be routinely placed in PDR Copies will be sent to coroner & hosp upon request SMITH.0 H Commission 77/08/03 ip
- --B004220380 Forwards EL Søenger 770830 ltr to PD Cameron re former patient at Riversida Methodist Hosp Hosp was requested to expedite requested info Related correspondence encl ALLAN, J M Region 3, Chicago, Office of the Director 77/09/12 7pp
- --B004220387 Forwards inquiry re former Riverside Methodist Hosp patient & request for info SAENGER,E L Cincinnati General Hosp Cincinnati,OH 77/10/06 3pp
- --800422039: Forwards J Flynn response explaining patient exclusion from review group H/o encl SAENGER.E L Cincinnati General Hosp Cincinnati.OH 77/10/21
- --8004220397 Requests that govt send representative to verify computations for patients burned by rediation overdose Recalculations & after-effects do not correspond VOLKEMA, R, H Volkema, Pees & Sarap 77/10/26 1p
- --8004220403 Suggests that Commission responsibilities re Riverside Methodist Hosp overexposures be examined to define course of action for 1E regional & consultant personnel, Repulatory aspects of matter have been resolved KEPPLER, J G Region 3, Chicago, Office of the Director 77/11/11
- --B004220404 Requests that NRC redetermine vol of work to be undertaken by medical consultants in reviewing autopsy cases NRC medical consultants should not advise Franklin County, OH coroner or plaintiffs of complicated oversposure questions BAENCER, E. L. Cincinnati General Hosp Cincinnati, OH 77/11/17

- --8004220409 Forwards proposed response to EI Koch 760824 request for info re radiation overexposure at Riverside Methodist Hosp VOLGENAU.E Office of Inspection & Enforcement, Office of the Director 76/09/10 6pp
- --8004220435 Forwards response to questions posed in 760820 ltr to WA Anders re excessive radiation exposures at Riverside Methodist Mosp Summary section of NRC investigation rept sect
 - enci STRASMA, J Region 3, Chicago, Office of the Director 76/09/13 3pp
- --8004220439 Ack receipt of 760820 ltr informing NRC of steps taken to correct violations in IE insp rept Corrective actions will be examined during future insp
 THOMPSON,D Office of Inspection & Enforcement, Office of the Director 76/09/15 ip
- --8004220442 Responds to 760824 request for info re radiation overexposure of patients at Riverside Methodist Hosp Forwards summary describing NRC investigation EL Sænger 760910 ltr to county coroner encl ROWDEN.M Commission 76/09/20 8pp
- ~~B004220444 Responds to NRC mailgram re calibr of Picker C~9 Co-60 teletherapy unit at Riverside Methodist Hosp Provides table of exposure rates w/values decayed from original measurements for half-life of 5 26 yrs KARTHA.M K Riverside Methodist Hosp Columbus.OH 76/09/27
- --800422044B Submits addl info to further comply w/NRC 760714 order to modify license Forwards hosp organizational chart & job descriptions for Medical Director of Radiation Therapy & Radiological Physicist DDATHRIGHT,N C Riverside Methodist Hosp Columbus,OH 76/11/09 Boo
- --B004220452 Ack receipt of 761107 ltr containing addl info requested re NRC 760714 order to modify license Response is incomplete Requests adequate description of mgt control sys within 20 days EL Saenger ltrs encl MADE. L. Radioisotopes Licensing Granch (Pre 790501) 76/11/18 Gpp
- --8004220458 Responds to NRC 761118 request for description of mgt control sys Forwards protocol for Co-60 teletherapy unit calibr BDATWRIGHT.N C Riversida Mothodist Hosp Columbus.OH 76/12/06 4ap
- --8004220461 Notifies that OH Sanberg has been appointed Radiological Physicist of Riverside Methodist Hosp Position authorizes OH Sanberg to handle routine radiation safety & licensing applications
 BDATHRIGHT.N C Riverside Methodist Hosp Columbus, DH 76/12/13
- --8004220463 Summarizes Riverside Hethodist Hosp efforts to ensure that radiation safety program is conducted in accordance w/RC regulations & license terms Forwards description of radiosotope committee EL Saenger 77012 ltr encl BOATMRIGHT.N.C Riverside Methodist Nosp Columbus.OH 76/12/28 600
- --B004220465 Responds to 770926 ltr to EL Baenger re analysis of radiation treatments received by former patient Medical consultants have only reviewed autopsied decedents Former patient will not be included in review KEPPLER. J O Region 3, Chicago, Office of the Director 77/11/18 ip
- --8004220466 Summarizes 771111 meeting w/EL Basnger re Riverside Methodist Hosp overexposure incident EL Basnger proposed that high level Commission position be developed re further patient evaluation or review of individual cases. LONEROAN.G T Region 3. Chicago. Office of the Director 77/11/25 ip.
- ~-8004220467 Requests response to EL Saenger questions re need for add1 review of autopsy cases & necessity of NRC advice to county officials

 KEPPLER, J Q Region 3, Chicago, Office of the Director 77/11/30 in
- --8004220468 Requests info about current NRC activities re medical use of radioisotopes, bases for IE use of medical consultants & Region 3 areas of concern DAVISI. O. Office of Inspection & Enforcement, Office of the Director, 77/12/01 ip

- --8004220469 Requests response to EL Gaenger 771117 questions & J Ke 771105 memo DAVIS.J O Office of inspection & Enforcement, Office of the Director 77712/12 ip
- --8004220470 Provides brief answers to questions in 770201 memo re Riverside Methodist Hosp teletherapy radiation overexposure incident More complex issues will be addressed in Commission paper EL Saenger 740709 ltr to JR Flynn encl HIDGINBOTHAM.L Diffice of Inspection & Enforcement, Office of to Director 78/01/04 5pp
- --B004220472 Discusses recommended enforcement action re Riverside Methodist Hosp overexposure incident Lists major factors contributing to overexposure Six items of noncompliance were identified during 1E 760420-22 & 0512-13 insps THOMPSON.D Office of Inspection & Enforcement, Office of the Director 76/06/2i ip
- --8004220473 Mati/Byproduct License 34-01055-03 for Riverside Method:
 Hosp is amended in its entirety per 780307 application Amend
 13 authorizes possession & use of 2.000 Ci Co-60 in
 teletherapy sealed sources
 VACCA,P C Licensing Management Branch 78/04/05 App
- --800422047& Amend 13 to Matl/Byproduct License 34-01055-03 for River Methodist Hosp authorizing use of licensed matl by GC Taylor or SM Rahman VACCA.P C Licensing Management Branch 77/12/27 ip
- --8004220479 Amend 11 to Mati/Byproduct License 34-01055-03 for River Methodist Hosp, adding Conditions 23 & 24 VACCA,P C Licensing Management Branch 77/01/13 ip
- --B004220480 Amend 12 to Matl/Byproduct License 34-01055-03 for River Methodist Hosp, authorizing use of licensed matl by LJ Fahey, GC Taylor or SR Andress DAVI8, F C Radioisotopes Licensing Branch (Pre 790501) 76/08/1
- --B004220482 Amend 7 to Matl/Byproduct License 34-01055-03 for Rivers Methodist Hosp, authorizing use of licensed matl by LJ Fahey or QC Taylor DAVIS, F. C. Radioisotopes Licensing Branch (Pre 790501). 76/07/0
- --80042204B5 Matl/Byproduct License 34-01055-03 for Riverside Methodi Hosp is amended in its entirety per 751014 application. Amend B authorizes use & possession of 2000 Ci Co-60 in teletherapy sealed sources DAVIS.F.C Radioisotopes Licensing Branch (Pre 790501) 75/12/1
- --B004220486 Amend 7 to Mati/Byproduct License 34-01055-03 for White Cross Hosp Association, authorizing use of 2,000 Ci Co-60 in teletherapy sealed sources BABSIN:N Atomic Energy Commission 76/06/28 2pp
- --B004220488 Amend & to Mat1/Byproduct License 34-01055-03 for White Cross Association authorizing use of 10,000 Ci (two sources of not more than 5,000 Ci each) MALARO, J C Atomic Energy Commission 71/04/01 1p
- --8004220491 Amend 5 to Matl/Byproduct License 34-01055-03 for White Cross Mosp Association, changing expiration date in Item 4 to 751130 & authorizing MB Schwartz or DR Schmidt as users of licensed matl MALARO, J C Atomic Energy Commission 70/10/14 ip
- --8004220512 Amend 4 to Matl/Byproduct 34-01055-03 for White Cross Ho Association revising Subitems 7 A & B A to read teletherapy sealed sources & 7.000 Ci. respectively BUCHANAN.C R Atomic Energy Commission 49/02/07 ip
- --8004220517 Amend 3 to Matl/Byproduct License 34-01055-03 for White Cross Hosp Association adding Condition 20 BUCHANAN, C R Atomic Energy Commission 47/11/24 1p
- --B00422052i Mati/Byproduct License 34-01055-03 for White Cross Hosp Association is amended in its entirety per 651026 application Amend 2 authorizes use & possession of 6,000 Ci Co-60 in teletherapy saaled sources HOWELL.D B Atomic Energy Commission 65/11/19 5pp
- --8004220528 Requests amend of Matl/Buproduct License 34-01055-03 for Riverside Methodist Hosp authorizing CK Yin as user of Co-16 Amend fee certification & NY City license amend encl REEHAL, B & Riverside Methodist Hosp Columbus, OH 79/10/04 3pp

- --B004220532 Requests deletion of M Kartha & addition of BS Reehal as radiation safety officer for Riverside Methodist Hosp ES Reehal curriculum vitae encl W/o encl FLYNN, J R. Riverside Methodist Hosp Columbus, OH 78/03/09 ip
- --8004220539 Requests that S Rahman be included as authorized user of licensed matl for Matl/Byproduct Licenses 34-01055-01 & 03 S Rahman curriculum vitae encl M/o ancl KARTHA-M K Riverside Methodist Hosp Columbus.OH 77/11/21
- --8004220944 Confirms 76:219 telcon re mgt control sys Hosp must file rept demonstrating that radiation safety program is conducted in accordance w/NRC regulations & license terms HADE, L. Radioisotopes Licensing Branch (Pre 790901) 76/12/19
- --BD0422054B Confirms telcon granting extension until 770104 for receipt of rapt re mgt control sys Requests acknowledgement BDATHRIGHT, N C Riverside Methodist Hosp Columbus, OH 76/12/27 to
- --B004220551 Order modifying License 34-01055-03 by adding Condition 23 to license & requiring written description of mgt control sys to ensure compliance w/NRC regulations Order is effective immediately CHAPMAN, K.R. Office of Nuclear Haterial Bafety & Safeguards 76/07/14 Spp
- --B004220557 Ack receipt of 760921 & 1020 ltrs re appointment of M Kartha as acting radiation safety officer
 BOHYER.J E Radioisotopes Licensing Branch (Pre 790501)
 76/11/03 ip
- ---B004220562 Forwards M Kartha curriculum vitae in response to NRC 761004
 request M/o encl
 BOATHRIGHT.N C Riverside Methodist Hosp Columbus. CH 76/10/20
 in
- --8004220567 Requests amend of Mat1/Byproduct License 34-01055-03 to incorporate J Axt as radiation protection afficer & ER Andresen as user of intracavitary sources KARTHA-M K Riverside Mathodist Hosp Columbus,DH 76/09/20 1p
- --8004220573 Informs NRC that M Karthe has been appointed consultant physicist for Riverside Methodist Hosp effective May 1976. Position authorizes M Karthe to take necessary action w/NRC in handling radiation safety & licensing applications FLYNN, J R Riverside Methodist Mosp Columbus. QH 76/09/21 ip
- --8004220579 Requests complete description of M Kartha experience in radiation & radioactive matls & radiation protection training. BOMYER.J.E Radioisotopes Licensing Branch (Pre 790501) 76/10/04 1p
- --B004220585 Forwards Amend 10 to Matl/Byproduct License 34-01055-03 adding SR Andresen as individual user of Co-60 teletherapy unit at Riverside Methodist Hosp Requests concurrence W/o enci HADE,L Radioisotopes Licensing Branch (Pre 790501) 76/08/06
- --8004220591 Discusses Riverside Methodist Hosp request for 20-day extension to comply w/NRC 760714 order Hosp must submit request in writing BINDER.B. Radioisotopes Licensing Branch (Pre 790501) 76/07/29

Andresen not be added as authorized user on 1-01055-03 based on results of nforcement action against licensee section & Enforcement, Office of the

Methodist Hosp request for amend to Matl/ G. ification Branch, 76/06/28 ip

- --8004220602 Application for amend to Matl/Byproduct License 34-01055-03 authorizing LJ Fahey & OC Teylor to use 8/or supervise use of Co-60 Bealed sources to be housed & used in Picker 629F Go-60 teletherapy unit TAYLOR, O C. Riverside Methodist Hosp. Columbus, OH 76/06/30, 4pp.
- --8004220606 Informs that Riverside Methodist Hosp concurs w/GC Taylor request to be added to Matl/Byproduct License 34-01055-03. FLYNN, J. R. Riverside Methodist Hosp. Columbus.OH 76/06/30 1p

- --B004220609 Requests reactivity of teletherapy license
 TAYLOR. G C Riverside Methodist Hosp Columbus. OH 76/06/23 ip
- --8004220612 Forwards balance of matl requested for inclusion in License 34-01055-03 W/o encl ANDRESEN, S. R. Riverside Methodist Hosp Columbus, CH 76/04/29 in
- --B004220616 Advises that S Andreson served as resident from Jan-Jui 1972 Experience included use of Co-60 teletherapy Cs-137 brachytherapy Recommends approval of S Andreson for independent use of matls Suppl to license application encl WEIGENBERGO. I Methodist Medical Center of Illinois Peoria, IL 76/04/24 4pp
- --B004220618 Verifies that S Andresen completed residency at univ on 750801 Training included experience w/superficial voltage, orthovoltage therapy.Co-60 machines & linear accelerators Suppl to license application encl
 DEER.D A California. Univ of, San Diego 76/03/16 3pp
- --B004220622 Discusses Amend 8 to License 34-01055-03 re inclusion of 8 Andresen as individual user of toletherapy unit Requests addi info re 8 Andresen certification in radiology or therapautic radiology & training DAVIB,F C Radioisotopes Licensing Branch (Pre 790501) 75/12/19
- --8004220625 Forwards request for renewal of License 34-01055-03 for Co-60 teletherapy sealed source & addition of 8 Andresen to license AXT, J C Riverside Methodist Hosp Columbus, QH NRC 75/10/09 in
- --8004220629 Application for renewal of Matl/Dyproduct License 34-01055-03, authorizing LJ Fahey & S Andresen to use &/or supervise use of 20,000 Ci Co-60 in form of sealed sources for teletherapy. TAYLOR, O C Riverside Methodist Hosp Columbus, OH 75/10/14 Sho
- --8004220633 Notifies that 721009 survey rept following installation of teletherapy unit fulfills requirements of Condition if of License 34-01057-03 Special attention should be paid to requirements of Conditions 18 & 19
 BASSIN:N Atomic Energy Commission 72/11/22 lp
- ~-8004220635 Forwards OH Callendine radiation survey & analysis for radiation exposure in teletherapy room at hosp subsequent to installation of Picker C-9 teletherapy device BCHWARTZ, W B Riverside Methodist Hosp Columbus, CH 72/10/09 22ab
- --8004220639 Supplemental application for amend to License 34-01085-03 authorizing WB Schwartz.DR SchwidT.GC Taylor,JV Blazek & LJ Fahey to use &/or supervise use of 20,000 Ci Co-60 in sealed sources for teletherapy # White Cross Hosp Association Columbus.OH 72/04/20 2pp
- --8004220644 Forwards Forms AEC-313 & 313a in support of application for amend to License 34-01095-03 re inclusion of LJ Fahey as authorized user of licensed matl & replacement of colbalt machine w/rotational cobalt teletherapy unit CALLERDINE, O W Riverside Methodist Hosp Columbus, OH. 72/04/19
- 8004230008 Responds to FOIA request for documents detailing spent fuel shipment routes & alternate routes from Chelk River, Canada to 8C that traverse NY & PA Info withheld (ref FOIA Exemption 4)
 FELTON.J M Division of Rules and Records 80/04/09 ip
- 8004230011 FOIA request for documents detailing spent fuel shipment routes & alternate routes from Chalk River, Canada to BC that traverse NY & PA KATZ, B E The Press Binghampton, NY 80/03/17 Ip.
- B004230015 Responds to FOIA request for last insp rept of Doctor's Hospital in Columbus.OH Forwards documents listed in App A. Insp rept will be forwarded upon completion FELTON.J M Division of Rules and Records B0/04/10 2pp
- ---8004230023 Ack receipt of 761116 ltr informing of steps taken to correct item of noncompliance identified in NRC 761104 ltr Corrective actions will be examined during future insp. ALLAN,J M. Region 3, Chicago, Fuel Facility & Materials Bafety Branch 76/12/06 ip

NONDOCKETED ITEMS

- ---8004230029 Forwards leak/wipe test analysis rept & sealed source inventory data to satisfy infraction & deficiency identified in MRC 761104 ltr Full compliance should be achieved Requests confirmation HOBBS.T C Doctors Hosp Columbus.OH 76/11/16 lp
- --8004230032 DDDD
 "Leak/Hipe Test Analysis Rept " Sealed source inventory enc!
 EARLY:P J Nuclear Medicine Associates:Inc Cleveland,OH; 78/07/15 2pp
- --B004230040 Discusses IE insp of Licenses 34-05488-01,02 & 03 on 761021 & 22 & forwards notice of violation ALLAN.J M Region 3, Chicago, Fuel Facility & Materials Safety Branch 76/11/04 2pp
- --8004230045 Notice of violation from insp on 761021 & 22 Noncompliance noted byproduct matl inventory included 12 Cs-137 sealed sources that were not leak tested between 750222 & 761021 & no quarterly inventory for sealed sources conducted * Region 3, Chicago, Fuel Facility & Materials Safety Branch 76/11/04 ip
- --8004230050 Draft IE insp rept on 761021 & 22 Noncompliance noted byproduct matl inventory included 12 Cs-137 sealed sources that were not leak tested between 750222 & 761021 & no quarterly physical inventory for sealed sources conducted SCHULTZ, W H Region 3. Chicago. Office of the Director 76/10/21 9pp
- 8004230019 FOIA request for last insp rept for Doctor's Hospital in Columbus, OH SMITH. J D Affiliation Unknown 80/01/24 ip
- BOO4290087 Responds to FOIA request for NRC Translation 520
 "Radioecological Assessment of Wyhl Nuclear Power Plant"
 Forwards requested document W/o encl
 FELTON, J M Division of Rules and Records BO/04/18 ip
- BOO4270087 FOIA request for NRC Translation 520 "Radioecological Assessment of Wyhl Nuclear Power Plant" WA Post 791111 nows article enct OROSSMAN.K Island Closeup News Service BO/04/08 ip.
- 8004270074 Addl response to FOIA request for info re members of ASLB Forwards addl documents per JC Carr 77:107 ltr FELTON.J M Division of Rules and Records 80/04/14 ip
- 8004270077 Responds to FOIA request for internal documents used to establish iS-minute notification requirement (Footnote 3 in FR notice) for NRC proposed rule 10GFR50 re emergency planning Forwards documents listed in App A H/o encis FELTON.J M Division of Rules and Records 80/04/14 ip
- BOO4270103 FOIA request for internal documents used to establish isminute notiffication requirement (Footnote 3 in FR notice) for NRC proposed rule iOCFR50 re emergency planning MADAK: A C Yankee Atomic Electric Co BO/03/21 ip
- 8004290150 Responds to FOIA request for issues of "Heekly Highlights" from 1976 to present, All issues since 771216 have been put in PDR in Washington, DC No repts exist for 1976 or 1977, except for 760324 rept FELTON, J M. Division of Rules and Records 80/04/14 1p
- 8004290152 FOIA request for issues of "Weekly Highlights" from 1976 to present POWER.D F Affiliation Unknown 80/03/31. 1p
- 8004290155 Responds to FOIA request for all documents requested by public under FOIA re Union Carbide Corp NRC has not been asked for info re Union Carbide Corp Provides NRC criteria for disclosing proprietary info FELTON.J M Division of Rules and Records 80/04/14 1p
- BOO4270161 FOIA request for all documents requested by public under FOIA re Union Carbide Corp CHAIFETZ, D.H. Union Carbide Corp. BO/04/07, 2pp
- 8004270163 Responds to FOIA request for two specific documents contained in nugget file Provides detailed description of nugget file. Forwards requested documents W/o encis FELTON.J M Division of Rules and Records 80/04/17 ip
- 8004290166 FOIA request for two specific documents contained in nugget file QNOBSMAN,K Island Closeup News Service 80/04/14 ip

- 8004290169 Responds to FOIA request for all applications for radioactive matls licensure & radioactive matls licenses issued to Pharmatopes, Inc. excluding IL Forwards requested documents W/o encls FELTON, J IS Division of Rules and Records 80/04/17 lp
- 8004270173 FOIA request for all applications for radioactive mat licensure & radioactive matts licenses issued to Pharmatopes.Inc. excluding IL MCDONALD.D D Nuclear Pharmacy, Inc 80/04/01 ip
- 8004290182 Responds to FQIA request for info re Patistani & Liby shipments & design &/or const of nuclear explosive device Forwards news articles identified in App A Other documents were originated by Btate Dept & CIA FELTON.J M Division of Rules and Records 60/04/14 App
- 8004290184 FDIA request for info re Pakistani & Libyan U shipmen design &/or const of nuclear explosive device COCHRAN,T B Natural Resources Defense Council 79/11/26 2
- GEN TEC IS GENERIC TECHNICAL ISSUES
- 7906010119 FOIA request by UCB for all documents re Task Action , A-40 & A-41.info on sessmic issues prepared for BEP & insp repts for Beaver Valley WE185 E R Bheldon, Harmon & Weiss 79/03/19 2pp
- B00402014B NUREO-0460 V4
 "ATMS for LMRs.Resolution of Unresolved Safety Issue Task
 Action Plan A-9," Vol 4.for comment
 * Office of Inspection & Enforcement, Office of the Director
 B0/03/31 202pp Available at NTIS
- 8004030004 NUREO-0460 V4
 "ATMS for LMRs.Resolution of Unresolved Safety Issue Task
 Action Plan A-9 " For comment issue
 "Office of Nuclear Reactor Regulation 80/03/31 200pp
 Available at NTIS
- 8004070263 Discusses Generic Task 8-24 (Containment Purge) schedimpacts NRC has commitment to complete task action plan by Apr 1980 Browns Forry, Ptairie Island & Turkey Point have not met schedules for submitting info LAINAB.O Plant Bystums Branch 80/03/17 ip
- 800414038B Forwards commonts on final rept on Phase I of sys interaction study prepared by Bandia Labs Section 5 0 should note that boiling in core & condensation in steam generator is viable heat removal scheme
 MILLE, L M Tennessee Valley Authority 80/04/04 2pp
- BOO4;50353 Forwards "Method of Applying Mark II Bingle Vent Dunad Lateral Load to Mark II Plant W/Multiple Vents." on behalf of Mark II owners group Rept withheld (ref 10CFR2 790) Affidavit enci BUCHHOLZ.R H General Electric Co RHD-027-BO BO/04/09 6p
- 8004180478 Notification of ACRS Subcommittee on Plant Arrangement 800220-21 meeting w/Bandia Labs in Washington.DC to discuss "Final Rept (draft) on Phase I of Generic Task A-17.8ys Interaction in Nuclear Power Plants" & items re LWRs HOYLE,J C ACRS - Advisory Committee on Reactor Safeguards, 80/01/30 3pp
- INSPECTION AND ENFORCEMENT
- 7909050241 IE Bulletin 78-06. "Defective Cutler-Hammer,Type M Rel w/DC Colls " * Office of Inspection & Enforcement, Office of the Director 78/05/31 App

- 8002280644 IE Bulletin 79-03A. "Longitudinal Weld Defects In ASME 8A-312 Type 304 Stainless Steel Pips " # Office of Inspection & Enforcement, Office of the Director 800/04/04 3pp

- 8002280648 IE Bulletin 80-07, "BWR Jet Pump Assembly Failure "
 * Office of Inspection & Enforcement, Office of the Director 80/04/04 7pp
- 8002280649 IE Info Notice 80-14. "Safety Suggestions From Employees "
 * Office of Inspection & Enforcement, Office of the Director
 80/04/02 2pp
- B002280650 IE Info Notice 80-13. "OE Type SBM Control Switches Defective CAM Followers "
 Office of Inspection & Enforcement, Office of the Director
- 8002280654 IE Info Notice 80-12, "Instrument Failure Causes Opening of PORTY & Block Valve "

 9 Office of Inspection & Enforcement, Office of the Director
- 8002280657 IE Circular 80-07, "Problems W/HPC1 Turbine Dil Bys "
 * Office of Inspection & Enforcement, Office of the Director 80/04/03 | 3pp
- 8004080578 EN-80-007 on 800314 notice of violation & notice of proposed imposition of civil penalties to be issued for License 45-09358-02 Action based on alleged items of noncompliance re-matifalse statements in application for license renewal BROCKETT.T W. GDMER.0 C Office of Inspection & Enforcement, Office of the Director 80/03/11 ip
- 8004080584 PNO-V-80-020A on 800317, lost Ir-192 seed found in restricted area of radioisotopic storage room No radiation exposures to operational personnel THOMAS,R D Region 5, San Francisco, Office of the Director 80/03/18, 1p
- 800409017B PNO-I-80-042 on 800317, notified by several sources that radioactive math package containing 13 8 Ci Ir-192 source in radiographic device dropped at Philadelphia Airport was leaking Nonradioactive insulating math spilled out KINNEMAN, J. Region 1, Philadelphia, Office of the Director 80/03/17 2pp
- 8004090193 PNO-III-80-048 on 800314, unknown caller informed duty DOADVOING PRO-II-80-049 on BOOSIA, Unknown caller informed duty officer of stolen Ra-226 implant needles bought from friend Feared contamination & agreed to place device in local Chicago phone booth Two more calls received w/no results PAPERIELLO, C. J. DAVIS, A. B. Region 3, Chicago, Office of the Director 80/03/14 2pp
- BO04090197 PNO-I-80-044 on B00318, call received from individual in Belmont, MA re retrieval of gamma sample charger from trash compactor in Hinchester, MA Unlabelled sealed wource reading it mrem/hr found Little radiation exposure occurred KINNEMAN, J. Region I. Philadelphia, Office of the Director 80/03/19.
- B004100017 PNO-V-80-020 on B00314, safety officer for License 50-17838-01 notified duty officer re 0 6 mCi Ir-192 seed missing from ribbon Radiological surveys conducted of room t patient w, THOMAS, R D Re & patient w/o results THOMAS.R D Region 5. San Francisco, Office of the Director
- BOO4140102 PNO-III-76-078 285 patients received radiation overdoses between Har 1975-Jan 1976. Caused by malfunctioning of cobalt therapy unit, IE plans to initiate investigation Medical consultant has been contacted for assistance HHITT.K W Region G. Chicago. Office of the Director 76/04/19
- 8004140106 PND-111-76-027 255 patients received radiation overdoses between Mar 1975-Jan 1976 Caused by malfunctioning of cobalt therapy unit IE plans to initiate investigation Medical consultant has been contacted for assistance ALLAN, J H Region 3, Chicago, Office of the Director 76/04/19 2pp
- BOO4140110 PNO-III-76-031 new info was received re overexposure of 255 patients from improperly calibr teletherapy machine Caused by human error: rather than progressive instrument deterioration IE will complete investigation.

 LONERGAN, O T., ALLAN, J M Region 3, Chicago, Office of the Director 76/05/07 ig
- BOO4:40202 PNO-III-76-110 newspaper reported that preliminary autopsy findings on two patients at Riverside Methodist Hosp indicated radiation overexposure was major cause of death Coroner has scheduled 760702 press conference MARNICK, R. F. . ROY, O. W. , THOMPSON. D. Office of Inspection & Enforcement, Office of the Director 76/07/02 1p

PUBLIC DOCUMENT ROOM MISCELLANEOUS MISC

- 7902060387 Forwards repts of the activities of the Natl Energy Goftware Center for FY1978 Midyear review of NESC work scheduled for 790220 BENNETT, G L. Research Support Branch 79/01/18 2pp
- --7902060388 Natl Energy Software Center rept for FY1978 Outlines program accomplishments, breakdown of library collection by classification category. West saller" list & number of program packages contributed to center BUTLER,M Argonne National Laboratory 78/11/07 8pp
- 7902080199 Informs NRC that nuclear liability pools are able to provide \$160 million as max combined limit under primary nuclear energy liability insurance policies Will maintain \$30 million of contingent Hability capacity BARDES, CR Nuclear Energy Liability Insurance Association 79/01/09 lp
- 7902140361 Announces RER midgear review on 790220 of Nati Energy Software Center of accomplishments to date & plans for rest of FY1979 & FY1980 BENNETT, O. L. Research Support Branch 79/01/31 2pp
- 7902280271 Staff position to Transnuclear application to export 779 kg enriched 4 05% U-235 to Canada License should be granted MODRE.R N Assistant Director for Export/Import & International Safeguards 78/12/04 3pp
- 7903060654 Notification of 790322 meeting w/UCLA to discuss status of steam transient research program funded by NRC Div of Reactor Safety Research UCLA pool dynamics program will be discussed ANDERSON, C J Containment Systems Branch (Pre 790101) 79/02/13
- 79030B0166 Notification of 790301 meeting in Bethesda.MD to discuss NRC generic questions re ATMS THADANI.A C Reactor Bystems Branch 79/02/15 1p
- 7903080264 Notification of 790228 meeting w/Nuclear Associates Intl in Bethesda.MD to discuss progress made on calculations of "Steam Line Break Sensitivity Studies" SALAH S Analysis Branch 79/02/26 ip
- 7903090072 Notification of date change to 790329 for meeting w/DWR Reload Licensing Users Group MORRIS, B Reactor Safety Branch (Pre 791030), 79/02/27 1p
- 7903090076 Notification of 790314 meeting in Nethesda, MD w/BWR Reload Licensing Users to discuss BWR Reload Startup Tosts MDRRIG. B Reactor Safety Branck (Pre 791030) 79/02/97, ip
- 7903200103 Responds to 790219 request for withdrawal of 790105 response to NRC new applications survey Request has been honored Original ltr is being returned No FOIA request for ltr has been made BERKOW.H N Division of Project Management 79/03/05 lp
- 7904130116 Notification of 770411 meeting w/American Inst of Steel Const in Bethesda.MD, to discuss proposed response to request for add info dated 781107 BPRAUL.J Quality Assurance Branch 79/04/04 ip
- 7904170340 Summary of anomalies between semiscale test 8-07-6 results & analytical predictions Improved downcomer insulator will be installed in semiscale in Apr 1979 No addl cold leg injection tests will be conducted MURLEY, T.E. Division of Reactor Safety Research 79/03/28 App
- 7904210192 Rejects documentation submitted re "Bafeguards Use of Process Control & Quality Control Data " PARTLON.J G Material Control Licensing Branch 79/04/03 is
- 7905140144 Forwards rept re operating characteristics of numerous models of limitorque electric actuators when mounted on Velan valves Constitutes coincidental acquisition CLEMENSON, F Plant Bystems Branch (Pre 791030) 79/04/17 2p. 79/04/17 2pp
- 7905190090 Forwards monthly rept for Apr listing transfer or radioactive scaled sources used in FILTEC level detection equipment; to monagreement states CALHOUN, F. L. Industrial Dynamics 79/05/09. 2pp.

NONDOCKETED ITEMS

- 7706010332 Summary of 770216 QA Branch briefing for Ofc of Nuclear Regulatory Research & DUE on proposed graded approach for QA programs W/supporting documentation BENNETT.G L Research Support Branch 79/04/25 32pp
- 7906050031 Responds to 781122 telegram alleging radiation overexposure to individual during radiographic operations Forwards IE investigation rept W/o encl KEPPLER, J G Region 3. Chicago, Office of the Director 79/03/23
- 790725025B Requests clarification of NRC 790611 ltr re implementation of Category 2 & 3 Reg Guides in BEP SCHAFFSTALL,R E KMC, Inc 79/07/23 ip
- 7907300056 Summary of 790524-25 workshop in Silver Spring.MD re recommendations for condensation models in TRAC SHOTKIN.L M Analysis Development Branch 79/06/15 6pp
- 7908010063 Forwards Region i Investigation Rept 078-154 which contains results of radiation survey efforts in Norton,MA through Dec 1978 & related background info N/o encl STOHR,J P Region i, Philadelphia, Office of the Diractor 79/06/04 ip
- 7908030084 Forwards staff position re safe shutdown capability for fires Specifies safe shutdown equipment & performance objectives for licensee consideration in demonstrating safe shutdown capability w/existing or alternate equipment LAINAS.G Plant Bystems Branch (Pre 791030) 79/06/19 9pp
- 7908060334 Suggests storage of spent fuel rods at ND antiballistic missile site.const of Thorium slow light-water-breeder reactors & storage of liquid wastes in NV under atomic bomb test holes MURPHY.F E Affiliation Unknown 79/07/30 ip
- 7908100158 Forwards draft IE Bulletin proposing interim position on containment purging during normal operation LAINAS.O Plant Bystems Branch (Pre 791030) 79/06/27 8pp
- 790B190054 Advises that suppl guidelines have been initiated to expedite completion of fire protection programs at operating plants Ouidelines will be prepared by DOR reviewers FEROUSON.R Plant Bystoms Branch (Pre 791030) 79707717 3pp
- 7908150708 Responds to 790612 ltr se GEIS on handling & storage of spent fuel NRC will follow Commission decision in response to 790801 request DIRCKS.W J Office of Nuclear Material Safety & Bafeguards 79707/12 1p
- 7908200112 Forwards proposed functional organization for Section A of Plant Bys Branch Requests that lead engineers be authorized to perform managerial paperwork TONDI.D Plant Bystems Branch (Pre 791030) 79/07/26, 3pp
- 7908280824 Expresses regrets that Tondi was unable to attend 770726 meeting w/Rydnert at MD Natl Dank Bldg Requests that apologies be extended to Rydnert TONDI, D Plant Systems Branch (Pre 791030) 79/07/27 ip
- 7909140279 Disagrees w/NRC plan to lift reactor licensing moratorium LEVIN.C Senate 79/09/10 2pp
- 7909190504 Responds to 790814 ltr & 790824 telcon re licensing requirements for import of Progesterone Kits containing I-125 forwards IOCFR110 & applicable form W/o encl MODRE,R N Office of International Programs 79/08/27 ip
- 7909190514 Responds to 790730 ltr re suggestions for storage of spent fuel rods & low level radioactive wastes & support for light water breeder reactors Provides explanations for angoing program of concern DENTON:H R Office of Nuclear Reactor Regulation 79/08/20 ip
- 7910020720 Suggests topics for Japan/U S meeting on nuclear safety Topics include Mark II full scale condensation tests & firs protection & diesel generator reliability Summary of programs encl.

 LAINAS-0 Plant Systems Branch (Fre 791030) 79/09/05 35pp
- 7910020843 Requests summary of screening reviews of licensee responses to IE Bulletin 79-01 re environ qualification of Class IE equipment DENTON.H R Office of Nuclear Reactor Regulation 79/09/21 ip

- 7910050109 Natification of 791001 meeting w/Ofc of IC to discuss computer sys info re NRC Form 766
 BELKE, W L Quality Assurance Branch 79/09/21 ip
- 7910050156 Advises of review completion of draft IE circular re failure of General Telephone & Electronics Sylvania relay. Type PM Bulletin 7305, Catalog Sul2-11-AC cail Issuance of proposed circular is endorsed w/no comments GAMHILL. W Assistant Director for Operating Reactor Projects (Pre 771030) 79/09/13 ip
- 7710050603 Notifies of review of proposed bulletin re dewatering sys at operating plants & endorses issuance OAMMILL.H Assistant Director for Operating Reactor Projects (Pra 771030) 77/09718 ip
- 7910190161 Notifies that univ lab facilities generate no low level wastes GRANT.J J St Peter's College 79/09/29 ip
- 7910310051 Summary of 790B21 research review group meeting in Albuquerque. NM re progress of two NRC sponsored studies FOULKE, J D Environmental Effects Research Branch (Pre 791030) 79/10/01 Spp
- 7911050375 Reply to Atlantic Research Corp brief No finding that licensee minimized chances of noncompliance Ngt competence not basis for imposition of penalty ALAB-542 should be reversed Certificate of Bvc encl MURRAY.
- 8003250855 Concurs w/issuing proposed draft AO rept to Congress for Oct-Dec 1979 Forwards marked-up pages of rept DENTON, H R Office of Nuclear Reactor Regulation B0/02/26 App
- 8004020023 Inquires why Nuclear Safety, bimonthly technical progress review, is advertised as govt publication & who is responsible for review Gimilar ltrs to GAO & Dept of Labor encl
 ECCUE, N R Affiliation Unknown 79/12/04 Spp
- BOO4020298 Discusses proposed ltr to licensees on high energy line pipe breaks inside containment No sufficient technical basis evident to advise whether method proposed by NRC for satisfying General Design Criteria 4 is legally sufficient BCINTO, J.F. Office of the Executive Legal Director BO/03/14 ip
- 8004080102 Forwards proposed FR notice of ACRB Bubcommittee on ECCB 800326 masting Requests publication on 800311 BATES, A L. ACRB Advisory Committee on Reactor Bafeguards 80/03/04 3nn

- 8004140071 Notice of issuance & availability of proposed minor amends of sys of records Amends clarify & update info in NRC sys of records necessitated by adding senior executive svc training records to existing NRC training records DIRCKS, W J Office of the Executive Director for Operations 80/03/14 4pp
- 8004140092 Responds to 800216 itr re operator training Nuclear power plant simulators used in operator training programs since 1769 Under revised requirements, simulators will be programmed for multiple facilures DENTON, HR Office of Nuclear Reactor Regulation 80/03/20 ip
- --B004140095 Expresses concern about role of plant operator error in nuclear incidents & suggests training in realistic simulated emergency situations BLANCHARD, W. H. Affiliation Unknown 80/02/16 2pp
- 8004140483 Responds to 800214 ltr forwarding E Griffin 800207 ltr re safety of various aspects of nuclear fuel cycle Forwards copy of proposed change to 100FRSO & other matt re concerns & discusses goal of natt waste mat program with certil KAMMERER.C Dffice of Congressional Affairs 80/03/01 2pp
- --BOO\$140485 Requests info responsive to encl E Oriffin BO0207 ltr expressing concern re safety of various aspects of nuclear fuel cycle BOREN,D L Senate BO/02/14 2pp
- BOO4170111 Comments on Nuclear Data Link Urges caution in implementation Admirable objective is not practical, safe or prudent for required level of overview LUNDVALL, A E Baltimore Qas & Electric Co 80/04/10 3pp
- 8004210098 Forwards 780901-790131 replacement pages for "Intrusion Detection Handbook." SAND 76-0354 Superseded pages should be destroyed H/o enc1 VAR9A.S.A Assistant Director for Light Water Reactors 79/11/15
- 8004220035 Bubmits reply to inquiries re NRC manitoring of Inst for Nuclear Power Operations activities Inst has not developed specific procedures & criteria for monitoring operator training programs
 SKOVHOLT:D J Assistant Director for Guality Assurance & Operations
 80/04/01 Ip
- 8004300573 Advises that IE Circular 80-05 was sent to listed licensess & CP holders ORIER,B.H Region 1, Philadelphia, Office of the Director 80/04/01 opp

NUREO REPORTS AND RELATED CORRESPONDENCE

- B003250002 Comments on draft NUREO-0590, Revision 1 no discussion made of recomissioning & conversion No modes of decomissioning should be precluded at this time Classification of decomissioning modes & timing by half lives unreasonable REYNOLDS, N S Debevoise & Liberman 80/02/20 Spp
- 8003270223 NUREO-D030 V3 Ni Vellow Book "Const Status Rept, Nuclear Power Plants," data as of 791231, * Office of Management and Program Analysis 80/02/29 160pp
- 8004010320 Comments on NUREG-03i3, Revision 1 evaluation should be made of nonservice sensitive lines to determine potential for intergrenular stress-corrosion crecking MILLS, L. H Tennessee Valley Authority 80/03/25 ip
- 8004020032 Comments on NUREO-0225, "Rept of Biting Policy Task Force "
 recommends addit measures to prevent accidents & mitigate
 effects Biting should be strengthened as factor in defense
 PLESBET.M.S ACRS Advisory Committee on Reactor Bafeguards,
 80/02/14 7pp
- 8004020111 Certified summary of ACRS Site Evaluation Subcommittee 791220 meeting in Washington, DC re recent policy changes & implementation in area of siting & emergency planning p ACRS Advisory Committee on Reactor Saraguards 80/02/09 13pp
- --B004020116 Discusses conflicts in guidance & interpretation re offsite margancy plans per review of NUREQ-0396.NUREQ-0388 & draft NUREQ-0610.

 GODWIN.A.V Alabama. State of 79/11/14, 25pp

- --8004020120 Forwards comments on "Basis for Emergency Action Levels for Nuclear Power Facilities" Minor events having no effect on public health & safety do not warrant consideration of public officials or agencies JURGENSEN,R W American Electric Power Co , Inc 79/11/30 4pp
- --B004020123 Comments on NUREO-0610 recommends four classes of emergency action levels in-plant occurrence emergency alert, site emergency & general emergency HARD, J. E. Atomic Industrial Forum 79/11/28 14pp
- --8004020128 Comments on NUREG-0610 draft estimate too low Experience indicates that, using draft examples of initiating condition, frequency would be six to ten times per yr rather than once or tuice VETTER.W E Region 4. Dallas, Office of the Director 79/11/27 2as
- --B004020131 Forwards DE Donaldson comments on NUREG-0610 8MITH,O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/11/26 1p
- --8004020138 Comments on NUREC-0610 supports basic intent, however, does not agree w/nomenclature designation of various classes or w/sorting of example initiating conditions for various classes Marked-up draft guidelines encl DDNALDSON, D Region 1. Philadelphia. Office of the Director 79/11/21 24pp
- ---B004020144 Comments on draft NUREO-0610 release potentials should be expanded for offsite agency guidance Notification should be to both state & local authorities for all classes BROWER.OW New York, State of 79/10/30 2pp
- 8004020139 NUREO/CR-1350
 "Evaluation of Factors Affecting Toxicity of Chlorine to
 Aquatic Organisms "
 CRUMLEY, B C , STOBER, Q J , DINNEL, P A Washington, Univ of FIN
 B-5479 80/03/31 95pp
- 800402014B NUREO-0460 V4
 "ATMS for LMRs.Resolution of Unresolved Bafety Issue Task
 Action Plan A-9." Vol 4, for comment
 # Office of Inspection & Enforcement, Office of the Director
 80/03/31 202pp Available at NTIB
- B004020429 Forwards HCAP-9691, "Transient & Accident Analytis," in compliance w/ltem 2 1 9 c of NUREG-0578 REED.C Westinghouse Operating Plants Owners Group OG-32 B0/03/31 ip
- --8004020432 WCAP-9491
 "Transient & Accident Analysis "
 HITCHLER: M J . SMARP, D R , ANDERBON, T M Westinghouse Electric Corp 80/03/3i 180pp
- B004030002 NUREO/CR-1312

 "Methods for Evaluating Leak Tightness of Spent Fuel
 Container Closures."

 BENDA, B J , LANGLAND, R T Lawrence Livermore Laboratory FIN
 A-0117 UCRL-5273B 80/03/31 200pp Available at NTIS
- 8004030004 NUREO-0440 V4
 "ATMS for LWRs.Resolution of Unresolved Safety Issue Task
 Action Plan A-9 " For comment issue
 Office of Nuclear Reactor Regulation 80/03/31 200pp
 Available at NTIS
- B004030005 NUREO/CR-1280
 "Power Plant Staffing "
 WEONER, W Basic Energy Technology Associates NURC-03-80-116
 BETA-103 80/03/31 54pp Available at NTI8
- 8004040272 Discusses recommendations of Task Force on Bulletins & Orders Recommends vendor methods used for small break LOCA analysis be revised documented & submitted for review PLESETIM S ACRS Advisory Committee on Reactor Safeguards 80/03/11 4pp
- --B004040274 Discusses near-term OL items from Draft 3 of NUREG-0660 & NRC action plans developed as result of TMI-2 accident PLESSET.M 8 ACR8 Advisory Committee on Reactor Bafeguards 80/03/11. 5pp.
- --8004040277 Comments on recommendations of NRC special inquiry group re ACRB activities PLESSET.M S. ACRS - Advisory Committee on Reactor Safeguards 80/03/12 2pp

8004040326 Confirms 800314 telcon re BWR owners group response to NUREO-0578 Requirement 2 1 9 FSAR Chapter 15 event review

General Electric Co MFN-074-80 80/03/31 75pp

B004040379 Bubmits info re interpretation of App 3 of NUREG-0654 Principal objective of App 3 is to provide means of prompt notification to population NRC licensees urged to cooperate w/state b local govts to achieve objective JASKE.R T Federal Emergency Management Agency B0/03/28 2pp

8004040459 NUREQ/CR-0858

NATIONAL NUMBER OF CHOOSE
"Btress Corrosion Cracking of Income! 600 Tubing in
Deaerated High Temp Water"
BULISCHECK, T S , PARK, Y S , VAN RODYEN, D Brookhaven National
Laboratory FIN A-3208 BNL-NUREG-51027 79/06/30 52pp

8004070406 Forwards NUREO-0396, "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Bupport of LMRs," in response to encl 791219 ltr including resolution re emergency planning for handicapped W/o enci GRIMES.B K Assistant Director for Engineering & Projects 80/03/12 4pp

B004090241 Comments on proposed rules 10CFR30, 40, 50 & 70 endorses comments on NUREQ-05B4, Revision 1 NUREQ-0613 is too tentative in scope & purpose In-place entonbment should be considered viable alternative for decommissioning objective PORTER.W L Duke Power Co 80/03/14 3pp

8004100025 NUREQ/CR~1007

JUMICUOUND NUMEQ/CR-1007
"Evaluation of Selected Signal Processing Methods for Characterization of Steam Geneator Eddy Current Signals "BRGNN,8 D , HAYFORD,D T Battelle Memorial Institute, Columbus Laboratories FIN A-30119 BNL-NUREG-51044 79/08/31 90pp Available at NTIS

8004100028 NUREQ/CR-1104

"Preliminary Analysis of Containment Failure Probability by Steam Explosions Following Hypothetical Core Meltdown in COURADINI.M I

Sandia Laboratories FIN

8004100029 NUREG/CR-1203
"Quarterly Technical Progress Rept on Water Reacter Safety
Programs." Oct-Dec 1979
YBARRONDO, L J EG & G. Inc FIN A-6038 EGG-2012 80/01/31
42pp Available at NTIS \$3 00

8004100319 NUREG/CR-1202 "COPS - Model for Estimating Local Law Enforcement Agent Availability " BERMBIGLER, K P Gandia Laboratories FIN A-1173 BAND 78-8237 80/03/31 39pp

8004100323 NUREO-0651 "Eyaluation of Steam Generator Tubs Rupture Events" MARSH.L B Office of Nuclear Reactor Regulation 80/03/31 120pp

8004100586 NUREO/CR-1320
"Measured Concentrations of Radioactive Particles in Air in Vicinity of Amaconda U Mill "
MOHENI,M H , KISIELEGKI,W E Argone National Laboratory 8KI,WE Argonne National Laboratory 80/01/31 45pp Available at NTIS ANL/E8-89

B004100591 NUREO/CR-1230
"Local Drag Laws in Dispersed Two-Phase Flow"
IBHII/N , CHAWLA.T C Argonne National Laboratory FIN A-2026
AML-79-105, 79/12/31 46pp Available at NTIS

8004110048 NUREG/CR-1265
"Dynamic Analysis to Establish Normal Shock & Vibration of Radioactive Matl Shipping Packages." quarterly progress Radioactive mari onipping Factages: quartering problems that caboratory FIELDB, S. R. MECH, B. J. Hanford Engineering Development Laboratory FIN 8-2263 REDL-TME 79-71 80/03/31 80pp Available at NTIS.

8004110045 NUREG/CR-1109
"Measurement of Radon Diffusion from U Mill Tailing Piles "
BILKER, W B , WOOMAN, N A., THOMAS, C W, Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2269 PNL-3107 79/10/31

BOO4140005 Forwards comments on proposed rules 10CFR30:40,50 & 70 on behalf of CPC financial provision for decommissioning is most efficient & economical procedure REYNOLDS, N S Debevoise & Liberman SO/03/20 4pp

BOO4140036 Advises that no further action is indicated on Critical Mass Energy Project 791102 petition for NRC to conduct investigation to determine if OLs of LWRs which base ECCB on faulty analytical codes should be suspended DENTON, H.R. Office of Nuclear Reactor Regulation BO/03/03 2pp

"Xinetics of Monochloramine Decomposition in Presence of Bromide" TROFE, T W. JOHNSON, J D., INMAN, G W. North Carolina, Univ of FIN 8-6248 80/03/31 92pp Available at NTIS

8004140470 NUREQ/CR-1337

"LNR Safety Research Program," quarterly progress report, Jul-Sept 1979 MASSEY, W E , KYOER, J A Argonne National Laboratory FIN A-2014 ANL-79-108 79/02/28 35pp Available at NTIS

8004140478 NUREG/CR-1257

"Summary of FY79 Progress on Refill Effects Program,"
quarterly progress report Jul-Sept 1979
ROTHE, PH, CROWLEY, C. J. Creare, Inc. FIN A-4070 CREARE TN-312
80/03/31 34pp Available at NTIS

8004150022 NUREG/CR-1150

"Impact of Disperison Paramaters on Calculated Reactor Accident Consequences " ALDRICH, D C Sandia Laboratories FIN A-1042 SAND79-2081 79/11/30 46pp Available at NTIS

8004150028 NUREG/CR-1029

"Program Plan for Investigation of Vent-Filtered Containment Conceptual Designs for LWRs " BENJAMIN.A S Sandia Laboratories FIN A-1220 SAND79-108B 79/10/31 72pp Available at NTIS

8004150033 NUREO/CR-1149

NOTIONAL MOMERATOR AND ADDRESS AND ADDRESS AND ACCIDENTS INVOLVING Radioactive Matls "
ALDRICH,D C. ERICSON,D M., FINLEY,N C. Sandia Laboratories FIN
A-1042 SAND79-2017 79/11/30 54pp Available at NTIS

8004150042 NUREO-0571

"Gummary of Tube Intergrity Operating Experience w/Once-Through Steam Generators" LIAW.B D , STROSNIDER.J Engineering Branch 80/03/31 41pp

8004150049 NUREQ/CR-1309

"Markov & Semi-Markov Modelling of Small Engagements "
ENGI.D., FARRELL.R L. Sandia Laboratories FIN A-1040
BAND79-2013 79/12/31 48pp

8004150074 NUREG/CR-1151

"Infiltration of Particulate Matter into Bidgs"
ALDRICH,D C Sandia Laboratories COHEN,AF, COHEN,B L
Pittsburgh, Univ of FIN A-1042 SAND 79-2079 79/11/ 79/11/30 26pp

8004150D78 NUREG/CR-1307
"Fixed Site Neutralization Model User Manual "
ENGI.D , CHAPMAN.L Sandia Laboratories FIN A-1060 GAND79-2241

B004170310 NUREO-0540 V2 Nt
"Title List of Documents Made Publicly Available." Jan 1780

* Division of Technical Information & Document Control 80/01/31
477pp Available at NTIS

BOO4170329 NUREO/CR-1351
"Fatigus of Weldments in Nuclear Pressure Vessels & Piping "
BOOKER-M K , BOOKER-B L P , MEIERAN.H B Dak Ridge National
Laboratory FIN B-0103 ORNL/NUREO-44 B0/03/31 93pp

8004170336 NUREO/CR-0722
"Fission Product Release From Highly Irradiated LHR Fuel "
LORENZ/R A . COLLINS.J T . MALINAUSKAS.A Dak Ridge National
Laboratory FIN B-0127 ORNL/NUREO/TM-2 B0/02/27 164pp

8004170337 NUREO-0398
"Federal-State Cooperation in Nuclear Power Plant Licensing"
SPANGLER.M. B Division of Site Safety & Environmental Analysis 80/03/31 105pp Available at NTIS

8004170341 NUREO/CR-1193
"Transportation of Radioactive Hatl in IL," Jun 1978-Jun 1979
1979
* Illinois, State of, Dept of Public Health NRC-06-78-358
80/03/31 53pp Available at NTIS

8004170345 Transcript of AIF BO0402 briefing in Washington.DC Pp 1-53
* Commission, 80/04/02 54pp

BOO4180420 Notification of BOO40B meeting w/C-E in Bethesda.MD to discuss high range effluent monitors for Lessons Learned requirements & Reg Guide 1 97.
BARRETT, L Environmental Evaluation Branch 80/04/02 lp

8004210213 Forwards comments re NUREO-0588. "Interim Staff Position on Equipment Qualification of Safety-Related Electrical Equipment "Trend studies could be conducted that point to equipment aging at unacceptable rate RENBERGER.D L Heshington Public Power Supply System ELE-058-80-094 80/04/11 5pp

8004210225 Forwards comments on NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Believes approach to equipment qualification good as long as impact on older plants recognized MQMELL.8.H Atomic Industrial Forum 80/04/14 13pp

BOOA21029B NUREO/CR-1139

"Evaluation of In-Pile Pressure Data From Instrumented Fuel Assemblies IFA-432 & IFA-432

BRADLEY, ER, CUNNINGHAM E, LANNING, D D Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2043 PNL-3206 79/10/31 70pp Available at NTIB, \$5 25

8004210301 NUREO/CR-1273
"Investigation of Rn-222 Emissions From Underground U
Mines"

JACKSON,P D , CLISSMEYER, J A , ENDERLIN,W I Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-2270-7 PNL-3262
80/02/29 100pp

8004220010 Comments on NRC draft study to Congress re extension of NRC regulatory authority over DDE waste operation Serious conflict would arise if NRC regulatory activities interfere widefense-related activities.

MOROAN, R. L. Energy, Dept of, 79/01/26 7pp

8004230300 RIL-62
Forwards NURE9/CR-0379.Vol 5, "Repts Distributed Under NRC Reactor Safety Research Foreign Technical Exchange Program," & NURE9/CR-0430, "New Hadrid Seismotectonic Study - Activities During FY78" LEVINE.8. Office of Nuclear Regulatory Research 79/10/18. 6pp

8004230300 RLL-62
Forwards NUREG/CR-0379.Vol 5. "Repts Distributed Under NRC Reactor Safety Research Foreign Technical Exchange Program."
& NUREG/CR-0450, "New Hadrid Seismotectonic Study - Activities During FY78"
LEVINE.8 Office of Nuclear Regulatory Research 79/10/18 6pp

--8004230303 NUREQ/CR-0379 V5

"Repts Distributed Under NRC Reactor Bafety Research Foreign Technical Exchange Program," Vol 3 (Jan-June 1978), QUEENER, D. B. Cak Ridge National Laboratory, FIN 8-0126 NSIC-156 78/11/30, 101pp. Available at NTIS.

--8004230307 NUREQ/CR-0450
"New Madrid Seismotectonic Study -- Activities During FY78 "
BUSCHBACH.T C Illinois, State of NRC 04-76-204 78/10/31
135pp Available at NTIS

8004230417 Comments on NUREO-0654 sirens are inadequate to warn farmers who live within 10-mile emergency planning zone Use of weather alert sys would be costly for state govt Emergency planning & related financing nood more attention HANSEN.R H Nabrasia, State of 80/04/15 2pp

8004230436 Comments on NUREQ-0654.App 3 Criteria for design of outdoor warning siren sys should exceed design guidlines specified in FEMA Publication CPOI-17. "Outdoor Warning Sys Guide." or Bolt.Bernack & Neumann. Inc Rept 4100 ANDERSON.M E Federal Signal Corp., Signal Div 80/04/15 2pp

8004240022 Submits trip rept re 761213-15 visit to DDE Richland operations & Hanford plant site Forwards agenda, list of attendees, summary of Hanford wastes & summary of site trip w/C Compton KLIOFIELD. G Vranium Fuel Licensing Branch 79/01/03 13pp

B004240454 NUREO/CR-1105
"Phenomenological Modeling of Small-Scale Vapor Explosion
Experiments "
CORRADINI,M L Sandia Laboratories FIN A-1030 SAND77-2003
B0/02/29 B9pp Available at NTIS

8004240444 NUREQ/CR-0989
"Recommendations for Program Dovelopment for Safety-Related Equipment Qualification Stds & Quides "
BGNZON.L L Bandia Laboratories SAND79-0944 79/12/31 145pp
Available at NTIS

8004240528 Forwards point-by-point response to ACRS 800311 rept re near-term OL items from Draft 3 of NUREQ-0640 Criteria used in near-term OL reviews are not suitable for all licensees DIRCKS, M J Office of Nuclear Material Safoty & Safeguards 80/04/01 11pp

8004240959 Forwards partial response to NRC request for review of NRC 790115 draft rept. "Regulation of Federal Radioactive Waste Activities" Discussion of DDE wastes & commercial wastes nonfactual & easily misconstrued
BARBER, R W Energy, Dept of 79/02/01 53pp

8004240565 NUREO/CR-1148

"BEACON/MOD3 Computer Program for Thermal-Hydraulic Analysis
of Nuclear Reactor Containments - User Manual "
BROADUS,C R. DOYLE,R J. JAMEG, B W EQ & Q, Inc FIN A-6042
E00-2008 80/04/30 228pp Available at NTIS

8004240566 NUREO/CR-1330

"Review of Methods & Criterion for Dynamic Combination in
Piging Sys "
REICHM, WANO.P C , CURRERI, J Brookhaven National Laboratory FIN
A-3123 80/03/31 560pp Available at NTIS

8004230047 NUREO/CR-1228
"Relative Hazard of Radioiodins as Function of (A) Radiation
Quality & (B) Age at Exposure "
BOOKS A California, Univ of, Davis FIN B-3028 80/04/30
23pp. Available at NTIS

8004250032 Comments on proposed draft NUREG-0448 "Study of NRC Appellate Bys " Existing sus & immediate effectiveness rule have worked well Rulemaking unnecessary MACRAE,C F LeBoeuf, Lamb, Leiby & MacRae 80/03/17 7pp

8004250057 Bubmits supplemental data to NRC 790103 trip rept re radioactive liquid waste discharged to ground at Hanford plant Provides complete listing of all active & inactive cribs & quantities of liquid waste discharged KLIQFIELD. Q Technology Assessment Branch 79/01/08 2pp

8004250370 Comments on NUREG-0654, App 2, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparadness in Support of Nuclear Power Plants " Some discrepancy exists between App 2 & other o

```
8004280024 NUREG/CR-1352
     204280024 Norte of the American Safety Studies for Div of Reactor Safety Studies for Div of Reactor Safety Research, " quarterly progress rept,Oct-Dec
     1979
BALL:5 J . CLEVELAND.J C . CONMLIN.J C Oak Ridge National Laboratory FIN B-0122 ORNL/NUREG/TM-3 80/03/31 10pp
8004280028 NUREO/CR-1123
"Fuel Agrosol Simulant Test Data Record Rept Argon Tests"
MRIGHT, A. L., SMITH, A. M., ROCHELLE, J. M. Dak Ridge National
Laboratory FIN 8-0121 CRNL/NUREG/TM-3 80/03/31 36pp
 8004280034 NURED/CR-0929
"BABRES II Individual Resolution Small Arms Combat
Simulation Model "
           Mulation ...
LAGUIL:P Sa
403/31 33pp
                                     Sandia Laboratories
                                          andia Laboratories FIN A-1173 SAND79-8249
Available at NFIS
 8004280035 NUREQ/CR-0976
     "User's Guide to Interactive FESEM "
SABSER.D W , BARKER.D E Sandia Laboratories F
SAND79-1895 80/01/31 50pp Available at NIIS
                                                                                                                      FIN A-10A0
B0042B004B NUREG/CR-1372

"Eddy-Current Insp for Steam Generator Tubing Program,"
quarterly progress rept for period ending 790930

DOAD.C V. DEEDS.W E. MCCLUNGR W Oak Ridge National Laboratory
FIN B-0417 URNL/NUREG/TM-3 B0/03/31 11pp
8004280075 NUREQ/CP-0011
    "Proceedings of Horkshops on Proposed Rulemaking on Emergency Planning for Nuclear Power Plants"
PEABODY C A. MORRONGIELLO, A Division of Siting, Health & Safeguards Standards 80/04/30 113pp Available at NTIS
8004280263 Forwards trip rept re 781219-20 visit to ORNL Purpose of
trip was to compile present & future waste inventory data
Info gathered re DOE.Union Carbide.Natl Lead & Goodyear
Atomic operations Agenda & list of attendees enc1
TOURIGNY,E 0 Operations & Planning Branch 79/01/11 7pp
8004280383 Bubmits comments on NUREO-0588, interim staff position on
environ qualifications of satety-related electrical
equipment Environmentally qualified safety-related
electrical equipment continues to be major problem
PIELAGC.H W Affiliation Unknown 80/04/18 2pp
80042804/3 Comments on proposed rules 10CFR30,40,50 & 70 EPA stds re
ladioactivity levels currently under discussion & should not
be considered final
PORTER.H L Duke Power Co 80/03/14 3pp
8004270001 NUREO/CR-1108
    "Numerical Study of Condensation in Concurrent Stratified Flows"
    PALY, B J , HARLOW, F H Los Alamos Scientific Laboratory LA-8077
80/02/29 27pp
8004290007 NUREO/CR-1126
    "Properties of Radwastos & Waste Containers," Progress Rept
12 for Jan-Mar 1979
COLOMBO,P , NEILBON,R M Brookhaven National Laboratory FIN
A-3027 BNL-NURGO-51101 79/10/31 25pp
8004290007 NUREC/CR-1268
   "Btructural Integration of Mater Reactor Pressure Boundary
Components," quenterly progress rept for Oct-Dec 1979
LOSB, F. J. Navy, Dept of, Naval Research Laboratory FIN
4174 60/03/20 64pp
                                                                                                                                FIN 0-5520 NRL
B004290012 Summary of NRC 781211-12 trip to INEL in ID Falls, ID Purpose was to get first-hand data re federal waste mgt programs at ID & Hanford operations Agenda, list of attendees & narrative
    KLIGFIELD, O Technology Assessment Branch 78/12/29 20pp
8004279017 NUREO/CR-1323
"Simulation of Thermohydraulic Transient in Pipe Using Commix-1A Computer Code"
CHEN.N J. DINANUS,H M , BHA,W T Argonne National Lab
```

"Impact of Decontamination on LWR Radwaste Treatment Sys "
PCRRIGOL D , DIVINE, J R , HOENES, L Q Battelle Memorial Institute,
Pacific Northwest Laboratory FIN B-2281 PNL-3277 79/04/30

8004270020 NUREO/CR-0986

Argonne National Laboratory FIN 73pp

```
8004290468 Forwards "Response to NUREQ-0487.Criteria for Computing
Loads on Submorged Structures." on behalf of Mark II owners
group as part of Task C 15 of Mark II containment program
BUCHHOLZ,R H General Electric Co , Nuclear Energy Products Div
MFN-081-80 80/04/21 2pp
  --8004290474 SAI-161-79-PA

"Response to NUREG-0487.Criteria for Computing Loads on Submerged Structures"

CHANDRA, V. HSIEH, J. S. Stone & Webster, Inc. DOMASHDVETZ, I Sargent & Lundy, Inc. 80/03/31 73pp
   8004300192 NUREQ/CR~0981
      overducing MUNEG/CR-0981
"Evaluating Strength & Ductility of Irradiated Zircalog,
Task 5," progress rept for Jul-Dec 1978
LOWRY,L M , PERRIN,J S , MARKWORTH,A J Battelle Memorial Institute,
COlumbus Laboratories FIN A-4068 BMI-2020 BD/04/30 80pp
Available at NTIS
  8004300206 NUREG-0592
      "Compilation of Reported Noble Gas Effluent Monitor
Capabilities at Operating Nuclear Power Plants "
FIALKOVICHIJ E. BLOCK.S Office of Nuclear Reactor Regulation
NUREG-0592 80/04/30 30pp Available at NTIS
 8004300540 NUREG-0430 VI N4

Grey book "Licensed Fuel Facility Status Rept," Vol 1,data
for decisions fuel cycle operations
* Office of Inspection & Enforcement, Office of the Director
B0/01/01 70pp
  DRG
                                CORRESPONDENCE WITH OTHER ORGANIZATIONS
  8004080572 Advises that IE Circular 80-05, "Emergency Diesel 
Oenerator Lubricating Dil Addition & Onsite Supply" was 
sent to listed utils on 800401 
CARROLL.D E Region 3, Chicago, Office of the Director 80/04/02
  8004090082 Informs that Naval Reactors plans to continue operation of
      present light water breader reactor core at Shippingport
Atomic Power Station beyond 18,000 effective full power
hours Summary of revised reactor operating parameters encl
RICKOVER, H G Energy, Dept of 80/03/10 3pp
  8004090087 informs that Naval Reactors plans to continue operation of
      present light water breeder reactor core at Bhippingport
Atomic Power Station beyond 18,000 effective full power
hours Summary of revised reactor operating parameters encl
RICKOVER, H O Energy, Dept of NRC 80/03/10 3pp
 B0041000B6 Advises that IE Bulletin B0-06, "Engineered Safety Feature (ESF) Reset Controls" was sent to listed utils on B00313 CARROLL, D E Region 9, Chicago, Office of the Director 80/03/17
 8004100089 Advises that IE Info Notice 80-08, "States Co Sliding Link
Electrical Terminal Block" was sent to listed utils on
800207
      CARROLL, D E Region 3, Chicago, Office of the Director 80/03/10
8004100517 Requests signing & returning encl std order for DOE work "Technical Assistance to NRC/DOR Emergency Preparedness Task Force " Work is being incrementally funded until NRC supplemental appropriation has been approved EISEMMUT.D 9 Division of Operating Reactors FIN A-7114
      80/03/20
--8004100520 Btd order for DDE work "Technical Assistance to NRC/DDR
Emergency Preparedness Task Force," Issued to LABL.
TRIPLETT.M P Office of Nuclear Reactor Regulation FIN A-7114
B0/03/20 Ip
 8004140085 Forwards std order for DOE work "Technical Assistance to
NRC/Div of Operating Reactors Emergency Preparedness Task
Force " Requests indication of acceptance by signing encl
       form 0173
      EIGENHUT, D @ Division of Operating Reactors FIN A-7114
      80/03/20
---800414008B Std order for DDE work "Technical Assistance to NRC/Div of Operating Reactors Emergency Proparedness Task Force," issued to ORNL TRIPLETT, H P Division of Operating Reactors. FIN A-7114
```

- BOO4150150 Advises that IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve," was sent to listed utils on 800331 CARROLL,D E Region 3. Chicago, Office of the Director 80/04/01
- 8004220154 Advises that IE Bulletin BO-OB, "Exam of Containment Liner Penetration Welds," was sent to listed utils on 800408 CARROLL.D E Region 3, Chicago, Office of the Director 80/04/09
- BO04220203 Advises that IE Info Notice 80-14, "Safety Suggestions From Employees" was sent to listed utils on 800404 CARROLL D E Region 3, Chicago, Office of the Director 80/04/09 200
- 8004220410 Advises that IE Circular BO-07. "Problems w/HPCI Turbine Dil Sys." was sent to listed utils on 800403 CARROLL.D E Region 3. Chicago, Office of the Director 80/04/07
- 8004230308 Advises that IE Builetin 79-03A. "Longitudinal Weld Defects in ASME 8A-312 Type 304 Stainless Steel Pipe." was sent to listed utils on 800404 for action CARROLL, D E Region 3, Chicago, Office of the Director 80/04/07
- 8004240002 Forwards std order for DOE work, "Atmospheric Release Advisory Capability Site Installations at Nuclear Power Plants," issued to LLL KERR.OW Office of State Programs 80/04/02 Jp
- --8004240006 Btd order for DDE work, "Atmospheric Release Advisory Capability Bits Installations at Nuclear Power Plants," issued to LLL KERR, 0 W Office of State Programs FIN A-0351-0 80-80-006 80/04/02 7pp
- 8004280259 Notification of 800416 meeting w/DDE & GRNL in Silver Spring.MD for FY80 mid-yr review of NSIC FY81 program assumption & 15t of topics/questions encl FARMER.W S Research Support Branch 80/04/04 4pp
- B004290038 Submits branch Info Rept 7 update on epidemiologic studies of Portsmouth Naval Shipyard workers
 QQLBSMITH,R Assistant Director for Radiol Health & Safeguards
 Standards B0/04/07 3pp

PR PROPOSED RULE

- 7904i10030 Ack receipt of editorial "Patient Exposure to X-Rays Whose Responsibility " Explains NRC regulations re use of radiolisotopes in medicine & actions re patient safety Federal Register notice encl COSSICKL V Office of the Executive Director for Operations 79/03/30 10pp
- --7904110034 Order modifying licenses to authorize possession & use of MO-99/Tc-99m generators DIRCKB.W J Office of Nuclear Material Safety & Safeguards 79/03/12 6pp
- 7907110564 Notice of new sys of records identified as Oral History Program.NRC-25 Collection of taped interviews w/NRC members will facilitate future writing of NRC history ODSBICK,L V Office of the Executive Director for Operations 79/06/04 4pp
- 7910230124 Notice of new routine use re Privacy Act of 1974 Records from NRC sys of records may be disclosed as routine use NRC contractor on need-to-know basis within scope of pertinent NRC contract ODSSICK, L V Office of the Executive Director for Operations 79709/21 3pp
- 7910250127 Notice of new sys of records re Privacy Act of 1974 Beecial Inquiry File, NRC-33 will provide access by individual name to records of special inquiry GOBSICK, L V Office of the Executive Director for Operations 79/09/21 6pp
- 7910250135 Notice of exemptions in 10CFR9 95 Portions of Special Inquiry Film are exempt from certain requirements of Privacy Act of 1974.

 OBSBICK, V Office of the Executive Director for Operations 79/09/21. 3pp.

- 8004030138 Comments on proposed rule 10CFR50 opposes change, due to possible extortion tactics by community or county-level officials Proposed rule should be withdrawn pending review of Rogovin Rept & NUREG/CR-1225 CRANDELL.J D 10ws State of 80/02/07 ip
- B004030277 "Computer Bys & Data Processing Requirements for Wasto Isolation Pilot Plant Conceptual Design Rept." Addendum M YOUNG,R Sandia Laboratories AT (29-1)-789 77/06/30 10pp
- 8004030281 SAND77-0274
 "Mine Safety Code Review for Waste Isolation Pilot Plant. Conceptual Design Rept." Addendum L
 = Sandia Laboratories AT (29-1)-789 77/06/30 16pp
- 8004030284 SAND77-0274
 "Soils & Foundation investigation for Proposed Haste Isolation Pilot Plant.Concoptual Design Rept." Addendum I PETTIGREN, R R Sandia Laboratories 77/04/30 31pp
- 8004030287 BAND77-0274 "Tailings Disposal Proposal for Waste Isolation Pilot Plant:Conceptual Design Rept." Addendum B POLI.D L Sandia Laboratories 77/04/30 7pp
- 8004030288 SAND77-0274
 "Conceptual Pesign Rept of Supportive Equipment in High Level Waste Facility.Conceptual Design Rept." Addendum B * Sandia Laboratories 77/04/30 92pp
- 8004030292 NP-23021
 "Considerations of Environ Protection Criteria for Radwaste," background rept

 Environmental Protection Agency 78/02/28 46pp
- 8004030274 ANL/EIS-11
 "Generic Haste Mgt Concepts for Six LWR Fuel Cycles"
 LUNER:C Argonne National Laboratory 79/04/30 115pp Available
 at NTIS
- 8004030298 INIS-MF-4745 "Handling & Final Storage of Unreprocessed Spent Nuclear Fuel" * Sweden 78/12/31 111pp
- 8004030279 Y/CHI/SUB-77/42500
 "US LWR Spent Fuel Inventory & Projection "
 HODDHALL, C B Nuclear Assurance Corp 77/06/30 203pp
- 8004030337 Comments on proposed rule 10CFR50 adequate state & local emergency plans should be made prerequisite for OLs Public can play constructive role in NRC review of local licenses OROSS,M Affiliation Unknown 80/02/23 3pp
- 8004030341 Comments on proposed rule 10CFR30 natl emergency planning/preparedness effort long overdue Implementation of proposed rulemaking re emergency planning somes presents political nightmare RENBERGER.D L. Washington Public Power Supply System 80/02/19600
- 8004030343 Comments on proposed rule 10CFR50 NRC should withdraw proposed rule that would preclude issuance of OLs for safe power plants Rule is extreme reaction rooted in politics MCMORMACK, M House of Rep , Science & Technology 79/12/20 2pp
- B004030345 Comments on proposed rule 10CFR50 opposes premise that low probability events should play important role in emergency planning size of emergency planning zones should be determined on case-by-case basis ANDERSON.T M Westinghouse Electric Corp , Nuclear Energy Systems NS-TMA-220B 80/02/19 3pp
- 8004030351 Comments on proposed rule 10CFR50 NRC should review local radiological emergency planning Concurs w/idea that local populations usually have more faith in local authorities than state gov!

 MECCA, J E Puget Sound Power & Light Co 80/02/15 2pp
- 8004030361 Comments on proposed rule 10CFR50 emergency response plan should contain contingency procedures for accidents & conditions unrelated to operation BRADLEY.J P Affiliation Uninown 80/02/20 9pp

- 8004040007 Advisos that on 800220,CA Energy Commissioner E Varanini sent attached 1tm to JF Abearne ELLISON,C T California, State of 80/03/03 1p
- ---B004040008 Discusses refusal of hearing officer to consider CA Energy Commission procedural suggestions to public participation & recordkeeping of rulemaking proceedings Order limits credibility of hearing process VARANINIEE C California, State of B0/02/20 Bpp
- 800A070187 Forwards joinder in NRDC motion to direct presiding officer to certify issues on NRC role in proceeding KINDER, E T New Hampshire, State of 80/02/24 1p
- --8004070202 Joinder in NRDC motion to direct presiding officer to certify issues on NRC role in proceeding on proposed rulemaking re radwasts Views of independent experts should be solicited Cortificate of Box onc!

 KINDER.E T New Hampshire. State of 00/02/26 7pp
- BOO40BOD4: Forwards comments on proposed rule 10CFR50, submitted by Ban Luis Obispo Area Task Force on Nuclear Power Issue emergency plans should be fully implemented as precondition of licensing ORIFFIN.R C Affiliation Unknown 80/02/15 27pp
- 8004080046 Responds to FDIA request for documents re-extraordinary nuclear occurrence concept, including proposed rulemaking, regulations & rules adapted by AEC Forwards documents listed in App A FELTON.J M Division of Rules and Records 80/03/18 Spp
- --8004080142 Forwards formal statement presented by M Zarin at AEC/industry 680611 conference 6 Natl Lead Go 680612 ltr commenting on proposed amend to indemnity regulations Ltr only encl PRICE, E R Atomic Energy Commission 68/06/19 1p
- 80040B0119 Comments submitted on behalf of WA Public Power Supply Sys. on proposed rule 10CFR90 FEMA role as lead agency must be reflected in final regulation REYNOLDB,N S Debevoise & Liberman 00/02/19 14pp
- BCC40B0125 Comments on proposed rule 10CFR50 technique of imposing util between federal, state & local courts is unprecedented & w/o justification State should have primary responsibility for coordinabling emergency plans PARKER.W O Duke Power Co 60/02/17 App
- 8004080147 Comments on proposed rule 10CFR50 new regulatory requirements are imposed on licensees before rule promulgation & w/o due process Objects to NRC use of utils to obtain & maintain concurrence in local emergency plans WARD. J E Atomic Industrial Forum 800/02/20 16pp
- 8004080152 Comments on proposed rule 10CFR50 only those interested in actual making of plans should be present BCALPI,M New York, State of 80/02/13 lp
- 8004080228 Comments on proposed rule 10CFR50 on behalf of Bouthern CA Edison Co FEMA is best suited to assess adequacy of local emergency planning Rule fails to provide objective stds for NRC concurrence. CASEY.8 D Chickering & Oregory 80/02/15 50pp
- 8004080245 Comments on proposed rule iOCFR50 rule is fundamentally flawed Link between NRC plan concurrence & licensing is harmful to industry & consumers NRC should consider emergency planning w/public safety & other vital goals MCCULLAM, W Edison Electric Institute 80/02/22. S5pp
- BOD40B0659 Comments on proposed rule 10CFR50 requests placement on mailing list for workshops on transporation & disposal of nuclear waste BEDR091AN. Y Novada, State of BO/02/09 1p
- 8004080674 Comments on proposed rule 10CFR90 agrees that upgrading omergency preparedness is necessary to protect public health to safety COTE. A Maine, State of 80/02/11 ip
- 8004080682 Comments on proposed rule 10CFR30 NRC should only allow review by persons or organizations who are totally independent of licensee & employees Plume exposure pathway rone should not be limited to 10-mile radius CLINTON.8 Arkansas, State of 80/02/19 4pp

- 8004090116 Comments on proposed rule 10CFR50 new concept of emergency planning iones will have greatest impact in Northeastern US where political jurisdictions overlap Agrees w/requirement for NRC concurrence w/state & local plans
 HEUBNER, A T Connecticut, State of 80/02/22 ip
- 8004090145 Comments on proposed rule 10CFRS0 extrasensory perception suggests possibility that nuclear power facilities are not well constructed BISHOP.0 Affiliation Unknown 80/02/18 ip
- 8004090152 Forwards comments on proposed rule 10CFR50 nuclear emergency planning has been neglected by Commission despite repeated warnings of significant problems Studies have established importance of emergency planning & proper siting POLLOCK, R P Critical Mass Energy Project 80/02/22 16pp
- 8004090156 Comments on proposed rule 10CFR50 implementation of Alternative II in FR notice may have unnecessarily harsh economic & social consequences Requests FR notice seeking public comments re Alternative A KITTRIDEE, GR Minnesota. State of 80/02/19 3pp
- 8004090160 Comments on proposed rule 10CFRBO requests clarification renumber of plans & patent of participation required for each govt entity State & local authorities should be able to coordinate needs
 MILLS, L. M. Tennessee Valley Authority 80/02/19 3pp
- 8004090165 Forwards W Connor 791207 ltr re proposed rule on emergency planning Requests comments CHILES.L Senate 80/01/03 ip
- --8004090168 Comments on proposed rule 10CFR50 opposes authority to closs down plants located in areas w/o acceptable state & local emergency plans Forwards Tampa Tribune 791206 articls recently anning CONNOR, W Affiliation Unknown 79/12/07 3pp
- 8004090172 Commonts on proposed rule 10CFR50 lack of communication between Met Ed & Governor Thornberg should be corrected State of NJ legislation will provide financial assistance from tax funds for upgrading health & public safety plans WILLODSEN, A F Affiliation Unknown 80/02/16 2pp
- 8004090186 Comments on proposed rule 10CFR50 thought should be given to developing practical implementation program which will follow publication of formal rules & guidelines Comments prepared for NY workshop on proposed rule changes encl
- 8004090188 Forwards comments on proposed rule 10CFR50, submitted on behalf of Southern CA Edison Co CASEY, 8 B Chickering & Gregory 80/02/15 1p
- ---8004070176 Comments on proposed rule 10CFR50, submitted on behalf of Bouthern CA Edison Co specific time limits in proposed rule should be replaced w/more realistic & flexible limitations Suggested util amends to proposed rule enci CASEY, S B Chickering & Gregory 80/02/15 53pp
- 8004090213 Forwards West Branch Conservation Association comments on proposed rule 10CFR80 ratepayers should not have to bear financial burden of safety mods to facilities emergency sys FLEISHER,W L. West Branch Conservation Association 80/02/18 2pp
- B004090229 Comments on proposed rule 10CFR50 contept of NRC concurrence in adequacy of offsite response to emergency is sound Model plans have proved to be of little assistance in past programs
 KYLE, J S Arizone, State of B0/02/28 5pp
- 8004070241 Comments on proposed rules 10CFR30, 40, 50 & 70, endorses comments on NUREO-0584. Revision 1 NUREO-0513 is too tantative in scope & purpose. In-place entombment should be considered viable alternative for decommissioning objective PORTER. W L Duke Power Co 80/03/14 3pp
- BOD4090247 Comments on proposed rules 10CFR30.40.50 & 70 averemphasizes probability of premature permanent shutdown NRC should not imply util future financial instability WILLIAMS.H P Florida Power & Light Co 80/03/13 3pp
- 8004090266 Forwards comments on proposed rule 10CFR50 no provision for public intervention in NRC concurrence process State & local emergency planners should be allowed to argue for or against concurrence before NRC DUMS,D Affiliation Unknown 80/02/27 3pp

- 8004090271 Comments on proposed rule 10CFR50 rule is vague, ambiguous & Gisellows public participation Intervention in concurrence is denied to currently operating plants MERRITTID Citizens for a Better Environment 80/02/19 5pp
- BO04090300 Forwards Luzerne County, PA 800116 ltr to NRC submitting comments on proposed rule 100FR50
 TOWNEND, F Affiliation Unknown 80/02/08 ip
- 8004090309 Comments on proposed rule 10CFR50 suggests FEMA obtain emergency plans directly from state & local govts Supports proposed Alternative A Questions benefit of 15-minute notification
 DISE,DP Niegara Mohawk Power Corp 80/03/05 2pp
- 8004090331 Comments on proposed rule 10CFR50 on behalf of three utils regulations are premised upon unsound legal assumptions Role of FEMA in emergency planning as significant & requires recognition in rule
 MCGARRY, J M Debevoise & Liberman 80/02/19 3pp
- 8004090460 Comments on proposed rule 10CFR50 recommends withdrawal of proposed rule precluding issuance of OLs w/o NRC concurrence on state & local emergency response plans WYDLER, J W House of Rep . Science & Technology 79/12/20 2pp
- BOD4D90463 Comments on proposed rule 10CFR30 emergency planning is as important as siting of facility All emergency related agencies should be staffed 24-h per day Public hearings should be held on emergency plan exemptions MANN, D L Susquehanna Alliance BO/02/15 3pp
- 8004100006 Comments on proposed rule 10CFR50 no exemptions to licenso should be given until emergency reponse plans are deemed adequate NRC should reconsider issuance of CP to facility BEIDTE/M 0 Affiliation Unknown 80/03/03 ip
- BOO4:0004: Comments on proposed rule iOCFR50 on behalf of Buffolk County,NY emergency planning must be viewed as equivalent rather than secondary to siting design in achieving public protection OILMARTIN,D J , LIKE,I Reilly & Like BO/02/26 13pp
- --8004100046 Transcript of 790710 testimony before NV State Board on Electric Ceneration Siting & Environ Pp 1-6 KLEIN.J.V.N Suffolk County, NY 79/07/10 8pp
- --8004100050 Transcript of 790629 testimony before NY State Board on Electric Generation Biting & Environ Pp 1-3 GEISELMAN, J N Environmental Protection Agency 79/06/29 6pp
- --8004100055 Transcript of 790629 testimony before NY State Board on Electric Generation Biting & Environ Pp 1-20 GIARDINA, P A Environmental Protection Agency 79/06/29 25pp
- 8004100074 Forwards comments on proposed rule 10CFR50 on behalf of Haddam.CT comments will be presented at workshop in NY Communication during an emergency is concern for local govt CONTILL L. Affiliation Unknown 80/02/14 3pp
- 8004100075 Forwards Oldham County, KY 800215 resolution as comment on proposed rule 100FR50 W/o state legislation that defines a authorizes local goves to implement emergency plans, any plan would be useless
 MOGREW. Affiliation Unknown 80/02/16 Soo

on proposed rule 10CFR50 insufficient attention y planning for research reactors NRC & FEMA which federal or state agency should key planning zones f. State of 80/02/15, 3pp

on proposed rule 10CFR50 applicant should provide or evacuation on exposure pathway zone be necessary for every type of potential lons may be more appropriate al Electric Co 80/02/22 16pp

on proposed rule 10CFRSO NY Dept of Health will compassing suggestions of various state

rk, State of 80/02/13 1p

comments on proposed rule iOCFRSO on behalf of ion should be taken against hasty strate that NRC is making substantial TMI-R accident.

ER.R E Shaw, Pittman, Potts & Trowbridge

- BOO4100294 Comments on proposed rule 10CFR61 disposal facility space should be used efficiently Storage facilities should also be addressed Some requirements should be given for incinerator use & for contaminated oil CHANDLEY, C.A. Tennessee Valley Authority BO/03/04 3pp
- BOO4100388 "Determination of Extraordinary Nuclear Occurrence."
 iOCFR140 83 financial protection requirements & indemnity
 agreements Extends date until BOO328 to determine whether
 TMI constitutes extraordinary occurrence
 CHILK.S J Office of the Secretary of the Commission BO/03/14
 lp
- 8004100418 Comments on proposed rule iOCFR50 NRC should permanently shut down all U mines % mills:processing plants,generating stations:nuclear weapons const & refurbishing sites & all other nonpower reactors to protect public health & safety HYDE,D W Affiliation Unknown 80/02/15 4pp
- B004100434 Forwards comments on proposed rule 10CFR50 supports Commission policy of upgrading emergency preparedness for operators of nuclear plants Local govt emergency planning is assential component of overall emergency plan PRATT.C M Power Authority of the State of New York 80/02/19 3ps
- 8004100438 Comments on proposed rule 10CFR50 submitted by Putnam County, My future workshops should include only those involved in making of plans SCALPI.M Affiliation Unknown BD/02/13 1p
- 8004100439 Comments on proposed rule 10CFR50 neither Alternative A or D acceptable Concurrence rule would pre-empt NRC authority to shut down plants or withhold licensing Fifteen-minute notification requirement is not justified STAMPLEY,N L Mississippi Power & Light Co AECM-80/39 80/02/19
- B004100450 Testimony before NY State Board on Electric Generation Siting & Environ re proposed Jamesport facilities KLEIN.J V Suffolk County, NY 79/07/10 Bpp
- --G004100460 Testimony before NY State Board on Electric Generation Siting & Environ re proposed Jamesport facilities Prof qualifications encl GEISELMAN, J N Suffolk County, NY 79/06/29 App
- --8004100472 Testimony before NY State Board on Electric Generation Biting & Environ re proposed Jamesport facilities Related diagrams, ref & prof qualifications entl DIARDINA, PA Suffolk County, NY 79/06/29 25pp
- 8004100441 Comments on proposed rule 10CFR50 local funding issue should be considered Federal & state manpower should be available to aid in problems at local level Local personnel should be consulted prior to formulation of related regulations TERRELL.D Suffolk County, NY 80/02/08 1p
- 8004100443 Ack receipt of 800201 ltrs requesting comments on proposed emergency planning rule Comments from state representatives will be consolidated into single response SMITH-E H New York, State of 80/02/13 1p
- 8004100445 Comments on proposed rule 10CFR50 15-minute early warning is impractical Recommends use of Emergency Broadcast Sys Deadline for NRC concurrence in state & local plans is not reasonable Lack of county govt in CT poses special problems MANCUSD,F. Connecticut, State of 80/02/28 2pp
- 8004100449 Comments on proposed rule 10CFR90 shortcoming lies in NRC inability to direct govt units to prepare plan & compel adequacy WYDLERJ W House of Rep , Science & Technology 80/02/15 lp
- 8004100494 Comments on proposed rule 10CFR30 no OL should be granted unless NRC finds that appropriate protective actions can be taken within emergency planning zone
 AMATO.S Rhode Island, State of 80/02/25 2pp
- 8004100901 Comments on proposed rule 10CFR50 submitted on behalf of Brooklyn SHAD If locality unable to finance adequate plan. Itcensee should finance or formulate own plan Supports Alternative B GROBS.M Affiliation Unknown 80/02/28 Spp
- 8004100515 Comments on proposed rule 10CFR50 rule does not provide definitive guidance & criteria Objects to use of utils to obtain concurrence in state & local emergency plans FEMA should have lead responsibility
 WARD, J E Atomic Industrial Forum 80/02/20 16pp

1

- 8004100540 Comments on proposed rule 10CFR50 insufficient time allowed to develop comprehensive emergency response plans Recommends revised draft plans be submitted to NRC/FEMA for review by BiO101 & final concurrence achieved by BiO701 KEARNS, J. J. California, State of 80/02/15 App
- --8004100544 Comments on proposed rule 10CFR50 NRC involvement in review & evaluation of response plans is integral part of overall responsibility for protection of public San Luis Obispo County 800115 ltr to 8tate of CA encl
 LANGLEY.C Affiliation Unknown 80/01/08 6pp
- 8004100588 Comments on proposed rule 10CFRSO legislation should be proposed comments on proposed rule tOCFRSO legislation show proposed requiring that tax revenues generated by operating plants be applied to costs of emergency planning Addresses problem on generic basis 2 assures continued cooperation MAURO, J Ebasic Services, Inc. (subs. of Enserch Corp.) 80/02/11 4pp
- BOO4100604 Forwards comments concerning proposed rule 10CFR50 NAMDJ, M New Hampshire. State of BO/02/28 1p
- -B004100609 Comments on proposed rule 10CFRSD improved prompt notification & warning of general public needed Bys should be evailable & applicable to air hazards which would require prompt notification FQLEY.E New Hampshire, Btate of B0/02/27 ip
- -8004100612 Comments on proposed rule 10CFR50 NRC should approach proposal as significant regulatory change Flexibility in concurrence procedure is necessary & deserves commitment KINDER, E T New Hampshire, State of 80/01/15 App
- 8004110109 Forwards comments on proposed rule 10CFR50 evacuation may not be necessary for every type of potential accident Fifteen-minute notification period should begin after state or local officials decide evacuation is necessary KAPLAN.A L General Electric Co., Nuclear Energy Products Div 80/02/22 16pp
- 8004110127 Comments on proposed rule 10CFR50 cooperative working relationships should be developed in areas of radiological emergency response planning to assure protection of public health & safety CLINE.W E Georgia. State of 80/03/04 3pp
- 8004110147 Comments on proposed rule 10CFR50 language is ambiguous in places More clarification & numerous editorial changes QRENDON, I Affiliation Unknown 79/12/27 App
- 8004110367 Comments on proposed rule 10CFR90, opposes mandatory participation in NPRDS Improvement to NPRDS can & should be achieved but not by adding regulatory actions in areas of questionable near-term safety significance KEARNEY, J J Edison Electric Institute 80/03/31 2PP
- 8004110477 Comments on proposed rule iOCFR2 expresses great disappointment that proposed changes fail to solve problems of NRC licensing sys Proposed regulations only protect over-inflated agos of licensing members KEPFORD.C Environmental Coalition on Nuclear Power 80/03/03
- BOO4110480 Comments on proposed rule iOCFR2 proposed use of part-time members as special master or alternate board members would be contrary to both Atomic Energy Act & Administrative Procedure Act
 LEBOCUF.R. J. LAMB, H.R., LEIBY.A.C. LeDoeuf, Lamb, Leiby & MacRae LAMB, H R . LEIRY, A C LeBoeuf, Lamb, Leiby & MacRee 80/03/24
- 8004110484 Comments on proposed rule 10CFR2 provisions for preparation of advisory repts by special assistants should be deleted VAN BRUNT, E. E. Artzona Public Service CO. 80/03/25 3pp
- 8004110491 Comments on proposed rule 10CFR30. opposes requirement for mandatory participation in NPRDS Implementation costs are overstated MCMEER, C S Wisconsin Electric Power Co 80/03/20 2pp
- 8004110496 Comments on proposed rule 10CFR50 NRC should perform thorough reassessment of needs served by NPRD8 before mandating wider participation MCCUTCHAN. D A Westinghouse Electric Corp 80/03/07 3pp
- 8004110505 Comments on proposed rule IOCFR50 opposes regulations making NPRDS mandatory Submits response to 21 questions in FR notice HAVETER,R L. Consumers Power Co 80/03/11 18pp

- B004110523 Comments on proposed rules 10CFR2.19,20,21,30,40,51,60. & 70 rules are inadequate re-participation of Indian Tribal govts Failurs to involve tribes in initial process will result in later practical & political difficulties STONE.R J Energy, Dept of 80/03/24 2pp
- 8004110535 Comments on proposed rule 10CFR50 budget severely limits county emergency proparedness Overall emergency planning operation would be enhanced of facility & county personnel Could meet

 HAYES, W.K. Orean County, NJ 80/02/17 3pp
- 8004110558 Comments on proposed rule 10CFR50 alternatives to negative declaration may offer comparable bonefits but cost significantly loss Provisions should be made for basis to assess replacement costs associated w/plant shutdown PARKER,W O Duke Power Co 80/02/19 2pp
- 8004140009 Forwards comments on proposed rules lOCFR30,40,50 & 70 on behalf of CPC financial provision for decommissioning is most efficient & economical procedure REYNOLDS.N & Debevoise & Liberman 80/03/20 4pp
- 8004140025 Comments on proposed rule 10CFR50 NRC has broadly interpreted Commission charter re requiring emergency plans to be formulated, but stops short of forcing state govts to see plans are prepared Handatory requirements are needed WYDLER.J W House of Rep., Science & Technology 80/02/15 80/02/15 16
- 8004140047 Forwards comments on proposed rule 10CFR50 made at NRC 800117 emergency preparedness workshop in Ban Francisco, CA OLCOTT, K. Affiliation Unknown 80/01/17 ip
- ---8004140052 Comments on 10CFR50 presented at NRC B00117 emergency preparedness workshop in San Francisco.CA Adequate amergency planning should be requirement for nuclear facility CP & DL DLCOTT.K Affiliation Unknown B0/01/17 2pp
- GOO4140094 Comments on proposed rule 10CFRSO size of emergency planning runes should be determined on individual basis redemography, topography, land characteristics, access routes & local jurisdictional boundaries ANDERBUN, T M Hostinghouse Electric Corp NB-TMA-220B 80/02/19
- 8004140046 Forwards comments on proposed rule 10CFR50 TOWNEND.F Luserne County.PA 80/02/08 tp
- ~-8004140100 Comments on proposed rule 10CFR50 util should be responsible for activities on nuclear facility site Govt should be responsible for offsite activities Use of term "plume exposure pathway emergency planning zone" is misleading TOWNEND,F Luserne County,PA 80/01/16 2pp
- 8004140105 Comments on proposed rule 10CFR50 realistic plume exposure & ingestion pathway zones must be established regardless of difficulty of evacuation
 HYDE D W Affiliation Unknown 80/02/15 App
- 8004140109 Comments on proposed rule 10CFR80 App E acceptable, but waste of time to have applicant provide analysis of time required to evacuate sectors in plume sepasors pathway Suggests that NRC consider plant siting more critically PAONO, C. L. New Jersey, State of 80/02/22 ip
- 8004140112 Comments on proposed rule 10CFR50 on behalf of SCANP Ofc has yet to receive requested documents that are essential for preparation of comments, due to NRC delay TOLEERT.PE Leed.R M 80/02/22 Zpp
- 8004140131 Comments on proposed rulemaking submitted by NY City Bar Association supports AEC Intention to withdraw 2-yr discovery clause Bupports exclusion re claimants w/ abnormally sensitive activities AXELRAD, N Affiliation Unknown 69/01/20 5pp
- 8004140149 Comments on proposed rule iOCFR30 NRC role during nuclear emergency & final authority of govenor must be clearly defined State should be directly notified of NRC requirements re licensee or local authority PAGANO.C L New Jersey, State of 80/02/22 ip
- 8004140419 Comments on proposed rule 10CFR80 actual emergency preparedness should be criteria for concurrence & not merely existence of state & local plans Criteria for determining insignificant deficiencies heeds to be established CARR:H League of Homen Voters of Ban Luis Obispo, CA 80/02/14

- 8004140426 Comments on proposed rule 10CFR5D adequate emergency planning should be required for CP Plants should be shut dawn in absence of concurrence Public should be notified of emergency procedures at 3-6 month intervals OLCOTT, K Affiliation Unknown 80/01/17 3pp
- 80D4i50i22 Comments on proposed rule iOCFR50 requirements for local & state approval of licensee emergency plans can result in subversion of entire open licensing process by small group of individuals

 BTEINDLER, M J Argonne National Laboratory 80/01/02 3pp
- BOC-4150224 Forwards FR Notice of proposed rule 10CFR70 re issuance of general license to carriers of irradiated BNN Final version of rule will be developed after consideration at public comments
 MINDQUE.R B Office of Standards Development 80/03/25 2pp
- 8004i60055 Comments on proposed rule 10CFR90 no GL should be issued unless NRC finds that appropriate protective actions can be taken for any reasonably anticipated population within plune explosure emergency planning ione AMATO.8 Shode Island. State of 80/02/25 2pp
- BOO4160078 Forwards comments on proposed rule 10CFR50 each nonpower reactor operation needs emergency planning zone unique to operation Basic plan should be appropriately designed Evacuation may not be needed for all potential incidents KAPLANAL General Electric Co. Nuclear Energy Products Div 80/02/22 16pp
- 8004160076 Comments on groposed rule 10CFR50 NRC is trying to impose detailed requirements from draft document NUREG-0654 NRC has ignored industry & peer comments Rush to implement draft mattix causes concern, Util 800219 add1 comments encl VANDENBUROH, D Yantee Atomic Electric Co WYC-80-3 80/02/29 200
- --BO04160102 Comments on proposed rule 10CFR50 linkage between enforcement actions against NRC licensess & failures by stats & local govts to achieve concurrence u/federal govt is illogical Negative declaration entirely fallacious VANDENBURGH, D Yankee Atomic Electric Co HYC 80-2 80/02/19
- BOO4160185 Requests comments an proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by BOO415 FR notice encl 'AHEARNE'J F Commission 80/03/12 1p
- --BOO4160190 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl
 AHEARNEJ F Commission 80/03/12 2pp
- ---BOO4160173 Requests comments on proposed rulemaking concerning disposal of radwastas produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE.JF Commission 80/03/12 2pp
- --8004160196 Requests comments on proposed rulemaking concerning disposel of radwastes produced by nuclear facilities Comments due by by 800415,FR notice encl AMEARNE.JF Commission 80/03/12 2pp
- --BOO4160200 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by BOO415 FR notice encl AHEARNE.J F Commission BO/03/12 2pp
- --BOO4160202 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by BO0415.FR notice and AHEARNE, J F Commission 80/03/12 2pp
- --BOO4160203 Requests comments on proposed rulemaking concerning disposal of redwastes produced by nuclear facilities Comments due by BOO415 FR notice encil AMEARNE, J F Commission 80/03/12 2pp
- ~-BOO4160206 Requests comments on proposed rulemaking concerning disposal of radwestes produced by nuclear facilities Comments due by BO0415 FR notice encl AHEARNE.J.F Commission 80/03/12, 2pp
- --8004160209 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by BO0413 FR notice encl AHEARNE.J.F Commission 80/03/12 2pp

- --8004160212 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AMEARNE, J F Commission 80/03/12 2pp
- ---8004160215 Requests comments on proposed rulemaking concerning disposal of radustes produced by nuclear facilities Comments due by BO0415 FR notice and AMERINE, J F Commission BO/03/12 2pp
- ---8004160220 Requests comments on proposed rulemaking concerning disposal of raduastes produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE, J F Commission 80/03/12 5pp
- BOO4170202 Forwards questions & comments resulting from BO0219-20 meeting w/Radiological Assistance Committee.Radiological Emergency Planners & FEMA Region 3 state directors in Olen Ellyn.IL re revised criteria in NUREG-0654/FEMA REP-1 MCCOLLOUGH,P H Federal Emergency Management Agency B0/03/07 600
- B0041702B4 Forwards comments on proposed rule 10CFRSO Includes Jan 1980 ltr from NH assistant attorney general to NRC NAMOJ.H New Hampshire, State of 80/02/28 Spp
- 800417034B "Deletion of Ref to Panama Canal Zone Minor Amends," 10CFR4, 20, 30, 40, 50, 55, 70, 110 & 150 final rule Minor amends revise portions of Commission regulations to reflect revised status of Canal Zone DIRCKB.W.J. Diffice of the Executive Director for Operations 80/03/14 5pp
- 8004170355 "Export of Certain Minor Quantities of Nuclear Math," 10CfR110 final rule Amends regulations to establish or expand general licensing provisions for gram quantities of SMM & certain kinds of source & byproduct matl CHILK-S J Office of the Secretary of the Commission 80/03/14
- 8004180211 Responds to 800128 ltr re NRC emphasis on emergency planning for nuclear accidents NRC & FEMA cooperate in developing emergency planning rules & related state guidance AHEARNE. J F Commission 80/03/18 lp
- ~-8004i80220 Comments on proposed rule re emergency planning more emphasis should be placed on planning for probability of catastrophic nuclear accident in context of potential danger from nuclear weapons & other possible diasters WYOLER.J W House of Rep. 80/01/28 19
- B004180304 Responds to 791120 ltr re certain aspects of NRC proposed new 10CFR60. "Disposal of High Level Radwaste in Geologic Repositories: Procedural Aspects " Need for in situ testing & exploration supported by USOS, NAS & earth science community AHEARNE, J F Commission 80/03/18 Spp
- --8004180311 Responds to 791120 ltr re certain aspects of NRC proposed new iOCFR60, "Disposal of High Level Radwaste in Geologic Repositories/Procedura! Aspects "Need for in situ testing & exploration supported by USGS.NAS & earth science community AHEARNE.J F Commission 80/03/18 Spp
- --8004180319 Comments on Proposed Rule 10CFR40 multiple geologic testing & exploration unnecessary & costly NRC should support DOE repository development program WYDLER.J W. House of Rep , Science & Technology 80/01/20 2pp
- BOO4180477 Comments on proposed rule IOCFR50 opposes any regulations which make NPRDS mandatory Persons supplying info would become more interested in compliance w/requirements than using sys to enhance plant safety & reliability GARY,R J Texas Utilities Generating Co 80/03/10 ip
- BO042:0110 Comments on proposed rule 10CFR50 illogical linkage between enforcement actions & failures by local & state goyts to achieve concurrence w/federal agencies is flaw which could result in substantial environ impact VADENBURGH.D Yantes Atomic Electric Co HYC 80-2 80/02/19 3pp
- BOO4210118 Comments on proposed rule 10CFR50 intended to write something into record before deadline Time did not permit mention of issues Advising other II residents that FR exits BONNEVILLE, R B Affiliation Unknown 80/02/16 2pp
- 8004210140 Comments on proposed rule 10CFR50 NRC role during course of nuclear emergency should be clearly defined Governor should be final authority to render decisions State needs to be made aware of NRC requirements for licensee & authorities PAGANO.C L New Jersey. State of 80/02/22 ip

- 8004210150 Comments on proposed rule 10CFR50 nuclear plants would be pawns in game in which owner-operators have little ability to affect outcome
 HUNTER.R S American Electric Power Co , Inc. 80/02/20 5pp
- 8004210154 Forwards comments on proposed rule 100FR50 from MN Dept of Public Safety
 FRENZEL, B House of Rep 80/03/07 1p
- --8004210160 Comments on proposed rule 10CFR50 consequences should be weighed re reactor sites inwhich adjoining states are within reactor emergency planning ione KITTRIDGE, G R Minnesota, State of 80/02/23 3pp
- 8004210353 Forwards statement of position per presiding officer 800201 re proposed rulemaking in radwaste storage & disposal DISTEFANO.J., COLEMAN.L R. BROWN.O F Energy.Dept of 80/04/15
- --8004210361 Statement of position re proposed rulemaking on radwaste storage & disposal Fuel may be disposed of offsite & may be stored safety onsite or offsite until ultimately disposed W/supporting documentation & Certificate of Svc DISTEFANO, J. DOLEMAN, C.R., BROWN, O.F. Energy, Dept of DOE/ME-0007 80/04/15 714pp
- ROO4210446 Comments on proposed rule 10CFRSO during operation all response coordinators should be operational as unit.vs existing situation County maintains four salaried personnel to achieve some degree of emergency preparedness HAYES.W K Ocean County. NJ 80/02/17 3pp
- 8004230047 Forwards list of participants & computer bibliography index of waste storage & disposal documents placed in PDR List will be updated periodically & copies sent to participants CYR.K D Rulemaking & Enforcement Division 80/03/28 28pp
- 8004230073 Comments on proposed rule iOCFR2 NRC should not adopt provisions except for 2 713(b) Submits add1 comments reproposed changes in govt discipline adjudicatory proceedings JOHNSRUD, J H Environmental Coalition on Nuclear Power 80/03/03
- 8004240230 Advises that 148 core documents on waste storage & disposal have been placed in PDR per proposed rules 10CFR30 & 31 List of documents & info on placing orders encl
 CYR.X D Office of the Executive Legal Director. 80/03/28 27pp
- 8004240568 Forwards comments on proposed rule 100FRSO smergency plans should be upgraded in response to potential hazards. Fundamental problem exists in coordinating plans of state & local acencies Energy, Dept of 80/03/04 1100 PRESSESKY A J
- 8004250071 Comments on proposed rule 10CFR50 FEMA position on proposed rule, that action should be deferred for further evaluation, is appropriate KNUTH, D.F. MMC, Inc. 80/03/14 3pp
- 8004250306 Comments on proposed rule 10CRF50 air lock testing of air lock not used in sir-month period should not be required until after usage or within three days of first opening, if containment integrity required ERVIN.P E Affiliation Unknown 80/02/19 ip
- 8004280075 NUREG/CP-0011 104280075 NUREGYET-OUTS "Proceedings of Horkshops on Proposed Relemaking on Emergency Planning for Nuclear Power Plants" PEABODY,C A, MORRONGIELLO, A Division of Biting, Health & Bafeguards Standards 80/04/30 113pp. Available at NTIS
- 80042B0077 Forwards summary of NRC licensing program for high level radioactive waste disposal includes NRC 791206 FR notice & Div of Waste Mgt FY81 budget for high level waste mgt program
 CYR,K D Rulemaking & Enforcement Division 80/04/16 32pp
- 8004280172 Forwards comments on proposed rule 10CFR50 definition of local govt entities needed. Required NRC concurrence in state & local emergency plans gives NRC undue influence in local affairs, particularly in area of employment stability PRESGESKY, A J Energy, Dept of 80/03/04. 11pp
- 8004280218 Preliminary statement in response to Chairman Ahearne 800312 Itr re proposed rulemaking on radwaste storage & disposal Solid radwaste may be disposed of w/o risk based on fundamental earth science processes Interior,Dept of, Geological Survey 80/04/15 i4pp

- B004280473 Comments on proposed rules 10CFR30,40,50 & 70 EPA stds re radioactivity levels currently under discussion & should not be considered final PORTER.W L. Dute Power Co. 80/03/14 3pp
- 8004300279 Comments on proposed rule 10CFR2 not appropriate to specify number of sites & media to be explored in advance; endorses concepts & intent re site characterization reptiNRC requirements concerning site selection should be broad BARTLETT, U W The Analytic Sciences Corp 80/03/03 7pp
- 8004300532 Comments on Proposed rule 10CFR2 opposes Subsections 2 722 (a)(2) & (3) Proposed regulation would subj special assistant to disqualification procedures Proposal to amend rule & allow ASLB special assistants should be deleted VAN BRUNT, E E Arizona Public Service Co 80/03/25 3pp
- PETITION FOR RULEMAKING
- 8004040243 Comments on petition for rulemaking requests NRC position re question of vulnerability to possible enemy action in design of nuclear power plants HK Watson 800106 ltr encl DICKS, N D House of Rep 80/02/15 ip
- 8004080110 Draft ltr responding to 680703 comments re publication of proposed amends re financial protection requirements & indemnity agreements DOT concerns have been resolved by adding language clarifying effective rule PRICE, E R Atomic Energy Commission 68/07/18 ip
- 8004090224 Comments on petition for rulemaking 50-26 petition is based on several erroneous assumptions & should be denied Petition forces unreasonable requirements on now nuclear facilities OILMAN,D W San Diego Gas & Electric Co 80/03/07 2pp
- 8004100033 Transcript of 800313 Affirmation Session 80-10 in Washington.DC Pp 1-5 * Commission 80/03/13 Spp
- --8004i00039 SECY-80-095 Recommends NRC approval of FR publication of encl motice of denial of petition for rulemaking 2-5 SHAPAR, H K Office of the Executive Legal Director BD/02/14
- B004100057 Comments on petition for rulemaking concern about explosion of nuclear weapon in vicinity of nuclear facility exemplifies NRC overreaction to potential hazards Planning for such contingencies increases energy cost to ratepayers PETERSON, R J Affiliation Unknown B0/03/05 ip
- BOO4100064 Comments on petition for rulemaking proposed further increase cost & delay const of needed power p for no useful purpose LOVE.E. Affiliation Unknown BO/03/03 ip

- ---B004140133 Forwards FR notice denying state of NH 781031 petition for rulemaking re efficiency in licensing Denial based on public comments & current extensive review & evaluation of NRC licensing requirements & procedures W/o encl CHILK, S J Office of the Secretary of the Commission B0/03/21
- --8004140135 Forwards FR notice denying State of NH 781031 petition for rulemaking re efficiency in licensing Denial based on public comments & current extensive review & evaluation of NRC licensing requirements & procedures W/o encl CHILK S J Office of the Secretary of the Commission 80/03/21 ip
- --8004140139 Forwards FR notice denying State of NH 781031 patition for rulemaking re efficiency in licensing Denial based on public comments & current extensive review & evaluation of NRC licensing requirements & procedures W/o encl CHILK.S J Office of the Sacretary of the Commission 80/03/21
- --8004140140 Forwards FR notice denying State of NH 781031 petition for rulemaking re efficiency in licensing Deniel based on public comments & current estensive review & evaluation of NRC licensing requirements & procedures CHILK, S J Office of the Secretary of the Commission 80/03/21 24ms
- ---B004i40i43 Notice of denial of petition for rulemaking re efficiency in licensing nuclear power facilities Denial based on public comments & current extensive review & evaluation of NRC licensing requirements & procedures

 CHILK.S J Office of the Secretary of the Commission B0/03/21
- 8004140245 Forwards draft notice of denial of Petition for Rulemaking 2-9 requesting to amend 100FR2 to limit intervenor cross-examination SHAPARIH K Office of the Executive Legal Director. 80/03/12 Spp
- 8004240194 Discusses, on behalf of Northern IN PSC. Btate of IL & Porter County Chapter of Izaat Halton League of America Inc et al. 791220 petitions seeking amend or rescindment of IOCFR50 55(b) No good cause re const completion date shown SHEALK H. FRANTZ. B P Lowenstein. Newman, Reis. Axelrad & Toll 80/04/07 12pp

PROJECTS - PREDOCKET LICENSING

- 8004020063 Forwards Denver & Albuquerque public meeting transcripts in response to 800212 request Name of commentator & affiliation are identified in transcript where possible. H/o encl
 FISHER: B Uranium Recovery Licensing Branch 80/03/18 ip
- 8004030317 Bubmits info re util 800222 survey of files of intervenor-City of Roseville.CA Burvey was done to verify document discovery re comprehensive performance of NCPA Omissions discovered MEISB.R L Pacific Oas & Electric Co 80/02/29 2pp
- BOO404005B Forwards belance of exhibit to second supplemental answers to fourth set of interrogatories from CA Dept of Water Resources

 MEIBR.R L Pacific Gas & Electric Co 80/03/13 ip
- --800404006B Prepared testimony re transmission functional sub categories within transmission cost category required for accounting purposes Description of transmission functions & related financial info encl.
 PATTERSON
- 8004080012 Notice of appearance in proceeding Certificate of Svc encl CDSORIFF, J E Pacific Oas & Electric Co. CDSORIFF, J E McCutchen, Doyle, Brown & Emersen 80/03/18. 4pp.
- 8004080132 Motion to compai CA Dept of Mater Resources compliance \(\sigma \) ABLB 791109 \(k \) 80011\(d \) orders be answers to certain of PO&E fifth set of interrogatories Supplemental answers dtd 800303 do not comply \(\sigma / \) orders. Certificate of 8vc encl COBORIFF, J. E. COBORIFF, J. E. Pacific Oas \(k \) Electric Co. \(* \) McCotchen, Doyle. Brown \(k \) Emersen. \(80/03/18 \) 30pp
- B0040B0445 Forwards City of Santa Clara responses to PQME fifth set of interrogatories directed to Northern CA Power Agency & CA Dept of Mater Resources & to PQME fourth set of interrogatories directed to cities of Anheim & Riverside ADRAQNA.J.M Spiegel & McDiarmid. 80/03/13. 2pp

- 8004090208 Motion stating points & authorities directed to US ninth circuit court of appeals re review of ASLB 780828 subpoena duces tecum Requests order requesting 90-day stay for briefing schedule W/draft order & Certificate of Svc RIZZI,R A . BARRY,D N Southern California Edison Co RIZZI,R A Gibson, Dunn & Crutcher 80/03/03 7pp
- 8004100547 Responds to 800227 ltr refusing to accept Northern CA Power Agency voluntary document production & insisting on green dotting process Deplares PGBE harrassment tactics Requests maeting to resolve problem ADRAGNA, J M Spiegel & McDiarmid 80/03/05 3pp
- B004100556 Forwards responses to PG&E fifth set of interrogatories to Northern CA Power Agency & Dept of Water Resources & fourth set of interrogatories to Cities of Anaheim & Riverside dtd 790719 M/o encl TRAUGER, T C Spiegel & McDiarmid B0/03/03 App
- 8004150173 Order granting extension until 800417 for CA Dept of Water Resources to respond to POVE 800328 fifth set of interrogatories MILLER.M E Atomic Safetu and Licensing Board Panel 80/04/08 in
- 8004160280 Advises of omitted transmittal slips & corresponding boxes re stipulation concerning production of documents stored in warehouse Requests production of boxes during final visit to records ctr
 OCLOBERO, J R Antitrust Division B0/04/15 2pp
- BOD41B0277 Forwards response to 791206 inquiry re NRC Agreement States program & Church Rock dam failure RI submittal satisfied Atomic Energy Act; Section 274 requirements for admission as Agreement State AHEARNE, J F Commission BO/03/17 10pp
- 8004230275 Forwards Southern CA Edison Co & NRC agreement & joint statement re subpoema duces tecum Also forwards NRC stipulation re Edison documents production Issue resolved QDLDBERG. J R Antitrust Division 80/04/22 ip
- --8004230302 Executed agreement & joint statement re subposed duces tocum issued to Southern CA Edison Co re production of documents by Edison to NRC EHERHODD: A L Southern California Edison Co ODLDBERG. J R Antitrust Division 80/04/08 6pp
- --B004230317 Executed stipulation re production of documents by Southern CA Edison Ca to CA Dept of Water Resources & NRC Production agreed upon will satisfy subpoena for which Edison will uithdraw appeal before US 7th circuit Draft order enci SHERWOOD. A L. Bouthern California Edison Co STRUMMASSER, M California, State of OOLDBERO, J R Antitrust Division 80/04/10 4pp
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8004100061 Part 21 rept re defective Rosemount Model 5100U trip/calibr units & Model 1152 pressure transmitters Caused by failure of essential switch that determines trip output logic & failure of transmitter capacitor, respectively SHERWOOD, O G General Electric Co MFN-065-80 80/03/21 2pp
- B004210345 Deficiency rept re NIBD23 fire damper spring brackets Cause unstated Tests being conducted to demonstrate effectiveness of bracket scraws & to establish more stringent installation requirements
 HILL.T D Ruskin Manufacturing Co 80-193-001 80/03/17 ip
- 800428024B Part 21 rept revising 800206 notification re ITT AH90 & NH90 series electrohydraulic actuators Attachment listing customers & projects should contain addl item Baint Lucie facility & customer Buffalo Forge Co should be added BLOAN, D E American Warming & Ventilating, Inc 80/03/19 3pp
- B004300274 Part 21 rept re improper installation & inconsistent closure of Ruskin Mfg Co NIBD23 fire damper spring brackets during cycling tests Mfg taking corrective action HILL.T D. Ruskin Manufacturing Co 80/03/17. 2pp.
- 8004300556 Part 21 rept re Dresser Industries pilot operated relief valves & ABME code safety valves designed & tested for saturated steam as only flow medium Utils & AEs have been notified TACY. H Dresser Industries, Inc. 80/04/01 App

NONDOCKETED ITEMS

QA999 QUALITY ASSURANCE INSPECTIONS

- 8004010512 Forwards GA Program Insp Rept 99700022/79-01 an 791218-19 PDTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/01/14 2pp
- --B004010515 GA Program Insp Rept 99900022/79-01 on 791218-19 Insp revealed vendor ASME NPT certificate of authorization omitted product description Corrected certificate requested OLLER, R E, HUNNICUTT D M Region 4, Dallas, Office of the Director B0/01/14 3pp
- 8004020423 Forwards GA Program Insp Rept 9990251/80-01 on 800128-0201 No nancompliance noted FDTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/02/14
- ---8004020434 QA Program Insp Rept 99900251/80-01 on 800128-0201 No noncompliance noted Major areas inspected mot meeting & implementation of QA program interface w/ANI.mgt process control.control of nonconformance & corrective action WHITESELL.D E , BROWN,R L Region 4, Dallas, Vendor Inspection Branch 80/02/13 15pp
- B004030235 Ack receipt of B00305 ltr informing NRC of steps taken to correct violation noted in QA Program Insp Rept 97900342779-02 PDTAPOVS.U Region 4. Dalias. Office of the Director 80/03/19
- --B004030237 Responds to NRC 791210-14 audit deviation noted in QA Program Insp Rept 99900342/79-02 Corrective actions welds ultrasonically tested to insure soundness. Floor inspectors instructed to survey use of template sticks ROZEK.R Lakeside Bridge & Bteel Co B0/03/05 2pp
- --8004030237 Forwards GA Program Insp Rept 97900342/79-02 on 791210-14 & notice of deviation POTAPDVB.U Region 4, Dallas, Office of the Director 80/01/07 200
- --8004030242 Notice of deviation from insp on 791210-14 # Region 4, Dallas, Office of the Director 80/01/04 ip
- --8004030244 OA Program Insp Rept 99900342/79-02 on 791210-14
 Noncompliance noted welding performed w/o welders equipped
 to measure interpass temps, certain areas not evaluated
 by qualified welders
 ELLERSHAW, L. E. : HUNNICUTT, D. M. Region 4, Dallas, Office of the
 Director 80/01/04 9pp
- 8004040100 Forwards GA Program Insp Rept 9970004/80-01 on 800122-23 No noncompliance noted. BRCMN:0 D Region 4. Dalias. Fuel Facility & Materials Safety Branch 80/02/24 ip
- --8004040104 GA Program Insp Rept 9970004/80-01 on 800122-23 No noncompilance noted Major areas inspected radiological evaluations conducted in Moab.UT WILBORN.L Region 4. Dallas, Office of the Director BROWN.G D Region 4. Dallas. Fuel Facility & Materials Safety Branch 80/02/20 App
- 8004040111 Forwards GA program Insp Rept 97900048/79-02 on 791210-13 No noncompliance noted POTAPOVS.U Region 4. Dalias, Vendor Inspection Branch 80/02/06
- ---G004040122 GA Program Insp Rept 99900048/79-01 on 791210-13 No noncompliance noted Major areas inspected review of corrective actions for reported deficiencies under 10CFR21 HUNTER,V H. HHITEGELL,D E Region 4, Dallas, Vendor Inspection Branch 60/01/30 9pp
- 8004040476 Ack receipt of 800228 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 97900004/80-01 POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/03/10

- --8004040479 Responds to NRC 800122 ltr re deviation noted in QA Progra Insp Rept 99900004/80-01 Corrective actions coater operating procedure is being revised to reference correct parameter sheet FMD 1197 GALLAMAY, W. C. General Atomic Co. (subs. of Qulf Oil Co.) 80/02/28 4pp
- --8004040348 Forwards QA Program Insp Rept 97900004/80-01 on 800107-11 & notice of deviation POTAPDVB.U Region 4, Dallas, Vandor Inspection Branch 80/01/22 2no
- --8004040352 Notice of deviation from insp on 800107-11
 * Region 4, Dallas, Office of the Director 80/01/18 ip
- --8004040361 GA Program Insp Rept 99900004/80-01 on 800107-i1
 Noncompliance noted review of product documents did not
 assure all requirements were clearly & accurately stated
 Approval not indicated by signature
 WHITESELL.D E , MCNEIL.W M Region 4, Dallas, Vendor Inspection
 Branch 80/01/18 5pp
- 8004070076 Ack receipt of 790912 & 800219 ltrs informing NRC of steps taken to correct violation noted in GA Program Insp Rept 99900372/79-01 PDTAPEVS.U Region 4. Dallas. Vendor Inspection Branch 80/03/04
- --800407007? Forwards response to 800214 telcon w/Foster re deviation noted in GA Insp Rept 99900372/79-01 Corrective action engineering instructions reissued w/proper sign-off blocks ROSEN.A E Anaconda Co , Anaconda Industries Wire & Cable Div 80/02/19 3pp
- --8004070081 Responds to NRC 790822 ltr re deviation noted in GA Progra Insp Rept 99700372/79-01 Corrective action instruction re production tags provided to responsible GA & mfg personnel ROSEN,A.E. Anaconda Co . Anaconda Industries Wire & Cable Div 79/09/12 Spp
- --8004070083 Act receipt of 790912 ltr in response to NRC 790822 ltr Add1 info requested per 790926 telcon w/AE Rosen POTAPOVS.U Region 4. Dellas. Vendor Inspection Branch 79/09/28
- --8004070087 Forwards GA Program Insp Rept 99900372/79-01 on 790807-10 notice of deviation POTAPOVB.U Region 4. Dailas. Vendor Inspection Branch 79/08/22 2pp

- --8004080276 Forwards GA Program Insp Rept 99900379/79-01 on 791015-19 & notice of deviation POTAPDVS.U Region 4, Dallas, Vendor Inspection Branch 79/11/05
- --8004080279 Notice of deviation from insp on 791015-19
 Region 4, Dallas, Office of the Director 79/11/05 2pp
- --8004080287 GA Program Insp Rept 99900379/79-01 on 791015-19
 Noncompliance noted inconsistent GA practice re Criterion 5
 of App B to 10CFR50 No requirement to initiate test
 procedures re tests in machanical pneumatic test lab
 HUNNICUTT, D M , FOBTER, W E Region 4, Dallas, Vendor Inspection
 Branch 79/11/05 7pp
- BOO4080291 Ack receipt of BO0229 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 97900300/BO-01
 POTAPOVS, V Region 4, Dailas, Vendor Inspection Branch GO/03/17
 - -8004080277 Responds to NRC 800207 itr re deviation noted in GA Program Insp Rept 9700300/BB-01 Corrective actions mfg enginesring std revised Mfg supervisor instructed machine operators to fill out operation sheets upon work completion MORGAN.J F Colt industries. Inc., Fairbanks Morse Engine Div 80/02/27 | 11pp
- ~~8004080301 Forwards QA Program Insp Rept 99700300/80-01 on 800121-25 & notice of deviation POTAPOVS, U Region 4, Dallas, Vandor Inspection Branch 80/02/07 250
- --8004080316 GA Program Insp Rept 97900300/80-01 on 800121-25
 Noncompliance noted meg engineering stds, revisions &
 addends not maintained & issued by meg engineering dept to
 all holders
 FOSTER.H E , HUNNICUTT.D M Ragion 4. Dallas, Vandor Inspection
 Branch 80/02/06 12pp
- 8004080338 Ack receipt of 800227 itr informing NRC of steps taken to correct deviation & violation noted in GA Program Insp Rept 99900387/79-01 POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/03/14
- --8004080365 Responds to NRC 800128 ltr re deviation & violation noted in QA Program Insp Rept 99900387/79-01 Corrective actions. inspectors instructed to process cleanup sheet when subassably travelers are encountered COMPAS.M J Qeneral Atomic Co (subs of Oulf Oil Corp) 80/02/27. 3pp.
- --B004080369 Forwards GA Program Insp Rept 99900387/79-01 on 791210-14 & notices of deviation & violation POTAPOVS.V Region 4. Dallas. Vendor Inspection Branch 80/01/24
- ---BOO4080382 Notice of deviation from insp on 791210-14 * Region 4, Dallas, Office of the Director BO/01/24 4pp
- --B0040B03B9 GA Program Insp Rept 999003B7/79-01 on 791210-14
 Noncompliance noted.implementing instructions/procedures
 made no provisions for identifying test procedures on
 subassembly
 FOSTER.W E., HUNNICUTT,D M Region 4, Dailas, Vendor Inspection
 Branch. 80/01/24, 11pp
- BOO4090035 Ack receipt of B00227 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99700403/ BO-01.

 POTAPOVS.U Region 4. Dellas, Vendor Inspection Branch B0/03/10
- --B004070059 Responds to NRC 800131 ltr rs deviation noted in GA Program Insp Rept 99900403/80-01 Corrective actions responses to future NRC inquiries that involve hardware quality will be based on extensive review of applicable data BARNARD, J. General Electric Co. 80/02/27 3pp
- 8004090047 Ack receipt of 800128 Itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900403/79-03 Add info required re prevention of Item B recurrence POTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch 80/02/22

- --8004090072 Responds to NRC 791214 ltr re deviation noted in GA Program Insp Rept 99900403/79-03 Corrective actions records were validated & reviewed by QC records specialists & found acceptable Tags removed from wide range monitors BARNARD, J General Electric Co 80/01/28 10pp
- --B004090078 Forwards GA Program Insp Rept 99900403/79-03 on 791001-05 & 30 & notice of deviation SEYFRIT.K V Region 4, Dallas, Office of the Director 79/12/14
- --80040700B1 Notice of deviation from insp on 791001-05 & 30 * Region 4, Dallas, Office of the Director 79/11/27 4pp
- --8004090086 GA Program Insp Rept 99900403/79-03 on 791001-05 & 30 Roncompliance noted qualifications of functioning GE GA representative not certified & no source insps or surveillance performed during fabrication of fuel grapples COBTELLO, J. R. FOSTER, W. E. HALE, C. J. Region 4, Dallas, Vendor Inspection Branch 79/11/27 44pp
- 8004090282 Ack receipt of 800303 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900268/80-01 Region 4, Dallas, Vendor Inspection Branch 80/03/14 p
- --8004090287 Responds to NRC 800201 ltr re deviations noted in GA Program Insp Rept 99900268/80-01 Corrective actions filed eye records for all AMD pipe examiners Revised heat treatment operating Procedure 134 re recording of charge numbers MODN.R E ARMCO International. Inc 80/03/03 2pp
- --8004090290 Forwards GA Program Insp Rept 99900268/80-01 on 800114-18 & notice of deviation POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/02/01 2pp
- --B004090293 Notice of deviation from insp on 800114-18
 * Region 4: Dallas, Office of the Director 80/01/31 2pp
- --B004090299 GA Program Insp Rept 99900268/80-01 on B00114-18
 Noncompliance noted deficiencies reported in Mar 1979 audit
 repts not resolved as required by GA manual
 HUNNICUTT,D M, CLLER,R E. Region 4. Dallas, Vendor Inspection
 Branch 80/01/31 9pp
- 8004090307 Forwards GA Program Insp Rept 99700265/80-01 on 800128-31 No noncompliance noted POTAPOVE, V Region 4, Dalias, Vendor Inspection Branch 80/02/15 Zpp
- --8004090310 GA Program Insp Rept 97900266/80-01 un 800128-31 No noncompliance noted Major areas inspected implementation of App B to 10CFR50 & applicable codes & stds.including design document control.mfg control & special process control HUNTER.V H . WHITESELL, D E Region 4. Dallas, Vendor Inspection Branch 80/02/14 2pp
- B004070371 Ack receipt of 791023.800116 & 0305 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9900319/79-03 POTAPOVS, U Region 4. Dalias, Vendor Inspection Branch B0/03/20
- --8004090377 Responds to NRC 800215 ltr re deviation noted in GA Program
 Insp Rept 99900519/79-03 Specific SNUPPS findings will be
 answered applicable to all Gaithersburg projects within 90
 days
 MCMES.J M Bechtel Power Corp (subs of Bechtel Corp)
 80/03/05 in
- --8004090382 Ack receipt of 791023 & 800116 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900519/79-03 Requests confirmation that delayed response to Deviation C will apply to all licensee divs POTAPOVS, U Region 4, Dellas, Vendor Inspection Branch 80/02/15
- --B004090386 Responds to NRC 791221 ltr re deviation noted in OA Program
 Insp Rept 99900519/79-03 Corrective actions IE Bulletin
 79-14 re generic implementation program for operating
 plants.Revision 2 was approved & issued for use on 791019
 KOMEB, J M Bechtel Power Corp (subs of Bechtel Corp)
 B0/01/16 3pp
- 8004100001 Forwards GA Program Insp Rept 99900075/B0-01 on 800204-07 Na noncompilance noted PATAPOVB.U Region 4, Dallas, Vendor Inspection Branch 80/02/22 2pp

- --8004100005 GA Program Insp Rept 99900075/80-01 on 800204-07 No noncompliance noted Major areas inspected design verification.computer programs.procurement document control, mfg process control,matl identification & training NHITEGELL, D E . KELLEY, W D Region 4, Dallas, Vendor Inspection Branch 80/02/21 13pp
- B004100031 Forwards QA Program Insp Rept 99900107/80-01 on 800107-11 No noncompliance noted POTAFDVS, U Region 4, Dallas, Vendor Inspection Branch 80/02/22
- --8004100034 GA Program Insp Rept 99900107/80-01 on 800107-11 No noncompliance noted Major areas inspected control of nonconformances & corrective action & field reported const deficiencies in containment vessels WHITESELL.D E. JUNISON, J. M. BROWN, R. L. Region 4, Dallas, Vendor Inspection Branch 80/02/14 19pp
- 8004110031 Ack receipt of 800311 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900302/80-01
 POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/03/25
- --8004i10037 Responds to NRC 800228 ltr re deviations noted in OA Program Insp Rept 99900302/80-01 Corrective actions come-up file sys instituted to reinforce audit requirement & all purchase orders will be forwarded to QA for review FRIEDMAN.K A Western Piping & Engineering Co , Inc 80/03/11 3pp
- --8004110064 Forwards QA Program Insp Rept 99700302/60-01 on 800128-0201 & notice of deviation POTAPOVB.U Region 4. Dalias, Vandor Inspection Branch 80/02/28 200
- --8004110044 Notice of deviation from insp on 800128-0201 * Region 4, Dallas, Office of the Director 80/02/27 2pp
- --8004110057 GA Program Insp Rept 99900302/80-01 on 800128-0201
 Noncompilance noted failure to take action re audits of
 personnel records. GA manager not reviewing all purchase
 orders & purchase orders issued to nonqualified vendors
 WHITESELL, D E , 8UTTON, J W Region 4, Dallas, Vendor Inspection
 Branch 80/02/27 7pp
- 8004140011 Ack receipt of 800303,0201 & 791220 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9900047/79-02 POTAPGVS, U Region 4. Dallas, Vendor Inspection Branch 80/03/24
- --8004140015 Responds to NRC 800219 Itr requesting add1 info re deviation noted in QA Program Insp Rept 99900047/79-02 Corrective actions appropriate instructions have been forwarded to storeroom attendants re welding electrodes & log sheets MILLERIT D Westinghouse Electric Corp TDM-80-025 80/03/03 Ann
- --B004140018 Ack receipt of B00201 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900047/ 79-02 Add1 info required PQTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/02/19
- --8004140020 Responds to NRC 800116 ltr requesting addl info re deviation noted in QA Program Insp Rept 9990047/79-02 Corrective actions storeroom attendants were reinstructed as to procedural requirements & importance of compliance MILLER,T D Wastinghouse Electric Corp TDM-80-013 80/02/01 2pp
- --8004140029 Ack receipt of 791220 ltr informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 49900047/79-02 Addl info required POTAPCVS.U Region 4. Dallas. Vendor Inspection Branch 80/01/16 2pp
- --8004140034 Responds to NRC 791115 itr re deviation noted in GA Program
 Insp Rept 9990047/79-02 Corrective actions importance of
 compliance re storeroom activities was reiterated to all
 personnel & unit manager will review log sheets daily
 MILLER.T D Hestinghouse Electric Corp TDM-79-089 79/12/20
 7an
- --8004140037 Forwards GA Program Insp Rept 99900047/79-02 on 791015-19 & notice of deviation POTAPOUS,U Region 4, Dallas, Vendor Inspection Branch 79/11/15

- --8004140040 Notice of deviation from insp on 791015-19
 * Region 4: Dailas: Office of the Director 79/11/15 3pp
- --8004140043 GA Program Insp Rept 99900047/79-02 on 791015-19

 Noncompliance noted storage practices for electrodes not in accordance w/required procedures, absence of mechanical test data & failure to prepare MRR before weld repairs

 HUNNICUTT, D M, ROBERDS, H W, BARNES, I Region 4, Dallas, Vendor Inspection Branch 79/11/15 10pp
- BO04150145 Forwards GA Program Insp Rept 99900403/80-01 on 800107-11 No noncompliance noted PATAPDVS.U Region 4. Dallas. Vendor Inspection Branch 80/01/31 2pp
- --8004150149 GA Program Insp Rept 99700403/80-01 on 800107-11 No noncompliance noted Major areas inspected special insp to verify responses to deviation in Insp Rept 99700403/79-02 HALE,C J, ELLERGHAWLL E Region 4. Dallas, Vendor Inspection Branch 80/01/31 10pp
- 8004280136 Forwards QA program insp rept 99900400 on 790529 & 1104-08 & notice of violation STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/10 3pp
- --8004280139 Notice of violation from insp on 790529 & 1106-08 * Office of Inspection & Enforcement, Office of the Director 80/04/10 3pp
- --8004280142 Notice of proposed imposition of civil penalties in amount of \$100.000 re NRC 770527 & 1104-08 insp

 * Defice of Inspection & Enforcement, Office of the Director 79-HQ-001 80/04/10 lp
- --8004280146 Rept of 790514-31 investigation re B&W 205 fuel assembly PMR/alleged susceptibility to small break LGCAs THOMPSON D , WARD, H J Executive Officer for Operations Support 79/06/26 300pp
- --8004280149 Rept of 791025-1126 investigation re 8&W NPOD/possible violation of 10CFR21

 UARD, U. J., GOMER. O. Executive Officer for Operations Support WILBUR. H. A. Division of Reactor Operations Inspections 79-H0-003
- --8004280153 Rept of 790719-0817 investigation re B&W/NPOD possible violation of 10CFR21 HARD, M J , GDMER, O C Executive Officer for Operations Support 79-40-002 79/09/18 100pp
- 8004290016 Ack receipt of 800321 itr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900025/79-03 POTAPDVS, U Region 4. Dallas, Vendor Inspection Branch 80/04/03 in
- --8004270023 Responds to NRC 800208 1tr re deviations noted in QA Program Insp Rept 97900025/79-03 Corrective actions deficiencies due to lack of nondestructive exam on eight subassemblies corrected prior to 791231 MDERKE N H Boothwest Fabricating & Welding Co (subs of IV International Corp) 80/03/21 Bpp
- --8004270021 Forwards GA Program Insp Rept 99900025/79-03 on 791205,19 & 20 & notice of deviation POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/02/08 2pp
- --8004270027 Notice of deviation from insp on 791205,19 & 20 * Region 4, Dallas, Office of the Director 80/02/07 2pp
- --8004270031 GA Program Insp Rept 97900025/79-03 on 791205,19 & 20 Noncompliance noted fallure to perform certain math nondestructive exams, inadequate insp of piping assemblies & failure to perform radiographic stam of weld repairs BARNES, I., RUBERDS, H. W., HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch 80/02/07 lipp
- 800427016B Ack receipt of 800111 & 0317 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 79790386/77-01 SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/03
- --B004290176 Responds to NRC 800222 ltr re violation & deviation noted in GA Program Insp Rept 9790033B/77-01 Corrective actions signing off of mfg order being monitored on delly basis Inspectors & GA manager cautioned on use of insp stamps FRIEDMAN, J Marvin Engineering Co , Inc 80/03/17. 10pp.

- ---B004290179 Ack receipt of B00111 ltr informing NRC of steps taken to correct violations & deviations noted in QA Insp Rept 99900338/79-01 Add1 info required re notice of deviation Items 3,6,7,9,16,18,23 & 24
 BEYFRIT,K V Region 4, Dallas, Office of the Director B0/02/22
- --8004290186 Responds to NRC 791025 ltr re deviations & violations noted in QA Program Insp Rept 99900338/79-01 No proprietary info Corrective action GA manual revised to reflect organizational changes FRIEDMAN.O M Marvin Engineering Co , Inc 80/01/11 34pp
- ~-B004290191 Forwards QA Program Insp Rept 97900338/79-01 on 790918-21 & notices of violation & deviation BEYFRIT, K. V Region 4. Dallas, Office of the Director 79/10/25 200
- --8004290201 Notice of violation from insp on 790918-21 * Region 4. Dallas. Office of the Director 79/10/25 ip
- --8004290203 Notice of deviation from insp on 790918-21
 * Region 4, Dallas, Office of the Director 79/10/25 13sp
- ~-B004290212 0A Program Insp Rept 99900339/79-01 on 790918-21
 Nomcompliance noted failure to camply w/10CFR21 re adoption
 of procedures for evaluation of deviations
 BARNESS I. ELLENSHAW.L E . HUNNICUTT.D M Region 4. Dalles. Vendor
 Inspection Branch 79/10/25 26pp
- BO04300084 Act receipt of 800128 & 0317 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 979900403/79-03 PDTAPOVE, U Region 4, Dallas, Vendor Inspection Branch 80/04/03 is
- --8004300092 Responds to NRC 800222 ltr re deviation noted in GA Program Inap Rept 99700403/79-03 Corrective actions will revise Quality Procedure 30 120 to strengthen welding quality requirements & checklist will be developed BARNARD, J General Electric Co 80/03/17 2pp
- --8004300098 Ack receipt of 800128 ltr requesting add1 info re Item B Commits to review of supplier fabrication process sheets to assure proper sequencing PATAPOVS, U. Region 4. Dellas. Vendor Inspection Branch 60/02/22
- ---B004300107 Responds to NRC 791214 ltr re deviations noted in QA Insp Rept 99900403/79-03 No proprietary info Delinates QA mgt level personnel responsibilities & commits to review of work orders
 BARNARD, J General Electric Co B0/01/2B 10pp
- 8004300217 Forwards GA Program Insp Rept 99900705/80-01 on 800213-15 No noncompliance noted POTAPDVS,U. Region 4, Daklas, Vendor Inspection Branch 80/03/05
- --8004300222 GA Program INsp Rept 99900705/80-01 on 800213-15 No noncompliance noted Major areas inspected followup on repts re incorrect math used for fabrication of springs for electro-hydraulic valve actuators ELLERSHAW.L E., HUNNICUTT.D M Region 4. Dallas, Vendor Inspection Branch. 80/02/29, 5pp

REGULATORY QUIDEB

8004020389 Proposes changes to Reg Quide 1.133.Draft 4,re calibr method for loose part monitors which will significantly reduce radiation exposure of operators during V&LPM channel calibr. Draft of revised Paragraph 3.a (3) encl. PEKRUL.P.J Rockwell International Corp 80E80-2661, 80/03/24 30e.

- --8004080628 Comments on proposed Reg Quide 1 97 guide does not have proper approach to accident info Requirements are too pervosive Guide should differentiate between info need in accident situation & normal operation BENDER: M ACRS Advisory Committee on Reactor Bafeguards 79/11/03 3pp
- --8004080631 Questions Reg Quide 1 97.Revision 2 re timely heat balance feedwater sys temps & reactor coolant inventory requirement CATYON: L ACRS - Advisory Committee on Reactor Safeguards 77/11/02 1p
- --8004080639 Comments on proposed Rog Guide 1 97.Revision 2 guide is weak in defining what should be done w/measured info LIPINSKI.W C Argonne National Laboratory 79/10/29 2pp
- --B0040B0646 Comments on proposed Reg Guide 1 97. Revision 2 design should consider effects of nonseismic Category 1 bldg on instrumentation components
 ZUDANS. Z Franklin Institute/Franklin Research Center 79/10/30
- --B0040B0655 Comments on proposed Reg Guide 1 97.Revision 2 requirements are unjustified More graded set of requirements should be specified so quality of instruments is commensurate w/safety importance
 BUCHHOLZ, R H General Electric Co MEN-270-79 79/i1/05 App
- --B0040B0&61 Forwards comments on proposed Reg Guide 1 97.Revision 2 format of Table 2 & 3 should be reversed so that purpose appears first Variable types D & E should be deleted from scope TAYLOR.J H. Babcock & Wilcox Co. 79/11/06 App
- B004090254 Comments on proposed Revision 2 to Reg Quide 1 97 ref to ANS 4 5 is inappropriate until ANS 4 5.Draft 4, has been approved ANS 4 5 committee post-accident qualification period of 100 days should be endorsed BTAMPLEY.N L Mississippi Power & Light Co AECM-80/53 80/03/10 day
- 8004100071 Comments on proposed Reg Guide i 97.Revision 2 permanently installed remote monitors should have upper range of 10 R/hr Points immediately adjacent to release point should be kept at 100 R/hr
 KROON, J C Affiliation Unknown 80/03/07 3pp
- B004100936 Cumments on draft reg guide, "Heasurement of Radiation Levels on Burfaces of Packages of Radioactive Matis " Values in Table 1 should be changed to assure surface radiation level never exceeds 200 mrems-h MUNRQ, J J Tech/Ops (Technical Operations, Inc.) 80/03/10 3pp
- BOO4100341 Comments on proposed Reg Guide 1 97 Revision 2 QA program should be invoked re instrumentation, application & design, but not imposed on manufacturer of instrumentation components for Type 0 or E sys
 BTAMPLEY
- 8004100543 Comments on proposed Reg Guids 1 97.Revision 2 environ radioactivity exposure rate in upper range of 10 rems per h should be adequate.

 KROOM, J C Reuter-Stokes, Inc 80/03/07 lp
- 8004100546 Forwards addl comments on proposed Reg Ouide 1 97, Revision 2 clarification is needed to use of instrumentation for routine environ monitoring purposes & type of monitors required for sample analysis LOOMIS, J S Bargent & Lundy, Inc 80/03/11. 3pp
- BOO4100361 Comments on draft reg guide, "Measurement of Radiation Levels on Burfaces of Packages of Radioactive Matis "Guestions if Paragraph is Section Comeans that special form natural & depleted U can be shipped in exposed state LEVIN.8 Army.Dept of, Matls & Mechanics Research Center BO/03/06
- 8004110127 Comments on proposed draft reg guide, "Measurement of Radiation Levels on Burfaces of Packages of Radioactive Mati "Energy response should be addressed using relative intercomparison w/energy independent instru
- 8004110359 Forwards comments on proposed Reg Guide i 97,Revision 2 variables can be grouped in generic categories & guidance should be provided for proper selection DOPCHIE.H Beigium 80/03/13 App
- B004140179 Comments on proposed Reg Quide 1 97, Revision 2 pressurizer temp & pressurizer spray flow or spray valve position should be added to Table 2, Page 11 COX.E L Black & Veatch, B0/03/07 1p

- 8004180420 Notification of 800408 meeting w/C-E in Bethesda, MD to discuss high range effluent monitors for Lessons Learned requirements & Reg Guide i 97 BARRETT, L Environmental Evaluation Blanch 80/04/02 1p
- 8004180532 Comments on proposed Revision 2 to Reg Guide 1 97 instrument Types D & E could jeopardize operation of seismic qualified instrumentation if on same power source Pressurizer temp & spray flow should be added as maeasured variables CUX.E L Black & Veatch, Bouthern Science Applications, Inc , Div 80/03/07 ip
- 8004210172 Forwards revised PWR near-term OL group generic comments for Reg Guide 1 97, proposed Revision 2 PARKER, W O Duke Power Co 80/04/01 14pp
- 8004220147 Comments on proposed Revision 2 to Reg Quide 1 97 Type A variables omitted due to plant-specific nature should be grouped in generic categories w/quidance for proper selection
 DOPCHIE H Affiliation Unknown 2/500/D B /C D 80/03/13 App
- 8004220210 Comments on proposed Revision 2 to Reg Ouide 1 97 upper limit of environ radioactivity exposure rate measurement range should be reduced to allow for atmospheric dispersion Forwards Presidential public statement on Kemeny rept KROON, J C Reuter-Stokes, Inc 80/03/07 ip
- BO04290240 Comments on proposed Revision 2 to Reg Quide 1 97 does not state where permanently installed monitors for assessment of plant & environ conditions following accident should be placed Telemotry will pose maint problem PILANT, J M Nebraska Public Power District LOAGOOOOSE BO/03/03

REB RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- BOO4150152 "WRRD Monthly Rept for Jan 1980"
 VBARRONDO,L J Energy Engineering Group YBR-34-80 B0/02/29
 200pp.
- 8004010415 Forwards final rept, "Policy Recommendations for Treatments of ATME Events for Standardized Nuclear Power Plants" GULAY,M W Massachusetts Institute of Technology NRC-03-79-144 80/02/21 ip
- --8004010422 8004010415

 "Policy Recommondations for Treatments of ATMS Events for Standardised Nuclear Power Plants," final rept
 GOLAY, M M Massachusetts Institute of Technology NRC-03-79-144
 BO/01/09 37pp
- 8004020142 "Data Summaries of LERs of Diesel Concrators at US Commercial Nuclear Power Plants from Jan 1976-Dec 1978," data summary rept POLOSKI,J P. SULLIVAN,W H EO & G, Inc | FIN A-6276 | EEQ-EA-5072 80/02/29 | 398pp
- 8004020198 RIL-057
 Research Info Ltr 57 submits results of emergency core coolant bypass research performed at Battelle Columbus Labs & Dartmouth College
 LEVINE, B Office of Nuclear Regulatory Research 79/08/10 App
- 8004040027 "Investigation of Post-Critical Heat Flux Heat Transfer for Mater-Cooled Reactor Application & Development of Two-Phase Flow Instrumentation," monthly progress rept for Feb 1980 CHEN.J C., GUNDARM,R K., NIJHAWAN,B Lehigh Univ FIN A-4055 NRC-04-74-180 80/03/17 6pp.
- 8004040028 "Experimental Criticality Data for Code Validation," informal monthly progress rept for Feb 1980 BIERMAN.S R Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2094 80/03/04 3pp
- 8004040204 "Bhipping Cask Babotage Bource Term Investigation." monthly progress rept for Feb 1980 BCHMIDT.E N Battelle Memorial Institute, Columbus Laboratories FIN 8-6012 NRC-04-76-293 80/03/05 4pp
- 8004040210 "Impact of Decontamination on LWR Radwaste Treatment Sys." monthly progress rept for Feb 1980 DIVINE.JR Battelle Hemorial Institute, Pacific Northwest Laboratory FIN 8-2303 80703/12 19pp.
- 8004040270 "Accident Aerosol Characterization," monthly progress rept for Feb 1980 MIGHIMA,J., UMZARSKI.P Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 80/03/07 3pp

- 8004040342 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels," monthly progress rept for Jan 1980 HUTTON,P H , KURTZ,R J Battelle Hemorial Institute, Pacific Northwest Laboratory FIN B-2088 80/02/19 16pp
- BOO4040369 "Gafeguards Amalysis for Byproduct Matis & Emall Quantities of SNM." monthly progress rept for Jan 1980 CHESTER,R O , KONAK,K K , RANDOLPH,M L Oak Ridge National Laboratory FIN D-6108 DRNL/HABRD-68 BO/02/13 Opp
- 8004070145 "forecasting Electricity Demand by State & by Util Svc Area," progress rept for Feb 1980 CHERN,W S Oak Ridge National Laboratory FIN D-0190-8 80/03/07 Spp
- 8004070413 "Core Melt & Separate Effects Program," monthly ltr for Feb 1980 BERMAN,M Sandia Laboratories 80/03/04 4pp
- 8004080075 "Loft Monthly Progress Rept for Jan 1980" KAUFMAN,N C EG & G. Inc fin A-6048 LG-MR-003 80/02/27 94pp
- 8004080082 "Calibr of Loft Modular DTT & Loft Production DTT W/Small Drag Disc." Vol 2 80LBRIO,C W, SHULL,O B, ODDD,R R EQ & G, Inc FIN A-6048 LO-00-80-113 80/02/29 233pp
- 8004080094 "Stress Corrosion Cracking of PWR Steam Generator Tubing," monthly highlight lit fro Jan 1980 BULISCHECK.T. VAN RODYEN,D Brookhaven National Laboratory FIN A-3208 80/02/15 5pp
- 8004080215 RIL-084
 Research Info Ltr 84 submits results of study of
 liquefaction resulting from 760204 earthquake near Lake
 Amatitlan Guatemala
 BUDNITZ.R J Office of Nuclear Regulatory Research 80/03/24
- B0040B0242 "LUR In-Plant Measurement Program," monthly progress rept for Feb 1980 MANDLER,J.W E0 & G, Inc FIN A-6075 B0/03/18 4pp
- 8004080283 "Biocide Byproducts in Aquatic Environs," quarterly programs rept for Det-Dec 1979 BEAN,R M Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2098 797/2/31 39pp
- 8004080270 "88C Code Development & Validation." monthly highlight ltr for Dec 1977 AGRAMAL,A,K, OUPPY,J Ø Drockhaven National Laboratory FIN A-3015-0 79/12/31 &pp
- 8004080294 "TRAC Assessment & Model Development," monthly highlight ltr for Jan 1980 JONES.O C Brookhaven National Laboratory FIN A-3215 80/01/31 5ao
- BO04080302 "LWR Thermal Hydraulic Development Program," monthly highlight ltr for Dec 1979

 JONES, O. C. Brookhaven National Laboratory FIN A-3045 79/12/31 4pp
- 8004080585 "Ramona Code Mod & Evaluation," monthly highlight 1tm for Dec 1979 LEVING.M M Brookhaven National Laboratory, FIN A-3014 79/12/31 5pp
- 8004080675 "Evaluation of LWR Residual Heat Removal Under Accident Conditions," monthly highlight ltr for Jan 1980 BURIJR A Brookhaven National Laboratory FIR A-3315, BO/01/31, Son
- 8004080684 "Best Estimate Prediction for LOFT Nuclear Experiment L-3-2," pretest prediction rept KEE.E J, SHINKO,M S, ORUSH,W H EO & O. Inc FIN A-6048. E00-LOFT-8087 80/02/27 80pp
- B004090068 "Electrical, Instrumentation & Control Aspects of Proposed Tech Specs Change Re Blocking of Bafaty Injection Bignals When Pressure Is Dalow 2000 psig," technical evaluation rept MAYB, S E EO & O. Inc FIN A-6256 EQQ-CA-8106 B0/02/29 Bpp
- 8004090138 "HTGR Bafety Program," monthly highlights ltr for Jan 1980 8ABTRE, C Brookhaven National Laboratory FIN A-3014 80/02/04

- BOD4090312 "Thermal Hydraulic LMFBR Safety Experiments," monthly highlight ltr for Dec 1979
 JONES, O C Brookhaven National Laboratory FIN A-3024 79/12/31
- 8004090324 "Thermal Hydraulic LMFBR Bafety Experiments," monthly highlight ltr for Jan 1980 JONES O C Brookhaven National Laboratory FIN A-3024 80/01/31
- 8004100258 "Advanced Reactor Safety Analysis," monthly highlight ltr for Dec 1979 BARI,R A Brookhaven National Laboratory FIN A-3000 80/01/07
- BOO4100328 "Estimators for Binomial Failure Rate Common Cause Model "ATHOOD.C L E0 & G. Inc FIN A-6272 E00-EA-5112 80/03/31
- B004100378 "LOFT Test Support Branch Data Abstract Rept LOFT fuel Rod Thermocouple Calibr Test-Rod RRF A-88102 " SOLBRIO,C W , TOLMAN,E L , SELCHO,H S EG & O, Inc FIN A-6048 LTR 141-100 79/04/30 53pp
- 8004100398 "Definition of Parameters for Major Accidents at Waste Solidification & Spent Fuel Storage Facilities," informal monthly progress rept for Feb 1980 FEDERICK, E. J. Oat Ridge National Laboratory FIN 8-0425 80/03/26
- BOO4100411 "Div of Reactor Bafety Research-DRNL Programs," Feb 1980 monthly highlights
 MUYATT Dak Ridge National Laboratory FIN B-0413 NRC-60-19-11-01 BO/03/10 30pp
- 8004100587 "Advanced Reactor Safety Analysis Technical Assistance, Reactor Projects," monthly highlights for Jan 1980 BARIJR A Brookhaven National Laboratory FIN A-3000 80/02/01 40s.
- BOO4100590 "SSC Code Development & Validation," monthly highlight ltr for Jan 1980 AGRANELA K., GUPPY, J. Ø Brookhaven National Laboratory FIN A-3015-8 80/01/31 App
- BOO4100594 "Bubtask A'RAMONA Code Hod & Evaluation" & "Subtask B IRT & RETRAN Code Hod & Evalution," monthly highlight ltr for Jan 1980
 LEVINE, M H Brockhaven National Laboratory FIN A-3014 BO/01/31
- BOO4100599 "LWR Thermal Hydraulic Development Program," monthly highlight ltr for Jan 1980 JCNEB,O L Brookhaven National Laboratory FIN A-3045 80/01/31 4pp
- BOO4:1052: Evaluation of LWR Residual Heat Removal Under Accident Conditions," monthly highlight ltr for Dec 1979 BARI,R A Brookhaven National Laboratory FIN A-33:5 BO/01/07 5pp

lactrical Instrumentation & Control Aspects of Override of Purge Valve Isolation & Other Safety Feature informal rept
0 & 0, Inc EG0-EA-5098 80/02/29 13pp

- lecht-Beaset Program." monthly progress rept for Jan 1980 Westinghouse Electric Corp NRC-04-77-127 80/02/22
 - tle Facility Nonsecurity Personnel Response to khaven National Laboratory FIN A-3000 78/12/15 33co
 - Facility Employees Response to Intrusion Alarm."
 otheren National Laboratory FIN A-3000.
 78/11/15 38pp.
 - Facility Threat Analysis & Tactical Response mal rept khaven National Laboratory FIN A-3000 79/10/19 103pp
 - Assessments of Fuel Cycle Facilities, monthly Feb 1980 idge National Laboratory, FIN B-0279, 80/02/29 App

- 8004150036 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for Feb 1980 LANTI, PM , DICKSON, H W Dak Ridge National Laboratory FIN A-9085-7 DRNL/HABRD-70 80/02/29 20pp
- B004150056 "Reactivity Initiated Accident Test Beries Test RIA 1-4 Experiment Predictions" FUKUDA.9 K, MARTIKSON.Z R EQ & G, Inc FIN A-6041 EGQ-TFBP-5023 80/02/29 74pp
- 8004150063 "BWR Blowdown/Emergency Control Ctr Program." monthly progress rept for Feb 1980 BURNETTE.O W Oeneral Electric Co FIN B-3014 NRC~94-76-215 80/02/27 5pp
- 8004150066 "Physical Protection of Nuclear Matl In Transit" quarterly progress report Jan-Mar 1980 CHAPMAN.L D Sandia Laboratories FIN A-1173 80/03/20 6pp
- 8004150475 "Once-Through Steam Generator Modeling for Analysis of TMI Incldent," conference paper HSU.C J. BHIER.W O. LEVINE.M M Brookhaven National Laboratory BNL-NURED-27185 80/04/10 6pp
- BOO4160088 "Assessment of Radiation Doses Resulting From Releases of Rn-222 & Ra-226 From V Mining & Milling Activities," monthly progress rept for Feb 1980
 TRAVIS.C C. MCDOWELL-BOYER, WATGON, A P Gak Ridge National Laboratory FIN 8-0281 GRNL/HASRD-72 BO/03/14 3pp
- 8004160095 "Safeguards Analysis for Dyproducts Matls & Small Guantities of BNM," monthly progress rept for Feb 1980 CHESTER C J. KANAKI, K K., RANDOLPH, M L. Oak Ridge National Laboratory FlN B-6108 DRNL/HASRD-71 80/03/15 6pp
- 8004170120 "Guick Look Rept on LGFT Nuclear Experiment L3-2,"
 experiment data presentation rept
 LINEBARGER, J H EG & G, Inc FIN A-6048 EGG-LOFT-5104 80/02/29
 30aa
- 8004170274 "Technical Evaluation Rept of Degraded Grid Protection for Class IE Power Sys at Brunswick Steam Electric Plant," technical evaluation rept CLEVELAND, J C EO & G, Inc FIN A-6256 EGG-EA-5109 B0/02/29 BDD
- 8004170276 "Inservice Testing Evaluation of Check Valves at St Lucie Unit 1 Nuclear Station," technical evaluation rept FEHRINDER.J M EQ & 0, Inc FIN A-6258 EQG-EA-5097 80/02/29 130e
- B004170287 "BWR Refill-Reflood Program." monthly ltr for Feb 1980 BURNETTE, 0 W General Electric Co NRC-04-79-184 80/03/13 5pp
- B004170289 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Signals.EI Hatch Nuclear Plant," informal rept UDY.A.C. EO & O. Inc FIN A-6255 EGO-EA-5110 B0/02/29 9pp
- 8004170334 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Bignals Millstone Nuclear Power Station." informal rept UDY, A C EO & O. Inc FIN-A-6236 EGO-EA-5111 BO/02/27 9pp
- 8004230300 RIL-62
 Forwards NUREG/CR-0379,Vol 5, "Repts Distributed Under NRC
 Reactor Safety Research Foreign Technical Exchange Program,"
 & NUREG/CR-0450, "New Madrid Seismotectonic Btudy —
 Activities During FY76"
 LEVINE
- 8004240152 Forwards informal progress rept for Dec 1979 for FLECHT-8EASET MASSIE,H W Westinghouse Electric Corp NRC-04-77-127 80/02/11
- B004240460 "Fuel Cycle Facility Threat Assessment & Response Procedures," informal rept O'RRIAN, J N. CADMELL, J J Brookhaven National Laboratory FIN A-3000 BNL-NUREG-2487; 78/12/15, 74pp
- B004240465 "Mati Control & Accounting Effectiveness Evaluation Development," informal monthly progress rept for Jan 1980 P00010.A Lawrence Livermore Laboratory FIN A-0115 B0/04/04 7pp
- 800424046B "Semiscale Mod~3 Small Break Test S-88-2A" FAUBLE.T J EG & 9, Inc FIN A-6038 EGG-8EMI-5113 80/03/04 61pp

- 8004240475 "Experimental Evaluation of Ventilation Sys Components During Large Pressure Pulses," informal monthly progress rept for Feb 1980 OREGORY,WS Los Alamos Scientific Laboratory FIN A-7028 80/03/20 3pp
- 8004240487 "Unified Transport for Power Plant Assessment," monthly progress rept for Jan 1980

 * Oak Ridge National Laboratory FIN B-0168-9 ORNL/ED/EIS-119 80/01/31 App
- BOO4280032 "Analysis of Oas Circulation in Containment of High Temp Oas Cooled Reactor," informal rept OHATA,I, TAKAHAGHI.H Brookhaven National Laboratory FIN A-3016 BNL-NUREG-27369 BO/03/31 170pp
- B00428003B "Critical Flashing Flows in Nozzles W/Gubcooled Inlet Conditions " ABUAF,N , JONES,D C , WU.B J C Brookhaven National Laboratory FIN A-3045 BNLONUREG-27512 80/03/31 3App
- BOO4280041 "High Temp Mass Transport Experimental Program," informal rept GROMCOCK, F. B., HEISER, J. H. Brookhaven National Laboratory FIN A-3016 BNL-NUREO-27502 BO/03/31 34pp
- 8004280057 "NRC Bafeguards Mati Control Project," monthly progress rept for Feb 1980 PDG01D,A Laurence Livermore Laboratory FIN A-0115 MC 80-04-02-LR 80/03/07 7pp
- 8004280063 "Task 5-Natl Haste Pockage Program " 8CHMEITZER,D Q Brookhaven National Laboratory FIN A-3158 BNL-NUREG-27545 80/03/31 10pp
- 8004280071 "Praliminary Pretest Analysis of FFTF Loss of Power Acceptance Tests: "informal rept EPELL Q , QUPPY, J Q , KENNETT, R J Brookhaven National Laboratory FIN A-3041 BNL-NUREO-27116 G0704/30 63pp
- B004300032 "General Legal Problems Affecting Nuclear Guard Tactical Responses," informal rept CADHELL, J. Brookhaven National Laboratory FIN A-3067 BNL-NURCG-24672 76/11/15 20pp
- 8004300574 "Physical Protection of Nuclear Facilities, "progress rept for Feb 1980 CHAPMAN, L. D. Bandia Laboratories FIN A-1060 80/03/20 7pp

REVIEW GRP NRC RESEARCH REVIEW GROUPS

- 8004100485 Forwards summary of Advanced Code Review Ordup 800124-25 meeting in Silver Spring.MD ZUBER.N RROW 1-14, Advanced System Code 80/03/28 ip
- --8004100470 Bummary of Advanced Code Review Group 800124-25 meeting in Bilver Spring.MD re review of COBRA-TF & COBRA/TRAC code development program at PNL * RROW 1-14. Advanced System Code 80/03/28 32pp
- --8004100497 "COBRA-TF Model Description"

 * Battelle Memorial Institute 79/12/31 100pp
- 8004220874 Forwards initial outline of acceptance & verification criteria for early warning fire detection sys BOCCIO, J Brookhaven National Laboratory BO/04/15 6pp
- 8004240141 Forwards summary of 800214 meeting w/Qualification Testing Evaluation review group re Commission-directed electrical connector tests McQuire penetration assemblies can be used for next series of tests MCRLEY.T E Division of Reactor Safety Research EIBENHUT.D Q Office of Nuclear Reactor Regulation, MATTSON.R.J Division of Systems Safety 80/04/02 4pp
- 8004280187 Forwards Sandia Labs & UL viewgraphs entitled "Fire Protection Research Program," presented to NRC on 800328 UL is planning to complete program on evaluation of IEEE-383 flame test FEIT.R Research Support Branch 80/04/04 2pp
- 8004280200 Forwards Sandia Labs 800321 ltr documenting tests to determine degree of fire retardency of Raychem splices Splices could be included in planned fire tests on electrical equipment cables in fire protection ress

- --8004280206 Forwards results of evaluation of fire resistance of Raychem heat shrinkable splice matl for comparison w/resistance of cable FR-1 test showed that splices looked as good as average cable matl
 KLAMERUS: L J Sandia Laboratories 80/03/21 Bpp
- 8004280285 Forwards NRC div directors' 800402 ltr re agreement to proceed w/next series of tosts using connectors from McOuire penetration connectors MCOuire MCREEY,T E Division of Reactor Safety Research 80/04/10 lp

SECY POSITION PAPERS BEFORE THE COMMISSION

- 7812120219 Responds to 780316 FOIA request for SECY77-268, SECY77-2680, SECY77-2680 COPE memo Portions of documents withheld (ref 10CFR9 15 & 2 790) FELTON, J M Division of Rules and Records 78/12/05 3pp
- 8004010016 Transcript of 800319 meeting in Washington.DC re NRC enforcement program Pp 1~59
 * Commission 80/03/19 59pp
- --8004010017 SECY-80-139

 Describes various types of enforcement actions re request for Commission approval of general statement of enforcement policy

 STELLO.V Office of Inspection & Enforcement, Office of the Director 80/03/13 30pp
- --8004010021 Endorses objective re development of strong explicit enforcement program Requests mod of coordination statement to include benefits, costs & Commission guidance requirements HALLER.N M Office of Management and Program Analysis 80/03/10
- 8004010051 SECY-80-045
 Forwards Executive Branch position on 800121 applications for licenses to export highly enriched U to Belgium. Hest Germany. France & the Netherlands Requests comments SHEA, J R Office of International Programs 80/01/24 ip
- --8004010478 Executive Branch position re five Transnuclear, Inc applications for licenses to export highly enriched U to Belgium West Germany France & the Netherlands Recommends issuance of licenses Ltrs of assurance encl NOSENZO, L V State, Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/01/21 15pp
- --8004010075 Forwards two applications for licenses to export 22 050 kg U enriched to max 93 3% U-235 & 777 kg U enriched to max 4 05% U-235 W/o latter application
 MATBON: V Transnuclear, Inc 78/06/22 2pp
- --8004010097 Application by Transnuclear, Inc for license to export 20 090 kg U, in form of U hezafluoride enriched to max 93 3% U-235, to the Netherlands End use statement encl MATBON, V Transnuclear, Inc 78/06/22 2pp

--a

--8004020028 SECY-80-107 (FRN) Establishes technical bases re interim hydrogen control requirements for small containments Technical discussions DENTON, HR Office of Nuclear Reactor Regulation 80/02/22

8004030166 SECY-77-064

NAGOSOLOG SECY-77-064
Recommends approval of encl licensee contractor & vendor insp program (as continuing part of NRC insp program) & approval of conducting 2-yr trial program to test use of third party insp sys to supplement program VQLOENAU, E Office of Inspection & Enforcement, Office of the Director 77/02/02 Hopp 86рр

--8004030148 Comments on vendor 3 third party insp program Use of third party ABME inspectors should be included in Commission paper re licensee contractor & vendor insp program HUBERMAN.B Commission 76/12/23 2pp

8004040200 SECY-80-131

UNIONABLE SECT-BU-131
Recommends discontinuance of accident classification
groupings & interim policy re use of probablistic risk
assessment methods in NEPA reviews Proposed FR notice &
related methods in NepA reviews Proposed FR notice &
DENTON, H R Office of Nuclear Reactor Regulation 80/03/11 3ipp

8004070148 BECY-80-142

004070148 BECY-BO-142
Recommends issuance of license to export reactor & associated components to Philippines Proposed export would not be inimical to US common defense & security No further action required on SECY-79-100
SHEA,J R Office of International Programs 80/03/14 6pp

--8004070180 Discusses deaths of two energy activists & physical security of Proposes of reactors of two energy activists & physica of Proposes of reactor Continued repression creates highly unstable environ "Mother Jones" Dec 1979 article re state of civil war in Philippines encl PERLAGN. M Philippine Movement for Environmental Protection 80/01/27 13pp

8004090162 BECY-B0-001

004090162 BEUT-BO-001 Recommends approval of JP Gleason as part-time member of ASLB Commission comment or consent should be provided to Ofc of Becretary by BO0116 Resume encl W/o encl LAZA:R M Atomic Safety and Licensing Noard Panel 80/01/02 2pp

8004090297 SECY-80-054

004090297 SECY-80-034
Recommends Commission approve publication for comment of proposed amend codifying licensee compliance w/EPA "Environ Radiation Protection Stds for Nuclear Power Operations "Proposed FR notice & proposed amend encl
MINOQUE,R B Office of Standards Development 80/01/28 22pp

--B004090301 Draft value/impact assessment re proposed amend to 10CFR20 405 to codify licenser compliance w/EPA regulation 40CFR190 Requirement is necessary part of NRC enforcement responsibilities
HICKEY, J. W. Office of Standards Development 79/11/30 5pp

--8004090306 BECY-79-646

004090306 BECY-79-646
Informs Commission of plans & practices for implementation of EPA environ radiation protection stds for nuclear power operations. Primary thrust has been to make in-place NRC license mechanisms work for EPA stds implementation DENTON, H R. Office of Nuclear Reactor Regulation 79/12/07 3pp

8004090321 BECY-80-002

004090321 BECY-BO-UU2
Recommends approval of LJ Carter as part-time member of
ABLB Commission comment or consent should be provided to Ofc
of Becretary by 800116 Resume encl H/o encl
LAZA,R M Atomic Befety and Licensing Board Panel 80/01/02 2pp

8004100033 Transcript of 800313 Affirmation Session 80-10 in Washington, DC Pp 1~5 # Commission 80/03/13 5pp.

--8004100039 SECY-80-095

Mecoaments ARC approval of FR publication of encl notice of denial of petition for rulemaking 2-5
BHAPAR, H K Office of the Executive Legal Director 80/02/14

B004100429 Transcript of B00331 meeting in Bethesda. MD re-physical protection of irradiated reactor fuel in transit Pp i-33 * Commission. B0/03/31 33pp

--8004100431 SECY-80-166 Recommends NRC approval of amends to 10CFR73 for immediately effective requirements re physical protection of irradiated fuel in transit for publication in final form Draft FR notice encl DIRCKS,W J OF 80/03/28 52pp Office of Nuclear Material Bafety & Safeguards

8004230123 Forwards corrected Page 10 to 800404 advance notice of rulemaking on technical criteria for regulating geologic disposal of high level radwastes

* Office of Standards Development 80/04/08 ip

--8004230126 Corrected Page 10 to 800404 advance notice of rulemaking on technical criteria for regulating geologic disposal of high level radwastes

Defice of Standards Development 80/04/04 1p

--8004230130 SECY-80-177
Seeks NRC approval to publish in FR encl advance notice of rulemaking on technical criteria for regulating goologic disposal of high level radwastes
MINDQUE.R 8 Office of Standards Development 80/04/04 3pp

~-8004230136 Advance notice of rulemaking re technical criteria for regulating geologic disposal of high level radwaste # Office of Standards Development 80/04/04 80pp

--8004230141 Value/impact assessment supporting solicitation of public cumment on issues & questions important to development of technical criteria for regulation of disposal of high level

* Office of Standards Development BO/04/04 6pp

B004240130 Notifies of Commission approval of Nissho-Iwai American Corp application for license to export 42 kg U.enriched to 93 3%, to Japan Requests detailed description of transportation method & physical security for transit CHILK.S J. Office of the Secretary of the Commission B0/04/02 in

8004240471 Transcript of 800414 meeting in Washington,DC to discuss SECY-80-139 & SECY-80-130A Pp 1-59 * Commission 80/04/14 40pp

8004270072 BECY-80-026A

Updates SECY-BO-26 re amend to code requirements for reporting therapy misadministrations Licensee is not required to notify patient before consultation w/physician MINDOUE,R B Office of Standards Development 80/02/26 App

8004300002 SECY-80-136

Recommends approval of delegation of authority to director, Ofc of Administration, germitting director to approve termination of contracts & agreements Draft delegation of authority encl DONOQHUE, D J Office of Administration 80/03/11

--B004300007 Delegates authority to administer contracting activities of Commission, including contracts & interagency agreements for conduct of nuclear regulatory research Draft delegation of BONDOHVE, D J Office of Administration 75/01/20 2pp

STATE PROO STATE PROGRAMS

80040200B0 Responds to 800118 ltr re Subcummittee on Nuclear Energy recommendations four, five & six concerning state emergency response plan & radwaste mgt FEMA responsible for assisting state w/emergency response plans DDE should be contacted YDUNG, FW Assistant Director for Program Development 80/03/20

80040200B9 Provides Special Joint Committee on Nuclear Energy w/info on document distribution.per 800204 request Forwards list of firms authorized to receive packaged radwaste in states over which NRC has regulatory authority MCCARTHY.E Office of State Programs 80/03/17 5pp

--B004020237 Requests placement on distribution lists to receive documents re MI nuclear facilities Also requests info re NRC licensees BCANLON.W J. CLODFELTER.M., ROSS.D. Michigan, State of B0/02/04 3pp

- --8004020102 Discusses W Scanton info request Adding W Scanton to distribution list for all documents relicensing not feasible due to vol of licensing actions & related correspondence Dept of Public Health should be contacted NUSBSAUMER.D A Assistant Director for Material Safety & Licensing 80/02/03 lp
- ---BOO4020106 Forwards documents requested by W Scanlon W/o encl PAULUB,R C Office of inspection & Enforcement, Office of the Director BO/03/06 ip
- 8004020170 Responds to 800226 ltr to 8 Schwartz Requested info re waste disposal issues encl NRC hopes to avoid schedule conflict during regional meetings w/states; on low level waste site licensing in spring W/o encls
 YUUNG.F W Office of State Programs 80/03/19 2pp
- ---8004020176 Requests info concerning state strategy underway to resolve problem of nuclear waste disposal Welcomes suggestions re course of action State of MD might pursue EASTER.U H Maryland, State of 80/02/26 lp
- 8004020209 Forwards documents requested re J Hendrie 791107 testimony on low level radwaste disposal W/o encl WEISSBERO.S (Office of State Programs 80/03/20 ip
- BOO4040193 Expresses pleasure that Hazle has been appointed liaison officer to NRC Forwards list of key NRC personnel responsible for nuclear power plant project within US W/o encl RYAN,R O Office of State Programs BO/01/16 ip
- 8004040470 Confirms discussion re evaluation of SC radiation control program Program deemed adequate to protect public health & safety KERR. O W Office of State Programs 80/03/17 2pp
- BOO4070069 Provides info on state transportation data base currently being developed at ORNI Contains pending legislation, state & federa! laws & local ordinances re radioactive matl transport MCCARTHY, E A Office of State Programs GO/03/14 lp
- 8004070368 Confirms acceptance of control of agreement matl program & recommends independent measurements of teletherapy units radiation output be taken KERR, C W Office of State Programs 80/03/17 ip
- 8004070417 Discusses possibility of detailing NRC radiation specialist to state for two-wrs under Intergovernmental Personnel Acts of 1970 in response to 800200 requests State would have to assume 50% of employee salary DIRCKB.W J Office of the Executive Director for Operations 80/03/11 ip
- --80040/0426 Requests NRC radiation specialist be detailed to state for two-yrs under Intergovernmental Personnel Acts of 1970 Appointment would provide opportunity for closer working relationship between state & federal govts ORASSO, E Connecticut. State of 80/02/06 ip
- 8004080164 Confirms 800220-21 meeting room reservations MCCARTHY, E Office of State Programs 80/02/01 1p
- 8004090206 Advises that Commission has approved BECY-BO-017 recommendation to issue revised criteria for evaluating agreement state radiation control programs as Commission policy statement Statement should be modified as noted CHILK.8 J Office of the Secretary of the Commission BO/03/21 App
- 8004110544 Responds to NRC comments re recent review of state regulatory program State will enforce requirements of 10CFR19 when regulations have been approved by ID Board of Health & Welfare FUNDERBURG.R D Idaho. State of 80/03/03 2pp
- 8004110553 Extends invitation to NRC 800115 emergency preparedness workshop in New York NY to discuss feasibility impact & procedures for complying w/encl proposed rule 10CFR50 Lists areas that rule would affect Agenda encl SCHWARTZ.8 A Assistant Director for Program Development 80/01/04
- 8004140047 Forwards comments on proposed rule 10CFR90 made at NRC 800117 emergency preparedness workshop in San Francisco, CA GLCGTT, K Affiliation Unknown 80/01/17 ip

- --8004140052 Comments on 10CFR50 presented at NRC 800117 emergency preparedness workshop in San Francisco,CA Adequate emergency planning should be requirement for nuclear facility CP & GL GLCOTT,K Affiliation Unknown 80/01/17 2pp
- 8004140181 Extends appreciation for participation in regional state liaison officers meeting in San Francisco.CA Exchange of ideas useful to all responsible for safe use & operation of nuclear matls & Pacilities
 KERR.O W Office of State Programs 80/03/13 ip
- 8004140189 Confirms discussion following evaluation of NV radiation control program Program for regulation of agreement matl is adequate & compatible w/NRC program Recommends improvement re Beatty burial site
 KERR.G W Office of State Programs 80/03/27 2pp
- BOO4170341 NUREO/CR-1193
 "Transportation of Radioactive Mati in IL." Jun 1978-Jun 1979
 # Illinois, State of, Dept of Public Health NRC-06-78-358
 BO/03/31 53pp Available at NTIS
- 8004180023 Discusses NRC actions taken in response to recommendations in GAO rept. "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established to verify that serious violations are corrected AHEARNE. J F Commission 80/03/31 4pp
- --8004180078 Forwards position paper supporting Agreement State program
 Paper includes comments on advantages of Agreement State vs
 NRC administering radiation health & safety program
 TEDFORD, C F Arizona, State of 80/01/23 App
- --8004180082 Discusses NRC actions taken in response to recommendations in OAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established to verify that serious violations are corrected AHEARNE, J.F. Commission 80/03/31 4pp
- --8004180086 Provides Subcommittee on Nuclear Regulation w/NRC response to recommendations in QAO rept, "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established AHEARNE.JF Commission 80/03/31 App
- --8004180099 Provides Subcommittee on Energy & Environ w/NRC response to recommendations in GAO rept. "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established AHEARNE, J F Commission 80/03/31 4pp
- --8004180097 Provides Subcommittee on Energy & Pawer w/NRC response to recommendations in OAD rept. "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established AHEARNE, J F Commission 80/03/31 4pp
- ---B004180100 Provides Subcommittee on Environ Energy & Natural Resources w/NRC response to recommendations in OAO rept, "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established AHEARNE, J.F. Commission 80/03/31 4pp
- --B004180101 Discusses NRC actions taken in response to recommendations in GAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established to verify that serious violations are corrected AHEARNE, J. F. Commission B0/03/31 4pp
- --8004180103 Discusses NRC actions taken in response to recommendations in OAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established to verify that serious violations are corrected AHEARNE, J F Commission 80/03/31 4pp
- 8004180279 Forwards response to 791206 inquiry re NRC Agreement States program & Church Rock dam failure RI submittal satisfied Atomic Energy Act. Section 274 requirements for admission as Agreement State
 AHEARNE, J F Commission 80/03/17 10pp
- --8004180298 Advises that Environ Improvement Board will promulgate implementation of proposed revisions to regulations rehealth & environ aspects of radiation BACA, T E New Mexico, State of 79/10/18 lp

- B004230095 Responds to B0011B ltr re concern & dissatisfaction w/Region i workshop on proposed changes in NRC rules on emergency preparedness Hemo providing summary of results of four warkshops encl. Apologics for inconvenience AHEARNE. J F Commission 80/03/21 2pp
- --B004230110 Discusses four wortshops to proposed emergency planning rule changes held on B00115.17.22 & 24 Rept will be prepared summarting lessons learned from series of workshops to conduct of public meetings Agenda encl OULLER.K R Division of Siting, Health & Safeguards Standards B0/01/28 7pp
- --B004230118 Informs NRC of deep concern & dissatisfaction w/Region 1 workshop on emergency planning held 600115 Meeting accomplished next to nothing Suggests NRC undertake extensive measures to recover valuable comments & input VANDENBURGH, D. E. Yankee Atomic Electric Co. 80/01/18 2pp
- 8004240077 Discusses 800220-21 meeting to identify problems experienced by nuclear waste generators, transporters, collectors & disposal site operators Summary of meeting will be forwarded KERR, 0 W Office of State Programs DISIBIO,R Nevada, State of 80/03/27 2pp
- ---B004240081 Discusses 800220-21 meeting to identify problems experienced by nuclear waste generators transporters collectors & disposal site operators Summary of meeting will be forwarded KERR.O U Office of State Programs DISIBIO.R Nevada, State of B0703/27 Spp
- 8004240139 Submits comments in response to 791227 ltr, identifying specific new or updated procedures in radiation control program Insp guides are currently being copied & will be supplied to each inspector STRONG, T R Hashington, State of 80/03/07 2pp
- 8004240451 Responds to telcon re role of Governor-appointed state limison officers Program initiated in 1977 to improve NRC-state cooperation Regional meetings held to acquaint officers w/operations & to discuss mutual interests WEIBSBERO.8 Office of State Programs 80/03/28 2pp
- 8004230060 Forwards SC first quarterly progress rept re transportation surveillance program under contract w/NRC & DOT for period 770727-1231 W/o encl UANINEK.M. Office of State Programs 80/03/27 ip
- --8004250072 Forwards first quarter progress rept under Contract NRC-06-78-357 for 790927-1231.w/tabulation of results obtained W/o progress rept WILLIAMS,E F. Bouth Carolina, State of NRC-06-78-357 80/03/10
- 8004280323 Forwards std order for DDE work "Offsite Emergency Instrumentation for Accidents Involving Light Nater Nuclear Plants," issued to INEL KERR.0 W Office of State Programs FIN 8-1404-0 80-80-008 80/04/17 ip

200

--8004280327 8td order for DDE work "Offsite Emergency Instrumentation for Accidents Involving Light Water Nuclear Plants," issued to INEL KERR: 0 W Office of State Programs FIN 8-1604-0 80-80-008

*O123 ltr re agreement state program will be helpful in promoting n NRC t states 10/02/08 1p

reaffirm agreement state program Details am improvements are required to 80/01/23 App

sting of NRC resource personnel assigned
Programs 80/04/04 3pp

) RELATED CORRESPONDENCE

ineral organization changes to B&R-002A c do not affect program Changes , major revision to topical rept 'p (subs of Halliburton Corp.)

- BO0401049B Forwards Figures 17-1.1/-2,17-2A.17-3 & 17-5, reflecting organizational changes, to be incorporated into CENPD-210-A. Revision 3. "GA Program Manual" SCHERER.A E C-E Power Systems LD-80-015 80/03/27 lp
- --8004010501 CENPD-210-A R3
 Figures 17-1:17-2:17-2A:17-3 & 17-5:reflecting organizational changes:to be incorporated into "GA Program Hanual"
 C-E Power Systems 80/03/31 5pp
- B004020254 Forwards NEDE-24794-P, "Dynamic Lateral Loads on Mark II Main Vent Downcomer - Correlation of Independent Ref Data " Affidavit for withholding encl Rept withheld (ref 10CFR2 790) BUCHHOLZ:R H General Electric Co MFN 070-80 80/03/31 5pp
- 8004020267 Forwards proprietary & nonproprietary versions of EDR-1-A. Revision 2. "Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes." incorporating changes identified in 791023 itr Proprietary version to Central Files only CLARK, C W Ederer. Inc (subs of Formac International, Inc.) 80/03/28 19
- --8004020271 EDR-1 (NP) R2
 "Nuclear Bafety-Related Extra-Safety & Monitoring (X-SAM)
 Cranes," nonproprietary version
 * Ederer, Inc (subs of Formac International, Inc.) *
 Affiliation Unknown 80/02/15 150pp
- 8004020396 Forwards updated Pages 2-2 & 2-3 of WCAP-7800, "Nuclear Fuel Div QA Program Plan " Revision 5A Pages reflect organizational changes at Columbia plant Changes will be incorporated in next rept revision ANDERBON, T M Westinghouse Electric Corp NS-TMA-2222 80/03/26 ip
- --8004020402 WCAP-7800 R5A
 Updated Pages 2-2 & 2-3 of "Nuclear Fuel Div QA Program Plan." Revision 5A, reflecting organizational changes at Columbia plant
 # Mestinghouse Electric Corp 80/03/26 2pp
- B004020404 Forwards responses to NRC 790712 ltr re XN-NF-75-27. Buppl 2. "Neutronic Design Method for PHRs "
 OHSLEY.OF Exxon Nuclear Co. Inc (subs of Exxon Corp)
 OFO 060 B0 80/03/24 4pp
- 8004020429 Forwards WCAP-949i, "Transient & Accident Analysis," in compliance w/item 2 1 9 c of NUREQ-0578 REED.C Westinghouse Operating Plants Cwners Group OG-32 80/03/31 1p
- --8004020432 WCAP-9691
 "Transient & Accident Analysis "
 HITCHLER,M J , SHARP,D R , ANDERSON,T M Westinghouse Electric
 Corp 80703/31 180pp
- 8004020453 Notification of NRC B00401 meeting w/Hestinghouse owners group in Bethesda,MD re encl guidance on analysis of accidents & transients & preparation of emergency procedure guidelines
 ROSS,D F Division of Project Management B0/03/17 7pp
- B004020464 Forwards B&N 800304 ltr & BAW-10144A to inform of availability WILSON, J N Light Water Reactors Branch 4 BAW-10144-A 80/03/18
- --8004020469 Forwards BAW-10144-A, "Evaluation of Atypical Weldment," TAYLOR.J. H Babcock & Wilcox Co 80/03/04 ip
- --8004020475 BAH-10144-A "Evaluation of Atypical Weldment " MODRE:K E , LOHE,A L , HARRIB,C E Babcock & Hilcox Co 80/02/29
- 8004040324 Confirms 800314 telcon re BWR owners group response to NUREC-057B Requirement 2 1 9 FBAR Chapter 15 event review encl KEENAN.T P General Electric Co MFN-074-80, 80/03/31 75pp
- --8004040333 NEDO-24708 Errata consisting of Section 3 2 1 "Loss of Feedwater" # General Electric Co 80/03/31 200pp
- ---8004040337 Draft (Revision 7) of "Emergency Procedure Guidelines BWR 1-5." * General Electric Co 80/03/26 25pp

- 8004070095 Notifies that NRC Ofc of Controller has been asked to bill company for review & approval of GAI-TR-106, "GA Program for Nuclear Power Plants"
 MILLER. H O License Fee Management Branch 80/03/19 ip
- 8004070190 Notifies that NRC Ofc of Controller has been asked to bill company for review & approval of Amend 5 to TR-21A, "GA Program" MILLER.W O Licensø Fee Management Branch 80/03/19 ip
- 8004070209 Notifies of billing for review & Approval of Revision 8 to CPC-1-A, "QA Program Manual "
 MILLER.W O License Fee Management Branch 80/03/05 1p
- 8004070232 Summarizes 800229 discussions w/NRC re review status of WCAP-8646. "Analysis of Fuel Rod Fretting Wear" Requests review of proprietary & nonproprietary versions be discontinued Retain rept for info only ANDERSON.T M Westinghouse Electric Corp NS-TMA-2223 80/03/25
- 8004070360 Forwards proposed Revision 4 to TVA-TR75-1A, "GA Program Description for Design.Const & Operation of TVA Nuclear Power Plants "
 MILLS,L M Tennessee Valley Authority 80/04/01 2pp
- ---B004070363 TVA-TR75-1A R4
 Proposed Revision 4 to TVA-TR75-1A, "GA Program Description
 for Design,Const & Operation of TVA Nuclear Power Plants "
 * Tennessee Valley Authority B0/04/01 117pp
- BO040B003i Advises that local-to-bulk at values noted in P A 2 7 of NEDE-24223 & are contained in GE 791214 ltr & can be used as nonproprietary WEIBS, J M General Electric Co BO/03/07 ip
- --8004080036 Forwards list of pages in NEDE-24222, Vols 1 & 2 & NEDE-2422 containing proprietary info for use until nonproprietary repts are available Nonproprietary versions should be available within couple of wks
 PFEFFEREEN.H C General Electric Co 80/03/06 2pp
- 8004080252 Notifies that NRC Ofc of Controller has been asked to bill company for review & approval of BVTR-1-0, "GA Program Description" MILLER: # 0 License Fee Management Branch 80/03/19 1p
- 8004090316 Forwards proprietary version of NEDE-24720-P "Mark III Confirmatory Test Program 1/9 Area Scale Multicell Condensation & Stratification Phenomena Test Beries 6003 "Rept available in Central Files only BUCHHOLZ, R H General Electric Co , Nuclear Energy Products Div B0/03/19 6pp
- 8004090461 Forwards "Mark-BZ Demonstration Assembly Licensing Rept." Revision i.nonproprietary version TAYLOR.J H Babcock & Wilcox Co B0/03/26 ip
- --8004070464 BAN-1533 Ri
 "Mark-BZ Demonstration Assembly Licensing Rept." Revision 1.
 nonproprietary version
 # Babcock & Wilcox Co 80/02/28 12pp
- BOO4100199 Forwards visugraphs shown at B&W/NRC B00326 meeting on TAFY beginning of life pin pressure in LOCA analyses Explanation & discussion encl
 TAYLOR, J H Babcock & Wilcox Co B0/04/02 4pp
- 8004100213 Notification of cancellation of 800403 meeting w/C-E owners group in Bethesda,MD re transient analyses & emergency procedure guidelines
 COX.T H Standardization Branch 80/03/27 2pp
- 8004100217 Notification of cancellation of 800401 meeting w/ Westinghouse owners group in Bethesda. MD re transiant analyses & emergency procedure guidelines O'REILLY, J P Standardization Branch 80/03/27 2pp
- 8004100237 Notification of cancellation of 800402 meeting w/OE BWR owners group in Bethesda. MD re transient analyses & emergency procedure guidelines THOMAS.C O Standardisation Branch. 80/03/27 2pp
- 8004100333 Forwards fire protection recommendations on proposed rule refire protection program for nuclear power plants operating prior to 790101 HALL, R E Brookhaven National Laboratory 7590-01 80/04/01 27on

- 8004100379 Forwards monthly fire protection rept for Mar 1980. constituting completion of short-term priority item of licensee backlog review
 HALL, R. E. Brookhaven National Laboratory 80/04/02 3pp
- 8004110209 Forwards response to 800124 request for add1 info re
 "Properties of Fuel & Core Component Mat1," WCAP-9224 (NP)

 & WCAP-9179 (P).Revision 1 Application for withholding encl
 Response re WCAP-9179 & affidavit withheld (ref 10CFR2 790)
 ANDERBON, T M Westinghouse Electric Corp., PWR Systems Div
 NB-TMA-2218 80/03/31 2pp
- 8004110216 Forwards "Response of C-E NBSS to Transients & Accidents," CEN-128. Vols 1 & 2 Info in rept intended for use in training of reactor plant operators & revision of emergency procedures

 LIEBLER, G E C-E Power Systems 80/04/01 2pp
- --8004110223 CEN-128 V2
 "Response of C-E N6SS to Transients & Accidents," Vol 2
 * C-E Power Systems 80/04/30 850pp
- --8004110225 CEN-128 V1
 "Response of C-E NSSS to Transients & Accidents." Vol 1
 * C-E Power Systems 80/04/30 330pp
- 9004110481 Notification of 800403 meeting w/B&W & B&W licensees in Bethesda, Md to discuss B&W reactor response & volnerability of task force rept REID, R W Operating Reactors Branch 4 80/03/31 3pp
- BOO4110537 Responds to BOO303 ltr re changes in organization chart of GA dept NRC approves changes
 HABS, MP Quelity Assurance Branch BO/03/21 1p
- B0041400B3 Responds to 800307 questions re Levels 1, II & III qualified insp personnel functions Level I personnel w/specific experience can perform direct insps Level II or III individual should review & evaluate Level I HAABB, W P Guelity Assurance Dranch 80/03/27 2pp
- 8004140113 Responds to 800228 request for re-evaluation of fee assessment for Revision 1 & exemption for NEDE-24011-P-A Re-evaluation of Revision 1 fee results in same assessment No basis for walving topical rept fee MILLER, W O License Fee Management Branch 80/03/20 2pp
- --8004140116 Requests re-evaluation of fee assessment for review of Revision 1 & exemption from fee requirements for NEDE-24011-P-A ENDEL, R E General Electric Co MFN-049-80 80/02/28 2pp

- 8004150324 Summary of 800108 meeting w/Westinghouse in Bethesda: MD. returbine disc cracks
 RDSB: W J Operating Reactors Branch 1, 80/04/04 5pp
- 8004150353 Forwards "Method of Applying Mark II Single Vent Dynamic Lateral Load to Mark II Plant W/Multiple Vents," on behalf of Mark II owners group Rept withheld (ref 10CFR2 770) Affidavit encl BUCHHOLZ, R H General Electric Co RHB-029-80. 80/04/09 App
- 800417002B Forwards "Failure Mode & Effects Analysis of Engineered Bafety Features Actuation Sys." Revision 1, nonproprietary version Affidavit & application for withholding proprietary info encl Proprietary version withheld (ref 10CFR2 790). ANDERBON. T M Westinghouse Electric Corp., PWR Bystams Div NB-TMA-2220 80/03/20 9pp

- --BOQ4170035 "Failure Mode & Effects Analysis of Engineered Safety Features Actuation Sys." Revision i.nonproprietary version Eighteen oversize pages encl MEBHERINGER, J. Westinghouse Electric Corp., PUR Systems Div 80/02/29 77pp
- 8004180420 Ngtification of 800408 meeting w/C-E in Bethesda, MD to discuss high range affluent monitors for Lessons Learned requirements & Reg Quide 1 97
 BARRETILL Environmental Evaluation Branch 80/04/02 ip
- 8004210244 Submits review of Draft 1 of proposed Revision 2 to SRP 4 2 Section 4 2 Choice of 1 3 safety factor on fuel assembly lateral impact load is conservative for loads created by crossflow TAYLOR, J H Babcock & Wilcor Co 80/04/14 4pp
- 8004210303 Advises of availability of NEDE-24226-P & NEDG-24226, "Evaluation of Control Blade Lifetime w/Potential Loss of B4C "
 - IPPOLITO, T A Operating Reactors Branch 3 80/03/24 1p
- --8004210306 Forwards NEDO-24226 & NEDE-24226-P, "Evaluation of Control Blade Lifetime w/Potential Loss of BAC " Proprietary version to Central Files only (ref 10CFR2 790) CODK.K W General Electric Co MFN 037-80 80/02/12 2pp
- --B004210307 NEOD-24226
 "Evaluation of Control Blade Lifetime w/Potential Loss of B4C." nonproprietary version
 BRAYHAN,K W General Electric Co 79/12/31 56pp
- 800421036B Forwards summary of ECCB evaluation model improvements Will justify continued use of TAFY w/improvements which will offset impact of increased beginning-of-life pin pressure Bix months required for pin-to-pin radiation model TAYLOR.J H Babcock & Wilcox Co 80/04/14 26pp
- B004220434 Forwards presentation math used at 800327 meeting w/NRC re vendor design approach to post-TMI requirements for technical support & info display sys.parameter console & sys status monitoring ANDERSON.T M Westinghouse Electric Corp NS-TMA-2226 B0/04/08 200
- 8004220497 Forwards "Assistance for Use in Analyzing Mark II 8WR 8Uspression Pool Temp Response to Plant Transients Involving Safety Relief Valve Discharge" BUCHCLZ/R H General Electric Co HFN-071-80 80/04/18 1p
- --8004220499 "Assumptions for Use in Analyzing Mark II BHR Suppression Pool Temp Response to Plant Transients Involving Bafety Relief Valve Discharge and Plant Owners Oroup 80/03/24 14pp
- 8004230315 Confirms clarification re organizational changes Topical rept revision not required for minor changes that do not significantly impact GA program SCHERER, A E C-E Power Systems LD-80-017 80/04/18 1p
- 8004240521 SAND77-0274 C
 "Gost Worksheets for Waste Isolation Pilot Plant Conceptual Design Rept." Addendum C
 * Sandia Laboratories 77/04/30 374pp
- 8004240523 SAND77-0274 D
 "Alternative Energy Sources for Waste Isolation Pilot
 Plant," Addendum D
 * Sandia Laboratories. 77/04/30, 70pp
- 8004240527 BAND77-0274 E
 "Electrical Load Summery for Weste Isolation Pilot Plant Conceptual Design Rept," Addendum E.
 " Bandia Laboratories 77/04/30, 25pp
- 8004240549 8AND77-0274 F

 "Heating, Ventilation & Air Conditioning Sys Energy Analysis for Waste Isolation Pilot Plant Conceptual Design Rept,"

 Addendum F.

 * Sandia Laboratories 77/04/30 42pp
- 8004250004 Requests pretest analyses for representative experiment re HDR bloudoum program. Analyses should be submitted by 800615 to keep within schedule for evaluation of MCAP-8707 (P) & MCAP-8709 (NP).

 DENISE, R. P. Assistant Director for Reactor Safety 80/04/01, 2pp
- 8004230005 Forwards "Dow Egs for Solidification of Low Level Radwasts from Nuclear Power Plants." Amends 1 - 3 & NRC 780628,1019 & 1207 Itrs requesting add1 info per beloon request, W/o encl BAER,R.L. Light Water Reactors Branch 2, 80/04/11, 19

- 8004250066 Requests comments on encl draft proposal re Atmospheric Release Advisory Capability site installations in NY & IL ORPHANIR C Lawrence Livermore Laboratory 80/03/20 9pp
- B004230409 Forwards bimonthly activities rept for Feb-Mar 1980 HANN,C R Battelle Memorial Institute, Pacific Northwest Laboratory FIN D-2313 80/04/17 19pp

1

- BO04280103 Notification of BO0415 meeting to discuss potential generic problems w/tight radius U-bend tubes in Westinghouse steam generators. Trajan program for U-bend tube removal & establish actions to address potential generic problems LIAW, B D Engineering Branch 80/04/09 2pp
- 8004280182 Extends invitation to 800424 FY80 mid-yr review of program entitled "Experimental Support & Development of Single-Rod Fuel Codes:" w/BNNL in Silver Spring, MD FY80 draft program brief.FY81 program assumptions & review agenda encl JOHNSTON, W V Fuel Behavior Branch FIN 8-2043 80/04/08 5pp
- 8004280329 Forwards Revision 1 to Section 3 0 of WCAP-9402.
 "Verification Testing & Analyses of Westinghouse 17:17
 Optimized Fuel Assembly "Application for withholding & affidovit encl Proprietary version withhold(ref 10CFR2 790)
 ANDERSON, T M Westinghouse Electric Corp NS-TMA-2232 80/04/16
- --8004280344 WCAP-9402
 Revision 1 to Section 3 O of WCAP-9402, "Verification
 Testing & Analyses of Westinghouse 17x17 Optimized Fuel
 Assembly," nonproprietary version
 # Westinghouse Electric Corp 80/04/16 67pp
- 8004280400 Provides commitment for thermal hydraulic analysis of Test V-31 for CENPD-252-P, "Blowdown Analysis Method-Method for Analysis of Blowdown Induced Forces in Reactor Vessel" List of add1 data required encl BCHERER, A.E. C-E Power Systems LD-80-018 80/04/23 3pp
- B0042B0504 Forwards responses to NRC 790B17 questions on core spray design methodology confirmation tests.addl info requested at 791115 meeting & NEBD-24706. "Lynn SBTF Bundle Flow Heasurement Sys Description & Calibr "
- --8004280507 NEDU-24706
 "Lynn SBTF Bundle Flow Measurement Bys Description & Calibr "
 DANIELSON, D W General Electric Co 79/08/31 130pp
- 8004290434 Forwards "Implementation Guidelines for Technical Support Ctr & Related Control Room Instrument Sys," Revision 2, dtd 800214 REED.C Westinghouse Operating Plants Owners Group GG-33 80/04/22 22pp
- 800429046B Forwards "Response to NUREG-04B7. Criteria for Computing Loads on Bubmerged Structures." on behalf of Mark II owners group as part of Task C 15 of Mark II containment program BUCHHOLZ,R H General Electric Co , Nuclear Energy Products Div MFN-081-80 80/04/21 2pp
- ~-8004290474 SAI-161-79-PA

 "Response to NUREO-0487.Criteria for Computing Loads on Submerged Structures"
 CHANDRALV, HSIEH.J S Stone & Webster, Inc DOMASHOVETZ, I Sargent & Lundy, Inc 80/03/31 73pp

WASTE MOT NUCLEAR WASTE MANAGEMENT

- B004020046 Forwards requested info coordinates of receptor locations, map of restricted area boundary & yellowcake drier stack location, joint frequency tables & clarification of seepage analysis

 LANGE, B L Pioneer Nuclear, Inc 15731 80/03/06 19pp
- 8004020057 Forwards Anaconda Co rept, "Justification for Waiver of Landownership Requirement — U Mill Tailings Disposal Area " SETHNEGS.E D Camp Drysser & McKee, Inc., Environmental Sciences, Div 19734 80/02/25 ip
- ~~8004020061 "Justification for Waiver of Landownership Requirement -U Mill Tailings Disposal Area " * Camp Dresser & McKee, Inc., Environmental Sciences, Div 13734 80/02/08 55pp

- 8004020159 Ack receipt of NRC B00125 itr requesting delay of issuance of license to Bokum Resources Corp for U mill NRC itr cantained no technical objections to project, therefore license was issued on 800129
 KING.B Hew Merico, State of 15710 80/01/29 Ip
- 8004020165 Requests permission to continue tailings discharge into Pund 1 until limiting conditions qublined in Acres American, Inc 800314 Itr are reached or another discharge pund authorized REKEMEYER, P C Union Carbida Corp 15786 80/03/14 1p
- 8004020182 Notifies that draft rept on Church Rock scheduled for 800801 & final rept by 800901 Schedule depends on livestock data, dose assessments & Battelle soil sampling rept BUHL.T Hew Mexico, State of 15784 80/03/12 ip
- 8004020196 Requests structural stability evaluation of proposed evaporation pond dam at disposal site & catchment dam at mill site per Reg Ouide 3 il guidance MACKIN.J.L. New Marico. State of 15794 80/03/11 ip
- 8004070240 Notification of 800307 meeting w/state & føderal agencies in Santa Fe.NM to discuss methods of estimating radiation doses resulting from ingestion of meat from livestock watering in Rio Puerco
 - BUHL, T New Mexico, State of 15465 80/02/28 19
- 8004070246 Notifies that San Miguel Ranch included in preoperational radiological monitoring program, is occupied by three persons including one preschool age child For dose assessment purposes, no milk or vegetable pathway included MDONEY, F 8 Oulf Gil Corp., Gulf Mineral Resources Co. 1565; 80/02/22 ip
- 8004070353 Forwards NRC correspondence file re proposal from Cotter Corp to dispose of miscellaneous contaminated solid wastes in portion of new tailings impoundment at U mill Requests review & assessment.w/recommendations.of encl matl ROTHFLEISCH.J Uranium Recovery Licensing Branch 80/03/17 ip
- --8004070355 Forwards 800226 request for assistance from A Hazle Director of Radiation & Hazardous Wastes Control Div.CD Dept of Health re trash disposal at Cotter Corp U mill KERR.G W Assistant Director for State Agreements Programs 80/03/05 ip
- --B004070359 Forwards addl info re Cotter Corp proposel to dispose of contaminated trash, machinery & const matls in secondary impoundment Requests NRC further critique or concur w/proposal HAZLE, A J Colorado, State of B0/02/26 Spp
- 8004070369 Forwards latest correspondence re tailings mgt for proposed pitch project; as promised in 800311 telcon Both applicant b state no longer consider burial at Site B viable alternative for tailings disposal M/o encls ROTHFLEISCH. J Uranium Recovery Licensing Branch 80/03/17 ip
- 8004080151 Responds to V Halker inquiry re radioactive matl release from Church Rock U mill 790716 tailings dam failure Contamination cleanup complete in most heavily affected areas near mill site DIRCKS.H J Office of the Executive Director for Operations 80/03/05 2pp
- B004080226 Requests waivers of land numership requirements for licensing U mill tailings disposal Surface tracts used for disposal are under lease & planned to be returned to lessors
 DAVIS.O R, WILLIAMS.M Anaconda Co (subs of Atlantic-Richfield Co) 15737 80/02/28 3pp
- 8004080278 Requests permission to continue discharge of tailings into Pond i through 800325 subject to operating conditions discussed in Acres American. Inc 800107 itr w/exception that plezometer levels be limited to one ft above 800108 levels REKEMEYER.P.C. Union Carbide Corp. 15660 80/02/15 lp
- 8004080665 Discusses AJ Harle 791219 request for NRC assessment of potential radiological impact of U mill operation on proposed residential subdivision Results of NRC evaluation are summarized in NRC 800123 ltr to Harle ONUONOLI, Q Uranjum Recovery Licensing Branch 80/03/13 2pp
- 8004070020 "Ground Water Discharge Plan.Mt Taylor U Mill Project.NM " * Earth Sciences Associates 15849 80/01/31 42pp

- 8004090115 Forwards responses to NM Environ Improvement Div questions re U mill license application All containment basins and sized to contain drainable vol of slurry & liquid in both pipelines, plus 10 minutes of flow in pipelines ROGERS, WL Gulf Oil Corp., Gulf Mineral Resources Co. 15745 80/03/04 15pp
- BOO4090135 Forwards discussions of work planned as part of investigation of Hale Gulch as considered site for deposition of taskings Work includes field drilling, lab testing & dam design SIMCHUCK.O Homestake Mining Co 15698 80/02/28 14pp
- --8004090140 "Evaluation of Existing Osohydrologic Data Homestake Mining Co Pitch Project. Hale Gulch (Site A) Tailings Pond Bite, Baguache County, Co "Related correspondence encl ROUSE, J V Envirological Bystems, Inc. 15678 80/01/10 13pp
- 8004110118 Forwards Co Dept of Health 800221 & 17 ltrs & Union Carbide Corp 800213 & 17 ltrs re discharge of tailings into Pond 1 MEAVER. K. Colorado: State of 15771 80702/22 9pp
- 8004110144 Forwards State of CO 800226 request for assistance re trash disposal at Cotter Corp.Canon City U mill.CO KERR.G W Office of State Programs 15707 80/03/05 ip
- --B004110146 Forwards addl info re Cotter proposal to dispose of contaminated trash, machinery & const matls in secondary impoundment Requests further critique or concurrence on proposal per Public Law 95-604 HAZLE: A J Colorado. State of B0/08/26 Opp
- 8004180105 Advises of completed dam safety review for Union Carbide Uravan mill per 791104 request Results of encl safety evaluation Indicate that Pand 2 & 3 do not mest safety factors recommended by NRC Reg Guide 3 11 WZ encl SCARAND.R A Uranium Recovery Licensing Branch 20/03/21 lp
- 8004210416 Forwards summary of B00214 meeting between NRC, vendor & State of TX organizations Also forwards NRC comments on vendor mill tallings disposal ropt Statements made re site characteristics are consistent w/NRC visual observations, MILLER, H J Uranium Recovery Licensing Branch 80/03/25 4pp
- 8004220200 Forwards response to Question 10 in 791221 ltr re 100-yr flood boundary & final tailings discharge from wash filter Contour interval map & photos of final teilings encl LANOE, B L Pioneer Nuclear, Inc. 13663 80702/29 Bpp
- 8004230148 Discusses NM Environ Improvement Div approval of Discharge Plan DP-100 & issuance of radioactive meths license Expresses concern re question of public role in review of matl generated by vendor in response to license conditions ROBINSON.P. HECTOR.A Southwest Research and Information Center 15939 80/03/10 16pp
- 8004240060 Advises that E Reed & Associates has been employed to develop techniques for return of tailings to pitrafter mining for final disposition Borings have been taken & company expects to review final Reed rept on 800416
 DAVIS, G R Anaconda Co , Anaconda Copper Co Div 15914 80/03/24
- 8004240116 Responds to B00314 request for third interim authorization to discharge tailings to Pond 1 CO Dept of Health will authorize continued discharge of tailings through B00315 if requirements of dept 800108,0219 & 21 ltrs are met HAZLE, A J Colorado, State of 15834 80/03/20 2pp
- 8004280231 Submits trip rept re 791105 visit to review proposed site for mining & milling facility Review should be complete in approx four months assuming timely resolution of questions on proposal Schedule & maps encl
 KRUO,K E Uranium Recovery Licensing Branch 80/03/11 9pp.
- 8004270507 Expects review of 800227 draft agreement between NRC & State of WA will include stability review of embankment against requirements of Reg Guide 3 11 STRONG/T R Washington State of 15970 80/04/03 1p
- 8004290520 Forwards analytical results of 791015-16 sampling trip to Canon City to investigate water, soil 5 vegetation contamination

 DREESEN, D R Los Alamos Scientific Laboratory 16054 79/12/18

- 8004300215 Forwards Ford, Racon & Davis UT, Inc "Appraisal Rept." prepared for State of DR.re area under consideration by Placer Ames in connection m/proposed tailings disposal facility Related correspondence enci
 HGGRATH.E J McGrath, E J 15912 80/03/27 4pp
- --8004300219 UC-329 יישור איז יישור איז טער שאיז שאיז איז טער שאיז איז טער איז איז טער שאיז איז טער שאיז איז איז שאיז איז איז איז "Appraisal Rept," pregared for Div of State Lands, State of Ford Bacon & Davis Utah, Inc 15712 80/03/27 35pp
- B004300237 Safety evaluation for Tailings Ponds 2 & 3

 * Geotechnical Engineers, Inc. NRC-02-79-055 15966 80/03/07
- B004300284 Requests written confirmation of agreement re items discussed in NRC 791214 ltr & 800312 telcon Revised UDAD analysis & evaluation of environ impact of radon & particulates requested HAZLE, A J Colorado. State of 15842 80/03/17 ip
- 8004300297 Hritten comments of Homestake Mining Co before Dept of Agriculture re appeal of Regional Foresters decision on administrative appeal of approval of U mill operation FISKE,T N , HATBON.J F Gorsuch, Kirgis, Campbell, Halker & Grover FISKE,T N Homestake Mining Co 15840 80/03/25 27pp
- XPORTLIC EXPORT AND IMPORT LICENSES
- 8004010051 SECY-80-045 Forwards Executive Branch position on 800121 applications for licenses to export highly enriched U to Belgium West Germany, France & the Netherlands Requests comments SHEA, JR Office of International Programs 80/01/24 ip
- --B004010478 Executive Branch position re five Transnuclear, Inc applications for licenses to export highly enriched U to Belgium, Mest Germany, France & the Netherlands Recommends issuance of licenses Ltrs of assurance encl NOSENZO.L.V State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs. B0/01/21 15pp
- --8004010095 Forwards two applications for licenses to export 22 050 kg U enriched to max 93 3% U-235 & 779 kg U.enriched to max 4 05% U-235 H/o latter application MATBON.V Transnuclear, Inc. 78/06/22 2pp
- ---B004010097 Application by Transnuclear, Inc for license to export 20 050 kg U.in form of U hexafluoride enriched to max 93 3% U-235, to the Netherlands End use statement encl HATBON.V Transnuclear, Inc 78/06/22 2pp
- --8004010101 Forwards Transnuclear, Inc application for license to export 72 6 kg U in form of U hexafluoride enriched to max 93 3% U-235, to France.
 MATSON V Transnuclear, Inc 78/08/08 1p
- --8004010105 Application by Transnuclear, Inc for license to export 72 6 kg U, in form of U hexafluoride enriched to max 93 3% U-235, to France End use statement & related checklist of info encl MAYBON,V Transnucteer, Inc 78/08/08 Bpp
- 8004020184 License for Exxon Nuclear Co, Inc to export nuclear fuel element hardware including Zircaloy tubes, Zircaloy end caps. Inconel plenum springs & other specially designed nuclear reactor parts to West Germany. PETERSON.H R Assistant Director for Export/Import & International Safeguards 80/03/13 ip
- 8004020236 Application by Bargent Industries-Sweeney Div for license to export 125 Ci tritium contained in foils
 SQUITIERI.R J Sargent Industries, Sweeney Div XB-5-385 80/03/12
- 8004020240 Application by Byron Jackson Pump Div for license to export specifically designed or prepared parts & components for pumps to India * Borg Warner Corp : Bryon Jackson Pump Div INDIA. 80/03/06 ip
- BOO4020246 Application by Byron Jackson Pump Div for license to export two rotating face rings, four carbon bearings, four retaining rings, one coolant rectirculating impeller & one bearing retainer assembly to India * Borg Warner Corp . Bryon Jackson Pump Div. 793-V-2785 BO/03/06

- 8004020369 Executive Branch position re Transnuclear, Inc application for license to export 100,000 kg natural U to West Germany Ltrs of assurance encl License should be granted NDSENZOL V State. Dept of. Bureau of Oceans & Internatl Environ & Scientific Affairs 80/03/06 4pp
- 8004020387 License for Aldrich Chemical Co.Inc to export 10 kg deuterium, contained in 40 kg deuterium oxide, to United Kingdom PETERSON, M R Assistant Director for Export/Import & International 6180 80/03/06 2pp Safequards
- 8004020393 Amend 1 to Edlow Intl Co export license, extending expiration date from 800401 to 820401 PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/12 1p
- 8004020397 Amend 1 to Edlow Intl Co export license extending expiration date from 800401 to 820401
 PETERSDN.M R Assistant Director for Export/Import & International Safeguards 80/03/12 ip
- 8004020401 Amend 1 to Edlaw Intl Co export license, extending expiration date from 800401 to 820401
 PETERSON M R Assistant Director for Export/Import & International Safeguards 10-44-78-1 80/03/12 ip
- B004020406 Amend 1 to Ediow Intl Co export license, extending expiration date from B00401 to B20401
 PETERSON,M R Assistant Director for Export/Import & International Safeguards 10-44-78-2 80/03/12 ip
- 8004020467 Requests early review of applications to export two nuclear reactors & initial fuel cores in advance of util award of project Early review would be significant step to enhancing foreign confidence in US supply & licensing process WILBON.B D General Electric Co BDW-B0027 B0/03/07 2pp
- ---8004020471 Application by GE Tech Bvc Co & GE for license to export 239.000 kg low enriched U oxide as fabricated BWR fuel bundles to Talwan MILEGON.B D General Electric Co BDN-80031 80/02/07 to
- 8004020472 Forwards application by Transnuclear, Inc for license to export 30,476 kg U.containing 1,234 kg U-235 & 127,224 kg U.containing 919 kg U-235, to West Germany MATSON, V Transnuclear, Inc 80/03/19 ip
- -8004020479 Application by Transnuclear, Inc for license to export 30.746 tg U.containing 1.234 tg U-235 & 129.224 kg U. containing 919 kg U-235,to West Germany * Transnuclear, Inc NUK-319 80-059/ 80/03/19 3pp
- 8004020484 Submits application to amend licenses extending expiration dates from 800401 to 810401
 YAMAGUCHI,T Power Reactor & Nuclear Fuel Development Corp 80-0-009 80/02/26 1p
- 8004030043 Forwards application by Coordination Council for North American Affairs to export 4000 kg heavy water to Taiwan HU,K Coordination Council for North American Affairs 80/03/12
- --B004030046 Application by Coordination Council for North American Affairs for license to export 4000 kg heavy water to Taiwan End use statement encl # Affiliation Unknown 80/03/10 2pp
- 8004030049 License for Westinghouse Electric Co to export BF 3 counter tube, Model NL-23744 to France PETERSON, M R Assistant Director for Export/Import & International Bafguerds 80/03/25 ip
- 8004030274 Forwards application for license to export component sys & parts for two OE forced circulation single cycle light water cooled & moderated BWRs w/designed power level of 984 MW. to Talwan WILSON,B D General Electric Co BDW-B0029 80/03/07 2pp
- --8004030280 Submits application for license to export component sys & parts for two QE forced circulation, single cycle light water cooled & moderated BMRs w/design power level of 984 MM, to Taiwan WILGON, B. D. General Electric Co. BDW-80030 80/03/07 2pp.
- 8004030364 Requests Executive Branch position re Transnuclear.Inc application for license to export SNM to West Germany PETERSON M R Office of International Programs 80/03/27 ip

NONDOCKETED ITEMS

- 800404003B Waives 15-day waiting period for License XB-1090 PETERBON.M R Assistant Director for Export/Import & International Safeguards 80/03/27 4p
- --8004040042 License for Gearhart-Owen Industries, Inc to export 5 Ci Am-241 to Poland
 PETERSON:M R Assistant Director for Export/Import & International Safeguards 40-180/80049 80/03/27 2pp
- 8004040045 Waives 15-day waiting period for License XB-1089
 PETERSON.M R Assistant Director for Export/Import & International
 Safeguards 80/03/27 1p
- --8004040047 License for Kay-Ray. Inc to export 400 mCi Cs-137 in two sources to Crechoslovakia PETERSON.M R Assistant Director for Export/Import & International Safeguards 2072 80/03/27 2pp
- BOO40400B7 Forwards ltr from Embassy of Israel requesting cancellation of Application XB-1041 W/o encl
 PETERSON M R Assistant Director for Export/Import & International
 Safeguards BO/03/19 1p
- 8004040090 Requests cancellation of application to export byproduct matl to Southwest Africa (Namibia)
 JOHNSON, N R Eberline Instrument Corp EI-917682 B0/02/28 ip
- 8004040099 Requests Executive Branch position re Metal Bellows Corpapilication for license to export flexible metal hoses to Bpain Bpain PETERSON, M R Assista Assistant Director for Export/Import & International
- 80040400103 Application by Rockwell Inti-Flow Control Div for license to export Rockwell-Edward globe stop valve metal diaphragm sealed. ASME III. 1521 special class rated, body & bonnet of SA182, Grade F316 stainless steel, to India OF8ANIK, W J Rockwell International Corp 2929FE 80/03/14 lp
- 8004040107 Application by Sigma Chemical Corp for license to export equivalent of 5 kg deuterium liquid over two-yr period to Canada GUICH,P A Sigma Chemical Co (subs of Sigma-Aldrich Corp.) D-39 80/03/07 ip
- 8004040110 Forwards application by Transnuclear. Inc for license to export 10.794 kg U.enriched to max 3 4% U-235, to Belgium MATBON, V Transnuclear. Inc 80-037/01 TNP-3 80/03/12 1p
- --8004040ii4 Application by Transnuclear, Inc for license to export 10,794 kg U. enriched to max 3 4% U-235, to Belgium
 * Transnuclear, Inc 80-037/01 TNP-3 80/03/12 3pp
- 8004040135 Submits applications to amend license extending expiration date to 830501 HARMON, D W E Edlow International Co 80/03/10 ip
- 8004040141 Application by Par Sys Corp for license to export Par Model ISI-2, inservice insp sys. to United Kingdom PARSONS, W B Par Systems Corp 667-3 80/03/10 ip
- ~-8004040152 Ack receipt of NRC 791015 ltr Expresses surprise w/NRC opinion that sale of inservice insp sys should require NRC permit PARSONS,W B Par Systems Corp 79/11/27 2pp
- B004040147 Executive Branch position re Saunders-Roe Developments.Ltd application for license amend to export addl 500.000 Ci tritium to United Kingdom License should be granted.
 NDZENZOL V Bates.Dept of Bureau of Oceans & Internati Environ & Scientific Affairs 80/03/14 2pp
- 8004040178 License for CERAC, Inc. to export 8 78 kg thorium, contained in 10 kg thorium oxide as powder, to Italy PETERBON, MR Assistant Director for Export/Import & International Safeguards 80/03/25 2pp
- 8004040477 Amend 1 to Saunders Roe Developments, Inc license changing B00501 expiration date to 810915 & increasing amount of export to one million Ci tritium as tritium gas PETERBON, MR Assistant Director for Export/Import & International Bafeguards B0/03/21 2pp
- 8004040480 Requests Executive Branch position re Ediow Intl Co application for license to export source matl to Taiwan PETERBUN.H R Assistant Director for Export/Import & International Bafeguards 80/03/27 ip

- 8004070023 License for Eberline Instrument Corp to export 0 02 microgram Pu-239 electroplated on stainless steel in DNS-10 alpha calibr std set to South Korea MODREN N Assistant Director for Export/Import & International Safeguards 5 0 6957 80/03/07 2pp
- B004070026 Ltr of assurance that Oovt of Japan has appointed Hansai Electric Power Co.Inc as authorized party for import of 25 mg of U-235.enriched to max of 93 15/ MIYABAYABHI.M Japan 79/11/29 1p
- BOO407002B License for QA Co to export 405 g U-235, contained in 579 g U, as FLIP TRIOA fuel elements; to Mexico PETERSON, M R Assistant Director for Export/Import & International Safeguards IEL-992 80/03/06 2pp
- 8004070027 Forwards notice of applications for licenses to export nuclear facilities or matls for FR publication SHEA, J R Office of International Programs 80/03/08 ip
- ---8004070034 Notice of applications for licenses to esport nuclear facilities or matis received 80021-0303 GHEA.JR Office of International Programs 80/03/08 2pp
- 8004070037 Forwards application for export license for minor nuclear export Ltr of assurance required PETERSON.H R Assistant Director for Export/Import & International Safeguards 80/03/27 ip
- 8004070073 License for DDE to export 3 95 kg U-235.contained in 20 kg U as metal & 2 25 kg U-235.contained in 5 kg U as metal, to the Netherlands & West Germany MOORE.R N Assistant Director for Export/Import & International Safeguards 80/03/07 2pp
- 8004070078 Amend to GA Co export license, increasing quantity of authorized matl from 1 72 g U-235, contained in 1 84 g U, to 3 52 U-235, contained in 3 84 g U HOURE, R N Assistant Director for Export/Import & International Safeguards IEL-1020 80/03/06 ip
- 8004070080 License for DDE to export 3 95 kg U-235.contained in 20 kg U as metal & 2 25 kg U-235.contained in 5 kg U as metal. to France & the Netherlands
 MODRE, R N Assistant Director for Export/Import & International Safeguards 80/03/07 2pp
- BOD40700B5 Bubmits application to amend license to export, changing quantity of authorized matl to 10 1 kg U-235, contained in 51 2 kg U MATBUN, V Trenenuclear, Inc. 80/03/05 1p
- BOO40700BB License for Chase Nuclear Div of Chase Brass & Copper to export ii.000 lbs zirconium 2 5% niobium alloy extruded tubes to Italy PETERBON.H R Assistant Director for Export/Import & International Bafeguards A2-2020 80/03/07 ip tubes to lead PETERBON M R Assist
- 8004070148 SECY-80-142 004070148 SECY-80-142
 Recommends issuance of license to export reactor & associated components to Philippines Proposed export would not be inimical to UB common defense & security No further action required on SECY-77-100
 SHEA.J R. Office of International Programs 80/03/14 App
- --8004070180 Discusses deaths of two energy activists & physical security of proposed reactor Continued repression creates highly unstable environ "Mother Jones" Dec 1979 article re state of civil wer in Philippines encl PERLAS,N Philippine Movement for Environmental Protection 80/01/27
- 8004070407 Requests Executive Branch position on encl Coordination Council for North American Affairs application for license to export 4.000 kg of heavy water to Taiwan Wo encl PETERBONN R Assistant Director for Export/Import & International Bafeguards 80/03/20 ip
- BOO4080009 Foewards application by GA Co to export SNM contained in 20 TRIOA fuel slements & four fission chambers to Indonesia HOWRY, W R General Atomic Co (subs of Gulf Di) Co) BO/03/14

- --8004080014 Application by GA Co for license to export 6,478 g
 U-rirconium hydride, contained in 20 TR19A fuel elements &
 four fission chambers containing U-235, to Indonesia
 HGMRY.W R General Atomic Co (subs of Gulf Dil Co) IEL--1159
 B0/03/14 1p
- 8004090020 Submits application to amend license, changing ultimate consignee address
 MATSON.V Transnuclear, Inc. 80/03/21 10
- 8004080032 Application by Edlow Intl Corp for license to export 600 kg depleted U dioxide powder to Talwan End use statement oncl HARMON, D W Edlow International Co IM-1 80/03/17 2pp
- 8004080039 Forwards application by Transnuclear. Inc for license to export 1.438.45 kg U-235.contained on 49.455 kg U,to France MATSDN.V Transnuclear. Inc 80/03/20 lp
- --B0040B0042 Application by Transnuclear, Inc for license to export 1,638,63 kg U-235, contained in 49 636 kg U, to France End use statement encl HATBON, V Transnuclear, Inc 80-042/01 80/03/21 2pp
- 8004080050 Application by Teledyne Wah Chang Albany for license to export 108 tons Zircolay tubes to Argentina AERNI,B L Teledyne Wah Chang Albany 3155 80/03/21 ip
- BOO40800A9 Advises that route for transport of AECL spent fuels from Ogdensburg, NY to Dunbarton.NC must be changed due to local ordinance in Geneva, NY Proposes alternate route STUKENBROEKER.O NL Industries. NL Nuclear Div 15807 80/03/11
- 8004000079 Forwards application by Transnuclear, Inc for license to apport 22 142 kg U.containing 10 033 kg U-235, to Japan MATSON, V Transnuclear, Inc 80/03/25 ip
- --8004080085 Application by Transnuclear, Inc for license to export 22 142 kg U.containing 10 053 kg U-235,to Japan End use Btatement encl HATSON, V Transnuclear, Inc 80/03/25 18pp
- 8004080087 License for Mitsubishi Intl Corp to export 500 mci Cf-252 as encapsulated cernet wire to Japan PETERSON M R Assistant Director for Export/Import & International Safeguards 80/03/25. 2pp
- BO04080096 License for Mitsubishi Intl Corp to export 500 mci CF-252 as encepsulated cernet wire to Japan PETERSON.H R Assistant Director for Export/Import & International Gafeguards 64-7407-80 80/03/25 2pp
- BOO4080104 Forwards application by Transnuclear, Inc for license to export 40 48 kg U.containing 37 768 kg U-235 to Japan MATBON.V. Transnuclear, Inc 80/03/25 ip
- --8004080259 Application by Transnuclear, Inc. for license to export 40 48 tg U.containing 37 768 kg U-235, to Japan End use statement encl. MATSON, V. Transnuclear, Inc. 80/03/25 35pp.
- 80040801iG Executive Branch position re CONAX Corp application for license to export adapter module assemblies & seal components for electrical penetration assemblies to Spain License should be granted

 NOBENZO,L. V Btate, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/03/25 2pp
- 8004080126 Executive Branch position rs Carpenter Technology Corpapplication for license to export Zircalog-4 fuel channels to Spain License should be granted NOSENZO.L.V. State.Dept of, Sureau of Oceans & Internati Environ & Scientific Affairs 80/03/25 2pp
- 8004080131 Executive Branch position re Reactor Experiments Inc application for license to export 0.3 mg Np-237 electroplated on mickel discs for use in dosimetry to Czechoselovakia License should be granted NOSENZO.L V. State.Dept.of. Bureau of Oceans & Internatl Environ & Scientific Affairs 80/03/25 2pp
- 8004080138 Executive Branch position re Westinghouse application for license amend to export low enriched U to Korea in Jan 1984 rather than 1985 License amenó should be granted NOBENZOLL V State, Dept of. Bureau of Oceans & Internet! Environ & Scientific Affairs, 80/03/26 2pp

- 8004080251 License for Reactor Experiments, Inc to export 0 342 mg Np-237 to Ciechoslovakia PETERBON.H R Assistant Director for Export/Import & International Safeguards CZ 2806 80/03/27 2pp
- 8004080295 License for Westinghouse to export 43 mg U-235.contained in 43 mg U-ta Yugoslavia PETER80N,M R Assistant Director for Export/Import & International Safeguards BX-11006 80/03/27 2pp
- 8004080299 Waives 13 day waiting period for proposed license for Aldrich Chemical Co to export deuterium oride to Brazil PETERSON,M R Assistant Director for Export/Import & International Bafeguards 80/03/27 lp
- ---8004080303 License for Aldrich Chemical Co.Inc to export 1 kg deuterium contained in 5 kg deuterium oxide, to Brazil PETERSUN, M R Assistant Director for Export/Import & International Bafeguards 80/03/27 2pp
- 8004080311 License for Carpenter Technology Corp to export 96 pieces of 2 mm Zircaloy-4 alloy fuel channels, to Spain PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/26 ip
- 8004080315 License for Conax Corp to export adapter module assemblies & electric penetration seal components to Spain PETERSON.M R Assistant Director for Export/Import & International Bafeguards 7-85800 80/03/27 ip
- 8004080332 Application by Kay-Ray, Inc for license to export 400 mCi Cs-137 in two sources to Crechoslovskia BAKER, R Kay-Ray, Inc 2872 80/03/21 ip
- 8004080342 Application by Westinghouse for license to export six WL23465 incore detector units to Guitterland POCHAL,W F Westinghouse Electric Corp ZE-10289 80/03/17
- 8004080345 Application by Teledyne Wah Chang Albany for license to export 400 lbs Zircaloy-2 tube shells to Norway WATTENBARGER.S Teledyne Wah Chang Albany 2849 80/01/28 ip
- 8004080350 License for Ediow Intl Co to export 68,500 kg U.as natural V hexaflouride, to France PETER80N.H R Assistant Director for Export/Import & International Safeguards KWK 80/03/24 2pp
- B004080353 License for Transnuclear, Inc to export 100,000 kg U oxide, containing 715 kg U-235, to West Germany PETERSON, MR Assistant Director for Export/Import & International Safeguards NUK-291 79-211/ B0/03/26 2pp
- 8004080620 Requests Executive Branch position re Edlow Intl Co application for license to export U-308 to West Germany for eventual use as fuel in Emsland power reactor PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/03/12 1p
- 8004080627 License for Hestinghouse to Export 0 0164g U-235, contained in 0 0176 g U to Yugoslavia PETERBON, M R Assistant Director for Export/Import & International Bafeguards ZEPW-11017 80/03/27 2pp
- BO04080643 Application by Aldrich Chemical Co.Inc for license to export 1 kg deuterium.contained in 5 kg deuterium oxide to Brazil EDELBTEIN.B Aldrich Chemical Co. Inc (subs of Bigma-Aldrich Corp) 80/03/27 lp
- B004080650 Application be Gearhart-Gwen Industries, Inc for license to export 5 cf Am-241 in neutron source to Poland CLAUNCHIA Gearhart-Gwen Industries, Inc., 00 Mireline Services Div 40-180/80049 80/03/20 lp
- 8004090113 Forwards Bargent Industries application for license to export tritium contained in foils to Condition 2 countries
 New request required because licensee inadvertently allowed old export license to expire
 PETERSON, M R Assistant Director for Export/Import & International Bafeguards 80/03/20 19
- 800409019B Forwards license to export gauges to China License issued w/o 19-day waiting period due to urgent requirement of matl PETER80N.M R Assistant Director for Export/Import & International Safeguards 80/03/21 ip

- ---B004090202 License for Campbell Pacific Nuclear Corp to export 10 mCi Cs-137 & 50 mCi Am-24i/He contained in molsture density gauge to China PETERBON.M R Assistant Director for Export/Import & International Bafeguards 80/03/21 ip
- 8004100044 Executive Branch position re Exxon Nuclear Co Inc application for license to export 1.740 kg of U-235, contained in 55.440 kg of U.to Belgium Ltr of assurance encl License should be granted NOSENZO.L V State. Dept of: Bursau of Oceans & Internat! Environ & Scientific Affairs 80/03/28 2pp
- BOO4100049 License for Sigmo Chemical Cu to export 5 kg deuterium oxide.to Canada PETERSON,M R Assistant Director for Export/Import & International Safeguards BO/04/01 2pp
- 8004100058 Executive Branch position re Exxon Nuclear Co, Inc application for license to export 2,110 kg U-235, contained in 68,000 kg of U.to West Germany Ltr of assurance encl License should be granted NGSENZO, L V State. Dept of, Bureau of Oceans & Internat! Environ & Scientific Affairs 80/03/28 2pp
- 8004100060 Executive Branch position re Nuclear Metals, Inc application for license to export 150 lbs depleted U for R&D to Oermany License should be granted NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Sclentific Affairs 80/03/27 2pp
- BO04100062 Requests Executive Branch position re Teledyne Isotopes application for license amend, extending explration data from 800501 to 820501 PETERSON, M.R. Assistant Director for Export/Import & International Safeguarde 80/03/31 lp
- B004100063 Notifies of withdrawal re 780718 application for license to export 25,000 kg enriched U
 HERBCH, M M Westinghouse Electric Corp 80/03/03 lp
- BOO4100175 Requests Executive Branch position re OA Co application for license to export SNM to Bangladesh PETERBON, MR Assistant Director for Export/Import & International Bafeguards 80/04/OZ lp
- BOO4100179 Requests Executive Branch position re Edlow Intl Co application for license to export Cf-252 neutron sources to United Kingdom PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/04/02 1p
- BOO4100180 Requests Executive Branch position re GA Co application for license to export SMM to Indonesia PETERBON, M R Assistant Director for Export/Import & International Safeguards BO/04/03 ip
- BOO4100181 Requests Executive Branch position re Per Sus Corp application for license to export inservice insp sys to South Africa PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/04/03 ip
- 8004100184 Requests Executive Branch position re Transnuclear.Inc application for license to apport SMM to Japan PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/04/03 ip
- 8004100232 License for Nissho-Iwai American Corp to export 39 186 kg U-235,contained in 42 kg U. to Japan. PETERSDN,M R Assistant Director for Export/Import & International Safeguards 80/04/02 3pp
- GOO4100306 Application by Eberline Instrument Corp for license to export Pu-239 alpha calibr sources, electroplated on 47 mm metal disc to Canada
 JOHNBON, N L Eberline Instrument Corp 50 7491 60/03/29 ip
- 8004100597 Advises of Commission acceptance of recommendation to approve Edlow Intl Co license to export 68,500 kg of U in form of UF6. to France Comments of Chairman Ahearne noted CHILK.B J Office of the Secretary of the Commission 80/03/25 in
- BOO4110117 Advises of Intention to cancel 791108 application re export of 1 O Ci tritium gas to Israel APPELBAUN. A Israel 07/80/312 BO/03/13 2pp

- 8004110141 Forwards Isotope Products Labs note transmitting IAEA 800317 Itr providing add1 end use info re license application XB-1069 W/o encl PETERBONN MR Assistant Director for Export/Import & International Safeguards 80/03/28 ip
- 800411053B Forwards GE application for license to export two BWRs to Taiwan W/g encl SHEA.J R Office of International Programs 80/03/17 1p
- 8004140010 Application by NL Nuclear Industries to amend license, increasing matl for import to 72 087 kg U, containing up to 42 541 kg U-235 as spent NRX & NRU fuel to Savannah River Plant STUKENBROEKER, O NL Industries, NL Nuclear Div 80/03/17 9pp
- 8004140064 Requests expeditious handling of 790129 application for license to export Korean Nuclear Units 7 & 8 concurrent w/Executive Branch review Undue delay could jeopardize contract as discussed in encl 791107 ltr to State Dept HERSH,M M Westinghouse Electric Corp ICS-0042 80/03/26 App
- 8004160082 Forwards 781129 license application w/o action per 800320 request
 PETERSON, H R Assistant Director for Export/Import & International Bafeguards 80/04/01 lp
- 8004170183 Forwards end use statement for completion of 791219 export license application HELM.K Isotope Products Laboratories 80/03/17 2pp
- 8004170270 Confirms that SNM identified in export llcome application will be subject to terms & conditions of 570528 agreement for cooperation & consigness identified on application are authorized to receive & possess matl
- 8004170291 License for Carpenter Technology Corp to export 48 Zircaloy-4 fuel channels to Japan PETERSGN.M R Assistant Director for Export/Import & International Bafeguards 80/04/04 ip
- BOO4180088 Forwards applications for licenses to export flexible metal hose to Spain
 ROGERS, WF Metal Bellows Corp. BO/03/14 in
- --8004180089 Application by Metal Bellows Corp for license to export 25 pieces flexible metal hoses to Spain ROGERS.W F Metal Bellows Corp 14812 80/03/14 ipp
- --8004180092 Application by Metal Bellows Corp for license to export four pleces hose assembly 7001-08E-0707-M-AB-AS to Spain ROGERS;W F Metal Bellows Corp 14845 80/03/14 1p
- 8004180200 Forwards application to export 32 6 kg U metal, enriched to 19 79% U. to France ANL 800125 memo encl BENGELSDURF.H D Energy, Dept of 80/03/28 1p
- --8004180207 Application by DOE for license to export 32 6 kg U metal, enriched to 19 79% U. to France
 BEN9ELSDORF,H Energy,Dept of 80/03/26 3pp
- 8004180229 Executive Branch position re Transnuclear, Inc application for license to export 367 kg U-235, contained in 10,774 kg U, to Belgium MARCHAL, J State, Dept of 80/03/27 ip
- 8004180242 Application by Mitsui & Co. Inc for license to export Zircaloy-2 tube shells & Zircaloy-4 tube shells to Japan MONDEN.T. Mitsui & Co. Ltd 80/04/03 2pp
- 8004i80307 Requests Executive Branch position re Helix Process Sysapplication for license to export two hydrogen recombiners to South Africa PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/27 lp
- --B004iB03iO Application by Helix Process Bys for license to export waste gas mgt treatment sys consisting of two hydrogen recombiners followed by ambient temp charcoal absorption equipment to Bouth Africa MURPHY.W J. Helix Technology Corp., Process Bystems Div 270000 79/11/19. 1p
- --8004i803i4 Forwards 791ii9 application for license to export waste gas mgt treatment sys to South Africa MURPHY.W J Helix Technology Corp , Process Systems Div 80/03/17 ip

- BOO4180480 Extends appreciation for prompt issuance of license amend, changing expiration date to 810301 MOURY,M R General Atomic Co (subs of Gulf Oil Co) IEL-1160 BO/03/14 ip
- BOO4180485 Bubmits application to amend export licence, changing expiration date to 820501 due to administrative decisions PABINDSRY, J P Teledyne Isotopes 80/03/24 lp
- 8004180507 Ltr of assurance re Teledyne Wah Chang Albany application for license to export 400 lbs Zircaloy-2 tube shell DAHL.J M Norway 80/03/18 ip
- 8004210002 Advises of NL Industries 800320 request that license be returned w/o action Application for export of 50.000 tg depleted U to Condition 2 countries was transmitted for review on 781221
 PETERSON, H R Assistant Director for Export/Import & International Bafeguards 80/03/27 ip
- 8004210026 Forwards application to export 7 3 kg U-235,contained in 245 kg U.to Canada W/o enci its application to import same matl to US upon completion of experimental work ELOERT, U.J. Energy, Dept of 80/03/31 ip
- --8004210149 Application by DDE for license to export 7 3 kg U-235, contained in 245 kg U, to Canada HAMSEN,C D Energy,Dept of BR-1593 80/03/25 ip
- 8004210090 Application by Sigma Chemical Co for license to export compounds containing deuterium to Malaysia STERN.W C Sigma Chemical Co (subs of Sigma-Aldrich Corp) D-40 BO/03/2B lp
- ,8004210092 Application by Sigma Chemical Co for license to export compounds containing deuterium to New Zealand STERN.H C. Sigma Chemical Co (subs of Sigma-Aldrich Corp.) D-41 SO/O3/31. 1p
- 800421009A Bubmits application for license to import several mg Pu-23B, probably from France
 O'BRIEN.M J Washington Univ 80/03/31 2pp
- BOO4210123 Application by Westinghouse for license to export 1 68 g U. contained in 1 81 g U-235 to Italy POCHAL.W F Westinghouse Electric Corp ZE-40039 B0/03/28 ip
- BOO4210136 Application by Westinghouse for license to export three units WL-23944 compensated ionization chamber to France POCHAL, W. F. Westinghouse Electric Corp. ZE-20293-4 80/04/02 ip
- BOO4210156 Application by OA for license to export 291 elements containing U-irronium hydride fuel w/max isotope weight of 11 kg U-235 k TRIOA reactor neutron detectors containing max of 6 dg m U-235 to Bangladesh MOMRY, MR General Atomic Co (subs of Gulf Dil Corp.) 80/03/24
- ---BO04210159 Forwards application to export SNM contained in fuel elements & neutron detectors to Bangladesh HOMRY-W R General Atomic Ca (subs of Gulf Dil Corp) BO/03/24 2pp
- 8004210364 Requests Erecutive Branch position re Teledyne Hab Cheng Albany application for license to export Zircaloy TREX tubes to Argentina PETERBONNM R Assistant Director for Export/Import & International Bafeguards 80/03/31 ip
- 8004210369 Requests Executive Branch position re Self-Powered Lighting revised application for license to export tritium gas to Dominican Republic PETERBON.4 R Assistant Director for Export/Import & International Bafeguards. 80/04/02 1p.
- 80042i0379 Requests Executive Branch position re Transnuclear Inc application for license to export 8NM to Japan PETERSON.H R Assistant Director for Export/Import & International Bafeguards 80/04/02 jp.
- 8004210426 Application by Matheson Oas Products for license to export 500 liters deuterium chemically pure (90 g) to Australia Matheson Oas Products 101-77252 80/04/01 1p.
- 8004210451 Amend 1 to license for NL Industries, Inc. increasing quantity for import to 72 089 kg U. containing up to 42 541 kg U-235 & extending expiration date to 810701 PETERSON.H R Assistant Director for Export/Import & International Bafeguards. 80/04/08 2pp

- 8004220111 Forwards 800326 license for export of six WL23088 fission counters w/plugs & cables to Japan POCHAL, W.F. Westinghouse Electric Corp. 80/03/26 ip
- --8004220116 License for Westinghouse to export six WL23088 fission counters w/plugs & cables to Japan
 PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/26 ip
- BO04230127 Forwards application by DDE to export matl to Canada & import application to return matl following experimental work H/o export application ELGERT,O J Energy, Dept of BO/03/26 1p
- --8004230133 Application by DOE for license to import SNM upon completion of experimental work in Canada, exported under License XSNM-1671 ELOERT, D J Energy, Dept of 80/03/26 2pp
- 8004240063 Forwards application for license to export approx 15 lbs depleted U to West Germany for use as metallurgical samples HOLDEN.T J AAI Corp (subs of United Industrial Corp) 80/03/24
- --8004240067 Application by AAI Corp for license to export U-238, as depleted U. to Hest Germany HOLDEN, T J AAI Corp (subs of United Industrial Corp) 80/03/24 tp
- BOO4240130 Notifies of Commission approval of Nissho-Iwal American Corpapplication for license to export 42 kg U.enriched to 93 3%, to Japan Requests detailed description of transportation method & physical security for transit CHILK,S J. Office of the Secretary of the Commission BO/04/02
- BOO4240224 Requests Executive Branch position re Halprin Supply Co application for license to export 250 mCi tritium, contained in two static electricity detection meters, to Egypt PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/04/07 ip
- 8004250007 Ltr of assurance re Univ of Helsinki application for license to export 3 g Btd Ref Matl (SRM) 500 & 1 g each of BRM-015, BRM-030 & BRM-050, to Finland MAKIPENTI, I Finland 80/04/07 ip
- 8004250028 Notifies that NRC has not completed licensing action on application to export depleted U to France for enrichment Final NRC action delayed pending Executive Branch clarification
 SNEA, J R Office of International Programs 80/04/10 ip
- 8004250037 Waives customary i5-day waiting period for issuance of license for Bandvik Special Metals Corp to export 2,350 pieces Zirconium 2 8% niobium seamless tubing to Canada PETERSONM R Assistant Director for Export/Import & International Safeguards 80/03/24 tp
- --B004250042 License for Sandvik Special Metals Corp to export 2,350 pieces Zirconium 2,5% niobium seamless tubing to Canada PETERBUN,M R Assistant Director for Export/Import & International Bafeguards B0/03/24 ip
- 8004280045 Forwards revised 790806 application for license to export tritium gas to Dominican Republic HARPER.R.Q Self-Powered Lighting, Ltd 80/03/18 ip.
- --8004280053 Amended application by Self-Powered Lighting Ltd for license to export tritium gas to Dominican Republic. Amend reduces tritium to 250,000 Ci & changes shipment form to adsorption on finely divided depleted U
 HEGARTY. W Self-Powered Lighting. Ltd 80/03/18 7pp
- 8004280095 Application by Ediow Intl Co for license to export 40 mg Cf-252 as cermet wire to Great Britain HARMON, D H Ediow International Co. TRC-4 80/03/21 3pp
- BOO4300010 Discusses NRC findings re proposed license for Univ of WA to import 10 mg Pu-238, greater than 10% by weight, from France Importation will not be inimical to common defense & security

 MODRE,R N Office of International Programs BO/04/10 ip
- --B004300016 Lirense for Univ of WA to import 10 mg Pu-23B, greater than BOX by weight from France PETERSON.M R Office of International Programs B0/04/10 ip.

8004300454 Application by Sigma Chemical Co for license to export compounds containing deuterium to Belgium STERN.W C Sigma Chemical Co (subs of Sigma-Aldrich Corp) D-42 BO/04/09 ip

8004300458 Application by Westinghouse for license to export three units ML23770 proportional counters to West Germany POCHAL, W.F. Westinghouse Electric Corp. ZE-10214-1 80/04/08 19

8004300459 Application by Westinghouse for license to export two units, WL6937A uncompensated ionization chamber, to The Netherlands POCHAL, W.F. Westinghouse Electric Corp. ZE-10303 80/04/11 1p

		1

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents,"

AAHODT, H H BO04100142* S0-289	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR
AAHODT, N D BO04100142* BO04201015* BO0410015* BO0410010015* BO0410015* BO0410015* BO0410015* BO0410015* BO0410015* BO0410015* BO0410010015*	AAMODT, M M	8004100136	50-289 Q	AHEARNE, J F
AAHDDT, N D B004100159 30-289 0 AHEARNE, J F AHDDT, N D B004100150 30-289 0 AHEARNE, J F AHDDT, N D B004100150 30-289 0 AHEARNE, J F AHDDT, N D B004100150 30-289 0 AHEARNE, J F AHDDT, N D B00410072 50-289 0 AHEARNE, J F AHDDT, N D B004010072 50-289 0 AHEARNE, J F AHDDT, N D B004010072 50-289 0 AHEARNE, J F AHDDT, M M B004010070 50-289 0 AHEARNE, J F AHDDT, M M B004010070 50-289 0 AHEARNE, J F AHDDT, M M B004010070 50-289 0 AHEARNE, J F AHDDT, M M B004010072 50-289 0 AHEARNE, J F AHDDT, M M B004010072 50-289 0 AHEARNE, J F AHDDT, M M B004010082 50-289 0 AHEARNE, J F AHDDT, M M B004010073 50-289 0 AHEARNE, J F AHDDT, M M B004010073 50-289 0 AHEARNE, J F AHDDT, N D B004250053 50-289 0 AHEARNE, J F AHDDT, N D B004250053 50-289 0 AHEARNE, J F AHDDT, N D B004250053 50-289 0 AHEARNE, J F AHDDT, N D B004250053 50-289 0 AHEARNE, J F AHDDT, N D B004250053 50-289 0 AHEARNE, J F AHDDT, N D B004250053 50-289 0 AHEARNE, J F AHDDT, N D B004250053 50-289 0 AHEARNE, J F AHDDT, N D B004250051 50-289 0 AHEARNE, J F AHDDT, N D B004250051 50-289 0 AHEARNE, J F ABDDT, N D B004250051 50-289 0 AHEARNE, J F ABDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F ADDDT, N D B004250051 50-289 0 AHEARNE, J F B00425015 50-289 0 AHE				
AAHODT, N D BO04100154* 50-289 0 AHEARNE, J F AAHODT, N D BO0410072* 50-289 0 AHEARNE, J F AAHODT, N D BO04010072* 50-289 0 AHEARNE, J F AAHODT, N D BO04010072* 50-289 0 AHEARNE, J F AAHODT, M M BO04010072* 50-289 0 AHEARNE, J F AAHODT, M M BO04010072* 50-289 0 AHEARNE, J F AAHODT, M M BO04010072* 50-289 0 AHEARNE, J F AAHODT, M M BO04010072* 50-289 0 AHEARNE, J F AAHODT, M M BO04010082* 50-289 0 AHEARNE, J F AAHODT, M M BO04010082* 50-289 0 AHEARNE, J F AAHODT, M M BO04010082* 50-289 0 AHEARNE, J F AAHODT, N D BO04250055 50-289 0 AHEARNE, J F AAHODT, N D BO04250055 50-289 0 AHEARNE, J F AAHODT, N D BO04250055 50-289 0 AHEARNE, J F AAHODT, N D BO04250065 50-289 0 AHEARNE, J F AAHODT, N D BO04250061* 50-289 0 AHEARNE, J F AHEARNE, J F ABHORN, N BO04260039 RES AHEARNE, J F AHEARNE, J F ABHORN, N BO04300612 50-320 T AHEARNE, J F AHEARNE, J F ABHORN, R BO04300612 50-320 T AHEARNE, J F AHEARNE, J F AHEARNE, J F ADAHB, J E BO04226601 50-384 P AHEARNE, J F AHEARNE, J F ADAHB, J E BO04220601 50-384 P AHEARNE, J F ADAHB, J E BO0420262 50-289 0 AHEARNE, J F ADAHB, J E BO0420037 50-289 0 AHEARNE, J F ADLER, T A BO0430170 50-289 0 AHEARNE, J F ADLER, T A BO0430170 50-289 0 AHEARNE, J F ADLER, T A BO0430170 50-289 0 AHEARNE, J F ADLER, T A BO0430170 50-289 0 AHEARNE, J F ADLER, T A BO0430170 50-289 0 AHEARNE, J F ADLER, T A BO0430170 50-289 0 AHEARNE, J F ADLER, T A BO0430170 50-289 0 AHEARNE, J F ADLER, T A BO0430170 50-289 0 AHEARNE, J F ADLER, T A BO043010059 RES ABADEN, J F BO0430050	AAMODT, N O	8004100145*		AHEARNE, J F
AAHODT, N D BO04100154* 50-289 0 AHEARNE, J F AAHODT, N O BO04010072* 50-289 0 AHEARNE, J F AAHODT, N O BO04010072* 50-289 0 AHEARNE, J F AAHODT, N O BO04010070* 50-289 0 AHEARNE, J F AAHODT, M M BO04010070* 50-289 0 AHEARNE, J F AAHODT, M M BO04010070* 50-289 0 AHEARNE, J F AAHODT, M M BO04010070* 50-289 0 AHEARNE, J F AAHODT, M M BO04010072* 50-289 0 AHEARNE, J F AAHODT, M M BO04010072* 50-289 0 AHEARNE, J F AAHODT, M M BO04010072* 50-289 0 AHEARNE, J F AAHODT, M M BO04010072* 50-289 0 AHEARNE, J F AAHODT, M M BO04010072* 50-289 0 AHEARNE, J F AAHODT, N O BO04250059* 50-289 0 AHEARNE, J F AAHODT, N O BO04250075* 50-289 0 AHEARNE, J F AAHODT, N O BO04250075* 50-289 0 AHEARNE, J F AAHODT, N O BO04250075* AHEARNE, J F ABOOT, N O BO04250075* AHEARNE, J F ABOOT, N O BO04250075* AHEARNE, J F ABO0404011 50-289 RES AHEARNE, J F ABO04070262 40-8584 AHEARNE, J F ABABSN, R W BO04220601 50-398 P ADAHSN, E BO040220601 50-398 P ADAHSN, E BO040022 50-289 0 AHEARNE, J F ADAHS, J E AHEARNE, J F ADLER, T A BO0400229 50-289 Q AHEARNE, J F ADLER, T A BO0400229 50-289 Q AHEARNE, J F ADLER, T A BO0400229 50-289 Q AHEARNE, J F ADLER, T A BO0400229 50-289 Q AHEARNE, J F ADABANA, J M BO0400050 XPORTIC AHEARNE, J F BO04000523 XOMMIBSION AHEARNE, J F BO04000524 COMMIBSION AHEARNE, J F BO04000524 COMMIBSION AHEARNE, J F BO04000525 XOMMIBSION AHEARNE, J F BO04000525	AAHODT, N O	8004100150*		AHEARNE, J F
AAHODT, N G 8004010072* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 8004010070* 80040	AAHODT, N O	8004100156*	50-289 Q	
AAHODT, N D AAHODT, M H BO04010070* 50-289 0 AHEARNE, J F AAHODT, M M, BO04010070* 50-289 0 AHEARNE, J F AAHODT, M M, BO04010070* 50-289 0 AHEARNE, J F AAHODT, M M BO04010082* 50-289 0 AHEARNE, J F AAHODT, M M BO04010082* 50-289 0 AHEARNE, J F AAHODT, M M BO04010082* 50-289 0 AHEARNE, J F AAHODT, M M BO04010082* 50-289 0 AHEARNE, J F AAHODT, N G BO04250063 50-287 0 AHEARNE, J F AAHODT, N G BO04250063 50-287 0 AHEARNE, J F AAHODT, N G BO04250061* 50-287 0 AHEARNE, J F AAHODT, N G BO04250061* 50-287 0 AHEARNE, J F AAHODT, N G BO04250081* 50-287 0 AHEARNE, J F AAHODT, N G BO04250081* 50-287 0 AHEARNE, J F AAHORT, N BO04300412 90-320 T AHEARNE, J F ACGBTA, A BO04160003 ACR8 AHEARNE, J F ACGBTA, A BO04160003 ACR8 AHEARNE, J F ACGBTA, A BO0416003 ACR8 AHEARNE, J F AAHAN, BO04220601 30-384 P AHEARNE, J F ADAHSJ, B BO04220601 30-384 P AHEARNE, J F ADAHSJ, B BO04220601 30-384 P AHEARNE, J F ADAHSJ, B BO04220601 30-289 Q AHEARNE, J F ADALER, T A BO04040229 50-289 Q AHEARNE, J F ADLER, T A BO04040229 50-289 Q AHEARNE, J F ADLER, T A BO04040229 50-289 Q AHEARNE, J F ADLER, T A BO04030170 50-289 Q AHEARNE, J F ADLER, T A BO04030170 50-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F ADLER, T A BO04030210 SO-289 Q AHEARNE, J F AHEARNE, J F BO04080241 SO-289 Q AHEARNE, J F AHEARNE, J F BO04080241 SO-289 Q AHEARNE, J F AHEARNE, J F BO04080241 SO-289 Q AHEARNE, J F BO04080241 SO-289 Q AHEARNE, J F BO04080231 SO-289 Q AHEARNE, J F BO04080231 SO-289 Q AHEARNE, J F AHEARNE, J F BO04080231 SO-289 Q AHEARNE, J F BO04080231 SO-289 Q AHEARNE, J F AHEARNE, J F BO04080231 SO-289 Q				
AAHODT, H M AAHODT, H M BO04010070** BO-289 0 AHEARNE, J F AAHODT, H M BO04010082* BO-289 0 AHEARNE, J F AAHODT, H M BO04010082* BO-289 0 AHEARNE, J F AAHODT, H M BO04010083* BO-289 0 AHEARNE, J F AAHODT, H M BO04010093* BO-289 0 AHEARNE, J F AAHODT, H M BO04010093* BO-289 0 AHEARNE, J F AAHODT, H M BO04010093* BO-289 0 AHEARNE, J F AAHODT, H M BO04010093* BO-289 0 AHEARNE, J F AAHODT, H M BO04250075* BO04250075* BO-289 0 AHEARNE, J F BO04080239 BO04080239 BO04080239 BO04080239 BO04080230 BO04080239 BO04080230 BO04080				
AAMODT, M. M. AAMODT, M. M. BO04010073** SO-289 O AHEARNE, J. F. AAMODT, M. M. BO04010083** SO-289 O AHEARNE, J. F. AAMODT, M. M. BO04010083** SO-289 O AHEARNE, J. F. AAMODT, M. M. BO04010083** SO-289 O AHEARNE, J. F. AAMODT, M. M. BO04010093** SO-289 O AHEARNE, J. F. AAMODT, M. M. BO04010093** SO-289 O AHEARNE, J. F. AAMODT, M. M. BO04250075** SO-289 O AHEARNE, J. F. AAMODT, M. M. BO04250075** SO-289 O AHEARNE, J. F. AAMODT, M. M. BO04250075** SO-289 O AHEARNE, J. F. AAMODT, M. M. BO04250081** SO-289 O AHEARNE, J. F. AAHEARNE, J. F. ABUAF, M. BO04250081** SO-289 O AHEARNE, J. F. BO040802445 AHEARNE, J. F. AHEARNE, J. F. BO040802470 AHEARNE, J. F. BO040802481 AHEARNE, J. F. BO040802491 AHEARNE, J. F. BO04080231				
AAHDDT, M M AAHDDT, M M BO04010082* S0-289 0 AHEARNE, J F AAHDDT, M M BO04010083* S0-289 0 AHEARNE, J F AAHDDT, M M BO04010093* S0-289 0 AHEARNE, J F AAHDDT, M M BO04010093* S0-289 0 AHEARNE, J F AAHDDT, M M BO04290063 S0-289 0 AHEARNE, J F AAHDDT, M M BO04290063 S0-289 0 AHEARNE, J F AAHDDT, M M BO04290063 S0-289 0 AHEARNE, J F AHEARNE, J F ABERCROMBLE, H L B004290081* S0-289 0 AHEARNE, J F ABERCROMBLE, H L B004290081 REB AHEARNE, J F ABERCROMBLE, H L B004290081 REB AHEARNE, J F ADLER, T A B004040229 S0-289 0 AHEARNE, J F AHEARNE, J F ADLER, T A B0040903170 S0-289 0 AHEARNE, J F AHEARNE, J F ADLER, T A B0040903170 S0-289 0 AHEARNE, J F AHEARNE, J F ADLER, T A B0040903170 S0-289 0 AHEARNE, J F B004100599 REB AHEARNE, J F AHEARNE, J F AHEARNE, J F B004100599 REB AHEARNE, J F B004100599 REB AHEARNE, J F AHEARNE, J F B004100599 REB AHEARNE, J F B004100599 REB AHEARNE, J F B004100599 REB AHEARNE, J F B004100599 COMMISSION AHEARNE, J F B0040080229 COMMISSION AHEARNE, J F B0040080231 COMMISSION AHEARNE, J F B004100523 SO-445 M AHEARNE, J F B0040080231 COMMISSION AHEARNE, J F B004100523 SO-445 M AHEARNE, J F B004100523 SO-445 M AHEARNE				
AAMODT, M M BOO4010082* 50-289 0 AHEARNE, J F AAMODT, M M BOO4010093* 50-289 0 AHEARNE, J F AAMODT, M M BOO4010093* 50-289 0 AHEARNE, J F AAMODT, M M BOO4250053 50-289 0 AHEARNE, J F AAMODT, M M BOO4250053 50-289 0 AHEARNE, J F AAMODT, N D BOO4250051* 50-289 0 AHEARNE, J F ABOO4250051* 50-289 0 AHEARNE, J F ABUAF, M BOO4250061* 50-289 R AHEARNE, J F ABUAF, M BOO4250061* 30-320 T AHEARNE, J F ACCUSTA, A BOO4200612 30-320 T AHEARNE, J F ACCUSTA, A BOO4200612 30-320 T AHEARNE, J F ACCUSTA, A BOO4200612 30-320 T AHEARNE, J F ADAMS, M BOO420601 30-384 P AHEARNE, J F ADAMS, M BOO420601 30-384 P AHEARNE, J F ADAMS, M BOO420601 30-384 P AHEARNE, J F ADAMS, M BOO400229 50-289 C AHEARNE, J F ADLER, T A BOO400229 50-289 C AHEARNE, J F ADLER, T A BOO400270 50-289 C AHEARNE, J F ADLER, T A BOO400170 50-289 C AHEARNE, J F ADLER, T A BOO400170 50-289 C AHEARNE, J F ADLER, T A BOO400170 50-289 C AHEARNE, J F ADLER, T A BOO400170 50-289 C AHEARNE, J F ADLER, T A BOO400170 50-289 C AHEARNE, J F ADLER, T A BOO400170 50-289 C AHEARNE, J F ADLER, T A BOO400170 50-289 C AHEARNE, J F ADLER, T A BOO4000170 50-289 C AHEARNE, J F ADLER, T A BOO4000170 50-289 C AHEARNE, J F ADLER, T A BOO4000170 50-289 C AHEARNE, J F ADLER, T A BOO4000170 50-289 C AHEARNE, J F ADLER, T A BOO4000050 XPORTLIC AHEARNE, J F AMEARNE, J F BOO4000050 XPORTLIC AHEARNE, J F AMEARNE, J F BOO4000050 XPORTLIC AHEARNE, J F BOO40000231* COMMISSION AHEARNE, J F BOO40000231* COMMISSIO	AANUDT, M M.	8004010076*	50-289 0	AHEARNE, J F
AAHODT, M M BOO4010093* 50-289 0 AHEARNE, J F AHODT, N D BO04290043 50-287 0 AHEARNE, J F AHODT, N D BO04290043 50-287 0 AHEARNE, J F AHODT, N D BO04290043 50-287 0 AHEARNE, J F AHODT, N D BO04290038 RES AHEARNE, J F ABERCROMBLE, N BOO4280038 RES AHEARNE, J F AHEARNE, J F ABUAF, N BO04280038 RES AHEARNE, J F AHEARNE, J F BO04070262 40-8584 AHEARNE, J F AHEARNE, J F ADAMS, N E BO0428061 50-320 T AHEARNE, J F AHEARNE, J F ADAMS, N E BO0428061 50-320 T AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04070262 40-8584 AHEARNE, J F AHEARNE, J F BO04070262 40-8584 AHEARNE, J F AHEARNE, J F ADAMS, N E BO04220601 50-388 H AHEARNE, J F AHEARNE, J F ADAMS, N E BO04220601 50-389 P AHEARNE, J F ADAMS, N E BO04080434 50-289 G AHEARNE, J F ADLER, T A BO04040229 50-289 G AHEARNE, J F ADLER, T A BO04040229 50-289 G AHEARNE, J F ADLER, T A BO04030170 50-289 G AHEARNE, J F ADLER, T A BO04030170 50-289 G AHEARNE, J F ADLER, T A BO04030170 50-289 G AHEARNE, J F ADLER, T A BO04030170 50-289 G AHEARNE, J F ADLER, T A BO0409039 TO-289 G AHEARNE, J F ADLER, T A BO0409039 TO-289 G AHEARNE, J F ADLER, T A BO0409039 TO-289 G AHEARNE, J F ADLER, T A BO0409039 TO-289 G AHEARNE, J F ADLER, T A BO0409039 TO-289 G AHEARNE, J F ADLER, T A BO0409039 TO-289 G AHEARNE, J F ADLER, T A BO0409039 RES AHEARNE, J F AHEARNE, J F BO0409039 RES AHEARNE, J F BO0409044 BO040904 RES AHEARNE, J F BO0409049 RES AHEARNE, J F BO04100390 RES AHEARNE, J F BO04090490 RES AHEARNE, J F BO04100390 COMMISSION AHEARNE, J F BO04090490 RES AHEARNE, J F BO04				
AAHODT, N M AAHODT, N M BO04250053				
AAHODT, N O BO04250063 SO-287 O AHEARNE, J F AAHODT, N O BO04250081* SO-287 O AHEARNE, J F AAHODT, N O BO04250081* SO-287 R AHEARNE, J F BO04260411 BO0426038 RES AHEARNE, J F ADLER, T A BO04090279 ADLER, T A BO04090370 SO-287 Q AHEARNE, J F AHEARNE, J F ADLER, T A BO04090370 ADLER, T A BO04090370 ADLER, T A BO04090370 ADLER, T A BO04090370 AHEARNE, J F AHEARNE, J F ADRAGNN, J M BO04100547 ABORAMAL, A K BO04090370 RES AHEARNE, J F AHEARNE, J F BO0409038 AHEARNE, J F BO04090397 AHEARNE, J F BO04090398 AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04090398 AHEARNE, J F				
AAMODT, H M AAMODT, N O AAMODT, N O BOO4250031* BO04250031* S0-287 G AHEARNE, J F AHEARN, C D ADAHSIJ, E 7708150364* S0-358 H AHEARN, C D ADAHSIN, R U BO04220601 S0-384 P AHEARN, C D AHEARN, C D AHEARN, C D AHEARN, C D AHEARNE, J F ADLER, T A BO0400032 S0-287 G AHEARNE, J F ADLER, T A BO04003170 S0-287 G AHEARNE, J F ADLER, T A BO04003170 S0-287 G AHEARNE, J F ADLER, T A BO04003170 S0-287 G AHEARNE, J F ADLER, T A BO04003170 S0-289 G AHEARNE, J F ADLER, T A BO04003170 S0-289 G AHEARNE, J F ADLER, T A BO04003170 S0-289 G AHEARNE, J F ADLER, T A BO040030170 S0-289 G AHEARNE, J F ADLER, T A BO04000050 XPORTLIC ADRAMAL, A K BO04000050 XPORTLIC APPRILIC APPRIL APPRILIC APPRILIC APPRILIC APPRILIC APPRILIC APPRILIC APPRILIC				
AAMDOT. N O ABEAGROMBLE, H L BO04280031		9004830093	30-287 0	AUEWRINE) O E
ABERGROMBLE, H L BO0428003B RES AHEARNE, J F ACCBTA, A BO04180003 ACRB ACGBTA, A ACGBTA, A BO04180003 ACRB AHEARNE, J F BO04070262 40-B584 AHEARNE, J F AHEARNE, J F ADAMS, J E J 7903150364* BO0420601 BO048003B AHEARNE, J F BO04090270 RES AHEARNE, J F AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04090270 AHEARNE, J F AHEARNE, J F BO04090270 AHEARNE, J F AHEARNE, J F BO04090270 AHEARNE, J F BO04090270 AHEARNE, J F AHEARNE, J F BO04090280 COMMISSION AHEARNE, J F AHEARNE, J F BO04090291 COMMISSION AHEARNE, J F BO04090293 COMMISSION AHEARNE, J F BO04090293 COMMISSION AHEARNE, J F BO04090293 COMMISSION AHEARNE, J F AHEARNE, D F				
ABUAF, N BO042003B RES ACKERMAN, N BO04300612 BO-320 T AHEARNE, J F AHEARNE, J F ACOBTA, A BO04180003 ACRB ACOBTA, A BO04180003 ACRB ACOBTA, A BO04180003 ACRB ACOBTA, A BO04070262 AO-8584 AHEARN, C D ADAMSON, R BO04220601 BO04080434 BO0-3286 AHEARNE, J F ADAMSON, R BO04220601 BO04080434 BO0-3287 AHEARNE, J F ADLER, T A BO0408027 BO0408027 ADER, T A BO0400030170 BO0-2879 AHEARNE, J F ADLER, T A BO0400030170 BO0-2879 AHEARNE, J F ADLER, T A BO04090370 BO0408043 ADRACNA, J M BO04100347 BROJ AHEARNE, J F AGRANAL, A K BO04080290 RES AHEARNE, J F BO04080290 RES AHEARNE, J F BO04100397 BO04100397 BO04100397 BO04100397 BO04100397 BO04100397 BO04100397 BO04100390 AHEARNE, J F BO04100390 AHEARNE, J F BO04080243 COMMISSION AHEARNE, J F BO04080227* COMMISSION AHEARNE, J F BO04080231* COMMISSION AHE				
ACKERMAN, N BO04300612 SO-320 T AHEARNE, J F ACQBTA, A BO04070262 40-8584 AHEARNE, C D AHEARNE, J F ADAHSJ, E BO04070262 40-8584 AHEARNE, J F ADAHSON, R W BO04220601 ADAHSON, R W BO04220601 ADAHSON, R W BO04220601 ADAHSON, R W BO04080434 SO-255 R AHEARNE, J F ADAHS, W E BO04080434 SO-255 R AHEARNE, J F ADLER, T A BO0400227 BO0400227 ADLER, T A BO0400227 BO0400007 ADLER, T A BO04000170 BO0400007 BO0400007 BO0400007 ADLER, T A BO04000170 BO0400007 BO0400007 BO04000007 BO04000000 AHEARNE, J F AHEARNE, J F ADRAGNA, J M BO04000000 BO04000000 AHEARNE, J F ADRAGNA, J M BO04000000 BO04000000 AHEARNE, J F AHEARNE, J F BO040000000 AHEARNE, J F BO04000000 AHEARNE, J F BO04000000 AHEARNE, J F BO04000000 AHEARNE, J F BO04100000 AHEARNE, J F BO04000000 AHEARNE, J F BO04100000 AHEARNE, J F BO040000000000 AHEARNE, J F BO040000000 AHEARNE, J F BO04000000000 AHEARNE, J F BO040000000 AHEARNE, J F BO0400000000 AHEARNE, J F BO040000000 AHEARNE, J F BO0400000000 AHEARNE, J F BO0400000000 AHEARNE, J F BO0400000000 AHEARNE, J F BO040000000000000000000000000000000000				
ACOBTA: A P BOO4070262 40-8584 AHEARN. C D ADAHS: J. E 7908150364* 50-358 H AHEARN. C D ADAHS: J. E 8004220601 50-358 H AHEARN. C D ADAHS: J. E 8004220601 50-355 R AHEARNE, J. F ADAHS: J. E 8004080434 50-255 R AHEARNE, J. F ADLER: T. A 8004040229 50-289 G AHEARNE, J. F ADLER: T. A 8004040229 50-289 G AHEARNE, J. F ADLER: T. A 8004030170 50-289 G AHEARNE, J. F ADLER: T. A 8004030170 50-289 G AHEARNE, J. F ADLER: T. A 8004030170 50-289 G AHEARNE, J. F ADLER: T. A 8004030170 50-289 G AHEARNE, C. D ADLER: T. A 8004030170 50-289 G AHEARNE, C. D ADLER: T. A 8004030170 50-289 G AHEARNE, C. D ADLER: T. A 8004030170 50-289 G AHEARNE, C. D ADLER: T. A 8004030170 50-289 G AHEARNE, C. D ADLER: T. A 8004020011 50-289 G AHEARNE, J. F ADRAGNA: J. M 8004100347 PR. J. J. AHEARNE: J. F ADRAGNA: J. M 8004100347 PR. J. J. AHEARNE: J. F AMEARNE: J. F R. SO04080050 XPORTLIC AHEARNE: J. F AMEARNE: J. F R. SO04080050 XPORTLIC AHEARNE: J. F R. SO04080050 XPORTLIC AHEARNE: J. F R. SO04100390 RES AHEARNE: J. F R. SO04100390 RES AHEARNE: J. F R. SO04100390 TO-143 AHEARNE: J. F R. SO04080249 COMMISSION AHEARNE: J. F R. SO04080249 COMMISSION AHEARNE: J. F R. SO04080231* COMMISSION AHEARNE: J. F R.				
ACOBTA: A P BO04070262 40-8584 AHEARN. C D ADAHS: J.E 790819564* 50-358 H AHEARN. C D ADAHS: J.E 800429061 50-384 P AHEARN. C D ADAHS: J.E 800429061 50-384 P AHEARNE. J.F ADAHS: J.E 8004080434 50-255 R AHEARNE. J.F ADLER: T.A 8004040229 50-289 G AHEARNE. J.F ADLER: T.A 8004040229 50-289 G AHEARNE. J.F ADLER: T.A 800403170 50-289 G AHEARNE. J.F ADLER: T.A 8004030170 50-289 G AHEARNE. C D ADLER: T.A 8004030170 50-289 G AHEARNE. C D ADLER: T.A 800420011 50-289 G AHEARNE. J.F ADRAGNA. J. M 8004100547 PROJ AHEARNE. J.F ADRAGNA. J. M 8004100547 PROJ AHEARNE. J.F ADRAGNA. J. M 8004080445 PROJ AHEARNE. J.F ADRAGNA. J. M 8004080250 RES AHEARNE. J.F AHEARNE. J.F 8004100509 RES AHEARNE. J.F 8004080240 RES AHEARNE. J.F 8004080227* RES AHEARNE. J.F 800408	ACOSTA, A	8004180003	ACRS	AHEARNE, J. F.
ADAHSON, R W BOO4220601 50-384 P AHEARNE, J F ADAHS, H E BO04080434 50-285 R AHEARNE, J F ADLER, T A BO04040229 50-289 G AHEARNE, J F ADLER, T A BO04040229 50-289 G AHEARNE, J F ADLER, T A BO04040229 50-289 G AHEARNE, J F ADLER, T A BO04030170 50-289 G AHEARNE, J F ADLER, T A BO04030170 50-289 G AHEARNE, J F ADLER, T A BO04030170 50-289 G AHEARNE, J F ADLER, T A BO04030170 50-289 G AHEARNE, J F ADLER, T A BO0422011 50-289 G AHEARN, C D AHEARNE, J F ADRAQNA, J M BO04100847 PROJ AHEARNE, J F ADRAQNA, J M BO04100847 PROJ AHEARNE, J F ADRAQNA, J M BO04100847 PROJ AHEARNE, J F AGRAHEL, A K BO04100807 RES AHEARNE, J F AHEARNE, J F BO04100807 COMMISSION AHEARNE, J F AHEARNE, J F BO04100809 COMMISSION AHEARNE, J F BO04100809 COMMISSION AHEARNE, J F BO04100809 TO-143 AHEARNE, J F BO04080268 COMMISSION AHEARNE, J F BO04080269 TO-143 AHEARNE, J F BO04080231* COMMISSION AHEARNE, J F BO04080227* COMMISSION AHEARNE, J F BO0	ACOSTA, A P			
ADAMS, W E BO04080434 SO-255 R AHEARNE, J F ADLER, T A BO04040229 SO-289 G AHEARNE, J F ADLER, T A BO04040229 ADLER, T A BO04040229 ADLER, T A BO04040229 ADLER, T A BO04030170 SO-289 G AHEARNE, J F AHEARNE, J F ADLER, T A BO04030170 SO-289 G AHEARN, C D AHEARN, C D AHEARNE, J F ADLER, T A BO04030170 SO-289 G AHEARN, C D AHEARNE, J F ADLER, T A BO040220011 SO-289 G AHEARN, C D AHEARNE, J F ADRACNA, J M BO04100547 PROJ AHEARNE, J F AHEARNE, J F AGRAHAL, A K BO04080250 RES AHEARNE, J F AHEARNE, J F BO0410539 AHEARNE, J F BO0410539 AHEARNE, J F BO0410539 AHEARNE, J F BO0410539 AHEARNE, J F BO04070127 AHEARNE, J F BO0410539 AHEARNE, J F BO04080268 COMMISSION AHEARNE, J F BO04080268 COMMISSION AHEARNE, J F BO04080279 AHEARNE, J F BO04080231 COMMISSION AHEARNE, J F BO040802279 COMMISSION AHEARNE, J F BO04080231* COMMISSION AHEARNE, J F BO04080231* COMMISSION AHEARNE, J F BO04080231* AHEARNE, J F BO0			50-358 H	
ADKIBBION, L. F. ADLER, T. A. BO04090458+ BO04040229 SO-289 G. AHEARNE, J. F. ADLER, T. A. BO04090170 SO-289 G. AHEARNE, J. F. ADLER, T. A. BO04090170 SO-289 G. AHEARNE, J. F. ADLER, T. A. BO04090170 SO-289 G. AHEARN, C. D. AHEARN, C. D. ADLER, T. A. BO04090170 SO-289 G. AHEARN, C. D. AHEARN, C. D. AHEARN, C. D. ADLER, T. A. BO0409011 BO0409011 SO-289 G. AHEARN, C. D. AHEARNE, J. F. ADRAGNA, J. M. BO04090290 RES. AHEARNE, J. F. BO04080050 XPORTLIC AHEARNE, J. F. BO04100590 RES. AHEARNE, J. F. BO04100590 AHEARNE, J. F. BO04100590 COMMISSION AHEARNE, J. F. BO0408026B COMMISSION AHEARNE, J. F. BO04080243 COMMISSION AHEARNE, J. F. AHEARNE, J. F. BO04080243 COMMISSION AHEARNE, J. F. BO04080243 COMMISSION AHEARNE, J. F. BO040802270 COMMISSION AHEARNE, J. F. BO040802210 AHEARNE, J. F. AHEARNE, J. F. BO040802210 AHEARNE, J. F. BO040802210				
ADLER, T. A. BOO400229 50-289 0 AHEARNE, J. F. ADLER, T. A. BOO40030170 50-289 0 AHEARNE, J. F. ADLER, T. A. BOO40030170 50-289 0 AHEARNE, J. F. ADLER, T. A. BOO4030170 50-289 0 AHEARN, C. D. ADLER, T. A. BOO4030170 50-289 0 AHEARN, C. D. ADLER, T. A. BOO4030170 50-289 0 AHEARN, C. D. ADLER, T. A. BOO4220011 50-289 0 AHEARN, C. D. ADLER, T. A. BOO4220011 50-289 0 AHEARNE, J. F. ADRAÇNA, J. M. BOO4100547 PR. D. AHEARNE, J. F. ADRAÇNA, J. M. BOO408045 PR. D. AHEARNE, J. F. ADRAÇNA, J. M. BOO408045 PR. D. AHEARNE, J. F. AORAMAL, A. K. BOO4080270 RES. AHEARNE, J. F. BOO4100590 PR. BOO4	ADAMS, W E	8004080434	50-255 R	AHEARNE, J F
ADLER, T. A. 8004040229				
ADLER, T A BO04030170 50-289 G AHEARNE, J F ADLER, T A BO04030170 50-289 G AHEARN, C D ADLER, T A BO04090399 50-289 G AHEARN, C D ADLER, T A BO04090399 50-289 G AHEARN, C D ADLER, T A BO04220011 50-289 G AHEARNE, J F ADRAÇNA, J M BO04100547 PROJ AHEARNE, J F ADRAÇNA, J M BO0408045 PROJ AHEARNE, J F AGRANAL, A K BO04080290 RES AHEARNE, J F AGRANAL, A K BO04100590 RES AHEARNE, J F AGRANAL, A K BO04100590 RES AHEARNE, J F BO04090127 50-244 U AHEARNE, J F BO04090127 50-244 U AHEARNE, J F BO04090127 SO-244 U AHEARNE, J F BO04090230 SO-445 M AHEARNE, J F BO04090231 COMMISSION AHEARNE, D F BO04090231 COMMISSION AHEARN	ADLER I A			
ADLER, T A B004090379 D0-289	ADLERTI.A			
ADLER, T. A ADRAGNA, J. M BO04100547 PROJ AHEARNE, J. F ADRAGNA, J. M BO04080489 APROJ AHEARNE, J. F AORAMAL, A. K BO04080290 RES AHEARNE, J. F BO04100599 RES AHEARNE, J. F AHEARNE, J. F BO04100599 RES AHEARNE, J. F AHEARNE, J. F BO04100599 TO-143 AHEARNE, J. F BO04100599 TO-143 AHEARNE, J. F BO04070127 SO-244 AHEARNE, J. F BO04070127 AHEARNE, J. F BO04070127 AHEARNE, J. F BO04080268 COMMISSION AHEARNE, J. F BO04080268 TO-143 AHEARNE, J. F BO04080283 TOMMISSION AHEARNE, J. F BO04080283 TOMMISSION AHEARNE, J. F BO04080227* COMMISSION AHEARNE, J. F BO04080221* COMMISSION AHEARNE, J. F BO04080231* COMMISSION AHEARNE, D. F BO04080231* AHEARNE, D. F AHEARNE, D. F AHEARNE, D. F AHEARNE, D. B AHEARNE, D				
ADLER, T. A ADRAGNA, J. M BO04100547 PROJ AHEARNE, J. F ADRAGNA, J. M BO04080489 APROJ AHEARNE, J. F AORAMAL, A. K BO04080290 RES AHEARNE, J. F BO04100599 RES AHEARNE, J. F AHEARNE, J. F BO04100599 RES AHEARNE, J. F AHEARNE, J. F BO04100599 TO-143 AHEARNE, J. F BO04100599 TO-143 AHEARNE, J. F BO04070127 SO-244 AHEARNE, J. F BO04070127 AHEARNE, J. F BO04070127 AHEARNE, J. F BO04080268 COMMISSION AHEARNE, J. F BO04080268 TO-143 AHEARNE, J. F BO04080283 TOMMISSION AHEARNE, J. F BO04080283 TOMMISSION AHEARNE, J. F BO04080227* COMMISSION AHEARNE, J. F BO04080221* COMMISSION AHEARNE, J. F BO04080231* COMMISSION AHEARNE, D. F BO04080231* AHEARNE, D. F AHEARNE, D. F AHEARNE, D. F AHEARNE, D. B AHEARNE, D	ADLER, T A	8004090399	50-989 n	AMEARN.C D
ADRARNA, J. M BO04100547 PROJ AHEARNE, J. F BO04080455 APROTIC APPRILIC APP				
ADRAPAN, J M AERNI, B L. BO04080050 XPORTLIC AHEARNE, J F AORAMAL, A K AORAMAL, A K AORAMAL, A K BO04100570 RE9 AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04100570 COMMISSION AHEARNE, J F AHEARNE, J F BO04100589 70-143 AHEARNE, J F AHEARNE, J F BO04070127 50-244 U AHEARNE, J F AHEARNE, J F BO04080268 COMMISSION AHEARNE, J F BO04104048 70-143 AHEARNE, J F AHEARNE, J F BO04080638 50-445 M AHEARNE, J F AHEARNE, J F BO04080638 50-445 M AHEARNE, J F AHEARNE, J F BO04080231 COMMISSION AHEARNE, J F AHEARNE, J F BO04080227* COMMISSION AHEARNE, J F AHEARNE, J F BO04080227* COMMISSION AHEARNE, J F AHEARNE, J F BO04080227* COMMISSION AHEARNE, J F BO0408028* SO-445 M AHEARNE, J F BO0				
AGRAMAL, A K BO04100590 RES AHEARNE, J F BO0410538 AHEARNE, J F AHEARNE, J F BO04070127 SO-244 AHEARNE, J F AHEARNE, J F BO04080268 COMMISSION AHEARNE, J F AHEARNE, J F BO04080269 COMMISSION AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04080233 COMMISSION AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04080227* COMMISSION AHEARNE, J F AHEARNE, J F BO04080227* COMMISSION AHEARNE, J F BO04080231* AHEARNE, J F BO04080231	ADRAGNA, J M			AHEARNE, J F
AGRAMEL, A K AD04100399 AGRAMEL, A K BO04100399 AHEARNE, J F BO04100398 TO-143 AHEARNE, J F AHEARNE, J F BO04100398 TO-143 AHEARNE, J F AHEARNE, J F BO04070127 S0-244 U AHEARNE, J F AHEARNE, J F BO04080268 COMMISSION AHEARNE, J F AHEARN, C D BO04080638 S0-445 AHEARNE, J F BO04080639 S0-445 AHEARNE, J F BO04080639 COMMISSION AHEARNE, J F AHEARNE, J F BO04080227 COMMISSION AHEARNE, J F AHEARNE, J F BO04080227 COMMISSION AHEARNE, J F BO04080227 COMMISSION AHEARNE, J F BO04080231 COMMISSION AHEARN, C D AHEARN, C D BO04100323 S0-445 AHEARN, C D BO04100323 S0-445 AHEARN, C D BO04100323 S0-445 AHEARN, C D AHEARN, C D AHEARN, C D BO04100323 S0-445 AHEARNE, J F BO04100323 S0-445 AHEARNE, J F BO04100323 S0-445 AHEARNE, J F BO04100323 BO04100323 BO04100321 BO04100323	AERNI, D L.	8004080050	XPORTL1C	AHEARNE, J F
AHEARNE, J. F. 8004100509 COMMISSION AHEARNE, J. F. 8004100508 70-143 AHEARNE, J. F. 8004100508 70-143 AHEARNE, J. F. AHEARNE, J. F. 80041005127 50-244 U AHEARNE, J. F. AHEARNE, J. F. 8004100408 70-143 AHEARNE, J. F. 8004104048 70-143 AHEARNE, J. F. 8004104048 70-143 AHEARNE, J. F. 8004080638 50-445 M AHEARNE, J. F. 8004080638 50-445 M AHEARNE, J. F. 8004080623 COMMISSION AHEARNE, J. F. 8004080623 COMMISSION AHEARNE, J. F. 80040806227* COMMISSION AHEARNE, J. F. 80040806231* COMMISSION AHEARNE, J. F. 80040806234* COMMISSION AHEARNE, C. D. 8004100523* 80-445 M AHEARNE, D. B. 8004100523* 80-445 M AHEARNE, J. F. 8004100524* 80-445 M AHEARNE, J. F. 8004100524* 80-445 M AHEARNE, J. F. 80041005		8004080290	RES	AHEARNE, J F
AHEARNE, J. F. BO04100538 70-143 AHEARNE, J. F. AHEARNE, J. F. BO04070127 50-244 U AHEARNE, J. F. AHEARNE, J. F. BO04080268 COMMIBBION AHEARNE, J. F. AHEARN. C. D. BO04080638 50-445 M AHEARNE, J. F. AHEARNE, J. F. BO04080639 50-445 M AHEARNE, J. F. AHEARNE, J. F. BO04080639 COMMIBBION AHEARNE, J. F. AHEARNE, J. F. BO04080243 COMMIBBION AHEARNE, J. F. AHEARNE, J. F. BO04080227* COMMIBBION AHEARNE, J. F. AHEARNE, J. F. BO04080229* COMMIBBION AHEARNE, J. F. BO04080231* COMMIBBION AHEARN, C. D. AHEARN, C. D. BO04100523* SO-445 M AHEARN, C. D. AHEARN, C. D. BO04100525* SO-445 M AHEARN, C. D. AHEARN, C. D. BO04100525* SO-445 M AHEARNE, J. F. BO04100525* SO-445 M AHEARNE, J				
AHEARNE, J. F. AHEARNE, J. F. BO04070127 BO04070127 BO04070127 BO04070127 BO04080268 COMMISSION AHEARNE, J. F. AHEARNE, J. F. BO04080638 BO04080639 BO04080639 BO04080639 BO04080639 BO04080639 BO04080639 BO04080639 COMMISSION AHEARNE, J. F. BO04080227* COMMISSION AHEARNE, J. F. BO04080231* COMMISSION AHEARNE, J. F. BO04100523* BO04100525* BO04100525* BO04450025* BO044				
AHEARNE, J. F. AHEARNE, J. F. AHEARNE, J. F. BO04080268 C0 MM18810N AHEARNE, J. F. BO04140448 70-143 AHEARNE, J. F. BO04080638 50-445 M AHEARNE, J. F. BO04080639 C0 MM18810N AHEARNE, J. F. BO04080243 C0 MM18810N AHEARNE, J. F. BO04080227 AHEARNE, J. F. BO04080231 C0 MM18810N AHEARNE, J. F. BO04080231 C0 MM18810N AHEARNE, J. F. BO04080231 AHEARNE, J. F. BO04080231 AHEARNE, J. F. BO04080234 AHEARNE, J. F. BO04080234 AHEARNE, J. F. BO04100523 BO04100523 BO04100523 BO04100523 BO04100523 BO0445 AHEARNE, J. F. BO04100523 BO0445 AHEARNE, J. F. BO04100523 BO04100523 BO0445 AHEARNE, J. F. BO04100523 BO0445 AHEARNE, J. F. BO04100523 BO0445 BO04100523 BO0445 BO				
AHEARNE, J F AHEARNE, J F BO0418063B 50-445 M AHEARNE, J F AHEARNE, J F BO0408063B 50-445 M AHEARNE, J F AHEARNE, J F BO0408063B 50-445 M AHEARNE, J F AHEARNE, J F BO04080223 COMMIBBION AHEARNE, J F AHEARNE, J F BO04080227* COMMIBBION AHEARNE, J F AHEARNE, J F BO04080231* COMMIBBION AHEARN, C D AHEARN, C D AHEARN, C D AHEARN, C D BO04100528* 50-445 M AHEARN, C D AHEARN, C D BO04100528* 50-445 M AHEARNE, J F AHEARNE, J F BO04100528* 50-445 M AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F AHEARNE, J F BO04100528* 50-45 M AHEARNE, J F		8004070127	50-244 U	
AHEARNE, J F 8004140448 70-143 AHEARNE, J F 8004080638 50-445 M AHEARNE, J F AHEARNE, J F 8004080638 50-445 M AHEARNE, J F AHEARNE, J F 8004080243 COMMISSION AHEARNE, J F 8004080227 COMMISSION AHEARNE, J F 8004080231 COMMISSION AHEARNE, J F 8004080231 COMMISSION AHEARNE, J F 8004080234 COMMISSION AHEARN, C D AHEARN, C D 8004100523 50-445 M AHEARN, C D AHEARN, C D 8004100525 50-445 M AHEARNE, J F 8004100525 50-445 M AHEARNE, J F 8004100025 AHEARN, C D 8004100025 8004100025 8004100026 AHEARNE, J F 8004100027 AHEARNE, J F 8004100026 AHEARNE, J F 8004100027 AHEARNE, J F 8004100027 AHEARNE, J F 80041000026 AHEARNE, J F 8004100027 AHEARNE, J F 8004100027 AHEARNE, J F 80041000000000000000000000000000000000			COMMISSION	
AHEARNE, J. F. BO04080239 COMMISSION AHEARNE, J. F. AHEARNE, J. F. BO04080227* COMMISSION AHEARNE, J. F. AHEARNE, J. F. BO04080227* COMMISSION AHEARNE, J. F. BO04080231* COMMISSION AHEARNE, J. F. BO04080231* COMMISSION AHEARNE, C. D. AHEARNE, C. D. BO04100523* AHEARN, C. D. BO04100514 AHEARN, C. D. BO04100525* SO-445 M. AHEARNE, J. F. BO04100525* AHEARN, C. D. BO04100525* AHEARNE, J. F. BO04100525* AHEARNE, J		8004140448		
AHEARNE, J. F BO04080223 COMMISSION AHEARNE, J. F BO04080227 COMMISSION AHEARNE, J. F BO04080227 COMMISSION AHEARNE, J. F BO04080229* COMMISSION AHEARNE, J. F BO04080231* COMMISSION AHEARN, C. D AHEARN, C. D AHEARN, C. D AHEARN, C. D BO04100323* BO04100324 BO04100325*				
AHEARNE, J F 8004080223 COMMISSION AHEARNE, J F 8004080227* COMMISSION AHEARNE, J F 9004080227* COMMISSION AHEARNE, J F 9004080231* COMMISSION AHEARNE, J F 9004080231* COMMISSION AHEARNE, C D 9004080234* COMMISSION AHEARN, C D 9004080234* COMMISSION AHEARN, C D 9004080234* COMMISSION AHEARN, C D 9004100514 50-445 M 9004100525* 90-445 M 9004100525* 90-445 M 9004100525* 90-445 M 900410525* 900410525* 900410525* 900410525* 900410525* 900410525* 900410525* 900410525* 900410525* 900410525* 900410525* 900410525* 900410525* 900410525* 900410525*				
AHEARNE, J. F. 8004080227* COMMISSION AHEARNE, J. F. 8004080227* COMMISSION AHEARNE, J. F. 8004080231* COMMISSION AHEARNE, C. D. AHEARNE, J. F. 8004080234* COMMISSION AHEARN, C. D. AHEARN, C. D. 8004100514 50-445 M AHEARN, C. D. 8004100525* 50-445 M AHEARN, C. D. 8004100525* 50-445 M AHEARNE, J. F. AHEARNE, J. F. 8004100025* 50-445 M AHEARNE, J. F. AHEARNE, J. F. 8004100024 COMMISSION AHEARE, L.	AHEARNE, J. F	8004080243	COMMISSION	AHEARNE, J F
AHEARNE, J. F. BO04080223+ COMMISSION AHEARNE, J. F. BO04080231+ COMMISSION AHEARN, C. D. AHEARN, C. D. COMMISSION AHEARN, C. D. AHEARN, C. D. BO04100514 SO-445 M AHEARN, C. D. BO04100523+ SO-445 M AHEARN, C. D. BO04100525+ SO-445 M AHEARN, C. D. BO04100525+ SO-445 M AHEARN, C. D. AHEARNE, J. F. BO04100025+ COMMISSION AHEARNE, J. F. BO04100024 COMMISSION AHEARNE, J. F. BO041000024 COMMISSION AHEARNE, J. F. BO04100000000000000000000000000000000000				
AHEARN.C.D BO04100529 50-445 M AHEARN.C.D AHEARN.C				
AHEARN.C.D BOO4100514 50-445 M AHEARN.C.D AHEARN.C.D BOO4100523* 50-445 M AHEARN.C.D BOO4100523* 50-445 M AHEARN.C.D BOO4100525* 50-445 M AHEARN.C.D AHEARN.C.D COMMISSION AHEARNE.J.F BOO4100525* COMMISSION AHEARRE.L.				
AHEARN, C, D BO04100514 50~445 M AHEARN, C, D AHEARN, C, D, BO04100523* 50~445 M AHEARN, C, D BO04100523* 50~445 M AHEARNE, J F AHEARNE, J, F BO04160024 COMMIBBION AHEARER, L				
AHEARN.C.D. BOO4100323* 30-443 M AHEARN.C.D BO04100323* 30-443 M AHEARNE.J.F AHEARNE.J.F BOO4100024 COMMIBBION AHEADER.L.	AHEARN, C. D	8004100514		AHEARN.C D
AHEARN.C.D BOO4100525* 50-445 M AHEARNE.J.F AHEARNE.J.F BOO4160024 COMMIBBION AHENDER.L.				
AHEARNE, J. F 8004160024 COMMISSION AHENOER, L				
				AHENOER, L
	AHEARNE, J. F	8004080037	COMMISSION	AKER, R E

ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY
8004150137	COMMISSION	ALDEN, W M	B004170230#	50-277 f
8004150317	COMMISSION	ALDEN, W M	8004240391	50-277 (
8004160186	COMMISSION	ALDRICH, D C	8004150022	NUREG
B004160190*	COMMISSION	ALDRICH, D C	8004150033	NUREO
B004160193*	COMMISSION	ALDRICH, D C	80041500/4	NURED
8004160196*	COMMISSION	ALLAN, J M	8004140106	INE
8004160200*	COMMISSION	ALLAN, J M	8004220033*	FOIA
8004160202*	COMMISSION	ALLAN, J M	8004140110	I&E
8004160203*	COMMISSION	ALLAN, J M	8004220080#	FD1A
8004160206*	COMMISSION	ALLAN, J M	0004220202*	FDIA
8004160209*	COMMISSION	ALLAN, J M	8004220236*	FOIA
8004160212#	COMMISSION	ALLAN, J M	8004230040*	FOLA
8004160215*	COMMIBBION	ALLAN, J M	8004230023*	FOIA
8004160220*	COMMISSION	ALLAN, J, M	8004030312*	FOIA
8004080288	40-1341	ALLAN. J M	8004220370*	FOIA
8004080300*	40-1341	ALLAN, J M	8004220380*	FUIA
8004080305*	40-1341	ALLEN, J E	8004150102*	71-273
#70E0B0400B	40-1341	ALLEN, J E	8004150108*	71-273
8004080091 8004080108*	COUNTESION	ALTHAN, W	8004020049	70-135

AUTHOR	ACCESSION NUMBER	SUBJECT CATECORY	AUTHUA	ACCESSION NUMBER	SUBJECT CATEGORY	ADHTUA	ACCESSION NUMBER	EUBJECT CATEGORY
ANDOGNINI. G C ANDOGNINI. G C ANDRESEN. B R AND, W P ANG, W P	B004240357 B004290424 B004220612* B004020043* B004230026*	50~293	BALLENTINE, M BALLENTINE, M BALLENTINE, J M BALLENTINE, J M BALLENTINE, J M BALLENTINE, J M	8004030249 8004030233 8004030222 8004150418 8004150402	50-327 8 50-327 8 50-327 8 50-327 8 50-327 8	BAXTER, T A BAXTER, T A BAYNARD, P BAYNE, J P BAYNE, J P	8004080705 8004230090 8004240467 8004080632 8004210061*	50-312 0 50-312 0 50-302 F 50-284 0 50-284 0
ANSHUTZ, T L ANSON, W B ANSON, W B APFELBAUN, A ARANOV, R	8004030010 8004110303 8004240545* 8004110117 8004250064	50-275 H 50-275 H 50-275 G XADRILIC 70-2909	BALLENTINE, J M BALLENTINE, J M BALLINGER, P L BALLINGER, P L BALDUOH, R C	8004150408 8004180391 8004280579± 8004090304÷ 8004100535	50-327 S 50-327 R 50-298 8 50-298 R 50-445 M	P LAYVE BAYNE, J P P LAYVE P LAYVE P LAYVE	8004220787 8004030267 8004110437 8004140416 8004180448	50~246 0 50~286 0 50~286 8 50~286 8 50~286 8
ARNOLD, R C	8004220373 8004070420* 8004150478 8004170048 8004250340	50-320	BANNER.A P BARBER.R W BARDES.C R BARI.R A BARI.R A	8004290197 8004240559 7902080199 8004100258 8004110521	50-329 h Nureg Hibl Reb Reb	Bayne, J P Bayne, J P Bean, R M Bebas, P G Bechkoefer, C E	8004180426 8004220741 8004080283 8004070200 8004020146	50-286 r 50-286 b reb 50-3 r 50-387 t
ARAURIUS.O ARP, D ARTHAN, K L ARTHAN, K L ASH, R F	8004080169 8004030314 8004140006 8004180034 8004220782	50-367 0 F01A 70-364 70-364 50-317 P	BARIIR A BARWER: B E BARWER: J L BARWER: J L BARWER: D Q	8004100507 8004280035 8004100432* 8004030110 8004010377	RES NUREO 50-10 G 50-249 B 50-498 A	BECHNDEFER, C BECHNDEFER, C BECHNDEFER, C BECHNDEFER, C BECHDEFER, C	8004080685 8004080592 8004210091 8004230111 8004020087	50-387 G 50-358 G 50-409 G 50-387 G 50-387 T
ASHER, T R ASHTON, A M ASWELL, D L ASWELL, D L ASWELL, D L	8004080689 8004040120* 8004010343 8004070308 8004150420	50-574 0 CONTRACT 50-382 S 50-382 S 50-382 A	BARLETT, J BARLETT, J BARNARD, J BARNARD, J GRANARAG	800409D239 800425D419 8004090072* 8004300107* 8004090059*	50-220 G 50-410 A GA999 GA999 GA999	BECKER, J M BECKMAN, D A BECKMAN, D A BECKMAN, D A BEDADSIAN, T	8004030324* 8004280079* 8004040177* 8004170309* 8004080459	FOIA 50-334 P 50-334 Q 50-334 Q PR
ASWELL, D L ASWELL, D L ASWELL, D L ATWOOD, C L AUSTIN, M A	8004250347 8004260576 8004250365 8004100328 8004210081	50-382 8 50-382 8 50-382 I RES 70-135	L ARAIARD DARNES, I, EARNES, I DARNES, I DARNES, D	8004300092* 8004290212* 8004140043* 8004290031* 8004140236	0a999 0a999 0a999 0a999 50—338 F	BEERB.R H DEERB.F C BEERB.F C BEERB.F C BEILENBON.A C	6004230528* 6004150370* 6004150361* 6004150352* 8004060164*	CONTRACT 50-309 H 50-271 H 50-29 H 50-142 U
AUSTIN: M A	8004070388* 8004290105 8004210084* 8004210207* 8004180099	70-364 70-364 ,70-135 70-135 70-364	DARRETT, PA BARRETT, PA BARRETT, PA BARRETT, L BARRETT, L	8004040052* 8004080190* 8004040048 8004180420 8004090208	50-341 0 50-373 0 50-341 8 TOPREP PROJ	BELCHER: R BELEW BELIELE: G A BELKE: W L BENAROYA: V	7908020467 8004270406* 8004210113* 7910050109 8004020439	50-144 H 50-327 G 50-302 G M18C RECOD
AUSTIN, M A AUSTIN, M A AUSTIN, M A AUTIO, H A AVEL, A P	8004180533 8004180026 8004290061 8004080489 8004180264*	70-364 70-135 70-135 50-29 8 50-853 A	DARRY, D N BARTAL, L J BARTH, C A BARTH, C A BARTH, C A	8004070208 8004070276* 8004070182 8004180111 8004210445	PROJ 50-317 R 50-358 G 50-358 G 50-358 G	BENDA, B J BENDER, M. BENDELSDORF, H BENJAMIN, A S	8004030002 8004080628* 8004180207* 8004180200 8004180028	NUREQ XPORTLIC XPORTLIC NUREQ
AVER, A A AXELRAD, M AXELRAD, M AXELRAD, M AXELRAD, M	8004020276* 8004140131* 8004020225 8004020625 8004220625*	40-2061 Foia 50-344 o 50-344 o Foia	BARTLETT, J W BARTLETT, J BARTLETT, J BARTLETT, J BARTLETT, J	8004300279 8004300290# 8004070269 8004210407 8004180345	PR 50-410 0 50-220 F 50-220 P 50-220 F	BENNETT, O L BENNETT, O L BENNETT, C L BENTON, C T	7902060387 7902140361 7906010332 8004070373* 8004170229*	M180 M180 M180 50-367 H 50-327 F
AYRES, S T AYRES, S T BABCOCK, S L BACA, T E BACON, J L	8004090005 8004090008* 8004160030* 8004180298* 8004140391	50-272 G COMMISSION GOMMISSION 50-229 K	BARTLETT.J BARTLETT.J BARTLETT.J DARTLETT.J BARTLETT.J BARTON.R D	8004220501* 8004280394 8004280440 8004290363 8004250022*	50~220 P 50~410 H 50~220 H 50~220 H CONTRACT	BENTBEN, L BERKBIGLER, K P BERKOH, H N BERMAN, M BERNSTEIN, D L	B004240428 B004100319 7903200103 B004070413 B004220008	50-445 H NUREG MISC REB 50-320 G
BADER.S BADRAN,S BAER.R L BAER.R L BAER.R L	8004140429* 8004210288* 8004020441 8004020446 8004020451	50~237 8 50~249 8 50~352 A 50~414 A 50~354 A	Dabalyga. O. Baskiii K. P Baskiii K. P Baskiii K. P Baskiii K. P	B004300071# B004220503 B004220634 B004300375 B004230494	90-397 Q 50-206 P 50-206 P 50-361 D 50-206 P	BERNSTEIN, D L GERNSTEIN, D L GERNSTEIN, D L BERNSTEIN, D L BERNSTEIN, D L	6004220008 6004220102 6004220405 6004220403 6004220403	50~320 G 50~320 G 50~320 G
BAER,R L BAER,R L BAER,R L BAER,R L	8004080723 8004140123 8004110028 8004300468 8004280072	50-553 A 50-359 A 50-361 A 50-395 A 50-369 A	Baskin, k p Daskin, k p Daskin, k p Daskin, k p Bassin, n	8004270640 8004300011 8004300363 8004240374 8004220633*	50-361 A 50-361 A 50-206 F 50-206 P FOIA	BERNSTEIN.DL BERNSTEIN.DL BESECKER.KH BEVAN.R BEVEL.KA	6004210085 6004210085 6004110566* 6004100313 6004220418	50-320 G 50-320 G 50-320 F 50-320 H
L	8004280076 8004280084 8004280038 8004250005 8004300142	50-349 A 50-416 A 50-389 A TOPREP 50-369 A	DASAIN.N DASAIN.N DASAIN.N DAST.J BATEMAN.W H.	8004220486* 8004040432* 8004040446* 8004070332 8004100168*	FOIA FOIA 40-8760 50-320 R 50-354 Q	BEYEA, J BHATIA, P BICKWIT, L BIDDLE, C T BIDDLE, C T	8004100127* 8004100265 8004290171 8004020232 8004020232	50-9 F 50-917 G 50-927 A 50-466 G 50-466 G
	0024* 0191* 0216* 0446* 0509	50-272 Q 70-33 50-247 Q 50-344 R CDNTRACT	Bateman, W Bates, A K Bates, A, L Bates, A, L	8004210359* 7907170211 8004040271 800402042& 8004080102	70-143 30-443 H ACRB MISC MISC	BIDDLE.C T BIDDLE.C T BIDDLE.C T BIDDLE.C.T BIDDLE.C T	8004100274 8004100274 8004140415 8004140415 8004080687	50~498 Q 50~478 Q 50~486 Q 50~466 Q 50~466 Q
BAKER, K R BAKER, R O BAKER, R BAKER, R BALDWIN, J M	8004080594* 8004040004* 8004230024 8004080332 8004110169	50-155 G 50-287 H 50-466 G XPORTLIC 50-445 H	Bates.r W Bauer.e R Bauer.e R Bauer.e.R Bauer.e G	8004280530# 8004010448# 8004010383* 8004010388# 8004170252#	50-336 8 50-318 8 50-318 8 50-318 8 50-277 P	BIDDLE, C T BIDDLE, C T BIDDLE, C T BIDDLE, C T BIDDLE, C T	8004080687 8004100557 8004100587 8004230022 8004230022	50-466 Q 50-466 Q 50-466 Q 50-466 Q
BALLARD, R C BALL, A C BALL, A C BALL, A C BALLARD, R C	8004230074* 8004220560* 8004220565* 8004280024 8004030149	50~445 M 50~111 R 50~111 R NUREQ 50~416 A	Bauer, r Baum, e a Baum, e a Baum, e. a Bauman, r e	8004270479* 8004010267 8004140258 8004250387 8004080280*	50-317 8 50-280 I 50-280 F 50-338 J 50-320 U	Biddle: C T. Bier. J. Bierbaum. G A Bierman. B R Bigiarelli. M J	6004240538 6004070137* 6004080487* 6004040028 6004180440*	50-466 D 50-155 H 50-133 B RES 50-245 B
BALLARD,R L BALLARD,R L BALLARD,R L GALLARD,R L BALLARD,R L	8004020205 8004210048 8004150075 8004280114* 8004280112	50-382 A 50-29 H 50-446 D 50-514 D 50-514 D	Baunack, W Baunack, W Baunack, W Baunack, W Baunack, W	8004160146# 8004040411# 8004090138# 8004180320# 8004280147#	50-293	Bigiarellith J Bimal, B. Birkel, R. Bibek, D. G Bibhop. C. J	8004270303* 8004040047* 8004150051 8004150117* 8004020231*	50-245 B 50-344 T 50-369 A 71-367 50-389 C

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC ¹ CATEGOR	
BISHOP,C J BISHOP,C J BISHOP,M BISHOP,C J	8004020282* 8004150168 8004070145 8004070100 8004030076	50-387	BORDENICK, B M	8004080437 8004070370 8004070376 8004230051 8004150243	50-514 0 50-320 0 50-320 0 50-322 0 50-514 0	BREY.H L BRICKLEY.R H BRIDGES.G BRIGGS.L BRIGGS.L	8004010450 8004220244# 8004210305# 8004070262# 8004070422#	50-267 50-445 50-10 50-219 50-219	Р О Н О
BISHOP.C J BISHOP.C J BISHOP.C J BISHOP.C J BISHOP.C J	8004090450 8004080562 8004090123 8004230162* 8004080574	50-466	BORDENICK, B M BORDENICK, B M BOREIKO, T BOREN, D L BORES, R J	8004150312 8004250398 8004020489 8004140485* 8004070112*	50-516 0 50-322 0 50-327 0 MISC 70-1100	BRIGGS, T DRIGHT, R M BRIGHT, R M BRIGHT, R M BRIGHT, R M	8004210450* 8004040010 8004100365 8004210111 8004080374	50-217 50-302 50-302 50-302 50-302	0 P 0 P
BISHOP,C J BISHOP,R W BISHOP,C J BISHOP,C J	8004100253 8004080272 8004150320 8004100240 8004240541	50-272	BORES, R J BOREB, R J BOROMANN, E A BOROMANN, E A BOROMANN, E A	8004080352* 8004300328* 8004300604* 8004160009 8004040340	50-317 @ 50-225 @ 50-358 @ 50-358 @ 50-358 I	BRIGHT, R M	8004080613 8004210238 8004280351 8004180239 8004180462	50-302 50-302 50-302 50-302	P R P P
BISHOP,C J BISHOP,C J BISHETT.P H BIXEL.D A BIXEL.D A	8004210141 8004230098 8004080599* 8004100480* 8004100469*	50-445 M 50-275 Q 70-364 50-155 Q 50-155 Q	BORGMANN.E A BORST.L BOSSER.M A BOSTIAN.R W BOUKNICHT.J A	8004280317 8004210022* 8004280337* 8004100558 8004080273	50-358 F FOIA 50-320 H 70-2423 50-445 M	BRIGHT,R M BRIGHT,R M BRIGHT,R M BRINKMAN,T J BRINKLER,J E	8004220526 8004280567 8004300331 8004010520 8004180492*	50-302 50-302 50-302 50-322 50-307	Q P Q Q S
BLACK,R L BLACK,R L BLACK,R L, BLACK,R L BLAKE,E L	8004020468 8004100487 8004110142 8004140482 8004020202	50-522 Q 50-522 A 50-312 Q 50-312 Q 50-287 Q	А Г.ТНОІИЖИОВ В Г.ТНОІИЖИОВ В Г.ТНОІИЖИОВ В Г.ТНОІИЖИОВ	8004020113 8004020119* 8004020119* 8004170312 8004170312	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	BRINKLER.J E BRIBTOL.M BROADUB.C R BROCKETT.T W BROCHL.D J	8004210278* 8004070193 8004240565 8004080578 8004040065*	50-309 50-387 NUREO I&E 50-344	ន H T
BLAKE, E L BLAKE, E L BLAKE, E L BLAKE, E L BLAKE, E L	8004020202 8004100549 8004100566 8004110561 8004110567#	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0	A C,THOINXUOB A C,THOINXUOB A AINXUOB A AINXUOB A AINXUOB	8004230154 8004230154 8004240061 8004020413 8004280051	50-445 M 50-445 M 50-445 M 50-373 F 50-373 A	BROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J	8004040073# 8004010334 8004020409 8004280296 8004080504	50-344 50-344 50-344 50-344 50-344	T P P
BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L	8004100549 8004100566 8004110567* 8004140004 8004140004	50-287 G 50-289 O 50-289 G 50-289 G 50-289 G	BOWERS, C E BOWERS, C E BOWERS, J BOWERS, J	8004230533 8004240160 8004220177 8004030322 8004100563	70-820 70-820 70-820 50-287 50-289	BROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J BROOKS, E H	8004180466 8004220695 8004300380 8004300387 8004020263*	50-344 50-344 50-344 50-344 50-259	P P G
BLANCHARD, W H BLOCK, B BLUMBERG, N DLUMBERG, N J BLUME, M	8004140095# 8004300204 8004160144# 8004280147# 8004020198#	M180 NUREG 50-273 Q 50-272 G 50-445 M	BOWERS, J BOWERS, J BOWERS, E 8 BOWERS, E 8	8004100565* 8004100567* 8004110075 8004080597 8004150092	50-287 0 ' 50-287 0 50-287 0 50-514 0 50-514 0	BRODKS, E H BROSS, I D BROUDE, M BROWER, O N BROWN, B H	8004100202* 8004040320 8004270083* 8004020144* 8004080148*	50-250 50-320 50-320 ACRS FOIA	<u>а</u> н
BLUME, M B BLUME, M B BLUME, M B BLUME, M B BLUME, M, B.	8004030347 8004010262 8004080420 8004100126 8004270227	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	BOWERS, E 8 BOWYER, J E BOWYER, J E BOYYER, J E	8004210128 8004040155 8004220579* 8004220557* 8004280379*	50-250 G 50-322 H FOIA FOIA 50-10 H	Brown, J Brown, S. D Brown, G. D Brown, R. A	8004140358* 8004100025 8004300081* 8004300068* 8004160172*	50-369 NUREO 40-4492 40-4492 50-277	A G
BOATWRIGHT, N C	8004220562* 8004220448* 8004220458* 8004220461* 8004220548*	FOIA FOIA FOIA FOIA FOIA	BOYD, D C BOYD, D C BOYD, D C BOYD, D C	B004040444* B004040299* B004100290* B004070427 B004070192	50-315 Q 50-315 Q 50-282 Q 50-315 8 50-315 S	Brown, R A Brown, R A Brown, R A Brown, G D Brown, R A	8004210035* 8004210120* 8004280310* 8004040094* 8004040453*	40-672 50-289 50-293 50-313 40-2061	G G
BOATWRIGHT, N. C BOCCIO, J BODMER, M BODTKE, P BOE, E	8004220463* 8004220574 8004220037* 8004080438* 8004100491*	FOIA REVIEW ORP 50-316 P 50-255 R MIBC	BOYD, D C BOYD, D C BOYER, V S BOYNS, P K	8004070030 8004040059 8004280641 8004080543 8004030308*	50-315 8 50-315 8 50-275 8 50-277 P FOIA	erown, r a erown, r a erown, r L grown, r L erown, r a	8004040035* 8004040379* 8004020434* 8004100034* 8004080147*	50-255 50-315 QA999 QA999 27-47	Q Q
Booden, o Booden, o Booden, o Booden, o, Bohn, r. J	8004090064 8004090250 8004090255 8004080606 8004080331	40-1162 40-1162 40-1162 40-1162 50-367 R	BRADELY,R D BRADFORD,W BRADFORD,P A BRADFORD,P A BRADFORD,U H	8004070084* 8004300187* 8004180274* 8004080053* 8004280143*	50-400 G 50-302 G 50-247 E 50-309 P 50-348 G	Brown, g d Brown, g d Brown, r A Brown, r A Brown, g d	8004040104* 8004300059* 8004100528* 8004040171* 8004040100	GA999 40-4492 50-254 50-331 GA999	Q G
BOHN, R J BOHN, R J BOHN, R J BOHN, R J BOLT, B. A	8004150453 8004220553 8004280494 8004300431 8004170257#	50-367 R 50-367 R 30-367 R 50-367 R 50-70 P	BRADLEY,E R BRADLEY,J P BRADLEY,R D BRADLEY,E J BRADLEY,E J	8004210278 8004030361 8004070331* 8004140317 8004150246	NUREG PR 50-400 G 50-352 I 50-277 I	BROWNLEE, V L BROWN, O D BROWN, H H BROWN, G D BROWN, G, D,	8004220221* 8004250277* 8004070033 8004250273 8004300043	50-321 50-313 50-275 50-313 40-4492	G G G
BDNNEVILLE,R B BONZON,L L. BODK,H E BOOK,H E	8004210118 8004240464 8004240505 8004100056* 8004100053	PR NUREG 50-274 P 70-25 70-25	BRADLEY, E J BRADLEY, E J BRADLEY, E J BRADLEY, M	8004150267 8004150470 8004170246 8004170252* 8004100582*	90-171 I 50-277 I 50-277 P 50-277 P 50-320 H	BROWN, S C BROWN, S C BROWN, O F BROWN, O F, BROWN, M S	8004010465 8004020157 8004210353 8004210361* 8004230432*	50-404 50-404 PR PR 50-316	G R B
BOOK, H, E BOOK, H, E BOOK, H E BOOK, H E BOOK, H E	8004030247# 8004210248# 8004040055# 8004210241# 8004040054	50-278 0 50-312 0 50-312 0 50-312 0 50-312 0	BRAMLETT,L,S BRAMLETT,L,S BRAMLETT,L,S BRAMLETT,L,S BRAMLETT,L,S	8004140333* 8004150641* 8004140360* 8004150549* 8004210220*	50-313 8 50-313 8 50-313 8 50-313 8 50-313 R	BROWN, B C BROWN, B C BROWN, B C BROWN, B C BROWN, B C	8004220641 8004220234 8004220379 8004220611 8004300415	50-337 50-404 50-338 50-404 50-404	P A Q 8
800K, H E 800K, H, E 800K, H, E, 800K, H, E, 800K, B A	8004210020# 8004110543 8004110550# 8004210231 8004250047	50-320 Q 50-243 Q 50-243 Q 50-312 Q NUREQ	BRAMLETT, L 8 BRAMLETT, L, 8 BRAMSON, L BRAND, W, E BRANDON, R J	8004230473* 8004270385* 8004300073* 8004280004 8004070476*	50-313 8 50-313 8 50-387 0 50-395 M 50-293 P	BROZ.R E BRUGGER.R M BRUNE.J N BRUNNER.E J BRUNNER.E J	8004100423 8004300505 8004210325* 8004280070* 8004070120*	70-754 70-754 50-275 50-334 50-322	Q P Q
BOOKE, B. L. BOOKE, B. L. BOOKER, M. K. BORCHELT, M. L. BORDENICK, B. M	6004210388* 6004210388* 6004170329 6004230007* 8004070192	40-1162 40-1162 NUREQ 50-445 M 50-320 Q	BRAY,T C BRAYMAN,K W BREED,A BREED,A BRESLER,B	8004220558 8004210307* 8004150280* 8004150270 8004040070*	50-111 R TOPREP TOPREP TOPREP 50-344 T	BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8004160137* 8004070247* 8004040168* 8004040407 8004090131	50-293 50-219 50-334 50-293 50-213	G G G

	ACCESSION	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR BRUNNER, E J	#UMBER 80041501594 8004100072 8004090417 8004090448 80042100454	50-277 0 50-277 0 50-322 0 50-219 0 50-213 0 50-309 0	BURCHETTE. W H BURCHETTE. W H BURCHETTE. W H GURDETTE. T E BURDETTE, T E	8004090427 8004240061 8004240071* 8004160062* 8004300493*	50-445 M 50-445 M 50-445 M 90-553 0 50-375 0	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8004220753 8004220698 8004220649 8004220646 8004220742	50-327 8 50-327 8 50-260 8 50-259 8 50-259 8
BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8004210059 8004210146 8004170288 8004210439 8004160145	50-244 0 50-322 d 50-272 d 50-219 d 50-293 0	BUPGESS.D BURGIN.R E BURI.R A BURN.P BURNETTE.G W	8004140388 8004020274* 8004080679 8004180076 8004150063	50-320 H 40-2061 RES 50-201 F RES	CALHOUN, J R	8004250396 8004280593 8004290311 8004290435 8004290515	50-259 8 50-259 8 50-327 8 50-327 8 50-327 8
BRUNKER, E U BRUNNER, E U BRUNNER, E U BRUNKER, E U BRUNNER, E U	80042801304 8004180138 8004070114 8004070238 8004180318	50-272 Q 50-245 Q 50-322 Q 50-219 Q 50-320 Q	Burnette.g W Burns, 5 G Burns, D Burns, 5 A Durns, 6 G	8004170287 7911050375 8004080156 8004080062 8004080067*	RES 1196 50-387 9 50-255 0 50-255 0	CALLAN, L. J CALLENDINE, G. W CAMM, F CAMM, F CAMPBELL, E. R	8004100335# 8004220644# 8004070188# 8004030024 8004140398#	F01A 50-324 F 50-320 0 50-369 A
GRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J GRUNNER, E J	8004070469 8004070118 8004160183 8004160125 8004280111	50~293 Q 50~245 S 50~277 Q 50~293 Q 50~272 Q	Burns, S. C. Burns, S. C. Burns, S. C. Burns, S. C. Bursey, B.	8004080006 8004170258 8004170258* 8004210232 8004070002	50-255 0 50-255 0 50-255 0 50-255 0 FD1A	CAMPBELL, M CANTER, H L CANTERL, F B CANTRELL, F B CANTRELL, F S	7909290207* 8004300453* 8004100151* 8004100506* 8004040125*	FOIA 50-312 Q 50-312 Q 50-546 Q 50-416 Q
DRYAN, S E BRYAN, S E DRYANT, J C BRYANT, J C BRYANT, J C	8004220214* 8004220593* 8004020029 8004040424* 8004040174	FOIA FOIA 50-395 Q 50-424 Q 50-259 Q	BURSTEIN, S BURSTEIN, S BURWELL, S B BUSCHBACH, T C BUTCHXG, P R	8004010223 8004270428 8004070053 8004230307* 8004330054*	50-266 0 50-266 F 50-445 F NUREO 50-387 0	CANTRELL, F S	8004090400* 8004230046* 8004160062* 8004160072* 8004210121*	50-370 & 50-353 Q 50-327 Q 50-327 P
CTMAYRD CTMAYRD CTMAYRD CTMAYRD CTMAYRD CTMAYRD CTMAYRD	8004100481 8004070158* 8004040084 8004040203 8004040201	50~546 0 50~438 0 50~416 0 50~566 0 50~416 0	CADWELL, J J CADWELL, J J CADWELL, J J	7902040388* 8004070108 8004020050 8004300032 8004240460	915C 50-596 G 50-166 H RES RES	CANTRELLIC E CAPHTON, D L CAPRA, R A CAPRA, R A CARFAGNO, S P	8004210151# 8004250368 8004180470 8004070042#	50-322 0 50-269 P 50-269 P 50-271 P
BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	8004070071* 8004070384 8004070388 8004100045 8004020188*	50-400 0 50-518 0 50-438 0 50-416 0 50-424 0	Cadhell, V J Cahill, W J Cahill, W J Cahill, W J	8004150021 8004180389 8004080254 8004300009* 8004080410	RES 50-247 P 30-247 Q 50-387 Q 50-247 P	CARFAGND, S P CARLEGN, R T CARLEGN, R T CARLEGN, R T CARLEGN, R T	8004080494 7812110287 8004070109* 8004070282* 8004230079*	50-387 0 50-443 0 50-245 0 50-382 0
BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	2004090284 2004090351 2004090346 200423009 2004230036	50-348	CAHILL, W J CAHILL, W J CAHILL, W J CAHILL, W J CAHILL, W J	8004080417 8004210255 8004220589 8004220627 8004240410	50-247 P 50-247 P 50-247 P 50-247 P 50-247 P	CARLEDN, R T CARLEDN, R T CARLEDN, R T CARLEDN, J C CARLEDN, R T	9004100158# 8004100103# 8004070385# 8004100303# 8004090395	50-387
DRYANTIJ C DRYANTIJ C BRYANTIJ C DRYANTIJ C DRYANTIJ C	8004080122 8004070315* 8004110503 8004110572 8004160057	50-338	Cahilly J Cahilly J Cahilly J Cahilly J Cahilly J	8704210249 8004300429 8004300307 8004300416 8004300419*	50-3 R 50-247 P 50-247 P 50-247 P 50-247 P	CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T	8004150137 8004070435 8004100077 8004100276* 8004100533	50-352 0 50-352 0 50-410 0 50-482 6
BRYANT, J. C.	8004160066 8004070039* 8004300100* 8004210116 8004210175*	50-327 Q 50-400 Q 50-546 Q 50-566 Q 50-269 Q	Cahill W J Cain, C L Cain, C L Caldwell, J J Caldwell, R A	8004300411 8004300081* 8004210020* 8004150020 8004070036*	50-247 P 40-4492 50-220 0 RES 50-285 G	CARLEON, R T CARLEON, R T CARLEON, R T CARLEON, R T	8004100980 8004070432 8004180327 8004180508 8004070213	50-443 0 50-219 0 50-307 0 50-245 0
BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	8004220215 8004280174 8004210242* 8004210247* 8004160118*	50-413 Q	CALDHELL, R A CALHOUN, F L CALHOUN, J R CALHOUN, J R CALHOUN, J P	8004270011* 7903170090 8004020365 8004010375 8004010379	50~298	CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, J P	8004090127 8004070102 8004070314 8004210003 8004210194*	50~443 & 50~355 8 50~423 @ 50~243 @
BRYANT, J C BRYAN, J K BRYANT, J C BRYANT, J C BRYAN, J K	8004300484* 8004110327* 8004280079 8004240430* 8004030208	50-483 G 50-261 G	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J P CALHOUN, J R	8004010360 8084010393 8004010433 8004010451 8004010460	50-327	CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8004070379 8004100038 8004080109 8004100132 8004100606	50-387 G 50-4443 Q 50-354 8 50-354 G 50-423 8
BRYAN, J. K BUCHANAN, C R BUCHANAN, C R BUCHANAN, J P BUCHHOLZ, R H	8004040362 8004220517* 8004220512* 8004180337* 8004080455	F01A 50-390 R	Calhoun, J R Calhoun, J, R Calhoun, J R Calhoun, J R Calhoun, J R	8004010464 8004010487 8004010502 8004070288 8004070418	50~327 8 50~259 8 50~327 8 50~260 8 50~327 8	CARLBON, R T CARLBON, R, T CARLBON, R T CARLBON, R T CARLBON, D D	8004100611 8004100094 8004300602 8004230059 8004280277*	50-311 B 50-387 0 50-293 0 50-352 0 50-377 0
BUCHHOLZ,RH BUCHHOLZ,RH BUCHHOLZ,RH BUCHHOLZ,RH BUCHHOLZ,RH	800407031 <i>6</i> 8004020254 8004150353 8004280504 8004270448	TOPREP TOPREP TOPREP TOPREP TOPREP	Calhoun, J R Calhoun, J R Calhoun, J R Calhoun, J R Calhoun, J R	8004080519 8004080616 8004090333 8004090429 8004090453	50-327 8 50-327 8 50-327 8 50-327 8 50-327 8	CARLBON, R T CARLBON, R T CARNEY, J A CARNEY, J A, CARR, H	8004280171 80043300282 8004090387 8004090387 8004140419	50-354 S 50-410 Q 50-445 M 50-445 M PR
BUCHOLZ, R H BUCKALEH, W H BUCKEY, B C BUCKE, N BUDNITZ, R, J	8004220497 8004240505 8004140016 8004020048 8004080215		CALHOUN.JR CALHOUN.JR CALHOUN.JR CALHOUN.JR	8004150515 8004180460 8004140428 8004140433 8004150528	50-240 8 50-327 8 50-327 8 50-240 8 50-327 8	CARRIB E CABRIERIM J CARRICKIJ GABRIERIW B GARROLLID E	8004070100* 8004070136 8004010227 8004170282 8004100089	70-2786 50-294 P 70-2909 URQ
BUDNITZ, R J BUFFINGTON, D E BUFL, T BUFL, T BULISCHECK, T S	8004300601 8004170221 8004070240 8004020182 8004040457	* 50-317 S UASTE MOT UASTE MOT	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8004150539 8004150573 8004180399 8004180451 8004180452	50-327 8 50-259 8 50-327 8 50-260 6 50-296 8	CARROLL, D. E CARROLL, D. E CARROLL, D. E CARROLL, D. E CARROLL, D. E	800410086 8004100146 8004150150 800408086 800408087	DR0 50-10 G 50-10 G DR0 50-10 G
BULISCHECK, T BULLUCK, J B BURCHETTE, W, H BURCHETTE, W H BURCHETTE, W H	8004080074 8004110466 8004080018 8004080018 8004090427	TOPREP 50~445 II 50~445 M	CALHOUN, J R GALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8004150\$25 8004150500 8004150523 8004150554 8004220715	50-259 S 50-327 S 50-259 S 50-327 B 50-327 S	CARROLL, D E. CARROLL, D E CARROLL, D E CARROLL, D E CARROLL, D E	8004080572 9004180395 8004220410 8004230304 8004230308	50-10 % ORG 50-10 % ORG

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CARROLL, D E	8004220154 8004220161 8004220179 8004220203 8004270416*	GRO 50-10 G 50-10 G GRO 50-318 8	CHESKOR C CHESTER, R D CHESTER, R D CHIANGIN J CHIANGIN J	8004220466* 8004040369 8004140095 8004170047 8004170053	50-346 S RES RES 50-400 A 50-400 S	CLAYTON, F L	8004080029* 8004110003 8004010507 8004010425 8004030212	50-348 Q 50-348 S 50-348 P 50-348 R
CARSON, G B CARTER, R S CARTER, R S CARTER, K W CARTER, K W	8004080070* 8004070174* 8004100007* 8004100537 8004140074	50-150 I 50-184 Q 50-184 Q 50-289 G 50-289 G	CHILDS'M A CHIFDS'M A CHIFDS'M A CHIFDS'M A	8004030278* 8004030218* 8004090440* 6004220771* 8004280559*	50-333 S 50-333 S 50-333 S 50-333 S 50-333 S	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8004080403 8004030192 8004070267 8004080492 8004080657	50-348 P 50-348 P 50-348 F 50-348 R 50-348 P
CARTER,K W CARTER,K W CARTER,K W CARTER,K W CARTWRIGHT,J E	8004140077* 8004140080* 8004140084* 8004210453 8004280030	50-287	CHILK, S J CHILK, S J CHILK, S J	8004270511# 8004270482* 8004070165 8004040268 8004100388	50-333	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8004080651 8004080540 8004160242 8004100330 8004150447	50-348 P 50-348 S 50-364 S 50-364 A 50-348 P
CARTWRIGHT, W R	8004010505* 8004030221* 8004030226* 8004080536* 8004030238*	50-338 6 50-338 5 50-338 5 50-338 5 50-338 R	CHILK,8 J CHILK,8 J CHILK,8 J CHILK,8 J	8004170355 8004070143 8004080681 8004090206 8004140068	PR 50-556	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8004300594 8004220729 8004150426 8004250401 8004280434	50-34B G 50-34B S 50-34B R 50-364 G 50-34B P
CARTHRIGHT, W R	8004070307 8004070309* 8004220446 8004220653* 8004280549	50~338 8 50~338 9 50~338 8 50~338 8 50~338 8	CHILK,S J CHILK,S J CHILK,S J CHILK,S J	8004140072* 8004140124* 8004140128* 8004140133*	PRM PRI1 PRIM PRM PRM	CLAYTON, F L CLAYTON, F L CLEMENSON, F CLEMONS, P CLEMONS, P E	8004270284 8004270367 7905140144 8004280300* 8004070401*	50-348 P 50-348 S MISC 50-293 G 70-364
CARTHRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W R CARUSO, R, CARUSO, R	8004280554* 8004280604 8004280608* 8004100161 8004100171	50-338 8 50-338 9 50-338 8 50-213 P 50-245 P	CHILK, B J CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8004140139* 8004140140* 8004140145* 8004150043* 8004100597	PRM PRM 50-272 G XPORTLIC	CLEMONS, P CLEVELAND, J C CLEVELAND, J C CLINE, W E	8004070358# 8004210087# 8004170274 8004280024 8004110129	50-293 G 70-1143 RES NUREG PR
CABARO, R CABE, E O CABE, E O CASEY, S B CABEY, B B	8004140449* 8004070063* 8004230014* 8004080228 8004090188	50-456 A 50-281 G 50-266 G PR PR	CHILK, S J CHILK, B J CHILK, B J CHILK, B J	8004070045 8004080548 8004250011* 8004070454 8004240130	50-443 G 50-275 G 50-556 G 50-275 G XPORTLIC	CLINTON, B CLODFELTER, M COCHRAN, T B COCHRAN, T B COFFIN, J	8004080682 8004020237* 8004270184 8004210352 8004070016	PR State Prog FOIA 70-143 FOIA
CABEY, 8. B CAREY, T & CATALAND, G, R CATCHPDLE, G J CATCHPDLE, G J	8004090194# 8004080713 8004080092 8004030001 8004240563	PR F01A 40-2041 40-8745 40-8745	CHILK'S T CHILK'S T CHILK'S T CHILK'S T	8004150073 8004210165 8004210168 8004210174 8004210180	50-3 G 50-486 G 50-275 G 50-407 G 50-400 G	COGGIN, C L COGGIN, C L COGGIN, C L COGGIN, C L	8004070324* 8004070283* 8004110476* 8004110483* 8004150481*	50-366 S 50-366 S 50-366 S 50-366 S
CATTON.I. CELLIER.F CERNE.A C CERNE.A C CERNE.A C	8004080631* 8004180090 8004300309* 8004090441* 6004219011*	ACRB 70-2909 50-410 G 50-443 G 50-423 G	CHILK'S J CHILK'S J CHILK'S J CHILK'S J	8004280165 8004280178 8004280222 8004240374* 8004240452*	50-443	COGOIN, C L COGOIN, C L COGOIN, C L COGOIN, C COHEN, A F	8004150572* 8004220671* 8004280419* 8004280447* 8004150074	50-366 S 50-366 S 50-366 S 50-366 S NUREG
CHAIFETZ, D H CHANANIA, F D CHANANIA, F D CHANANIA, F CHANANIA, F D	8004270161 8004020149 8004020164# 8004020198# 8004080559	FDIA 50-445 M 50-445 M 50-445 M 50-445 M	CHILSON, V. T CHILSON, V T CHILSON, V T CHILSON, V T CHILSON, V, T	8004240356* 8004240474* 8004240459* 8004240363* 8004240444*	50-250 R 50-250 R 50-250 R 50-250 R 50-250 R	COHEN, I COHEN, I COHEN, W COHN, W COHN, D B	8004070207# B004100030* B004210104# B004240435 B004010294	70-1100 70-820 70-971 50-309 H 50-367 G
CHANANIA, F D CHANANIA, F D CHANANIA, F D. CHANANIA, F CHANANIA, F	8004030347 8004080172 8004180167* 8004240061 8004150157	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	CHILSON, V T CHILSON, V T CHILSON, V T CHILSON, V T	8004240446* 8004240440* 8004240422* 8004230332* 8004230470*	50-250 R 50-250 R 50-250 R 50-250 R 50-250 R	COHN, D B COLEMAN, E G COLEMAN, L R COLL, N A	8004010300* 8004040207 8004090008* 8004210353 8004020265*	50-367 G 50-272 G 50-272 G PR 50-367 G
CHANANIA: F D CHANANIA: F D CHANDLEY: C A CHANDLER: L J CHANDRA: V	8004170347 8004270227 8004100294 8004020462 8004290474*	50-445 M 50-445 M PR 50-361 H TOPREP	CHILBON, V T CHILBON, V T CHILBON, V T CHILBON, V T	8004230326* 8004180528* 8004180530* 8004180374* 8004080239	50~250 R 50~250 R 50~250 R 50~250 R 50~250 G	COLLING, C COLLING, C COLLING, R COLLING, R	8004020265* 8004020005 8004170330 8004140197* 8004040140*	50-387 G 50-387 G 50-250 G 50-10 U 50-247 G
CHANDRABEKARAN CHANDLER.L J CHANDLER.L J, CHAPLIN.8 D CHAPLIN.8 D	8004140340+ 8004070445 8004150226 8004040344+ 8004040349*	50-10 R 50-320 0 50-320 0 50-320 B 50-320 B	CHONIN, N CHONIN, N CHRIBTA-MARIA CHRIBTOFFER, O CHRIBBOTIMOS, N	8004080239 8004240086 8004140031* 8004040047* 8004080625*	50-250 0 50-250 0 50-155 H 70-143 50-254 0	COLLINS' 1 L COLTINB' 1 L COLTINB' 1 L COLTINB' 1 L	6004170336 6004070103 6004100579 6004080121 8004020072	NUREQ 50-320 S 50-320 P 50-320 P 50-320 S
CHAPLIN, 8 D CHAPLIN, 8 D CHAPMAN, K. R CHAPMAN, L CHAPMAN, L. D	8004140377# 8004250389# 8004220551# 8004150078 8004150046	50-320 B 50-320 B FOIA NUREQ RES	CHRISTOFFER, O CHRISTMAN, J IX CHRISSOTIMOS, N CHRISSOTIMOS, N CHRISTMAN, J N	8004080640* 8004080692 8004080573 8004030110 8004250381	50-263	COLLINS.D M COLLINS.J T COLLINS.J T COLLINS.P F COLLINS.J T	8004020067 8004020094 8004020077 8004070048 8004020097	50-287 P 50-320 S 50-320 S 50-334 V 50-320 B
CHAPMAN, L D CHAUDHARY, 8 CHAULA, T. C CHECKER, J CHEN, M J	8004300574 8004070438* 8004100571 8004210310* 8004150326	REB 50-352 G NUREO 50-10 H NUREO	CHRISTENBURY, E CHRISTENBURY, E CHRISTNER, R B CHUNO, J CHURCH, F	8004080246 8004280037 8004230517 8004160146* 8004080323*	50-358 A 50-282 H 50-334 J 50-293 Q COMMISSION	COLLINS, P F COLLINS, J T COLLINS, J T COLLINS, J T	8004030257 8004100496 8004170344 8004100385 8004100502	50-272 V 50-320 P 50-320 R 50-320 P 50-320 P
CHEN, M. J. CHEN, J. G CHERN, W. S CHERRY, M. M CHERRY, M. M	8004290017 8004040027 8004070145 8004020033 8004080435*	NUREG RES RES 50-454 G 50-454 G	CIESZKIEWICZ, B CLARK, K H CLARK, M CLARK, D CLARK, C W	8004150387* 8004220358* 8004080169 8004020353* 8004020267	50-10 R 50-259 P 50-367 H 50-265 S TOPREP	COLLING.P F COLLING.S T COLLING.S T COLLINS.S T	8004100420 8004150158 8004250102 8004280230 8004280244	50-287 V 50-273 V 50-320 P 50-320 R 50-320 P
CHERRY, M M CHERRY, M. M. CHERRY, M. M CHERRY, M. M CHERRY, M M	8004070177 8004020033 8004080429 8004080435* 8004070177	50-454	CLARK: 8 CLAUNCH: A CLAY: E L CLAY: E L CLAYTON: F L	8004220596* 8004080650 8004090244* 8004040117* 8004100096	50-295 5 XPORTLIC 70-143 70-143 50-348 Q	COLLINS, J T COLLINGS, D M COLLINS, J T COLLINS, J, T COLLINS, P F	8004280558 8004140430 8004300273 8004240498 8004280177	50-320 H 50-269 P 50-320 P 50-320 P 50-250 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBS I DN NUMBER	SUBJECT CATEGORY
COLLINS.J T COLLOPY.T J COLOMBO.P COLOMBO.R W COLOMBO.R W	8004300303 8004090154 800429007 8004070316* 8004160270*	50-320 P 70-371 NUREO 50-312 S 50-312 R	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8004070218* 8004040066 8004100608* 8004090466 8004140129	50-245 Q 50-213 P 50-423 S 50-336 Q 50-245 Q	CREMS, E H CREMS, E H CREMS, E H CRISCIONE, J L CRISCIONE, J L	8004150548 8004280498 8004220455 8004010429* 8004170199*	50-395 B 50-395 B 50-395 Q 50-336 B 50-336 B
COLOMBO.R W COLOMBO.R W COLOMBO.R W COLOMBO.R W	B004140405# B004210262# B004290491# B004290465# B004100051#	50-312 5 50-312 5 50-312 5 50-312 5 50-416 0	COUNSIL.W C COUNSIL.W O COUNSIL.W O COUNSIL.W O	8004110012 8004100417 8004030261 8004030293 8004210411	50-213	CRNICH, J CRNICH, J CROCKER, H W CROCKER, H W	8004010347* 8004070310* 8004280605* 8004210145* 8004040213*	50-382 8 50-382 8 50-382 8 70-1100 70-82
COLON, J E COMPAS, W J COMPTON, R M CONICH, J CONKLIN, J C	8004240360* 8004080363* 8004080127* 8004250352* 8004280024	50-424 0 QA999 50-33B 0 50-382 8 NUREG	COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G	8004250132 8004290057 8004030211 8004020345 8004020331	50-213 Q 50-245 Q 50-213 Q 50-213 P 50-245 P	CROCKER.H W CROCKER.H W CROCKER.H W CROCKER.H W CROCKER.H W	8004280300* 8004070401* 8004100014* 8004210222* 8004070358*	50-273 0 70-364 50-184 0 70-135 50-273 0
CONLON, T E	8004040430* 8004070392* 8004110575* 8004070043* 6004220221*	50-424 0 50-438 0 50-395 0 50-400 0 50-321 0	COUNSIL.W G COUNSIL.W G COUNSIL.W G	8004030215 8004040249 8004040306 6004070265 8004040331	50-245 P 50-336 P 50-245 P 50-213 P 50-213 R	CROCKER.H W CROCKER.H W CROCKER.H W CROCKER.H W CROCKER.H W	8004300244* 8004100234* 8004080282* 8004210089* 8004160098	50-244 0 50-201 0 50-333 0 70-1143 70-1251
CONLON.T E CONNER.D E CONNER.T B CONNER.E L CONNER.T B	8004240434* 8004040234* 8004080409 8004070138 8004030338	50-491 Q 50-320 H ' 50-375 Q 50-336 P 50-358 Q	CONVEIT'N C CONVEIT'N C CONVEIT'N C	8004040205 8004150487 8004030232 8004020408 8004080309	50-245 R 50-213 R 50-336 P 50-213 F 50-336 P	CROCKETT, J CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A	8004180411* 8004180218* 8004140047* 8004160050* 8004220244*	50-336 8 50-498 G 50-498 G 50-445 G
CONNER, T B CONNER, E L CONNELL, C CONNER, T B CONNER, T B	8004030338 8004170318* 8004180434* 8004220156 8004220156	50-358 C 50-317 F 50-286 R 50-358 G 50-358 C	COUNSIL.W O COUNSIL.W O COUNSIL.W O COUNSIL.W O	8004070274 8004110457 8004150297 8004180346 8004140375	50-213 P 50-245 P 50-213 P 50-213 P 50-245 Q	CROSSMAN,W A CROSSMAN,W A CROUSE,R P CROUSE,R P CROUSE,R P	8004300035* 80042500B3* 8004020135 8004070424* 8004040455	50-498 Q 50-445 Q 50-346 Q 50-346 Q
CONNOR,W CONNOR,R J CONSTABLE,G L CONTE,R J CONTE,R J	8004070168* 8004230190* 8004040025 8004070103 8004020072	PR 50-3 H 50-298 8 50-320 S 50-320 8	COUNSIL, W C COUNSIL, W C COUNSIL, W C COUNSIL, W C	8004170012 8004180224 8004170012 8004230413 8004230299	50-213 P 50-213 P 50-213 P 50-423 A 50-213 F	CRDUBE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8004100091* 8004010419 8004080514 8004300617 8004180333	50-346 P 50-346 P 50-346 P 50-346 P 50-346 F
CONTE,R J CONTE,R J CONTI,L L CONTRELL,F S CONWAY,W F	8004020094 8004020077 8004100074 8004080563 8004010256	50-320 8 50-320 5 FR 50-438 8 50-271 P	CONNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8004220364 8004240373 8004250362 8004270442 8004270651	50-336 P 50-245 P 50-245 P 50-213 P 50-245 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8004220534 8004220457 8004250376 8004280380 8004280456	50-346 P 50-346 P 50-346 P 50-346 I 50-346 F
CONHAY, W F CONHAY, W F COOK, K W COOK, R J	8004080238 8004110190 8004110465 8004210307* 8004040475*	50-271 P 50-271 P 50-271 F 10PREP 50-329 G	CDUNSIL,W O CDURCHAINE,R J CDWAN,B Z CGWOILL,M O COX.E L	8004280465 8004150531* 8004280036 8004290371* 8004140179	50-213 P 50-315 P 50-574 Q 50-537 A REGGD	CROW, W T CROW, W T CROW, W T CROW, W T CROW, W T	8004150115 8004150118* 8004220018 8004240217* 8004040207	70-1287 70-1257 70-135 90-438 A 70-82
COOREY, M J COOKEY, M J COOKEY, M J	8004210306# 8004100056# 8004250302 8004070311 8004150560	TOPREP 70-25 71-6144 50-278 S 50-277 S	COX,E L COX,T H CRANDELL,J D CRANE,P A CRANE,P A	8004180532 8004100213 8004030138 8004040131 8004010436	REGOD TOPREP PR 50-275 B 50-275 A	CROW, W T CROW, W T CROW, W T CROW, W T CROW, W T,	8004020193 8004020070 8004160104 8004150305* 8004240159*	70-1100 70-1151 70-1151 70-820 70-143
COONEY, M J COONEY, M J COONEY, M J COOPERSTEIN, R COOPERSTEIN, R	8004170228 8004220547 8004270423 8004020160 8004110168	50-277 R 50-171 P 50-277 P 40-8502 40-8502	CRANE, P, A CRANE, P A CRANE, P A CRANE, P A CRANE, P A	8004080466 8004040281 8004080481 8004100233 8004150337	50-275 A 50-275 A 50-133 S 50-133 I 50-275 A	CROWLEY, B R CROWLEY, C J CRUMLEY, J J CRUMLEY, S C	8004180098 8004040208* 8004140478 8004280267 8004020139	70-2707 50-566 & NUREO 50-320 H NUREO
COOPER.S COPELAND.J G COPELAND.J G COPELAND.J G	8004150427 8004080244 8004020208 8004020208 8004240188	50~280 D 50~466 Q 50~445 M 50~445 M 50~466 Q	GRANE,P A GRANE,P A GRANE,P A GRANE,P A GRANE,P A	8004140253 8004170076 8004150343 8004220406 8004220492	50-275 A 50-275 A 50-275 A 50-275 A 50-275 A	CULP.R H CULP.R H CULP.R H CULP.R H CULVER,M W	8004020136 8004020136 8004220003 8004220003 8004210240*	50-49B G 50-49B G 50-466 G 50-302 R
COPELAND, J Q COPELAND, J Q COPELAND, J Q COPELAND, J Q COPELAND, R L	8004240188 8004220003 8004220003 8004180167* 8004290364	50-466 0 50-466 0 50-466 0 50-465 M 50-537 A	CRANE.P A CRATER.J CREE.R E. CREWS.J L CREWS.J L	8004280373 8004070024 8004030334 8004100282* 8004070175	50-275 A 50-352 H 50-387 H 50-344 G 50-275 G	CUNNINOHAM, M E CUNNINOHAM, A L CUNNINOHAM, O E CUNNINOHAM, A L CUNNINOHAM, O E	8004210278 8004040365* 8004250284 8004070134* 8004250084	NUREQ 50-250 Q 71-5939 50-339 Q 71-5971
COPPLAND, R L COPPER, W E CORDANI, R A	8004150473 8004210066 8004070153	50-537 A 71-381 70-27 50-483 Q 50-320 R	CREWS.J L CREWS.E H CREWS.E H CREWS.J L	8004180521 8004300439* 8004020292 8004140174 8004210189	50-344 0 50-312 0 50-395 8 50-395 8 50-243 0	CUNNINGHAM, 0 E	8004010061 8004020129 8004090195* 8004080217 8004080286	71-9049 71-5939 50-338 Q 50-183 R 50-18 R
		50-320 R NUREO J J	CREWS,E H CREWS,E H CREWS,E H CREWS,E H	8004020321 8004220049 8004210226 8004040447 8004100359	50-395 S 50-395 S 50-312 Q 50-395 Q 50-395 Q	CUNNINOHAM, Q E	8004080308 8004080348 8004070398 8004070317 8004170044	50-73 R 50-70 R 71-380 50-18 J 50-73 P
			CREWS.J L. CREWS.J L. CREWS.J L CREWS.E H	8004100264 8004280080 8004280272 8004280214 8004170004	50-344 0 50-344 0 50-397 0 50-312 0 50-395 8	CUNNINOHAM, Q E CURRAN, J M CURRAN, J M CURRAN, J, M CURRAN, J M	8004300052 8004080539 8004180454* 8004150345 8004210287*	50-70 P 50-204 B 50-204 B 50-204 R 50-204 B
			CREWS,E H CREWS,E H CREWS,J L CREWS,E H	8004300561 8004020078 8004030175 8004300425 8004150501	50-375 8 50-375 K 50-375 K 90-312 0 50-375 8	CURRAN, J M CURRAN, J M CURRERI, J CURTIB, J R CURTIB, N W	8004230335 8004250420* 8004240564 8004110550* 8004080516	50-206 B 50-206 B NUREO 50-243 Q 50-387 B

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, A P	8004080363 8004140352 8004270374 8004300374 8004150431	50-387 S 50-387 A 50-387 B 50-387 S 50-124 P	DANIELBON, D H DANIELBON, D H DANIELB DARMITZEL, R U DARMITZEL, R U	8004150476* 8004280039* 8004290406* 8004020185 8004170254	50-341 0 50-454 0 50-327 0 50-70 P 50-70 P	DENONCOURT, R F DENTON, H R	8004210366* 8004280375* 7908210247 7908140243 7909190514	50-320 P 50-10 H 50-320 H COMMISSION Misc
CURTNER, A P CURTNER, A P CURTNER, A, P CURTNER, A P CURTNER, A P	8003310411* 8003310415* 8003310417* 8003310421* 8003310427*	50-124 B 50-124 B 50-124 B 50-124 B 50-124 B	DAUGHERTY, T M DAVIDSON, D R DAVIES, L M DAVIE, F C DAVIS, F C	8004280036 8004230353 8004140354* 8004220485* 8004220622*	50-574 0 50-440 B 50-369 A FOIA FOIA	DENTON, H R DENTON, H R DENTON, M M DENTON, M M DENTON, M M	7910020843 8004100519* 8003310411* 8003310415* 8003310417*	MISC 50-320 0 50-124 B 50-124 B 50-124 B
CURTNER, A P CURTNER, A P CUTCHIN, J, M CUTCHIN, J M CUTCHIN, J M	8003310432* 8003310439* 8004100571 8004080347 8004090011	90-124 B 50-124 B 50-387 Q 50-289 G 50-289 O	DAVIS.F C DAVIS.J G DAVIS.F C DAVIS.J G DAVIS.J G	8004220482* 8004220282* 8004220480* 8004220468* 8004220469*	FOIA FOIA FOIA FOIA FOIA	DENTON, M M DENTON, H R	8003310421± 8003310427± 8003310432± 8003310439± 8004090306±	50-124 B 50-124 B 50-124 B 50-124 B SECY
M C.INIHOTUO N C.INIHOTUO M C.INIHOTUO M C.INIHOTUO M C.INIHOTUO	8004080004 8004080019 8004110016 8004150069 8004150273	50-289 G 50-289 0 50-387 0 50-387 0 50-289 0	DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B	8004040075 8004070172 8004040029 8004070157 8004040032	40-8135 50-373	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004240507* 8004020028* 8003250855 8004020217 8004040225	50-286 P 100FR MISC 50-320 H 50-320 H
CUTCHIN, J M CUTCHIN, J M CYPBERT, S B CYPHERT, B B CYPHERT, B B	8004170055 8004280246 8004020164* 8004020149 8004020181*	50-287 Q 50-387 Q 50-445 H 50-445 M 50-445 M	DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B	8004040392 8004040450 8004070131 8004040019* 8004100140	50-315 Q 40-2061 27-47 50-10 Q 50-10 Q	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004040247 8004040464* 8004070139 8004070142* 8004220417	50-320 H CGNTRAC T 50-275 G 50-275 G 50-409 G
CYPHERT, B B CYPHERT, B B CYPHERT, B B CYPHERT, B B CYPHERT, B B	8004020170# 8004020178# 8004020078 8004080557 8004090204	50-449 M 50-445 M 50-445 M 50-445 M 50-445 M	DAVIS.A B DAVIS.J F DAVIS.A B DAVIS.A B DAVIS.G R	8004100518 8004180389 8004040160 8004090319 8004080226	50-254 Q 50-247 P 50-331 Q 50-2 Q WASTE MOT	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004220422* 8004220430* 8004020454 8004020461 8004030019	50-409 G 50-409 G 50-320 H 50-320 H 50-320 H
CYPHERT, 8 B CYPHERT, 8 B CYPHERT, 8 D CYPHERT, 8 D CYPHERT, 8 D	8004110056 8004100218 8004100084 8004080028 8004080033*	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,J H	8004100372 8004100380 8004110259 8004230138 8004280255*	50-150 0 50-162 0 50-151 0 70-925 70-1319	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004030022 8004030035 8004030052 8004030061 8004030087	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H
CYPHERT, B D CYR, K D CYR, K D CYR, K D D'AMORE, M	8004100177 8004240230 8004230047 8004280077 8004100463*	50-445 M PR PR PR PR 70-1151	DAVIS,A B DAVIS,L D DAVIS,A B DAVIS,A B DAVIS,A B	8004070173 8004100235 8004030257 8004100067 8004100117	1&E 50-556 0 50-331 0 50-282 0 50-10 0	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004030123 8004040211 8004040214 8004040215 8004040218	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H
DAHLJH DAHLMAN,L C DAILJL C DAILJL C DAILJL C	8004180307 8004180307# 8004230085 8004220105 8004240426	XPORTLIC 50-306 G 50-488 G 30-491 G 50-491 G	DAVIB,A B DAVIB,A B DAVIB,G R DAVIB,A B, DAVIS,S H	8004040014 8004300544 8004240060 8004020477 8004010351*	50-10 Q 50-10 Q HASTE MOT 40-7127 50-310 S	DENTON, H R	8004040219 8004040220 8004040223 8004140036 8004140122	50-312 H 50-320 H 50-320 H 50-320 H
DALE, L F DALE, L F DALE, L F, DALE, L F DALE, L F	8004230070 8004170071 8004280517 8004280501 8004150568	50-416 G 50-416 B 50-416 B 50-416 S 50-416 B	DAVIS,8 M DAVIS,L D DAVIS,8 M DAVIS,L D	8004010368* 8004150098 8004150638* 8004210323 8004220371	50-310 S 50-556 0 50-318 B 50-317 S 50-275 0	DENTON H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004210275 8004220136 8004220159 8004030070 8004040202	50-546 H 50-320 H 50-320 H 50-320 H 50-320 H
DALE:L F DALE:L F DALE:L F DALE:L F DALE:L F	8004280484 8004280541 8004100362 8004210228 8004280520	50-416 S 50-416 S 50-416 H 50-416 A 50-416 B	DAVIS,8 M DAVIS,8 M DAWSON,D M DAWSON,D K	8004270350* 8004270447* 8004270484* 8004240267 8004140082*	50-318 8 50-317 8 50-317 8 70-1308 70-1308	DENTON, HR DENTON, HR DENTON, HR DENTON, HR DENTON, HR	8004040421 8004070129 8004020173 8004020218 8004020222*	50-320 H 50-155 H COMMISBION 50-389 O 50-389 Q
DALE, L F DALE, L F DALE, L F, DALE, L F, DALE, L F	8004280610 8004280481 8004170243 8004220421 8004280479	50-416 B 50-416 B 50-416 A 50-416 C 50-416 B	DAWEON, D M DAWEON, D M DAY, B D DE LAGUIL, P	8004180133 8004240277* 8004140073* 8004180472* 8004280034	70-1308 70-1308 70-1308 50-243 8 NUREG	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004040005 8004040200 8004090061 8004080078 8004080083*	50-320 P 5ECY 50-320 P 50-295 Q 50-295 Q
DALE, L F DALTON, A T DALTROFF, B. L DALTROFF, B L DALTROFF, B L	8004280606 8004230082 8004160187* 8004100211 8004140064	50-416 8 50-356 0 50-277 0 50-277 0 50-277 0	DEAKYNE, K DEALE, V B DEANE, R H DEBNAM, J DEBNAM, J	8004220772* 8004080017 8004090187 8004220560* 8004220565*	50-346 8 50-522 0 50-312 0 50-111 R 50-111 R	DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004080088* 8004110077 8004020250 8004030112 8004070070	50-295 G MISC 50-275 H 50-309 H 50-483 H
DALTROFF,8 L DALTROFF,8 L DALTROFF,8 L DALTROFF,8 L DALTROFF,8 L	8004100261 8004010406 8004240402 8004240372# 8004270001	50-171 Q 50-277 P 50-277 P 50-277 Q NUREO	DEEDS,W E DEEQ.F H DEER.D A DECEN.O DELANEY.J L	8004280048 8004020219 8004220618# 8004210300* 8004240217#	NUREO 50-333 J FOIA 50-10 H 50-438 A	DENTON, H R	8004070075 8004140303* 8004090056 8004140111 8004140117*	50-327 H 50-309 U 50-320 O 50-320 G 50-320 G
DANCE, H C DANCE, H C, DANCE, H, C, DANIELSON, D W DANIELSON, D, H	8004150074* 8004150155* 8004070413* 8004280507* 8004040410*	50-321 Q 50-321 Q 50-327 Q TOPREP 50-263 Q	DELANEY, J C DELANEY, J C DELANEY, J C DELANEY, J C DELQEORGE, L D	8004040207 8004020485* 8004080570* 8004240159* 8004140213	70-82 50-364 A 70-143 70-143 50-373 I	DENTON, H R DENTON, H R. DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004210381 8004210376 8004220112 8004220168 8004220182	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H
DANIELBON, D. H DANIELBON, D. H DANIELBON, D. H, DANIELBON, D. H DANIELBON, D. H	8004070173# 8004040150# 8004030255# 8004040339# 8004080447#	50-483	DELOEDRGE, L D DELGEORGE, L D DELLA RATTA, A DELONG, 8 D DELONG, 8 D	8004010352 8004080522 8004100072* 8004230444* 8004230447*	50-373 F 50-373 K 70-364 50-315 S 50-315 S	DENTON, H R. DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004220185 8004240270 8004240441 8004250111 8004280260	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H
DANIELSON, D H DANIELSON, D H DANIELSON, L J DANIELSON, D H DANIELSON, L J	8004100130# 8004100207# 8004070181 8004280025# 8004020053	50-305 G 50-254 G 40-4492 50-265 G 40-4492	DENISE, R P DENNISON, A B DENNISON, A B DENNY, T L DENNY, T L	8004250004 8004100468 8004100468 8004180061 8004210348	TOPREP 50-358 9 50-358 9 40-2061 40-2061	DENTON, H R DENTON, H R. DENTON, H R DENTON, H R DENTON, H R	8004280273 8004280279 8004280289 8004280325 8004280327	50-320 H 50-320 H 50-320 H 50-320 H

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004280535 8004280542 8004290064 8004290076 8004140092	50-320 H 50-320 H 50-320 H 50-320 H MISC	DICEY, B B DICHARRY, R F DICKERSON, M H DICKS, N D DICKSON, H H	B004040102# B0040B0058 B0040B0602* B004040243 B004150036	40-8135 71-102 50-267 G PRM RES	DDLAN, J E DDLAN, J E DDLAN, J E DDLEMAN, C R	8004300611 8004080544 8004280378 8004230367 8004210361*	50-315 Q 50-315 F 50-315 Q 50-315 F PR
DENTON, H R	8004080047 8004210402 8004210354 8004210363 8004280342	50-307 P 50-320 H 50-320 H 50-320 H 50-320 H	DIETCH, R DIETCH, R DIETCH, R DIETCH, R	8004150141* 8004030141* 8004030140 8004080491 8004080498*	NUREG 50-206 P 50-206 P 50-206 P 50-206 P	DOMANUS, H M DOMANUS, H M DOMABHOVETZ, I DONALDSON, D DONALDSON, D	8004150326 8004270017 8004270474* 8004020141* 8004020138*	NUREG NUREG TOPREP ACRS ACRS
DENTON, H R DENTON, H R DENTON, H DENTON, H R DENTON, H R	8004280357 8004280550 8004280565 8004280565 8004140066 8004290054	50-320 H 50-320 H 50-320 H 50-344 F 50-3 H	DIETCH, R DIETZ, G R DIGGS, R M DIGGS, R M DIGGS, R M	8004140161 8004070220 8004070215 8004080201 8004240244	50-361 R 71-9 50-346 P 50-155 P 50-317 P	N C 'MAHONDO C G 'BAHOONDO C G 'BAHOONDO C 'BAHOONDO C 'MAHONDO C	8004070112* 8004100583 8004300007* 8004300002 8004160235*	70-1100 50-311 0 8ECY 8ECY 50-269 0
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004070056 8004150211 8004170292 8004170296* 8004180154	50-281 G 50-10 H 50-424 G 50-424 G 50-339 A	DIGGS.R M DIGOS.R M DIIANNI.D C DILLON.R L DIMEOLID.A F	8004160001 8004210036 8004210263 8004070093 8004080103*	50-269 P 50-244 P 50-289 F ACRS 50-193 I	DOPCHIE, H DOPCHIE, H DOPCHIE, H DOPCHIE, H	8004160240* 8004160219* 8004160244* 8004220147 8004110359	50-269 Q 50-269 Q 50-269 Q REGOD REGOD
DENTON, H R	8004240145 6004250056 6004250388 6004100574 8004100581	50-424 0 50-10 0 50-10 H 50-320 H 50-320 H	DINNEL.P A DIPIAZZA,R P DIRCKS,W J DIRCKS.W J DIRCKS.W J	8004020139 8004090046 7904110034* 7908150708 8004020169	NUREG 71-9009 PR MISC 40-1341	DOPSOVIC.D A DOPSOVIC.D A DOPSOVIC.D A DOPSOVIC.D A DORMITZEL.R U	8004020164* 8004020198* 8004100177 8004170340 8004170260*	50-445 M 50-445 M 50-445 M 50-445 M
DENTON: H R DENTON: H R DENTON: H R DENTON: H R DENTON: H R	8004100573 8004150317* 8004210320* 8004210336 8004150085	50-320 H 50-516 G 50-339 T 50-247 H 50-3 H	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8004080151 8004080193 8004240364 8004080212 8004080137	WASTE MOT 50-3 U 50-440 H 50-387 U 50-289 U	DOROUGH: R DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J	8004300013* 8004150206 8004080340* 8004100357* 8004070140*	50-387 Q FOIA CONTRACT CONTRACT CONTRACT
DENTON, H R	8004160173 8004170342 8004180510 8004210088 8004210173	50-3 H 50-3 H 50-302 H 50-3 H 50-3 H	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8004080260 8004070417 8004080254 8004080157 8004140071	50-409	DOUGHERTY, D J	8004040197* 800070007* 8004040494* 80001100037*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, KR DENTON, KR DENTON, KR DENTON, KR DENTON, KR	8004210208 8004250013 8004250018 8004180122 8004180126*	50-3 H 50-3 H 50-247 H 50-301 0 50-301 0	DIRCKS, H J DIRCKS, H J DIRCKS, H J DIRCKS, H J DIRCKS, H J	8004170348 8004140286 8004140297 8004140299 8004140374	PR 50~522 U 50-339 U 50-309 U 50-266 U	DOUGHERTY, D J DOUGHERTY, D J DDUGHERTY, D J DDUGHERTY, D J DDUGHERTY, D J	8004040162* 8004070485* 8004030023* 8004040217* 8004070032*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H R	8004180281 8004230185 8004270047 8004250036 8004280347	50-247 E 50-3 H 50-320 H 50-280 Q 50-369 И	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8004140252 8004140294 8004140183 8004140208 8004140235	50-358 U 50-266 U 50-10 U 50-10 U 50-409 U	DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J	8004100524* 8004100531* 8004040186* 8004100600* 8004240542*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON: H R	8004300078 8004230084 8004250283 8004300508 8004180431	50-336 P 50-320 0 50-320 H 50-320 0 50-320 H	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8004170301 8004180234 8004100431# 8004140459# 8004140169	50-409 H 50-3 H 10CFR 50-10 U 50-10 U	DOUGHERTY, J B L,YTREHOUDD B L,YTREHOUDD B L,YTREHOUDD B L,YTREHOUDD	8004240553* 8004150101 8004150101 8004280211 8004280211	CONTRACT 50-574 0 50-574 0 50-338 0 50-338 0
DENTON: H R DENTON: H R DENTON: K R DENTON: K R DENTON: K R	8004270200 8004240480 8004250232 8004280054 8004280159	50-339 A 50-286 P 50-247 P 50-286 P 50-311 A	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8004140225 8004180114 8004240528 8004150024 8004300292	50-10 U 50-289 H COMMISSION 70-1308 50-3 U	DOUGHERTY, J B DOYLE, R J DRAOONETTE, K B DRAOONETTE, K B DRAKE, F E	8004280211 8004240565 8004070410 8004070414* 8004220110	50-338 Q NUREQ 27-47 27-47 50-244 P
DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004280362 8004280384 8004220719* 8004280190 8004280195*	50-10 H 50-289 H 50-317 8 50-311 0 50-311 0	DISALVO DISALVO DISE.D P DISE.D P DISE.D P	8004220043 8004220059* 8004080415 8004090307 8004010330	71-379 71-379 50-220	DREEBEN, D R DREHER, F DREY, K DROMERICK, A W DROMERICK, A W	8004270520 8004220224 8004250062* 8004030179 8004100318	WASTE HOT 50-272 S 50-10 Q 50-339 A 50-339 A
DENTON: H R	8004280196* 8004300585 8004300590* 8004300598* 8004300046*	50-311 0 50-272 0 50-272 0 50-272 0 50-387 0	DISIBIO, R DISIBIO, R DISTEFANO, J DISTEFANO, J DITTO, S J	8004240077 8004240081* 8004210353 8004210361* 8004030291	State Prog State Prog PR PR ACRS	DROMERICK, A W DROMERICK, A W DROMERICK, A DROMERICK, A W DROMERICK, A W	8004140079 8004140033 8004240092 8004140016 8004250031	50-339 A 50-339 A 50-339 A 50-275 A 50-339 P
DETRICH, B F DEVINCENTIB, J DEVINE, J F DEVLIN, J W DEVLIN, J W	8004300023* 8004070106* 8004020283 8004070221* 8004210024*	50-387	DIVINE, J R DIVINE, J R DOAD, C V DODDS, R T DODDS, R T	8004270020 8004040210 8004280048 8004230270> 8004020180+	NUREG RES NUREG SO-440 G SO-528 G	DUBIN, K J DUBRY, N E DUBRY, N E DUBRY, N E	8004300042* 8004230189* 8004230157* 8004070192 8004040059	50-387 0 50-123 0 70-925 50-315 8 50-315 8
DEVLIN, J W DEVLIN, J W DEVLIN, J W DEVLIN, J W	8004100068* 8004100191* 8004210218* 8004250059* 8004210330*	50-334 @ 70-33 50-247 @ 50-213 @ 50-217 @	DODDS, R T DODDS, R T DODDS, R T DODDS, R T DODDS, R T	8004300121# 8004040161# 8004020062* 8004300278* 8004280180*	50-328 0 50-312 0 50-341 0 50-397 0 50-312 0	DUCKWORTH, J P DUCKWORTH, J P DUCKWORTH, J P DUGAN, D W DUGGINB, L	8004150062 8004230053 8004100217* 8004240505 8004240340	50-201 R 50-201 R 50-201 0 50-276 P 50-193 0
DEVLIN, J W DEVLIN, J DEVLIN, J DEVLIN, J DEVLIN, B,	B004230128* B004150193* B004280632 B004300552 B004040309	50-309 Q 70-371 50-320 8 50-293 8 50-155 P	DODDS,R T DODDS,R T DOHERTY,J F DOHERTY,J F DOLAN,J E	8004280074* 8004210428* 8004110551 8004240548 8004110445	50-460 Q 50-312 Q 50-466 Q 50-466 Q 50-315 R	DUMMER.O H DUMB.D DUNBAR.J.F DUNFERD.E F DUNN.C N	8004250043* 8004070266 8004270427* 8004160184* 8004070177*	CONTRACT PR 50-249 8 50-320 P 50-334 G
DEWITT, R B DEWITT, R, B DEYQUNG, R C DEYQUNG, R C DIAZ, N J	8004150398 8004150474 8004160004 8004160019* 8004220213	50-255 P 50-255 P 50-272 G 50-272 G 70-106B	DDLAN, J E DDLAN, J E DDLAN, J E DDLAN, J E	8004070411 8004210415 8004010325 8004010420 8004010486	50-315 0 50-315 P 50-315 P 50-315 P 50-315 P	DUNN, C N DUNN, C N DUNN, C N	8004100358* 8004040165* 8004070009 8004150221 8004110160	50-334 Q 50-334 Q 50-334 Q 50-334 Q

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT
DUNN'C N DUNN'C N DUNN'N W DUNN'N W	8004180062 8004180069* 8004010459 8004030201 8004040354	71-96 71-96 50-334 P 50-334 P 50-334 F	EISENHUT,D G EISENHUT,D G EISENHUT,D G EISENHUT,D G	8004100300 8004110510 8004110528 8004110534 8004110559	50-317 P 50-335 P 50-213 P 50-285 P 50-313 P	ENGELKEN, R H	8004180155 8004110007 8004230360 8004230364 8004230368	50-312
DUNN'C N DUNN'C N DUNN'C N DUNN'C N	8004110482 8004210283 8004220574 8004210261 8004270354	50-334 P 50-334 P 50-334 P 50-334 R 50-334 R	EISENHUT.D G EISENHUT.D O EISENHUT.D O EISENHUT.D O EISENHUT.D O	8004110570 8004240141 8004100607 8004230293 8004300055	50-309 P REVIEW GRP 50-344 G 50-344 G 50-259 P	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8004230370 8004230373 8004230374 8004230376 8004230379	50-397 0 50-528 0 50-133 0 50-344 0 50-275 0
DUNNING, G M DUTTON, D DUTTON, D DUTTON, D	8004080211* 8004080222* 8004070198 8004040420 8004020335	FOIA FOIA 50-424 Q 50-424 Q 50-424 B	EISENHUT.D G EISENHUT.D G EISENHUT.D G EL-ASHRY.M T EL-ASBRY.M T	8004300589 8004280287 8004280140 8004020447* 8004020385	50-206 P 50-286 H 50-3 H 50-327 S 50-390 A	ENGELKEN, R H	8004240503 8004250118 8004220170 8004220172 8004220176	50-206 P 50-397 A 50-528 Q 50-133 Q 50-275 Q
DUTTON, D	8004020187	50-424 Q	EL-ASHRY,M T EL-ASHRY,M T EL-ASHRY T EL-ASHRY,M T EL-ASHRY,M T	8004110425	50-390 A	ENGELKEN, R H	8004220179	50-344 Q
DUTTON, D	8004100348	50-424 Q		8004150551	50-327 P	ENGELKEN, R H	8004220190	50-312 Q
DUTTON, D	8004010349	50-424 5		8004150559+	50-327 P	ENGELKEN, R H	8004220195	50-206 Q
DUTTON, D	8004020370	50-424 5		8004150392	50-553 R	ENGELKEN, R H	8004220198	50-361 Q
DUTTON, D	8004240344	50-424 Q		8004180331	50-390 R	ENGELKEN, R H	8004220201	50-397 Q
BUTTON, D	8004140336	50-424 A	EL-ABHRY,M T	8004220533	50-259 P	ENDI, D	8004150049	NUREO
BUTTON, D	8004150421	50-425 8	ELD,M E	8004110143	PRM	ENDI, D	8004150078	NUREO
BUTTON, D	8004150427	50-424 8	ELGERT,D J	8004230129	XPORTLIC	ENTWISLE, E	8004030340*	COMMISSION
BUTTON, D	8004280491	50-424 8	ELGERT,D J	8004230133*	XPORTLIC	EPEL, L G	8004280071	RES
BUTTON, D	8004150427	50-424 8	ELGERT,D J	8004210026	XPORTLIC	EPLER, E P	8004030295	ACRS
DYER, J A DYER, J A DZIEWISZ, J S EARLY, P J EARLY, P J	8004070163* 8004280241* 8004240183* 8004230032* 8004010259	50-302	ELIASON, LR ELIN, JO ELKUS, RJ ELLENSHAW, LE	8004080400 8004020062* 8004300278* 8004170005 8004270212*	50-263 P 50-361 Q 50-397 Q 50-228 P QA999	ERB,C M ERICKSON,J R ERICKSON,L W ERICSON,D M ERNST,M L	8004100267* 8004010106* 8004040065* 8004150033 8004240253	50~329 Q 27-39 50~344 T NUREQ 50~320 H
EARLY,P J	8004010367	50-333 P	ELLERSHAW, L E	8004030244*	QA799	ERTLE,R F	6004280380	50-346 I
EARLY,P J	8004080381	50-284 P	ELLERSHAW, L E	8004130149*	QA999	ERVIN,P E	8004250306	PR
EARLY,P J	8004080473	50-333 P	ELLERSHAW, L E	8004300222*	QA999	ESCUE,N R	8004020023	MISC
EARLY,P J	8004140378	50-333 B	ELLIOTT, C P	8004300076*	50-387 G	ESKIN,L D	8003310411#	50-124 B
EARLY,P J	8004150364	50-333 P	ELLISON, C T	8004040007	PR	ESKIN,L D	8003310415#	50-124 B
EARLY,P J EARLY,P J EARLY,P J EARLY,P J EARLY,P J	8004170061 8004150508 8004300041 8004150458 8004170064	50-286 P 50-333 B 50-286 G 50-286 G 50-333 P	ELROD, 8 A ELROD, 8 A ELROD, 8 ELTAWILA, F ELTAWILA, F	8004240390* 8004280241* 8004090051 8004080660* 8004020466	50-250 G 50-335 G 50-335 B 50-387 A 50-322 A	EGKIN, L D. EGKIN, L D EGKIN, L D EGKIN, L D	8003310417# 8003310421# 8003310427# 8003310432# 8003310439#	50~124 B 50~124 B 50~124 B 50~124 B 50~124 B
EARLY,P J	8004180343	50-286 P	ELTAWILA, F	8004030122	50-322 A	ESSIO,T H	8004110274#	50-151 Q
EARLY,P J	8004180350	50-286 P	ELTAWILA, F	8004040474	50-322 A	ESSIG,T H	8004300555#	50-10 Q
EASTID J	8004210387	40-1162	ELTAWILA, F	8004300064	50-322 A	ESTEY,H P	8004090370	70-1257
EASTER,J H	8004020176*	State Prog	ENDERLIN, W	8004210301	NUREO	ESTEY,H P	8004140458	70-1257
EATON,L	8004240534*	50-443 H	ENDRIZZI, D	8004080175	50-387 O	EBTEY,H P	8004180072	70-1227
EATON.J EBEL.P E EUNETER.S D EUNETER.S D EUNETER.S D	8004010472 8004210041 8004070111* 8004070231* 8004070396*	50-443	ENGEL,RE ENGELKEN,RH ENGELHARDT,TW ENGELKEN,RH	8004230343* 8004140116* 8004070251 8004070176 8004100492	50-219 P TOPREP 50-528 S 50-320 P 50-361 S	EBTEY, H P EBTRADA, P EVANS, C A EVANS, V R EVANS, C A	8004070102 8004280545* 8004070036* 8004080391 8004270011*	70-1257 50-320 H 50-285 0 50-317 F 50-298 0
EBNETER, 8	8004150143*	50-352 G	ENGELKEN, RH	8004100488	50-397 S	EWALD, S.C.	8004040194#	50-338 Q
EBNETER, 8	8004070438*	50-352 G	ENGELKEN, RH	8004150203	50-528 Q	EWING, J.F.	8004040137#	70-27
EBNETER, 8 D	8004100112*	50-352 G	ENGELKEN, RH	8004150205	50-133 Q	FABIC, B.	8004220531#	50-259 P
EBNETER, 8 D	8004180334*	50-219 G	ENGELKEN, RH	8004150207	50-344 Q	FABRIKANT, R.	8004040072	50-445 M
ECKERT, R M	8004230338	50-311 P	ENGELKEN, RH	8004150214	50-204 Q	FAHMER, W.J.	8004230489	50-341 8
ECKHARDT, J H	8004020180*	50-528 G	ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H	8004150218	50-312 0	FAHRNER,W J	8004020403	50~341 8
ECKHARD, T	8004240822*	50-528 G		8004150220	50-397 0	FAIRTILE,M D	8004080644	50-307 H
ECKLER, J.	8004220137*	FOIA		8004100097	50-528 0	FALCONER,J C	8004010472	50-443 Q
ECONOMOS, N	8004090291*	50-348 G		8004100101	50-133 0	FALK,K M	8004180130*	50-301 G
ECONOMOS, N	8004210199*	50-249 G		8004100104	50-344 0	FALK,K M	8004010387	50-266 Q
ECONOMOS, N	8004160122#	50-413 Q	ENGELKEN, R H	B004100107	50-204 Q	FALLON, P	8004300029#	50-387 0
EDELSTEIN, B	8004080643	XPORTLIC	ENGELKEN, R H	B004100108	50-312 Q	FALTER, H W	8004270066	50-518 8
EDGEWORTH, P J	8004070125	CONTRACT	ENGELKEN, R H	B004100109	50-397 Q	FARBER, R C	8004300008#	50-387 0
EDGEWORTH, P, J	8004040191	50-184 Q	ENGELKEN, R H	B004110107	50-528 Q	FARMER, W S	8004280257	ORG
EDGEWORTH, P	8004100020	CONTRACT	ENGELKEN, R H	B004110111	50-133 Q	FARR, R J	8004140449#	50-454 A
EDGEWORTH, P J	8004030020	CONTRACT	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8004110113	50-344 0	FARRELL, R L	8004150049	NUREG
EDGEWORTH, P J	8004040212	CONTRACT		8004110114	50-206 0	FARRELL, D	8004030339	50-556 H
EDGEWORTH, P J	8004070025	CONTRACT		8004110115	50-312 0	FARRIB, J, R	8004100605*	50-556 G
EDLOW, J	8004040427*	FOIA		8004110119	50-397 0	FARRIB, J R	8004100610*	50-556 G
EDMONBON, L D	8004020234*	50-320 H		8004180502	70-984	FARRIB, J R	8004100595	50-556 D
EDSON, K. EDHARDS, D. L. EDWARDS, D. L. EDWARDS, D. H EDWARDS, D. H	8003190734*	50-128 P	ENGELKEN,R H	B004220009	70-25	FARRIS, J R	8004100605#	50-556 0
	8004080055	40-3453	ENGELKEN,R H	B004220013	70-1257	FARRIS, J R	8004100610#	50-556 0
	8004290449	40-3459	ENGELKEN,R H	B004220015	70-734	FASANO, A N	8004070103	50-320 8
	8004010468*	50-324 R	ENGELKEN,R H	B004220022	70-754	FASANO, A N	8004020072	50-320 6
	8004040323*	50-261 R	ENGELKEN,R H	B004220031	50-528 G	FASANO, A N	8004020094	50-320 8
EICH, E	8004210258*	50-247 R	ENGELKEN, RH	8004220038	50-133	FABAND.A N	8004020077	50-320 8
EICHHORN, W H	8004020092	50-367 G	ENGELKEN, RH	8004220046		FABAND.A N	8004020097	50-320 8
EICHHORN, W H	8004020092	50-367 G	ENGELKEN, RH	8004220048		FABCID.P	8004040224	50-387 H
EISENHUT, D Q,	7906290854	50-312 H	ENGELKEN, RH	8004220050		FAUBLE.T J	8004240468	RES
EISENHUT, D Q	8004280369*	50-10 H	ENGELKEN, RH	8004220052		FAULKENBERRY	8004300453*	50-312 0
EISENHUT, D G EISENHUT, D G EISENHUT, D, G EISENHUT, D, G EISENHUT, D G	8003240555 8004070288 8004030102 8004100517 8004140085	50-302 Q 50-27 G 50-320 P GRO GRO	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8004180135 8004180139 8004180144 8004180148 8004180152	50-206	FAULKENBERRY, B FAULKENBERRY, B FAY, C W FAY, C W FAY, C W	8004210229* 8004280226* 8004040123 8004070206 8004030353	50-312 Q 50-312 Q 50-266 P 50-266 Q 50-266 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
FAY, C W FAY, C W FAY, C W FAY, C W FAY, C W	8004020326 8004010319 8004240449 8004020333 8004020344*	50-266 P 50-266 P 50-266 Q 50-266 5 50-266 S	FERGUSON, R FERGUSON, J H FERGUSON, J H FERGUSON, J H	7708150054 80042500414 8004020027 8004210372 8004210279	50-338 F	FISHAR F G FISHAR G FISHAR FISHERAR J	B004210248* B004040030 B004040415 B004080115* B004030033*	50-312 0 30-70 B 50-70 B FOIA 50-320 H
FAY.C W Fay.c M Fay.c W Fay.c W Fay.c W	8004020410 8004240419 8004220278 8004290307 8004290310*	50-266 F 50-266 0 50-301 P 50-266 S	FIALKOVICH, J E FIELDSETH, H FIELDER, J FIELDS, S R	8004300204 8004280043* 8004080281 8004080485 8004110048	NUREG 50-282 H 50-250 J 50-348 G NUREG	J FISHER, W L	8004070166* 8004070174* 8004040034* 8004100383* 8004230189*	50-10 Q 50-373 Q 50-254 Q 50-189 Q 50-123 Q
FAY,C W Fay,C W Fay,C W Fay,C W Fay,C H	8004270464 8004270467* 8004220475 8004270298 8004270306*	50-301 9 50-301 9 50-266 P 50-266 9 50-264 9	FIELDER, J FIELDER, J FIKAR, L F FILKINS, D FINFROCK, I R	8004140442 8004280449 8004230041* 8004180471* 8004220514*	50-244 5	J FISHER, W.L. FISHER, W.L. FISHER, D	8004090327* 8004100377* 8004230157* 8004070424 8004020063	50-2 Q 50-150 Q 70-925 40-1162 PROJ
FAY, C W FAY, C W FEDERICK, E J FEE, W F FEE, W F	8004290470 8004290479+ 8004100398 8004070218+ 8004110012	50-301 S 50-301 S RES 50-245 Q 50-213 G	FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R	8004020006 8004020383 8004020317 8004020508 8004020511*	50-363 0 50-217 R 50-217 P 50-217 P 50-217 P	FISKE, T N FITZGERALD, J A FITZSIMMDNS, T R	8004300297 8004300297 8004180136 8004070389 8004290058*	WASTE MOT WASTE MOT 50-3B7 9 71-9067 50-3 H
F6E, W F FEE, W F FEE, W F FEE, W F FEE, W F	8004030293 8004210411 8004250132 8004150297 8004230413	50-213 P 50-213 P 50-213 G 50-213 P 50-423 A	FINKEL, A E FINLEY, N C FINLEY, A G FINLEY, A Q FINLEY, A Q	8004180334* 8004150033 8004090431* 8004030350* 8004110498*	NUREO 50-305 G	FLEISHER, Z S FLEISHER, W L FLEISCHAKER, D	8004070213 8004180237* 8002290456 8004020133 8004070038	PR 50~3 H 50~286 H 50~275 D 50~275 O
FEHRINGER, J M FEHRINGER, J M FEHRINGER, J M FEHRINGER, J M FEIERABEND, C D	8004150025 8004150038 8004170276 8004250364 8004100290*	50-155 P 50-271 P RES 50-275 P 50-282 G	FIGRELLI, O FIGRELLI, G FIGRELLI, O FIGRELLI, O	B004040060 B004040418* B004040143 B004040036 B004040043	50~483 0 50~546 0 50~346 0 50~373 0 50~546 0	FLEIBCHAKER, D FLEIBCHAKER, D FLEIBCHAKER, D	8004090132 8004090137* 8004230107 8004210322 8004080554	50-275
FEIT,R FEIT,R FELTON,J M FELTON,J M RELTON,J M	8004280187 8004280200 7812120219 8003310090 8004010163	REVIEW GRP REVIEW ORP FOIA FOIA 50~269 P	FIGRELLI, G FIGRELLI, O FIGRELLI, G FIGRELLI, G	B004070167 B004030251 B004040050 B004040175 B004040405	50~483 Q 50~306 Q 50~341 Q 50~10 Q 50~263 Q	FLEISCHAKER, D FLETCHER, G W FLYNN, J R FLYNN, J R FLYNN, J R	8004210322 8004080241* 8004220075* 8004220092* 8004220107*	50-275 Q CONTRACY FOIA FOIA FOIA
FELTON.J M FELTON.J M FELTON.J M FELTON.J M FELTON.J M	80040B0046 8004010033 8004010049 B004010056 B004070194	50-150 I FOIA FOIA FOIA 50-3 H	FIORELLI.O FIORELLI.O FIORELLI.O FIORELLI.O FIORELLI.O	8004040471 8004040316 8004080629 8004100122 8004090272	50-329 0 50-275 0 50-373 0 50-305 0 50-373 0	ELYNN' 7 K ELYNN' 7 K ELYNN' 7 K ELYNN' 7 K	8004220604 8004220242* 8004220286* 8004220346* 8004220373*	FOIA FOIA FOIA FOIA
FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8004030355 8004010281 8004040415 8004020788 8004030303	50-382 H FQIA 40-8740 FQIA 40-2061	FIGRELLI.G FIGRELLI.G FIGRELLI.G FIGRELLI.G	8004110150 8004080182 8004100172 8004040145 8004110284	50-440 Q 50-373 Q 50-254 Q 50-500 Q 50-456 Q	FLYNN, J R FLYNN, P FLYNN, J, D FLYNN, M FOLEY, E,	8004220532* 8004030263 8004150301 8004030040 8004100609*	F01A 50-312 H 50-358 A CQNTRACT PR
FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8004070136 8004070130 8004070425 8004030304 8004030310	FOIA FOIA FOIA FOIA FOIA	FIORELLI,O FIORELLI,O FIORELLI,O FIORELLI,O FIORELLI,O	8004210134 8004100245 8004070130 8004280020 8004280046	50-35B Q 50-329 Q 50-341 Q 50-265 Q 50-454 Q	FORBEA, R. L. FORD, W. H FORD, W. H FORD, W. H FORD, W. H	8004150019# 8004040221 8004020155 8004070231 8004220088	50-255 B 40-8502 40-8502 40-8502 40-8502
FELTON, J M FELTON, J M FELTON, J, M FELTON, J, M FELTON, J, M	8004070001 8004070004 8004070012 8004080690 8004080709	FOIA FOIA FOIA 50-3 F FOIA	FIORELLI,0 FIORELLI,0 FIORELLI,0 FIORELLI,0 FIORELLI,0	8004280031 8004090039 8004070201 8004070204 80040901,67	50-454 Q 50-327 8 50-546 8 50-327 8 50-440 8	FORD, W H FORD, W H FORMELLA, R L FORMEST, Z FOSTER, J E	8004240198 8004220074 8004080521* 8004040307 8004220186*	40-8502 40-8502 90-307 9 50-320 H
FELTON, J M	8004070044 8004070171 8004070023 8004070353 8004100048	FOIA 50-320 P FOIA FOIA FOIA	FIORELLI,O FIORELLI,O FIORELLI,O FIORELLI,O FIORELLI,O	8004070197 8004040039 8004040048 8004030173 8004030177	50-546 8 50-461 8 50-341 8 50-374 6 50-327 8	FOBTER, J E FOBTER, K. FOBTER, W. E FOBTER, J D FOBTER, W E	8004220176# 8004030129# 8004070071# 8004030147 8004080287#	FOIA 50-320 H QA999 40-2061 QA999
FELTON.J, K FELTON,J K FELTON,J K FELTON,J K	8004110038 8004150013 8004150213 8004220020 8004150201	50-3 P FOIA FOIA FOIA FOIA	FIORELLI, G FIORELLI, O FIORELLI, O FIORELLI, O	8004070228 8004070230 8004080672 8004020083 8004040064	50-454 8 50-483 8 50-483 8 50-329 5 50-483 0	FOSTER.W E FOSTER,R F FOSTER,W E FOSTER.J B FOSTER.W E	8004090086* 8004180481 8004080389* 8004010106* 8004080316*	0A999 ACR8 QA999 27-39 QA999
•	8004210095 8004210350 8004170131 8004210013 8004210047	FOIA 70-143 FOIA FOIA FOIA	FIORELLI, G FIORELLI, G FIORELLI, G FIORELLI, G	8004100240 8004080645 8004070141 8004110548 8004110526	50-329 0 50-341 0 50-546 0 50-546 0 50-341 8	Foster, J. M Foster, J. M Foster, J. M Foster, J. M Foster, E. R	8004030032 8004040154 8004090263 8004040180 8004090311*	TOARTHOO TOARTHOO TOARTHOO TOARTHOO 8 BEF-08
	8004210038 8004210069 8004230008 8004230015 8004270094	FDIA 50-320 C FDIA FDIA	FIORELLI, Q FIORELLI, Q FIORELLI, G FIORELLI, Q	8004100287 8004110318 8004170249 8004180219 8004180301	50-546 Q 50-483 Q 50-546 8 50-358 S 50-341 8	FOUKE, R L FOULKE, J D FOULER, D K FRANCE, E R FRANCE, E R.	8004240424* 7910310031 8004290438* 8004130601* 8004130579*	50-445 0 MISC 50-390 A 50-368 F 50-368 F
	8004270097 8004270150 8004290155 8004290182 8004290195	FOIA FOIA FOIA FOIA 50-329 H	FIORELLI.Q FIORELLI.Q FIORELLI.Q FIORELLI.Q FIORELLI.Q	8004180486 8004240122 8004300334 8004280628 8004200592	50-483 8 50-546 8 50-306 Q 50-10 Q 50-358 Q	Frankhauser, n Franklin, h J Franklin, h J Franklin, h J Franklin, h J	8004030308* 8004080285* 8004080370 8004210397* 8004040184	FDIA 50-445 H 50-445 H 50-445 H
	8004270106 8004270163 8004270167 8004270188 8004270087	50-341 H F01A F01A 50-320 H F01A	Figrellig Figrellig Figrellig Figrellig Figrestone, L	8004290050 8004290053 8004300048 8004300060 8004080479	50-483 8 50-341 8 50-461 8 50-483 8 50-334 I	FRANKLIN, W J FRANKLIN, W J FRANKLIN, W J FRANKLIN, W J FRANKLIN, W J	8004210384 8004210392# 8004210400* 8004210392* 8004210400*	50-445 H 50-445 H 50-445 H 50-445 H

AUHTUR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FRANKLIN, W J FRANKLIN, W J FRANKLIN, W J FRANKLIN, W J FRANTZ, B P	8004140003 8004140008* 8004210147 8004210147 8004040053	50-445 M 50-445 M 50-445 M 50-445 M 50-347 Q	GAMMILL, W P GAMON, T H GANNIG, S GARCIA, P J GARCIA, P J	8004280044# 8004010341 8004150018 8004070249 8004110135	50-285 P TOPREP FOIA 40-8452 40-1162	GILLILAND, D L GILLILAND, D L GILLILAND, D L GILLILAND, D GILLMAN, D	8004080220* 8004080313* 8004280311 8004180208* 8004070157	50-183 R 50-73 R 50-70 P 50-358 G 50-359 H
FRANTZ, S P FRANTZ, J FRANTZ, B P FREDRICKSON, C FREEMAN, K D	8004040053 8004300133 8004240194 8004150407 8004090187	50-367 0 50-367 0 P8M 50-320 H 50-312 0	GARRITY, J H GARRITY, J H GARY, R J GARY, R J GARY, R J	8004140154 8004280562 8004010147 8004040101* 8004040083*	50-309 R 50-309 R 50-445 Q 50-445 G	GILMARTIN, D J GILMAN, D W GILMORE, D W GINTECK, P GIRQUARD, P R	8004100041 8004090224 8004180439* 8004020221* 8004090144	PR PRM 50-320 H 50-320 H FOIA
FRENCH, L D FRENZEL, B FREY, D O FRIDAY, O P FRIEDLANDER, H	8004080476# 8004210154 8004020470 8004070347* 8004070078#	50-29 5 PR 50-546 H 50-320 R 50-3 P	GARY,R J GARY,R J GARY,R J GARY,R J GARY,R J	8004180477 8004010295 8004150199 8004010296 8004150001	PR 50-445 S 50-445 B 50-445 S 50-445 A	GLAGDLA, A F GLAGOLA, A F GLAGOLA, A F GLAGOLA, A F GLAGOLA, A F	8004080326 8004100354 8004100596 8004240535 8004240546	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
FRIEDMAN, O IS FRIEDMAN, C FRIEDMAN, K A FRIEDMAN, J FRIED, R	8004270186* 8004040216 8004110037* 8004270176* 8004080165	QA777 50-352 H QA797 QA777 50-367 H	GARY.R J GARY.R J GARY.R J GARY.R GARY.R J	8004070278 8004220424 8004220423 8004250373 8004270521	50-445 S 50-445 K 50-445 B 50-320 O 50-445 A	GLASER, M L GLASIER, G E GLASS, D N GLAZIER, K M GLAZIER, K M	8004080663 8004020151 8004040403* 8004210437 8004100177	50-445 M 40-8675 71-35 50-445 M 50-445 M
FROHNE, R FROBT, B R FROST, B R FROST, B R FUKUDA, B K	8004150570* 8004250350 8004280555 8004280614 8004150056	50-346 8 50-255 8 50-155 F 50-255 F RES	GARY.R J GARY.R J GARY.R J GARY.R J GARY.R J	8004290250 8004290271 8004290411 8004290430 8004290437*	50-445 S 50-445 S 50-445 S 50-445 S 50-445 S	GLENN, J GLENN, J GLENN, J GLENN, T D	8004210045# 8004210025# 8004210057# 8004210062# 8004240322#	F0]A F0[A F0[A F0[A 71-107
FULLER, J K FULLER, J K FULLER, J K FUNDERBURG, R D FURR, B J	8004070286 8004030130 8004270370 8004110544 8004070134	50-267 P 50-267 G 50-267 G State Preg 50-261 G	GARY,R J GARY,R J GAGKIN,C E GATES,J GAY R R	8004290634 8004300526 8004280013* 8004220681* 8004210223*	50-445 A 50-445 A 50-344 Q 50-10 B 50-3 H	GLISSMEYER,J A GNUGNOLI.G GUDDARD,R J	8004240331* 8004210301 8004080665 8004150223 8004150258	71-107 NUREG WASTE MGT 50-367 G 50-367 G
FURR, B J FURR, B J FURR, B J. OAGE, L OAGE, L	8004040461 8004100343 8004230076 8004090438# 8004150143#	50-324	GECKLER.R P GECKLER.R P GECKLER.R P GEIGER.G GEISELMAN,J N	8004230076# 8004020126# 8004210431# 8004080161 8004100460#	50-367 G 50-286 D 50-367 G 50-387 G 50-516 T	GOODDARD, R J GOODWIN, A V GOOGIN, C L	8004270217 8004270237 8004020116* 8004020736* 8004010422*	50-454
OAGNER, 8 F OAGNER, 8 F OAHM, J W OAHM, J, W OAHM, J W	8004070462 8004100487 8004080427* 8004080512* 8004210271*	MISC MISC 50-267 S 50-267 S 50-267 R	GEJBELMAN, J N GEKLER, R P GERLACH, F T GERTZ, B M GERTZ, B M	8004100050* 8004230093* 8004220002 8004140420 8004250395	PR 50-367 0 F01A 50-320 R 50-320 R	GOLDBERG, J R GDLDBERG, S C	8004010415 8004110576 8004070471 8004080656 8004230302*	REG 50-367 G 50-293 M 50-250 G PRDJ
H L WHAD W L WHAD W L WHAD W L WHAD W L WHAD	8004150334* 8004150552* 8004150611* 8004150634* 8004210276*	50-267 R 50-267 B 50-267 B 50-267 B 50-267 B	GETTY, B.C. GIARDINA, P.A. GIARDINA, P.A. GIBBONB, T.D. GIBBS, C.F.	8004170236* 8004100472* 8004100055* 8004110575* 8004040238	50-133 R 50-516 T PR 50-395 0 50-556 H	COLDBERG.J R COLDBERG.J R COLDBERG.B C	8004210425 8004230317* 8004160280 8004210207 8004230295	50-367
QAHM, J W. QALER,R R QALLAQHER,V C QALLAQHER,E J QALLAQHER,E J	8004240328* 8004230343* 7907250327 8004210142* 8004100252*	50-267 B 50-219 P 50-443 H 50-358 Q 50-329 Q	GIBBB, M C GIBERT, J D GIBBON, A F GIBBON, A F GIBBON, A F	8004100310 8004030238* 8004040156* 8004080043* 8004080038*	50-255 G 50-338 R 70-27 50-348 G 30-250 G	ODLDBERG, S C GOLDHOR, F GOLDSMITH, R	8004250415 8004300389 8004250030* 8004270038 8004230110*	50-367 G 50-367 G 50-3 H GRG COMMISSION
QALLAWAY, W. C QALLAGHER, J W QALLAGHER, J W QALLAGHER, J W QALLINA, C	8004040479* 8004080538 8004250045 8004080349 8004280300*	QA999 50-277 P 50-277 Q 50-277 P 50-293 Q	OIDSON, A F OIDSON, A F OIDSON, A F GIBSON, A F OIBSON, A F	8004270141# 8004040174# 8004070302# 8004110027# 8004250291#	50-324 0 50-338 0 70-1201 70-1151 50-261 0	QOODHOPE, A.C. QOODHAN, L. S. QOODMAN, L. S.	8004080082 8004090412 8004140367# 8004300463* 8004080049	RES 50-471 0 50-409 R 50-409 S 70-1151
GALLINA, C O GALLO, R M GALLO, R M GALLO, J GALLO, J,	8004210173* 7812110291* 8004100111* 8004020278 8004080191	50-273	OIBBON: A F. OILDERT, R B OILBERT: R B OILDERTS: D E OILBERTS: D E	8004280255* 8004240282* 8004240447* 8004100070* 8004070058	70-1317 50-320 H 50-320 H 50-282 G 50-282 G	GOODMIN'S GOODMIN'M F	8004100273* 8004100463* 8004110015 8004080447 8004030240	50-344 Q 70-1151 70-1151 50-344 P 50-344 P
OALLO, J OALLO, J. OALLO, J OALLO, J GALLO, J	8004100570 8004100273 8004100275* 8004100278* 8004100273	50-155 0 50-155 0 50-155 0 50-155 0 50-155 0	OILBERTS, D E OILBERT, L D OILBERTS, D E OILBERTS, D E OILBERT, L D	8004070210 8004300035* 8004300337* 8004040456 8004250083*	50-282 0 50-498 0 50-306 0 50-282 0 50-445 6	9 9000WIN, C 9 9000WIN, C 9 9000WIN, C,	8004030243* 8004080388 8004100459 8004080542 8004180361	50-344 P 50-344 P 50-344 P 50-344 Q 50-344 P
GALLO, J GALLO, J. GALLO, J GALLO, J GALLO, J	8004100276* 8004100278* 8004080180 8004080186* 8004160161	50-155	OILBERTS,D E OILBERT,J D OILINSKY,V OILINSKY,V OILINSKY,V	8004140013 8004170052* 8004030024* 8004030014 8004020112	50-282 0 50-338 F 50-3 F 50-3 F 50-289 F	R GORDON,L H GORSICK,L V	80041 80362* 8004280268* 8004290418 79041 1 0030 79071 1 0564	50-344 P 50-320 H 50-266 I PR PR
GALLD, J. GALLD, J GALLD, J GALLD, J GALLD, J	8004080186* 8004160161 8004100451 8004100455* 8004100455*	50-155	OILINSKY, V GILINSKY, V GILINSKY, V GILINSKY, V	8004040002 8004180113 8004160034 8004280250* 8004220173	50-289 F 50-320 F 50-320 F	H QGSSICK, L V H QDSBICK, L V P QDSBICK, L V P GDSBICK, L V H QGSSICK, L V	7910250124 7910250127 7910250135 8004070188* 8004030024	PR PR PR 50-324 P 50-320 0
QALLO,J QALLO,J. QALLO,J. QALLO,J. QALSIER.O E.	8004210420 8004210401 8004280015 8004250372 8004020487	50-155 Q 50-155 Q 50-155 F 50-556 Q 40-8681	OILINSKY,V OILLESPIE,F P OILLESPIE,F P OILLESPIE,F P, OILLESPIE,F P	8004240472 80040702444 8004070059* 8004100482* 8004040021*	70-149 70-149 70-1151	P GOUGE, M J GOUGE, M J GOUGE, M J GOURGE, M J GOWDA, B C	8004100506* 8004040125* 8004160072* 8004210121* 8004270371*	50-566 Q 50-416 Q 50-327 Q 50-566 Q 50-537 A
OAMBINO, M CAMMILL, W CAMMILL, W. CAMMILL, W. CAMMILL, W P	8004280350* 7910050156 7910050603 8004080233 8004080005*	50-320 H MISC MISC MISC 50-275 P	GILLESPIE,F P GILLETT,W T GILLESPIE,F GILLESPIE,F P,	8004040117* 8004150365* 8004150371* 8004290177* 8004290157*	50-315 50-315 50-259	ODMER.O C R ODMER.O C R ODMER.O C. Q ODMER.O C. Q ORAHAM,R L	8004220247 8004280153* 8004280149* 8004280578 8004230091	50-263 8 0A979 0A979 18 E 50-367 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	PIDHT UA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RAHAMAR L	B004230101*	50-367 0	GRIER, B H	8004150262	50-213 0	ORIER, B H GRIER, B H GRIER, B H GRIER, B H ORIER, B H	8004240313	50-322 Q
E CANAHARO	B004010405	50-261 1	GRIER, B H	8004150264	50-334 0		8004240315	50-320 G
E GRAHAMARO	80041B0344	50-261 J	GRIER, B H	8004150266	50-412 0		8004240318	50-309 Q
E GRAHAMARO	8004240379	50-261 J	GRIER, B H	8004150269	50-217 0		8004240319	50-245 Q
UNITARIO	7910150161	MISC	GRIER, B H	8004150271	50-363 0		8004240324	50-220 Q
GRANT.W B GRASSO, E GRATENHUIS.II GRAVES.R S GRAVES.R H	8004040149* 8004070426* 8004140199 8004220762* 8004020372	50-500 Q State Prog 50-306 Q 50-3 G 50-213 R	GRIER, B H GRIER, B H GRIER, B H ORIER, B H GRIER, B H	8004150274 8004150274 8004150277 8004150279 8004150282	50-322	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8004240330 8004240333 8004240335 8004240337 8004240339	50-410 9 50-286 0 50-333 0 50-352 0 50-277 0
GRAVES: R H	8004010362	50-213 S	GRIER, B H	8004150285	50-410 G	GRIER, B H	8004240341	50-387 Q
GRAVES: R H	8004010369*	50-213 S	GRIER, B H	8004150284	50-333 G	GRIER, B H	8004240342	50-272 9
GRAVES: R H	8004240437	50-213 R	GRIER, B H	8004150288	50-286 O	GRIER, B H	8004240346	50-311 0
GRAVES: R H	8004240439*	50-213 R	GRIER, B H	8004150291	50-277 G	GRIER, B H	8004240348	50-443 0
GRAVES: R H	8004290264	50-213 R	GRIER, B H	8004150293	50-352 G	GRIER, B H	8004240349	50-244 Q
GRAVES,R H	8004210251	50-213 R	GRIER.D H GRIER.D H GRIER.D H GRIER.D H GRIER.D H	8004150295	50-387 0	GRIER.B H	8004240351	50-485 Q
GRAVES,R S	8004220754	50-3 0		8004150296	50-272 0	GRIER.B H	8004240353	50-271 Q
GRAY,P F	8004300036*	50-387 0		8004150299	50-311 0	GRIER.B H	8004240355	50-27 Q
GRAY,C M	8004160078	70-2909		8004150302	50-449 0	GRIER.B H	8004180166	50-217 Q
GRAY,R J	8004160237	50-445 K		8004150303	50-244 0	GRIER.B H	8004180167	50-334 Q
GRAY. J R	8004280006	50-344 0	GRIER.B H	8004150308	50-485 Q	GRIER.B H	8004180173	50-443 0
OREENMAN. E O	8004140194*	50-277 0	ORIER.B H	8004150309	50-271 Q	GRIER.B H	8004180174	50-307 0
GREEN. H P	8004020199*	COMMISSION	ORIER.B H	8004150310	50-27 Q	GRIER.B H	8004180179	50-322 0
OREEN. D O	8004090439	50-445 H	GRIER.B H	8004280167	50-273 P	GRIER.B H	8004180180	50-410 0
GREEN. D O	8004020119*	50-445 M	ORIER.B H	8004090037	50-273 Q	GRIER.B H	8004180184	50-352 0
GREEN.D G	8004080073	50-445 M	GRIER, B H	8004090042	50-317 0	GRIER.B H	8004180184	50-311 Q
GREEN.D G	8004040198*	50-445 M	GRIER, B H	8004090045	50-3 0	GRIER.B H	8004180187	50-387 Q
GREEN.D G	8004140111	50-449 M	GRIER, B H	8004090047	50-213 0	GRIER.B H	8004180172	50-412 Q
GREENLEE.E A	8004100194*	CONTRACT	GRIER, B H	8004090048	50-334 0	GRIER.B H	8004180210	50-3 Q
GREEN.D G	8004100271	50-445 M	GRIER, B H	8004090052	50-412 0	GRIER.B H	8004180224	50-213 Q
GREEN, D G GREEN, D G GREEN, D G GREEN, D G	8004100278* 8004230064 8004250106 8004170312 8004100552	50-445 M 50-445 H 50-445 M 50-445 M	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8004070057 8004070060 8004070063 8004070065 8004070069	50-219 0 50-363 0 50-322 0 50-320 0 50-309 0	GRIER.B H ORIER.B H ORIER.B H GRIER.B H ORIER.B H	8004180227 8004180231 8004180236 8004180241 8004180243	50-293 G 50-245 G 50-333 G 50-284 O 50-485 G
GREEN, D O OREEN, D O OREEN, D O OREEN, D O OREEN, D O	6004100560* 8004230154 8004100552 8004100560* 8004230154	50-445 M 50-445 M 50-445 M 50-445 M	GRIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8004070074 8004070077 8004070080 8004070083 8004070092	50-245 G 50-410 G 50-220 G 50-233 G 50-286 G	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	9004180246 8004180248 8004180251 8004180255 8004180257	50-272 G 50-244 Q 50-271 Q 50-27 G 50-317 G
OREER, R J OREGER, L R OREGO, R J OREGO, R J OREGO, R J	8004110274* 8004070166* 8004180392 8004180046 8004180020	50-191 0 50-10 9 70-820 70-820 70-820	GRIER.B H ORIER.B H GRIER.B H GRIER.B H GRIER.B H	8004070073 8004070075 8004070077 8004070077 8004070101	50-352	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8004180260 8004180261 8004180262 8004180263 8004110050	50-320 G 50-363 G 50-220 G 50-277 G 50-273 G
GREGORY, W S	8004240475	RES	ORIER.B H	8004090103	50-443	GRIER.B H	8004110053	50-322 Q
OREHER, E	8004220207+	FOIA	ORIER.B H	8004090105		ORIER.B H	8004110054	50-245 G
OREHER, E	8004180197*	COMMISSION	ORIER.B H	8004090106		ORIER.B H	8004110058	50-410 Q
ORENDON, I	8004110147	ACRS	ORIER.B H	8004090107		GRIER.B H	8004110061	50-333 Q
ORENDON, A	8004020212	ACRS	ORIER.B H	8004090110		GRIER.B H	8004110063	50-352 Q
ORIDLEY,R L	6004090474*	50-293 P	GRIER.B H	8004300573	MISC	GRIER, B H	8004110066	50-277 G
ORIER, B H	6004170304	50-334 Q	Grier.B H	8004110122	50-293 Q	GRIER, B H	800411006B	50-387 G
ORIER, B H	8004080341*	50-317 Q	Grier.B H	8004110124	50-317 Q	GRIER, B H	8004110071	50-384 G
ORIER, B H	8004070195	50-334 Q	Grier.B H	8004110126	50-3 Q	GRIER, B H	8004110072	50-271 G
ORIER, B H	8004220416	50-272 Q	Grier.B H	8004110128	50-213 Q	GRIER, B H	8004230386	50-220 G
GRIER.B H	8004090385	50-293 F	GRIER.BH	8004110131	50-334 0	GRIER, DH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8004230392	50-482 G
GRIER.B H	8004210097	50-320 Q	GRIER.BH	8004110133	90-412 0		8004230394	50-317 G
GRIER.B H	8004110070	50-334 Q	GRIER.BH	8004110134	50-363 0		8004230397	50-271 G
GRIER.B H	8004080669	50-245 P	GRIER.BH	8004110137	50-219 0		8004230399	50-352 G
GRIER.B H	8004080430	50-309 Q	GRIER.BH	8004110140	50-322 0		8004230401	50-213 G
GRIER, BH	8004080433	50-271 Q	GRIER, BH	B004110147	50-320 Q	ORIER.B H	8004230403	50-3 Q
GRIER, BH	8004280277	50-273 Q	GRIER, BH	B004110154	50-309 Q	ORIER.B H	8004230408	50-334 Q
GRIER, BH	8004070409	50-289 Q	GRIER, BH	B004110154	50-245 Q	ORIER.D H	8004230433	50-245 Q
GRIER, BH	8004080324	50-317 Q	GRIER, BH	B004110158	50-220 Q	ORIER.D H	8004230435	50-244 Q
GRIER, BH	8004040159	50-334 Q	GRIER, BH	B004110159	50-410 Q	ORIER.B H	8004230439	50-333 Q
ORIER, B. H	6004250338	50-293 8	GRIER, 0 H	8004110163	50-286 0	ORIER, B H	8004230442	50-272 0
ORIER, B. H	8004110005	50-334 0	GRIER, 0 H	8004110499	50-333 0	ORIER, B H	8004230452	50-286 0
ORIER, B. H	8004110008	50-293 0	GRIER, 8 H	8004110501	50-277 0	ORIER, B H	8004230455	90-311 Q
ORIER, B. H	8004070377	50-352 0	GRIER, 8, H	8004110502	50-352 0	ORIER, B H	8004230459	50-309 0
ORIER, B. H	8004070398	50-354 0	GRIER, 8 H	8004110504	50-367 0	ORIER, B H	8004230463	50-293 0
GRIER.B H	8004090402	50-387 Q	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8004110306	50-272 0	GRIER.B H	8004230468	50-289 Q
GRIER.B H	8004090404	50-245 Q		8004110307	50-311 0	GRIER.B H	8004230472	50-485 Q
GRIER.B H	8004090407	50-220 Q		8004110511	50-443 0	GRIER.B H	8004230475	50-412 Q
GRIER.B H	8004090409	50-333 Q		8004110512	50-485 0	GRIER.B H	8004230476	50-219 Q
GRIER.B H	8004090410	50-271 Q		8004110513	50-244 0	GRIER.B H	8004230481	50-387 Q
ORIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8004090414 8004090416 8004090420 8004240552 8004210203	50-322	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8004110515 8004110519 8004240290 8004240293 8004240297	50-271 0 50-29 0 50-293 0 50-317 0 50-3 0	GRIER, B. H ORIER, B. H ORIER, B. H GRIER, B. H ORIER, B. H	8004230486 8004230491 8004230505 8004230507	50-410 d 50-322 d 50-320 d 50-320 d 50-363 d
GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8004210016 8004210039 8004150242 8004150247 8004150253	50-272	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	B004240298 B004240302 B004240303 B004240306 B004240311	50-213 Q 50-334 Q 50-412 Q 50-363 Q 50-219 Q	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	B004230512 B004230514 B0041B0115 B0041B0117 B0041B0125	50-277 6 50-29 6 50-293 6 50-317 6 50-3

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
ORIER, B H ORIER, B H GRIER, B H GRIER, B H ORIER, B H	8004180131 8004180134 8004180144 8004180149 8004180156	50-213	HAGUE,R L HAIRSTON,W G HAIRSTON,W G HAIRSTON,W O HAIRSTON,W G	8004110245* 8004010510* 8004010513* 8004150428* 8004080547*	50-246 0 50-348 5 50-348 5 50-348 8 50-348 8	HARNAGE, H H HARNAGE, H H HARNAGE, H H HARPER, R Q HARRAN, Q	8004080239 8004080239 8004240086 8004280045 8004180388*	50-250 0 50-250 0 50-250 0 XPORTLIC 50-245 R
GRIER, B H	8004180161	50-322 0	HAIRSTON, W O HAIRSTON, W G HAIRSTON, W G HAIRSTON, W O HAIRSTON, D P	8004080554*	50-348 5	HARRAIL, G	8004210249*	50-245 R
GRIER, B H	8004180171	50-287 0		8004220738*	50-348 5	HARRISON, H C	8004300081*	40-4492
GRIER, B H	8004180178	50-320 0		8004220746*	50-348 5	HARRISON, H C	8004040094*	50-313 Q
GRIER, B H	8004180194	50-309 0		8004270367*	50-348 6	HARRIS, J R	8004070043*	50-400 Q
GRIER, B H	8004180201	50-245 0		8004040161*	50-312 0	HARRIS, C E	8004020475*	TOPREP
GRIER, B H	8004180205	50-410 Q	HAIST, D P	8004300278*	50-397 0	HARRISON, G	B004020417* B004300536* B004240360* B004140467* B0041B0016*	50-373 F
GRIER, B H	8004180209	50-220 Q	HAIST, D P	8004280074*	50-460 0	HARRISON, J		50-546 G
GRIER, B H	8004180212	50-286 Q	HAKANSSON, K	8004280488*	COMMISSION	HARRIS, J R		50-424 G
GRIER, B H	8004180245	50-333 Q	HALE, C J	8004070086*	OA999	HART, G		70-143
GRIER, B H	8004180252	50-277 Q	HALE, C J	8004150149*	OA999	HART, G		COMMISSION
GRIER, B H	8004180267	50-352	HALE,C J	8004220244*	50-445 Q	HART. O	8004080314*	40-1341
GRIER, B H	8004180270		HALL,R E	8004080696*	50-285 Q	HART. O	8004080250*	COMMISSION
GRIER, B H	8004180276		HALL,R E	8004180218*	50-478 Q	HART. J	8004010347*	50-382 8
GRIER, B H	8004180280		HALL,J D	8004070238	40-4472	HARTLEY. R H	8004210394*	50-445 M
GRIER, B H	8004180284		HALL,R C	8004160050*	50-445 Q	HARTNETI. R A	8004070310*	50-382 8
GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIFFIN.R E	8004180287 8004180291 8004180293 8004180302 8004080041	50-244 G 50-485 G 50-271 G 50-27 G PR	HALL,RE HALL,RE HALL,RE HALL,RE HALL,RE	8004300035* 80042500B3* B004010357 B004010446 8004010329	50-49B Q 50-445 Q 50-295 F 50-29 F 50-171 F	HARTNETT, R A HARTNETT, R A HASS, W P HATMAKER, D F HAUCK, F	8004250352* 8004280605* 8004110537 8004140354* 8004170173	50-392 8 50-382 8 TOPREP 50-369 A 50-546 A
GRIMES, B K	7910180103	50-2 P	HALL,R E	8004010336	50-266 F	HAUETER,R L HAUGHNEY,C J HAUGHNEY,C J HAUGHNEY,C J HAUCHNEY,H M	8004110505	PR
GRIMES, B K	8004070184	50-324 P	HALL,R E	8004010410	50-409 F		8004030315	50-201 W
GRIMES, B K	8004080077	50-275 F	HALL,R E	8004070243	50-333 F		8004140142	50-201 P
GRIMES, B K	8004070404	NUREQ	HALL,R E	8004070272	50-254 F		8004240560	50-201 P
GRIMES, B K	8004080128	50-320 P	HALL,R E	8004080515	50-206 F		8004150132	71-97
GRIMES, B	8004030162	50-320 F	HALL,R E	8004100333	TOPREP	HAUSEN, D B	8004180307*	50~306 Q
GROCE, R H	8004080263	50-307 Q	HALL,R E	8004100379	TOPREP	HAVERKAMP, D R	8004020097	50~320 S
GROCE, R H	8004080404	50-307 P	HALL,R E	8004080449	50-331 F	HAVEY, G K	8004290510	50~320 S
GROCE, R H	8004080406	90-307 R	HALL,R E	8004140403	50-271 F	HAUKINS, F C	8004040046*	50~546 Q
GROCE, R H	8004140308	50-307 P	HALL,R E	800 230318	50-295 F	HAWKINB, F C	8004040418*	50~546 Q
GROCE,R H GROGS, M GROGES, M GROSEMAN, H GROSEMAN, H	8004180438 8004030337 8004100501 8004080591 8004080567	50-309 P PR PR 50-155 Q 50-347 Q	HALL,R E HALL,R E HALL,R E HALL,R E HALL,R E	8004230387 8004230483 8004230510 8004230320 8004230524	50-263 F 50-317 F 50-271 F 50-206 F 50-254 F	HAYES, D W HAYES, W K HAYES, W K HAYES, W K	8004040199* 8004040046* 8004110535 8004210446 8004080190*	50-10 Q 50-546 Q PR PR 50-373 Q
Großban, H	8004100008	50-367 G	HALL, R E	8004250382	50-284 F	HAYES, D W	8004100252*	50-329 G
Großban, K	8004290089	FOIA	HALL, R E	8004250385	50-331 F	HAYES, D W	8004040079*	50-483 G
Großban, K	8004290166	FOIA	HALLER, N M	8004010021*	10CFR	HAYFORD, D T	8004100025	NUREG
Großban, H	8004230075	50-155 G	HALLIGAN, T J	8004020040	50-387 Q	HAYNES, R C	8004240522*	50-528 G
Grotenhuib, H	8004020279	50-250 Q	HAMMER, T J	8004110074	50-312 Q	HAYNES, R C	8004280022*	50-275 G
OROTENHUIS, M OROTENHUIS, M OROTENHUIS, M OROTENHUIS, M OROTENHUIS, M	8004100187 8004110093 8004140120 8004070179 8004090275	50-250 Q 50-250 P 50-250 P 50-250 F 50-250 F	HAMMER.M F HANAUERR.B H HANCHETT.J O HANCOCK.J A HANCOCK.D	8004010455* 8004020125* 8004150188 8004300151* 8004100078	50~263 S 50~3 0 50~361 H 50~302 0 50~466 0	HAYNES, J G HAYNES, J G HAYNES, G	8004210417* 8004210186* 8004280095* 8004020327 8004030181	50-361 0 50-361 0 50-361 0 50-206 P 50-361 A
GROTENHUIS, M ORDTENHUIS, M ORDVES, K L ORDVES, K L ORDVES, K L	8004100486 8004140099 8004240314 8004150272 8004150099	50-282 P 50-282 P 71-107 71-49 71-273	HANCOCK, D HANCOCK, D HANCOCK, D HANCOCK, D HANCOCK, J A	8004100078 8004040445* 8004100532 8004020318	50-466	HAYNES, J G HAYNES, J G HAYNES, J G HAYNES, J G HAZELTON, W S	8004080395 8004090326 8004180449 8004220446 8004010313*	50-204 F 50-206 P 50-206 P 50-206 P 50-338 0
OROVES, K. L OROVES, K. L OROVES, K. L OROWCOCK, F. D ORUENSFELLDER, K	8004150112 8004150123 8004300082 8004280041 7908210253*	71-367 71-116 71-9043 REB 50-320 H	HANCOCK, J A HANCOCK, J A HANCOCK, J A HANN, C R HANNON, J	8004010488 8004090313 8004290480 8004250409 8004070176	50-302 R 50-302 8 50-302 S TOPREF 50-324 F	HAZLE,A J HAZLE,A J HAZLE,A J HECK,A E	8004070359* 8004110146* 8004300254 8004240116 8004080170	WASTE MOT WASTE MOT WASTE MOT WASTE MOT SO-367 H
GRUSH, W H GUHIN, M A GUICH, P A GUMBLE, F W GUMBLE, F W	8004080684	RES	N C, NONNAH	8004080113	50-293 P	HECTOR.A	8004230148	WASTE MGT
	8004210080*	70-2478	N C, NONNAH	8004080680	50-324 F	HEGARTY.W	8004280053*	XPORTLIC
	8004040107	XPORTLIC	N C, NONNAH	8004090294	50-324 P	HEIDEL.R P	8004010435*	50-317 S
	8004110442*	50-284 S	N C, NONNAH	8004030332	50-273 P	HEIBEL.R P	8004080488*	50-318 S
	8004140422*	50-286 B	N C, NONNAH	8004150053	50-324 P	HEIBEL.R P	8004080507*	50-317 S
QUMBLE, F W	8004180461*	50-286 8	HANNON, J N	8004300599	50-247 P	HEIBEL.R P	8004150486*	50-319 S
QUMBLE, F W	8004220749*	50-286 8	HANRAHAN, E J	8004290171	50-327 A	HEIBEL.R P	8004220621*	50-317 B
QUPPY, J Q	8004080290	RE8	HANSELL, D	8004140130*	50-367 0	HEIBEL.R P	8004220758*	50-318 S
QUPPY, J Q	8004100590	RE8	HANSELL, D	8004080181	40-2061	HEIBEL.R P	8004270497*	50-317 S
QUPPY, J Q	8004280071	REB	HANSELL, D	8004020273*	40-2061	HEIDER.L H	8004110444*	50-29 P
QUBTAVE,R P	8004100366	CONTRACT	HANSEN, W H	8004040062*	50-483 G	HEIDER, L. H	8004110434	50-27 P
QUBTAVE,R P	8004100360	CONTRACT	HANBEN, L E	8004070216	71-9007	HEIDER, L. H	8004220307	50-271 P
HAASS,W P	8004140083	TOPREP	HANBELL, D	8004140129	50-367 G	HEIDER, L. H	8004270415	50-271 P
HAELB10,R J	8004220184	71-9130	HANSEN, C D	8004210149*	XPORTLIC	HEISER, J. H	8004280041	RES
HAFERA,T.	8004020445*	50-265 8	HANSEN, R A	8004170257*	50-70 P	HEISHMAN, R. F	8004040434	50-315 Q
HAFER, F D	8004070477	50-320 I	HANSELL.D.	8004150461	50-367 P	HEISHMAN,R F	8004100013	50-344
HAGAN, T F.	8004080237	CONTRACT	HANSEN.R H	8004230417	NUREO	HEISHMAN,R F	8004080588	
HAGAN, T F	8004100572	CONTRACT	HARDIN.A K	8004080361	50-261 S	HEISHMAN,R F	8004100426	
HAGAN, T F	8004100189	CONTRACT	HARDIN.A K	8004070111	50-324 S	HEISHMAN,R F	8004080617	
HAGAN, T F	8004100337	CONTRACT	HARDWICK.R J	8004110575*	50-395 Q	HEISHMAN,R F	8004300014	
HAGEN, T F	8004210117	CONTRACT	HARKAHIK, D P	8004010060	FOIA	HEISHMAN, R F	8004100269	50-282 Q
HAGEY, H	8004070076	CONTRACT	HARLOW, F H	8004290001	NUREQ	HEISHMAN, R F	8004180187	50-373 Q
HAGEY, H,	8004010002	CONTRACT	HARMON, D W	8004040135	XPORTLIC	HEISHMAN, R F	8004220157	50-295 Q
HAGEY, H	8004070005	CONTRACT	HARMON, D W	8004080032	XPORTLIC	HEISHMAN, R F	8004110230	50-266 Q
HAGEY, H,	8004250035	CONTRACT	HARMON, D W	8004280096	XPORTLIC	HEISHMAN, R F	8004070427	50-315 8

renouNAL AUTHUR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F	6004070192 6004090030 6004040059 8004090415 6004100081	50-315 S 50-315 S 50-315 S 50-346 Q 50-346 Q	HICKLE.B J HIESTAND.O S HIGGINBOTHAM.L HIGGINBOTHAM.L HIGGINS.J C	8004150395* 8004070303 8004220276* 8004220470* 8004070123*	50-285 R 50-409 P FOIA FOIA 50-322 Q	HOLLOWAY, C J HOLLY, J T HOLMAN, J F HOLDDY, D J HOLTAN, A A	8004080123* 8004180433* 8004100342* 8004210104* 8004020324	FOIA 50-305 P CONTRACT 70-371 50-320 H
HEISHMAN,R F HEISHMAN,R F HEITMULLER,H HELM,K HELMS,R E	8004180172 8004280654 8004280532* 8004170183 8004150125*	50-315 Q 50-295 S 50-320 H XPORTLIC 71-116	HIGOINS, J HILL, T D HILL, T D HILL, T D	B004100111* B004100077* B004160153* B004210365 B004300274	50-387 Q 50-322 Q 50-293 Q PT21 PT21	HOOD, D 8 HOPKING, L J HOPPER, D N HOPPER, D K	8004110020 8004140262* 8004040162* 8004030238* 8004170052*	50-327 A 50-358 U CONTRACT 50-338 R 50-338 R
HEMMENDINGER, R HEMPLEREE, R HENDERSON, O K HENDERSON, J B HENDERSON, D M	8004080154 8004040241 8004090186 8004100301 8004290444	50-387 C 50-554 H PR 50-410 A 40-4622	A C.ONIH A C.ONIH A C.ONIH A C.ONIH A C.ONIH	8004080640* 8004040132* 8004090431* 8004040115 8004080637	50-263	HOREY, O K HORWITZ, F D HOSEY, C M HOSSLI, W HOSSLER, D E	8004180338 8004240051* 8004080043* 8004220017* 8004150372	50-320 R CONTRACT 50-348 Q 50-316' P 50-320 H
HENDRIE. J M HENDRIE. J M HENDRIE. J M HENDRICKS. T J HENDRIE. J M	8004020107 • 8004020105 * 8004080048 • 8004030308 * 8004170112	50-3 G 50-3 G COMMISSION FOIA COMMISSION	V Г.QИІН V Г.QИІН V Г.QИІН V Г.QИІН	8004090428 8004030350* 8004030325 8004030349 8004110498*	50-305 Q 50-278 Q 50-259 Q 50-278 Q 50-285 Q	HOSTETTER, J J HOUGHTON, T C HOUSTON, R W HOVEY, G K HOVEY, G K	8004100578* 8004100584 8004140127* 8004140179 8004170023	50-320 H 50-416 F 50-367 0 50-320 P 50-320 P
HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J HENDRIE, J	8004020195 8004070011 8004140392 8004210100 8004220081	COMMISSION 50-320 P COMMISSION 50-275 G 70-143	HIND: J A HIND: J A HIND: J A HIND: J A HIND: J A	8004110487 8004240513 8004300089 8004070135* 8004080649*	50-285 Q 50-2 Q 50-2 Q 50-341 Q 50-341 Q	HOVEY.O K HOVEY.O K HOVEY.O K	8004150436 8004160290 8004170039 8004250377 8004240399	50-320 P 50-320 P 50-320 P 50-320 8 50-320 P
HENSLEY, K D HENSLEY, K D HERBEIN, J G HERBEIN, J G	8004300085 8004180213 8004220219 8004070416* 8004300586*	70-143 70-143 70-143 50-287 Q 50-287 O	HINES, E HIRT, C W HITCHENS, D C HITCHLER, M J HODDS, T C	8004300382 8004150141* 8004220761* 8004020432* 8004230027*	50-341 Q NUREG 50-346 B TOPREP FOIA	HOVEY, O K HOVEY, O K HOVEY, O K HOVEY, O E	8004250433 8004250354 8004180339* 8004070470 8004100386	50-320 P 50-320 P 50-320 R 50-293 P 50-293 P
HERBEIN, J C HERBEIN, J C HERBEIN, J C HERBEIN, J C HERBEIN, J C	8004090013 8004020056 8004040336 8004010412 8004030241	50-287 Q 50-289 Q 50-320 B 50-287 P 50-320 I	HOCKERT, J HOCKERT, J HODDER, M H HODDER, M H HODDER, M H	8004020069 8004080177 8004210109 8004020239* 8004020272*	70-135 70-135 50-387 50-389 6	HOWARD, A S HOWE, P W HOWE, P W HOWE, P W HOWE, R S	8004170040 8004070058 8004070295 8004070035 8004150290	50-320 H 50-400 G 50-400 G 50-400 G 50-309 I
HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O	8004070284 8004070290 8004070291 * 8004070319 8004070323*	50-287 P 50-287 P 50-287 P 50-287 P 50-287 P	HODGDON, A P HODGDON, A P HODGDON, A P HODGDON, A P HOEFLING, R K	B004030347 B004100126 B004150157 B004290227 B004030326	50-445 M 50-445 M 50-445 M 50-445 M 70-2623	HOWELL'S H HOMELL'S H HOMELL'S H HOMELL'D B	8004220521* 8004100349 8004010397 8004070293 8004090248	FDIA 50-329 Q 50-329 B 50-329 R 50-329 K
HERBEIN' O G O'NIBEBH O'NIBEBH HERBEIN' O G	8004070335 8004080560 8004080703 8004080707* 8004100350	50-320 R 50-289 P 50-289 P 50-289 P 50-320 F	HOEFLING,R K HOEFLING,R K HOEFLING,R K HOEFLING,R K HOELLER,J	8004230078 8004210009* 8004210007 8004160265 8004150498*	50-269 G 50-322 Q 50-322 Q 50-269 Q 50-269 S	HOMETT'S H HOMETT'S H HOMETT'S H HOMETT'S H	8004090251* 8004080404 8004080431 8004100384 8004100387*	50-327 K 50-329 A 50-329 A 50-329 A 50-329 A
HEUBE IN' 7 O HEUBE IN' 7 O HEUBE IN' 7 O HEUBE IN' 7 O	8004110395 8004140386 8004170106* 8004230406 9004150349	50~287 P 50~289 P 50~287 P 50~287 S 50~289 P	HOENES, L O HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8004270020 8004070383* 8004010287 8004040327 8004040371	NUREO 50-255 Q 50-255 P 50-155 P 50-255 R	HOWELL, 8 H HOWELL, 8 H HOWELL, 8 H	8004100390# 8004290157# 8004190354 8004170083 8004210225	50-329 A 50-339 G 50-329 B 50-329 B NUREG
HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J G	8004150446 8004150499 8004180473 8004220223 8004220224*	50-320 P 50-320 Q 50-289 D 50-289 P 50-289 P	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8004070320 8004030217 8004070305 8004080232 8004080470	50-255 P 50-255 R 50-255 P 50-255 P 50-155 S	HOWELL, 8 H HOWELL, 8 H HOWLETT, Q, H HOYLE, J C HOYLE, J C	8004210318 8004280440 8004220413* 8004150017 8004150077	50-329 B 50-329 F 50-336 R ACRS ACRS
HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O	8004220542 8004170104 8004220454 8004230493 8004250367	50-287 P 50-287 P 50-287 P 50-287 R 50-287 P	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8004070387 8004100374 8004100403 8004100413 8004280402	50-255 P 50-255 S 50-255 S 50-255 S 50-255 C	HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J, C	8004150111 8004150114 8004150241 8004140056 8004140089	ACRB ACRB ACRB ACRB ACRB
HERBEIN, J Q HERBEIN, J Q HERDI, A R HERDEN, A R	8004280430 8004300409 8004020043* 8004040176*	50-320 I 50-320 F 50-375 Q 50-259 Q 50-438 Q	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8004140334 8004150012 8004140309 8004150215 8004150530	50-255 Q 50-255 8 50-155 P 50-255 P 50-255 B	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C	8004150212 8004150222 8004150249 8004140043 8004180036	ACRB ACRS 50-280 P ACRB ACRS
	146 18 6	50-566 Q 50-416 Q 50-348 Q 50-302 Q 50-240 Q	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D, P HOFFMAN, D, P HOFFMAN, D P	8004150544 8004150627 8004180497 8004210159 8004220575	50-255 S 50-255 P 50-255 Q 50-255 P 50-155 Q	HOYLE, J C HOYLE, J. C HOYLE, J. C HOYLE, J. C	8004180032 8004180044 8004150244 8004180025 8004180049	ACRS ACRS ACRS ACRS ACRS
		0 0 0 0	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8004220589 8004230383 8004240472 8004240450 8004250354	50-255 Q 50-155 H 50-155 P 50-255 P 50-255 8	HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C	8004180406 8004180498 8004180506 8004180506	ACRS ACRS ACRS ACRS ACRS
			HOFFMAN, D P HOFFMAN, D P HOHN, A HOHN, A HOHNE, F C	8004250426 8004280519 8004220027* 8004220034* 8004040227	50-255 P 50-255 P 50-316 P 50-316 P 40-8502	HOYLE, J C HOYLE, A, HOYLE, A, HOYLE, J C	8004150254 8004150005 8004150245 8004040116 8004150248	ACR8 ACR8 ACR8 CONTRACT ACR8
			HOLCOKB, O R HOLDEN, T J HOLDEN, T J HOLLEY, M J HOLLENBACHER, R	8004150171* 8004240063 8004240067* 8004040070* 8004220273*	CONTRACT XPORTLIC XPORTLIC 50-344 T 50-331 F	HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C	8004150228 8004150232 8004150236 8004150240 8004180085	ACRS ACRS ACRS ACRS ACRS

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
HOATE' 7 C HOATE' 7 C HOATE' 7 C HOATE' 7 C	8004140035 8004070047 8004080576 8004220030 8004220474*	ACRS 50-3 0 50-331 0 50-247 0 TOPREP	IPPOLITO, T A	8004110084 8004040127 8004110519 8004110525* 8004110525*	50-271 P 50-259 P 50-259 P 50-259 P 50-259 P	ЈОНИ, Р F ЈОНИ, Р F ЈОНИЗОИ, Т D ЈОНИЗОИ, М C ЈОНИЗ, S J	8004080174 8004100498 8004210355* 8004020035* 8004070137*	50-445 M 50-445 M 50-320 P 50-395 G 50-155 H
HSU, C J HUBBARD, R B HUBERMAN, B HUDSON, G HUETER, L J	8004150475 8004210393* 8004030168* 7904110103 8004040034*	RES 50-275 G SECY 50-2 P 50-254 G	IPPOLITO, T A	8004110531* 8004100032 8004100037 8004210303 8004100602	50-259 P 50-220 P 50-263 P TUPREP 50-333 P	104N20N, D 104N20N, A 104N20N, A 104N20N, W 104N20N, W 104N20N, W	8004100335* 8004100303* 8004100034* 8004100182* 8004170273*	50-313 0 50-344 0 9A999 50-335 0 50-272 0
HUETER, L J HUFF, M HUFF, M HUFFAKER, T HUGHES, J	8004100383* 8004150601* 8004150579* 8004290501* 8004040179*	50-182 Q 50-348 F 50-348 F 50-349 A 50-10 Q	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8004230409 8004230414* 8004230441* 8004150185 8004230221	50-277 P 50-277 P 50-277 P 50-259 F 50-220 F	JOHNSON, D F JOHNSON, R W JOHNSON, R R JOHNSON, R R JOHNSON, M C	8004220427* 8004040090 8004020225 8004070347* 8004020201	50-272 Q XPORTLIC 50-344 Q 50-320 R 50-375 Q
HULMAN, L G HULMAN, L G HUNNICUTT, D M HUNNICUTT, D M	8004040052* 8004270119* 8004270125* 8004070091* 8004270212*	50-341 Q 40-3453 40-3453 QA999 QA999	IPPOLITO, T A	8004240167 8004180253 8004180258* 8004180278* 8004210008	50-933 f 50-220 f 50-220 f 50-220 f 50-321 f	н А «ИОЗИНОС Ч и «ИОЗИНОС В Э «ИОЗИНОС Н С «ДОЯЗИНОС	8004230073 8004040375 8004090458 8004080384 8004280143#	PR 71-6698 50-309 0 50-271 0 50-348 0
HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT D M HUNNICUTT, D M	9004080287* 8004140043* 8004030244* 8004010515* 8004080387*	QA799 QA799 QA799 QA799 QA799	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8004280252 8004240299 8004240307* 8004240329* 8004250007	50-277 F 50-277 P 50-277 P 50-277 P 50-277 P	JOHNSON, M C JOHNSON, A H JOHNSON, J H JOHNSON, W P	6004300119# 6004280125# 6004250299# 8004080697 6004080351	50-395 Q 50-250 Q 50-313 Q 50-387 G 50-309 Q
HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D 0	8004070297* 8004080316* 8004270031* 8004300222* 8004220315*	GA777 GA777 GA777 GA777 70-2623	IPPOLITO, T A	8004250017 8004250021 8004250024 8004250032 8004250034	50-271 P 50-263 P 50-331 P 50-333 P 50-220 P	М о МОЗБИНОГ В ИМОЗВИНОГ Н И ИМОЗВИНОГ Н И ИМОЗВИНОГ Н ИМОЗВИНОГ	8004080269 8004140061 8004100369* 8004040063 8004280087*	50-271 0 50-320 0 CDNTRACT 50-344 T 50-344 0
HUNSTAD, A A HUNSTAD, A A KUNSTAD, A A HUNSTAD, A A HUNSTAD, A A	8004140344* 8004080484* 8004140440* 8004150603* 8004180386*	50-282 R 50-282 B 50-282 B 50-306 B	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8004250037 8004280027 8004290028 8004290055 8004290104	50-293 P 50-293 P 50-259 P 50-321 P 50-249 P	ЈОНИВОМ, М С ЈОНИВОМ, Р Н ЈОНИВОМ, М С ЈОНИВОМ, М L	8004170085 8004280277* 8004250394* 8004140110 8004100306	50-395 B 50-397 G 50-10 H 50-395 G XPORTLIC
HUNTAD, A A HUNT, M D FHUNT, M D HUNT, M D HUNT, M D HUNT, M D	8004230359# 8004070084# 8004070374# 8004020194# 8004070331#	50~292 8 50~400 0 50~280 0 50~424 0 50~400 0	IPPOLITO, T A IPPOLITO, T A IRBY, 8 C IRLEYN, K S IRVINO, 8 M	B004300510 B004230283 B004030028* B004270501* B004230466	50-298 P 50-259 P 50-320 H 50-369 A 50-458 M	о и човинас о и човинос о и човинос о и човинос	8004140455 8004300478 8004280182 8004250404 8004250429	NUREO 50-395 G TOPREP 50-395 S 50-395 S
HUNT, H D HUNTER, V H HUNTER, V H HUNTER, R S HUNTER, R S	8004070183 8004040122* 8004070310* 8004210150 8004180181*	50~416 8 GA999 GA999 PR 50~319 G	18HII.M JABLON.R A JABLON.R A JACKIN.O N JACKBON.O N	8004100591 8004150610# 8004230176 8004080664 8004290141#	NUREO 50-263 8 50-389 M 50-331 B 50-324 Q	JOHNBON, B D JONES, D JONES, D JONES, O C	8004300436 8004080302 8004070312 8002040380 8004080274	50-280 J RES RES 50-320 G RES
HUNTER, R. E HUNTER, R. B HUNTER, R. B HUNTER, R. B HUSERY, D. E	8004140324 8004150509 8004150507 8004150510* 8004010368*	50-315 J 50-315 P 50-315 F 50-315 F 50-316 S	JACOBEA JACOBEA JACOBEA JACOBEA JACOBEA JACOBEA JACOBEA JACOBEA	8004210301 8004300021 8004020205 8004110127 8004150166	NUREO 50-559 A Contract Regod Contract	JONES, O C JONES, O L JONES, C E JONES, D W JONES, W C	8004070324 8004100597 8004040040# 8004100482* 8004290086	RES RES 50-373 0 70-1151 50-285 0
HUSEBY, D E HUSEBY, D, E HUSEBY, D, E HUSEBY, D E	8004150638* 8004220621* 8004270350* 8004270416* 8004270447*	50-318 5 50-317 8 50-318 8 50-318 8 50-317 8	JACOBB: A. JACOBB: A JACOBB: J C JACOBB: J C JAMES: M	8004240047 8004240009 8004220152 8004220152 8004270280	CONTRACT CONTRACT 50-445 M 50-449 M 50-133 G	JONES, E JONES, D W JONES, C E JONES, C E	6004230128# 8004040021# 8004040149# 8004140021 8004280074#	50-309 G 70-1201 50-500 G 50-285 G 50-454 G
HUSTON, R. W. HUSTON, R. W. HUSTON, R. W. HUSTON, R. W. HUSTON, R. W.	8004020166 8004020285 8004250313 8004250425 8004270324	80-255 P 50-155 R 50-255 Q 50-255 P 50-155 Q	JAMEB, 8 W JANACEK, R F JANACEK, R F JANECEK, R F JANECEK, R F	8004240545 8004070245 8004110458 8004010359 8004040341	NUREO 50-237 P 50-237 P 50-237 P 50-10 P	JONES, W C JONES, W C JONES, W C	8004220001 8004010346 8004140362 8004280038 8004150371	50-275 Q 50-285 P 50-285 P RES 50-285 R
HUTTON:PH HYDE:DW HYDE:DW IDSER:HW. IFFLAND:RR	8004040342 8004100418 8004140105 8004010382 8004150379	RES PR PR 50-312 Q 50-213 J	JANECEK, R F JANECEK, R F JANECEK, R F JANECEK, R F JANECEK, R F	8004080235 8004070227 8004110377 8004150344 8004180217	50-237 P 50-10 P 50-237 F 50-10 F 50-10 P	JDNES, W C JONES, J A JONES, J, A JONHSRUD, J H JORDAN, E L	8004220561 8004280560 8004280561 8004080143 8004220245*	50~285 P 50~400 S 50~400 S 50~387 G FOTA
I FFLAND, R. R. I QNE, E. I QNE, E I QNE, E I NGRAM, F	8004160254 8004070241* 8004070239 8004040246 8004180109	50-245 J ACRB ACRB ACRB 50-287 H	JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. JANENCEK, R. F. JANINEK, M.	8004220332 8004220348 8004230072 8004140395 8004250068	50-10 P 50-237 P 50-10 P 50-237 P State Prog	JORDAN, W H JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S	8004220350 8004160138* 8004160131 8004160138* 8004280026	50-287 0 50-287 0 50-287 0 50-287 0
INMAN.OW. IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	8004140455 8004080296 8004070377 8004070381 8004070384	NUREG 50-237 P 50-263 P 50-249 P 50-259 P	JANINEK, M JANUBKA, A G JAPE, F JAPE, F JASKE, R, T	8004270167 8004030327* 8004230277* 8004250357* 8004040379	State Prog FOIA 50-249 G 50-269 G NUREG	JORDAN, W S JORDAN, W H JORGENSEN, B L JORGENSEN, G D JOSEPH, R L	8004280026 8004100222 8004030327* 8004100357* 8004040403*	50-287 0 50-289 0 FDIA CONTRACT 71-35
IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A	8004070370 8004070375 8004070397 8004070400 8004070402	50-298 P 50-331 P 50-133 P 50-333 P 50-220 P	JAX,M JEANEB,J W JEFFERB,T JENKINB,G R JENKINB,G R	8004150129 8004030038* 8004040412 8004040365* 8004040402*	70-1308 50-320 H 40-8760 50-250 Q 50-269 Q	JDYNER, J. H JOYNER, J. H JOYNER, J. H JOYNER, J. H JOYNER, J. H	8004220068* 8004080354* 8004100209* 8004070207* 8004080599*	70-1143 70-135 70-135 70-1100 70-364
IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A. IPPOLITO, T A. IPPOLITO, T A.	8004070404 8004070405 8004070408 8004080187 8004080194	50-324 P 50-273 P 50-271 P 50-321 P 50-277 P	Jenkins, g v Jenkins, g r Jenkins, g v Jenkins, g v	8004070134* 8004140480* 8004070195* 8004150477* 8004150526*	50-337	JOYNER, J H	8004070417* 8004100555* 8004070217* 8004100072* 8004100030*	70-135 70-135 70-135 70-364 70-820

				ALCESSION	SUBJECT		ACCESSION NUMBER	SUBJECT CATEODRY
AUTHOR	WINDER EX	ATEODRY	AUTHOR	PUNILER	CATEGORY	AUTHOR KEPPLER, J G	0004100125	50-440 O
JOYNER, J H JULIAN, C JURENPO, R C JUPGENSEN, R W	80042200414 70°		NFLLUGG,F J HELLUGG,P J HELLUGG,P J KELLT,A HEMPER,J S	8004050111 80040801844 8004210371+	50-324	KEPPLER J G KEPPLER, J G VEPPLER, J G KEPPLER, J G KEPPLER, J G	8004100134 8004100134 8004100135	50-329 d 50-155 d 50-409 d 50-331 d
KABAK, A C KAHLE, J B YAHLE, J B KAHLE, B KAHLE, B	8004210176* 70 8004040097* 70 8004280255* 70 8004040130* FO	-1113 1151 1319	VEMPER, J S KEINPER, J S MENNA, II B KENNA, II B	E\20414024 BAEVOE1608 *0450904698	50-352	KEPPLER, J C KEPPLER, J C KEPPLER, J C KEPPLER, J C	8004100138 8004100139 8004100143 8004100144 8004100146	40-461
FAISER, W. T FALIVIANATS, R KALIVIANATS, R KALIVIANATS, R KALIVIANATS, R	8004150004 50 6004020422 50 8001020435 50 8004020350 50	0-254 R 0-254 S 0-265 S 0-254 S	KENNA, U B KENNA, U B KENNA, U B KENNA, U B KENNA, U B	8004070054 8004210167 8004040037 8004040000	70-1+3 70-1113 70-143 70-1151 70-1151	KEPPLER J G KEPPLER J G KEPPLER J G KEPPLER J G KEPPLER, J D	8004100148 8004100149 8004100153 8004070212 8004070221	50-483 0 50-266 0 50-305 0 50-331 P 50-409 P
Kalivianakis, n Kalivianakis, n Kalivianakis, n Kalivianakas, n Kalivianakis, n	8094020430 50 8394150463 50 8394150462 50 8004150457 50	0-265 S 0-265 S 0-254 S 0-265 S 0-254 S	PENNA, H B KENNA, H B KENNA, H B KENNA, H B KENNA, H B	8304040018* 8304040323 8304040113 80040404012 8001090232	70-1201 70-2478 70-143 70-1201 70-143	MCPPLET O MEPPLET.J G MEPPLET.J G MEPPLET.J G MEPPLET.J G	8004070778 6004080187 8004080824 8004090379 8004100076	50-283 P 50-305 F 50-286 F 50-255 0 50-155 P
KALIVIANAKAS, N KALIVIANAKIS, N KALIVIANAKIS, N KALTMAN, M KAMM, R	8004220333 \$ 8004270380 \$ 8004250271 \$ 80040800004 F	0-255 S 0-254 R 0-265 S 0-320 P	KENIA, W B KENNA, W B KENNA, W B KENNA, W B KENNA, W B	8004100456 8004070351 9004070361 8004110545 8004110562	70-1151 70-143 70-143 70-2479 50-309 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	BOU4100102 BOG4100114 BON4100154 BOO4100165 BOO4100170	50-10 P 50-409 P 50-255 P 50-315 P 50-331 P
KAMMERER, C KANAK, K KANE, J D KANE, J D KANE, B F	8004160075 R 8004270115* 4 8003200211 5 8004110522 5	1180 10-3453 50-362 A 30-470 A	KENNA, W B KENNA, W B KENNA, W B KENNA, W B KENNA, W B	8004210155 8004220188 8004270170 8004270151 8004270471	00-1113 50-259 50-259 00-259	KEPPLER, J C KEPPLER, J C KEPPLER, J C KEPPLER, J C	8004100172 8004100175 8004100183 8004100186 8004240524	50-246 P 50-346 P 50-263 P 50-305 P 50-346 F
KAPLAN A L KAPLAN A L KAPLAN A L KAPLAN A L KAPLAN A L	8304(10109 F 8004160078 F 8034230163 7 8004210162*	-R -R 70-1113 70-1113	KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, R T	8004280485 8004300597 8004270126 8004230233 8004277131	COM418810N COMM18810N COMM18810N COMM18810N	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004240531 8004240540 8004300012 8004300925 8004300925	50-10 F 50-155 F 50-318 F 50-349 B 50-546 &
KAPLANIA L KAPLANIA L KAPLANIA L KAPLANIA L KAPLANIA L	8004183121* 8004090149 8004020143 8004180515	70-1113 70-1113 70-1113 71-9019 70-1007 71-9019	KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, B T KENNEDY, R T	8004390231 8004290134 8004300591 8004280444 8004290144	COMMISSION COMMISSION COMMISSION COMMISSION	REPPLER, J O VEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8004140484 8004150162 8004150153 0804150159 8004150163	50-315 0 50-315 0 50-315 0 50-10 0 50-358 0
Kaplan, a l Kapple, a h Kapple, a h Kapple, a h Karkan, n	8004223796* 8004010370* 8004110494* 8004290217	71-9019 50-272 S 50-272 S 50-454 G F01A	KENNEDY, R T	8004280448 8004280450 8004280453 8004280464 8004280468	COMMISSION COMMISSION COMMISSION COMMISSION	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004150172 8004150167 8004150170 8004150170	50-440 Q 50-327 Q 50-159 Q 50-409 Q 50-341 Q
KARTHAIN X KARTHAIN X KARTHAIN X KATZIB E KAUFHANIN C	9004220444* 8004220539* 8004230011	FD1A FD1A FD1A RES 40-8728	PENNERLY, F H KENNETT, R J KENT, B C KEPFORD, C R KEPFORD, C	8004220331* 8004280071 8004140268 800414006/* 8004140076*	70~2423 RE9 90~387 A 90~320 0 90~320 0	KEPPLER, J C KEPPLER, J C KEPPLER, J C KEPPLER, J C	B004150174 BC04150175 B004150184 B004150184	50-J31 G 50-461 & 50-367 G 50-269 G 50-546 G
Kaufman, R 9 Kaufman, D H Kawahara, B Hay, J A Kai, J A	8004100504 8004240190* 8004230064 8004100370 8004110415	50-289 H 10-2805 50-29 P 50-29 R 50-29 P	KEPFORD, C KEPFORD, C KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004110477 8004240544 8004220051* 800422015*	PR 50-207	KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004150191 8004150192 8004150194 8004150196 8004080686	50-346 G 50-483 G 50-266 G 50-305 G 50-10 G
KAY, JA KEARNS, JJ KEARNEY, JV KEE, EJ	8004280500 8004100540 8004110547 8004110367 8004080684	50-29 P PR PR RES TOPREP	KEPPLER, J O KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220164* 8004220221* 8004220231* 8004220246* 8004220251*	PDIA FDIA FDIA FOIA FOIA	KEPPLER. J G KEPPLER. J G KEPPLER. J G KEPPLER. J G	9004090694 9004090699 9004090702 9004090704 9004090706	50~358 G 50~440 G 50~327 G 90~155 G 50~407 G
KEENAN, T P KEEPLER, J Q KEHOE, D KEHOE, D KEHOE, D V	8DD429DD39 8D04040411* 8D04160153* 8D04090473* 8D04040244	50~295 F 50~293 G 50~293 G 50~293 G	Keppler, J Q Keppler, J O Keppler, J O Keppler, J G Keppler, J G	8004220259* 8004220257* 8004220314* 8004220317* 8004220323*	F014 F014 F014 F014	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	BDD40B0708 B0040B0710 BD040B0714 B0040B0717 B0040B071B	50-341 0 50-331 0 50-441 0 50-315 0 50-367 0
KEIL J KEIMIO, R R KEIMIO, R R KEIMIO, R R	8004040251 8004280070* 8004280070* 8004070422* 8004080450*	50-352 H 50-334 P 50-219 Q 50-219 G 50-213 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220329# 8004220330# 8004220337# 8004220351# 8304220366#	FOIA FOIA FOIA FOIA FOIA	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	800408071 <i>9</i> 8004080721 8004080724 8004080725 8004080727	
KEIMIG,R R KEIMIG,R R KEIMIG,R R KEIMIG,R R KEIMIG,R R	8004170273* 8004220427* 8004210450* 8004180147* 8004070118	50-272 0 50-272 0 50-219 0 50-245 0 50-245 5	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8004220403* 8004220465* 8004220467* 7906050031 8304170262*	F01A F01A F01A MISC 50-255 0	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8004080778 8004180011 8004180014 8004180024 8004180034	50-315 G 50-10 G 50-358 G
MECTOGOS & N WETTEN D WETTEN D WETTEN D WETTEN G	8004040262* 8004080696* 8004100005* 8004100416* 8004090252*	50-285 0 50-285 0 04999 50-395 0 50-259 0	KEPPLER, J O KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004040022 8004100548 8004040414 8004040285 8003310412	50-341 0 40-261 50-546 0 50-315 0 40-215	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004150035 8004150037 8004150037 8004150040 8004150044	50-195 0 50-407 0 50-341 0
KETFOGO'L N WETFOGO'L N WETFOGO'L N WETFOGO'L N WETFOGO'L N	8004090413* 8004240914* 8004240014* 8004240157* 8004060361	50-327 0 50-338 0 50-395 0 50-325 0 50-281 8	Keppler, J o Keppler, J o Keppler, J g Keppler, J g	8004230167 8004020268 8004100114 8004100118 8004100123	50-123	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004150045 8004150045 800415005 800415005 800415005	50-367 G 50-263 G 50-546 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004150057 8004150059 8004150041 8004180018 8004180030	50-483 Q 50-266 Q 50-305 Q 50-315 Q 50-10 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004230285 8004230288 8004230291 8004230297 8004240561	50-346 Q 50-266 Q 50-305 Q 50-263 Q 50-331 F	KISTER, H B KISTER, H B KITTRIDGE, G R KITTRIDGE, G R KLAMERUS, Ł J	8004100077# 8004210071# 8004090156 8004210160# 8004280206#	50-322 G 50-244 G PR PR REVIEW GRP
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004180037 8004180038 8004180040 8004180041 8004180048	50-358 Q 50-440 Q 50-155 Q 50-329 Q 50-409 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004300479 8004270080 8004220047 8004220053 8004220057	50-266 P 50-123 0 50-263 0 50-266 0 50-346 0	KLEIN, J V II KLEIN, J V KLEIN, P W KLEINSDRGE, II P KLEIN, B	8004100046* 8004100450* 8004040127 800430010B* 8004030012	PR 50-516 T 50-322 G 50-566 Q 50-312 H
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004180050 8004180051 8004180052 8004180054 8004180055	50-341 Q 50-331 Q 50-461 Q 50-367 Q 50-263 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220060 8004220069 8004220089 8004220094 8004220098	50-305 Q 50-10 Q 50-331 Q 50-546 Q 50-483 Q	KLIGFIELD, G KLIGFIELD, G KLIGFIELD, G KLIGFIELD, G	8004240416 8004240420 \$ 8004240012 8004240022 8004250057	50-128 R 50-128 R NUREO NUREO NUREO
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004180059 8004180060 8004180063 8004180065 8004180067	50-546 Q 50-346 Q 50-483 Q 50-266 Q 50-305 Q	KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	8004220100 8004220104 8004220108 8004220114 8004220121	50-341 0 50-409 0 50-338 0 50-347 0 50-329 0	KLINGER, G KLINGER, O KLINGER, G KLINGER, G KLINGER, O	8004210433 8004210440 8004210441 8004210224 8004180517	50-304 S 50-247 S 50-335 S 50-344 S 50-346 S
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220090 8004220093 8004220113 8004220118 8004220123	50-319 Q 50-10 Q 50-358 Q 50-440 Q 50-199 Q	KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	8004220129 8004220139 8004220144 8004220149 8004150489*	50-315 Q 50-440 Q 50-461 Q 50-155 Q 50-341 Q	KLINDER, G KLINDER, O KNAPP, P J KNAPP, P J KNAPP, P	8004180518 8004180520 8004100173* 8004210173* 8004090027	50-257 S 50-255 S 50-220 G 50-273 G 50-213 S
KEPPLER, J. G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220126 8004220135 8004220138 8004220140 8004220142	50-329 Q 50-409 Q 50-341 Q 50-331 Q 50-461 Q	KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	8004300166 8004300178* 8004300184* 8004300189* 8004300194*	50-483 0 50-483 0 50-483 0 50-483 0 50-483 0	KNOGHT,R J KNOP,R C KNOP,R C KNOP,R C KNOP,R C	8004170270 8004040062* 8004040475* 8004040052* 8004210142*	XPORTLIC 50-483 0 50-327 0 50-341 0 50-350 0
KEPPLER, J. O KEPPLER, J Q KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220145 8004220149 8004220150 8004220151 8004220153	50-367 G 50-263 G 50-346 G 50-346 G 50-483 G	KERNE,A C KERR.G W KERR.G W KERR.G W KERR.G W	8004100040* 8004110144 8004070355* 8004140181 8004040470	50-443 Q WASTE MOT WASTE MOT State Prog State Prog	KNOP, R C KNOP, R C KNOP, R C KNOP, R C KNOTE, J D	8004100267* 8004070037 8004040037 8004040048 8004230033	50-327 0 50-329 8 50-461 8 50-341 8 50-449 M
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8004220158 8004220160 8004220324 8004220336 8004220339	50-246 G 50-305 Q 50-10 G 50-327 G 50-315 G	KERR, O W KERR, O W KERR, O W KERR, O W KERR, O	8004070368 8004140189 8004240077 8004240081* 8004040385	State Prog State Prog State Prog State Prog 50-2 P	0 C'STIONY 0 C'STIONY 0 C'STIONY 0 C'STIONY	8004030258 8004080401 8004180151 8004240173 8004240173	50-445 M 50-445 M 50-445 M 50-445 M
KEPPLER, J O KEPPLER, J O KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220344 8004220347 8004220354 8004220357 8004220345	50-358 Q 50-440 Q 50-341 Q 50-407 Q 50-155 Q	KERR.O W KERR.O W KERR.O W KERR.O, W KETCHEN.E O	8004240002 8004240004* 8004280323 8004280327* 8004020086	ORO ORO State Prog State Prog 50-275 O	В Г'STIONY В Г'STIONY В Г'STIONY В Г'STIONY	8004240071* 8004240562 8004220021 8004240562 8004230033	50-449 M 50-445 M 50-445 M 50-445 M 50-445 M
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J. O	8004220368 8004220373 8004220378 8004220382 8004220384	50-461	KETCHEN, E O	8004080372 8004180432 8004230081 8004160197 8004230210	70-2423 50-269	KNUDBON, D A KNUTH, D F KOCH, E I KOCIB, R KOESTER, O L	8004290467* 8004250071 8004220355* 8004110386* 8004040264	50-390 A PR FDIA 50-344 B 50-482 S
KEPPLER. J. O KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER, J. O	8004220388 8004220392 8004220399 9004220398 8004220058	50-483 0 50-266 0 50-305 0 50-546 0 70-8	KETZLACH, N KEY, W J KEY, W J KEY, W J KEY, W J	8004020153 8004030255* 8004040337* 8004110176* 8004280025*	70-1100 50-304 G 50-295 G 50-440 G 50-265 G	KDESTER, G L KDESTER, G L KDESTER, G L KDESTER, G L KDESTER, G L	6004010030 6004010034 6004170172 8004070292 6004220730	50-482 Q 50-482 B 50-482 B 50-482 S 50-482 I
KEPPLER, J. O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8004220059 8004220063 8004220065 8004220066 8004220070	70-572 70-1309 40-7982 40-2061 70-925	KIDDS,M S KIMBLE,K KIMMEL.J J KINDER,E T KINDER,E T	8004240378* 8004280540* 8004030014* 8004100612* 8004070187	50-338 G 50-320 H CONTRACT PR PR	KOHL, K A KOHLER, J E KOHLER, J E KOJAHN, C	B004140322* 8004140340* 8004220175* 8004280641 8004210395*	50-275 R 50-10 R 50-295 Q 50-295 B 50-275 Q
KEPPLER, J Q KEPPLER, J Q KEPPLER, J. Q KEPPLER, J Q KEPPLER, J. Q,	8004220073 8004110023 8004110025 8004110032 8004110033	70-1193 50-373	KINDER,E T KING,W H KING,B, KINNEMAN,J KINNEMAN,J	8004070202* 8004020137* 8004020159 8004090178 8004090197	PR 71-5939 Waste Mot 1&e 1&e	KOLTAY, P S KOLTAY, P KOMES, J M KOMES, J M KONAK, K K	8004070231* 8004090262* 8004090386* 8004090377* 8004040369	50-245 Q 50-217 Q GA999 GA999 RES
KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	8004110034 8004110035 8004110036 8004110041 8004110042	50-155 G 50-407 G 50-341 G 50-331 G 50-461 G	KINSEY, W. H KINSEY, W. H KINSEY, W. H KINSEY, W. H	8004020371* 8004010506* 8004070426* 8004080526* 8004080622*	50~327	KONKLIN, J E KOTTAN, J J KONKLIN, J E KONKLIN, J E	8004110174* 8004280074* 8004080352* 8004090274* 8004010282	50-440 0 50-454 0 50-317 0 50-320 H FOIA
KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	8004110043 8004110047 8004230196 8004230197 8004230201	50-367 Q 50-263 Q 50-155 Q 50-409 Q 50-440 Q	KINSEY,W H KINTNER,L L KINTNER,L L KIRBY,M S KIRK,W F	8004090433* 8004090155 8004110088 8004180337* 8004210043	50-327 B 50-413 A 50-341 A 50-390 R 70-371	KRAUSE, L KREDS, A H KREMSER, T R KRIEMELMEYER, H KROES, R J	8004030352 8004150431 8004160151* 8004070279* 8004070328	50-382 H 50-124 P 70-1251 50-320 H 50-433 R
KEPPLER, J G. KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004230207 8004230211 8004230217 8004230224 8004230245	50-358	KIRK.W F KIRKEBO,J A KIRKLAND.R 8, KIRKLAND.R 8 KIRKLAND.R 8	8004210067* 8004040057* 8004280486 8004280477 8004280512	70-371 50-458 \$ 50-160 \$ 50-160 \$ 50-160 \$	KROOM, J C KROOM, J C KROOM, J C KRSYKWA, E J KRUO, M E	8004100543 8004100071 8004220210 8004300061* 8004280231	REGOD REGOD REGOD 50-397 O WASTE MOT
KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8004230250 8004230266 8004230274 8004230280 8004230282	50-544 G 50-461 Q 50-331 Q 50-367 Q 50-483 Q	KIRSCH, DF KIRSCH, DF KISIELESKI, WE KISS, E KISTER, HB	8004240522* 8004280022* 8004100584 8004070476* 8004070123*	50-528	KRUMPOS, P J KUEHNLE, G KUEHIN, J L KULLBERO, J A	8004180307* 8004150400 8004110308 8004040108 8004180127	50-304 G 50-320 H 50-155 P 50-387 H 50-344 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KURTH, W R KURTIZ, R J KUSHNER, W L KUSHNER, W L KUSHNER, W L	8004040342 8004040354* 8004080733* 8004100209*	50-304 8 RES 70-135 70-135 70-135	LEGNARD, J D LEGNARD, J D LEGNARD, J D LEGNARD, J D LEGNARD, J D	8004220445 8004080419 8004090125 8004090452 8004080266*	50-333 Q 50-333 Q 50-333 Q 50-333 Q	LEWIS,S R LEWIS,R C LEWIS,S R LIAW,B D LIAW,B D	8004160232* B004300143 B004220690* B004150042 B0042B0103	50-287 5 50-302 9 50-269 5 NUREG TOPREP
KARHNEW'M F KAFE'T & KAGEB'T Y KARHNEW'M F KARHNEW'M F	6004080733* 8004100555* 6004140470 8004070227 6004220068*	70-135 70-135 NUREO PR 70-1143	LEONARD. J D LEONARD. J D LEONARD. J D LERNER. N C LESH. L	8004030273 8004030216 8004070296 8004080340* 8004220181*	50-333 S 50-333 S 50-333 R CONTRACT 50-320 H	LIBERMAN, J LIBRIZZI, F P LIBRIZZI, F P LIBRIZZI, F P LIBRIZZI, F P	8004210232 8004010331 8004010322 8004010354 8004040317	50-295 Q 50-272 R 50-272 B 50-272 B 50-272 B
LADUN.R LADUN.R LADUN.R H LAGERGREN.B LAGIEWSKI.J S	80040702214 8004100068* 8004250059* 8004220707* 8004010448*	50-201	LESLIE.R B LESSOR.L C LESSOR.L C LEVINSON.C F LEVIN.H A	8004210329* 8004280574 8004090303 8004080134* 7812040303	50-275 G 50-298 S 50-298 R FOIA 50-10 P	LIBRIZZI,F P LIBRIZZI,F P LIBRIZZI,F P LIBRIZZI,F P LIBRIZZI,F P	8004080390 8004110492 8004080525 8004110497 8004140320	50-272 P 50-272 8 50-272 8 50-272 G 50-272 G
LAGIEWSKI, J S LAGIEWSKI, J S LAGIEWSKI, J S LAGIEWSKI, J S	8004010388* 8004150620* 8004250417* 8004270377* 8004270388*	50-318 S 50-317 S 50-318 8 50-317 S 50-317 S	LEVINE, S LEVINE, S LEVINE, M M LEVINE, M M	8004020158 7909140279 8004230300 8004080585 8004100594	RES MISC RES RES RES	LIBRIZZI,F P LIBRIZZI,F P LIBRIZZI,F P LIBRIZZI,F P LICHTENBERGER,H	8004140407 8004150553 8004170062 8004250366 8004210138*	50-272 B 50-272 B 50-272 P 50-272 P 70-1100
LAGIEWSKI, J S LAGOMARSINO, R J LAINAS, G LAINAS, G LAINAS, G	8004290472* 8004030013 7908030084 7908100158 7910020720	50-317 5 50-275 U HISC MISC MISC	LEVINSON, J O LEVIN, K F LEVIN, K F LEVIN, K F LEVINSON, J O	8004030025* 8004100027 8004100027 8004100027 8004030018*	50-3 H 50-454 G 50-454 G 50-454 G 50-3 H	LICHTENBERGER LICHTENBERGER, H LICITRA, E A LICITRA, E A LICITRA, E A	8004240169 8004210130* 8004040472 8004100526 8004140486	70-1100 70-1100 50-311 A 50-311 A
LAINAS, G LAINAS, G LAINAS, G LAMACCHIA, P J LAMB, H R	8004020178 8004030107 8004070263 8004290113* 8004110480	50-259 P 50-368 F GEN TEC IS CONTRACT PR	LEVIN, S LEVIN, H A LEVINE, M M LEVINE, J A	8004100561 8004090259 8004010426 8004150475 8004290092	RE00D 50-10 P 50-334 G RES 50-334 T	LICITRA, E A LIEBERMAN, J LIEBLER, G E LIEBLER, G E LIEDER, C	8004140016 7911050375 8004020011* 8004110216 8004100079	50-275 A HISC 50-387 D TOPREP PR
LANCASTER, K F LANCASTER, K F LANCASTER, K F LANDSHAN, R B LANGE, B L	8004020323* 6004070315* 8004270488* 8004040077* 8004220200	50-302 5 50-302 8 ,50-302 8 50-483 G WASTE MOT	LEWIS, N D LEWIS, R C LEWIS, R C LEWIS, R C	80040103454 8004240170* 8004300171* 8004300158* 8004040250*	50-508 A 70-135 50-302 G 50-302 G 50-280 G	LIKE, I LIKE, I LIN, Y L LINDMALD, W J LINDER, F	8004100041 8004100440 8004110500* 8004180357 8004010108	PR 50-322 T 50-272 G 50-514 F 50-409 G
LANOE,S L LANOLEY.C LANOLAND,R T LANNING,D D LANTZ,P M	8004020046 8004100544* 8004030002 8004210298 8004150036	WASTE MOT PR NUREG NUREG RES	LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8004020252* 8004230249* 8004150079* 8004100409* 9004040232	50~259	LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8004150119 8004090369 8004140312 8004140365 8004150204	71-6400 50-407 P 50-407 P 50-407 R 50-407 P
LANTZ, E LANTZ, E LARINI, O J LAROCHE, G LATHAM, B B	E004140227* 8004140230* 8004300017* 8004300005* 8004210007*	50-269 0 50-269 0 50-387 0 50-289 0 50-322 0	LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8004090036# 8004300230# 8004150142# 8004040447# 8004090245	50-321 Q 50-267 Q 50-321 Q 50-302 Q 50-257 Q	Linder, F Linder, F Linder, F Linder, F Linder, F	8004150489 8004220584 8004210200 8004290341 8004300456	50-407 B 50-407 B 50-407 B 50-407 B 50-407 B
LAUDIG, S LAUTZENHEISER, C LAUTZENHEISER, C LAUTZENHEISER, C LAVERTY, E	8004150217 8004040295* 8004040296* 8004040301* 8004160176*	FOIA 50-317 G 50-317 G 50-317 G 50-3 H	LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8004100178 8004090405 8004100195 8004250340* 8004240383*	50-335	LINEBARGER, J H LINEHAN, J J LINEHAN, J J LINEHAN, J J LINENBERGER, G	8004170120 8004080607 8004070249 8004070387 8004230055	RES 40-1162 40-9452 40-9802 50-446 Q
LAWSON, J D LAWSON, L LAZA, R M LAZA, R M LAZARUB, W J	8004180120* 8004100331 8004090162 8004090321 8004210053*	50-287 H 50-387 G SECY SECY 50-309 G	LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8004070133 8004240373 8004240408 8004210105 8004280233	50-302 Q 50-338 Q 50-280 Q 50-302 Q 50-335 Q	LIPINGKI.W C LIPINGKI.W C LIPPOLD.W J LITTLE.L W	8004080639* 8004040469 8004020226 8004300079 8004220350	ACRB 50-20A D ACRB 71-383 50-287 Q
LAZD,R M LEAR,G LEAS,J LEBOEUF.R J LEE,B	8004080626 8004150151 8004210072 8004110480 8004170350*	50-133 0 50-335 P 50-320 C FR 10CFR	LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8004020242 8004280115 8004280134 8004280005 8004280150	50-259	LITTLE, W 8 LITTLE, W 8 LITTLE, R LITTLE, L W LITTLE, L W	8004220175* 800408044 8004210290* 8004100222 8004300001	50-295 0 50-331 B 50-10 H 50-267 Q 50-269 0
LEE.B LEE.E W LEE.J C LEE.J C LEE.D R	8004280493 8004070173* 8004280039* 8004030300 8004210166*	50-320 P 50-483 Q 50-454 Q ACRS 50-267 Q	LEWIS.S H LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8004020454 8004280057* 8004100395 8004040439 8004090032	50-312 0 50-324 0 50-395 0 50-302 0 50-321 0	LITVACK, B K LITVACK, B M LITVACK, B M LITVACK, B M LOCHSTET, W A	8004070475* 8004140104* 8004110139* 8004030207 8004110078	50-293 H 50-443 H 50-482 H 50-482 H 50-320 O
LEECH,K LEIBY,A C LEITHAUSER,J A LEITHAUSER,J LEITHAUSER,J A	8004150448* 8004110480 8004180402* 8004030363 8004180396	50-254 S PR 50-155 Q 50-155 Q 50-155 Q	LEWIS.R C LEWIS.S H LEWIS.R C LEWIS.R C LEWIS.S H	8004280050 8004020110 8004080183* 8004080178 8004030329	50-324 Q 50-286 D 50-337 Q 50-337 Q 50-312 Q	LOCKE, R F LOCKE, E U LOCKE, R F LOCAN, F LONERGAN, Q T	8004150003 8004010472 8004240384 8004110017* 8004140110	50-133 Q 50-443 Q 50-275 F 50-387 Q
LEITZELL,T L LEM,A LEMPGES,T E LEMPGES,T E LEMPGES,T E	8004170250 8004300033* 8004110055 8004100401 8004010373	50-272 P 50-387 0 50-220 0 50-220 0 50-220 0	LEWIS, 8 H LEWIS, 8 H LEWIS, 8 C LEWIS, 8 H	8004010292 8004080362 8004080414 8004230202 8004080329	50-312 0 50-312 0 50-312 0 50-267 0 50-312 0	LONERGAN, 0 T LONERGAN, 0 T LONERGAN, 0 T LONG, F J LONG, F J	8004220186* 8004220176* 8004220466* 8004300135* 8004070046	FOIA FOIA FOIA 50-395 Q 70-143
LEMPOES, T E LEMPOES, T E LEMPOES, T E LENAHAN, J J	8004010372 8004040404 8004080642 8004140406 8004040430*	50-220 Q 50-220 R 50-220 Q 60-220 R 50-424 Q	LEWIS, S R LEWIS, S H LEWIS, S R LEWIS, R C LEWIS, R C	8004070330* 8004080322 8004030224* 8004150065 8004150126	50-269 8 50-312 0 50-287 8 50-321 0 50-321 0	LONGBHORE, M L LOOMIB, J S LORENZ, R A LOSB, F J LOVE, E	8004040119 8004100546 8004170336 8004290009 8004100064	50-352 11 REOGD NUREO NUREO PRM
LENAHAN, J J LENAHAN, J J LEON, A LEONARD, J	8004020220* 8004090392* 8004240434* 8004040174 8004210360*	50-375 Q 50-438 Q 50-471 Q 50-387 H 50-320 H	LEWIS,R C LEWIS,R C LEWIS,M I LEWIS,8 R LEWIS,R C,	8004240371 8004250330 8004250053 8004080476* 8004210206*	50-250 G 50-267 G 50-269 G 50-269 E 50-160 Q	LOWE, A L. LOWERRE, R W. LOWRY, L M LUMB, R F LUNDVALL, A E	8004020475* 8004140281 8004300192 8004070485* 8004220441	TOPREP 50-466 Q NUREQ CONTRACT 50-317 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO
LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	8004090139 8004030311 8004080335 8004080333* 8004090243	50-317 Q 50-317 Q 50-317 Q 50-317 Q 50-317 Q	MACDONALD, C E	8004100212 8004100216* 8004100220 8004100224* 8004100228	71-4272 71-4272 71-4574 71-4574 71-9073	MANN, D L MANRY, M MANRY, M MANRY, M MANRY, M	8004070463 8004150454 8004020343 8004020361 8004010474	PR 50-346 50-366 50-366 50-321
LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	8004210192 8004010463 8004070275 8004040291 8004080465	50-317 R 50-317 P 50-317 R 50-317 G 50-317 P	MACDONALD,C E MACDONALD,C E MACDONALD,C E MACDONALD,C E MACDONALD,C E	8004100230* 8004100250 8004100254* 8004100259 8004100262*	71-9073 71-9009 71-9009 71-6078 71-6078	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004020315 8004020325 8004020428 8004150425 8004070314	50-366 50-366 50-366 50-366 50-366
LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNER, C	8004100227 8004170111 800417023B 8004280435 8004030294	50-317 P MISC 50-317 P 50-317 P PR	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8004180400 8004090014 8004090017* 8004100178 8004100200*	71-252 71-380 71-380 71-4679 71-4679	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004020354 8004010321 8004150410 8004040427 8004040414	50-321 50-321 50-366 50-364 50-321
LUGUE, N LUGUE, N LUTKEN, D C LUTKEN, D C	8004020181* 8004020170* 8004170340 8004280371* 8004280365	50~445 M 50~445 M 50~445 M 50~416 K 50~416 K	MAGDONALD, C E	8004100224 8004100229* 8004100231 8004100236* 8004100329	71-97 71-97 71-96 71-96 71-273	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004070281 8004110472 8004110479 8004150451 8004150474	50-321 50-366 50-366 50-366 50-366
LYNCH, M D LYNXH, J X LYONG, E HACDGNALD, C E	6004110345 8004150084 6004030307 8004210373* 8004690225*	50-397 A 50-367 A F0IA 50-320 H 71-9	MACDONALD, C E	8004100332+ 8004100336 8004100341+ 8004100346 8004100349+	71-273 71-116 71-116 71-367 71-367	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004150562 8004280531 8004150383 8004150388 8004150393	50-366 50-366 50-366 50-321 50-366
MACDONALD, C E MACDONALD, C E MACDONALD, C, E MACDONALD, C E MACDONALD, C E	8004110125 8004270475 8004020360 8004020364* 8004020373	71-6144 71-5 71-250 71-250 71-13	MACDONALD, C E	8004210418 8004280307 8004280314* 8004210019 8004210021*	71-6375 71-5395 71-5395 71-9142 71-9142	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004150399 8004220615 8004220628 8004220662 8004220713	50-321 50-366 50-366 50-366 50-321
MACDONALD, C E	8004070380* 8004010001 8004040092 8004070147 8004070152*	71-13 71-9006 71-9070 71-24 71-24	MACHAMER, G E MACKIN, J L, MACRAE, C F MADDEN, W MADDEN, W	8004300066* 8004020196 8004250052 8004250059* 8004210330*	50-387 G WABTE MOT NUREG 50-213 G 50-217 G	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004220728 8004220464 8004220452 8004220475 8004220689	50-366 646-07 646-07 646-07 646-07 646-07
MACDONALD, C E	8004020300 8004020304 800403009 8004030100 8004030104	71-9045 71-9049 71-9046 71-9016 71-9015	MADDEN, W MADDEN, W MADISON, W R MADISON, W R MADBEN, G L	8004150193* 8004280632 8004170211* 8004170212* 8004090151	70-371 50-320 S 50-338 R 50-338 R 50-313 Q	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004220705 8004220706 8004220726 8004280416 8004280441	50-366 50-366 50-366 50-366 50-366
HACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8004030114 8004030124 8004040082 8004040085 8004040374	71-9050 71-5938 71-9407 71-9072 71-230	MADSEN, O L MADSEN, O L MADSEN, O L MADSEN, O L MADSEN, O L	8004040252 8004100315 8004080691 8004040128 8004080600	50-285 Q 50-285 Q 50-285 Q 50-267 Q 50-267 Q	MANRY, M MANRY, M MANSER, W C MANSER, W C MANSER, W C	8004280570 8004280582 8004070237* 8004180482 8004180143	50-321 50-321 70-143 70-143 70-143
MACDONALD, C E	8004040388 8004040393 8004040462 8004070053 8004070133	71-370 71-135 71-5939 71-5998 71-180	MADSEN, O L MADSEN, O L MADSEN, O L MADSEN, O L MADSEN, O L	8004080402* 8004040089 8004030246 8004210175 8004210443*	50-267 Q 50-313 Q 50-278 Q 50-445 Q 50-445 Q	MANSER, W C MANSER, W C MANSER, W C MARCHAND, R MARCHAL, J	8004040041* 8004070049* 8004070235* 8004020458* 8004180229	70-143 70-143 70-143 50-320 XPORTLIC
MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E	8004030142 8004040157 8004040381 8004040458 8004040478	71-9036 71-5979 71-9007 71-6375 71-6387	MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, G	8004070143 8004210211 8004210432 8004070113 8004280057*	50-313 0 50-298 0 50-445 0 50-368 0 50-324 0	MARCHI'M L MARCUS'S F MARKOWSKI'R S MARKOWSKI'R S MARKWORTH'A J	8004220648* 8004140449* 8004300244* 8004210071* 8004300192	50-305 50-456 50-244 50-244 NUREG
MACDONALD, C E HACDONALD, C E HACDONALD, C E HACDONALD, C E HACDONALD, C E	8004070010 8004070014* 8004070018 8004070020* 8004070068	71-9079 71-9079 71-9080 71-9080 71-9043	MADSEN, Q L MADSEN, Q L MADSEN, O L MADSEN, D B MADSEN, Q L	8004070033 8004070036* 8004240306 8004300087 8004210163	50~285 Q 50~285 Q 50~313 P	MAROTTA,C R HAROTTA,C R HARRC	B004160221* B004160224*	50-269 50-269
MACDONALD, C E	8004080093 8004080097* 8004080107 8004080112* 8004020294	71-9019 71-9019 71-9089 71-9089 71-379	MADSEN.G L MADSEN.G L MAGAR,T.R MAGROW,R A MAGROW,R	8004270005 8004270011* 8004220284* 8004020337* 8004150513*				
MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C. E MACDONALD, C E	8004080205 8004070201 8004070203* 8004070214 8004070218*	71-9132 71-373 71-373 71-372 71-372	MAJOR,R MAJOR,R K MAKIPENTTI,I MALARO,J C MALARO,J C	8004100375 8004100508 8004250007 8004220491* 8004220488*				
MACDONALD, C E MACDONALD, C E, MACDONALD, C E, MACDONALD, C E, MACDONALD, C E,	8004070222 8004070226* 8004070227 8004070230* 8004100270	71-375 71-375 71-165 71-165 71-5796	MALINAUSKAS, A MALLORY, MALMROS, M. H MALMROS, M. H MALDNEY, Q, P	8004170336 8004220274 8004180327 8004280087 8004030204				

8004080520 8004080534 8004080367 8004080304 8004020064

8004100445 8004080242 8004210406 8004180073 8004080059

71-9010 71-9010 71-377 71-377 71-49

71-49 71-9020 71-9020 71-5908 71-5908

8004040121 8004040124* 8004070270 8004070273* 8004100239

8004100242* 8004100036 8004100038* 8004100205 8004100208*

HACDONALD, C E.
HACDONALD, C E.
MACDONALD, C E.
HACDONALD, C E.
HACDONALD, C E.

MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E

MALONEY, 0 P MALONEY, 0 P MALONEY, 0 P MALONEY, 0 P MANCINI, A, J

MANCUSD, F MANDLER, J W MANFRED, K M MANGUSI, J MANN, M M

AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUDJECT CATEGORY
HARTIN, W G MARTIN, T J MARTIN, W G MARTIN, W G MARTIN, T J	8004210212* 8004100157* 8004100080 8004080343* 8004100613*	50-247 50-354 70-364 70-135 50-311	Q Q S	MATTIA,M J MATTIMOE,J J MATTIMOE,J J MATTIMOE,J J MATTIMO,J J	8004210119+ 8004300433+ 8004100194+ 8004070312 8004030014+	CONTRACT 9 S1E-06 CONTRACT 50-312 8 CONTRACT TOARTMOD	MCCOOL, W B MCCOOL, W B MCCOOL, W B MCCOOL, W B MCCOORKLE, G	8004080208* 8004080184* 8004080179* 8004080120* 8004240127*	FOIA FOIA FOIA FOIA 70-135
MARTIN, W G MARTIN, R D MARTIN, R D MARTIN, T T MARTIN, W G	8004100026 8004240390≈ 6004250357≈ 8004210053≈ 8004210104≠	70-820 50-250 50-249 50-309 70-371	Q Q Q	MATTIA,M J MATTIA,M J MATTIMOE,J J MATTIMOE,J J MATTIMOE,J J	8004100342* 8004080610* 8004140397 8004150439 8004210259	CONTRACT CONTRACT 50-312 5 50-312 P 50-312 S	MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W	8004240114* 8004140002 8004230197 8004240222 8004020147	70-133 70-8 70-1739 50-244 P 70-2786
MARTIN, W G MARTIN, T T MARTIN, R D MARTIN, T T MARTIN, W G	8004250054 8004160153 9004070163 8004210102 8004210326	50-213 50-293 50-302 50-320 50-219	9 9 9	MATTIMOE, J J HATTIMOE, J J HATTIMOE, J J HATTIMOE, J J L JOMITTAM	8004160234 8004290485 8004210314 8004220568 8004220709	50-312 P 50-312 S 50-312 P 50-312 P 50-312 P	MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W	8004070040 8004070065 8004160003 8004240247 8004040473	70-1008 70-824 70-2322 70-2478 70-2322
MARTIN.W G MARTINSON.Z R MARTIN MARTIN.W G MARTIN.T T	8004150187 8004150036 8004080114* 8004230120 8004090473*	70-371 RES 50-354 50-309 50-293	5 0 0	MATTIME, U U L, SOMITTAM U L, SOMITTAM U L, SOMITTAM U L, SOMITTAM	8004230498 8004290339 8004280528 8004290454 8004300421	50-312 P 50-312 P 50-312 F 50-312 S 50-312 S	MCCRACKEN, K U MCCRARY, D L MCCUTCHAN, D A MCDADE, J M MCDERMOTT, R J	8004010372 8004250390 8004110496 8004080218* 8004040403*	50-348 P 50-321 P PR 50-387 U 71-35
MARTIN.W G MARTIN.W G MARTIN.W G MARTIN.W G MARTIN.W G MARTIN.W G	8004070200* 8004210077 8004220025 8004280241* 8004070171	50-184 70-371 70-371 50-335 50-184	0 0	MATTIA,M J MATTSON,R MATTSON,R J MATTSON,R J MATTSON,R J	8004030044# 7908150559 8004100530# 8004020476 8004210398	CONTRACT 50-358 H 50-320 D 50-320 P 50-320 H	MCDERMOTT, R J MCDIARMID, R C MCDIARMID, R C MCDIARMID, R C MCDIARMID, R C MCDONALD, D D	8004040398 8004090368* 8004090368* 8004090363 8004090362	71-35 50-416 H 50-416 H 50-416 H
MARTIM R D MARTIN W G MARTIN W G MARTIN W G MARTIN T J	6004280125* 6004090205 6004090393 6004100197 6004280174*	50-250 50-201 70-135 70-135 50-354	0 0 8	MATTSON,R J MAUGANS,E H MAUGANS,E H MAURA,F MAURO,J J	8004240141 8004150471 8004280386* 8004300022* 8004100588	REVIEW GRP 50-346 I 50-346 I 50-358 Q PR	MCDONALD.D D MCDOWELL-BOYER MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A	6004290173 8004140088 8004080451 8004220451 8004230328	FOIA RES 50-400 A 50-400 A
MARTIN, W G MARTIN, W G MARTIN, R MARTIN, T J MARTIN, W G	8004080334 8004100185 8004090051 8004250224 8004210210	70-135 70-33 50-335 50-354 50-247	5 0 0	MAYER, L G MAYER, L G MAYER, L G MAYER, L G MAYER, L G	8004040319 8004010452 8004080225 8004090223 8004080508	50-263 P 50-263 B 50-282 F 50-263 F 50-263 F	MCFARLAND, C R MCFARLAND, C R MCGARRY, J M MCGARRY, J M MCGARRY, J M	8004020194* 8004210247* 8004070331 8004110153	50-424 0 50-410 0 PR 70-2623 70-2623
MARTIN,W MARTIN,W MARTIN,W MARX,D J MASNIX,M T	8004280632 8004290051 8004300552 8004180368 8004020163*	50-320 50-213 50-273 50-271 50-272	8 9 8 9	MAYER, L O MAYER, L O MAYER, L O MAYER, L O MAYER, L O	8004080368 8004080373 8004080478 8004080479 8004150543	50-263 F 50-263 P 50-282 8 50-263 F 50-263 8	MCOARRY, J M MCGARRY, J M MCGAUGHY, R N MCGAUGHY, R N MCGAUGHY, R N	8004230012 8004230012 7812110291* 8004230114* 8004100111*	70-2623 70-2623 50-387 Q 50-352 Q 50-387 Q
MAGNIK,M T MAGGEY,W E MAGGE,R E MAGGE,H W	8004300600* 8004140470 8004040444* 8004040299* 8004240152	50-272 NURE0 50-315 50-315 RES	G G	MAYER, L O MAYER, L O MAYER, L O MAYER, L O MAYER, L O	8004140370 8004140435 8004140339 8004140431 8004150401	50-263 8 50-282 8 50-282 R 50-263 8 50-263 R	MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W	8004100168* 8004300309* 8004090441* 8004090473* 8004100040*	50-384 0 50-410 0 50-443 0 50-293 0 50-441 0
MASSIE,H W MASTER,N MATHEWS,E R MATHEWS,E R MATHEWS,E R	8004150008 8004210403* 8004100405 8004080457 8004080337	RES 50~320 50~305 50~305 50~305	H Q S P	MAYER, L O	8004150587 8004170056 8004180357 8004180339 8004180380	50-282 \$ 50-282 F 50-282 F 50-282 P 50-306 8	MCGAUGHY, R W MCGAUGHY, J MCGINNEBB, J MCGDNNAGLE, W MCGDVERN, G	8004210011* 8004230322 7909290207* 8004220037* 8004080314*	50-423 0 50-416 0 FOIA FOIA 40-1341
MATHEWS, E R	8004150354 8004150524 8004150581 8004170018 8004180428	50-305 50-305 50-305 50-305 50-305	R S S P P	MAYER, L O MAYER, L O MAYER, L O MAYER, L O MAYER, L O	8004180468 8004180341 8004180276 8004230358 8004230480	50-263 8 50-282 P 50-304 G 50-282 S 50-282 G	MCGRATH, E J MCGRANERY, J F MCGRIFF, J M MCGRIFF, J M MCGUIRE, D R	8004300215 8004150327 8004150533* 8004270519* 8004300135*	WASTE HOT 50-244 P 50-327 B 50-327 B 50-375 Q
MATHEWS,ER MATHEWS,ER MATHEWS,ER MATHEWS,ER MATHEWS,ER	9004190479 8004220756 8004210327 8004220642	50-305 50-305 50-305 50-305 50-305	5 P P P P P P P P P P P P P P P P P P P	MAYER, L D MAYER, J MAYE, S E MCARTHUR, T C MCCABE, E C	8004280547 8004250379# 8004090068 8004090195# 8004040177#	50-282 P 50-10 H RES 50-338 0 50-334 0	MCGUIRE, W F MCGUIRE, P J MCGUIRE, P J MCGUIRE, P J MCGUIRE, P J	8004010242 8004150576 8004140310 8004140337 8004170184	50-466 A 50-293 B 50-293 B 50-293 B 50-293 B
				MCCABE, E C MCCABE, E C MCCALLISTER, P MCCARTHY, E MCCARTHY, E A	8004170309* 8004160194* 8004220553 8004080166 8004070069	50~334 Q 50~277 Q 50~329 A State Prog State Prog	MCGUIRE,P J MCGUIRE,P J MCGURREN,H J MCGHENRY,T J	8004230497 8004220624 8004210289 8004170248 8004100182*	50-293 R 50-293 B 50-293 B 50-382 Q 50-333 Q
				MCCARTHY, E MCCLAIN, C M MCCLINTOCK, R D MCCLINTOCK, R O MCCLINTOCK, R O	8004020089 8004240432* 8004210052* 8004180511 7909290207*	State Prog 50-219 R FOIA 70-694 FOIA	MCINTOSH, W G MCKEOWN, L MCKEOWN, L MCKINLEY, J C MCLOUGHLIN, M T	8004220342* 8004070221* 8004300552 8004040261 8004150588*	70-2423 50-201 0 50-293 8 50-409 0 50-293 8
				MCCLINTOCK, R HCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R	8004210033* 8004210057* 8004070104* 8004070122 8004080230*	F01A F01A 40-6329 70-47 70-2254	MCLOUD, D O MCLOUGHLIN, M T MCLOUGHLIN, M T MCLOUGHLIN, M T MCLOUGHLIN, M T	8004270406* 8004140342* 8004170171* 8004210272* 8004220631*	50-32/ 0 50-273 8 50-273 6 50-273 8 50-273 8
				MCCLINTOCK,R O MCCLINTOCK,R O MCCLINTOCK,R O MCCLINTOCK,R O MCCLINTOCK,R O	8004150183 8004160156* 8004210012 8004160079 8004070089	70-1089 70-1251 70-2362 40-2284 40-6329	MCMORMACK, M MCNAMARA, A E MCNEER, C MCNEER, C 8 MCNEIL, W M	8004030343 8004150384* 8004270425* 8004110471 8004040361*	PR 50-244 R 50-266 I PR 0A999
				MCCLINTOCK, R O MCCLUNG, R H MCCOLLAM, W MCCOLLAM, W MCCOLLOUGH, P H	8004080199 8004280048 8004100513* 8004080245 8004170202	70-2254 NUREO COMMISSION PR PR	MCDSCAR, J J MCDSCAR, J J MCPHILLIPS, J MCRAE, C M MECCA, J E	8004080450* 800408041* 800425004 8004160023* 8004030351	50-213 Q 50-443 Q 70-2909 CONTRACT PR

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY
MECH, S J MEEKS, M MEIERAN, H B MEISS, R L MEISS, R L	8004110048 8004040266 8004170329 8004030317 8004040058	NUREG 50-554 G NUREG PROJ PROJ	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8004300076* 8004010320 8004010408 8004020395 8004280001	50-566 G NUREO 50-327 P 50-438 S 50-259 G	MILLS, L M MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8004300370 8004030160 8004070252 8004040400 8004080518	50-518 S 50-331 R 50-331 R 50-331 S 50-331 S
MELLON, K MENCZER, W B MENCZER, W B MENCZER, W B MENCZER, W B	8004220570 8004040435 8004070003 8004100523 8004100529	50-204 P CONTRACT CONTRACT CONTRACT CONTRACT	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8004280056 8004010374 8004160284 8004020414 8004020431	40-1341 50-327 G 50-327 G 50-438 S 50-438 8	MINECK.D L MINECK.D L MINECK.D L MINECK.D L MINECK.D L	8004080605 8004190340 8004090447 8004140363 8004140450	50-331 S 50-331 S 50-331 S 50-331 S 50-331 S
MERCURI, J MERRITT, D MERRILL, D K MERSON, B D MERSON, B D	8004030156* 8004070271 8004300057* 8004250407* 8004250406	50-320 H PR 50-387 G 50-317 R 50-317 R	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004020440 8004040377 8004020312 8004020417 8004180106	50-327 8 30-438 5 50-327 5 50-438 5 50-326 0	MINECK.D L. MINECK, D L MINOCUE, R B MINOCUE, R B MINOCUE, R B	8004220389 8004230346 8004090297 8004290072 8004150224	50-331 R 50-331 R SECY PR
MEBMERINGER, J MEBBITT, B R MEBBITT, B R METZGER, J R MEYER, K	8004170035* 8004040452* 8004240413* 8004220174* 8004040112	TOPREP 50-302	MILLS.L M MILLS.L M MILLS.L M MILLS.E D MILLS.L M	8004160216 8004160291 8004160296* 8004100334 8004070360	50-518 S 50-438 S 50-438 S 50-387 Q TOPREP	MINDGUE, R B MINTZER, D MIRHAN, J H MIHHAI, J MISHKIN, B	8004230130* 8004070009* 8004220180* 8004040270 8004300606*	SECY CONTRACT FOIA RES COMMISSION
MICHEL, C J MICHEL, C J MICHEL, C J MICHEL, C J	8004220133 8004070422 8004300003 8004140024 8004210198	70-143 70-143 70-143 71-249 70-143	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004080553 8004150413 8004150437 800407028 8004110186	50-553 A 50-390 S 50-390 S 50-327 P 50-327 F	MITCHELL.D G MITCHELL.D G METTL.R L MITTL.R L MITTL.R L	8004230411* 8004230495* 8004010438 8004010443 8004010447	50-289 8 50-289 R 50-311 A 50-311 A 50-311 0
MIDURA:H J MIDURA:H J MIDURA:H J MILHISER:R J MILHISER:R J	8004280225 8004150386 8004290489 8004010347* 8004070310*	50-272 S 50-272 R 50-272 R 50-382 S 50-382 S	MILLS,L M MILLS,L M MILLS L M MILLS,L M MILLS,L M	8004150414 8004150485 8004280453 8004140388 8004150423	50-518 8 50-553 8 50-328 8 GEN TEC IS 50-259 P	MITTLIR L MITTLIR L MITTLIR L MITTLIR L MITTLIR L	8004010447 8004010453 8004070250 8004040313 8004040282	50-311 A 50-311 A 50-311 A 50-311 A 50-311 A
MILHIBER,R J MILHIBER,R J MILLER,J R MILLER,M E MILLER,T D	8004250352* 8004280605* 8004010189* 8004020122* 8004140034*	50-382 8 50-382 8 70-1308 50-445 M 0A999	MILLS.L M MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8004150557 8004280170 8004280432 8004280537 8004140327	50-257 P 50-257 Q 50-438 S 50-370 S 50-327 P	MITTLIR L MITTLIR L MITTLIR L MITTLIR L MITTLIR L	8004110305 8004110431 8004110448 8004110474 8004110424	50-311 A 50-311 A 50-311 A 50-311 A 50-311 A
MILLER, D E MILLER, T D MILLER, T D MILLER, T D MILLER, M J	8004070174* 8004140020* 8004070327* 8004140015* 8004080557	50-373 Q QA779 50-2 G QA777 50-445 M	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004280536 8004180377 8004180381* 8004280548 8004290513	50-390 8 50-390 8 50-390 8 50-390 8 71-227	MITTLIR L MITTLIR L MITTLIR L MITTLIR L MIYABAYASHIIM	8004170040 8004240377 8004240345 8004250393 8004070024	50-272 P 50-311 F 50-311 F 50-311 A XPORTLIC
MILLER, W O MILLER, W O MILLER, W O MILLER, H L MILLER, H J	8004020450 8004070209 8004070220 8004080101 8004070428	90-155 P TOPREP 50-155 P 50-367 B 40-1341	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8004150608 8004170026 8004170065 8004180365 8004180444	50-327 P 50-327 8 50-327 K 50-328 8 50-390 8	MODENOS, L MODENOS, L MODENOS, L MODENOS, L MODENES, N H	8004040176* 8004070355* 8004280202* 8004280107* 8004270023*	50-257 Q 50-302 Q 50-259 Q 50-261 Q
MILLER, W O MILLER, W O MILLER, M E MILLER, W O	8004070055 8004070190 8004080252 8004090062 8004140113	TOPREP TOPREP TOPREP 50-344 Q TOPREP	Mills,L M Mills,L M Mills,L M Mills,L M Mills,L M	8004210202 8004230506 8004280388 8004170069 8004170213	50-327 P 50-259 P 50-390 S 50-327 P 50-390 A	MOGOLESKO, F J MOLHOLT, B MOLHOLT, B MOLHOLT, B MOLLOY, E J	8004080524* 8004170237 8004250378 8004270289 8004020418*	50-273 R 50-320 P 50-320 P 50-320 P 50-213 F
MILLER, W O MILLER, W O MILLER, H J MILLER, M E	8004140012 8004070334 8004100075 8004210416 8004070448	50-568 A 40-8728 70-1113 WASTE MOT 50-454 Q	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8004180256 8004220724 8004280503 8004280505* 8004170134	50-553 A 50-518 8 50-518 8 50-518 8 50-327 P	MOLONE,L MOMENI,M H MONDEN,T MONTOOMERY,D M MONTI,W A	8004210256* 8004100586 8004180242 8004140480* 8004150579	50-10 H NURE0 XPDRTLIC 50~261 G 50-3 R
MILLER, M E MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8004080424* 8004110540 8004170178 8004210112 8004170167	50-445 M 70-1257 50-316 P 50-286 P 70-1308	MILLB,L M MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8004170148 8004170225 8004220340 8004220420 8004220523	50-327 P 50-327 F 50-259 P 50-438 S 50-259 P	MODDY, D E MODDY, D E MODDY, D E MODDY, D E	8004080423 8004100422 8004020016 8004100406 8004210044*	50-2/1 Q 50-309 Q 50-309 Q 50-309 Q 50-309 Q
MILLER,W O MILLER,W O MILLER,W O MILLER,W O MILLER,W O	8004210005 8004210023 8004230042 8004210043 8004220788	50-344 P 50-282 P 50-348 P 50-271 P 50-313 P	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8004230347 8004280508 8004220541 8004280438 8004230380	50-553 Q 50-566 R 50-438 S 50-438 S 50-438 S	MOODY, D E MOODY, D E MOODY, D E MOODY, D E	8004230005 8004080339 8004110444* 8004140172 8004150347	50-309 Q 50-309 H 50-29 P 50-29 F 50-309 R
MILLER,M I MILLER,M I MILLER,M E MILLER,W O MILLER,L K	8004220334 8004220334 8004150173 8004270077 8004150387*	50-556 0 50-556 0 PROJ 50-29 P 50-272 R	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004230503 8004230527 8004240386 8004280516 8004240405	50-438 8 50-438 8 50-438 8 50-438 9 50-370 8	MODDY, D F MODDY, D, E MODDY, D E MODN, B T MODN, B T	8004150360 8004150350 8004280534 8004040289* 8004070049*	50-271 R 50-29 R 50-29 F 50-280 Q 50-321 Q
MILLERIM E MILLBAPIW J MILLBIL M MILLBIL M MILLBIL M	8004170351 8004040156* 8004100475* 8004040181* 8004020247*	50-445 M 70-27 50-546 G 50-257 Q 50-257 Q	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004250374 8004250380 8004250405 8004250413 8004250431	50-566 S 50-438 S 50-566 Q 50-370 B 50-556 B	MOON,R,E MOONEY,F & MOORE,R N MOORE,R N MOORE,W	8004070287* 8004070246 7702280271 7909190504 8004100075	QA999 WASTE MOT MIBC MISC PR
MILLSAP.W J MILLS.L M MILLS.L M MILLS.L,M MILLS.L M	8004090302* 8004090160 8004080207 8004280490 8004280496*	70-1201 PR 40-1341 50-327 8 50-327 8	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004280227 8004290453 8004290346 8004290379 8004290290	50-327 P 50-390 A 50-328 B 50-259 Q 50-327 P	MODRE, K. E. MODRE, R. N.	8004020475* 8004070078 8004070023 8004070073 8004070080	TOPREP XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MILLE,L M MILLE,L M MILLE,L M MILLE,L M	8004210188* 8004300474* 8004100364 8004210178 8004020193	50-553 Q 50-370 Q 50-257 Q 50-257 Q 50-553 A	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004270276 8004270327 8004270400 8004270455 8004300341	50-390 8 50-328 8 50-327 0 50-328 8 50-327 P	MODRE, D E MODRE, D E MODRE, D E MODRE, J E MODRE, G W	8004040117# 8004010469 8004110549# 8004090001 8004030176	70-143 50-302 R 70-2479 50-155 Q 50-334 R

					CUD JEST			ACCESSION	SUBJECT	
AUTHOR	ACCESSION NUMBER	SUBJECT	POHTUA	ACCESSION NUMBER	SUBJECT CATEGOR	Y 	AUTHOR NIX.R T		CATEODRY 50-344 S	
MODRE, J E MODRE, R N MODRE, J E	8004170302 8004300010 8004180405 8004270157*	50-155 0 KPORTLIC 50-272 T 50-339 0	MURPHY, P K MURPHY, C E MURPHY, C E MURPHY, M J	8004220334 8004300112 8004300462 8004140323* 8004140412*	50-554 50-395 50-390 50-272 50-272	ତ ପ ସ ଅ	T RIXIN T RIXIN T RIXIN T RIXIN	8004020330* 5 8004020347* 5 8004020437*	50-344 8 50-344 8 50-344 8 50-344 8	
MODRE, D E MODRE, D C MODRE, J E MODRE, J E MORGAN, R L	8Q04150307 8Q04220674 8Q04250422 6Q04220010	50-302 P 50-272 0 50-155 0 NUREG	MURPHY, N J MURPHY, R J MURPHY, N P MURPHY, N P MURPHY, N P	8004300090 8004150558* 8004150506 8004150514*	50-566 50-272 50-271 50-271	0: 8 8	NIX,R T NIX,R T NIX,R T NIX,R T NIX,R T	8004150455* 8004220721* 8004220617*	50-321 S 50-366 S 50-366 S 50-366 S	
MORGAN, J F MORIARTY, J M MORIARTY, J M MORISS	8004080297* 8004140156 8004020455 7903090072 7903090076	0A779 50-483 8 50-395 S MISC	MURPHY, W P MURPHY, C E MURPHY, C P MURPHY, J P	8004180413* 8004230355* 7911050375 8004090442	50-271 50-271 50-316 MISC 50-255	8 5 8	HIX.R T HIX.R T HIX.R T NIX.R T	8004220710* 8004220718* 8004220735*	50-344 S 50-321 B 50-344 S 50-346 B 50-321 B	
MORRILL.P J MORRILL.P J	8004280022* 8004210196*	50~275 0 50~243 0	MURRAY, J P MURRAY, J P	8004300519* 8004300069*	50~320 50~387	0	A H'YZIN A H'YZIN		70-135 40-8027	
MORRIE.E W MORROW D MORROWOIELLO, A	8004030180 8004070184 8004290075 8004280075 8004290514*	50 -275 H 40~8380 40~8502 PR CONTRACT	MURRAY, J MURRAY, J HURRAY, T D MURRAY, T D MURRAY, T D	8004290111 8004110485 8004110378 8004110487	50-341 50-346 50-346 50-346	H S S	NIXON NA NOLAN F NOLAN F NOLAN F	8004210433 8004220084 8004210440 8004210441	50-304 B 50-272 B 50-277 B 50-247 B	
MORTON, K V	8004240033 B004240041 * B004020215 * B004070100 * B004010009 *	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURRAY,T D MURRAY,R MURRAY,T D MURRAY,T D MURRAY,T D	8004140350 8004220423* 8004150563 8004210265 8004220657	50-346 50-265 50-346 50-346 50-346	R 8 8 8	MDLAN: F NDLAN: F NDLAN: F NDLAN: F NDLAN: F	9004210224 9004180517 9004180518 9004180520	90-344 9 50-345 8 50-257 8 50-255 8	
MORTON: K V	8004150171 * 8004070007 * 8004100369 * 8004100363 *	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MUYATT	8004220752 8004220765 8004280538 8004280572 8004100411	50~344 50~344 50~344 50~346 RE8	8 6 5	NOON, J C NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R	8004230372 B004020230 B004020238 B004100174 B004030006	70-25 70-1257 70-25 70-1143	
MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	8004250043# 8004250528# 8004250023# 8004250022# 8004240015#	CONTRACT CONTRACT CONTRACT CONTRACT	Myerb. I L Myradd. A L Nalepka. D Nalepka. D S Nalepka. D 8	8004300381* 8004150405* 8004230515* 8004080462* 8004080467*	70 -2905 50-263 50-305 50-305 50-305	8 8 8	NORDERHAVO, L R NORDERHAVO, L R NORDERHAVO, L R NORDERHAVO, L R NORDERHAVO, L R	8004040457 8004040460 8004110532 8004180443 8004170268	70-29 90-163 0 90-206 0 70-1257 50-206 0	
MOSELEY, N C MOSELEY, N C MOSELEY, N C	9004290033* 9004290033* 9004220238* 9004080074* 9004300495	FOIA 50-255 G 50-272 S	NALEPKA, D B NALEPKA, D B NANJAPPA, M NAPLEPKA, D B NAPUDA, O B	8004150576* 8004270336* 8004110500* 8004270327* 8004070138*	50-305 50-305 50-272 50-305 50-213	8 0	NORDERHAUG, L R NORDERHAUG, L R NORELIUG, C E NORELIUG, C E NORELIUG, C E	8004170278 8004300465 8004220274* 800404026* 8004040277*	70-25 50-204	
WOMEA'R B WOMEA'R B WOMEA'R B WOMEA'R B	8004080009 8004080014* 8004180480 8004170350 8004210156 8004210159*	XPORTLIC 50-585 A XPORTLIC	HAPUDA, 0 NARBUT, P NARBUT, P NARBUT, P NARBUT, P P	8004180320# 8004020180# 8004040161# 8004280180# 8004210428#	50-528 50-312 50-312	0 0 0	NOPELLUS, C E NORHOLM, L J NORIAH, P E NORRHOLM, L J NORTON, B	B004150496# B004170293# B004090257 B0D4220429* B004080712	50-241	
MOWRY, UR MUFFLER, R T MUFFLER, R, T MUFFLER, R T MULDER, K J	B00421017 B004210017 B004020290 B004100052 B0041003634 B004060275	FOIA FOIA FOIA	NAUGHTON, W F	B004020177 B004020189 B004080214 B004080397 B004180316	50-599 50-295 50-295 50-454 50-10	5 P	NORMICKI, 9 J NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V	8004170253 8004010478* B004020349 8004080118 B004080126	50-219 P SECY XPORTL 1C XPORTL 1C XPORTL 1C	
MULLER, DR MUNBOL J MUNBOL J MUNBOL J	9004020215 9004100536 9004280126 9004240499 7704170340	REGOD 71-9039 40-299	naughton, u f Naughton, u f Naugh, k Naugh, h Nedelman, J	8004100338 8004220356 8004100604 8004170284 8004140238	50-275 50-275 PR PR PR 50-405	5 F	NOBENIO, L. V NOBENIO, L. V NOBENIO, L. V NOBENIO, L. V	8004080139 8004100040 8004100044 8004100058	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	P
MURLEY, T E MURLEY, T E MURLEY, T E MURPHY, F E HURPHY, J A	8004240141 8004280283 79086033 8004100521 8004180310	REVIEW GRP HISC # 30-320 D	NEIDIO. M NEIGHBORB. D NEILBON. R M NELSLER. J H NELBON. J D	8004280303 8004110338 8004270007 8004070278 8004280420	50~28 NUREO * 50-37	0 0 3 0	Novacek, p Novarro, J P. Novarro, J P Novelive, C E	8004090004 8004040314 8004220420 8004100551*	50-322 50-322 50-322 40-261	à A A
MURPHY, C E MURPHY, C E MURPHY, C E	8004020036 8004100503 800404018 800409041 8004180314	5+ 50-375 0 3+ 50-566 0 5+ 50-259 0 1 50-454 0	NELEON, O NELEON, K NELEON, C NEUMANN, M R NEUMANN, M R	8004140238 8004040353 8004040142 8004080203 8004250023	50~38 50~70 40~83	7 H P	NDMICKI, S J NOZENZO, L V NWESSE, C J NUCENT, E L NURRAY, J P	8004100320 8004040147 8004070099* 8004020291 8004020228*	4PHRTL 10 40-4329 40-2259 90-394	Q
MURPHY. R J MURPHY. C E MURPHY. P M HURPHY. P M MURPHY. P M	8004070150 8004100320 8004100320 8004080420	0 50~438 0 2 50~454 0 2 50~454 0 9 50~454 0	Newman, J R Newman, J R Newman, P S Newman, J R Hewman, J R	8004020293 8004020233 8004280044 8004240188 8004240188	50-46 40-86 50-46	6 Q 98 6 Q	Nusbbaumer, D A D'Brien, J II D'Brian, J II D'Brien, J F D'Brien, M J	8004020102* 8004150015 8004240460 8004210074	XPORYL.1C	Ġ.
MURPHY, PM MURPHY, CE MURPHY, CE MURPHY, CE	800408042 800401048 800404016 800422033 800422013	1# 50-316 5 9 50-389 0 9* 50-491 0 4* 50-491 0	NEWMAN, J R NEWMAN, J R NEWPORT, E. G NEWTON, B M NICHOLG, T C	8004230023 800423023 8004230340 800424049 8004100403	50-46 50-46 50-26 40-27	66 0 24 0	G'CONNOR, P W G'CONNOR, P W G'CONNOR, L A G'MANLON, J P G'MANLON, J P	8004030188 8004100159 8004080557 8004280487 8004280521	90-206 50-105 50-245 50-313 50-368	P = 6 6
MURPHY, C © MURPHY, H P MURPHY, H P MURPHY, H J MURPHY, H P	900424035 800401048 900401049 800401034 800402038	9 50-271 8 99 50-271 8 18 50-272 8 16 50-271 8	Nicholas, H H Nicholas, D Nijhayan, S Nilagah, R Nilagah, R	B00421015 800415043 800404002 800410006 800410007) NURE(7 REB 5 70-11	0 257	D. WEILL, J D. WEILL, J D. WEILL, J D. WEILL, J	8004140276 8004140041 8004140044 8004140048 8004140059	\$0-155 # \$0-155	00000
# # # # # # # # # # # # # # # # # # #	800404032 800404032 800404033 800408053 800421018	24* 50~272 8 27 50~271 8 32* 50~271 8 33* 50~272 5	NINN, O E HIK. D. HIK. R. HIX. R. T NIX. R. T	800410050 800410054 800415046 800402036 800401047	2 50-3 0# 50-3 3* 50-3	7 21 8 66 8	D'NEILL, J H O'NEILL, A A O'NEILL, R A O'NEILL, R A	9004010519 8004010519 8004240043 8004240045 8004240053	50-445	99525

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	Υ
G'NEILL.R A O'NEILL.R A O'REILLY.J P O'REILLY.J P O'REILLY.J P	8004240043 8004240053 8004160038 8004090337 8004090339	50-445 M 50-445 M 50-34B Q 50-302 Q 50-414 Q	O'REILLY, J P	8004180321 8004180326 8004180375 8004180378 8004180382	50-250 0 50-269 0 50-488 0 50-261 0 50-437 0	ORLANDO, E ORLOSKY, P M ORPHAN, R C ORTH, D A ORTLOFF, G D	8004100471 7905190091 8004250066 8004140121 8004070154	50-352 50-57 TOPREP ACRS 40-8102	H P
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004090340 8004090343 8004090344 8004090349 8004090352	50-395	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004110010 8004110011 8004110014 8004110017 8004110021	50-324	ORTLOFF, G D ORTLOFF, G D OSANN, E W OSANN, E W OST, F	8004280403 8004290526 8004230091 8004230101 * 8004020313*	40-8102 40-8102 50-367 50-367 50-295	G G S
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004070358 8004070360 8004020211* 8004020220* 8004300124*	50-280 G 50-437 Q 50-395 Q 50-395 Q 50-395 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004210204 8004230102 8004230108 8004230109 8004230113	50-140 G 50-437 G 50-280 G 50-395 G 50-348 G	051, F 051, F 011050N, H L 011050N, H L 011050N, H L	6004220668* 9004290496* 8004070338 8004080177 8004080483*	50-295 50-295 50-206 50-206 50-205	5 5 6 5
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004070025 8004070391 8004100217 8004150313 8004150315	50-32B	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004230117 8004230122 8004230132 8004230142 8004230158	50-261 0 50-488 0 50-269 0 50-299 0 50-395 0	OTTOSON, H L OTTOSON, H L OTTOSON, H L OTTOSON, H L OUZTS, J E	8004210270 8004180450 8004210254 8004250418 8004280157*	50~206 50~206 50~206 50~206 50~325	5550
D'REILLY, J P D'REILLY, J P D'REILLY, J P D'REILLY, J P	8004150491 8004150492 8004150495 8004150497 8004150505	50-416 Q 50-375 Q 50-375 Q 50-261 Q 50-488 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004230165 8004230169 8004230173 8004230181 8004180317	50-250 Q 50-302 Q 50-321 Q 50-414 Q 50-302 Q	OVERDORFF. J S OVERLID. T W OVERLID. T W DVERLID. T W OVERLID. T W	8004080092 8004190955# 8004150964# 8004150623# 8004140437#	FOIA 50-263 50-263 50-263 50-263	8 S S S
O'AEILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004150511 8004150517 8004150521 8004150527 8004150540	50-269 Q 50-250 Q 50-321 Q 50-259 Q 50-280 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004180323 8004180328 8004180332 8004180335 8004180340	50-348 0 50-416 0 50-395 0 50-395 0 50-261 0	OWSLEY, O F OWSLEY, O F OWZARSKI, P PAGANO, C L PAGAND, C L	8004020404 8004020307 8004040270 8004140149 8004210140	TOPREP 50-261 RES PR PR	P
O'REILLY, J P	8004150550 8004080582 8004080583 8004080587 8004080587	50-437 Q 50-348 Q 50-395 Q 50-395 Q 50-416 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004180351 8004180358 8004180401 8004180417 8004180436	50-488 0 50-269 0 50-280 0 50-250 0 50-321 0	PAGE.R C PAGE.R O PAGE.R G PAGE.R G PAGE.R G	8004240201 8004240207* 8004150058 8004150068* 8004150107*	50~438 50~438 70~1113 70~1113 70~2909	A
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004080595 8004080598 8004080604 8004080611 8004080619	50-302	O'REILLY, J P O'REILLY, J P O'ROURKE, S O'TOOLE, J D	8004180445 8004180476 8004300205 8004080007 8004150433	50-259 Q 50-437 Q 50-269 Q 71-9029 50-247 P	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	8004150104 8004150289 8004240554+ 8004240550 8004020473	70-2909 70-1113 70-135 70-135 50-364	٨
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004080624 8004080636 8004080652 8004080658 8004150064	50-321	OBERG.C T OBERG.C R ODLAUG.M OESTMANN.M J OFBANIK.W J	8004040102* 8004140049* 8004220028* 8004300555* 8004040103	40-8135 50-459 G FOIA 50-10 G XPORTLIC	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	8004020481* 8004100573 8004150300 8004080565 8004240153	50-364 70-1113 70-820 70-143 70-143	۸
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004150067 8004150070 8004150075 8004150080 8004150081	50~261	OKRENT, D OKRENT, D OLCOTT, K OLCOTT, K	8004080623* 8004140030 8004140047 8004140052* 8004140426	ACRS ACRS PR PR PR	PAGE.R G PAGLIARD, J A PAGLIARD, J A PAGLIARD, J A PAGND, C L	8004160027 8004030327# 8004030316# 8004030319# 8004140108	40-1193 FDIA FDIA FDIA PR	
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004150088 8004150089 8004150091 8004150093 8004150097	50-416	DLEM, H OLLER, R E OLLER, R E OLMSTEAD, W J OLMSTEAD, W J	8004150376* 8004010515* 8004090299* 8004020277* 8004150160	50-553 R 0A999 0A999 50-387 G 50-389 G	PANCIERA.V PANETTA.L E PAOLINO.R J PAPAY.L T PAPAY.L T	7908210548 8004290146 8004070396* 8004020049* 8004150538	50-10 50-275 50-387 50-361 50-361	P 0 0 5
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004150105 8004150109 8004240224 8004240227 8004240229	50-280 0 50-437 0 50-332 0 70-27 70-824	OLSEN, A F OLSEN, A F OLSEN, A F OLSHAN, L N OLSON, R C	8004240235 8004220127 8004180355 8004100169 8004010212	70-824 71-6400 50-13 P 50-247 P 50-318 P	PAPERIELLO,C J PAPERIELLO,C PAPERIELLO,C J PARIB,O H PARIS,O H	8004040102* 8004100551* 8004070173 8004080695 8004230111	40-8135 40-241 !&E 50-387 50-387	G G
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004240231 8004240233 8004240235 8004240239 8004240239	70-1201 70-1113 70-143 50-437 G 70-1151	OLSON, J F OLSON, J F OLSON, R C OMATA, I ONCAVAGE, M A	8004230088 8004230100 8004090359 8004280032 8004240086	50-282	PARK, Y 8 PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8004040459 8004070362 8004230236* 8004080125 8004110559	NUREQ 50-269 50-269 PR PR	G G
O'REILLY, J P O'REILLY, J, P O'REILLY, J P O'REILLY, J P	8004240242 8004240245 8004240247 8004240254 8004240259	50-348	ONCAVAGE,M P ONSDORFF,K A OPEKA,J F OPEKA,J F OPEKA,J F	8004080550 8004080633 8004010407 8004010423 8004090308	50-250	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8004300214* 8004040358 8004080253 8004250334* 8004100351	50-269 50-269 50-269 50-269 50-269	Q Q Q Q
O'REILLY, J P O'REILLY, J, P O'REILLY, J, P O'REILLY, J, P O'REILLY, J P.	8004240260 8004240265 8004240268 8004240269 8004240271	50-250	OPEKA, J F. OPEKA, J F OPEKA, J F OPEKA, J F OPEKA, J F	8004170224 8004170194 8004180437 8004180398 8004180408	50-334	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8004020019 8004180515 8004240035 8004210164 8004020348	50-413 50-369 50-269 50-413 50-369	0 0 0
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P. O'REILLY, J P	8004240274 8004240284 8004180268 8004180269 8004180271	50-259 Q 50-280 Q 50-416 Q 50-395 Q	OPEKA, J F OPEKA, J F OPEKA, J F OPEKA, J F	8004180383 8004220411 8004210246 8004220670 8004280525	50-245 R 50-334 R 50-245 R 50-336 S 50-336 B	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8004070234 8004160272 8004010470 8004030157 8004030199	50-369 50-287 50-269 50-269	A S F P
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004180272 8004180274 8004180275 8004180277 8004180303	50-348 Q 50-302 Q 50-257 Q 50-280 Q 50-321 Q	OPEKA, J F OPPENHEIM, L OPREA, O W. OPREA, O W OPREA, O W .	8004270277 8004040308 8004040240 8004040374 8004040370	50-245 8 50-320 H 50-498 A 50-498 8 50-498 6	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8004070327 8004210191 8004210234 8004030152 8004030223	50-269 50-269 50-413 50-369 50-287	9 0 F 9

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8004080555 8004160116 8004210172 8004080614 8004080366	50-269 P 50-413 Q REGGD 50-269 P 50-369 A	PECK, C C PECK, C C PECK, O E PEERY, W W PEERY, W W	8004100383* 8004040055* 8004180337* 8004280288* 8004210034*	50-182	PETERSON, M R	8004040045 8004040049* 8004040480 8004070037 8004080251	XFORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8004080432 8004080455 8004080471 8004140348 8004170164	50-287	PEERY, W W PEERY, W W PEERY, W W PEERY, W W	8004210076* 8004210339* 8004210345* 8004220402* 8004080140*	50-272 Q 50-333 0 50-245 Q 70-1143 27-47	PETERSON, M R	8004080295 8004080299 8004080303* 8004080315 8004080627	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W C PARKER, W C PARKER, W C PARKER, W C PARKER, W C	8004170203 8004150465 8004160229 8004220443 8004180273	50-269 S 50-269 P 50-207 S 50-269 F 50-369 F	PEERY, W W PEERY, W W PEKRUL, P J PELL, B M PELL, B M	8004040023* 8004100408* 8004020387 8004020418* 8004020424*	50-10 Q 50-10 Q REGOD 50-213 F 50-213 F	PETERSON, M R	8004180309 8004210002 8004110141 8004100042 8004210364	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W C PARKER, W C PARKER, W C PARKER, W C PARKER, W C	8004220502 8004220682 8004220640 8004220649 8004220720	50-269 P 50-269 S 50-269 P 50-270 P 50-369 A	PELLEK, R R PELTIER, I A PENCE, W B PENCE, W B PENCE, W B	8004070347* 8004250026 8004010351* 8004150486* 8004290377*	50-320 R 50-358 A 50-318 S 50-318 S 50-317 S	PETERSON, M R	8004100049 8004160082 8004100179 8004100179 8004100232	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W O PARKER, W O PARKINSON, T F PARKINSON, T F PARKINSON, T F	8004180356 8004270473 8004150431 8003310406 8004040468	50-269 P 50-369 A 50-124 P 50-124 B 50-124 F	PENCE, W B PENDERGRAFT, R PENDERGRAFT, R PENDERGRAFT, R PENNEY, J A	8004290438* 8004020346* 8004210280* 8004290451* 8004090076	50-317 S 50-368 S 50-348 R 50-368 R 71-9019	PETERSON, M R PETERSON, M R PETERS, R J PETERSON, M R PETERSON, M R	8004210369 8004210379 8004080443 8004100180 8004100181	XPORTLIC XPORTLIC 50-275 A XPORTLIC XPORTLIC
PARMENTER,F H PARMENTER,F PARR,O D PARR,O D PARR,O D	8004090204 8004170340 8004020247 8004020256 8004040428	50-445 M 50-445 M 50-339 A 50-311 A 50-339 A	PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L	8004180389 8004030027 8004100128* 8004140119 8004140441	50-247 P 50-237 P 50-10 Q 50-10 Q 50-456 A	PETERSON: M R PETERSON: M R PETERS, R J PETERSON: M R PETERSON: M R	8004100184 8004170291 8004150435 8004240224 8004210451	XPORTLIC XPORTLIC 50-275 A XPORTLIC XPORTLIC
PARR, O D PARR, O D PARR, O D PARR, O D PARR, O D	8004070052 8004080654 8004070097 8004070101 8004080396	50-438 F 50-387 A 50-373 A 50-311 A 50-339 A	PEOPLES, D L	8004030172 8004070273 8004220299 8004180372 8004230479	50-10 F 50-284 F 50-237 F 50-249 P 50-373 A	PETERS, B PETERSON, M R PETIT, M R PETRICK, N A PETRICK, N A	8004170240 8004300016* 8004270514* 8004040267 8004100280	50-313 }L XPORTLIC CONTRACT 50-482 8 50-482 0
PARR, O D PARR, O D PARR, O D PARR, O D PARR, D D	8004150128 8004280308 8004040016 8004070189 8004210410	50~498 A 50~438 A 50~482 A 50~483 A 50~387 A	PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L	8004250427 6004240412 6004280509 6004230367 6004250353	50-373 A 50-265 P 50-295 P 50-10 F 50-249 P	PETRILLO, M PETRICK, N A PETRICK, N A PETRIE, L PETRICK, N A	8004110094 B004150179 8004150369 B004210264* B0042B0463	50-320 H 50-482 B 50-482 B 50-10 H 50-482 A
PARR.O D PARR.O D PARR.O D PARR.O D PARSONS,W D	8004110046 8004210408 8004100484 8004240149 8004040152*	50-438 A 50-460 A 50-387 A 50-311 A XPGRTL1C	PEOPLES, D.L. PEOPLES, D.L. PERKINS, J.L. PERLAS, N. PERLAS, N.	8004280410 8004270502 8004220032 8004070180* 8004040120*	50-373 A 50-295 P 50-397 G BECY CONTRACT	PETTIOREW,R R PFAFF.B J PFAFF.B J PFAFF.B J PFAFF.B J	8004030284 8004070144 8004070155* 8004070155* 8004070164*	PR 40~6657 40~6657 40~6659 40~6659
PARBONS, W B PARTLOW, J O PARTLOW, J G PARTLOW, J G PARTLOW, J G	8004040141 8004240137* 7904210192 8004070351 8004070419	XPURTL1C 70-138 H1SC 70-143 70-143	PERLMAN, J PERNY, C D PERNY, C D PERRIOD, L D PERRIN, J S	8004270113 * 8004040047 * 8004030362 * 8004270020 8004300172	CONTRACT 70-143 70-2478 Nureo Nureo	PFAFF.S J PFEFFEREEN.H C PHILDRICK.S S PHILIPS.M H PHILIPS.M H	8004070169* 8004080036* 8004040167 8004280189 8004280189	40-6659 TOPREP 50-30 D 50-356 Q 50-356 Q
PARTLOW, J G PARTLOW, J G PARTLOW, J G PARTLOW, J G PARTLOW, J G	8004080072 8004100105 8004270062 8004160018 8004210106	70-820 70-1287 70-371 70-1257 70-27	PERROTTIOU PERRY, W W PERRY, U C PERRY, U C PETERBON, M R	8004040402* 8004210082* 8004150442* 8004270478* 8004210077*	50-269 Q 50-277 Q 50-344 B 50-344 B 70-2478	PHILLIP.0 A PHILLIP.0 A PHILLIP.0 A PHILLIPS.L B PHILLIP.0 A	8004220178* 8004220196* 8004220327* 8004220171* 8004150496*	FDIA FDIA FDIA 50-320 H 50-341 0
PARTLOW, J G PASEDAG, W F PASINDSKY, J P PASTERNAK, R J PASTERNAK, R. J	8004270048 8004180416* 8004180485 8004070318 8004070436	70-1201 50-272 T XPORTLIC 50-333 R 50-333 S	PETERSON, R J PETERSON, M R	8004100057 8004020387 8004070028 8004070088 8004020373	PRM XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILLIPS, J R	8004020133 8004070038 8004070132 8004070137* 8004080556	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
PASTERNAK, R J PASTERNAK, R J PASTERNAK, R J PASTERNAK, R. J PATAPOVS, U	8004220/67 8004280552 8004290504 8004290476 8004150145	50~333	PETERBON, M R	8004020397 8004020401 8004020406 8004080620 8004020184	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILLIPS, J PHOENIX, D R PIELAGE, H W PIERGE, A C PIGOTT, D R	8004210322 8004210353* 8004280383 8004180076 8004100477	50-275 0 50-320 P NUREO 50-201 P 50-361 0
PATAPOVS.U PATAPOVS,U PATE.R J PATE.R J PATE.R J	8004100001 8004300098* 8004210417* 8004210166* 8004280095*	QA999 QA999 50~361 Q 50~361 Q 50~361 Q	PETERBON, M R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8004040087 8004040099 8004070407 8004090113 8004040477	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PIGDTT, D R PIGDTT, D R PIGDTT, D R PILANT, J M PILANT, J M	8004100477 8004100537 8004100537 8004230192 8004140479	50-361 0 50-361 0 50-361 0 50-298 0 50-298 0
PATON, W D PATON, W D PATON, W D PATON, W D PATOR, W D	8004020277* 8004150160 8004090043 8004220674 8004080204*	50~369 Q 50~369 Q 50~369 Q 50~272 G FOTA	PETERBON, M R	8004090198 8004090202* 8004290039 8004250042* 8004030049	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PILANT, J M PILANT, J M PILANT, J M PILANT, J M PILANT, J M	8004250277 8004250240 8004280184 8004010454 8004230371	50-278 G REOGD 50-278 G 50-278 R 50-278 F
PATTERN,K PATTERSON,J P PATTERSON,K P PATTERSON,J P PAUL,R A	8004020483 8004070431* 8004040068* 8004110498* 8004070327*	50~327 G 50~305 G PROJ 50~285 G 50~2 O	PETERBON, M R	8004040178 8004080087 8004080096 8004080311 8004080350	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PILANT, J, M PILANT, J M PLANJE, T J PLASKON, R E PLATO, P	8004040374 8004230457 8004270085* 8004220036 7704110103	50-29B R 50-29B P 50-123 G 50-516 G 50-2 P
PAUL,R A PAULUS,R C PAVLIND,R T PAYNE,J P PEABDDY,C A	80041003774 80040201044 8004100112* 8004080328 8004280075	50~150 G State Prog 50~352 G 50~286 G PR	PETERBON, M R, PETERBON, M R PETERBON, M R PETERBON, M R PETERBON, M R	8004080353 8004220116# 8004030364 800404003B 8004040042#	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PLESSET, M 8	8004150010 8004180079 8004020032 8004080070 8004180074	ACRB ACRB NUREO COMMISSION ACRS

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PLESSET.M S PLESSET.M S PLESSET.M S PLESSET.M S PLESSET.M S	8004030333* 8004040272 8004040274* 8004150016 8004150046	50-312 G NUREO NUREG ACRS ACRS	POTTER, J P POTTER, J P POTTER, J P POTTER, I P POTTER, J P	8004210035* 8004210120* 8004280310* 8004280288* 8004210034*	40-672 50-287 0 50-293 0 50-317 0 70-1100	RATHKOPF.C L RAUNER.L M RAUNER.L M RAUSCH.J K RAUSCH.J K	8004220124* 8004020192 8004010038 8004040125* 8004300493*	50-320 H FOIA FOIA 50-416 G 50-395 G
PLESSET. H S PLESSET. H S PLESSET. M S PLUMLEE, K E PLUMLEE, K E	8004150208 80040402774 8004150006 8004100014* 8004210102*	ACRS NUREQ ACRS 50-184 Q 50-320 Q	POTTER, J P	8004210076* 8004210082* 8004210339* 8004210345* 8004220402*	50-272 0 50-277 0 50-333 0 50-245 0 70-1143	RAUSCH, J K RAUSCH, J K RAYMOND, L W RAYMOND, W J READ, J	8004090183 8004220134* 8004220162* 8004210071* 8004020474*	50-416 S 50-491 G 50-320 H 50-244 G 50-522 G
POCHAL, W F POCHAL, W F POCHAL, W F POCHAL, W F POCHAL, W F	8004080342 8004220111 8004210123 8004210136 8004300458	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POTTER, J P	8004040035* 8004040379* 8004040453* 8004080147* 8004080140*	50-255 Q 50-315 Q 40-2061 27-47 27-47	RECORD, D J RECORD, D J RECORD, D J RECORD, D J RECORD, D J	8004170227* 8004010381* 8004010403* 8004010371* 8004010475*	50-327 F 50-327 S 50-327 S 50-327 S 50-327 S
POCHALIN F PODHURSTIO U PODHURSTID W PODHURSTID W POGGIO, A	8004300459 8004040422* 8004040437* 8004040442* 8004280059	XPORTLIC FOIA FOIA FOIA RCS	POTTER, J P	6004040023* 8004100408* 8004100528* 8004010009* 8004040171*	50-10 G 50-10 G 50-254 G CONTRACT 50-331 G	RECORD.D J RECORD.D J RECORD.D J RECORD.D J RECORD.D J	8004170229* 8004170231* 8004170234* 8004090336* 8004090457*	50-327 F 50-327 F 50-327 F 50-327 S 50-327 S
POGGIO, A POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R	8004240465 8004090434 8004030344 8004090434 8004080044	RES 50-445 M 50-445 M 50-445 M 50-445 M	POTTHOFF, F H POTTHOFF, F H POTTS, W E POWERS, J A POWER, D F	8004240555* B004100474 B004170106* B0040B061B B004010054	50-466 G 50-466 G 50-267 P CONTRACT FDIA	RECORD.D J RECORD.D J RECORD.D J RECORD.D J RECORD.D J	8004180465* 8004180407* 8004150512* 8004150565* 8004220722*	50-327 8 50-327 8 50-327 8 50-327 8 50-327 8
POIRIER, M R	8004080044 8004040078 8004190032 8004150050* 8004190050*	50-445 M 50-445 M 50-445 M 50-445 M	POWER.D F POWERS.M B POWER.D F PRAGER.J C PRATT.C M	8004090129 8004300243 8004290152 8004140246 8004100434	FOIA 40-8722 FOIA 50-280 P PR	RECORD, D J REED, J W REED, R W REED, C REED, M	B004220757* 8004040153* 8004150103 8004020429 8004290407*	50-327 S 50-70 P 50-346 P TOPREP 50-265 B
POLID L POLLARD, R D POLLARD, R D POLLARD, R O POLLARD, R G	0004030207 8004020113* 8004070170 8004030320 8004110175	PR 50-3 0 50-289 0 50-289 0 50-289 0	PRESSESKY, A J PRESSESKY, A J PRICE, E R PRICE, E R PRICE, E R	8004240568 8004280172 8004080142* 8004080110* 8004080060*	PR PR FOIA FOIA FOIA	REED.C REEHAL.B B REEVES.E REEVES.E A REEVES.E	8004290434 8004220528* 8004110573 8004110555 8004300588	TOPREP FOIA 50-348 F 50-295 Q 50-295 F
POLLARD, R Q POLLACK, G L POLLARD, R Q POLLARD, R Q POLLARD, R Q	8004230039 8004160039* 8004110157 8004110164* 8004110166*	50-289	PRICE, E R PRICE, E R PRICE, E R PRICE, E R PROFID, A E	8004080095* 8004080098* 8004080084* 8004080076* 8004070329*	FOIA FOIA FOIA FOIA 50-433 R	REGAN, H H REHM, T A REHM, T A REHM, T A REHM, T A	8004020154 8004070066 8004100572 8004140457 8004250046	50-272 P COMMISSION COMMISSION COMMISSION
POLLEY, R D POLLEY, R D POLLETT, K POLLOCK, R P POLOBKI, J P	8004240479* 9004020179* 8004040224 8004090152 9004020142	50-320 P COMM1881ON 90-352 H PR RES	PROXMIRE, W PROXMIRE, W PUCILLO, A C PUCKETT, J M GUARANTELLI, E	8004140379* 8004080244* 8004240041* 8004250291* 8004230514	50-266 U 50-409 U CONTRACT 50-261 Q 50-320 H	REICHERT,E C REICH,M REID,R W REID,R W REID,R W	8004070276* 8004240566 8004080437 8004080440* 8004030275	50-317 R NUREO 50-317 P 50-317 P 50-285 P
POPE, J R POPE, J R PORTER, W L PORTER, W L POTAPOVS, U	0004180223 8004080160 8004090241 8004280473 8004070087#	50~546	GUEENER.D S GUICK.D GUICK.D R GUIGG.C GUIGG.C	8004230303* 8004300187* 8004300260* 8004150031 8004010171	NUREG 50-302 G 50-269 G 50-268 P FOIA	REID,R W REID,R W REID,R W REID,R W REID,R W	8004040071 8004040076* 8004040107* 8004070160 8004210108	50-317 P 50-317 P 50-317 P 50-313 P 50-289 H
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8004070083* 8004080276* 8004140037* 8004030239* 8004010512	QA797 QA777 QA979 QA979 QA979	GOTUN'E' GOTOGEA'D K GOTOGEA'D K GOTOGO'G	8004280590 8004080679 8004100194* 8004020069 8004080197	50-295 G 70-1308 CONTRACT 70-135 70-135	REID.R W REID.R W REID.R W REID.R W REID.R W	8004070264 8004080002 8004150177 8004010255 8004030230	50-336 P 50-302 P 50-312 F 50-267 P
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8004140027* 8004040348* 8004080367* 8004070270*	QA999 QA999 QA999 QA999 QA999	GUIRK.J F GUISENBERRY.G F RADER.R M RAFI.A. RAGSDALE.J D	8004280422 8004020114* 8004110574 8004070276* 8004210395*	50-550 A 50-289 H 50-445 M 50-317 R 50-275 G	REID.R W REID.R W REID.R W REID.R W REID.R W	8004020449 8004170294 8004100115 8004150110* 8004150120*	50-312 P 50-287 P 50-312 P 50-346 P 50-346 P
POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVB, U POTAPOVB, U	8004040111 8004080301* 800429021* 8004020423 8004090307	QA999 QA999 QA999 QA999 QA999	RAINEY, J L RANDOLPH, M L RANDOLPH, M L RANSOHOFF, J A RAPKIN, A	8004070151 8004040367 8004160075 8004070121* 8004030302	40-2061 RES RES 71-121 FOIA	REID, R W REID, R W REID, R W REID, R W REID, R W	8004160180 8004150082 8004210321 8004100241 8004100246*	50-335 P 50-54 P 50-269 P 50-312 P 50-312 P
POTAPOVE, U POTAPOVE, U POTAPOVE, U POTAPOVE, U POTAPOVE, U	8004090382# 8004140018# 8004090067 8004100031 8004110044#	QA779 QA779 QA779 QA779 QA779	RABH, J L RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L	8004170020* 8004030054* 8004030071* 8004030093*	50-324 P 50-320 H 50-320 H	REID.R W REID.R W REID.R W	8004100255* 8004110481 8004170316	50-312 P TOPREP 50-317 F
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8004070076 8004300217 8004040476 8004070059 8004080255	QA979 QA979 QA979 QA999 QA999	RATHKOPF.C L RATHKOPF.C L RATHKOPF.C L RATHKOPF.C L RATHKOPF.C L	80040402 80040402 80040402 80040404 80040902				
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8004080358 8004090282 8004080271 8004030235 8004070371	0A799 GA799 GA799 GA799 GA799	RATHKOPF.C L RATHKOPF.C L RATHKOPF.C L RATHKOPF.C L RATHKOPF.C L	80042102 80042201 80042201 80040204 80040300				
MATERIA II	0004140011	UVABOO	RATHKOPF.C L	80040402				

RATHKOPFIC L RATHKOPFIC L RATHKOPFIC L RATHKOPFIC L RATHKOPFIC L

8004140011 8004110031 8004290016 8004300084 8004160172*

POTAPOVE, U POTAPOVE, U POTAPOVE, U POTAPOVE, U POTTER, J P QA999 QA999 QA999 QA999 50-277

a

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSIUM NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
REINMUTH C U REIS H F REIS H F REIS H F REIS H F	8004280098*	50-334 P	ROCKHOLD, H C	8004250364	50-295 P	ROTHE, P.H.	8004140478	NUREO
	8004020265*	50-389 G	RODACK, M	8004070184	50-387 H	ROTHFLEISCH, J.	8004070353	NASTE HOT
	8004220141	50-389 G	RODEN, J W	8004150385*	50-366 R	ROTHFLEISCH, J.	8004070369	WASTE HOT
	8004020265*	50-389 G	RODEN, J W	8004150390*	50-321 R	ROTHFLEISCH, J.	8004090209	40-8721
	8004220141	50-389 G	RODEN, J W	8004150404*	50-321 R	ROTHSCHILD, M. U.	8004080726	50-445
REIS, E J	6004080355	50-443 Q	RODGERS, L. M	8004020418*	50-213 F	ROTHSCHILD, M U	8004090015	50-445 9
REIS, H F	8004240484	50-250 G	RODGERS, L. M	8004620418*	50-213 F	ROTHSCHILD, M U	8004090446	70-1308
REIS, H F	8004246484	50-250 G	RODGERS, L. M	8004020424*	50-213 F	ROTHSCHILD, M U	8004100151	70-1308
REIS, H F	6004110529	50-250 Q	RODRIGUEZ, R. J	8004160266	50-312 R	ROTHSCHILD, M U	8004100164*	70-1308
RENEMEYER, P C	6004086276	HASTE MQT	RODRIGUEZ, R. J	8004220731	50-312 S	ROTHSCHILD, M M	8004210424	50-445 9
REKEMEYER P C	8004020165	WASTE NOT	ROE.D	8004040346	50-275 H	ROTHSCHILD, M U	8004240424*	50-445
REMLEY, M &	8004280061	71-6400	ROE.J W	80040701834	50-250 F	ROTHSCHILD, M U	8004250348	
RENBERGER, D L	8004030341	PR	ROE.J W	80040902773	50-250 F	ROTHSCHILD, M U	8004170251	
RENBERGER, D L	8004230271*	50-460 Q	ROGERS.R F	80041500963	50-321 Q	ROTHSCHILD, M U	8004230206	
RENBERGER, D L	8004020339	50-397 K	ROGERS.R F	80041501553	50-321 Q	ROTHSCHILD, M U	8004220377	
RENBERGER, D L RENBERGER, D L RENBERGER, D L RENBERGER, D L RENBERGER, D L	8004230248* 8004010340 8004020293 8004020302 8004070367	50-460 Q 50-508 A 50-397 S 50-397 S	ROGERS, W L ROGERS, B J ROGERS, H A ROGERS, W F ROGERS, W F	8004070115 8004210060> 8004140070* 8004180088 8004180089*	WASTE MGT 50-29 H 70-1308 YPORTLIC XPORTLIC	ROTHSCHILD, M U ROTHSCHILD, M U ROUNDTREE, R E ROUSE, L C ROUSE, J V	8004240421 8004240433* 8004100430* 6004010166* 8004090140*	5Q-445 0 50-445 0 50-445 M 70-1308 Waste Mot
RENDERGER, D L	8004170207	50-397 A	ROGERS, W F	9004180092*	XPORTCIC	ROUSE, L C	B004180441*	50-269 0
RENBERGER, D L	8004140345	50-397 K	ROGERS, L W	8004210297*	50-10 H	ROWDEN, M	B004220442*	FO1A
RENBERGER, D L	8004150443	50-508 A	ROGERS, C S	9004280030	50-556 G	ROWE, D S	B004070234	71-24
RENBERGER, D L	8004210213	Nureg	ROGERS, W H	9004020359*	50-321 8	ROY, G W	B004140202	18E
RENBERGER, D L	8004210285	50-397 A	ROGERS, W H	9004220658*	50-366 S	ROY, G W	B004220226	50-272 8
RENBERGER, D L RENDERGER, D L RENNELS, A E RENNO, E RESSLER, W C	8004280466 8004280475 8004080177 8004040300 8004140250	50-397 S 50-397 S 40-2061 50-320 H 50-320 R	ROGERS, W H ROGERS, W H ROMAN, T W ROOD, H ROONEY, M A	8004220684* 8004220717* 8004140411* 8004290133 8004140078	50-321 8 50-366 S 50-220 R 50-361 A 70-1308	RDY.G W ROY.G W RUBENSTEIN, L B RUBENSTEIN, L B	8004220249 8004210429 8004030237* 8004140090 8004010014	50-26J B 50-331 B 6A999 50-329 A 50-410 A
REYES,L. A REYNOLDS,N. S REYNOLDS,L. E REYNOLDS,L. E	8004100022+ 8004080119 8003250002 8004070254 8004040068	50-346	ROONEY, M A ROONEY, V L ROOT, L D ROOT, L D	8004140060 8004070040 8004160005 8004220269 8004140380	70-130B 50-271 P 50-331 Q 50-331 F 50-331 P	RUBENSTEIN, L S	8004040079 8004070041 8004070072 8004070419 8004070393	50-397 A 50-440 A 50-327 G 50-327 P 50-327 P
REYNOLDS, N S REYNOLDS, L E REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S	8004080221 8004090691 800404088 8004080221 8004140005	50-445	ROOT,L D ROOT,L D ROOT,L D ROREM ROSA,F	8004220507 8004280461 8004280454 8004150106 7811100178	50-331 P 50-331 P 50-331 F 70-1308 50-313 B	RUBENSTEIN, L B RUBENSTEIN, L B RUBENSTEIN, L B RUBENSTEIN, L B RUBENSTEIN, L B	8004020093 8004090034 8004100297 8004110493 8004100507	50 327 P 50 410 F 50-410 A 50 327 P 50-367 A
REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S RHEINKEIMER, D	6004280169 6004280169 6004160285 6004240424* 6004070191	50-556	ROSEN, A.E. ROSENTHAL. D S ROSEN, A E ROSOLIE, E ROSOH, D F	80040700B1* 8004300297* 8004070079* 8004230020 8004040275*	08797 U E-08 98799 0 44E-08 50-017	RUBENBTEIN, L 8 RUBENBTEIN, L 6 RUBENBTEIN, L 6 RUBENBTEIN, L 6 RUBENBTEIN, L 8	8004140115 8004140118 8004180306 8004230186 8004250001	50-454 F 50-454 F 50-327 F 50-546 A 50-327 A
RHEINHEIHER, D	8004070064	50~387 H	ROSOW.D F	8004040296*	50-317 G	RUBENSTEIN, LS RUBENSTEIN, LS RUBENSTEIN, LS RUBENSTEIN, LS	8004170263	50-443 1
RICE, O B	8004080163*	40~2041	ROSOW.D F	8004040301*	50-31/ G		8004180058	50-328 A
RICHARDBON, H D	8004210037	71~6717	ROSS.D M	8004020055	71-6387		8004180070*	50-328 A
RICHARDBON, H D	8004020025	71~9135	ROSS.D	8004020237*	State Prog		8004280619	50-397 A
RICHTER, S W	8004040275*	50~317 G	ROSS.D F	8004040031	50-275 A		8004300266	50-328 Q
RICHTER, S W	8004040276*	50-317 Q	ROSS.D F	8004040017	50-275 A	RUBENSTEIN, L S RUBENSTEIN, L S RUETER, D A RUETER, D. A RUFF, A B	8004300270*	50 328 9
RICHTER, S W	8004040301*	50-317 G	ROSS.D A	8004080421	50-217 G		8004240482	50-390 F
RICHTER, T	8004220567	50-320 H	ROSS.D A	8004090246*	50-217 G		8004010416	50-313 0
RICKOVER, H &	8004070082	DRG	ROSS.L L	8004010789*	PT9		8004240380	50-313 P
RICKOVER, H &	8004070087	DRG	ROSS.P A	8004150430	Nureo		8004100051*	50-416 0
RIINA, JR	8004170139	FOIA	ROSS.W J	E004020433	50-272 P	RUH-MING, L	8004280425*	40-8602
RILEY, BW	80042801974	50-325 0	ROSS.D F	B004230058	50-275 A	RUH-MING, L	8004280427*	40-8602
RISCHLING, JL	8004010500#	50-314 S	ROSS.D A	B004100424	50-217 O	RUITER, O H	8004180355*	50-305 R
RISCHLING, JL	8004080545#	50-314 S	ROSS.D F	B004020453	TOPREP	RUSSELL, W T	8004280065	50-334 P
RISCHLING, JL	8004230357#	50-314 S	ROSS.D F	B004110040	50-271 P	RUSSELL, L B	8004010439	50-318 B
RITSHER,J A RITYS,F H RIVARD,W C RIZZI,R A RIZZI,R A	8004070299 8004080559 8004150141* 8004090208 8004090208	50-443 I 50-445 M NUREQ PROJ PROJ	ROSS.W J ROSS.D F ROSS.D A ROSS.D A	8004150227 8004020213 8004010480 8004010485* 8004010503	50-272 P 50-329 H 50-219 B 50-219 B 50-217 B	RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8004010342 8004010376 8004010380 8004010430 8004010364	50-310 6 50-310 8 50-310 8 90-317 8 90-310 8

c

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION REMUN	SUBJECT CATEGORY
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUZICKA, W G RUZICKA, W G	8004270457 8004270475 8004270470 8004080548 8004070375	50-317 S 50-317 S 50-317 S 50-317 S 50-54 R	SCHMIDT, E W SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8004040204 8004180529 8004020377 8004030282 8004030249	RES 50-250 R 50-251 S 50-335 S 50-250 S	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004280151* 8004280156* 8004040179 8004040183* 8004240251	50-261 P 50-261 P 50-250 P 50-250 P 50-250 P
RYAN, R G	8004070094	50-3 P	SCHMIDT, A D	8004080601	50-250 S	SCHWENCER, A	B004240263*	50-250 P
RYAN, R O	8004040193	State Prog	SCHMIDT, A D	8004180373	50-250 R	SCHWENCER, A	B004240283*	50-250 P
RYAN, R M	8004300320*	50-225 G	SCHMIDT, A D	8004240309	50-250 S	SCHWEID, S	B004030012	50-312 H
SABOL, A R	8004070382*	50-387 G	SCHMIDT, A D	8004240334	50-335 S	SCHWENCER, A	B004070322	50-344 Q
SABOL, A R	8004100098*	50-387 G	SCHMIDT, A D	8004240369	50-335 B	SCHWENCER, A	B004220087	50-344 P
SAENGER, E L SAENGER, E L SAENGER, E L SAENGER, E L BAENGER, E L	8004220044* 8004220077* 8004220101* 8004220120* 8004220387*	FOIA FOIA FOIA FOIA	SCHNEIDER, F W BCHNEIDER, F W BCHNEIDER, F W SCHNEIDER, F W BCHNEIDER, F W	8004080318 8004100256 8004100247 8004300488 8004240494	50-272 Q 50-272 Q 50-272 Q 50-272 Q 90-272 Q	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004240442 8004080320 8004240462 8004300276 8004300280*	50-344 F 50-280 P 50-315 P 50-266 P 50-266 P
BAENGER, E. L.	8004220391*	FOIA	SCHNEIDER, F W	8004280124*	50-272 0	BCHWENCER, A	8004300287*	50-246 P
BAENGER, E. L.	8004220404*	FOIA	SCHNEIDER, F W	8004280207	50-272 0	BCHWENCER, A	8004210194	50-295 P
BALAH, B.	7903080264	MISC	SCHNEIDER, F W	8004070225	50-272 I	BCHWENCER, A	8004240163	50-247 P
BALTZMAN, J.	8004080173*	FOIA	SCHNEIDER, F W	8004160249	50-272 0	SCHWENCER, A	8004240175*	50-247 P
BALTZMAN, J.	8004140124*	FOIA	SCHNEIDER, E J	8004160246	50-272 0	BCHWENCER, A	8004020096	50-261 P
SALTZMAN, J	8004140078	50-443 M	SCHOPPMAN, M A SCHOPPMANN, M A SCHOPPMANN, M A SCHOPPMANN, M A SCHOPPMANN, M A	8004020391*	50-251 8	SCHWENCER, A	8004100268	50-250 P
SALTZMAN, J	8004140277	50-443 M		8004030285*	50-335 8	SCHWENCER, A	8004100275*	50-250 P
SALTZMAN, J	8004250355	50-338 J		B004030256*	50-250 S	SCHWENCER, A	8004100284*	50-250 P
SALZMAN, L	8004300080*	50-387 G		B004080608*	50-250 S	SCHWENCER, A	8004100458	50-251 P
SALZMAN, R	8004230103*	50-275 G		8004240317*	50-250 S	SCHWENCER, A	8004100467*	50-251 P
SAMWORTH, R B	7811300053	50-568 A	SCHOPPMANN, M A SCHOPPMANN, M A SCHUESSLER, W J SCHULTZ, W H	8004240343*	50-335 S	SCHWENCER: A	8004100475*	50~251 P
BANDERS, W F	8004070111*	50-443 G		8004240375*	50-335 S	SCHWENCER: A	8004110001	50~284 P
BANDERS, D	8004150601*	50-368 F		8004010492	50-305 P	SCHWENCER: A	8004250178	50~280 P
BANDERS, D	8004150579*	50-368 F		8004210153	50-466 G	SCHWENCER: A	8004250193*	50~280 P
BANDERS, W F	8004180512*	50-309 Q		8004220186*	FOIA	SCHWENCER: A	8004250212*	50~280 P
SANDS.B P SANDVIK.R M SARBANEB.P SARSOUR.B SASSER.D W	8004080677 8004250375 8004220659 8004140353* 8004280035	50-312 P 50-514 0 50-320 U 50-346 R NUREQ	SCHULTZ, W H SCHULTZ, W B ECHULTZ, W B SCHULTZ, G R BCHUMACHER, M C	8004230050* 8004010294 80040103004 8004230006 8004100377*	FDIA 50-367	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004220004 8004230125 8004110547 8004210014 8004240445	50-286 G 50-275 F 50-338 G 50-344 F 50-334 P
SABTRE, C	8004070158	RES	SCHUMACHER, K	8004080571	50-387 G	SCHWENCER, A	8004240456	50-315 P
SATTERFIELD, R	7811100178	50-313 B	SCHUR. B H	8004080188*	FOIA	SCHWENCER, A	8004140086	50-305 F
SATTERFIELD, R	8004220227*	50-287 Q	SCHWARTZ, W B	8004220635*	FOIA	SCHWENCER, A	8004140039	50-272 F
GAUDER, J L	8004110571	50-289 H	SCHWARTZ, E A	8004110553	State Prog	SCHWEITZER, D G	8004280063	RE9
SAUERS, M A	8004300083*	50-387 Q	SCHWARZ, M D	8004020134	50-498 G	SCHWENCER, A	8004250029	50-241 P
SAUER,D W SAUNDERS,S C SALYER,S SCALPI,M SCALPI,M	8004150532* 8004220785 8004040298* 8004100438 8004080152	50-305 B ACRS ACRS PR PR	SCHWARZ, M D SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004020134 8004180286* 8004080325* 8004080330* 8004040418*	50-498	SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A	8004160016 8004210010 8004240076 8004280273 8004280277*	50-316 P 50-280 P 50-266 P 50-266 P
ECANLON, W J	8004020237*	State Prog	BCHWENCER, A	8004240504*	50-286 P	BCHWENGER, A	8004280304*	50-266 P
BCARAND, R A	8004270041*	40-8602	SCHWENCER, A	8004020457	50-315 P	BCHWENGER, A	8004290077	50-250 F
BCARAND, R A	8004270044*	40-8602	BCHWENCER, A	8004020460	50-272 P	BCHWENGER, A	800430502	50-305 F
BCARAND, R A	8004280418*	40-8681	BCHWENCER, A	8004020463	50-295 P	BCHWENGER, A	8004180045	50-334 P
BCARAND, R A	8004030184	40-8502	BCHWENCER, A	8004140087	50-266 P	BCHWENGER, A	8004210032	50-272 P
ecarand, r a scarand, r a scarand, r a scarand, r a scarand, r a	8004070259 8004070412 8004180105 8004280417 8004270036	40-1162 40-8452 WASTE MOT 40-8681 40-8602	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004150318 8004110300* 8004030276 8004110089 8004150138	50-334 P 50-456 Q 50-338 F 50-295 F 50-315 P	SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A	B004220117 B004230010 B00425002 B004300250 B004300255*	50-247 P 50-266 Q 50-334 P 50-344 P
SCARAND, R A	8004300104	40-8602	SCHWENCER, A	8004020257	50-275 P	SCHWENCER, A	8004300264*	50-344 P
SCARAND, R A	8004270110	40-3453	BCHWENCER, A	8004020262*	50-295 P	SCHWENCER, A	8004280062	50-250 P
SCARTH. E D	8004020175*	50-445 M	BCHWENCER, A	8004020266*	50-295 P	SCHWENCER, A	8004300162	50-334 P
SCHAFFSTALL, R E	7907250258	MISC	SCHWENCER, A	8004020270*	50-295 P	SCHWENCER, A	8004300169*	50-334 P
SCHAPER, J F	8004040132*	50-346 Q	SCHWENCER, A	8004110520	50-282 P	SCHWENCER, A	8004300189*	50-334 P
SCHAPER, J F	8004040079*	50-483 Q	BCHWENCER, A	8004110524*	50-282 P	SCHWENCER, A	8004250020	50-348 P
SCHABER, H	8004030012	50-312 H	BCHWENCER, A	8004140481	50-280 P	SCHWENCER, A	8004250167	50-284 P
BCHAUER, F P	8004220042	50-424 A	BCHWENCER, A	8004140490	50-305 F	SCHWENCER, A	8004290158	50-247 P
SCHENDEL, K R	8004280283	40-9304	BCHWENCER, A	8004220172	50-295 P	SCHWENCER, A	8004280113	50-286 P
SCHERA, L	8004070423	50-250 H	BCHWENCER, A	8004010004	50-295 P	BCHWENCER, A	8004240458	50-247 P
SCHERER, A E	8004010478	TOPREP	SCHWENCER, A	8004020070	50-282 P	SCHWENCER, A	8004300072	50-280 F
SCHERER, S J	8004150101	50-574 0	SCHWENCER, A	8004020073*	50-282 P	SCHWENCER, A	8004280199	50-3 P
SCHERER, A E	8004230315	TOPREP	SCHWENCER, A	8004020075*	50-282 P	SCIANDRA, J	8004210093*	50-3 H
SCHERER, A E	8004280400	TOPREP	SCHWENCER, A	8004020079*	50-282 P	SCINTO, J	8004020298	MISC
SCHILLER, W	8004010521	50-322 0	SCHWENCER, A	8004140050	50-334 P	SCINTO, J	8004150098	50-556 0
SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8004240368 8004240448 8004240350 8004240470 8004240455	50-250 R 50-250 R 50-250 R 50-250 R 50-250 R	BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8004140054* 8004140058* 8004150041 8004040260 8004040423		BCOTT, A BCOTT, A BCOTT, J BCOTT, J	8004270233 8004140175* 8002270321 8004230035 8004150461	50-272 0 50-339 H 50-327 0 50-466 0 50-367 P
BCHMIDT, A D	8004240359	50-250 R	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004280217	50-275 P	SCRABIAN, J	8004090027	50-213 B
BCHMIDT, A. D	8004240443	50-250 R		8004280223	50-286 P	BCRANTON, W W	8004070015#	50-320 P
BCHMIDT, A D	8004240463	50-250 R		8004030271	50-250 F	SCWENCER, A	8004140014	50-286 P
BCHMIDT, A D	8004240436	50-250 R		8004090166	50-250 P	SEAL, M M	8004140026#	50-155 H
BCHMIDT, A D	8004240418	50-250 R		8004090169*	50-250 P	SEAL, M M	8004070077#	50-327 H
SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIEDER, J R	8004230330 8004230484 8004230321 8004180524 8004090354	50-250 R 50-250 R 50-250 R 50-250 R 50-250 R	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004090174* 8004040190* 8004080003 8004080013* 8004280148	50-250 P 50-275 P	BEAL, M M BEAL, M M BEAL, M M SEIDLE, W C. BEIDLE, W C	8004140097* 8004140190* 8004210031* 8004270492 8004180214	50-339 H 50-339 H 50-339 H 50-445 Q 50-498 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SEIDLE, W C SEIDLE W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8004140046 8004140081 8004220232 8004040081 800404008	50-45B Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V	8004010476 8004010493 8004080510 8004140438 8004150363	50-316 S 50-316 B 50-316 S 50-316 S 50-316 R	SHURTS, S J SHURTS, S J SHURTS, S J SHURTS, S J SIEGEL, S	8004150571* 8004150580* 8004150589* 8004150578* 8004030313	50-263 8 50-263 8 50-263 8 50-263 9 ACRS
SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDTS, M G	8004070057 8004300028 8004250079 8004300514 8004100006	50-498	SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V	8004150368 8004230430 8004230351 8004230438 8004290417	50-315 R 50-316 S 50-316 S 50-315 S 50-315 S	SILBERO, J E SILBERO, J E SILBERO, J E SILBERO, J E	8004100090 8004220008 8004220008 8004220102 8004220102	PR 50-320 0 50-320 0 50-320 0
SEIGEL.B L SEIKEN.S J SEKULA.P SEKULER,S N SELCHO.H S	8004210328 8004180352 8004100478* 8004210447 8004100328	50-267 P 50-402 A 50-267 G 70-1308 RES	Shanaman, 5 Shanaman, 5 Shanaman, 5 Shanaman, 5 Shanbaky, M	8004090478* 8004090479* 8004090480* 8004090481* 8004080352*	50-320 I 50-320 I 50-320 I 50-320 I 50-317 Q	SILBERG, J E BILBERG, J E BILKER, W B BILVER, M BILVER, R D	8004210083 8004210085 8004110065 8004070141 8004030182	50-320 0 50-320 0 NUREO 50-289 P 50-155 P
SELLS.D E SELLS.D E SELLS.D E	8004020284 8004020127 8004030265 8004090768 8004090276	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	SHANK,R B SHANK,H J SHAPAR,H X SHAPAR,H X SHAPAR,H X	7908010479* 7908010475 8004100039* 8004080209 8004140245	50-320 H 50-320 H 10CFR 50-327 G FRM	SILVER.R D SIMCHUCK, Q SIMMONS, D D SIMMONS, D B SIMMONS	8004100166 8004070135 8004280425* 8004280427* 8004010379*	50-255 P WABTE MOT 40-8602 40-8602 50-327 Q
SELLS, D E SELLS, D E SELTZER, A M SELTZER, A M	8004030153 8004040230 8004220079 8004070478# 8004090479*	50-320 H 50-320 H 50-367 D 50-320 I 50-320 I	SHAPAR, H K SHAPAR, H SHAPAR, H K SHARP, D R SHAUD, E T	8004080047 8004250003 8004180283 8004020432* 8004080579*	50-307 P 50-554 Q 50-416 M TOPREP 70-364	SIMMONS SIMON.P SIMPSON,A K SINGER.D SINGER.D	8004170155# 8004140180# 8004080314# 8004220578# 8004220571#	50-327 Q 50-10 U 40-1341 FOIA FOIA
SELTZER,A M SELTZER,A M SENECHAL,M E SENECHAL,M E SERABJAN,J A	8004070480# 8004070481# 8004230088 8004230100 8004210070#	50-320 1 50-320 1 50-282 0 50-282 6 50-286 0	SHAUB, E T SHAUB, E SHCWENCER, A SHEA, J R SHEA, J R	80040702!1* 80040701!9* 8004240492* 8004210078* 8004010051	50-184 Q 70-398 50-286 P 70-2478 SECY	SINGER, L N BINGER, L N BINGER, L N BINGER, L N BINGER, L N	8004020104 8004020107* 8004010287 8004100452 8004080045	50-287 0 50-287 0 50-287 0 50-287 0 50-289 0
SETHNESS, E D SETIER D R SEWELL, R B SEYFRIT, K V SEYFRIT, K V	B004020057 B004220326# B004100462# B004270171# B00407007B#	NASTE MGT 70-2623 50-155 G QA999 QA999	SHEA.X H SHEA.J J SHEA.K H SHEA.J J SHEA.K H SHEA.J R	8004020280 8004240181 8004040076 8004020092 8004020092	50-367 G 70-2805 50-409 A 50-367 G 50-367 D	SINGER, L N SINGER, L N SINGER, L N SINKIN, L SIPE, L W	8004080025* 8004100589 8004170058 8004280069 8004080106	50-289 Q 50-289 Q 50-289 Q 50-478 Q 50-320 H
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004100093 8004290179* 8004150231 8004150233 8004150234	50-298 Q QA979 50-313 Q 50-298 Q 50-285 Q	SHEA, J R SHEA, J R SHEA, J R SHEA, J J	8004070029 8004070034* 8004070148 8004110538 8004170322	XPORTLIC XPORTLIC SECY XPORTLIC SO-244 F	SKINNER, W F SKIBLAK, B SKOLDS, J L SKOLDS, J L SKOVHOLT, D J	8004210335 8004300037* 8004100414* 8004280014* 8004220035	50-320 P 50-387 0 50-375 0 50-375 0 NISC
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	5004150237 8004080646 8004080648 8004080670 8004080673	50-267 Q 50-313 Q 50-298 Q 50-265 Q 50-267 Q	SHEA, K H SHEA, K H SHEA, J R SHEDLOSKY, J T SHELDON, K P	8004230105 8004240194 8004250028 8004180147* 8004080364	50-367 G PRM XPORTLIC 50-245 G 50-443 G	SLICKER, FK SLICKER, FK SLICKER, FK SLICKER, FK SLICKER, FK	8004070164 8004070175 8004070180 8004100221 8004070164	50-445 H 50-445 H 50-445 H 50-445 H
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8004110097 8004110101 8004110102 8004110104 8004180493	50-313 Q 50-298 Q 50-285 Q 50-267 Q 50-313 Q	SHELLEY, W J SHELDON, K P SHELDON, K P SHELDON, K P	8004160138* 8004280026 8004280026 8004080158 8004110563	50-287 0 50-287 0 50-287 0 40-2061 70-425	SLICKER, FK SLICKER, FK SLICKER, FK SLIDER, JE SLOAN, DE	8004070175 8004070180 8004100221 8004180177* 8004280248	50-445 H 50-445 H 50-445 H COMMISSION PT21
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004180494 8004180496 8004180499 8004220206 8004240214	50-278 G 50-285 Q 50-267 G 50-458 Q 50-498 Q	SHELLY, F L SHERIDAN, C F SHERWOOD, G G SHERWOOD, A L SHERWOOD, A L	8004180247 8004210316 8004100061 8004230302* 8004230317*	50-3B7 Q 50-443 F PT21 PROJ PROJ	BLOBODIEN, M J BLOBB, C B BLYVIA, B R SMEDIRA, C BMEDIRA, C	8004210052* 8004080133* 8004100410 8004070117 8004070121*	FOIA FOIA 50-337 Q 71-121 71-121
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8004240218 8004240220 8004240225 8004180158 8004180159	50-482 Q 50-382 Q 50-445 Q 50-285 Q 50-313 Q	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHELDS, S W	8004080671 8004080168* 8004100291* 8004110556* 8004210131	50-546 A 50-546 A 50-546 G 50-546 G 50-546 G	SMITH, C W SMITH, O H SMITH SMITH, C V SMITH, O H	8004010175* 8004220374* 8004240084* 8004240150* 8004210137*	70-1308 FOIA 70-135 70-135 70-1100
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004180162 8004180165 8004220257 8004220260 8004220281	50-267 Q 50-298 Q 50-482 Q 50-498 Q 50-382 Q	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIER, W O	8004070146# 8004100371 8004270426 8004300348 8004150478	30-546 G 30-346 G 30-546 A 30-546 A Res	EMITH. 0 H EMITH. 0 H EMITH. 0 H EMITH. 0 H	8004020131* 8004210064* 8004070392* 8004100373* 8004100009*	ACRS 50-206
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004220268 8004220320 8004270168 8004110006 8004220770	50-45B Q 50-445 Q QA999 50-29B Q 50-45B Q	SHILLMAN, GR SHILDBOD, DS SHINEFLUG, M SHINKO, MS SHIVELY, CN	8004160184* 8004090486 8004140456 8004080684 8004020353*	50-320 P F01A 50-10 U REB 50-313 B	SMITH, O D SMITH, O C SMITH, O C SMITH, O C	8004230019 8004210214* 8004070207* 8004090419* 8004070217*	FOIA 70-135 70-1100 70-135 70-135
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8004220777 8004220779 8004220783 8004230324 8004230327	50-498 Q 50-445 Q 50-382 Q 50-313 Q 50-298 Q	SHOLLY, S C SHOLLY, S C SHOLLY, S C	9004080594* 9004150618* 9004220703* 8004010036 8004010040*	50-368 6 50-368 6 50-368 6 50-289 0 50-289 0	Smith. 0 h Smith. R Smith. 0 h Smith. 0 h Smith. 6, h	8004210135# 8004070159# 8004070354 8004070105 8004100223#	70-1100 50-313 G 50-293 G 70-1100 50-201 G
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004230350 8004230354 8004220208 8004220228 8004220233	50-267	SHOLLY, S C SHOLLY, S C SHOLLY, S C SHOLLY, S C	8004010042* 8004010044* 8004110541 8004110546* 8004020044	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0	SMITH, OH SMITH, EH SMITH, EH SMITH, EJ	8004300232* 8004100083 8004100443 8004100448 8004210133*	50-244 0 PR PR 50-244 F 70-1100
BEYFRIT,K V SEYFRIT,K V SHA,W T SHA,W T SHALEK,R J	8004220237 8004220241 8004150326 8004270017 8004220130*	50-458 Q 50-462 Q NUREG NUREG FOIA	SHOLLY, S C SHOLLY, S C SHOTKIN, L M SKULL, G B SHUM, E Y	8004070187 8004110184 7907300056 8004080082 8004180098	50-287 0 50-320 0 MISC RES 70-2909	SMITH, T. H BMITH, O H BMITH, R SMITH, G H BMITH, I W	8004080450* 8004080271* 8004040140* 8004100162 8004220350	50-213 0 50-333 0 50-267 0 50-220 0 50-289 0

AUTHÜR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SMITH. GH SMITH. GH SMITH. GH SMITH. GH SMITH. GH	8004D703B3 8004100347 8004210084 8004210169 8004160165	70-364 50-334 @ 70-1143 50-293 @ 50-277 @	SOLBRIO, C W SOLENBERGER, R SOUCY, A R SOUDER, J L SOUDER, J L	8004080082 8004280492 8004010395 8004070364 8004080064	RES 50-387 A 50-29 I 50-367 H 50-289 G	STALLINGS, C II STALLINGS, C II STALLINGS, C II STAMPLEY, N L STAMPLEY, N L	6004030210 6004030236 6004070262 8004100439 8004070254	50-33B Q 50-33B R 50-33B Q PR REGOD
SMITH, R SMITH, R SMITH, R SMITH, J D SMITH, O H	8004210179# 8004210438# 8004040465 8004110245# 8004100003	50-445 Q 50-445 Q 71-6375 50-266 Q 50-184 Q	SOUDER, J L SOWDON, T L SPANGLER, R G SPANGLER, R G SPANGLER, M B	8004110577 8004080524 8004090157* 8004210217* 8004170337	50~482 A 50~293 R 50~313 Q 50~298 Q NUREG	STAMPLEY,N L STAMPLEY,N L STAMPLEY,N L STAMPLEY,N L STARKEY,R B	8004100541 8004070341 8004150200* 8004220287 8004140468*	RFGGD 50-416 A 50-416 M 50-116 C 50-261 Q
SMITH, OH SMITH, OH SMITH, OH SMITH, OH	8004210027 8004210029 8004210074 8004210079 8004210115	70-1100 40-672 50-272	SPARGO, L L SPELLMAN, K SPENCER, G S SPENCER, G S SPENCER, G S	8004220303 8004110105* 8004230273* 8004020168* 8004300117	70-2623 MISC 50-460 Q 50-528 Q 50-528 Q	STARKEY.R B STARKEY.R B STARKEY.R D STARKEY.R B STARKEY.R B	8004250261* 8004030171 8004040305 8004100340 8004100345*	50-261 G 50-261 S 50-261 R 50-261 S 50-261 S
SMITH.G H SMITH.G H SMITH.G H SMITH.H	8004210334 8004210343 8004220379 8004280280 8004080284	50-333	SPENCER. 0 S SPENCER. 0 S SPENCER. 0 S SPENCER. 0 S SPENCER. 0 S	8004040146* 8004020054* 8004240508* 8004230253* 8004300293	50-312 0 50-361 0 50-528 0 50-460 0 50-397 0	STARKEY,R B STARKEY,R B STARKEY,R B STARKEY,R B STARKEY,R B	5004150374 8004180418 8004180425* 8004230520 8004230525*	50-261 8 50-261 8 50-261 8 50-261 5 50-261 5
SMITH.A E SMITH.R L SMITH.G F SMITH.J SMITH.I W	8004070075 8004080261 8004300322* 8004040235 8004080022	50-320 R 50-271 Q 50-225 Q 50-320 T 50-289 G	SPENCER.G S SPENCER.G S SPENCER.G S SPENCER.G S SPENCER.G S	8004280016 8004280168 8004210181 8004210412 8004020045	50-275 Q 50-312 Q 50-361 Q 50-361 O 50-361 O	STARKEY,R B STARKEY,R D STAUDT,H R STEARNS,C B STEDER,P	8004240362 8004240366* 7908140247* 7911140251 8004070421*	50-241 S 50-241 S COMMISSION Dacket 30 50-10 H
SMITH.A C SMITH.G SMITH.M SMITH.I W	8004100477 8004020132 8004070027 8004040228 8004100476	50-320 P 27-39 50-213 B 50-556 H 50-289 G	SPENCER, G S SPENCER, G S SPENCER, G S SPENCER, G S SPENCER, G S	8004020152 8004040126 8004280683 8004280092 8004210422	50-528 0 50-312 0 50-460 0 50-361 0 50-312 0	STEELE.P W STEINDLER.M J STELLO.V STELLO.V STELLO.V	8004210176* 8004150122 8004020118* 8004140022 8004010017*	70~1113 ACRS 50~3 G 50~155 H 10CFR
SMITH, I W SMITH, O H SMITH, I W SMITH, O H	8004080676 8004100214 8004210126 8004080026 8004080258	50~269 0 50-201 0 70~1100 50-289 0 50-333 0	SPENCER.W C SPENCER.W C SPENCER.O S SPENCER.O S SPENCER.W C	8004010384 8004030126 8004230239 8004240493 8004140219	50-280 P 50-280 P 50-460 Q 50-528 Q 50-281 P	STELLO, V STELLO, V STELLO, V STELLO, V	8004070425 8004170169 8004170129* 8004240485 8004240490*	50-213 Q 50-312 Q 50-312 G 50-272 Q 50-272 G
SMITH.D SMITH.A E SMITH.R L SMITH.I W SMITH.A E	8004300063* 8004010444 8004010237 8004080630 8004010490	50-387 8 50-320 R 50-271 P 50-287 G 50-320 R	SPERROFF, R SPERROFF, R SPESSARD, R SPESSARD, R SPESSARD, R SPESSARD, R	B0040B0561* B004220700* B004100432* B0040B0625* B0041B0203*	50-249 S 50-249 S 50-10 Q 50-254 Q 50-373 Q	STELLO, V STELLO, V STELLO, V STELLO, V STELLO, V	8004240495* 8004240510 8004240512 8004240514* 8004240517*	50-272
SMITH, Q H SMITH, Q H SMITH, A E SMITH, I W SMITH, A M	8004210056 8004300223 8004070222 8004070403 8004280028	50-286 Q 50-244 Q 50-320 R 50-287 G NUREQ	SPESSARD, R L SPESSARD, R L SPETH, O SPIEGEL, G SPIEGEL, G	8004080573 8004030110 8004030335 8004070185 8004100433	50-265 S 50-247 S COMMISSION 50-445 M 50-445 M	STELLO, V STELLO, V STELLO, V STELLO, V STELLO, V	8004240532 8004240537* 8004250336 8004250339* 8004280019	50-219 0 50-219 0 50-29 0 50-29 0 50-206 0
SMITH, I W SMITH, O H SMITH, I W SMITH, I W	8004100222 8004210015 8004080376 8004080579 8004080586	50-287	SPIEGEL, O SPIEGEL, O SPIEGEL, O SPIEGEL, O	8004100433 8004090185 8004030340 8004100428 8004100428	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	STELLO, V STELLO, V STELLO, V STELLO, V STELLO, V	8004280021 * 8004290002 8004290006* 8004290460 8004290466*	50-206 G 50-286 G 50-286 G 50-321 G 50-321 G
SMITH, I W SMITH, I W SMITH, I W SMITH, I W SMITH, E R	8004100018 8004100021 8004100024 8004100304 8004170052*	50-287	SPIEGEL.O SPIEGEL.G SPIEGEL.O SPITALNY.B S SPRAUL.J	8004150032 8004150050* 8004150050* 8004160179* 7704130116	50-445 M 50-445 M 50-445 M 50-269 G NISC	STELLO, V STELLO, V STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B	8004290477# 8004280134 8004140330 8004140423	50-321 G GA999 50-10 R 50-237 S
SMITH, R L. SMITH, I W SMITH, I W SMITH, I W SMITH, I W	8004080490 8004210114 8004150176 8004240176 8004210094	50-271 P 50-287 G 50-287 G 50-287 G 50-287 G	SQUITIERI,R J STAENBURG,M R STAENBERG,M R STAHL,D M STAHL,D M	8004 8004 8004 8004				
SMITH, O H SMITH, I W SMITH, A E SMITH, R L SMITH, R L	8004300317 8004230115 8004220415 8004220301 8004280506	50-225 Q 50-287 Q 50-320 R 50-271 R 50-271 P	STAHL, DM STAHL, DK STAHL, D STAHL, D STAHLE, CR	8004 8004 8004 8004 8004				
SMOKOWSKI,R T SMAPP,C SMIEZEK,J SMIEZEK,J SMIEZEK,J	8004180094 8004030015 8004210433 8004210440 8004210441	50-201 P 50-275 G 50-304 S 50-247 S 50-335 B	STAHL, DM STAHL, DM STALLINGS, CM STALLINGS, CM STALLINGS, CM	8004 8004 8004 8004 8004				
SNIEZEK, J SNIEZEK, J SNIEZEK, J SNOWE, O J	6004210224 6004180517 6004180518 8004150380 6004140304*	50-344 8 50-346 8 50-257 8 50-244 R 50-307 U	STALLINOS, C M STALLINOS, C M STALLINOS, C M STALLINOS, C M STALLINOS, C M	8004 8004 8004 8004 8004				
SNYDER, I E SNYDER, M G SODEN, R SOHINKI, S M SOHINKI, S M	8004040257# 8004090357 8004020357# 8004080319 8004080336	50-320 H 50-320 H 50-254 B 50-466 G 50-466 G	STALLINGS, C H STALLINGS, C H STALLINGS, C H STALLINGS, C H STALLINGS, C H	8004 8004 8004 8004				
SOHINKI,S M SOHINKI,S M SOHINKI,S M SOHINKI,S M	8004070021 8004080016 8004150181 8004170307 8004100378	50-437 G 50-466 Q 50-466 G 50-466 G RES	STALLINGS.C M STALLINGS.C M STALLINGS.C M STALLINGS.C M STALLINGS.C M	B004 B004 5004 B004 B004				

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHGR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STEVENSON, R L	8004140075	70-1113	SWARTZ.L L	8004080056	50-289 G	TERRY, J H THADANI, A C THIES, A C THIES, A C THOM, T	8004220559	50-410 S
STEVENSON, R L	8004170311	70-371	SWARTZ.L L	8004280356	50-289 G		7903080166	MISC
STEVENSON, R L	8004100593	70-1113	SWARTZ.L L	8004280358	50-289 G		8004020334	50-269 1
STEVENSON, R L	8004150305*	70-920	SWEET.K J	8004180349*	50-220 F		8004240296	50-269 Q
STEWART, W L	7909280009	50-281 Q	SWETLAND.P D	8004210053*	50-309 Q		8004240415*	90-259 R
STEWART, W P	8004300164*	50-302 G	SYLVIA, B R	8004030234	50-280 P	THOMAS, C W	8004110045	NUREO
STEWART, W L	8004030270*	50-280 S	SYLVIA, B R	8004030183	50-339 A	THOMAS, K C	8004290371*	50-537 A
STOBER, Q J	8004020139	NUREO	SYLVIA, B R	8004070261	50-339 A	THOMAS, L H	8004100173*	50-220 G
STOHR, J P	7908010063	MISC	SYLVIA, B R	8004080312	50-339 A	THOMAS, M	8004230046*	50-370 G
STOHR, J P	8004210070*	50-286 G	SYLVIA, B R	8004080372	50-338 Q	THOMAS, R D	8004040055*	90-312 G
P.AHOTE P.AHOTE P.AHOTE P.AHOTE P.AHOTE P.AHOTE P.AHOTE	8004040351* 8004080027* 8004080034* 8004040130 8004290128*	50-250	SYLVIA: B R SYLVIA: B R SYLVIA: B R SYLVIA: B R SYLVIA: B R	8004080528 8004080621 8004170050 8004040302 8004110478	50-338 S 50-338 P 50-338 R 50-337 A 50-280 G	THOMAS, M THOMAS, R D THOMAS, R D THOMAS, C D THOMAS, C D	8004210121* 8004100017 8004080584 8004100237 8004210405	50-566 Q I&E I&E TOPREP 50-466 A
P. STORES P. SHOTE P. SHOTE P. SHOTE P. SHOTE P. SHOTE P. SHOTE	80040403B3*	50-269 Q	SYLVIA, BR	6004110202	50-338 Q	THOMAS, C O	8004300074	50-466 A
	8004040182	50-338 Q	SYLVIA, BR	8004140167	50-339 B	THOMAS, C O	8004240557	50-466 A
	8004090294	70-1201	SYLVIA, BR	8004140444	50-338 Q	THOMAS, E B	8004220464	50-220 P
	8004090130	50-339 Q	SYLVIA, BR	6004150342	50-339 B	THOMPSON, D	8004220472*	FO1A
	8004080135	27-47	SYLVIA, BR	8004170210	50-338 R	THOMPSON, D	8004140202	1&E
PERMOTE STONR.J PERMOTE STONR.J PERMOTE STONR.J PERMOTE STONR.J PERMOTE	8004140473*	50-261 Q	SYLVIA,R B	8004170241	50-280 R	THOMPSON D	8004220252*	FOIA
	8004080145	27-47	SYLVIA,R B	8004180232	50-338 J	THOMPSON D	8004100510	PT9
	8004090173	50-338 Q	SYLVIA,D R	8004180446	50-339 B	THOMPSON D	8004220361*	FOIA
	80041100184	70-1151	SYLVIA,B R	8004280472	50-339 B	THOMPSON D	8004220439*	FOIA
	8004250275*	50-261 Q	SYLVIA,B R	8004180289	50-280 Q	THOMPSON D	8004220226	50-272 B
9 C.SHOT8	8004280247	70-1319	SYLVIA, B R	8004210177	50-339 A	THOMPSON, D	8004220249	50-243 S
9 C.SHOT8	8004080021	50-348 0	SYLVIA, B R	8004220311	50-280 F	THOMPSON, D	8004210429	50-331 B
9 C.SHOT8	8004040328	50-250 0	SYLVIA, B R	8004220318	50-280 P	THOMPSON, G	8004280146*	0A999
9 C.SHOT8	8004080010	50-250 G	SYLVIA, B R	8004220493	50-338 Q	THOMPSON, G	8004140466	ACRB
9 C.SHOT8	8004140462	50-261 G	SYLVIA, B L	8004230337	50-337 P	THOMPSON, O	8004150230	ACRB
STOHR. J P STOHR. J P STOKELY. M F STOLZ. J F STOLZ. J F	8004250251 8004270114 7908300422 8004020245 8004150225	50-261	SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R	9004230231 9004230519 9004250371 9004290334 8004300472	50-339 P 50-338 P 50-280 S 50-280 Q 50-280 P	THOMPSON, F THOMPSON, B THOMPSON, O THOMPSON, O THONUS, L H	8004300070* 8004180197* 8004150047 8004240502 8004100391*	50-387 0 COMMISSION 50-367 A 50-367 A 50-334 0
STOLZ.J F	6004070237	50-522 A	SYNAR,M	8004270175	50-554 H	THONUB.L. H THONUB.L. H THORNBURG.H D THORNBURG.H D THORPE.J R.	8004080282*	50-333 Q
STOLZ.J F	8004090260	50-556 H	SZWAJKOHSKI,R	8004280305	70-1308		8004210173*	50-293 Q
STOLZ.J F	8004230193	50-341 A	SZWAJKOHSKI,R	8004280305	70-1308		8004030321*	FOIA
STOLZ.J F	8004240520	50-275 A	T'NIEMI,W D	8004020412*	50-304 B		8004220253*	FOIA
STOLZ.J F	8004250048	50-364 A	TABBERT,J L	8004110470*	50-346 B		8004150621	50-287 Q
STOL7.J F BTONEBURNER,U RTONE,R BTONE,R BTONE,R BTONE,R BTONE,R BTONE,R BTONE,B	8004270145 8004210075 8004220017 8004110523 8004110384*	50-341 A 70-2478 50-289 H PR 50-346 S	TACY.W TAKAMASHI.H TAM.P TAM.P TAMBLING.T N	8004300556 8004280032 8004030260 8004040283 8004100022*	PT21 RES 50-320 0 ACRB 50-346 0	THURMAN, D S THURMAN, D S THURMAN, D S TIBDETTS, D L TIBBITTS, D L	8004240110* 8004240104* 800424095* 8004090284 8004140069	70-135 70-135 70-135 50-395 A 50-352 A
STOTZ.J C STOUDT, T STRASMA.J STRASMA.J STRASSER,J A	8004210267* 8004070030 8004220216* 8004220435* 8004170117*	50-346 S 50-352 H FOIA FOIA COMMISSION	TAPIA, J I TAUBER, H TAYLOR, O H TAYLOR, G C TAYLOR, G C	8004160050* 8004040278 8004080192* 8004220629* 8004220609*	50-445 Q 50-341 A FOIA FOIA	TIBBITS, D TIBETTS, L TIDRICK, O A TIERNAN, M W TILLMAN, A	8004070054 8004070116 8004010437 8004020059* 8004290177*	50-395 A 50-356 H 50-275 A 71-4387 50-259 Q
STRASMA.R J	8004280654	50-295 8	TAYLOR, G C	8004220212*	F01A	TIMKO, D R TIPTON, T E TOALSTON, A TOALSTON, A TOBIN, H J	8004290355*	50-334 R
STRATMAN.R A	8004010417*	50-336 8	TAYLOR, G C	8004220602*	F01A		8004160274	50-219 P
STRATMAN.R A	8004220679*	50-336 8	TAYLOR, M A	8004100521*	50-320 G		8004110121	50-482 H
STRAUSS.P L	8004220263*	FDIA	TAYLOR, J H	8004080661*	ACRS		8004150197	50-416 H
STREETER J F	8004300022*	50-358 0	TAYLOR, D J	8004040188	40-2061		8004040047*	70-143
Stringfield, H	6004070021	71-185	TAYLOR,M A TAYLOR,J H TAYLOR,J H TAYLOR,J H TAYLOR,J H	8004240518*	50-286 P	E W.NIBOT	B004030362*	70-2478
Strong, T R	6004240139	State Frog		8004010404*	50-327 8	L W.NIBOT	B004070361*	70-143
Strong, T R	6004290507	WASTE MOT		8004020459	50-327 8	L W.NIBOT	B004110546*	70-2479
Strosnider, J	6004150042	NUREG		8004020469*	TOPREP	L W.NIBOT	B004110566*	50-302 Q
Strumwabber, M	6004230317*	PROJ		8004030354	71-9142	L W.NIBOT	B004220204*	50-269 Q
STUKENBROEKER, G	8004080069	XPORTLIC	H L.ROLYAT	8004240511*	50-313 P	TODD.O A TOLDERT.P E TOLER.L G TOLLISON.A C TOLLISON.A C	8004040021*	70-1201
BTUKENBROEKER, G	8004140010	XPORTLIC	H L.ROLYAT	8004150209	50-438 8		8004140112	PR
SULLIVAN, W H	8004020142	RES	H L.ROLYAT	8004300570	50-438 8		8004010104	27-39
SUMMERS, R	8004070285*	70-135	TAYLOR.J H	8004070461	TOPREP		8004270122*	50-324 G
EUMMERS, R J	8004070211*	50-184 Q	TAYLOR.J H	8004100199	TOPREP		8004020297	50-324 S
SUMMERG, R SUN, B SUNDARAM, R K SUTHERLAND, J T SUTHERLAND, R	6004070119* 8004220083 8004040027 8004040144* 8004220362*	70-398 40-1162 RES 70-27 70-2623	TAYLOR, J H TAYLOR, J H TAYLOR, J H TEDESCO.R L TEDFORD, C F	8004210244 8004210368 8004290517 8004290127 8004180078*	TOPREP TOPREP 50-313 P 50-320 P COMMISSION	TOLLISON, A C	8004030174 8004010385 8004010370* 8004010374 8004010400*	50-324 B 50-325 B 50-325 B 50-324 B 50-324 B
SUTTON, J W	8004110057*	QA999	TEETS, T A TELFORD, F T TELFORD, C F TELFORD, J T TELFORD, J T	8004040274	50-320 H	TOLLISON, A C	8004010461	50-324 R
SYESLOSKY, F	8004150195*	50-361 H		8004110369	50-295 P	TOLLISON, A C.	8004080458	50-324 S
SWAN, W B	8004090400*	50-518 Q		8004280459*	COMMISSION	TOLLISON, A C.	8004080464*	50-324 S
SWANBY, O T	8004220099	40-3453		8004240483*	50-286 P	TOLLISON, A C.	8004080566	50-325 S
SWANSON, D T	8004010311	50-338 Q		8004240489*	50-286 P	TOLLISON, A C.	8004080575*	50-325 S
BWANSON, D T GWANSON, D T GWANSON, D T GWANSON, D T GWANSON, D T	8004080051* 8004100587 8004170245 8004220271 8004280247	50-287 G 50-287 G 50-522 G 50-287 G 50-287 G	TELFORD, J T TERG, N K	8004030309 8004080377 8004240486* 8004020259 8004070112*	50-284 P 50-295 P 50-284 P 50-247 P 70-1100	TOLLISON, A C	8004080357 8004070332 8004080453 8004080454* 8004070333	50-324 8 50-324 8 50-325 8 50-325 8 50-324 8
SWART,F E BWART,F E SWARTZ,L L SWARTZ,L L SWARTZ,L L	8004240469 8004210354 8004026018 8004010315 8004010514	50-267	TERC,N M TERPSTRA,O L TERRELL,D TERRELL,O D TERREY,S H	8004300328* 8004010440* 8004100441 8004030008 8004010227		TOLLISON, A C. TOLLISON, A C TOLLISON, A C TOLLISON, A C TOLLISON, A C	8004070337* 8004140445 8004150466 8004150504 8004150444	50-324 8 50-324 R 50-324 8 50-324 8

AUTHOR	ACCESS) ON NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TOLLISON A C	8004150448* 8004210273 8004220572 8004220583* 8004220597	50-324 S 50-324 Q 50-324 S 50-324 S 50-325 S	TRIPP.L E TRIPP.L E TROFE.T W TROSKOSKI.W N TROUP.G L	8004090401* 8004180512* 8004140455 8004210151* 8004110027*	50-293 G 50-309 G NUREO 50-322 G 70-1151	UDY, A, C, UDY, A, C UHRIG, R E UHRIG, R E UHRIG, R E	8004170289 8004170334 8004040003 8004040347* 8004080023*	RES RES 50-250 G 50-250 G 50-250 G
TOLLISON, A C	8004220676 8004220732 8004220538 8004220547* 8004280576	50-325	TRONBRIDGE, O F TROWBRIDGE, O F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F	8004070076 8004070076 8004010517 8004080425 8004080720	50-289 0 50-289 0 50-400 0 50-289 0 50-289 0	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8004040173# 8004080015# 8004020381 8004080257 8004240378#	50-389 Q 50-250 Q 50-335 R 50-335 R 50-250 Q
TOLLISON, A C	8004280586* 8004280587 8004280589 8004280583 8004280592*	50-325	YROWBRIDGE, O F TROWBRIDGE, O F TROWBRIDGE, O F TROWBRIDGE, G F TROWBRIDGE, G F	8004110029 8004010319 8004080425 8004080720 8004110029	50-287 0 50-400 0 50-289 0 50-289 0 50-289 0	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8004220237 8004220248 8004220313 8004210170 8004230537	50-389 A 50-389 K 50-389 C 50-389 S 50-335 Q
TOLLISON, A C	8004270397 8004290401* 8004290487 8004290494* 8004100378	50-325 S 50-325 S 50-325 S 50-325 S RES	TROWERIDGE, G F	8004100308 8004100308 8004100479 8004100479 8004110516	50-287 0 50-287 0 50-287 0 50-289 0 50-287 Q	UHRIG,R E UHRIG,R E UHRIG,R E UHRIG,R E UHRIG,R E	8004240030 8004010210 8004030289 8004040425 8004110533*	50-250 G 50-250 P 50-250 P 50-335 R 50-250 9
TOMKINS.D TOMLINSON.D P TONDI.D TONGUE,T M	8004070050 8004180218* 7908200112 7908280824 8004100432*	FOIA 50-498	TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F	8004110516 8004230030 8004230030 8004140007* 8004140013*	50-289 Q 50-289 Q 50-289 Q 50-289 Q	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8004240219 8004030229 8004040380 8004070279 8004090217	50-389 Q 50-389 F 50-250 R 50-335 F 50-335 R
TOOKER.D W TOOKER.D W TOOKER.D W TOOKER.D W	8004040413# 8004080531# 8004140369# 8004140452# 8004010338	50-331 S 50-331 S 50-331 S 50-331 S 50-289 S	TROWDRIDGE, G F	8004140017* 8004140019* 8004140023* 8004140028* 8004140032*	50-289 Q 50-289 Q 50-289 Q 50-289 Q	UHRIG,R E UHRIG,R E UHRIG,R E UHRIG,R E UHRIG,R E	8004220243* 8004080384 8004130341 8004080452 8004150404	A 78E-08 P 78E-08 P 78E-08 P 78S-08
TOTH, A D TOURIONY, E 0 TOURTELLOTTE, J TOURTELLOTTE, J TOWNEND, F	8004230270* 8004280263 8004020104 8004020107* 8004140100*	50-440 G NUREG 50-289 G 50-289 G PR	TROWBRIDGE. G F	8004140038* B004140045* B004140057* B004140062*	50-289 Q 50-289 Q 50-289 Q 50-289 Q	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8004300583 8004140227 8004300577 8004150519 8004230461	50-250 G 50-335 F 50-335 G 50-250 F 50-335 P
TOWNEND, F TOWNEND, F TRAGESER, C IN TRAMMELL, C TRAUGER, T C	8004070300 8004140094 8004270109 8004100307 8004100556	PR PR CONTRACT 50-344 P PROJ	TROWBRIDGE, G F	8004140045* 8004170273 8004170281* 8004140007* 8004140013*	50-287	UHRIG,R E ULLRICH,W T ULLRICH,W T ULLRICH,W T UPRIGHT,C M	8004280269 8004220432 8004290439 8004290443 8004040289*	50-250 P 50-278 8 50-277 8 50-277 8 50-280 0
TRAVIS.W H TRAVIS.C C TREGY.S A TREBY,S A TREVING.T	8004070247 8004160088 8004210414 8004150226 8004030037*	71-9853 RES 50-498 G 50-320 G CONTRACT	TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F	8004140017* 8004140017* 8004140023* 8004140028* 8004140032*	50-289 0 50-289 0 50-289 0 50-289 0	UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M	8004020243* 8004090049* 8004040452* 8004100202* 8004100182*	50-259 Q 50-321 Q 50-302 Q 50-250 Q 50-335 Q
TREVINO, T TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C	8004040184* 8004110508 8004250044 8004040276 8004090148*	CONTRACT 50-313 P 50-313 Q 71-9080 50-313 Q	TROWDRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F	B004140038* 8004140045* 8004140051* 8004140057* B004140062*	50-289	UPRIGHTIC M UPRIGHTIC M UPRIGHTIC M UBTICKIN UBTICKIN R	8004240413# 8004210113# 8004280143* 8004080440* 8004040132*	50-280 G 50-302 G 50-348 G 50-263 G 50-346 G
TRIMBLE, D C	8004250103 8004070118* 8004010301 8004250303 8004010216	50-368 Q 50-368 Q 50-313 P 71-9044 50-313 R	TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROY, M	8004140069* 8004170281* 8004210421 8004210421 8004210421	50-289	UTLEY, E E UTLEY, E E UTLEY, E, E UTLEY, E, E UTLEY, E, E	8004010324 8004040273 8004080648 8004070313 8004080383	50-261 P 50-261 P 50-261 P 50-261 F 50-324 P
TRIMBLE, D C	8004010386 8004020342 8004020349 8004030209 8004070287	50-313 F 50-348 B 50-313 B 50-313 P 50-313 P	TRULL,D TRUSSELL,H H TRZYNA,G TSCHAECHE,A N TBUJI,N	8004080213* 8004080178 8004020376* 8004180525* 8004240202*	70-2254 40-8064 50-295 8 70-1007 70-2805	OTLEY, E E OTLEY, E E OTLEY, E E OTLEY, E E	8004080472 8004140413 8004160282 8004170015 8004250410	50-324 F 50-261 P 50-324 P 50-324 P 50-324 P
TRIMBLE, D C	8004150304 8004170086 8004080577 8004070344 8004140328	50-313 P 50-313 P 50-348 8 50-313 P 50-313 8	TUNSTALL, J E TUNSTALL, J E TUNSTALL, J E TURK, S E TURK, S E.	8004080241# 8004100574# 8004210119# 8004210424 8004150464	CONTRACT CONTRACT CONTRACT 50-445 0 50-341 0	UTLEY, E E UTLEY, E E VACCA, P C	8004280497 8004300323 8004300443 8004300445 8004220479*	50-324 P 50-324 P 50-261 P 50-324 H FOIA
TRIMBLE, D C	8004150A30 800414035A 8004150541 8004150567 8004150235	50-313 \$ 50-313 \$ 50-313 \$ 50-368 F 50-313 1	TURK, B E TURK, B E TURK, B E TURK, B E TURNER, L J	8004150484 8004300366 8004300371* 8004300378* 8004290458*	50-341 Q 70-2909 70-2909 70-2909 50-390 A	VACCA, P. C VACCA, P. C VACCA, P. C VADENBURGH, D. VAHRENWALD, J	8004220476* 8004220473* 7911200274 8004210110 8004020427*	FOIA FOIA Docket 30 PR 50-254 8
TRIMBLE, D C	8004150605 8004160185 8004210148 8004210217 8004210274	50-348 8 50-313 P 50-313 P 50-313 R 50-368 R	TURNER, E A TURNER, E A TURNER, E A TURNER, E, A TURNER, E A	8004070062 8004070060* 8004300523* 8004010126 8004140107	50-498 Q 50-498 Q 50-498 Q 50-498 Q 50-498 Q	VAHRENWALD, J VALENTE, J V VALLERIO, J VALORE, C J VALORE, C J	8004020443* 8004140439 8004080202* 8004100466 8004100466	50-265 B 50-322 A FOIA 50-311 Q 50-311 Q
TRIMBLE, D C	B004220421 B004220427 B004220471 B004230471 B004290450	50-348 8 50-313 F 50-313 P 50-313 S 50-348 R	TURNER, E A	8004010332 8004180384 8004180423 8004180421 8004290398	50-478 8 50-478 8 50-478 8 50-478 8 50-478 8	VALORE, C J VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8004210291 8004020162* 8004070255* 8004010350 8004110484	50-272 0 50-528 9 50-528 8 50-528 8 PR
TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIPLETT, M P TRIPLETT, M P	8004290374 8004290244 8004290361 8004100520* 8004140088*	50-313 8 50-313 P 50-313 R ORG DRG	TURNER, E A TUTHILL, E UDALL, M K UDY, A C UDY, A C	8004220763 8004070122 8004080066* 8004080641 8004140138	50-498 K 50-322 H COMMISBION 50-270 P RES	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E,	8004300532 8004240501* 8004010244 8004150566 8004170045	PR 50-528 G 50-528 K 50-528 F 50-528 8

POHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VAN NESS,S C VAN RODYEN,D VAN RODYEN,D VAN SICKEL,J VAN SICKEL,J	8004090008 8004040459 8004080074 8004220369 8004220348 *	50-272	WALKER, J R WALKER, J R WALKER, J R WALKER, F M WALKER, J R	8004170229# 8004170231* 8004170234# 8004180394* 8004150615*	50-327 F 50-327 F 50-327 F 50-327 R 50-327 P	WEISS.D WEISS.E R WEISS.E R WEISS.D	8004210083* 8004100100 8004080375 8004080418 8004240288*	70-135 50-3 F 50-287 0 50-338 0 70-1308
VANDENBURGH, D E VANDENBURGH, D VANDEL, T E VANDENBURGH, D VANDEL, T E	8004230118* 8004160102* 8004210142* 8004160096 8004180267*	COMMISSION PR 50~358 Q PR 50~329 Q	WALLACE, A T WALLENSTROM, R WALLETT, S A WALTERS, E WALTON, O	8004220519 8004030003* 8004250014 8004070350 8004150143*	50~331 P 40-8745 CONTRACT 50-320 H 50-352 Q	WEISS.J D WEISS.J M WEISS.E R WEISS.E R WEISS.E R	8004210042* 8004080031 8004020099* 8004020091 8004020099*	71-6717 TOPREP 50-3 Q 50-3 Q 50-3 Q
VANDENBURGH, D E VANDENBURGH, D VANDDORN, P K VANDDORN, P K VANDDORN, P K	8004110444* 8004220522 8004070177* 8004040222* 8004110514*	50~29 P 50~309 P 50~438 0 50~416 Q 50~259 0	HALTON G A WALTON O A WAMBACH T V HAMBACH T V HANDKE N E	80040704014 8004300607* 8004080412* 8004170261 8004110087	50-293 Q 50-293 Q 50-255 P 50-244 P 50-304 Q	WEISS.E R WEISS.E R WEISS.E R WEISS.E R WEISS.J D	8004080678 8004080678 8004100562 8004100562 8004020101	50-289 0 50-289 0 50-289 0 50-289 0 70-687
VANHOOMISSEN, J VARANINIE E VARELA. A A VARELA. A A VARELA. A A	8004010181% 8004040008* 8004070111* 8004100168* 8004100112*	50-268 P PR 50-443 Q 50-354 Q 50-352 Q	WANDKE, N WANDKE, N WANDKE, N WANDKE, N WANDKE, N E	6004020311 6004020369 6004140306 6004020407 6004150472	50-295	WEISS,E R WEISS,E R WEISS,J D WEISS,J D	8004100277 8004100277 8004110045 8004080607 8004080612	70-143 70-143 50-3 P 70-1257 70-572
VARELA, A A VARGA, S A VARGA, S A VARGA, S A VARGA, S A	8004100040* 8004210078 8004020117 8004250332 8004020124	50-443 Q MISC 50-289 H 50-289 H 50-443 A	WANDKE, N E WANDKE, N E WANDKE, N E WANDKE, N E	6004150518 6004220586 6004220660 6004220674 6004270486	50-304 S 50-295 E 50-295 E 50-304 E 50-295 B	WEISS,E R WEISS,D WEISSBERG,S WEISS,D WEISS,D	8004080695 8004070380 8004020207 8004170108 8004140009	50-3 F 70-1426 State Prog 70-2072 70-827
VARGA, S A VARGA, S A VARGA, S A VARGA, S A VARGA, S A	8004110557 8004140093 8004140186 8004210028 8004110052	50-339 H 50-339 H 50-339 H 50-339 H 50-443 H	Wandke, n e Wang, p c Wang, a Ward, w J Ward, w J	8004290473 8004240566 8004290137 8004280146* 8004280153*	50-295 B NUREO 50-313 P GA999 GA999	WEISS, D WEISS, D WEISS, D WEISS, D WEISSBERG, S	8004140476 8004150178 8004150182 8004220062 8004240451	70-27 70-820 70-824 70-1739 Stata Prog
VARGA, 5 A VARGA, 5 A VARGA, 5 A VARGA, 6 A VETTER, W E	8004110060 8004110067 8004150131 8004250266 8004020128*	50-443 H 50-443 H 50-443 H 50-29 G ACRS	WARD, C E WARD, J E WARD, D T WARD, W J WARD, J E	8004150278* 8004020123* 8004040272* 8004280149* 8004080149	71-49 ACRS ACRS QA999 PR	WEISS,D J WEISS,J D WEISS,E R WEISS,E R WEISS,E R	8004160107 8004240108 8004150101 8004150101 8004220462	70-143 40-8768 50-574 0 50-574 0 50-247 E
VILLFORTH, J C VOELKER, L E VOLGENAU, E VOLGENAU, E VOLGENAU, E	8004220677 8004100028 8004220132* 8004220409* 8004030166	50-320 P NUREG FOIA FOIA SECY	WARD, JE WARD, KD WARDEN, WG WAREMBOURG, D WAREMBOURG, D	8004100515 8004100207# 8004080065 8004080399 8004080422	PR 50-254	WENDER, L O WENSLAWSKI, F WERLING, J A WERLING, J A	8004170221* 8004040030 8004040415 8004280078* 8004020002	50-317 8 50-70 8 50-70 8 50-334 P 50-334 8
VOLKEMA,R H VOLLEN,R J VOLLEN,R J VOLLEN,R J VOLLEN,R J	8004220397* 8004230091 8004230101* 8004040069 8004020214	FOIA 50-367 0 50-367 0 50-367 G 50-367 G	WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	8004080503 8004150333 8004150338 8004150432 8004150542	50-267 8 50-267 R 50-267 R 50-267 S 50-267 S	A C.ONIJAH WERLING, J A WERLING, J A WERLING, J A	8004220597 8004030198 8004030191 8004070341 8004070346*	50-334 8 50-334 8 50-334 8 50-334 8 50-334 8
VOLLEN,R J VOLLMER,R H VOLLMER,R H VOLLMER,R H VOLLMER,R H	6004020478 8004020227 8004030272 8004030279* 8004030283*	50-347 9 50-320 % 50-320 P 50-320 P 50-320 P	WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	B004190582 B004150626 B004210294 B004210268 B004220779	50-267 S 50-267 S 50-267 S 50-267 R 50-267 I	A C.ONIJER WERLING, J.A WERLING, J.A WERLING, J.A WERLING, J.A	8004070375* 8004110385 8004140329 8004140381 8004150516	50-334 8 50-334 8 50-334 8 50-334 8
VOLLMER.R H VOLLMER.R H VOLLMER.R H VOLLMER.R H VOLLMER.R H	8004070418 8004210252 8004210260 8004210272 8004210287	50-10 H 50-10 H 50-10 H 50-10 H 50-10 H	WAREMOOURG, D WARNICK, R F WARNICK, R F WARRINER, G H WATFORD, M L	8004240323 8004140202 8004110245* 8004040323* 8004150376*	50-267 8 1&E 50-266 0 50-261 R 50-261 R	WERLING, JA WERLING, JA WERLING, JA WERLING, JA WERLING, JA	8004150529* 8004150534* 8004150545* 8004230217 8004170223	50-334 8 50-334 8 50-334 8 50-334 8
VOLLMER:R H VOLLMER:R H VOLLMER:R H VOLLMER:P H VOLLMER:R H	8004210275 8004210277 8004210302 8004210308 8004140071	50-10 H 50-10 H 50-10 H 50-10 H 50-320 H	WATSON, A P WATSON, J F WATSON, J F WATTENBARGER, S WATTES, T E	8004160089 8004300297 8004300297 8004080345 8004150416	RES WASTE MOT WASTE MOT XPORYLIC 50-373 A	A C.ONIJABW A C.ONIJABW A C.ONIJABW A C.ONIJABW A C.ONIJABW	8004230208 8004240385 8004270503 8004270508* 8004270387	50-334 \$ 50-334 \$ 50-334 \$ 50-334 \$ 50-334 \$
	8004100047 8004180442 3004210319 1004210324 32	90-287 H 50-320 H 50-320 H 50-320 H 50-320 H	HATTSON, P WEAVER, J WEAVER, K WEBB, D H WEBB, R E	8004150347* 8004080063* 8004110118 8004150376* 8004210379*	50-206 R COMMISSION WASTE MOT 50-553 R 50-320 H	Werling, J A Werner, B J, Wescott, H West, B West, W e	8004270373* 8004280546* 8004040037 8004280352* 8004140463	50-334 S 50-346 S 50-461 S 50-368 H 50-498 A
		50-320 H 50-320 H 50-320 H 50-320 P 50-320 P	WEBSTER, E H WEEKS, E D WEGNER, W WEIGAND, J O WEIGAND, J G	8004280125* 8004170233 8004030005 8004040335 8004040363	50-280 G 50-133 R NUREO 50-458 A 50-458 A	WESTERN, P WESTERN, F WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F	8004080194* 8004080216* 8004090159* 8004040262* 8004100335*	FOIA FOIA 50-313 G 50-285 Q 50-313 Q
		50-320 P 50-10 H 50-528 G 70-687 50-306 Q	WEIGAND, J G WEIGAND, J G WEIGAND, J G WEIGAND, J G	8004040056 8004040106 8004040370 8004010018 8004010023	50-458 8 50-458 0 50-458 A 50-458 0	WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F WESTERMAN, T. F WESTERMAN, T. F	8004210219* 8004080696* 8004040140* 8004080602* 8004210179*	50-299 Q 50-285 Q 50-267 Q 50-267 Q 50-445 Q
		FOIA FOIA FOIA NUREO 50~460 G	WEIGAND.J G WEIGAND.J G WEIGAND.J G WEIGAND.J G WEIGAND.J G	8004010041 8004040378 8004180102 8004210182 8004280539	50-458 Q 50-458 A 50-458 A 50-458 I 50-458 R	WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F WESTNEOGE, T WESTON, K	8004210438* 8004250277* 8004040025 8004040166 8004300006	50-445 Q 50-313 Q 50-278 B 50-387 H 50-387 Q
		50-320 P 50-312 Q 50-312 Q 50-327 F 50-327 O	WEIGAND, J G WEIGENSBERG, I WEILL, C H WEILL, S M WEISS, E R	8004280543* 8004220616* 8004100851* 8004070071* 7906010118	50-458 R FOIA 40-261 50-483 H 50-334 Q	WETHY, C M WETTERBAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8004030167 8004030338 8004030338 8004150027 8004150030*	50-335 B 50-358 Q 50-358 Q 50-272 Q 50-272 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WETTERHAHN, M J WETTERHAHN, M J WEXLER, D WHITCOMB, D WHITE, T J	8004150030> 8004150456 8004030340* 8004020379 8004220358*	50-272 G 50-311 G COMMISSION 50-320 H 50-259 P	WILLIAMS, C E WILLIAMS, C C WILLIAMS, C C WILLIAMS, C C WILLIAMS, M	8004220225 8004070278# 8004040149# 8004110300# 8004080226	71-9010 50-373 0 50-500 0 50-456 0 WASTE MGT	WOODRUFF, R. L.	8004280288* 8004210034* 8004210076* 8001210662* 8004210339*	50-317 Q 70-1100 50-272 Q 50-277 Q 50-333 Q
WHITE, M P WHITENER, H L WHITESELL, D E WHITESELL, D E WHITESELL, D E	8004160046 8004020263* 8004040361* 8004040122* 8004020434*	ACRS 50-259 Q QA999 QA999 QA999	WILLIAMS,C C WILLIAMS,C E WILLIAMS,J L WILLIAMS,E F WILLIAMS,H P	8004280074+ 8004280166 8004010008 8004250072> 8004090247	50-454	NOODRUFF, R L WOODRUFF, R L WOODRUFF, R L WOODRUFF, R L WOOLEVER, E J	8004210345* 8004220402* 8004040023* 8004100408* 8004280188	50 245 Q 70-1143 50-10 Q 50-10 Q 50-412 Q
WHITESELL.D E WHITESELL.D E WHITESELL.D E WHITE.L D WHITESELL.D E	8004070310* 8004100034* 8004100005* 8004070445 8004110057*	QA999 QA999 QA999 50-244 Q QA999	WILLIAMS,C C WILLIS,C WILLODSEN,A F WILLSEY,W B WILSON,R D	8004300536* 8004140447* 8004090172 8004070270 80040802/2*	50-546 Q 50-324 R PR 50-277 R QA999	WOOLEVER, E J WOOLEVER, E J WOOLEVER, E J WOOLEVER, E J WOOLSEY, R T	8004070336 8004070277 8004220483 8004230429 8004280212	50-412 A 50-334 R 50-412 Q 50-412 5 40-1162
WHITE,W W WHITE,L D WHITE,L D WHITE,L D	8004040067* 8004230003 8004010355 8004110175 8004150434	50-344 T 50-244 Q 50-244 P 50-244 F 50-244 P	WILSON,R WILSON,R WILSON,B D WILSON,R D WILSON,R F	8004100554 8004140002 8004020471* 8004080262* 8004040231	ACRS ACRS XPORTLIC GA999 50-320 P	WRY, J R WRAY, J R WRIGHT, K H WRIGHT, G C WRIGHT, R W	8004080038* 8004250291* 8004300065* 8004080594* 8004160062*	50-250 0 50-261 0 40-4492 50-155 0 50-553 0
MHITE,L D WHITE,L D WHITE,L D WHITE,L D	8004150331# 8004150459 8004180458 8004230371 8004230389	50-244 P 50-244 P 50-244 B 50-244 P 50-244 P	WILSON, R F WILSON, R F WILSON, J H WILSON, B D WILSON, B D	8004040318 8004040321 8004020163* 8004020467 8004030274	50-320 P 50-320 P 50-272 P XPORTLIC XPORTLIC	WRIGHT, K H WRIGHT, R W WRIGHT, A L WU, B J C WU, G	8004300053* 8004080543 8004280028 8004280038 8004070361	40-4492 50-438 S NUREQ RES 40-8647
WHITE, L D WHITE, L D WHITMAN, F M WHITMEY, G G WHITSHURST, C	8004270378 8004300407 8004220341* 8004230479* 8004080165	50-244 P 50-244 Q FOIA 50-293 R 50-367 H	WILSON, B D WILSON, R F WILSON, R F WILSON, R WILSON, R E	8004030280* 8004040325 8004040330 8004140221 8004020012	YPORTLIC 50-320 P 50-320 P 50-247 P 50-320 S	WU.G WU.J WU.K WULLER.G E WULLER.G E	8004070376 8004210201# 8004030043 8004010249 8004010328	40-8727 50-3 H YPORTLEC 50-461 A 50-461 F
WHITT,K W WHITT,K W WHITT,K W WHITTLE,A J WICHERS,D L	8004140102 8004210429 8004220084 8004210357* 8004070235	18E 50-331 S 50-272 B 70-143 40-8502	HILSON, J N HILSON, W R HILSON, W R HILSON, W R HILSON, W R	8004020464 8004100442 8004100444* 8004100447* 8004100442	TOPREP 50-498 M 50-498 M 50-498 M 50-498 M	WULLER, 0 E WULLER, 0 E WURTZ, C B WYDLER, J W WYDLER, J W	8004140107 8004150170 8004210358# 8004070460 8004180317#	50-461 Q 50-461 Q 50-320 P PR COMMISSION
WICHERS, D L WICHERS, D L WICHERS, D L WICHERS, D L WICHERS, D L	8004070244 8004070194 8004080219 8004070070 8004210413	40-9502 40-9502 40-9502 40-8502 40-8502	WILSON, W R WILSON, W R WILSON, R F WILSON, R F WILSON, R F	8004100444# 8004100447# 8004010344 8004040304 8004070219	50-498 M 50-498 M 50-320 P 50-320 Q	WYDLER, J W WYDLER, J W WYDLER, J W WYKOFF, D YAMAGUCHI, T	8004180220* 8004100449 8004140025 8004150467* 8004020484	COMMISSION PR PR 50-254 \$ XPDRTLIC
WIDNER, W A	8004010112 8004150072* 8004070035* 8004150136* 8004110565	50-321 Q 50-321 Q 50-321 Q 50-321 Q 50-321 Q	WILSON, R F WILSON, R F WILSON, R F WILSON, R F WILSON, R F	8004070301 8004070318 8004110298 8004110362 8004110471	50-320 P 50-320 P 50-320 Q 50-320 R 50-320 P	YANDELL, L A YANICHKO, S E YATES, S R YBARRONDO, L J YBARRONDO, L J	8004210219* 8004240397* 8004140215* 8004100029 8004150152	50-278 G 50-204 P 50-10 U MUREG RES
WIDNER, W A	9004150178 9004170278 8004030227 9004150358 8004230467	50-321 Q 50-321 Q 50-321 P 50-321 P 50-321 Q	MILSON, N L WILSON, J W WILSON, J W WILSON, J W	8004070297 8004170234* 8004300600* 8004080474 8004080482*	50-334 I 50-327 F 50-272 Q 50-280 S 50-280 S	YIN, I T YIN, I T YIN, I T YIN, I YOUNG, R	8004040410+ 8004080647* 8004100130* 8004040150* 8004030277	50-263 Q 50-373 Q 50-305 Q 50-346 Q
WIDNER, W A WIDDEF, M P WIDDEF, M P WIDDEF, M P WIDDEF, M P	8004280452 8004080139 8004080146* 8004080150* 8004080167*	50-321 Q 50-289 Q 50-289 Q 50-289 Q 50-289 Q	WILSON, J L WILSON, R F WILSON, R R WILSON, K R WILSON, J N	8004080486* 8004180370 8004140372 8004170208* 8004300049	50-280 S 50-546 A 50-320 G 50-267 S 50-322 A	YOUNO, T YOUNO, D W YOUNO, F W YOUNO, F W YOUNODLOOD, B J	B004070178* B004280389* B004020170 B004020080 B004180196	50-275 G 50-289 H State Prog State Prog 50-352 H
WIDDFF,MP WIDDFF,MP WIDDFF,MP WIDDFF,MP WIDDFF,MP	8004080176* 8004080137 8004080146* 8004080150* 8004080167*	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0	WILSON, J L WILSON, J L WILSON, J L WINDSCHILL, J E WINTER, A J	8004280612 8004280616* 8004280626* 8004150617* 8004300025*	50-280 B 50-280 B 50-280 S 50-263 S 50-387 G	YTHIER, P YTHIER, P YUHAS, G P YUHAS, G P YUNDT, C P	8004100576* G004210119* 6004300244* 6004210102* 6004080442	CONTRACT CONTRACT 50-244 0 50-320 0 50-344 R
Hidoff, M P Higoins, R M Higoins, R M Higoins, E Higointon, D	8004080176* 8004070185 8004300067* 8004080105 8004220012	50-287 G 50-387 H 50-387 G CONTRACT 50-316 P	WIZNER, D G WOFFORD, A W WOGMAN, N A WOLFE, B J WOLFE, B J	8004080529* 8004070117* 8004110065 8004010517 8004090126	50-316 8 50-322 G NUREG 50-445 M 50-445 M	YUNDT,C P YUNDT,C P YURLSICH,B ZAHLER,R E ZAHLER,R E	6004150440 8004290471 8004290068* 8004100090 8004110212	50-344 S 50-344 S 50-320 H PR 50-269 Q
Wigointon, d Wigointon, d Wigoint, e Wigoint, e Wilborn, L	8004070264 8004240087 8004030011 8004080603 8004040104*	50-334 P 50-334 P CONTRACT CONTRACT GA999	WOLFE,S J WOLFE,S J WOLFE,S J WOLFE,S J WOLFE,S J	B004090456 B004100243 B0041500B3 B004230055 B004230094	50-445 M 50-445 M 50-445 M 50-466 Q	ZAHLER.R E ZAHLER.R E ZAHLER.R E ZAHLER.R E ZAHLER.R E	8004110155 8004110162* 8004210235 8004210250* 8004110162*	50-287 0 50-289 0 50-287 0 50-287 G 50-289 G
WILBUR, H A WILCOX, J B WILCOX, L WILKENS, P C WILKINSON, R	8004280149* 8004090374* 8004040001 8004100461 8004010227	0A979 50-280 Q 50-312 H 50-244 P 50-294 P	WOLFF.C E WOLLETT.S A WOLTNER,E WOLTNER,E WONG,T	8004070242 8004230523 800410030* 8004220041* 8004070347	40-8602 CUNTRACT 70-820 70-371 40-279	ZAHLER,R E ZAHLER,R E ZAHLER,R E ZAHLER,R F ZAHLER,R E	8004210250# 8004100435 8004100436# 8004100437# 8004100435	50-287 G 50-287 G 50-287 G 50-287 G 50-287 G
WILLHITE,S WILLIAMS,RA WILLIAMS,RA WILLIAMS,RA WILLIAMS,RA	8004070149 8004240056* 8004240078 8004240073* 8004240046*	50-554 G 70-135 70-135 70-135 70-135	MOOD'E C MOOD'E C MOOD'T C MOOD'T C	8004090421 8004090421 8004110024 8004180489 8004210277	50-498 M 50-498 M 50-498 M 50-309 S 50-309 S	ZAHLER.R E ZAHLER.R E ZAHLER.R E ZAHLER.R L ZAHLER.R C	8004100436* 8004100437* 8004080195 8004080200* 8004090281	50-287 G 50-287 G 50-287 G 50-287 G 50-289 Q
HILLIAMS,RA HILLIAMS,RA HILLIAMSON,PW HILLIAMS,CC HILLIAMS,CCC	8004240155* 8004240038* 7907250345 8004040040* 8004110176*	70-135 70-135 50-443 H 50-373 Q 50-440 Q	WOODFIN.R L WOODHALL,C B WOODHEAD.C P WOODHAD.C P WOODHAN.D P	8004100028 8004030299 8004100564 8004300403 8004170323*	NUREQ PR 50-407 0 50-466 0 50-317 F	ZAHLER,R C ZAHLER,R E ZAHLER,R E ZAHLER,R C ZAHLER,R E	8004090289 8004090295* 8004100279 8004100285* 80040802004	50-289 G 50-289 G 50-289 G 50-287 G 50-289 G

r⊙n1ua	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJEC	RY	AUTHOR	ACCESSION NUMBER	SUBJECT
ZAHLER, R F	6004090283*	50-287	G.	Z 10ULSKY, H	8004090285+	70-135		ZIEMANN D L	6004090147	50-245 P
ZAHLER, R E	60040702754	50-289	G	Z (BULSKY, H	80041000924	70-364		ZIEMANN, D L	8004100286	30-155 F
ZAHLER, R E	60041002854	50-289	G	ZIBULSKY, H	6004220041*	70 371		ZIEMANN, D L		
ZAHLER, R E	6004110077	50-289	Ğ	ZIEGLER	60040103/9*	50 327	Q		0004220780	50-244 P
ZAHLER, R E	8004110085	50-289	Ğ	ZIEGLER	6004170155+	50-327	Q.	ZIEMANN, D L	8004080444	50-245 F
PRICERIA E	0007110000	00 201	•	I ILVLL	0004170133-	30-327	· ·	ZIEMANN, D L	8004090142	50-206 P
ZAHLER, R E	8004110100	50-289	G	ZIEMANN.D L	8004030365	50-213	P	ZIEMANN, D. L.	8004110022	50-255 F
ZAHLER, R E	8004110085	50-289	G	ZIEMANN, D L	8004093242	50-204	P	ZIEMANN, D. L.	B004110145	50-29 F
ZAHLER, R F	8004110100	50 - 289	G	ZIEMANN. D L	8004100302	50-10	P	ZIEMANN, D L	8004110148	50-206 F
ZAHLER, R E	G004100010	50-287	G	ZIEHANN, D L	8004100309	50-213	P	ZIEMANN, D L	B0041B0094	50-244 P
ZAKLER, R E	BC04100015*	50-289	G.	ZIEMANN. D L	8004100311	50-245	P	ZIEMANN, D L	8004230216	50-220 F
							,			00 Ka0 1
ZAHLER, R E	8004100464	50-289	G	ZIEHANN, D. L.	8004100312	50-155	P	ZIEMANN, D L	B004230226	50-237 P
ZAHLER, R E	8004100010	50-289	G	ZIEMANN, D L	8004100314	50-409	P	ZIEMANN, D L	8004230234	50-219 P
ZAHLER, R F	80041000154	50-269	G	ZIEMANN, D L	6004100316	50~244	P	ZIEMANN, D L	8004240497	50-245 P
ZAHLER,R E	8004230001	50-269	G	ZIEMANN, D L	E004100317	50-219	P	ZIEMANN, D L	8004170279	50-10 P
ZAHLER,R E	8004230097	50-287	G	ZIEMANN, D L	B004100511	50-29	P	ZIEMANN, D L	8004210125	50-155 P
ZAHLER, R F	8004230127	50-289	G	ZIEMANN. D L	E004150135	50-255	Ъ	ZIEMANN, D L	6004210127*	50-155 P
ZAHLER, R E	8004230131	50-287	G	ZIEMANN.D L	8004080155	50~409	t _b	ZIEMANN, D L	8004210132#	50-155 P
ZAHLER, R E	8004230001	50-289	G	ZIEMANN.D L	8004080159	50-29	۶	ZIEMANN, D L	8004170285	50~217 ₽
ZAHLER, R E	G004140007#	50-269	G	ZIEHANN, D L	8004080162	50~219	P	ZIEMANN, D L	8004170290	50-409 P
ZAHLER,R E	8004140013*	50-289	G	ZIEMANN.D L	8004080699	50-206	P	ZIEMANN, D L	8004170297	50-206 P
**** 55 6 5	DDD44 100 174	50-289	_	*********						
ZAHLER R E	8004140017# 8004140023*		0	ZIEMANN. D L	8004090335	50-10	P	ZIEMANN, D L	8004170303	50-245 P
ZAHLER, R E	8004140023*	50~287	G	ZIEMANN, D L	6004070338	50-213	P	ZIEMANN, D L	800417030B	50-27 P
ZAHLER,R E ZAHLER,R E	8004140038*	50-269	G	ZIEMANN, D L	E004090344	50-155	P	ZIEMANN, D L	8004210190	50-155 P
		50÷289	G G	ZIEMANN, D.L.	B004100559	50-244	P	ZIEMANN, D L	8004210227	50-213 P
ZAHLER, R E	6004140051*	50-287	G	ZIEMANN, D L	8004100548	50~245	P	ZIEMANN, D L	8004230178	50-10 P
ZAHLER, R. E.	B004140007+	50-289	G	Z TEMANN, D. L.	8004020001	50-155	P	ZIEMANN, D L	8004240003	50-244 P
ZAHLER, R E	8004140013*	50-289	Ğ	ZIEMANN, D L	8004020003	50-409	P	ZIEMANN, D L	8004250123	50-27 P
ZAHLER, R E	8004140017*	50-269	o .	ZIEMANN, D L	8004020004	50-27	P	ZIMMERMAN, R P	8004180147*	50-245 0
ZAHLER, R E	8004140023*	50-289	G	ZIEMANN, D L	8004020007	50-213	P	ZIRWAS, K. R	8004020310*	50-249 8
ZAHLER, R E	8004140038*	50-207	Ģ	ZIEMANN, D L	8004020009	50-219	P	ZITTEL, H E	6004150029	REB
F777 CM 111 C		40.	•		550-1520007	30 217		ZIVIELJI E	0004130027	KEO
ZAHLER, R E	8004140045*	50-289	G .	ZIEMANN, D L	8004020010	50-10	P	ZUBER, N	8004100485	REVIEW CRP
ZAMLER, R E	6004140051*	50-289	G	ZIEMANN, D L	8004020013	50-204	į.	ZUDANS, Z	8004080646*	ACRB
ZARAKAS, P	8004030165	50-3	G	ZIEMANN, D L	8004020014	50-244	P	ZUDANS, Z	8004020241	ACRS
ZARIN, H S	8004080124+	FOIA		ZIEMANN, D L	8004020015	50~245	P	ZUFELT, E	8004090320+	50-333 R
ZECH. Q G	8004080240	MISC		ZIEMANN, D L	6004080402	50-255	, P	ZURAKOWSKI, P R	8004030247*	50-298 û
		-				200	•	LUMBNUMBRITT (uvv-ruaug4/×	JU-KYO U
ZEFF.D W	8004010157	70-1201		ZIEMANNID L	8004080405*	50-255	P	ZWETZIO, Q B	8004210229#	50-312 0
ZEFF.D W	6004220169	70-1201		ZIEMANN, D.L.	8004040086	50-219	P	ZWETZIO, O B	8004280226*	50-312 0
ZEFF.D W	8004280237	70-1201		ZIEMANN, D L	6004080183	50-29	P	ZWETZ10. G B	0004280214	50-312 0
ZEFF.D W	8004280243*	70-1201		ZIEMANN, D L	600403026B	50-245	F		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
ZEFF.D W	8004040015#	70-1201		ZIEMANN, D L	8004080426	50-255)F			

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents,"

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGOR	ΙΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
AAI Corp (subs of United Industrial Corp)	B004240063	XPORTLIC			8004250401 8004280434	50-364 50-348	Q P
	8004240067*	XPORTL10	:		8004280434	50-348	þ
AFL-CIO	8004080192*	FDIA			8004290284	50-348	Р
RMCO International, Inc	8004090287*	0A999			B0042902B6*	50~348	Þ
Academy of Natural Sciences of Philadelphia	8004210197*	50-317	R		8004290367	50-348	s
					8004270369*	50-348	5
dministrative Conference of the U S	B004160D30*	COMMISSI	UN		8004300594	50~348	G
dvanced Energy Systems	6004030313	ACRS FOIA			8004020114*	ACRE	
dvanced Tachnology, Inc	8004020192	50-22B	_		80043003B1*	70-2909	
herotest Operations	8004170005		P	Albarakk Callaga	00031701514	70 (05)	
kkin, Gump, Hauer & Feld	8004080174 8004080174	50-445	M		8004160151* 8004080643	70-1251 XPORTLIC	
		50-445			8004210041	FOIA	
	8004080174 8004080174	50-445	M M		8004220431*	50-313	F
	8004100498	50-445	M	Milia-Guarmera Corp	8004220436*	50-313	F
	8004100478	50-445	M				
	600410049B	50-445	н		8004220440# 8004220447#	50-313 50-313	F
	B004100498	50-445	11		8004220450*	50-313	F
labama Power Co	B004010372	50-348	P		8004220453#	50-313	F
	8004010425	50~348	p		8004220454*	50-313	F
	8004010507	50-348	6				
	0001040040	80.045			8004020120#	ACRS	
	8004010510*	50-348 50-348	8		8004210150 8004280248	PR PT21	
	8004010513* 8004030172	50-348	8 P	American Warming & Ventilating, Inc Amacunda Co (subs of Atlantic-Richfield		NASTE MO	т
	8004030174*	50~34B	P	Co)	0001000220	MAG IE NO	•
	8004030212	50-348	R		8004240060	WASTE MO	Т
	8004030214*	50-348	R	Anaconda Co , Anaconda Industries Wire &	8004070079*	04999	
	B004070267	50-348	F	Cable Div			
	8004080029*	50-348	Q		8004070081#	QA999	
	B0040B0403	50-348	P	Anefca, Inc	8004280235*	50-327	Р
	8004080492	50-348	R		8004030322 8004100563	50-289 50-289	G
	8004080501*	50-348	R				
	8004080540	50-348	8		8004100565*	50-289	G
	8004080547*	50-348	S		B004100567*	50-269	G
	8004080554#	50-34B	8		8004110095	50-287	0
	8004080451	50-348	Р		8004040443* 8004040448*	50-335 50-335	R
	E0040B0657	50-348 50-348	P	Aquatic, Inc	8004180371*	50-271	R
	8004100096	50-364	Q.		7902040388*	WISC	11
	8004100330 8004110003	50-346	A Q	Widnitis Martiduat Casolarold	8004020226	ACRS	
	8004140328	50-313	S		6004030294	PR	
	8004140333*	50-313	8		8004030328*	FOIA	
	B004140356	50-313	S		8004030330*	40-2061	
	B004140360*	50-313	S		8004040469	50-206	О
	8004150426	50-34B	R		8004080639*	ACRE	
	8004150428*	50-348	R		8004100586 8004100591	NUREG NUREG	
	8004150447	50-348	Р				
	8004150447	50-348	P		8004140470	NUREG	
	6004150447 6004150452*	50-348 50-348	P P		8004150122	ACRE	
	8004150447 8004150452* 8004150452*	50-348 50-348 50-348	P P P		8004150122 8004150326	ACRS NUREG	
	6004150447 6004150452*	50-348 50-348	P P		8004150122	ACRE NUREG NUREG	к
	8004150447 8004150452* 8004150452*	50-348 50-348 50-348 50-364	P P P		8004150122 8004150326 8004290017 8004010244	ACRS NUREG NUREG 50-528	
	8004150447 8004150452* 8004150452* 8004160242	50-348 50-348 50-348 50-364	P P S		8004150122 8004150326 8004290017	ACRE NUREG NUREG	KK

AUTHŪR AFF IL JAT (ON	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	Y
	8004010247* 8004010247* 8004010247* 8004010350 8004010358*	50-528 50-528 50-528 50-528 50-528	 K K K	Arkansas, State of Army Dept of, Corps of Engineers Army Dept of, Matls & Mechanics Research Center	8004290451* 8004080682 8004220555 8004100561	50-348 PR 50-329 REGGD	R A
	8004020162# 8004070255* 8004070258* 8004110484 8004150566	50-528 50-528 50-528 PR 50-528	Q S S	Arthur Young & Co Asher,T R , PC Atlantic Electric of New Jersey Atlas Minerals	8004080689 8004180285* 8004080055 8004080057* 8004220079	50~574 50~277 40~3453 40~3453 40~3453	0
Arizona, State of	8004170045 8004170051* 8004240501* 8004300532 8004070229	50-528 50-528 50-528 PR PR	8 0	Atomic Industrial Forum	8004290449 8004290452* 8004020123* 8004080136* 8004080149	40-3453 40-3453 ACR8 FOIA PR	
Arizone, Univ of Arkansas Power & Light Co	8004180078* 8004280459* 8004070100* 8004010216 8004010217*	COMMISS! COMMISS! CONTRAC: 50-313 50-313	T PA		8004100515 8004170350* 8004170352* 8004210225 8004280493	PR 10CFR 10CFR NUREO 50-320	þ
	8004010301 8004010386 8004010416 8004020342 8004020346*	50-313 50-313 50-313 50-348 50-349	P G S S	Austin, TX Australia Nabeock & Hilcox Co	8004100535 8004170270 8004010157 8004010404* 8004010404*	50-445 XPORTL1C 70-1201 50-329 50-329	H 9
	8004020349 8004020353* 8004030209 8004030209 8004040276	50-313 50-313 50-313 50-313 71-9080	5 9 P		8004010404* 8004010404* 8004010404* 8004010404*	50-329 50-329 50-329 50-329 50-329	8 8 8
	8004070118* 8004070287 8004070287 8004070344 8004070403*	50-368 50-313 50-313 50-313	0 P P P		8004020457 8004020457 8004020457 8004020457 8004020457	50-329 50-329 50-329 50-329 50-329	8 8 8
	8004070403* 8004080577 8004080596* 8004090148* 8004110508	50-313 50-368 50-368 50-313 50-313	P S G P		B004020447# B00402047B# B004040013# B004040137# B00407038B#	TOPREP TOPREP 70-1201 70-27 70-364	
	8004150235 8004150235 8004150239* 8004150237* 8004150304	50-313 50-313 50-313 50-313 50-313	î î î î		8004080661* 8004090461 6004090464* 8004100199 8004150209	ACRB TOPREP TOPREP TOPREP 50~439	0
	8004150304 8004150541 8004150549* 8004150567 9004150579*	50-313 50-313 50-313 50-368 50-368	P 8 6 F F		8004150207 8004150210* 8004150210* 8004180026 8004180077	50~439 50~439 50~439 70~135 70~364	8 8
	8004150401+ 8004150405 800415041#* 8004150630 8004150641*	50-368 50-368 50-368 50-313 50-313	# a a a a		8004180355 8004180533 8004180534* 8004210207* 8004210244	50-19 70-364 70-364 70-135 TUPREP	я
	8004160185 8004170086 8004170086 8004210148 8004210217	50-313 50-313 50-313 50-313 50-313	p p R		8004210368 8004220127 8004220169 8004240236 8004240511*	TOPREP 71-6400 70-1201 70-824 50-313	P
	8004210220* 8004210274 8004210280* 8004220427 8004220471	50-313 50-368 50-368 50-313 50-313	R R R F	Babcock & Wilcox Co . Naval Nuclear Fuel	8004280354# 8004290517 8004300570 8004300570 8004070153	50-902 50-919 50-498 50-498 70-27	р В О
	B004220691 B004220703* B004230471 B004230473* B0042403B0	50-368 50-368 50-313 50-313 50-313	8 8 8 8 5 P	Div Babtock & Wilcox Co , Nuclear Material Div	8004280237 8004280243# 8004140006	70-1201 70-1201 70-364	
	6004250044 6004250103 6004250303	50~313 50~368 71~9044	Q Q	p. (*	8004180034 8004210081	70-364 70-135	
	8004250347 8004250352* 8004250365 8004250369* 8004280487	50~382 50~382 50~382 50~382 50~313	9 9 1 1 9		8004210086* 8004240028 8004240038* 8004240046* 8004240046*	70-135 70-135 70-135 70-135 70-135	
	8004280521 8004290244 8004290361	50-368 50-313 50-313	G P R		8004240055* 8004240073* 8004240155* 8004240170*	70-135 70-135 70-135 70-135	
	8004290366# 8004290374 8004290385# 8004290450	50-313 50-313 50-313 50-368	R S S R		8004240177* 8004240177* 8004240177*	70-135 70-135 70-135	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILTATION	ACCESSION NUMBER	SUBJECT CATEODRY	
	8004240183* 8004240183* 8004240183* 8004240187* 8004270061	70-135 70-135 70-135 70-135 70-135			8004080335 8004080335 8004080391 8004080465 8004080465	50-317 (50-317 F 50-317 F	- 0 0 F P
Baker & Botts	8004290105 8004020136 8004020208 8004020232 8004080073	70-364 50-498 50-445 50-466 50-445	С М С М		8004080480 8004080488* 8004080500 8004080507* 8004090139	50-31B 9 50-317 9 50-317 8	5 5 5 6
	8004080244 8004080273 8004080273 8004080273 8004080285*	50-445 50-445 50-445 50-445 50-445	G M II M M		8004090243 8004090359 8004100227 8004100265 8004150483	50-317 P 50-317 P 50-317 0	
	8004080285* 8004080285* 8004080370 8004080487 8004100078	50-445 50-445 50-445 50-466 50-466	M M G Q		8004150486* 8004150606 8004150620* 8004150624 8004150638*	50-317 S	5 5 6 5
	8004100271 8004100271 8004100271 8004100274 8004100274	50-445 50-445 50-445 50-478 50-478	M M Q Q		8004170111 8004170217 8004170221* 8004170238 8004170238	MISC 50-317 S 50-317 S 50-317 P 50-317 P	5 P
	6004100278* 6004100278* 6004100278* 6004100532 6004100552	50-445 50-445 50-445 50-466 50-445	M M G M		8004210192 8004210197* 8004210197* 8004210323 8004210323	50-317 R 50-317 E	R R
	8004100552 8004100552 8004100557 8004100560# 8004100560#	50-445 50-445 50-466 50-445 50-445	м ю и м		8004220441 8004220614 8004220621* 8004220708 8004220719*	50-317 6 50-317 6 50-317 6 50-317 6 50-317 6	8 6 8
	8004100540* 8004110169 8004110169 8004140003 8004140003	50-445 50-445 50-445 50-445 50-445	н н н н		8004220745 8004220758* 8004220782 8004220782 8004250404	50-318 8 50-318 8 50-317 P 50-317 P 50-317 P	₿ P
	8004140003 8004140008* 8004140008* 8004140008* 8004140415	50-445 50-445 50-445 50-445 50-466	м м м м о		8004250407* 8004250407* 8004250411 8004250417* 8004280435	50-317 F 50-317 F 50-318 S 50-318 S 50-317 F	R 9 8
	8004170312 8004210392# 8004210392# 8004210392# 8004210400#	50-445 50-445 50-445 50-445 50-445	н н н н		8004290345 8004290350* 8004290372 8004290377* 8004290382	50-318 E 50-318 E 50-317 E 50-317 E	8 8 6
	8004210400* 8004210400* 8004220003 8004230022 8004230074*	50-445 50-445 50-466 50-466 50-445	М И О О М		8004290389* 8004290410 8004290416* 8004290433 8004290439*	50-317 5 50-318 5 50-317 5 50-317 5	8 8
	8004230074# 8004230074# 8004230154 8004230154 8004230154	50-445 50-445 50-445 50-445 50-445	н н н н		8004270440 8004270447* 8004270457 8004270472* 8004270475	50-317 5 50-317 6 50-317 6 50-317 6 50-317 6	3 5
Baltimore Gas & Electric Co	8004240188 8004010212 8004010342 8004010351* 8004010364	50-466 50-318 50-318 50-318 50-318	о р 8 8	Barry, David N III	8004270484* 8004270490 8004270499* 8004300079 8004070208		8 8
	8004010348* 8004010376 8004010380 8004010383*	50-318 50-318 50-318 50-318	8 8 8	Basic Energy Technology Associates Battelle Memorial Institute Battelle Memorial Institute, Columbus Laboratories	8004030005 8004100497# 8004040204	NUREO REVIEW GRF RES	P
	B0040103BB# B004010430	50-318 50-317	9		8004100025 8004300192	NUREO Nureo	
	8004010435* 8004010439	50-317 50-318	9 8	Battelle Memorial Institute, Pacific Northwest Laboratory	8004040028	RES	
	#844010448# 804010463 804010463 1160604008	50-318 50-317 50-317 50-317	8 P Q		8004040210 8004040270 8004040342 8004070093	RES RES RES ACRS	
	8004030311 8004040291 8004040292*	50-317 50-317 ACRS 50-317	о о		8004080283 8004110065 8004210298 8004210301 8004250409	RESINUREO NUREO NUREO NUREO TOPREP	
	8004070275 8004070276* 8004070276* 8004080333*	50-317 50-317 50-317 50-317	R R G	Beatty,Levin,Holland,Basofin & Sarsany Bechtel Corp	8004270020 8004100027 8004010467*	NUREG 50~454 (G P

AUFHOR AFFILIATION	ACCESSION NUMBER	SUBJE		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004010471* 8004030184* 8004040065* 8004040067* 8004220456*	50-317 50-361 50-344 50-344 50-313	A T T		8004090324 8004100258 8004100333 8004100379 8004100587	RES RES TOPREP TOPREP RES
Rechtel Power Corp (subs or Bechtel Corp)	8004280376* 8004280617* 8004280621* 8004280625* 8004040067*	50-416 50-255 50-255 50-255 50-344	F F		8004100590 8004100594 8004100599 8004110521 8004140403	RE8 RC8 RE8 RE8 50-271 F
Belgium Beltway Limousine Service, Inc	8004090377* 8004090386* 8004250428* 8004110359 8004080610*	GA999 GA999 50-373 REGGD CONTRAI	A CT		8004150015 8004150020 8004150021 8004150475 8004220574	REB REB REB REVIEW GRP
Berkeley, CA Geukers Laboratories, Inc Black & Veatch Black & Veatch, Southern Science Applications: Inc. Dl.	8004230340 8004180439* 8004140179 8004180532	50-224 50-320 REGOD REGOD	G H		8004230318 8004230320 8004230320 8004230387 8004230483	50-275 F 50-206 F 50-263 F 50-263 F 50-317 F
Black Hills Alliance Bloomsberg State College Boeing Computer Services, Inc. (subs. of Boeing Co.)		40-134 50-387 CONTRAC	CT A		8004230510 8004230524 8004240460 8004240566 8004250382	50-271 F 50-254 F REB NUREO 50-286 F
Sorg Härner Corp , Bryon Jackson Pump Di, Boston Edison Co	8004020246 8004010013 8004010304	XPORTL: XPORTL: 50-293	IC Q		8004250385 8004280032 8004280038 8004280041 8004280043	50-331 F RES RES RES RES
	8004080398 8004080511 8004080524* 8004090470	50-293 50-293 50-293 50-293	P R R P	Brown & Caldwell	8004280071 8004290007 8004300032 8004070345*	RES NUREO RES 50-206 R
	8004100386 8004100389* 8004100414 8004110079	50-293 50-293 50-293 50-293	P P P G		8004070345* 8004070345* 8004070357* 8004070357*	50-206 R 50-206 R 50-206 R 50-206 R
	8004140310 8004140311* 8004140337 8004140342* 8004150576	50-293 50-293 50-293 50-293 50-293	P P 8 8 8	Brown & Root Corp (subs of Halliburton Corp) Brown Boveri Corp (subs, Brown Bouveri & Co .Ltd)	8004010341 k 8004220017*	TOPREP 50-316 P
	8004150588* 8004160133* 8004170184 8004170191* 8004180363	50-293 50-293 50-293 50-293 50-293	8 0 8 8 P	Brownsville:TX	8004220023* 8004220027* 8004220034* 8004220039*	50-316 P 50-316 P 50-316 P 50-316 P
	8004210287 8004210272* 8004220580 8004220624 8004220631*	50-293 50-293 50-293 50-293 50-293	9 9 9 8	Bruce Norton	8004100430* 8004100433 8004150050* 8004080712	90-445 H 50-445 H 50-275 Q
•	8004230469 8004230477 8004230497 8004230499#	50-293 50-293 50-293 50-293	P G R R	Brush-Wellman, Inc Dunker-Ramo Corp , Amphunol North America Div Burns & Roe Co	8004300243 7908140247* 8004010282 8004070370* 8004070371*	40-8722 COMMIBSION FOIA 50-397 A 50-397 A
, Darton & Eckler ionai Laboratory	8004240357 8004250156 8004270424 8004280004 8004220137* 8004010327	50-293 50-293 50-293 50-395 FOIA 50-171	9 F M	C-E Power Systems	8004070372* 8004070374* 8004240041* 8004010498 8004010501*	50-397 A 50-397 A CONTRACT TOPREP TOPREP
		50-171 50-266 50-266 50-295 50-409	ج ج ج ج ج		8004110216 8004110223* 8004110225* 8004210130* 8004210138*	TOPREP TOPREP TOPREP 70-1100 70-1100
		50-29 NUREO 50-333 50-254 REB	F F F	California Institute of Technology California Polytechnic State Univ	8004230315 8004240169 8004280400 8004180003 8004220601	TOPREP 70-1100 TOPREP ACRS 50-384 P
		RES RES RES 50-331 50-206	F F	California, State of	8003190734* 8004040007 8004040008* 8004090187 8004100540	50-128 P PR PR 50-312 0 PR
		50-206 RES RES 71-9019 RES	F	California, Univ of, Davis California, Univ of, San Diego	8004100542 8004220570 8004230317* 8004250047 8004210325*	50-312 T 50-204 P PRGJ NUREO 50-275 0
		REB		California, Univ of, Banta Barbara	8004220418* 8004070328	FOIA 50-433 R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	łΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y
California, Univ of, Santa Cruz Camp Dresser & McKee, Inc , Environmental Beiences, Div Carolina Power & Light Co	8004070327* 8004210327* 8004020057	50-433	R G FT		8004220476 8004220687* 8004220732 8004220740* 8004230007*	50-325 50-325 50-324 50-324 50-445	55555 5555 5555 5555 5555
Carettua Fower & Light Co	8004010324 8004010385 8004010390* 6004010394 8004010400* 8004010405	50-325 50-325 50-324 50-324 50-261	5 5 5		8004230076 8004230328 8004230328 8004230328 8004230328	50~324 50~400 50~400 50~400 50~400	Q A A A
	8004010405 8004010407* 8004010461 8004010461 8004010468*	50-261 50-261 50-324 50-324 50-324	I I R R		8004230520 8004230525* 8004240362 8004240366* 8004240379	50-261 50-261 50-261 50-261 50-261	C 65 55 55 55 55 55 55 55 55 55 55 55 55
	8004010517 8004020297 8004030171 8004030176 8004030217	50-400 50-324 50-261 50-324 50-255	0 8 8 8		8004250261* 8004250410 8004250410 8004250412* 8004250412*	50-261 50-324 50-324 50-324 50-324	Q P P P
	8004040293 8004040297* 8004040305 8004040323* 8004040461	50-261 50-261 50-261 50-261 50-324	P P R Q		8004280497 8004280540 8004280541 8004280574 8004280583	50-324 50-400 50-400 50-325 50-324	6 8 8 8 8
	8004070035 8004070134 8004070295 8004070313 8004070333	50-400 50-261 50-400 50-261 50-324	0 0 F 6		8004280586* 8004280587 8004280592* 8004280599* 8004290122*	50-325 50-324 50-324 50-324 50-324	3 8 8 8 9
	8004070337* 8004080357 8004080357 8004080383 8004080383	50-324 50-324 50-324 50-324 50-324	88866		8004290397 8004290401* 8004290487 8004290494* 8004300323	50-325 50-325 50-325 50-325 50-324	8 8 8 8 8
	8004080451 8004080453 8004080454* 8004080458 8004080464*	50-400 50-325 50-325 50-324 50-324	A 5 8 8 8	Catholic Univ Canter for Law in the Public Interest	8004300443 8004300445 8004070099* 8004020133 8004020133	90-261 50-324 40-4329 50-275 50-275	P H 0 0
	8004080472 8004080472 8004080566 8004080575* 8004080648	50-324 50-324 50-325 50-325 50-261	F F 59 P		8004080554 8004080554 8004070038 8004070038 8004070132	50-275 50-275 50-275 50-275 50-275	0 0 0
	8004070058 8004070332 8004100340 8004100343 8004100345*	50-400 50-324 50-261 50-261 50-261	6 8 8 8		8004070132 8004070137* 8004070137* 8004210322 8004210322	50~275 50~275 50~275 50~275 50~275	0000
	8004140413 8004140445 8004140445 8004140447*	50-261 50-324 50-324 50-324 50-324	P R R R	Central & Houthwest Corp	8004080153 8004080360 8004080559 8004080559 8004090387	50-445 50-445 50-445 50-445 50-445	***************************************
	8004140468* 8004150374 8004150376* 8004150444 8004150448*	50-261 50-261 50-261 50-324 50-324	G R R B	Central & Bouthwest Bervices, Inc Central Power & Light Co Charles B Wurtz	8004070387 8004230002 8004220128 8004180167* 8004210358*	50-445 50-445 50-445 50-445 50-320	M M M P
	8004150466 8004150466 8004150504 8004150504 8004160282	50-324 50-324 50-324 50-324 50-324	8 8 8 F	Charlevoix,MI Chem-Nuclear Systems, Inc Cherry, M. M./Cherry, Flynn & Kanter	8004030363 8004070254 8004090091 8004020033 8004020033	50-155 71-9122 71-9122 50-454 50-454	0
	8004160282 8004170015 8004170019* 8004170047 8004170053	50-324 50-324 50-324 50-400 50-400	P P A S		8004090429 8004090429 8004090435* 8004090435* 8004090177	50-454 50-454 50-454 50-454 50-454	0000
	8004180344 8004180418 8004180425* 8004210293 8004220451	50-261 50-261 50-261 50-324 50-400	Jasa	Chesapeake Energy Alliance	8004090177 8004030320 8004090190 8004110157 8004110164*	50-454 50-289 50-289 50-289 50-289	0000
	8004220451 8004220451 8004220451 8004220538 8004220547*	50-400 50-400 50-400 50-925 50-925	A A A S S	Chicago, City of, IL	8004110166* 8004110175 8004230039 8004080092 8004080177	50-289 50-289 50-289 40-2061 40-2061	
	8004220572 8004220583* 8004220597 8004220608*	50-324 50-324 50-325 50-325	8888	Chickering & Gregory	8004080228 8004070188 8004070196* 8004100477 8004100537	PR PR PR 50-361 50-361	0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
honin:N Shrista-Harla Sincinnati Gas & Electric Co	8004080239 8004240086 8004140031* 8004030338 8004040340	50-250		8004040341 8004070227 8004070245 8004070273 8004070273	50-10 50-10 50-237 50-254 50-254	F
	8004040343* 8004150301 8004160009 8004220156 8004280317	50-358 I 50-358 A 50-358 0 50-358 0 50-358 F		8004070273 8004070273 8004080214 8004080214 8004080235	50-254 50-254 50-275 50-275 50-237	1
incinnati General Hosg - Cincinnati, OH	80042803,24 8004300404* 8004220044* 8004220097* 8004220242*	50-358 F 50-358 Q FOIA FOIA		8004080254 8004080397 8004080428 8004080428 8004080456	50-247 50-454 50-454 50-454 50-249	
incinnati, Univ of, Medical School	8004220387* 8004220391* 8004220404* 8004220101* 8004220120*	FOIA FOIA FOIA FOIA FOIA		8004080443* 8004080522 8004080522 8004080541 8004080549*	50-247 50-373 50-373 50-10 50-10	
itzzens Action For Saf∙ Energy	8004070149 8004100605* 8004100605* 8004100610* 8004100610*	50-556 0 50-556 0 50-556 0 50-556 0 50-556 0		8004080552 8004080561* 8004100128* 8004100322 8004100338	50-249 50-249 50-10 50-454 50-295	
itizens Ageinst Nuclear Dangers itizens Concerned About Nuclear Power, Inc ittizens Energy Forum	8004020040 8004280069 8004280211	50-387 0 50-498 0 50-338 0		8004110087 8004110397 8004110458 8004140119	50-304 50-237 50-237 50-10	
itizens for Fair Utility Regulation itizens for a Batter Environment	8004240424* 8004090271	50-445 G PR		8004140117 8004140117	50-10 50-10	
leveland Electric Illuminating Co calition for Safe Power chn, D B	8004150471 8004230353 8004280386* 8004230020 8004010294	50-346		8004140119 8004140119 8004140213 8004140306	50-10 50-10 50-373 50-275	
olorado State Univ	8004010300* 8004280420* 8004280425*	50-367 9 40-8681 40-8602		8004140330 8004140398 8004140423 8004140429*	50-10 50-237 50-237 50-237	
olorado. State of	8004280427* 8004070359*	40-8602 WASTE MGT		8004140441 8004140447*	50-456 50-456	
olt Industries, Inc	8004110118 8004110146* 8004240116 8004300254 8004020455	WASTE MOT WASTE MOT WASTE MOT WASTE MOT 50-395 B		8004150004 8004150314 8004150314 8004150316	50-254 50-10 50-10 50-10	
olt Industries, Inc. Fairbanks Morse Engine Div	8004080297*	0A999		8004150316 8004150316 8004150328*	50-10 50-10 50-10	
olumbus & Sauthern Ohio Electric Co ommerce Dept of, National Bureau of	800414015 <i>6</i> 8004040350* 8004070194*	50-483 6 50-358 I 50-184 Q		8004150344 8004150382	50-10 50-10	
Standards	8004100007*	50-184 Q		6004150382 6004150387* 6004150387*	50-10 50-10 50-10	
ommerce.Dept of, National Marine Fisheries Service ommonwealth Edison Co	8004170250 8004010352	50-272 P 50-373 F		8004150416 8004150417*	50-373 50-373	
	8004010359 8004020177 8004020189	50-237 P 50-597 A 50-295 P		8004150457 8004150463 8004150467* 8004150468*	50-254 50-254 50-254 50-254	
	8004020189 8004020309 8004020310* 8004020313*	50-295 P 50-249 S 50-249 S 50-295 S 50-295 S		8004150477* 8004150477* 8004150492 8004150498*	50-304 50-265 50-265 50-237	
	8004020332 8004020337* 8004020350 8004020352	50-249 S 50-247 S 50-254 S 50-265 S		8004150503 8004150513* 8004150518 8004150526*	50-237 50-304 50-304	
	8004020355* 8004020357* 8004020363 8004020367*	50-245 8 50-254 8 50-249 8 50-249 8	1	8004180217 8004180217 8004180217 8004180217	50-10 50-10 50-10	
	B004020369 B004020376#	50-295 8 50-295 8 50-304 8		8004180217 8004180372 8004180389 8004180389	50-10 50-249 50-247 50-247	
	8004020412# 8004020422 8004020427# 8004020430	50-304 S 50-254 B 50-254 B 50-265 S		8004180389 8004180389 8004180395* 8004180395*	50-247 50-247 50-247 50-247	
	8004020435 8004020443* 8004020445* 8004030027 8004030172	50-265		8004180375* 8004180375* 8004210286 8004210288*	50-247 50-247 50-249 50-249	
	8004030172	50-10 F		8004210288* 8004220299 8004220299	50-237 50-237	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Υ
	8004220332 8004220333 8004220333 8004220348 8004220356	50-10 50-254 50-254 50-237 50-295	P R R P F		8004110574 8004150027 8004150030* 8004150456 8004150469*	50-445 50-272 50-272 50-311	MGGGG
	8004220356 8004220586 8004220596* 8004220613 8004220623*	50-275 50-275 50-275 50-265 50-265	F S S S	Consolidated Edison Co of New York	8004220156 8004030165 8004070205* 8004070208* 8004070214*	50~3 50~3 50~3	9 9 1 1 1
	8004220430 8004220460 800422041 8184022408 E64022408	50-10 50-295 50-295 50-10 50-249	9 5 5 5 5		8004070224* 8004070229* 8004070233* 8004080410 8004080417	50-3 50-3 50-247	H H F P
	8004220494 8004220700* 8004220702* 8004230072 8004230367	50-304 50-249 50-304 50-10 50-10	8 8 8 P		8004150433 8004150599 8004150599 8004150599 8004150609*	50-3 50-3 50-3	P R R R
	8004230367 8004230367 8004230479 8004240412 8004250353	50-10 50-10 50-373 50-265 50-249	F F A P P		8004150609* 8004150609* 8004180389 8004180389	50-3 50-247 50-247	E E P P
	8004250427 8004280410 8004280412# 8004280414* 8004280509	50-373 50-373 50-373 50-373 50-275	A A A A		8004180395* 8004180395* 8004180395* 8004210255 8004210258*	50-247 50-247 50-247	PPRR
	8004280509 8004290380 8004290407* 8004290422 8004290429*	50-295 50-265 50-265 50-249 50-249	P 6 8 8		8004210269 8004210269 8004210269 8004210276# 8004210276#	50-3 50-3 50-3	R R R R
	8004290473 8004290483* 8004290486 8004290496* 8004290502	50-295 50-295 50-295 50-295 50-295	8 8 8 8		8004210276* 8004220589 8004220627 8004240410 8004300307	50-247 50-247 50-247	R F F P P
	8004290502 8004290506* 8004290506* 8004300416 8004300417*	50-275 50-275 50-275 50-247 50-247	Р Р Р Р	Consumers Pawer Co	8004300411 8004010287 8004010397 8004020166 8004020285	50-255 50-327 50-255	P P 6 P R
Cone, Owen, Hagner, Nugent, Johnson, Hazouri & Roth Connecticut Light & Power Co	8004300423* 8004300429 8004070008 8004080564*	50-247 50-247 FOIA 50-245	l b		8004020289* 8004030220* 8004040309 8004040311* 8004040327	50-255 50-155 50-155	RRPPP
Connecticut Yankes Atomic Power Co	8004150322* 8004010362 8004010367* 8004020374 8004020374*	50-245 50-213 50-213 50-213	1 8 8 8 8		8004040371 8004040376* 8004070293 8004070293 8004070294*	50-255 50-329 50-329	R R R R
	8004030211 8004040066 8004040331 8004040338* 8004070274	50-213 50-213 50-213 50-213 50-213 50-213	0 P R R P		8004070294* 8004070305 8004070320 8004070322* 8004080186*	50-255 50-255 50-255	6 6 8 8
	8004070274 8004080292 8004110012 8004150297 8004150487 8004170012	50-213 50-213 50-213 50-213 50-213	1 9 R P		8004080232 8004080404 8004080404 8004080431 8004080431	50-329 50-329 50-329	P A A A
	8004170012 8004180224 8004180344 8004210251 8004210253*	50-213 50-213 50-213 50-213 50-213	P P R R R		8004080436 8004080438* 8004080470 8004080475* 8004090248	50-255 50-255 50-155 50-155 50-329	R R S S K
	8004210411 8004230297 8004240437 8004240437* 8004250132	50-213 50-213 50-213 50-213 50-213	P F R R		8004070248 8004070251* 8004070251* 8004070258* 8004070258*	50-329 50-329 50-329 50-329 50-329	***
Connecticut, State of	8004250143* 8004280465 8004270264 8004270442 8004070426*	50-213 50-213 50-213 50-213 8tate Pr	0 Р R Р		8004090383* 8004090389 8004100293 8004100296*	50-255 50-255 50-155 50-155 50-155	0000
Conner, Moore & Corber	8004070428* 8004090116 8004100445 8004030338 8004080409	PR PR 50-358 50-375	G G		8004100368 8004100384 8004100384 8004100387* 8004100387*	50-329 50-329 50-329 50-329 50-329	Q A A A A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8004100390+ 8004100390+ 8004100396 8004100397+ 8004100403	50-329 50-329 50-255 50-255	A A S S S S	Debevoise & Liberman	8003250002 8004040088 8004080119 8004080221 8004080227	NUREO 50-445 PR 50-445 50-445	0 M
	8004100404# 8004100413 8004100455# 8004100455# 8004100462#	50-255 50-255	5 8 9 9		8004080247 8004080247 8004080401 8004080401 8004080401	50-445 50-445 50-445 50-445 50-445	м н н
	8004100469+ 8004100480+ 8004110308 8004110308 8004110505	50-155 50-155	G G P P		8004080638 8004090331 8004100514 8004100514 8004100514	50-445 PR 50-445 50-445 50-445	H H H
	8004140309 8004140334 8004140391 8004150012 8004150019*	50-155 50-255 50-329 50-255 50-255	P G K S S		8004100525* 8004100525* 8004110159 8004140005 8004140285	50-445 50-445 70-2623 PR 50-397	M H
	8004150215 8004150354 8004150354 8004150398 8004150474	50-255 50-329 50-329 50-255 50-255	P S S P P		8004140285 8004160285 8004180151 8004230012 8004230033	50-397 50-397 50-445 70-2623 50-445	A H H
	8004150479* 8004150530 8004150537* 8004150544 8004150556*	50-255 50-255 50-255 50-255 50-255	P S S S		8004230033 8004240173 8004240562 8004250047 8004280187	50-445 50-445 50-445 50-445 50-556	н н о
	8004150627 8004170083 8004170083 8004180487 8004210158	50-255 50-329 50-329 50-255 50-255	P S G P	Delmarva Power & Light Co Detroit Edison Co	8004150260* 8004020403 8004040278 8004070135* 8004080647*	50-277 50-341 50-341 50-341 50-341	1 8 A 0 0
	8004210318 8004220575 8004220581* 8004220588 8004230383	50-329 50-155 50-155 50-255 50-155	8 0 0 9 H	Doctors Hosp Columbus,OH Doherty,JF Dougherty,JB	8004230487 8004300382 8004230029* 8004240548 8004150101	50-341 50-341 FOIA 50-466 50-574	9 9 0
	8004230383 8004240372 8004240450 8004250313 8004250350	50-155 50-155 50-255 50-255 50-255	H P P G S	Oresser Industries, Inc Duke Pawer Co	8004150204 8004280211 8004300554 8004010470 8004010470	FOIA 50-338 PTR1 50-269 50-269	Q P P
	8004280354 8004250358* 8004280359* 8004250425 8004250426	50-255 50-255 50-255 50-255 50-255	8 8 9 P		8004010470 8004020019 8004020334 8004020338* 8004020348	50-269 50-413 50-269 50-269 50-369	9 1 1 1 8
•	8004280402 8004280460 8004280519 8004280555 8004280557*	50-255 50-327 50-255 50-155 50-155	G F P F F		8004020348 8004020358* 8004020358* 8004030152 8004030152	50-369 50-369 50-369 50-369 50-369	8 8 8
Control Data Corp Coordination Council for North American Affairs	8004280614 8004290324 8004290301* 8004150590* 8004030043	50-255 50-155 50-369 50-366 XPDRTLIC	F G A F		8004030157 8004030157 8004030157 8004030199 8004030199	50-269 50-269 50-269 50-269 50-269	6 6 6
Creare, Inc Critical Mass Energy Project Dairyland Power Cooperative	8004140478 8004090152 8004010108 8004090369 8004140312	NUREO PR 50-409 50-409 50-409	Q P		8004030199 8004030202* 8004030223 8004030224* 8004040358	50-269 50-269 50-287 50-287 50-269	8 8 6
	8004140314* 8004140365 8004140367* 8004150119 8004150204	50-409 50-409 50-409 71-6400 50-409	P R R		8004070234 8004070234 8004070236* 8004070236* 8004070327	50-369 50-369 50-369 50-369 50-269	A A A B
	8004190488 8004210200 8004220584 8004270341 8004300456	50-409 50-409 50-409 50-409 50-409	9 8 8 8		8004070330* 8004070362 8004080101 8004080125 8004080253	50-269 50-269 50-369 PR 50-269	9 9 9
	8004300463* 8004230082 8004010250* 8004040387* 8004210409	50-409 50-556 50-466 50-250 50-409	8 0 A R P		8004080366 8004080366 8004080432 8004080455 8004080457*	50-369 50-369 50-287 50-369 50-369	A G A A
sponsible	8004240499 8004040355* 8004100027	40-297 50-358 50-454	I Q		8004080461* 8004080461* 8004080471 8004080476* 8004080555	50-349 50-349 50-249 50-249 50-269	A B B P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC.	
	8004080614 8004090241 8004100351 8004100558 8004110153	50-269 PR	P G		8004150534* 8004150545* 8004170223 8004210261 8004210266*	50-334 50-334 50-334 50-334 50-334	9 9 8 8
	800411055B 800414034B 8004140430 8004140430 8004140430	PR 50-369 50-269 50-269 50-269	А Р Р		8004210283 8004220483 8004220594 8004220597 8004230208	50-334 50-412 50-334 50-334 50-334	P GI P S S
	8004140430 8004150465 8004150465 8004150465 8004160116	50-269 50-269 50-269 50-269 50-413	P P P G		8004230217 8004230427 8004230517 8004240087* 8004240385	50-334 50-412 50-334 50-334 50-334	8 9 9 9
	8004160229 8004160232* 8004160272 8004170164 8004170203	50-287 50-287 50-297 50-269 50-269	8 9 9 8 9		8004280078* 8004280188 8004270354 8004270355* 8004270387	50-334 50-412 50-334 50-334 50-334	P G R R
	8004170208* 8004170327 8004180273 8004180356 8004180516	50-267 50-267 50-367 50-267 50-367	S F F Q	E L Conwell & Co	8004270393* 8004270503 8004270508* 8004210066 8004210073*	50-334 50-334 50-334 71-381 71-381	8 8
	8004210164 8004210172 8004210171 8004210171 8004210171	50-413 REGOD 50-269 50-269 50-269	0 0 0	E 1 du Pont de Nemaurs & Co , Inc EDS Nuclear, Inc EQ & G, Inc	8004140121 8004220273* 8004020142 8004030308* 8004080075	ACRS 50-331 RES FOIA RES	F
	8004210234 8004220105 8004220105 8004220105 8004220443	50-413 50-491 50-491 50-491 50-269	0 0 0 0 F		8004080082 8004080242 8004080641 8004080641 8004080684	RES 865 50-270 50-270 RES	P P
	8004220443 8004220443 8004220502 8004220502 8004220640	50-267 50-267 50-267 50-267 50-267	F F P P		8004070048 8004100027 8004100328 8004100378 8004140138	RES NUREO RES RES	
	8004220640 8004220649 8004220682 8004220690* 8004220720	50-269 50-270 50-269 50-269 50-369	P B B A		8004150025 800415003B 8004150056 8004170120 8004170274	50-155 50-271 RES RES RES	P
	8004230012 8004230085 8004230236* 8004240035 8004240276	70-2623 50-488 50-269 50-269 50-269	0 0 0		8004170276 8004170287 8004170334 8004210340* 8004210344*	REB REB RES 50-320 50-320	P P
	6004240426 6004240426 6004240426 6004250334* 6004280473	50-491 50-491 50-491 50-269 PR	Q Q Q		8004210347# 8004210349# 8004240468 8004240565 8004250364	50-320 50-320 RES NUREO 50-275	ь Ь
Duquesne Light Co	8004270493 8004270501 * 8004300214 * 8004010457	50-369 50-369 50-269 50-334	A A G P	ETA Engineering, Inc Earth Sciences Associates Ebasco Services, Inc (subs of Enserch Corp)	8004150520* 8004090020 8004100588	50-315 WASTE M	
	8004020002 8004030191	50-334 50-334	8	Eberline Instrument Corp	8004140224* 8004040070	SO-201 XPORTLI	C P
	8004030196 8004030197* 800403019B 8004030201	80-334 50-334 50-334 50-334	R R S	Eckert. Seamans, Cherin & Mellott	8004100306 8004140322* 8004140340* 8004150007* 8004280036	XPORTL1 50-295 50-10 50-254 50-574	IC R R Q
	8004040165* 8004040354 8004040359*	50-334 50-334 50-334	Q F F	Ederer, Inc. (subs of Formac Internatio	8004020267	TOPREP	
	8004070199* 8004070277 8004070280*	50-334 50-334 50-334	G R R	nel, Inc) Edison Electric Institute	8004020271* 8004080245 8004100513* 8004110367	Toprep Pr Commiss Pr	3ION
	8004070336 8004070341 8004070346* 8004070375*	50-412 50-334 50-334 50-334	A S S S	Edlow International Co	6004040135 6004040422* 6004040427* 6004040437*	XPORTLI FOIA FOIA FOIA	(C
	8004070007 8004100358* 8004110160 8004110385 8004110482	50-334 50-334 50-334 50-334 50-334	Q Q S P	Eichhorn, Eichhorn & Liny Elbert P Epler	8004040442* 8004080032 8004280096 8004020092 8004030295	FOIA XPORTLI XPORTLI 50-367 ACRS	1 C
	8004140327 8004140381 8004150221 8004150516 8004150527*	50-334 50-334 50-334 50-334 50-334	8 0 8 8	Ellis Fischel St Cancer Hosp Columbia, MO Energy Engineering Group Energy Fuels Nuclear, Inc	8004010789* 8004150152 8004020487	PT9 RES 40-8681	1

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT CATEGORY
Energy, Dept of •	8004020055 8004020057* 8004020465* 8004030054* 8004030065*	71-6397 71-6397 50-320 H 50-320 H 50-320 H		8004090108* 8004090112* 8004090370 8004090378* 8004100066	70-1257 70-1257 70-1257 70-1257 70-1257
	8004030071* 8004030093* 8004040233* 8004040237* 8004040245*	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	FBF, inc	8004100073 8004140458 8004140464* 8004180072 8004070021	70-1257 70-1257 70-1257 70-1227 71-185
	8004040248* 8004040253* 8004040258* 8004040263* 8004040265*	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	FOI Service Federal American Partners	8004070022* 8004020270 8004100052 8004210017 8004300053*	71-185 FOIA FOIA FOIA 40-4492
	8004040431* 8004070247 8004070389 8004070082 8004090087	50-320 H 71-9853 71-9067 ØRG ORG	Federal Emergency Management Agency Federal Signal Corp , Signal Div	8004300065* 8004030026 8004040379 8004170202 8004230436	40-4492 50-320 Q NUREO PR NUREO
	8004090269* 8004100575* 8004110523 8004180200 8004180207*	50-556 H 50-320 H PR XPORTLIC XPORTLIC	Feldman, Hall, Franden, Reed & Woodward	8004100595 8004100595 8004100605* 8004100605* 8004100610*	50-556 Q 50-556 Q 50-556 Q 50-556 Q 50-556 Q
	8004210026 8004210149* 8004210282* 8004210353 8004210359*	XPORTLIC XPORTLIC 50-546 H PR 70-143	Finland Fire Equisment, Inc	8004100610* 8004250009 8004230309* 8004230313* 8004230316*	50-556 Q XPORTL1C 50-213 F 50-213 F 50-213 F
	8004210361* 8004220010 8004220124* 8004220143* 8004220191*	PR NUREG 50-320 H 50-320 H 50-320 H	Fleischater, D S	8004020133 8004020133 8004080556 8004080556 8004090038	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
	8004230129 8004230133* 8004240559 8004240568 8004280172	XPORTLIC XPORTLIC NUREQ PR PR		8004090038 8004090132 8004090132 8004090137* 8004090137*	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
Energy, Dept of, Clinch River Breader Reactor Plant	8004150473 8004270364	50-537 A 50-537 A		8004210322 8004210322 8004230107	50-275 0 50-275 0 50-275 0
Envirological Systems, Inc Environmental Coalition on Nuclear Power	8004070140* 8004080143 8004080143	WASTE MOT 50-387 0 50-387 0	Florida Cities	8004230107 8004220152	50-275 O 50-445 H
	8004080697 8004080697 8004110477 8004140061 8004140067*	50-387	Florida Power & Light Co	8004230174 8004010210 8004010210 8004010214* 8004010214*	50-387 H 50-250 P 50-250 P 50-250 P 50-250 P
En√ıronmental Defense Fund Environmental Law Institute	8004140076* 8004230073 8004240544 8004040346 8004030340*	50-320 G PR 50-287 G 50-275 H COMMISSION		8004010497* 8004020011* 8004020265* 8004020377 8004020381	50-302 R 50-387 0 50-387 0 50-251 9 50-335 8
Environmental Policy Center Environmental Protection Agency	8004070350 8004010345# 8004010444 8004010470 8004030272	50-320 H 50-508 A 50-320 R 50-320 R FR		8004020384* 8004020391* 8004030147 8004030229 8004030249	50-335 8 50-251 8 50-335 8 50-387 F 50-250 9
	8004040188 8004070222 8004070332 8004070075 8004100050*	40-2041 50-320 R 50-320 R 50-320 R PR		8004030256# 8004030282 8004030285# 8004030287 8004030287	50-250 8 50-335 8 50-335 8 50-250 P
	8004100050* 8004100055* 8004100055* 8004100477 8004140246	FR FR PR 50-320 F 50-280 P		8004040003 8004040003 8004040173* 8004040347* 8004040347*	50-250 G 50-250 G 50-367 G 50-250 G 50-250 G
, ttchen	8004220415 8004230375 8004230375 8004250370 8004250352	50-320 R 50-320 R 50-320 R NUREO 50-445 M		8004040380 8004040380 8004040397* 8004040425 8004040434*	50-250 R 50-250 R 50-250 R 50-255 R 50-335 R
ubs of Exxan	8004070154 8004080198 8004280403 8004290526 8004020307	40-8102 40-8044 40-8102 40-8102 50-241 P		8004070279 8004080015* 8004080023* 8004080257 8004080265*	50-335 F 50-250 Q 50-250 Q 50-335 R 50-335 R
	8004020404 8004070216 8004090102	TOPREP 71-9009 70-1257		8004080386 8004080452 8004080601 8004080608* 8004090217	50-335 P 50-250 P 50-250 8 50-250 8 50-335 R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC*	
	8004070217* 8004070247 8004110533* 8004110533* 8004110536*	50-335 PR 50-250 50-250 50-250	R G G		9004240334 9004240343* 9004240350 9004240350 9004240350	50-335 50-335 50-250 50-250 50-250	9 9 8 8 8
	8004110536* 8004140227 8004150156* 8004150341 8004150406	50-250 50-335 50-335 50-335 50-250	G F P I		8004240356* 8004240356* 8004240356* 8004240357 8004240359	50-250 50-250 50-250 50-250 50-250	R R R R
	8004150406 8004150406 8004150411* 8004150519 8004180373	50-250 50-250 50-250 50-250 50-250	I I F R		8004240359 8004240363* 8004240363* 8004240363* 8004240368	50-250 50-250 50-250 50-250 50-250	R R R R
	8004180373 8004180373 8004180374* 8004180374* 8004180374*	50-250 50-250 50-250 50-250 50-250	R R R R		8004240369 8004240374* 8004240375* 8004240378* 8004240418	50-335 50-250 50-335 50-250 50-250	S R S G R
	8004180524 8004180524 8004180524 8004180528* 8004180528*	50-250 50-250 50-250 50-250 50-250	R R R R		8004240418 8004240418 8004240422* 8004240422* 8004240422*	50-250 50-250 50-250 50-250 50-250	R R R R
	8004180528* 8004180527 8004180527 8004180527 8004180530*	50-250 50-250 50-250 50-250 50-250	R R R R		8004240436 8004240436 8004240435 8004240440* 8004240440*	50-250 50-250 50-250 50-250 50-250	R R R R
	8004180530* 8004180530* 8004210170 8004210184* 8004220141	50-250 50-250 50-389 50-389 50-389	R R S S G		8004240440* 8004240443 8004240443 8004240443 8004240444*	50-250 50-250 50-250 50-250 50-250	R R R R
	8004220239 8004220243* 8004220248 8004220250* 8004220256	50-387 50-387 50-387 30-387 50-389	A K K		8004240444* 8004240444* 8004240448 8004240448 8004240448	50-250 50-250 50-250 50-250 50-250	R R R R
	8004220258 8004220261 8004220264 8004220266 8004220271	50-389 50-389 50-389 50-389	К К К К		8004240452* 8004240452* 8004240452* 8004240455 8004240455	50-250 50-250 50-250 50-250 50-250	R R R R
	8004220275 8004220279 8004220283 8004220287 8004220276	50-389 50-389 50-389 50-389 50-389	K K K K		8004240455 8004240457* 8004240457* 8004240459* 8004240463	50-250 50-250 50-250 50-250 50-250	R R R R
	8004220298 8004220300 8004220305 8004220306 8004220308	50-389 50-389 50-389 50-389 50-389	K K K K		8004240463 8004240463 8004240466# 8004240466#	50-250 50-250 50-250 50-250	R R R
	8004220309 8004220313 8004220317* 8004220321* 8004230321	50-389 50-389 50-389 50-389 50-250	K C C R				
	8004230321 8004230321 8004230326# 8004230326# 8004230326#	50-250 50-250 50-250 50-250 50-250	R R R R				
	8004230330 8004230330 8004230330 8004230332* 8004230332*	50-250 50-250 50-250 50-250 50-250	R R R R	Florida Powe			
	8004230332* 8004230461 8004230464* 8004230484 8004230484	50-250 50-335 50-335 50-250 50-250	R P R R				
	8004230484 8004230490* 8004230490* 8004230490* 8004230537	50-250 50-250 50-250 50-250 50-335	R R R R				
	8004240030 8004240030 8004240219 8004240309 8004240317*	50-250 50-250 50-389 50-250 50-250	0 0 5 8				

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIAYION	ACCESSION NUMBER	SUBJECT CATEGOR	Y
	8004180237 8004180462 8004180484* 8004210111 8004210238	50-302 50-302 50-302	е 1 1 6		8004150353 8004170020* 8004170044 8004170046* 8004170049*	TOPREP 50-324 50-73 50-73 50-73	P P P
	8004210240* 8004220526 8004240467 8004280351 8004280567	50-302 50-302 50-302	R G P P		8004170254 8004170257* 8004170260* 8004170287 8004180525*	50-70 50-70 50-70 REB 70-1007	P P P
	8004280568* 8004280571* 8004290480 8004290488* 8004300151*	50-302 50-302 50-302	P P S G		8004210162* 8004210306* 8004210307* 8004220497 8004230343*	70-1113 TOPREP TOPREP TOPREP 50-217	P
Florida State Univ Florida, Univ of, Gainesville Ford Bacon & Davis Utah, Inc	8004300164* 8004300331 8004100369* 8004220213 8004300219*		o o		8004240267 8004240277* 8004240294* 8004250084 8004250284	70-1308 70-1308 70-1308 71-5971 71-5939	
Franklin Institute/Frankjin Research Center	8004020241 8004040120* 8004070042* 8004080474 8004080646*		P Q		8004280305 8004280311 8004280422 8004280504 8004280507*	70-1308 50-70 50-550 TOPREP TOPREP	P A
Fried, Frank, Herris, Shriver & Kampelman Friends United for Safe Energy Friends of the Earth GTE Sylvania, Inc. (subs. of General Telephone & Electronics Corp.)	8004110500+	50-272 COMMISSID 50-320 50-387	Q N H G F	General Electric Cø . Nuclear Energy Products Div	B004300056* 8004300056* B004300092* B004300107* B004020143	50-70 50-70 GA999 GA999 71-9019	P
Oage-Babcock Associates, Inc Gemma Corp Gearhart-Owen Industries, Inc , OO Wireline Services Div	8004140236 8004210037 8004080650	71-6717 XPORTLIC	F		8004090149 8004090316 8004110109 8004140070* 8004140073*	70-1113 TOPREP PR 70-1308 70-1309	
General Atomic Co (subs of Gulf Dil Co)	8004040479¥	QA999			8004140082*	70-1308	
	8004080007 8004080014* 8004170360 8004180480	XPORTLIC XPORTLIC 50-585 XPORTLIC	٨		8004150270 8004150280* 8004140078 8004180121	TOPREP TOPREP PR 70-1113	
General Atomic Co (subs of Gulf Oil Corp)	8004080365#	0A999			8004180124* 8004180133	70-1113 70-1308	
	8004210156 8004210159*	XPORTLIC XPORTLIC			8004180515 8004180515	70-1007 70-1007	
General Electric Co	8004010061 8004010066* 8004010181* 8004010175*	71-9049 71-9049	p		8004180522* 8004180522* 8004220789 8004220790* 8004230163	70-1007 70-1007 71-9019 71-9019 70-1113	
	8004020127 8004020137* 8004020185 8004020254 8004020467	71-5939 71-5939 50-70 TOPREP XPORTLIC	p	General Electric Operating Plant Gwners	8004270468 8004300052 8004220497*	TOPREP 50-70 TOPREP	P
	B004020471#	XPORTLIC		Group General Public Utilities - GPU Service Corp	8004090477	50-320	1
	8004030274 8004030280* 8004040112 8004040326	XPORTLIC XPORTLIC	Р	,	8004070482* 8004100354* 8004140250	50-320 50-219 50-320	I I R
	8004040333* 8004040337* 8004070136 8004070317	TOPREP TOPREP 70-2786 50-18	ı	Geo-Centers, Inc Georgia institute of Technology	8004150621 8004280638* 8004230528* 8004280477	50-289 50-320 CGNTRACT 50-160	1
	8004070321# 8004070378 8004080031 8004080036# 8004080217	71-380 TOPREP TOPREP	I R	Georgia Power Co	8004280486 8004280512 8004010112 8004010321 8004010321	50-160 50-160 50-321 50-321 50-321	8 8 0 R R
	8004080220# 8004080286 8004080289# 8004080308 8004080313#	50-183 50-18 50-18 50-73	R R R R		8004010326* 8004010326* 8004010349 8004010349 8004010474	50-321 50-321 50-424 50-424 50-321	R R 8 8
	8004080348 8004080357* 8004080695* 8004090057*	50-70 50-70 ACRS GA999	R		8004010477* 8004020187 8004020315 8004020317* 8004020325	50-321 50-424 50-366 50-366 50-366	8 8 8
	8004070072# 8004070476# 8004100061 8004100082	PT21 PR	Р		8004020330# 8004020335 8004020335 8004020340#	50-366 50-424 50-424 50-424	888
	8004100423 8004140116*	70-754 TOPREP			8004020340*	50-424	В
	8004150043	RES			8004020343 8004020347*	50-346 50-366	B B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004020354 8004020359# 8004020361 8004020365# 8004020390	50-321 50-321 50-366 50-366 50-424	ទ ១ ១ ១ ១ ១		8004280447* 8004280452 8004280452 8004280491 8004280491	50-366 S 50-321 Q 50-321 Q 50-424 S 50-424 S
	8004020390 8004020428 8004020437* 8004030227 8004040416	50-424 50-366 50-366 50-321 50-321	5 5 9 5		8004280531 8004280566* 8004280570 8004280582 8004280589*	50-366 S 50-321 S 50-321 S 50-321 S
	8004040420 8004040426* 8004040429 8004040438* 8004070198	50-424 50-321 50-366 50-366 50-424	0 5 5 6	Georgia, State of Geotechnical Engineers.Inc Gerlach,F T Getty Oil Co , Petrotomics Co Div	8004110129 8004200239 8004220002 8004070144 8004070155*	PR WASTE MOT FDIA 40-6659 40-6659
	8004070281 8004070283* 8004070314 8004070324* 8004070035*	50-321 50-321 50-366 50-366 50-321	5 5 5 5 G	Gibson, Dunn & Crutcher Gilbert/Commonwealth Cos	8004070159* 8004070164* 8004070169* 8004090208 8004070343*	40~6659 40~6659 40~6659 PROJ 50~320 R
	8004100348 8004110472	50-424 50-366	9 5	Gorsuch, Kirgis, Campbell, Walker &	8004090484* 8004300297	50-320 1 WASTE MOT
	8004110476* 8004110479 8004110483*	50-366 50-366	S S	Graver Government Services, Inc Graham, R. L.	8004240526# 8004230091 8004230101#	50-346 F 50-367 G 50-367 G
	8004110565 8004110565 8004140336	50-321 50-321 50-424	g o A	Grass Roots Organizing Workshop Gulf Dil Corp , Gulf Mineral Resources	8004070002 8004070246	FOIA WASTE MGT
	8004150072* 8004150136* 8004150198	50-321 50-321 50-321	a a	Co Gulf States Utilities Co	B004090115 B004010018 B00401001B	WASTE MGT 50-458 G 50-458 G
	8004150178 8004150358 8004150383 8004150385*	50-321 50-321 50-366 50-366	G P R R		B004010023 B004010023 B004010041 B004010041 8004040056	50-458 Q 50-458 Q 50-458 Q 50-458 Q 50-458 S
	8004150390* 8004150393 8004150399 8004150404*	50-321 50-366 50-321 50-321	R R R		8004040104 8004040335 8004040363 8004040370	50-458 G 50-458 A 50-458 A 50-458 A
	8004150410 8004150421 8004150425 8004150427 8004150427	50-366 50-425 50-366 50-424 50-424	9 9 9 9 8		8004040378 8004180102 8004210182 8004210182 8004210185*	50-458 A 50-458 I 50-458 I 50-458 I
	8004150451 8004150454 8004150455* 8004150460*	50-366 50-366 50-366 50-366	8 8 8		8004210185* 8004280539	50-458 R
	8004150476 8004150481*	50-366 50-366	8 6	HEW.Dept of, Food & Drug Administration Hanford Engineering Development	8004280543* 8004220028* 8004220477 8004110048	50-459 R F01A 50-320 P NUREO
	8004150562 8004150572# 8004170298 8004170298	50-366 50-366 50-321 50-321	5 0 0	Laboratory Hanse, Holley & Briggs, Inc Harnage,H H	8004040070* 8004080239 8004080239	50-344 T 50-250 G 50-250 G
	8004220615 8004220617# 8004220628	50-346 50-346 50-346	\$ 8 8		80042400B6 80042400B6	50-250 G 50-250 G
	8004220636* 8004220652 8004220659*	50-344 50-344 50-344	8 5	Hartford Electric Light Co Hartford Insurance Group Helix Technology Corp , Process Systems	B0040B05B1* B0041B0325* B0040B0115* B0041B0310*	50-245 I 50-245 I FOIA XPORTLIC
	8004220664 8004220664	50-366 50-366	8 8	Div	8004180314*	XPORTL1C
	8004220667* 8004220671* 8004220675 8004220684*	50-366 50-366 50-321 50-321	5 8 9	Hill & Knowlton, Inc Hill Christopher & Phillips Hittman Corp	8004170117± 8004090033 8004220043	COMM188ION 50-275 G 71-379
	8004220689 8004220705 8004220706	50-321 50-364 50-366	9 8 6 5	Hittman Nuclear & Development Corp (subs Hittman Corp)	B004220055* B004090234	71-979 71-24
	8004220710* 8004220713 8004220717*	50-321 50-321 50-366	8 8	Hodder,M H Homestake Mining Co	8004220274 8004020237* 8004020272* 8004090135	71-6574 50-387 0 50-387 0 Waste Mot
	8004220718* 8004220721*	50-366 50-321	8 S		8004300297	WARTE MOT
	8004220726 8004220728 8004220735* 8004220735*	50-366 50-366 50-366 50-366	8 9 8	Housatonic Bafe Energy Alliance House of Rep	8004220754 8004220762* 8004030013 8004040243 8004080164*	50-3 G 50-3 G 50-275 U FRM 50-142 U
	8004230467 8004230467 8004240344 8004280416 8004280419* 8004280441	50-321 50-321 50-424 50-366 50-366 50-366	0 0 8 8 8		8004080218# 8004140262# 8004140304# 8004180220# 8004210154	50-387 U 50-358 U 50-309 U COMMISSION PR

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
House of Rep , Appropriations House of Rep , Education & Labor	B004220359* B004290146 B004290175 B004140215* B0041401B0*	FOIA 50-275 U 50-556 H 50-10 U 50-10 U		8004140415 8004170312 8004180167* 8004180167* 8004180384	50-445 M 50-445 M 50-445 M 50-445 M 50-478 B
House of Rep , Foreign Affairs House of Rep , Interior & Insular Affairs House of Rep , Merchant Marine & Fisheries	8004140197* 8004300299* 8004080063* 8004080066* 8004080280*	50-10 V 50-3 V 8018510N 8018510N 50-320 U		8004180421 8004180423 8004210147 8004210392* 8004210392*	50-498 S 50-498 S 50-445 M 50-445 M
House of Rep , Science & Technology	8004030343 8004090440 8004100449 8004140025 8004180319*	PR PR PR PR COMMISSION		8004210392* 8004210392* 8004210400* 8004210400* 8004210400*	50-445 M 50-445 M 50-445 M 50-445 M
Houston Lighting & Power Co	8004010126 8004010242 8004010332 8004010332 8004010377	50-498 0 50-464 A 50-498 S 50-498 S 50-498 A		8004210400* 8004220003 8004220743 8004220743 8004220749*	50-445 M 50-466 G 50-498 K 50-498 K 50-498 K
	8004020119* 8004020119* 8004020119* 8004020119* 8004020136	50-445 M 50-445 M 50-445 M 50-445 M 50-479 0		8004220769* 8004230022 8004230074* 8004230074* 8004230074*	50-478 K 50-466 0 50-445 M 50-445 M 50-445 H
	8004020208 8004020232 8004040184 8004040184	50-445 M 50-466 G 50-445 M 50-445 M		8004230074* 8004230154 8004230154 8004230154 8004230154	50-445 M 50-445 M 50-445 M 50-445 M
	8004040240 8004040240 8004040390 8004040390 8004040394	50-478 A 50-478 A 50-478 9 50-478 9 50-478 9		8004240061 8004240061 8004240061 8004240188 8004240538	50-445 H 50-445 H 50-445 M 50-466 O 50-466 O
	8004040394 8004040409* 8004040409* 8004070060* 8004070062	50-498 S 50-498 S 50-498 G 50-498 Q 50-498 Q	Hunton & Hilliams ITT General Controls, Division of Intl Tel & Tel Corp	8004270378 8004300523* 8004080672 8004250381 8004080521*	50-49B B 50-49B G 50-33B G 50-33B G 50-387 B
	8004080073 8004080073 8004080073 8004080073 8004080273	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	Idaho, State of Idaho, Univ of Illinois Power Co	8004110544 8004110143 8004010249 8004010249 8004010328	State Prop PRM 50-461 A 50-461 A 50-461 F
	8004080273 8004080273 8004080273 8004080285* 8004080285*	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M		8004010328 8004140107 8004140107 8004150170 8004150170	50-461 F 50-461 Q 50-461 Q 50-461 Q
	8004080285* 8004080370 8004080687 8004100078 8004100271	50-445 M 50-445 M 90-466 C 50-466 G 90-445 M	Illimois Safe Energy Alliance Illimois, State of	B004140456 B004020273* B004030302 B0040B0181 B004140125	50-10 U 40-2061 FOIA 40-2061 50-367 Q
	8004100271 8004100271 8004100271 8004100274 8004100274	50-445 M 50-445 M 50-445 M 50-498 G 50-498 G	Illinois, State of, Dept of Public	8004140130* 8004150461 8004230307* 8004250394* 8004170341	50-367 0 50-367 P NUREO 50-10 H NUREG
	8004100278* 8004100278* 8004100278* 8004100278* 8004100532	50-445 M 50-445 M 50-445 M 50-445 M 50-466 Q	Health Indiana & Michigan Electric Co.	8004010325 8004010325 8004010420 8004010420 8004010476	50-315 P 50-315 P 50-315 P 50-315 P 50-314 B
	8004100552 8004100552 8004100552 8004100552 8004100557	50-445 M 50-445 M 50-445 M 50-445 M 50-466 Q		8004010481* 8004010486 8004010486 8004010493 8004010500*	50-316 B 50-315 F 50-315 F 50-316 B 50-316 B
	8004100540* 8004100540* 8004100540* 8004100540* 8004140003	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M		8004030204 8004070411 8004080304 8004080304 8004080347	50-315 P 50-315 Q 50-315 R 50-315 R 50-316 P
	B004140003 B004140003 B004140003 B004140008* B004140008*	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M		8004080510 8004080520 8004080529* 8004080534 8004080534	50-316 B 50-316 P 50-316 B 50-315 P 50-315 P
	8004140008* 8004140008* 8004140107	50-445 M 50-445 M 50-478 Q 50-478 Q		8004080544 8004080544 8004080545*	50-315 F 50-315 F 50-314 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	tΥ		AUTHOR AFFILIATION		NOI88333A RAEMUN	CATEOD	
	8004110445 8004110445 8004110449* 8004110449* 8004140324	50-315 50-315 50-315 50-315 50-315	R R R J				8004100278* 8004100310 8004100322 8004100451 8004100455*	50-155 50-255 50-454 50-155 50-155	00000
	8004140324 8004140438 8004140444* 8004150363 8004150365*	50-315 50-315 50-315 50-316 50-316	9 8 8 8				8004100570 8004110030 8004160161 8004210401 8004210420	50-155 50-445 50-556 50-155 50-155	0 10 0 0
	8004150368 8004150371* 8004150507 8004150507 8004150509	50-315 50-315 50-315 50-315 50-315	R R F P				8004220128 8004220334 8004230002 8004250372 8004280015	50-445 50-556 50-445 50-556 50-155	M Q M Q F
	8004150509 8004150510* 8004150510* 8004180181* 8004210415	50-315 50-315 50-315 50-315 50-315	P F G P	Isomedix. Enterpris	Island Closeup News Service Isomedix, Inc (subs of Maesfield Enterprises, Inc.)	8004270087 8004270164 8004070220	FOIA FOIA 71-9		
	8004230351 8004230355* 6004230357* 8004230430 6004230432*	50-314 50-314 50-316 50-316 50-316	5 5 8	Israel JH Klwir Jack R Be Japan	roducts Laboratories ifelder & Associates mjamin & Associates itral Power & Light	i . Inc	80041701B3 8004110117 8004100023* 8004040153* 8004070026 8004010480	XPORTLIC XPORTLIC CONTRACT 50-70 XPORTLIC 50-219	; T P B
	6004230438 6004230444* 6004230447* 6004260398 6004280398	50-315 50-315 50-315 50-315 50-315	0 9 9				8004010485* 8004010503 8004010509* 8004020004 8004020319	50-219 50-219 50-219 50-363 50-219	8 8 8 Q P
Indiana & Michigan Power Co Industrial Dynamics	8004290417 8004300611 8004300611 8004230369 7905190090	50-315 50-315 50-315 50-315 MIBC	S Q F				8004020320* 8004020383* 8004020386* 8004040284 8004040288*	50-219 50-219 50-219 50-219 50-219 50-219	P R R S S S
Interior,Dept of Interior,Dept of, Bureau of Land Management Interior,Dept of, Fish & Wildlife Service Interior,Dept of, Geological Survey	8004010104 8004070238 8004270070 8004030003* 8004010106*	27-39 40-4492 40-1341 40-8745 27-39					8004090246* 8004090329 8004090330* 8004090482* 8004100352	50-217 50-217 50-217 50-217 50-320 50-217	Q P P 1
international Business Services. Inc International Verbatim Reporters. Inc Iowa Electric Light & Power Co	8004020283 8004280218 8004080241* 8004040235 8004030160	50-275 PR CUNTRACT 50-320 50-331	A T R				8004100355* 8004100424 8004110422 8004160276 8004220508	50-219 50-219 50-219 50-219 50-219	1 0 0 P
	8004030161* 8004040400 8004040413* 8004070252 8004070256*	50-331 50-331 50-331 50-331 50-331	R 6 8 R R				8004220511* 8004220514* 8004230341 8004240425 8004240432*	50-219 50-219 50-219 50-219 50-219	P P R R
	8004080531# 8004080531# 8004080605 8004090447 8004140363	50-331 50-331 50-331 50-331 50-331	8 8 9 9	(subs UF John F Ho	iume & Associates, E RB Corp) Diman & Co , Inc Ontrois, Inc	Engineers	8004280513 8004070374* 8004100342* 8004080262*	50-219 50-255 CONTRACT GA999	P
	8004140367* 8004140380 8004140382* 8004140450 8004140452*	50-331 50-331 50-331 50-331 50-331	8 P 9 9	Jones, Bro Justice, De					
	8004150340 8004160005 8004220268 8004220385 8004220387*	50-331 50-331 50-331 50-331	8 F R						
	8004220507 8004230346 8004230348* 8004280454 8004280461	50-931 50-931 50-931 50-931 50-931	P R R F P						
lowa, State of Isham, Lincoln & Beale	800403013B 8004220519 800402027B 8004080153 8004080180	PR 50-331 50-155 50-445 50-155	P 0 M 0						
	8004080186# 8004080191 8004080360 8004080428 8004090387	50-155 50-155 50-445 50-454 50-445	9 9 M 9 M						
	8004090387 8004090411 8004100293 8004100296*	50-445 50-454 50-155 50-155	M G O						

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEGOR	Υ
	8004080033+ 8004080033+ 8004080033+ 8004080559 8004080559	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M		8004010347* 8004070308 8004070310* 8004150420 8004150424*	50-362 50-362 50-362 50-362 50-362	9 8 8 A
	8004080559 8004080559 8004090204 8004090204 8004090204	50-445 M 50-449 M 50-445 M 50-445 M 50-445 M	Lowenstein,Newman,Reis,Axelrad & Toll	8004280594 8004280405* 8004020092 8004020113 8004020113	50-382 50-382 50-367 50-445 50-445	8 9 M M
	8004090204 8004090475* 8004100084 8004100177 8004100218	50-445 M 50-293 M 50-445 M 50-445 M 50-445 M		8004020113 8004020113 8004020119* 8004020119* 8004020119*	50-445 50-445 50-445 50-445 50-445	H H H
	8004110056 8004110056 8004110056 8004110056 8004110137*	50-445 M 50-445 M 50-445 M 50-443 M 50-482 M		8004020134 8004020235 8004020232 8004020265* 8004020280	50-49B 50-344 50-466 50-389 50-367	0 0
Justice, Bept of, Attorney General's	8004170340 8004210437 8004210447 8004250375 8004030207	50-445 M 50-445 M 70-1308 50-514 G 50-482 M		8004040053 8004040198* 8004040198* 8004040198* 8004040198*	50-367 50-445 50-445 50-445 50-445	0 Н Н
Office K F Industries, Inc KMG, Inc	8004140104+ 7908210253+ 7907250258 8004250071	50-443 M 50-320 H MISC PR		8004080073 8004080073 8004080073 8004080273 8004080273	50-445 50-445 50-445 50-445 50-445	# # #
Kansas Gas & Electric Co	8004010030 8004010034 8004040264 8004070292 8004170172	50-482 G 50-482 S 50-482 B 50-482 B 50-482 S		8004080273 8004080285* 8004080285* 8004080285* 8004080370	50-445 50-445 50-445 50-445 50-445	H H H H
Kansas, Univ of Kay-Ray, Inc	8004220747* 8004220747* 8004220759* 8004240051* 8004080332	50-462 I 50-462 I 50-462 I CONTRACT XPORTLIC		8004070437 8004070437 8004070437 8004070437 8004100271	50-445 50-445 50-445 50-445 50-445	н н н
Kerr-McGee Corp Kerr-McGee Nuclear Corp	8004070151 8004080163* 8004180061 8004210348 8004080158	40-2061 40-2061 40-2061 40-2061 40-2061		8004100271 8004100271 8004100278* 8004100278* 8004100278*	50~445 50~445 50~445 50~445 50~445	Н Н Н
Kriemlmeyer,H LaMacchia, P J Lake Michigan Federation Lakeside Bridge & Steel Co Laudig, B	8004070277* 8004270113* 8004230028 8004030237* 8004150217	50-320 H CONTRACT 50-367 G GA999 FOIA		8004110529 8004140003 8004140003 8004140003 8004140008*	50-250 50-445 50-445 50-445 50-445	о н н
Lawrence Livermore Laboratory LeBoeuf, Lamb, Leiby & MacRae	8004030002 8004240465 8004250066 8004280059 8004010060	NUREO REB TOPREP REB FOIA		8004140008* 8004140008* 8004140111 8004140111	50-445 50-445 50-445 50-445 50-445	H H H
League of Women Voters of Rockford.IL	8004110480 8004150329 8004220464 8004250052 8004020033	PR 50-244 P 50-220 P NUREG 50-454 0		8004210147 8004210384 8004210386 8004210386 8004210386	50-445 50-445 50-445 50-445 50-445	H H H
	8004020033 8004080435* 8004080435* 8004070177 8004070177	50-454		8004210372* 8004210372* 8004210372* 8004210377* 8004210400*	50-445 50-445 50-445 50-445 50-445	н н н
League of Homen Voters of San Luis Obispo.CA Loed.R M	E004140419	PR PR		8004210400* 8004210400* 8004220003	50-445 50-445 50-466	H O
Leesburg.FL Lehigh Univ Lockheed Center for Marine Research Logical Technical Service Corp	8004180491* 8004040027 8004070352* 8004100194*	50-302 I RES 50-206 R CONTRACT		8004220141 8004230022 8004230066	50-387 50-466 50-445	0 H
Long Island Lighting Co	E004040314 E004070117# E004090004	50-322 A 50-322 Q 50-322 Q		8004230066 8004230066 8004230066 8004230074*	50-445 50-445 50-445 50-445	н н н
Los Alamos Scientific Laboratory	8004140439 8004220036 8004220620 8004080007 8004150140	50-322 A 50-516 Q 50-322 A 71-9029 NUREO		8004230074* 8004230074* 8004230105 8004240188 8004240194	50-445 50-445 50-367 50-466 PRM	11 0 0
Louisiana Power & Light Co	8004150141* 8004240475 8004270001 8004270520 8004010343	NUREO RES NUREO WASTE MOT 50-382 8	Lower Alloways Greek, NJ Luzerne County,PA	8004240484 8004250104 8004100466 8004100583 8004140096	50~250 50~445 50~311 50~311 PR	0 0 0

AUTHOR AFFIL IATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFF1LIATION	ACCESSION NUMBER	SUBJECT CATEGORY
MHB Technical Associates Maine Voice of Energy Maine Yankee Atomic Power Co	8004140100* 8004210393* 8004080653* 8004020016 8004020345	PR 50-275 G 50-309 H 50-309 Q 50-213 P		6004040336 8004040344 8004040344* 8004040347*	50-320 S 50-320 S 50-320 S 50-320 S 50-320 S
	8004080263 8004080339 8004080351 8004080406 8004080411*	50-309 0 50-309 H 50-309 0 50-309 R 50-309 R		8004040349* 8004070219 8004070219 8004070284 8004070285*	50-320 S 50-320 G 50-320 G 50-289 P 50-289 P
	8004080634 8004090458 8004100406 8004100422 8004140154	50-309 P 50-309 Q 50-309 Q 50-309 Q 50-309 R		8004070290 8004070291* 8004070301 8004070306* 8004070318	50-289 P 50-289 P 50-320 P 50-289 P 50-320 P
	8004140157* 8004140308 8004150290 8004150367 8004150370#	50-309 R 50-309 P 50-309 I 50-309 R 50-309 R		8004070318 8004070319 8004070323* 8004070325* 8004070335	50-320 P 50-289 P 50-289 P 50-289 P 50-320 R
	8004180438 8004180489 8004180492* 8004210044* 8004210277	50-309 P 50-309 S 50-309 S 50-309 Q 50-309 S		8004070335 8004070339* 8004070416* 8004070420* 8004080200*	50-320 R 50-320 R 50-289 0 50-289 G 50-289 G
	8004210278* 8004220522 8004220530* 8004230005 8004280562	50-309 S 50-309 P 50-309 P 50-309 Q 50-309 R		8004080425 8004080560 8004080703 8004080707* 8004080716*	50-289 G 50-289 P 50-289 P 50-289 P 50-289 P
Maine, State of Marchand Construction, Inc Marina Biological Consultants, Inc ,	8004080674 8004280564* 8004290514* 8004020458* 8004070348*	PR 50-309 R CONTRACT 50-320 H 50-206 R		8004090720 8004070013 8004070076 8004070283* 8004070285*	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0
Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div	8004010323 8004080281 8004080485 8004140346 8004140442	50-18 J 50-250 J 50-348 J 50-346 J 50-327 J		8004070482* 8004070482* 8004070482* 8004100010 8004100015*	50-320 I 50-320 I 50-320 I 50-289 G
Marvin Engineering Go , Inc Maryland, State of	8004280447 8004270176* 8004270186* 8004020176* 8004040375	50-250 J GA979 GA979 State Prog 50-320 P		8004100285* 8004100308 8004100350 8004100350 8004100435	50-289 G 50-289 G 50-320 F 50-320 F 50-289 G
Maryland, Univ of Massachusetts Institute of Technology	8004100079 7908020467 8004020050 8004010415 8004010422#	PR 50-146 H 50-146 H REB RCB		8004100436# 8004100437# 8004100479 8004100549 8004100566	50-287 G 50-287 G 50-289 G 50-289 G
Matheson Oas Products Matthews, Nowlin, Macfarlane & Barrett	8004250043* 8004210426 8004070421 8004100442 8004100442	CONTRACT XPGRTL1C 50-490 M 50-498 M 50-498 M		8004110029 8004110081* 800 800 600	50-289 G 50-289 G
Mayer, Brown & Platt	8004100444* 8004100444* 8004100447* 8004100447* 8004140060	50-498 M 50-498 M 50-498 M 50-498 M 70-1308		ſ	
McCutchen, Doyle, Brown & Emerson McGrath, E. J	8004140078 8004280305 8004080012 8004080132 8004300215	70-1308 70-1308 PROJ PROJ WASTE MOT			
Metal Bellows Corp Methodist Medical Center of Illinois	8004180089 8004180089* 8004180092* 8004220616*	XPORTLIC XPORTLIC XPORTLIC FOIA			
Peoria, IL. Metropolitan Edison Co	8004010338	50-289 S			
	8004010344 8004010412 8004020012 8004020056 8004020202	50-320 P 50-289 P 50-320 B 50-287 Q 50-287 Q			
	8004030241 1450E04008 1650404008 40E0404008 11E0404008	50-320 I 50-320 I 50-320 P 50-320 P 50-320 P			
	8004040321 8004040325 8004040330	50-320 P 50-320 P 50-320 P			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEQURY
	8004150436 8004150446 8004150446 8004150478 8004150479	50-320 P 50-320 P 50-320 P 50-320 H 50-320 G	Mississippi Power & Light Co	8004090254 8004090341 8004090341 8004090345* 8004090345*	REGGD 50-416 A 50-416 A 50-416 A 50-416 A
	8004150499 8004160179 8004160184* 8004160290 8004160298*	50-320 G 50-320 P 50-320 P 50-320 P 50-320 P		8004100362 8004100437 8004100541 8004150200* 8004150200*	50-416 H PR REGOD 50-416 M 90-416 M
	8004170023 8004170039 8004170048 8004170104 8004170106*	50-320 P 50-320 P 50-320 P 50-287 P 50-289 P		8004190568 8004190568 8004170071 8004170071 8004170074*	50-414 8 50-414 8 50-416 8 50-416 8
	8004170281* 8004180338 8004180339* 8004180473 8004210085	50-287		8004170074* 8004170243 8004170243 8004210228 8004220289	50-416 B 50-416 A 50-416 A 50-416 C
	8004210250* 8004210421 8004220008 8004220102 8004220223	50-289 0 50-289 0 50-320 0 50-320 0 50-289 P		8004220293* 8004220293* 8004220421 8004220421	50-416 C 50-416 C 50-416 C 50-416 C
	8004220224* 8004220393 8004220405 8004220542 8004220545*	50-289 P 50-320 Q 50-320 Q 50-289 P 50-289 P		8004230070 8004230322 8004230322 8004280365 8004280365	50-416 0 50-416 0 50-416 K 50-416 K
	8004220552* 8004220654 8004230001 8004230030 8004230406	50-289 P 50-289 P 50-289 0 50-289 G 50-289 S		8004280371* 8004280381* 8004280381* 8004280481	50-416 K 50-416 K 50-416 B 50-416 S
	8004230411* 8004230493 8004230493* 8004240379 8004250356	50~287 \$ 50~289 R 50~289 R 50~320 P 30~320 P		8004280484 8004280484 8004280479 8004280479 8004280501	50-416 8 50-416 8 50-416 8 50-416 8
	8004250360 8004250367 8004250377 8004250389* 8004250433	50-320 Q 50-289 P 50-320 S 50-320 S		8004280501 8004280517 8004280517 8004280520 8004280520	50~416 8 50~416 8 50~416 8 50~416 8
	8004280630 8004280633* 8004280633* 8004290510 8004300409	50-320 I 50-320 I 50-320 I 50-320 S 50-320 F		8004280522* 8004280522* 8004280541 8004280541 8004280606	50-416 8 50-416 8 50-416 8 50-416 8
Miami Valley Power Project Miami, FL, Univ of Michigan State Univ	8004300586* 8004090157 8004020239* 8004020272* 8004010227	50-289 Q 50-358 H 50-389 Q 50-389 Q 50-294 P		8004280606 8004280610 8004280610 8004280618*	50-416 8 50-416 8 50-416 8 50-416 8
Michigan. State of	8004010227# 8004160037# 8004240477# 8004020237# 8004070368#	50-274 P 50-320 P 50-320 P State Prog 50-416 M	Missouri, Univ of, Columbia Missouri, Univ of, Rolla Mitsui & Co , Ltd Mobile Systems Monsanto Research Corp	8004300505 8004270085* 8004180242 8004030014* 8004030384	70-754 50-123 Q XPORTL1C CQNTRACT 71-9142
Hichigan, Univ of	8004150531 * 7704110103 8004030300 8004040385 8004040389*	50-315 P 50-2 P ACRS 50-2 P 50-2 P	Montana, Univ of Morgan, Lewis & Bockius Murphy & Parish NL, Industries, Inc	8004030359* 8004030307 8004070303 8004100471 8004080148#	71-9142 FOIA 50-407 P 50-352 H FOIA
Middle South Utilities.Inc Mike Ausr Construction Co Miller.Balis & O'Neil	8004220535 8004020276* 8004240043 8004240043 8004240043	50-313 1 40-2061 50-445 M 50-445 M 50-445 M	NL Industries, NL Nuclear Div	8004080069 8004140010 8004220225 8004280166 8004070347*	XPORTLIC XPORTLIC 71-9010 71-9010 50-320 R
	8004240045 8004240045 8004240045 8004240045 8004240053	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	NUBAG, Inc National Wildlife Federation Natural Resources Defense Council	8004100465* 8004090485* 8004020053 8004070181 8004100299	50-155 Q CONTRACT 40-4492 40-4492 70-143
Minnesota, State of	8004240053 8004240053 8004070156 8004210160# 8004230088	90-445 M 50-445 M PR PR 50-202 G	Navy, Dept of	8004150101 8004210352 8004290184 8004150278* 8004150284*	50-574 0 70-143 FOIA 71-49 71-49
Minnesota, Univ of, Minneapolis	8004230088 8004230100 8004230100 8004080713 8004100343*	20-585 C 20-585 C 20-585 C 20-585 C	Navy,Dept of, Navel Nuclear Power Unit	8004210357* 8004300082 8004150099 8004150102* 8004150108*	70-143 71-9043 71-273 71-273 71-273

AUTHOR AFFILTATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004150112 8004150117* 8004150121* 8004150123 8004150125*	71-367 71-367 71-367 71-316 71-116	Nissho-Iwai American Corp Nondestructive Inspection Service	8004300270# 8004240170# 8004240202# 8004150132 8004150133#	50-410 0 70-2805 70-2805 71-97 71-97
	8004150127* 8004150272 8004240314 8004240322* 8004240331*	71-116 71-49 71-107 71-107 71-107	North Carolina State Univ	8004220558 8004220560* 8004220565* 8004140455 8004150171*	50-111 R 50-111 R 50-111 R NUREO CONTRACT
Navy,Dept of: Naval Research Laboratory Nebraska Public Power District	8004290009 8004010454 8004010457* 8004040396	NUREG 50-298 R 50-298 R 50-298 R	Northcutt Ely Northeast Nuclear Energy Co (subs of Northeast Utilities)	8004080018 8004090427 8004020331	50-445 M 50-445 M 50-245 P
	#40E07090B	50-298 R 50-298 R		B004030232 B004030270*	50-336 P 50-336 P
	8004140479 8004230192 8004230457 8004250077	50-278		8004100408* 8004110457 8004110443* 8004140375 8004150409*	50-423 S 50-245 P 50-245 P 50-245 Q 50-245 I
	8004250240 8004250391 8004280184 8004280186* 8004280574	REGOD 50-278 F 50-278 Q 50-278 G 50-278 B		8004160254 8004160254 8004160254 8004170012 8004170012	50-245 J 50-245 J 50-245 J 50-213 P 50-213 P
Nebraska, Stato of	B004280579* B004110127 B004230417	50-278 B REGOD NUREG		80041803B3 80041803B8*	50-245 R 50-245 R
Neutron Products, Inc	8004090119 8004090121*	71-121 71-121		8004180398 8004180404* 8004220364	50-336 S 50-336 S 50-336 P
Nevada, State of New England Medical Center Boston, MA New Hampshire, State of	8004080459 8004240077 8004240081* 8004080213* 8004070187	PR State Prog State Prog 70-2254 PR		8004220411 8004220413* 8004220670 8004220679* 8004230413	50-336 R 50-336 R 50-336 S 50-336 S 50-336 S
	8004070202* 8004100604 8004100607* 8004100612* 8004170284	PR PR PR PR PR		8004240373 8004250362 8004250362 8004280525 8004290057 8004290651	50-245 P 50-245 P 50-336 S 50-245 Q 50-245 P
New Jersey, State of	8004080633 8004070005 8004070008* 8004140108 8004140147	50-272 0 50-272 0 50-272 0 PR PR	Northeast Utilities	8004010407 8004010417# 8004010423 8004010429# 8004020408	50-336 S 50-336 S 50-336 S 50-336 S 50-336 S
New Hexico, State of	8004210140 8004020159 8004020182 8004020196 8004070240	PR WASTE MOT WASTE MOT WASTE MOT WASTE MOT		800402040B 800402040B 8004030215 8004030261 8004030273	50-213 F 50-213 F 50-245 P 50-219 Q 50-213 P
New York Univ New York, State Univ of, Buffalo New York, State of	8004180298* 8004010007* 7905170094 8004020144* 8004080152	COMMISSION CONTRACT 90-37 P ACRS PR		8004040205 8004040204* 8004040204* 8004040204*	50-245 R 50-245 R 50-245 R 50-245 R 50-336 P
New York,NY	8004100083 8004100443 8004100448 8004230190* 8004070098*	PR PR 50-244 F 50-3 H 50-3 P		8004040254* 8004040304 8004070218* 8004070265	50-334 P 50-245 P 50-245 Q 50-213 P 50-213 P
Niagara Kohawk Power Corp	8004210093# 8004010330 8004010373 8004010392 8004040404	50-3 H 50-220 P 50-220 Q 50-220 Q 50-220 R		8004090309 8004090557 8004090308 8004090311*	50-334 P 50-245 I 50-334 S 50-334 S 50-334 Q
	8004070269 8004080415 8004080642 8004090239 8004090309	50-220 F 50-220 Q 50-220 Q 50-220 Q PR		8004100417 8004140127 8004150320 8004150320 8004150379	50-336 Q 50-245 Q 50-245 I 50-245 I 50-213 J
	8004100401 8004110055 8004140406 8004140411* 8004180345	50-220 Q 50-220 Q 50-220 R 50-220 R 50-220 F		8004170174 8004170197* 8004170224 8004170226* 8004180408	50-334 8 50-334 S 50-334 S 50-334 S 50-334 S
	8004180349* 8004210407 8004220501* 8004220506* 8004220559	50-220 F 50-220 P 50-220 P 50-220 P 50-410 S		8004180411* 8004180437 8004180440* 8004210246 8004210249*	50-334 8 50-245 8 50-245 8 50-245 R 50-245 R
	8004220577* 8004250417 8004280376 8004280440 8004270363	50-410 B 50-410 A 50-410 H 50-220 H 50-220 H	Northeast Utilities Service Co	8004280530* 8004290299 8004290303* 8004020418*	50-336 S 50-245 S 50-245 S 50-213 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJ	GORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE(CATEQ(
	8004020418* 8004020418* 8004150327 8004150327 8004150493*	50-21:	3 F 3 F 5 R 5 R	Nuclear Energy Service, Inc Nuclear Fuel Services, Inc (subs of Getty Oil Co)	8004080117* 8004090376* 8004040041*	50-409 70-143	p
Northern Illinois Univ Northern Indiana Public Service Co	8904280366* 8004020092 8004040053 8004080331 8004150453	50-10 50-367 50-367 50-367 50-367	H 7 O 7 G 7 R		8004070422 8004070235* 8004070237* 8004100219* 8004140024	70-143 70-143 70-143	a
Northern States Power Co	8004220553 8004280494 8004300431 8004010151 8004010452	50-367 50-367 50-367 50-306 50-263	7 R 5 G		8004140027* 8004150062 8004150071* 8004180076 8004180143		R R P
	8004010455 • 8004040319 8004040456 8004070058 8004070058	50~263 50~263 50~262 50~262 50~282	9 2 G 2 G		8004180213 8004180482 8004210178 8004220081 8004220133	70-143 70-143 70-143 70-143 70-143	
	8004070210 8004070210 8004080225 8004080368 8004080373	50-282 50-282 50-263 50-263	Q F F		8004220217 8004230053 8004230060* 8004300003 8004300024*	70-143 50-201 50-201 70-143 70-143	R R
	8004080400 8004080478 8004080479 8004080484*	50-263 50-263 50-263	8 F 8	Nuclear Medicine Associates,Inc Cleveland,DH Nuclear Packaging, Inc	8004300085 8004230032* 8004220184	70-143 FOIA 71-9130	
	8004080508 8004090223 8004100070* 8004140339 8004140339	50-263 50-263 50-282 50-282	F G R	Nuclear Pharmacy, Inc	8004220187* 8004220193* 8004090362 8004290173	71-9130 71-9130 FOIA FOIA	
	8004140344+ 8004140390 8004140431 8004140435	50-282 50-263 50-263 50-282	R S 8	Nuclear Services Corp Nuclear Systems, Qamma Industries Div Oak Ridge National Laboratory	8004280624* 8004280627* 8004020025 8004030291	50-255 50-255 71-9135 ACRB	F
	8004140437* 8004140440* 8004150339 8004150401	50-263 50-282 50-282 50-263	8		8004040369 8004070145 8004100398 8004100411 8004110466	REB REB REB TOPREP	
	8004150564 8004150555 8004150555	50-263 50-263 50-263	8 8 8		8004150029 8004150036 8004160088 8004160095	RES RES RES RCS	
	8004150571* B004150580* B004150587 B004150589*	50-243 50-263 50-263 50-263	8 8 8		8004170329 8004170334 8004230303* 8004240487 8004280024	NUREO NUREO NUREO REB NUREO	
	8004150603* 8004150610* 8004150617* 8004150623*	50-282 50-263 50-263 50-263	0 00 00 00 00	Ocean County, NJ Ogle Petroleum, Inc	8004280028 8004280048 8004110535 8004210444	NUREO NUREO PR PR	
	B004160013 B004170056 B004170056 B004170059* B004170059*	50-282 50-282 50-282 50-282 50-282	د د د	Ohio Edison Co Ohio State Univ	8004030001 8004240563 8004080499 8004080502#	40-8745 40-8745 50-334 50-334	1
	8004180296 8004180307* 8004180341 8004180342* 8004180342*	50-306 50-306 50-282 50-282	0 0 P	Oklahoma State Uhiv Oklahoma, State of Omaha Public Power District	8004080070* 8004230514 8004080080*	50-150 50-320 FOIA 50-556	I H
	8004180357 8004180360* 8004180380 8004180386*	50-282 50-263 50-263 50-306 50-306	# ### ################################		8004010346 8004140021 8004140362 8004150391	50-285 50-285 50-285	P Q P R
	BUUNTANA	50-263 50-263 50-282 50-282	8 8 8	Omnidine Corp Oncavage, Mark	8004220561 8004220086 8004250086 8004020179*	50-285 50-285 COMMISB 10 50-250	R P O O O
		50-282 50-282 50-282 50-282	a a a	Oregon, State of	8004080239 8004080550 8004240086 8004240086 8004290500	50-250 50-250 50-250 50-250 50-514	0 0 0 D
		50-262 50-304 CONTRACT XPORTLIC	Q	Orlando,FL Osann, E W PRC Systems Services Co	8004180474* 8004180478* 8004230091 8004230101*	50-302 50-302 50-367 50-367	1 1 0 0
		PR 71-6698 MISC		PSE & Q Research Corp PHR System DIV PA/PI Pacific Gas & Electric Co	8004240387* 8004080394* 8004270066 8004010436	50-275 50-272 50-518 50-275	F B A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC.	
	8004010437 8004010441* 8004010441* 8004030317 8004040058	50-275	A A A		8004070186 8004070478* 8004070479* 8004070480* 8004070481*	PR 50-320 50-320 50-320 50-320	1 1 1 1
	8004040065* 8004040068* 8004040131 8004040281 8004040281	PROJ 50-275 50-275	T 8 A A		80041400539 8004140074 8004140077* 8004140080* 8004140084*	50-289 50-289 50-289 50-289 50-289	0 0 0
	8004080012 8004080132 8004080443 8004080443 8004080447	50-275	A A P		8004140268 8004210453 8004270092 8004290095* 8004290101*	50-387 50-287 50-334 50-334 50-334	A Q T T
	8004080464 8004080481 8004080487* 8004100233 8004100233	50-275 50-133 50-133 50-133 50-133	A S S I	People Against Nuclear Energy Personnel Assessment & Selection Service.Inc Peterson, Ross & Schloerb & Seidel	8004160138* 8004280026 8004170139 8004090176	50-287 50-287 FOIA 50-320	0 0 P
	8004100233 8004100244* 8004150003 8004150337 8004150337	50-133 50-133 50-133 50-275 50-275	I I G A	Philadelphia Electric Co	8004070270 8004070270 8004070271 * 8004070271 * 8004070271 *	50-277 50-277 50-277 50-277 50-277 50-278	P R R R
	8004150343 8004150343 8004150435 8004150441* 8004160253	50-275 50-275 50-275 50-275 50-275	A A A A		8004080347 8004080347 8004080338 8004080538 8004080543	50-277 50-277 50-277 50-277 50-277	P P P
	8004140253 8004140254* 8004160259* 8004160260* 8004160244*	50-275 50-275 50-275 50-275 50-275	A A A		8004080543 8004080543 8004100211 8004100261 8004100421	50-277 50-277 50-277 50-171 50-352	р О О
	8004160267# 8004160271# 8004170076 8004170233 8004170236#	50-275 50-275 50-275 50-133 50-133	A A R R		8004140044 8004140273 8004140317 8004140317* 8004150246	50-277 50-277 50-352 50-352 50-277	0 P I I
	8004220406 8004220692 8004220697* 8004220697* 8004220704*	50-275 50-275 50-275 50-275 50-275	A A A	•	8004150250* 8004150247 8004150470 8004150470 8004150540	50-277 50-171 50-277 50-277 50-277	I I I I
	B004220704* B004220716* 8004220716* 8004220727* B004220727*	50-275 50-275 50-275 50-275 50-275	A A A		8004160187* 8004170228 8004170228 8004170230* 8004170230*	50-277 50-277 50-277 50-277 50-277	Q R R R
	8004220737* 8004220737* 8004220744* 8004220744* 8004220751*	50-275 50-275 50-275 50-275 50-275	A A A A		8004170246 8004170246 8004170252* 8004170252*	50-277 50-277 50-277 50-277	P P
	8004220751 * 8004220755 * 8004220755 * 8004240384 8004240384	50-275 50-275 50-275 50-275 50-275	۸ ۹ ۶ ۲				
Pen American Horld Airways: Inc Per Systems Corp	8004280373 8004180062 8004180067* 8004040141 8004040152*	50-275 71-96 71-96 XPORTLIC XPORTLIC					
Pathfinder Minus Corp Pennsylvania Power & Light Co	8004020291 8004270444 8004070382* 8004080363 8004080516	40-2259 40-6622 50-387 50-387 50-387	G 8 8				
	8004100078* 8004140352 8004210335 8004270374 8004270374	50-387 50-387 50-320 50-387 50-387	Q A P S S				
	8004290379* 8004270377* 8004300374 8004300374 8004300383*	50-387 50-387 50-387 50-387 50-387	\$ \$ \$ \$ \$ \$ \$				
Pennsylvania Fower Co Pennsylvania, State of	8004300383* 8004070297 8004070298* 8004010426 8004070015*	50-387 50-334 50-334 50-334 50-320	6 1 1 6				

AUTHÚR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGOR	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Pittsburgh, Univ of Plateau Resources, Ltd Poliution & Environmental Problems, Inc Pollution Environmental Problems	8004040386* 8004150074 8004280064 8004010171 8004150031	50-458 NUREQ 40-8698 FOIA 50-268	A P		8004180434* 8004180448 8004180461* 8004210061* 8004220445	50-284 50-286 50-286 50-286 50-333	8 8 9
Porter-Gert: Consultants, Inc	8004280590 8004140420 8004250395 8004010008 8004010334	50-295 50-320 50-320 50-344 50~344	G R R G P		8004220741 8004220749* 8004220767 8004220771* 8004220787	50-284 50-286 50-333 50-333 50-284	5 5 5 0
	8004020225 8004020409 8004030240 8004030243* 8004040043	50-344 50-344 50-344 50-344 50-344	G P P P		8004280552 8004280559# 8004270476 8004270482* 8004270504	50-333 50-333 50-333 50-333 50-333	9 9 9 9
	8004040073* 8004080388 8004080442 8004080446* B004080506	50-344 50-344 50-344 50-344 50-344	T P R R	Fower Reactor & Nuclear Fuel Development Corp	8004290511* 8004300041 8004300044* 8004020484	50-333 50-286 50-286 XPORTL I	
	8004080509* 8004080542 8004100273* 8004100457 8004150440	50-344 50-344 50-344 50-344 50-344	P Q Q P 8	President of US & Executive Offices	8004030335 8004070077* 8004140026* 8004140077* 6004140190*	50-327 50-155 50-339 50-339	H H H
	8004150442* 8004180359 8004180361 8004180362* 8004180364*	50~344 50~514 50~344 50~344 50~514	9 F P F	President's Comm for Study of Ethical Prob in Wed & Biome & Behav Research Princeton Univ Public Interest Law Center of Philadelph	8004210031* 8004300606* 8004100127* 8004170237	50-337 CDMMI651 50-3 50-320	H ION F P
	8004180366* 8004180466 8004180467*	50-344 50-344 50-344	P P	ia	8004250378 8004290289	50-320 50-320	P P
	8004180470* 8004220695 8004280296 8004290471	50-344 50-344 50-344 50-344	P P B	Public Law Utilities Group Public Service Co of Colorado	8004230466 8004010450 8004030130 8004030131* 8004030132*	50-458 50-247 50-247 50-247 50-247	M P G G
Potomac Alliance	B004290478* B004300380 B004300387 B004280211	50-344 50-344 50-344 50-338	8 P Q	•	8004030133* 8004030134* 8004030134* 8004070286	50-247 50-267 50-267 50-267	0 0 0
Pawer Authority of the State of New York	8004010259 8004010367 8004020219 8004030216 8004030218*	50-333 50-333 50-333 50-333	P P J S		9004080377 9004080422 8004080427* 8004080503	50-267 50-267 50-267 50-267	F 8888
	8004030247 8004030273 8004030278* 8004070296	50-286 50-333 50-333 50-333	9 8 8		8004080512* 8004150333 8004150336* 8004150338	50-267 50-267 50-267 50-267	R R R
	8004070300* 8004080124* 8004080266* 8004080328	50-333 FOIA 50-333 50-286	R G G		8004150432 8004150438* 8004150542 8004150552*	50-267 50-267 50-267 50-267	8 8
	8004080381 8004080419 8004080473 8004080632	50-286 50-333 50-333 50-286	Р О Р		80041505B2 8004150611* 8004150626 8004150634*	50-267 50-267 50-267 50-267	8 8 8
	8004070318 8004070318 8004070320* 8004070354	50-333 50-333 50-333 50-286	Q R R		8004210166* 8004210268 8004210271* 8004210294 8004210296*	50-267 50-267 50-267 50-267 50-267	Q R R B
	8004090436 8004090440# 8004090452	50~333 50~333 50~333	8		8004210354 8004220775 8004220778* 8004240323	50-247 50-267 50-267 50-267	G I I
	8004110437 8004110442* 8004140398 8004140416	50-286 50-286 50-333 50-286	8 8	Public Service Co of Indiana, Inc	800424032B* 8004240469 8004290390 8004080160	50-267 50-267 50-267 50-546	g Q A
	8004140422* 8004150364 8004150458 8004150508 8004170061	50-286 50-333 50-286 50-333 50-286	9 9 9 9		8004080168* 8004090146* 8004100291* 8004100291*	50-546 50-546 50-546 50-546	A G
	8004170064 8004180343 8004180350	50-333 50-284 50-284	P P		8004100371 8004110556* 8004110556*	50-546 50-546 50-546	9
	8004180389 8004180389 8004180389 8004180395#	50-247 50-247 50-247 50-247	P P P		8004180223 8004210131 8004290426 8004300348 8004300348	50-546 50-546 50-546 50-546 50-546	99444
	8004180395* 8004180395* 8004180426	50-247 50-247 50-286	P P R		8004300350* 8004300350*	50-546 50-546	A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT CATEGORY
Public Service Co of New Hampshire Public Service Co of Oklahoma Public Service Electric & Gas Co of New Jersey	8004070104# 8004070302# 8004160161 8004220334 8004010322	50-443 Q 50-443 I 50-556 G 50-556 Q 50-272 S		8004220092* 8004220107* 8004220212* 8004220286* 8004220346*	FOIA FOIA FOIA FOIA FOIA
	8004010331 8004010337* 8004010348* 8004010356 8004010370*	50-272 R 50-272 R 50-272 S 50-272 S 50-272 S		8004220444* 8004220448* 8004220458* 8004220461* 8004220463*	FOIA FOIA FOIA FOIA
	8004010438 8004010443 8004010447 8004010449 8004010453	50-311 A 50-311 A 50-311 Q 50-311 A 50-311 A		8004220528* 8004220532* 8004220539* 8004220548* 8004220542*	FOIA FOIA FOIA FOIA FOIA
	8004040282 8004040313 8004040317 8004040324* 8004070225	50-311 A 50-311 A 50-272 S 50-272 S 50-272 I		8004220567# 8004220573+ 8004220602* 8004220606# 8004220609#	A103 A103 A103 A103 A103
	8004070250 8004080114* 8004080318 8004080390 8004080525	50-311 A 50-354 S 50-272 Q 50-272 P 50-272 B		8004220612* 8004220625* 8004220629* 8004220635* 8004220644*	FOIA FOIA FOIA FOIA
	9004080533* 9004090317* 8004100157* 8004100247 8004100256	50-272 S 50-355 S 50-354 Q 50-272 Q 50-272 Q	Rochester Gas & Electric Corp	8004010355 8004090445 8004100461 8004110195 8004150331*	50-244 P 50-244 P 50-244 P 50-244 F 50-244 P
	8004100613* 8004110305 8004110426 8004110431 8004110468	50-311 8 50-311 A 50-311 A 50-311 A 50-311 A		8004150332* 8004150334* 8004150335* 8004150380 8004150384*	50-244 P 50-244 P 50-244 P 50-244 R 50-244 R
	8004110474 8004110475* 8004110492 8004110494* 8004110497	50-311 A 50-311 A 50-272 S 50-272 S 50-272 S		8004150434 8004150459 8004150502 8004180458 8004180471*	50-244 P 50-244 P 50-244 I 50-244 S 50-244 S
	8004110500* 8004140320 8004140323* 8004140407 8004140412*	50-272 0 50-272 5 50-272 6 50-272 6 50-272 8		8004220110 8004230003 8004230371 8004230372 8004230389	50-244 P 50-244 P 50-244 P 50-244 S 50-244 P
	8004150030* 8004150252* 8004150386 8004150387* 8004150467*	50-272 G 50-277 I 50-272 R 50-272 R 50-311 G	Rockland Mobilization for Survival	8004270378 8004270381* 8004300227* 8004300407 8004080206*	50-244 P 50-244 P 50-244 G 50-244 G
	8004150553 8004150558# 8004160246 8004160249 8004170060	50-272 8 50-272 8 50-272 0 50-272 0 50-272 P	Rockwell International Corp Rockwell Inte Bystems Div	BD040203B9 BD04040103	REGOD XPDRTLIC
	8004170062 8004230338 8004240365 8004240377 8004240494	50-272 P 50-311 P 50-311 F 50-211 F 50-272 0	Rocky Mountair		
	8004240494 8004250224 8004250366 8004250366 8004250393	50-272			
	8004280124* 8004280174* 8004280207 8004280225 8004290489	50-272 0 50-354 8 50-272 0 50-272 8 50-272 R			
Puget Sound Power & Light Co R F Denoncourt R W Beck & Associates	8004290497* 8004300488 8004030351 8004210366* 8004100357*	50-272 R 50-272 Q PR 50-320 P CONTRACT			
Reilly & Like Rensselaer Polytechnic Inst Resources Publishing Co Reuter-Stokes, Inc	8004100041 8004300320* 8004070016 8004100543 8004220210	PR 50-225 0 F01A REGGD REGGD			
Rhode Island, State of Riversida Methodist Hosp Columbus,OH	8004100494 8004160055 7911140251 8004220075#	PR PR Docket 30 FOIA			

AUTHOR AFFILTATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004210259 8004210262* 8004210314 8004220568 8004220709	50-312 S 50-312 S 50-312 P 50-312 P 50-312 P	Senate, Foreign Relations Committee Shaw, Pittman, Potts & Trowbridge	8004180016# 8004080323* 8004010519 8004020202 8004080195	COMMISSION COMMISSION 50-400 G 50-289 G 50-289 G
	8004220731 8004230498 8004280528 8004270338 8004270454	50-312 S 50-312 P 50-312 F 50-312 P 50-312 S		8004080200* 8004080425 8004080705 8004080720 8004090094	50-289 0 50-289 0 50-312 0 50-289 0
	8004270465* 8004270485 8004270491* 8004270524* 8004300421	50-312 S 50-312 S 50-312 S 50-312 P 50-312 S		8004070281 8004070289 8004070295* 8004100010 8004100015*	50-287 0 50-287 0 50-289 0 50-289 0 50-289 0
San Antonio, TX	8004300433* 8004070421 8004070421 8004100442 8004100442	50-312		B004100090 B004100277 B004100285* B004100308 B004100435	PR 50-287 G 50-289 G 50-289 G 50-289 G
	8004100444* 8004100444* 8004100447* 8004100447* 8004110024	50-498 M 50-498 M 50-498 M 50-498 M 50-498 M		8004100436# 8004100437# 8004100464 8004100479 8004100549	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0
San Diego Gas & Electric Co San Luis Obispo Mothers for Peace San Luis Obispo.CA Sandia Laboratories	8004110024 8004070224 8004210322 8004280545* 8004030277	50-498 M PRM 50-275 G 50-320 H PR		8004100564 8004110029 8004110077 8004110085 8004110100	50-289 0 50-289 0 50-289 0 50-289 0
	8004030281 8004030284 8004030287 8004030288 8004070413	PR PR PR PR RES		8004110155 8004110162* 8004110516 8004110561 8004110567*	50-289 G 50-289 G 50-289 G 50-289 G 50-289 G
	8004100028 8004100319 8004110051* 8004150022 8004150028	NUREG NUREG 50-3 P NUREG NUREG		8004140004 8004140007* 8004140013* 8004140017* 8004140017*	50-287 G 50-287 G 50-287 G 50-287 G
	8004150033 8004150049 8004150046 8004150074 8004150078	NUREG NUREG REG NUREG NUREG		B004140023* B00414002B* B004140032* B00414003B* B004140045*	50-287 0 50-287 0 50-287 0 50-289 0 50-287 0
	8004240454 8004240464 8004240505 8004240521 8004240523	NUREO NUREO 50-294 P TOPREP TOPREP		B004140051* B004140057* B004140062* B004140065* B004170273	50-287 0 50-287 0 50-289 0 50-289 0 50-287 0
	8004240527 8004240549 8004280034 8004280035 8004280206#	TOPREP TOPREP NUREG NUREG REVIEW GRP		8004170281* 8004210085 8004210235 8004210250* 8004210421	50-287 0 50-320 0 50-287 0 50-287 0 50-289 0
Sargent & Lundy, Inc Sargent Industries, Sweeney Div Sassafras Audubon Society	8004300574 8004100546 8004290474* 8004020236 8004020490	RES REGOD TOPREP XPORTLIC 50-546 H		6004220068 8004220102 8004220405 8004230001 8004230030	50-320 G 50-320 G 50-320 G 50-287 G 50-289 G
· W B	8004010274 8004010300* 8004030037* 8004040186* 8004300067*	50-267	Sheldon, Harmon & Weiss	8004230070 8004230097 8004230127 8004230131 7906010118	50-312 0 50-289 0 50-289 0 50-289 0 50-334 0
d tive, Inc	8004180500* 8004280045 8004280053* 8004180467* 7909140279	50-302 1 XPDRTLIC XPDRTLIC 50-302 1 MIBC		8004020091 8004020091 8004020091 8004020099 80040200999*	50-3 0 50-3 0 50-3 0 50-3 0 50-3 0
] # # #	50-289 U 50-409 U 40-1341 PR 50-10 U		8004020099* 8004080364 8004080375 8004080418 8004080678	50-3 0 50-443 0 50-289 0 50-338 0 50-289 0
		50-409 U 50-266 U MISC 50-289 H 50-320 U		8004080695 8004100100 8004100299 8004100562 8004110045	50-3 F 50-3 F 70-143 50-289 G 50-3 P
		50-449 H 50-309 H COMMISSION 10-1341 70-143		8004150101 8004160131 8004160138* 8004220462 8004280026	50-574 G 50-289 G 50-289 G 50-247 E 50-289 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
Shoreham Opponents Coalition Sigma Chemical Co (subs of Sigma-Aldri ch Corp)	8004210090 8004210092	50-322 XPORTLI XPORTLI XPORTLI	c c c		6004230317* 6004230335 6004230494 6004240394 6004240395*	PROJ 50-206 50-206 50-206 50-206	S P
Sinnissippi Alliance for the Environment	B004300454 B004100027	XPGRTL I 50-454	c o		800425041B 8004250420*	50-206 50-206	5 S
(SAFE) Small Business Administration	8004080241# 8004100194# 8004100576# 8004210119#	CONTRAC CONTRAC CONTRAC CONTRAC	T T		8004270640 800427064 <i>0</i> 8004300011	50-361 50-361 50-361	A A
Spiral Research Applications Corp Source Production & Equipment Co .Inc South Carolina Electric & Gas Co	8004070140# 8004080058 8004020035# 8004020078 8004020201	CONTRAC 71-102 50-395 50-395 50-395		Southern Co Services, Inc	8004300011 8004300363 8004300375 8004150427 8004250390	50-361 50-206 50-361 50-424 50-321	A F D S F
	8004020292 8004020321 8004020322*	50-395 50-395 50-395	9 9 6	Southwest Fabricating & Welding Co (subs of IV International Corp) Southwest Research Institute	8004290023* 8004040280* 8004040295* 8004040296*	9A999 50-341 50-317 50-317	A Q
	8004030175 8004030178*	50-395 50-395	K	Southwest Research and Information Center	B004040301#	50-317	Q
	8004040467 B004100359 B004100402* 8004140161 B004140174	50-395 50-395 50-395 50-361 50-395	0 0 0 R S	Southwest Teras Electric Cooperative	8004240043 8004240043 8004240043 8004240043	WASTE M 50-445 50-445 50-445 50-445	ж н н
	8004150501 8004150548 8004160110 8004170004 8004170085	50-375 50-375 50-375 50-375 50-375	6 8 9 5 8	Spiegel & McDiarmid	8004240053 8004240053 8004240053 8004240053 8004260044	50-445 50-445 50-445 50-445 50-445	м м м м
	B004220049 8004220455 8004220459# B004250404 B004250429	50-395 50-395 50-395 50-395 50-395	8 0 8 8		8004080445 8004090185 8004090185 8004090185 8004090363	PRDJ 50-445 50-445 50-445 50-416	и м м
South Carolina, State of	8004280498 8004300119* 8004300478 8004300561 8004250072*	50-395 50-395 50-395 50-395 State Pi	8 0 0 8		8004090368* 8004090434 8004090434 8004090434 8004100428	50-415 50-445 50-445 50-445 50-445	M M M M M
South Mississippi Electric Power Association	8004070350*	50-416	A		8004100433 8004100433	50-445 50-445	M
Southern California Edison Co	8004020049* 8004020327 8004030140 8004030141*	50-361 50-206 50-206 50-206	0 Р Р		8004100433 8004100547 8004100556 8004150032	50-445 PROJ PROJ 50-445	M
	8004030145* 8004030181 8004030181 8004070338 8004070338	50-204 50-341 50-341 50-204 50-204	P A A R R		8004150032 8004150032 8004150032 8004150050#	50-445 50-445 50-445 50-445	H M M
	8004070342* 8004080395 8004080395 8004080395 8004080477	50-204 50-204 50-204 50-204 50-206	R F F 8	St Peter/s			
	8004080483* 8004080491 8004080498* 8004080504* 80040805339	50-206 50-206 50-206 50-206 50-206	8 P P S	Si			
	8004070208 8004070326 8004100477 8004100500* 8004100537	PRQJ 50-204 50-361 50-361 50-361	P 0 8	State.Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs	8004010478* 8004020369 8004040147	SECY XPORTLIC XPORTLIC	
	8004150345 8004150347* 8004150449 8004150538 8004150538	50-206 50-206 50-206 50-361 50-361	R R P S		8004080118 8004080126 8004080131 8004080139 8004100044	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8004150546* 8004150546* 8004180450 8004180454* 8004210254	50-361 50-361 50-206 50-206 50-206	S S S S	Steel. Hector & Dayss	B00410805B B004108040 B00402005 B004020265* B004170330	XPORTL 10 XPORTL 10 50-389 50-389 50-250	G G G
	8004210257* 8004210270 8004210273* 8004220446 8004220503	50-206 50-206 50-206 50-206 50-206	S3 53 55 P	Stane & Hebster Engineering Carp Stone & Hebster, Inc Storch Engineers	8004030128* 8004040057* 8004270474* 8004020418* 8004020424*	50-280 50-450 TOPREP 50-213 50-213	8 F F
	8004220434 8004230302*	50-206 PROJ	P	Suffolk County, NY	8004100046* 8004100046*	PR PR	

AUTHOR AFF 1L 1471ON	ACCESSION NUMBER	SUBJEC	3RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8004100440 8004100441 8004100450* 8004100450*	50-322 PR 50-514 50-516 50-516	T T T		8004020440 8004020447* 8004030222 8004030233 8004030245	50-327 50-327 50-327 50-327 50-327	9 9 9 9
Susquehanna Alliance Susquehanna Environmental Advocates	8004100460* 8004100472* 8004100472* 8004090463 8004230006	50-516 50-516 50-516 PR 50-387	T T T		8004040181* 8004040377 8004040377 8004040391* 8004040391*	50-259 50-438 50-438 50-438 50-438	9 9 9 9
Sweden Tallahasse,FL Tech/Ops (Technical Operations, Inc.)	8004030298 8004280488* 8004180503* 8004100536 8004280129	PR COMMISS 50-302 REOOD 71-9039	I	•	8004070288 8004070289* 8004070360 8004070363* 8004080207	50-260 50-260 TOPREP TOPREP 40-1341	9 9
Technassociates, Inc Technology for Energy Corp Teknekron Research,Inc	8004280133* 8004100576* 8004210117* 8004300612 8004080618	71-9039 CONTRAC CONTRAC 50-320 CONTRAC	T T		8004080210* 8004080519 8004080526* 8004080553 8004080616	40-1341 50-327 50-327 50-333 50-327	8 8 A 8
Teknekron, Inc Teledyne Isotopes Teledyne Wah Chang Albany	8004180197* 8004040406* 8004180495 8004080050 8004080345	COMMISS 50-298 XPORTLI XPORTLI XPORTLI	R C C		8004080622* 8004090160 8004090228 8004090228 8004090333	50-327 PR 50-327 50-327 50-327	9 P P
Tennessee Valley Authority	8004010320 8004010360 8004010371* 8004010374 8004010375	NUREG 50-327 50-327 50-327 50-327	8 9 8		8004090336* 8004090418 8004090426* 8004090429 8004090433*	50-327 50-327 50-327 50-327 50-327	88866
	8004010379* 8004010381* 8004010393 8004010399 8004010402*	50-327 50-327 50-296 50-327 50-296	9 9 9 9		8004090453 8004090437* 8004100294 8004100364 8004100364	50~327 50~327 PR 50~259 50~259	8 0 0
	8004010403* 800401040B 8004010433 8004010440* 8004010451	50-327 50-327 50-327 50-327 50-259	8 P 8 8 8		8004100364 8004100495* 8004110186 8004110425 8004110425	50-259 50-566 50-327 50-390 50-390	G F A
	8004010459* 8004010460 8004010464 8004010466* 8004010475*	50-259 50-240 50-327 50-260 50-327	9 9 8		8004140327 8004140332* 8004140388 8004140428 8004140432*	50-327 50-327 GEN TEC 50-327 50-327	P 18 8
	8004010487 8004010491# 8004010502 8004010506# 8004020193	50-257 50-259 50-327 50-327 50-553	8 8 6 A		8004140433 8004140434* 8004150392 8004150396* 8004150402	50-260 50-260 50-553 50-553 50-327	8 8 8
	8004020197* 8004020197* 8004020203* 8004020203* 8004020204*	50-553 50-553 50-553 50-553 50-553	A A A A		800415040B 8004130413 8004150413 8004150414 8004150414	50-327 50-390 50-390 50-518 50-518	8888
	8004020204# 8004020207# 8004020249#	50-553 50-553 50-259 50-327	A Q S		8004150414 8004150414 8004150417* 8004150417* 8004150417*	50-518 50-518 50-518 50-518	8888
			8888		8004150417* 8004150418 8004150423 8004150423 8004150423	50-518 50-327 50-259 50-259 50-259	9 9 9 9
			9 9 A		8004150437 8004150437 8004150450* 8004150450* 8004150485	50-390 50-390 50-390 50-390 50-553	88888
					8004150485 8004150474* 8004150474* 8004150500 8004150512*	50-553 50-553 50-553 50-327 50-327	8 8 8 8
					8004150515 8004150522* 8004150523 8004150525 8004150528	50-260 50-260 50-257 50-259 50-327	8 8 8 8
					8004150533* 8004150535* 8004150534* 8004150539 8004150547*	50-327 50-259 50-259 50-327 50-327	8 8 8 8

AUTHOR AFFILSATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY
	8004150551 8004150551 8004150554 8004150557 8004150557	50-327 50-327 50-327 50-259 50-259	P 5 5 P		8004220420 8004220523 8004220523 8004220523 8004220533	50-438 50-259 50-259 50-259 50-259	8 p p p
	8004150557 8004150559* 6004150555* 8004150565* 8004150573	50-259 50-327 50-327 50-327 50-259	F P P S S		8004220541 8004220541 8004220546* 8004220546* 8004220669	50-438 50-438 50-438 50-438 50-260	ឆេលសេស
	80041505854 8004150608 8004150608 8004150615* 8004150615*	50-259 50-327 50-327 50-327 50-327	8 P P P		8004220480* 8004220484 8004220498 8004220499* 8004220707*	50-260 50-259 50-327 50-259 50-327	96599
	6004160216 6004160216 8004160216* 8004160218* 6004160284	50-518 50-518 50-518 50-518 50-327	ខាធខាខាខា		8004220715 8004220722* 8004220724 8004220724 8004220724	50-327 50-327 50-518 50-518 50-518	9 9 9
	8004160291 8004160296* 8004170026 8004170031* 8004170065	50-438 50-438 50-327 50-327 50-327	8 8 8 K		8004220724 8004220724 8004220724 8004220742 8004220750*	50-518 50-518 50-518 50-259 50-259	ន្ទន្ទន
	8004170065 8004170067* 8004170067* 8004170069 8004170073*	50-327 50-327 50-327 50-327 50-327	К К Р Р		8004220753 8004220757* 8004220764* 8004220764* 8004220764*	50-327 50-327 50-518 50-518 50-518	55000
	8004170134 8004170140* 8004170148 8004170155* 8004170213	50-327 50-327 50-327 50-327 50-390	P P G A		8004220764# 8004220764# 8004220764# 8004230347 8004230380	50-518 50-518 50-518 50-553 50-438	555
	8004170225 B004170227* 8004170229* B004170229* B004170231*	50-327 50-327 50-327 50-327 50-327	F F F		9004230380 8004230382* 8004230382* 8004230503 8004230503	50-438 50-438 50-438 50-438 50-438	មា ខា ខា ខា
	B004170231* B004170234* B004170234* B004180106 B0041B0106	50-327 50-327 50-327 50-328 50-328	F F Q Q		B004230504 B004230507* B004230507* B004230527 B004230527	50-257 50-438 50-438 50-438 50-438	5 8 8 8 8
	8004180106 8004180106 8004180296 8004180296	50-328 50-328 50-328 50-553 50-553	Q Q A A		8004230529* 8004230529* 8004240386 8004240386 8004240388*	50-438 50-438 50-438 50-438 50-438	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
	8004180264* 8004180331 8004180337* 8004180365 8004180367*	50-553 50-390 50-390 50-328 50-328	A R R S		B004240388* 8004240405 8004240411 8004240415* 8004250374	50-438 50-390 50-259 50-259 50-566	55 R R B
	8004180377 8004180377 8004180381* 8004180381* 8004180391	50-390 50-390 50-390 50-390 50-327	8 8 8 R		8004250374 8004250379* 8004250379* 8004250380 8004250380	50-566 50-566 50-566 50-438 50-438	\$ \$ \$ \$ \$ \$
	8004180394* 8004180399 8004180407* 8004180444 8004180444	50-327 50-327 50-327 50-390 50-390	e s s s s		8004250384* 8004250384* 8004250394 8004250405 8004250405	50-438 50-438 50-259 50-564 50-566	S S G Q
	8004180451 8004180452 8004180456* 8004180457* 8004180460	50-240 50-296 50-296 50-260 50-327	8 8 8		8004250408# 8004250413 8004250413 8004250424# 8004250424#	50-259 50-390 50-390 50-390 50-390	9 8 8 8 9
	8004180465* 8004210178 8004210178 8004210178 8004210188*	50~327 50~259 50~259 50~259 50~553	6 0 0		8004250431 8004250431 8004250432* 8004250432* 8004280001	50-356 50-556 50-556 50-556 50-259	\$ 5 5 5 G
	8004210202 8004210202 8004210205* 8004220340 8004220340	50-327 50-327 50-327 50-259 50-259	Р Р Р		8004280056 8004280060* 8004280170 8004280170 8004280170	40-1341 40-1341 50-259 50-259 50-259	Q Q
	8004220340 8004220349* 8004220349* 8004220349* 8004220358*	50-259 50-259 50-259 50-259 50-259	P P P		8004280227 8004280388 8004280388 8004280432 8004280432	50-927 50-990 50-990 50-438 50-438	8 8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	3Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8004280436* 8004280436* 8004280438 8004280438 8004280442*	50-438 50-438 50-438 50-438 50-438	8 5 5 5		8004070175 8004070180 8004070180 8004070180 8004070180	50-445 50-445 50-445 50-445 50-445	M M M M
	8004280442* 8004280453 8004280458* 8004280470 8004280476*	50-438 50-328 50-328 50-327 50-327	5 6 8 8	Texas Utilities Generating Co	8004100221 8004100221 8004100221 8004100221 8004010147	50-445 50-445 50-445 50-445 50-445	M M M Q
	8004280503 8004280505* 8004280508 8004280510* 8004280514	50-518 50-518 50-564 50-564 50-438	8 S R R S		8004010295 8004010295 8004010296 8004010296 8004010299#	50-445 50-445 50-445 50-445 50-445	5555
	8004280516 8004280524* 8004280524* 8004280536 8004280537	50-438 50-438 50-438 50-370 50-370	E 5 5		8004010299* 8004030258 8004040083* 8004040088 6004040101*	50-445 50-445 50-445 50-445 50-445	8 M Q Q
	8004280544* 8004280548 8004280548 8004280593 8004280598*	50-390 50-390 50-390 50-259 50-259	8 8 8 8 8		8004070278 8004080221 8004080638 8004100525* 8004150001	50-445 50-445 50-445 50-445 50-445	8 0 M A
	8004290290 8004290290 8004290296 8004290311 8004290316*	50-327 50-327 50-390 50-327 50-327	P P S S		8004150001 8004150177 8004150177 8004150202* 8004150202*	50-445 50-445 50-445 50-445 50-445	A 55 55 55
	8004290329 8004290335* 8004290346 8004290346 8004290346	50-328 50-328 50-328 50-328 50-328	8 5 6 8		8004160237 8004160237 8004160243* 8004160243* 8004180477	50-445 50-445 50-445 50-445 PR	K K K
	8004290353* 8004290353* 8004290353* 8004290379 8004290379	50~328 50~328 50~328 50~257 50~257	8 8 9 0		8004220021 8004220021 8004220021 8004220021 8004220423	50-445 50-445 50-445 50-445 50-445	M M M M
	8004290379 8004290379 8004290400 8004290400 8004290406*	50-259 50-259 50-327 50-327 50-327	a a e a a		8004220426 8004230041 * 8004230041 * 8004230041 * 8004240071 *	50-445 50-445 50-445 50-445 50-445	К М М М
	8004270435 8004270446# 8004270453 8004270453 8004270455	50-327 50-327 50-390 50-390 50-328	8 8 A A B		8004240071* 8004240173 8004240424* 8004240424* 8004240424	50-445 50-445 50-445 50-445 50-445	H 0 0 H
	8004270458* 8004270458* 8004270461* 8004270462* 8004270462*	50-390 50-390 50-328 50-390 50-390	A S A A		8004240562 8004240562 8004240562 8004250049 8004250049	50-445 50-445 50-445 50-445 50-445	M M M
	8004270467* 8004270467* 8004270513 8004270515 8004270516*	50-390 50-390 71-227 50-327 71-227	A A		8004280189 8004280189 8004290230 8004290250 8004290254#	50-556 50-556 50-445 50-445 50-445	9 9 8 8
	8004270517* 8004300076* 8004300341 8004300341 8004300390	50-327 50-566 50-327 50-327 50-518	8 0 P P S		8004270254* 8004270271 8004270271 8004270411 8004270411	50-445 50-445 50-445 50-445 50-445	88888
	8004300390 8004300390 8004300397* 8004300397*	50-518 50-518 50-518 50-518 50-518	6 6 8 8		8004270430 8004270430 8004270437* 8004270437* 8004270521	50-445 50-445 50-445 50-445 50-445	8 8 8 8
Teras Electric Service Co	8004300397* 8004300397* 8004300474* 8004100534 8004100545	50-518 50-518 50-390 50-448 50-445	8 0 M M	Texas, State of	8004270634 8004270634 8004300526 8004300526 8004030344	50-445 50-445 50-445 50-445 50-445	AAAA
Texas Instruments, Inc Texas Public Interest Research Group Texas Utilities Co	8004040408* 8004230035 8004080247 8004090164 8004090164	50-220 50-466 50-445 50-445 50-445	Я О М М		8004030344 8004030344 8004030344 8004030360 8004040078	50-445 50-445 50-445 50-445 50-445	***
	8004070164 8004070164 8004070175 8004070175 8004070175	50-445 50-445 50-445 50-445 50-445	M M M M		8004080044 8004090185 8004090185 8004090185 8004090185	50-445 50-445 50-445 50-445 50-445	* * * * *

SUBJECT CATEGORY

70-1426 70-2478 50-280 D 50-312 G

40-8584 WASTE MOT WASTE MOT 90-54 R 50-54 R

40-299 50-54 50-54 70-687 FOIA

50-483 50-483 50-483 50-483 50-3

50-289 50-289 50-574 50-320 40-8602

70-820

70-820 70-820 70-820 70-820

70-820 70-371 70-371 70-371 50-367

40-8681 50-311 50-272 50-271 50-271

50-271 50-271 50-271 50-271 50-271

50-271 50-271 71-6375 50-271 50-271 99999

0000

Q

s

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	łγ	AUTHOR AFFILIATION	ACCESSION NUMBER
	8004090434 8004090434 8004090434 8004090434 8004140281	50-445 50-445 50-445 50-445	M M	Transportation, Dept of U.S. Court of Appeals 9th Circuit	8004190093 8004210075 8004150429 8004090187 8004250022*
Tesas, Univ of Texas, Univ of, Cancer Center Texas-Louisiana Electric Cooperative, inc	8004140463 8004240416 8004240420* 8004220130* 8004080018	50-498 50-128 50-128 FOIA 50-445	A R R	Union Carbide Corp	8004070262 8004020165 8004080278 8004080548 8004080551#
	8004080559 8004090427 8004240061 8004240061 8004240061	50-445 50-445 50-445 50-445 50-445	м м м		6004090347 6004090375 6004090380# 6004160042 6004290161
The Analytic Sciences Corp The Press Binghampton, NY	8004240071* 8004240071* 8004240071* 8004300279 8004230011	90-445 50-445 50-445 PR FOIA	M M		8004030208 8004040362 8004040368* 8004110329* 8004020099*
Three Mile Island Alort	6004030170 6004040227 6004080137 6004080144* 6004080150*	50-287 50-287 50-289 50-289 50-289	9999		8004080678 8004100562 8004150101 8004210072 8004070242
	80040801 <i>67*</i> 8004080176*	50-289 50-289	G G	United Nuclear Corp , UNG Recovery Systems Div	8004180020
Toledo Edison Ca	8004220011 8004010419 8004010427* 8004020135	50-287 50-346 50-346	FF		8004180046 8004180392 8004220177 8004230533
	8004040455 8004080514 8004090424* 8004100091*	50-346 50-346 50-346 50-346	P Q Q	United Nuclear Corp ,Navel Products Div	B004240140 B004090154 B004210043 B004210047* B004300133
	8004110378 8004110386* 8004110485 8004110487 8004110488*	50-346 50-346 50-346 50-346 50-346	8 8 8 8 8	Utah, State of Valore, C Vermont Yankee Nuclear Power Corp	8004300087 8004100466 8004210291 8004010237
	8004110470* 8004140353* 8004140353* 8004150563 8004150570*	50-346 50-346 50-346 50-346 50-346	8 8 8 8 8		8004010254 8004010254 8004010469 8004010479* 8004020354
	8004180353 8004210265 8004210267* 8004220457 8004220534	50-346 50-346 50-346 50-346 50-346	5 8 8 8		8004020342* 8004040327 8004040332* 8004040445 8004080238
	8004220457 8004220466* 8004220752 8004220761* 8004220765	50-344 50-344 50-346 50-346 50-346	9988		8004080261 8004080269 8004080376 8004080384 8004080423
	8004220772+ 8004250376 8004280380 8004280382+ 8004280456	50-346 50-346 50-346 50-346 50-346	9 I I F		8004080490
	8004280538 8004280546* 8004280572 8004280575* 8004300617	50-346 50-346 50-346 50-346 50-346	8860		
Topper, Alloway, Goodman, Deleone & Duffey Transcomm, Inc Transnuclear, Inc	8004220180* 8004080340* 8004010081* 8004010091* 8004010095*	FOIA CONTRACT 70-2845 70-2845 SECY			
	8004010097* 8004010101* 8004010105* 8004020472 8004020479*	SECY SECY SECY XPORTLIC XPORTLIC			
	8004040110 8004040114* 8004070085 8004080020 8004080037	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	:		
	8004080042* 8004080077 8004080085* 8004080104 8004080259*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	!		

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	łΥ	AUTH⊡R AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8004010401 8004010465 8004010504 8004010505* 8004020027	50-280 50-404 50-338 50-280	9 9 8 9		8004210372 8004210376* 8004220234 8004220234 8004220311	50-338 50-338 50-404 50-404	PPAAF
	8004020157 8004020161* 8004020328 8004020336 8004020400	50-404 50-404 50-339 50-339 50-280	R R S S H		8004220311 8004220318 8004220318 8004220399 8004220399	50-280 50-280	F P 0 0
	8004020400 8004020400 8004020400 8004030126 8004030183	50-280 50-280 50-280 50-280 50-339	H H F A		8004220493 8004220493 8004220611 8004220611 8004220641	50-338 50-338 50-404 50-404 50-339	0 0 5 5 P
	8004030185* 8004030170* 8004030173* 8004030175* 8004030200*	50-339 50-339 50-339 50-339 50-339	A A A		8004220646 8004220653* 8004230231 8004230238* 8004230246*	50-339	9 9 9 9
	8004030205* 8004030206* 8004030210 8004030210 8004030217	50-339 50-339 50-338 50-338 50-338	A Q Q 8		8004230255* 8004230260* 8004230337 8004230519 8004240509		ት ት ት ት
	8004030221* 8004030225 8004030226* 8004030234 8004030234	50-338 50-338 50-338 50-280 50-280	8 5 P P		8004240507 8004250041* 8004250371 80042503B7 80042503B7	50-280 50-280 50-280 50-338 50-338	0 0 0 0
	8004030234 8004030236 8004030236* 8004030238* 8004030242	50-338 50-338 50-338 50-338 50-338	R R R S		8004280472 8004280547 8004280554* 8004280604 8004280608*	50-338 50-338	88888
	8004030266 8004030270* 8004040242* 8004040302 8004070019	50-280 50-280 50-280 50-339 50-339	s G A S		8004280612 8004280616* 8004280626* 8004270334 8004300415	50-280 50-280 50-280 50-280 50-404	8 8 9 9
	8004070261 8004070282 8004070282 8004070307 8004070307*	50-339 50-339 50-338 50-338 50-339	A Q Q S		8004300436 8004300436 8004300472 8003310406 8003310408*	50-280 50-280 50-280 50-124 50-124	J 1 1 1 1 1
	8004080270 8004080312 8004080356 8004080372 8004080372	50-280 50-339 50-280 50-338 50-338	0 0 0		8003310411* 8003310415* 8003310417* 8003310421* 8003310427*	50-124 50-124 50-124 50-124 50-124	8 8 8
	8004080474 8004080474 8004080482* 8004080482* 8004080486*	50-280 50-280 50-280 50-280 50-280	88888	Virginia, Univ of	8003310432* 8003310437* 8004040468 8004150431 8004020215*	50-124 50-124 50-124 50-124 CONTRACT	B F P
	8004080528 8004080536* 8004080621 8004080621 8004100410	50-338 50-338 50-338 50-338 50-339		Volkema, Pess & Sarap Vollen, R J	8004220397* 8004020214 8004020478 8004040069 8004230091	FOIA 50-367 50-367 50-367 50-367	0000
	8004110202 8004110202 8004110478 8004140167 8004140217	50-338 50-338 50-280 50-339 50-281	g	Washington Public Power Supply System	8004230101* 8004010340 8004020273 8004020296* 8004020302	50-367 50-508 50-397 50-397 50-397	0 A B B B
	8004140258 8004140258 8004140258 8004140446 8004140446	50-280 50-280 50-280 50-338 50-338	F O		8004020305* 8004020337 8004020341* 8004030341 8004070367	50-397 50-397 50-397 PR 50-397	K
	8004150164 8004150342 8004170050 8004170052* 8004170079	50-280 50-339 50-338 50-338 50-280	S R R		8004140345 8004150443 8004150443 8004170207 8004210213	50-397 50-508 50-508 50-397 NUREQ	K A A
	8004170210 8004170211* 8004170212* 8004170241 8004170244*	50-339 50-338 50-338 50-280 50-280	R R R		8004210285 8004210285 8004210285 8004230248* 8004230271*	50-397 50-397 50-397 50-460 50-460	A A Q
	8004170244* 6004180232 8004180287 8004180446 8004210177	50-280 50-338 50-280 50-339 50-339	0 5	Weshington Univ	8004280466 8004280469* 8004280475 8004280476* 8004210096	50-397 50-397 50-397 50-397 XPORTLIC	8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF IL IATION	ACCESSION RESMUN	SUBJECT CATEGOR	ł٧
Washington, State of Washington, Univ of West Branch Conservation Association	8004240139 8004270507 8004020139 8004070213 8004070213	State Pr WASTE MO NUREG PR PR			8004020410 8004020410 8004030353 8004040123 8004070206	50-266 50-266 50-266 50-266 50-266	F O P O
West Chicago, IL	8004090213 8004180237* 8004180237* 8004180237* 8004030147	PR 50-3 50-3 50-3 40-2041	н н		8004110491 8004220278 8004220475 8004220475 8004220475	PR 50-301 50-266 50-266 50-266	년 년 대
Western Geophysical Hestern Massachusetts Electric Co Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.)	8004180348* 8004080590* 8004150412 8004080606	50-213 50-245 50-245 40-1162	I I		8004240419 8004240449 8004240449 8004290298 8004290306*	50-266 50-266 50-266 50-266 50-266	0 0 8 8
	8004090250 6004090255	40-1162			8004290307	50-266	s
Western Piping & Engineering Co , Inc Western Washington State College Westinghouse Electric Corp	B004070233 B004110037* B004030156* B004020396 B004020402*	QA999 50-320 TOPREP TOPREP	н		8004290310* 8004290418 8004290425* 8004290428	50-266 50-266 50-266	I I F
	8004020432* 8004070232 8004080049 8004080342 8004090046	TOPREP TOPREP 70-1151 XPORTLIC 71-9009	С	Wisconsin Public Service Corp	8004270464 8004270467* 8004270470 8004270477* 8004270477*	50-301 50-301 50-301 50-301 50-305	9999
	B004090064 B004100063 B004100463* B004110015 B004110496	40-1162 XPORTLIO 70-1151 70-1151 PR			8004010495* 8004080337 8004080457 8004080462* 8004080467*	50-305 50-305 50-305 50-305 50-305	5 B B B B
	8004140015# 8004140020# 8004140034# 8004140094 8004140210#	GA797 GA797 GA797 PR 50~304	G		8004100405 8004150354 8004150353* 8004150524 8004150532*	50-305 50-305 30-305 50-305	0 R R S S
	8004150008 8004150480* 8004160064 8004180070 8004180464	RES 50-537 XPORTLIC 70-2909 50-202	A C		8004150581 8004150596* 8004170018 8004180428 8004180433*	50-305 50-305 50-305 50-305 50-305	88666
	8004210123 8004210136 8004220111 8004220284* 8004220434	XPORTLIC XPORTLIC XPORTLIC 50-301 TOPREP			8004180479 8004180483* 8004210327 8004210331* 8004220642	50-305 50-305 50-305 50-305 50-305	P P P P
	8004240152 8004280329 8004280344# 8004290371# 8004300458	RES TOPREP TOPREP 50-537 XPORTLIC	A C		8004220648* 8004220756 8004230504 8004230515* 8004230321	50-305 50-305 50-305 50-305 50-305	8 8 8
Westinghouse Electric Corp , Nuclear	8004300459 8004030345	XPORTLIC PR	c	Wisconsin's Environmental Decade	8004290327* 8004290336* 8004010389	50-305 50-305 50-266	8
Energy Systems	B004180475* B004240397*	50-202 50-204	P P	Wiss, Janney, Elstner & Association, Inc	B004180130* B004040070*	50-301 50-344	G T
Westinghouse Electric Carp , PWR Systems Div	8004110209 8004170028 8004170035*	TOPREP TOPREP TOPREP		Worsham, Forsythe & Sampels	8004090164 8004090164 8004090164 8004090175 8004090175	50-445 50-445 50-445 50-445 50-445	M M M M
Westinghouse Electric Corp , Wyoming Mineral Corp	B004270404 B004040221	50-327 40-8502	Р		8004090175 8004090180	50-445 50-445	H M
	8004040227 8004080219	40-8502			8004090180 8004090180	50-445 50-445	M
Hestinghouse Operating Plants Owners	8004090070 8004020429	40-8502 TOPREP			8004100221	50-445 50-445	H H
Group White Cross Hosp Association Columbus, OH	8004290434 8004220639*	TOPREP FOIA		Wyle Laboratories	8004100221 8004140354* 8004140354*	50-445 50-369 50-369	H A A
White, M P Consulting Engineer Hidoff, Reager, Belkowitz & Adler	8004160046 8004030170 8004040227 8004080137 8004080146*	ACRE 50-289 50-289 50-289 50-289	0 0 0	Wyoming Mineral Corp	8004140358* 8004140358* 8004020155 8004070196 8004070235	50~369 50~369 40~8502 40~8502 40~8502	A
Wisconsin Electric Power Co	8004080150* 8004080167* 8004080176* 8004090379 8004010223	50-289 50-289 50-289 50-289 50-246	0 0 0		8004070231 8004210413 8004210413 8004220076 800422008B 8004240198	40~8502 40~8502 40~8502 40~8502 40~8502 40~8502	
	8004010319 8004010319 8004020326 8004020333 8004020344*	50-266 50-266 50-266 50-266 50-266	8 8 8	Wyaming Outdoor Council Wyoming, State of	8004240209* 8004280283 8004210387 8004210388* 8004020064	40-8502 40-8304 40-1162 40-1162 40-8745	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Yankee Atomic Electric Co	8004070186 8004270075 8004010395 8004010398* 8004040298*	40-8380 40-8502 50-29 50-29 ACRS	1			8004160096 8004160102* 8004210110 8004230064 8004230118*	PR PR PR 50-29 P COMMISSION
	8004080489 8004080496* 8004100374 8004100374* 8004110419	50-29 50-29 50-29 50-29 50-29	9 9 R R P	York Research York, PA	Corp	8004280534 8004280600 8004270103 8004150462* 8004080106	50-29 F 50-29 P FOIA 50-244 P 50-320 H
	8004110434 8004110444 = 8004140172 8004150350 8004150352*	50-29 50-29 50-29 50-29 50-29	Р Р R R				

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

₹ h 14 ‡	ACTE8510N	SUNJECT	OTHER PEPOKI	HFPORT	ACCESSION	SUBJECT	OTHER REPORT
t ibinE4	NIBMIFH	CATEGURY	PUMPER	A114RF4	NUMBER	CATEGORY	NUMBER

13904 V2 4C	#00414035#*	ኃ0 = 36 ዓ A		A004160UBH	#0041P00#8	PE3	URAL/HASRD=72
13904-1 41 44	900114J32U+	50-369 \$		A0041H0U95	8004160095	HES	ORNL/HASHO-71
11190-057-12	405501015014	50-466 A		M004170120	8000170120	RES	EGG-LOFT-5104
79-15 15	4004010106*	27-39		A004170274	8004170274	RES	EGG-EA-5109
4004034412	H904010415	*FS		HU0417027n	8004170276	PES	EGG-EA-5097
4004010415	*5500100008	PF 5		#104170287	8004170287	RES	
4004020102	4964850145	FES	EEG-t4-5012	AUA41702H7	5004170289	RES	EGG-EA-5110
A004646027	0004040727	46.5	VAC-)u= /u= 150	8004170331	A004170334	RES	EGG-EA-5111
5004040625	4004040028	RES	1.10-14-14-114	8004240152	8004240152	HES	
8000010201	4004040504	FES	1145-01-16-293	8004244440	8004240460	RES	ANL+HUREG = 24871
400000000000000000000000000000000000000	N120P0L009	+f5		4004240465	8004240465	KES	
A094040270	4004040210	HE3		4004544468	8000200468	RES	EGG-8EMI-5113
8004040332	K004040 \$47	RES		4004240475	8004240475	KES	
800 10 10 3aa	N#04040 \$64	hE 5	()4NL / () 4 SH() = 6 A	8004 <u>2</u> 40481	A004240487	RES	ORNL/EO/E18-119
8001070115	50040/01/15	HES		F004250 <i>5</i> 64	8010250364	50-295 F	+ EGG=EA=5117
A18467H415	4004070415	nt S		8004280042	6004280032	HLS	8NL=NUREG-27369
•	•						
A9040P0075	AUD4080075	HE'S	LA-MR-GA3	80942800 3 8	8004260038	HES	BNL-NUREG-27512
KRUUHQUAA	40040800A2	FLS	LD-00-80-113	H004280041	1400854008	RES	UNL-NUREL-27502
9004080094	4004080094	FES	· · ·	K004280059	8994289959	HE9	KC 80-04-02-LR
41 20 40 to 0 to 0	4004080545	HES		9004280065	F004280063	RES	BNL-NUREG-27545
40040445411	8001090290	RES		M1042KPA/1	80042800 7	HES	8NL-NUREG-27116
4041061544	NO04080294	HES		M004300042	8000300052	RES	UNL+NUREG-24872
30040HH302	20504040505	HES		8004500574	#004300574	HES	
というなのというよう	HUN4URNSA5	#FS		ALP-TOP-14	H004U70403*	50-313 P	•
8004080641	1000000041	50=270 P	FGG-LA-5060	ADL/E15-11	86205010008	PH	
A0040A0b75	H0040R0675	4E5		HAM-10144-6	8094020475*	THEREP	
NAABHDPOOR	8830H0H06R4	FES	EGG+LAFT+5084	94*-1533 H1	8004090464#	TOPREP	
9404040068	8004090068	RES	EGG-EA-8106	BA4=1607	#0004580354#	50-302 P	1
8004040154	A904090158	hES		Ct -1-A +13	#855151P00B	50-10 P	
A004040312	8004091312	FES		LEN-12# V1	#004110225#	TOPREP	
81040911424	8004040324	HES		TEN-128 V2	60001102234	TOPHER	
40041911556	5004100758	KFS		CFNPU-210-4 H3	8004010501	TUPREP	
9000100524	8004100328	HE5	EGG-FA-5112	CH+1 030 043 E	#004250039#	50-316 P	•
8004100574	8004100378	h 5	LTR 141-100	CH+1 050 051 E	H104220027*	50-316 P	
40041001408	4004104594	HFS	214 141-144	CH-T 000 072 E	#004220023*	50-316 8	
					1.00422.10232	11310 7	
3004100111	3004100411	RES	≒ ₩₹=60=19×11×01	C#*1 060030 E	4710055PDUR	50-316 6	•
8110410057	K0041905R/	HES		4 040040 T=h3	8004220034*	50-316 P	•
4004[0950]	X104100590	#F5		anan	8004230032*	FOIA	
AU041002A4	40C4100394	HF8		EDK-E (UB) HS	8004020271*	FOPRFP	
3004100244	8004140599	11.6.2		£ £ +21 =0 m d d	*2510F0B00#	50-267 0	P +80084
5034110521	8004110521	HFS		5100+S5+11	80040301344	50-267 0	P-80064
46646464646	*90414013A	RES	F GB+E A+409A	1 113-11-4705	89504030298	PR	
80041500ns	8000150008	NER		14 April 2011-04 41	*004150280*	TUPREP	780F0116R
8004151615	0004150015	FES	NUREG-NUL-25546	14 00-21326	8004240294*	70-1308	15326
8004151320	8004153029	PE 9	HNL-NUREG 24855	41 DO-541 BR	8004230343*		79NED288
3004120351	8004150051	KF &	UNL-YUREG-24950	11 nu= 5 1554= F	8004090476*		, BONED595
4004120925	4004150025		F4G-E4-5099	4FD0-54554	4004210307*	TOPREP	
9004156029	4004153029	468	04 11/E0/E10-122	* FAU=24235 R1	8104170020*		404E05238
400415603e	4004151056	hF8	ON IL/HASRD-70	NF00-2470-	8004280507+	1999401	
A004151113A	8964150038	50=271 P	F66=FA=\$100	KF00-21708	8004049333*	TUPREP	
309415 JuSa	8604150656	MES	ECB-T14P-5023	WFD0-24780	5004100423	70-754	15781
d 11415 10n 5	4004150065	115	NRC~91-76+215	16-53051	362050565	Ph	
900415906-	M00415404a	FIS		JUNETH-DONO AN POR	8004150430	VUINEG.	
4004159152	MU04150152	HES	A116+21-80	NURED-OUZU AT YOR	9003510553	MURFG	
4004151425	Auga150475	FES	47F 418F C= \$1182	%-)FEG=0053 510	40011H0160*	50-334 #	1

кр.н.т.е.Т Ог.∀а⊁ Ч	401 F 22 [117	SUBJECT	UTHER REPORT 4DMBER	#F#4F1 4041ER	ACCESSION 6494 E P	SUBJECT CATEBORY	OTHER REPORT
71 -111 -1	V(3 + 3) +	C#11 (12:41			********		***********
	Fug 1170537	POREL		40KFC/[H=1315	8004030002	NUREG	UCD1 - F 3376
*c16 E G = 0.517 m	2001110337 2004110337	10466		10RFG/CH=1120	8004100586		IICRL=52738
4-16-1030 V\$ ++						NUREG	ANL/ES-89
int boutton va	FU04050119	oth F.G		MULE BY CH = 1423	9004270017	PUPEG	ANL-CT-AG-15
III EGerar VI	HU0449 2A0U4	DIFFE		**************************************	H004240566	FURES	
9616-1517 54	46442401624	50-311 4	L	41HEG/CH= [337	8004110410	YUREG	ANL-79-108
ontefficification of 41	4000170310	takt b		1 JREG/LR-1350	A004020139	NURFG	
1 14F6=05/1	9001151002	No the Education		1119FG/CH-1351	8004170329	NUME G	URNL/NUREG=64
. 148 6 . 13122	4004700206	1,0246		50REG/CH-1352	A004280024	NUPEG	URAL/NUREG/IM-3
ATTRE GROBE	PUDITORD197	70-135		YURE 6/68-1372	8004280048	HUMEG	ORYL/HUREG/TH+3
AUDER-BAZZ APP A	4004050004	10-135		34P+1 +1	8004300056*		19055
' NRI G=0+51	HUD 1100123	utidle ti		#14 - 0 5 /	H004020158	PES	
aunt Grynne	800020068	50-320 6)	416+062	R004210300	kFS	
SHEE-COS AND 1	HU04217351.	50-320 F		414-084	8004080215	HES	
1946-757025	H004280114+	50-510		H+ 2	8004290458*		
909F6-75/00/ 3.7.c	8000280085	50-354		SA1-161-74-PA	8104270474*	50-390 A TOPREP	
*(*************************************	3110 SE 110011 1-	10-334 /		241-181414-14	N104270414#	IUPREP	
MIREONER-JULI	8904264075	P#		34NU77-0271	1850£00403	PR	
-U46G/C1 =11379 vs	K00423430\$*	t HHEG	NS1C=156	94ND71-0214	80040\$0284	PR	
3114F G/(n=0 250	HU0423U307+	• 13456		34ND77-0274	8004030287	Pk	
, 114E @\Cr- 1155	0004170336	19461	URKENDHEG/TH=2	SAND77-0214	8004030288	PH	
たいけんり/じゃ ー のからり	ann 1040454	PHREC	81'L=1018FG-51027	SANU17-0214 C	8004240521	TOPKLP	
11KF6/6×=11429	2004280054	NUMEG	7AND74-8244	\$4077-02/4 P	8004240523	TOPREP	
viint 1./[h=1/95]	8000150140	·UHE6		5ANU77-0274 F	8004240527	TUPREP	
"'UR 5/1 H=0953	4004150141+	41,RE 6	LA-7927	SAND77-0274 F	8004240549	TOPREP	
1/1171 6/CR=0376	8004280035	PRINE	SAND79-1595	SECY-77-064			
**************************************	8001100192	IURE G	0505+IMB	SECY-78-322	8004030166	SECY	
m.cayer-e-ri-1		113/51 (1		2001-14-355	8004240150*	70-135	
ルリネルトレ゙/じゃ ≈リタル6	4004540050	for the E to	PNL-3297	3FCY#79-646	*4000000306*	9ECY	
~URFG/C+=09A8	4004543464	4UHFG	344579-0944	\$FCY-&A-001	8004090162	SECY	
2114£67LK=1001	8004100025	· UREG	RNL-NUREG-51044	5ECY-80-002	8004090321	SECY	
11666768-1054	8900214098	HUPEG	84019-1088	\$1CY=80-026A	8004290072	SECY	
ARRECYCH-TTOR	85000100058	LAKEC	544079-2002	SFCY=80=045	8004010051	SECY	
* UHEG/LH#1105	Auga240454	NURLG	544079-2003	5ECY-40-054	8004093297	SECY	
1118FE/CH-1118	10004290001	HUREG	LA-8077	StCY-HO-OMIA	3004290171	50-327 A	
WINE 5/CH-1109	H104111065	LUKES	P+ L=3187	SECY-An-095	8104100039*	LUCFR	
WEEN H-1116	8004140455	NUREG		SECY-MU-LO!	500402002A*	JOCER	
, nwFd\Ch-1157	9004580058	ALIME C	CENT/DUREG/TH=5	5FCY=d0=120	8004240141	70-2805	
NUKEG/(K+1126	9004290007	MIREL	4 /L - NURFG-51101	5ECY#80-131	RE04040200	SFCY	
124EG/CK-1134	40 14214278	HINEG	BAC#350P	SECY-80-132	8004090061	50=320 P	
VINERACK+1 144	810124056S	INFE(EG0-2108	St CY + Bu + 1 Sa	8004300002	SECY	
" LREG/CH=1149	8604150033	1 DHE C	SA4D79-2017	SFCY=80=139	90040100174	LOCER	
14EG/1 K#1350	MIO4150022	10466	944079-2081	24CA-80-115	8004070148	PLCA	
1191 G/L K=1151	H004150074	FUREG	SA (D 19-2079	SFCY+80-100	8004100431+	10CF#	
(#REG/CR=1191	4004240505	50-296	\$ \$AVII79=2311	SECY-80-177	R004230130	SECY	
HIPEG/CHALLOS	A004170341	HUNEG		SECY=BU=45	8004010051	70=2845	
1111 SAT 1-1705	8004100319	NUPEG	SAND 78+8237	Inlelledke6	80041R0339*	50-320 R	
#164 EVCH+1503	6004100029	NUMEG	EGG-2012	TOP 31+6	8004180096	50-201 P	
#18FG/EP=1228	8004250047	A 11/62 G		TVA-TH75-1A HA	8004070363*	TOPREP	
	0.04530041	THE IS		1VA-1N75-1A KA 1VA/ANU-179/13	8004290467*	10PREP 50=390 A	
							15013
				UC=329	40043002194	MASTE MG1	15912
119EG/CH=1210	H004100591	NUMER	4"L-/9-105	14 RISH -0-094N	8004150480*	50-537 A	
JFEG/CK-1257	8004140478	ACINE'S	CREARE IN-512	4ARD+0+0252	8004290371*	50=537 A	
108EG/CK-1245	501411014F	VIDE C	100 THE 100 31	-CAD 3600 W A		TODGE II	
11/REG/CR=1263			HEDL-1ME 79-71	ACAP-TAUD HSA	4004020402*	TOPREP	
**************************************	KU0454000A	HINE (4RC 4174	KCAP-9402	**********	TOPREP	
tilbeettus 1117			5111 4 1 1 5	PCAP-9520	8004240397*	50-204 P	
* (IMEG/C K=1273	H004210301	FUREG	DNF-2595	#CAP-96 \$5	8004220284*	50-301 P	1021-3
1.19E671 K= 1.280	NO 040 30005	* 1)4 E G	9114-103	*CAP = 9691	80040204324	TUPREP	
"UPEG/(-1245	6004150326	PANE C	AVL-C1-80-10				
1/19t G/L x=130/	9004150074	"UKEG	1452-64D445	AR-50-10-80.02	8004150396*	50-553 R	
17P1 G/CR-1 109	8001159049	WIREG	544079-2013	Y/ON1/508-77/42500	8004030299	ьh	
				YCMF+SMH 5	8004280510*	50-566 P	
				YOUAP-I-A	8004110444*	50-29 P	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the doc! number and the symbol for the category of informati within that docket; for example, 50-320 P. The docket su ject categories are defined in Appendix A.

Subject categories for nondocketed items are also enter in this column by symbol; for example, ACRS. These cat gories are defined in Appendix B and listed in the Content

ACCESSION NUMBER

ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	,
7812110289 7812110291 7902060388	7812110287 7812110287 7902040387	78/10/17 78/10/17 79/01/18	50-387 50-387 MISC	0
7904110034 7905190137	7904110030 7905190134	79/03/30 79/ 0 5/15	PR 50-312	P
7908010479 7908140247	7908010475 7908140243	80/07/20 79/07/02	COMMISSIO	
7908150564 7908210253 7909290207	7908150559 7908210247 7909290201	79/07/11 79/06/25 79/07/03	50-358 50-320 FDIA	H
8003190734 8003310408	8003190717 8004040468	80/01/28 80/03/19	50-128 50-124	P F
8003310411 8003310415 8003310416	8003310406 8003310406 8003310412	80/03/19 80/03/19 80/03/03	50-124 50-124 40-215	8
8003310417 8003310421	8003310406 8003310406	80/03/19 80/03/19	50~124 50~124	B B
8003310427 8003310432 8003310439	8003310406 8003310406 8003310406	80/03/19 80/03/19 80/03/19	50-124 50-124 50-124	B B
8004010006 8004010007	B004010004 B004010002	80/02/29 80/02/25	CONTRACT	Ρ
8004010017 8004010021 8004010040	8004010014 8004010016 8004010036	80/03/19 80/03/19 80/02/25	10cfr 10cfr 50-289	G
B004010042 B004010044	8004010036 8004010036	80/02/25 80/02/25	50-289 50-289	G G
8004010066 8004010070 8004010072	8004010061 8004010064 8004010064	80/02/23 80/02/23	71-9049 50-289 50-289	G G
8004010076 8004010078	8004010064 8004010064 8004010051	80/02/23 80/02/23 80/01/24	50-289 50-289 70-2845	G G
8004010081 8004010082 8004010085	8004010051 8004010064 8004010064	80/05/53	50-289 50-289	G G
8004010087 8004010071 8004010073	8004010064 8004010051 8004010064	80/02/23 80/01/24 80/02/23	50-289 70-2845 50-289	G G
8004010075 8004010097	8004010051 8004010051	80/01/24 80/01/24	SECY	•
8004010101 8004010105 8004010106	8004010051 8004010051 8004010104	80/01/24 80/01/24 80/03/07	SECY SECY 27-39	
8004010181 8004010186	8004010163 8004010163	80/03/18 80/03/18		Ρ
8004010189 8004010195 8004010214	8004010163 8004010163 8004010210	80/03/18 80/03/18 80/03/28	70-1308 70-1308 50-250	P
8004010217 8004010229	8004010216 8004010227	80/03/25 80/03/11	50-313	R P

	PRINCIPAL	DATE	SUBJEC	т .
ENCLOSURE	DOCUMENT	ISSUED	CATEGO	
CHULUSUME	DOCOMENT	122051	CATEGO	K ¥
8004010236				
	8004010231	1E/E0/08	50-280	P
E004010243	B004010237	80/03/24	50~271	P
8004010247	8004010244	1E\E0\08	50-52B	۲
8004010250	8004010242	90/03/56	50-466	A
8004010275	8004010269	80/03/27	50-280	1
				-
8004010299	8004010295	80/03/21	50-445	9
8004010300	B004010294	80/05/59	50-367	0
8004010313				
	8004010311	80/03/54	50-338	G
8004010326	8004010321	80/03/56	50-321	Ħ
8004010337	E004010331	80/03/16	50-272	R
B004010345	8004010340	80/03/21	50~508	Α
8004010347	8004010343	80/03/28	50-362	S
8004010348	B004010322	80/03/27	50-272	s
8004010351	B004010342	80/03/25	50-318	5
8004010358	BD04010350	80/03/24	50-528	
0004010330	0004010330	80/03/24	20-25B	8
				_
8004010366	6004010363	B0/03/31	50-338	P
B00401036B	8004010344	B0/03/58	50-318	5
8004010369	B004010362	80/03/20	50-213	S
8004010370	B004010356	80/03/27	50~272	S
8004010371	8004010360	80/03/27	50-327	8
8004010379	8004010374	80/03/26	50-327	a
8004010381	8004010375	80/03/24	50~327	
8004010387				S
	B004010376	80/03/25	50-318	8
8004010387	8004010384	80/03/28	50-280	P
8004010368	8004010380	80/03/25	50-316	9
8004010370	8004010385	80/03/25	50-325	S
8004010398	8004010395	00/03/31	50-29	ï
8004010400	8004010394	80/03/27	50-324	S
8004010402	B004010393	80/03/28	50-296	Š
8004010403	8004010399	80/03/24	50-327	S
0001010103	0004010044	BU/U3/E4	20-751	Þ
8004010404	800401037/	80/03/27	EG 220	
			50-329	S
8004010409	B004010405	80/03/27	50-261	1
8004010417	8004010407	80/03/27	50~336	3
8004010422	8004010415	80/02/21	RES	
8004010427	8004010419	80/03/27	34E-06	F
8004010429	8004010423	80/03/27	50~336	S
8004010435	B004010430	80/03/25	50-317	Š
8004010440	8004010433	80/03/28	50-327	s
8004010441	B004010437	80/03/21	50-275	
8004010448	8004010437			A
0004010440	8004010424	80/03/24	50-318	8
00040404				
8004010455	8004010452	80/03/27	50-263	8
8004010457	8004010454	80/03/21	50~278	R
8004010459	8004010451	80/03/28	50-257	8
8004010466	B004010460	60/03/28	50-260	s
8004010467	8004010463	80/03/28	50-317	P
			w,,	•
8004010468	8004010461	80/03/28	50-324	R
B004010471	8004010463	80/03/58		
8004010471			50-317	Þ
	8004010469	80/03/25	50-302	Ŗ
8004010475	8004010464	80/03/58	50-327	8
8004010477	8004010474	80/03/25	50~321	6

TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			ACCESSION NUMBER	
PRINCIPAL ENCLOSURE DOCUMENT	DATE	SUBJECT CATEGORY	PRINCIPAL DATE ENCLOSURE DOCUMENT ISSUED	SUBJECT CATEGORY
8004010478 8004010051 8004010479 8004010467 8004010481 8004010474 8004010483 8004010469 8004010485 8004010460	80/01/24 80/03/25 80/03/21 80/03/25 50/03/24	SECY 50-302 R 50-316 S 50-302 R 50-219 S	8004020228 8004020218 80703706 8004020231 8004020218 80703706 8004020234 8004020227 80702705	50-389 G 50-389 G 50-389 G 50-320 H State Prog
8004010491 8004010487 8004010494 8004010488 8004010495 8004010492 8004010497 8004010488 8004010499 8004010489	80/03/28 80/03/31 80/03/27 80/03/31 80/03/26	50-259 S 50-302 R 50-305 P 50-302 R 50-271 S	8004020249 8004020242 80/03/11 8004020252 8004020242 80/03/11 8004020258 8004020242 80/03/11	50-387 G 50-257 G 50-259 G 50-259 G 50-275 P
8004010500 8004010473 8004010501 8004010479 8004010505 8004010504 8004010506 8004010502 8004010507 8004010503	80/03/25 80/03/27 80/03/28 80/03/28 80/03/24	50-314 S TOPREP 50-330 S 50-327 S 50-219 S	8004020265 8004020218 80/03/06 8004020226 8004020237 80/02/28 8004020270 8004020257 80/02/28	50-259 0 50-387 0 50-275 P 50-275 P TOPREP
8004010510 8004010507 8004010513 8004010507 8004010515 8004010512 8004010789 8004010787 8004020011 8004020005	80/03/21 80/03/21 80/01/14 80/03/13 80/03/14	50-348 S 50-348 S QA999 PT9 50-389 G	8004020273 8004020268 80703704 8004020274 8004020288 80703704 8004020276 8004020268 80703704	50-387
8004020028 8004020024 8004020035 8004020029 8004020036 8004020029 8004020039 8004020029 8004020043 8004020029	80/03/19 80/01/16 80/01/16 80/01/16 80/01/16	10CFR 50-395 Q 50-395 Q 50-395 Q 50-395 Q	8004020289 8004020285 80/03/28 8004020296 8004020293 80/03/21 8004020305 8004020302 80/03/21	50-389 Q 50-155 R 50-397 B 50-397 B 50-249 B
8004020047 8004020045 8004020054 8004020045 8004020059 8004020045 8004020057 8004020057	80/03/17 80/03/17 80/03/17 80/01/21 80/02/25	50-361 0 50-361 0 50-361 0 71-6387 WASTE MOT	8004020316 8004020312 80703728 8004020317 8004020315 80703725 8004020320 8004020319 80703731	50-275
8004020062 8004020045 8004020073 8004020070 8004020075 8004020070 8004020079 8004020071	80/03/17 80/02/29 80/02/29 80/02/29 80/03/10	50-361 0 50-282 P 50-282 P 50-282 P 50-3 G	8004020330 8004020325 80/03/25 8004020337 8004020332 80/03/26 8004020338 8004020334 80/03/28	50-302 9 50-366 9 50-249 9 50-267 1 50-424 9
8004020102 80040200B9 8004020105 8004020091 8004020106 80040200B9 8004020107 8004020104 8004020109 8004020091	80/03/17 80/03/10 80/03/17 80/03/21 80/03/10	State Prog 50-3 G State Prog 50-289 G 50-3 G	8004020344 8004020343 80/03/25 8004020345 8004020342 80/03/28 8004020347 8004020343 80/03/24	50-397 K 50-264 9 50-369 9 50-364 8 50-313 9
8004020114 8004020112 8004020115 8004020091 8004020116 8004020111 8004020118 8004020091 8004020119 8004020113	80/03/19 80/03/10 80/02/09 80/03/10 80/03/13	50-289 H 50-3 O ACR6 50-3 G 50-445 M	8004020337 8004020350 80703720 8004020358 8004020348 80703727 8004020359 8004020354 80703727	50-265 S 50-254 S 50-367 S 50-321 S 50-271 S
8004020120 8004020111 8004020122 8004020113 8004020123 8004020111 8004020125 8004020110 8004020126 8004020110	80/02/09 80/03/13 80/02/09 80/03/10 80/03/19	ACRS 50-445 H ACRS 50-3 G 50-286 D	8004020345 8004020341 80/03/24 8004020347 8004020343 80/03/25 8004020371 8004020366 80/03/17	71-250 50-366 8 50-249 8 50-327 8 50-213 R
800402012B 8004020111 8004020191 8004020111 8004020137 8004020127 800402013B 8004020111 8004020141 8004020111	80/02/09 60/02/09 80/02/21 80/02/09 80/02/09	ACRS ACRS 71-5739 ACRS ACRS	8004020380 8004020373 80/03/05 8004020384 8004020381 80/03/12 8004020386 8004020383 80/03/28	50-295 8 71-13 50-335 8 50-217 R 50-390 A
8004020144 8004020111 8004020161 8004020157 8004020162 8004020152 8004020163 8004020154 8004020164 8004020149	80/02/09 80/03/31 80/03/17 80/03/14 80/02/28	ACRS 50-404 R 50-528 Q 50-272 P 50-445 M	B004020402 B004020374 B0/03/26 B004020412 B004020407 B0/03/25 B004020416 B004020414 B0/03/27	50-291 8 TOPREP 50-304 9 50-438 9 50-213 F
8004020168 8004020152 8004020171 8004020153 8004020175 8004020149 8004020176 8004020170 8004020177 8004020173	80/03/17 80/03/17 80/02/28 80/03/19 80/03/06	50-528 Q 50-528 G 50-445 M State Prog COMMISSION	8004020419 8004020413 80/03/10 8004020421 8004020417 80/03/28 8004020424 8004020408 80/03/31	50-213 F 50-373 F 50-438 9 50-213 F 50-254 8
8004020180 8004020152 8004020181 8004020149 8004020188 8004020149 8004020190 8004020149 8004020194 8004020187	60/03/17 80/02/28 80/03/11 80/02/28 80/03/11	50-528	8004020434 8004020423 80/02/14 9004020431 80/03/27 8004020437 8004020428 80/03/25	TOPREP QA997 50-438 8 50-366 8 50-265 8
8004020197 8004020193 8004020198 8004020149 8004020199 8004020195 8004020203 8004020193 8004020204 8004020193	80/03/24 80/02/28 80/03/03 80/03/24 80/03/24	50-553 A 50-445 M COMMISSION 50-553 A 50-553 A	B004020447 B004020440 B0/03/27 B004020458 B004020455 B0/03/03 B004020465 B004020461 B0/03/03	50-265 B 50-327 B 50-320 H 50-320 H TOPREP
8004020207 8004020193 8004020211 8004020201 8004020215 8004020205 8004020220 8004020201 8004020221 8004020217	80/03/24 80/02/29 80/02/15 80/02/29 80/02/28	'50-553 A 50-395 Q CONTRACT 50-395 Q 50-320 H	8004020474 8004020468 80/03/20 8004020475 8004020464 80/03/18 8004020479 8004020472 80/03/19	XPORTLIC 50-522 Q TOPREP XPORTLIC 50-364 A

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION					ACCESSION	NUMBER		
ENCLUSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT
6004020462	6004020477	80/03/24	40-7127	•	8004030362	8004030323	BO/03/11	70-2478
8004020485 8004030003	8004020473 8004030001	80/03/12 80/03/06	40-8745	4	80040303 <i>6</i> 6 8004040004	8004030365 8004040002	80/02/26 80/03/19	50~213 P 50~289 H
8004030014 8004030018	8004030011 8004030016	80/03/26 80/03/11	CONTRACT 50-3	4	800404000B 8004040015	8004040007 8004040012	80/03/03	PR 70-1201
8004030023 8004030024	8004030020 8004030016	80/03/19 80/03/11	CONTRACT	•	8004040018	B004040012	B0/03/13	70~1201 50~10 G
8004030025 8004030028	8004030016 8004030022	80/03/11	50~3	f 1 1	8004040019 8004040021	8004040014 8004040012	80/03/21 80/03/13	70-1201
8004030028	8004030019	80\03\03		3	8004040023 8004040025	B004040014 B004040022	80/02/15	50-10 Q 50-341 Q
8004030037 8004030038	8004030032 8004030035	80/03/17	CONTRACT 50~320	4	8004040034 8004040035	8004040029 8004040032	80/02/12 80/02/13	50-254 0 50-255 0
8004030044 8004030046	8004030040 8004030043	80/03/05 80/03/12	CONTRACT		8004040040 8004040041	8004040036 8004040037	80/02/15 80/02/08	50-373 Q 70-143
8004030054	8004030052	80/03/03		4	8004040042	8004040038	80/03/27	XPORTLIC
80040300 <i>6</i> 5 8004030071	8004030061 8004030070	80/03/03 80/03/05	50-320	4 1	B004040044 B004040046	8004040037 8004040043	80/02/08 80/02/15	70-143 50-546 Q
6004030073 6004030116	8004030087 8004030102	80/03/03 80/03/12	50-320	f P	8004040047 8004040047	8004040037 8004040045	80/02/08 80/03/27	70-143 XPORTL1C
8004030128	8004030124	80/03/28			8004040052	B004040050	B0/02/16	50-341 G
8004030129 8004030131	8004030123 8004030130	80/03/03	50-267	H 1	8004040055 8004040057	8004040054 8004040056	80/02/22 80/02/01	50-312 Q 50-458 B 50-483 G
8004030132 8004030133 8004030134	8004030130 8004030130 8004030130	80/03/31 80/03/31 80/03/31	50-267	9	8004040061 8004040062	8004040060 8004040060 8004040063	80/02/12 80/02/12 80/03/17	50-483 G 50-344 T
8004030134	8004030130	80/03/31		<u>a</u> a	8004040065 8004040067	8004040063	80/03/17	50-344 T
8004030141 8004030145	8004030140 8004030140	80/03/31 80/03/31	50-204	9	8004040068 8004040070	8004040058 8004040063	80/03/13 80/03/17	PROJ 50~344 T
8004030156 8004030161	8004030153 8004030160	80/03/12	50-320	H R	8004040071 8004040073	8004040064 8004040063	80/03/20 80/03/17	50-483 G 50-344 T
8004030168	8004030166	77/02/02	SECY		B004040079	8004040064	80/03/20	50-483 G
8004030178 8004030185	8004030175 8004030183	80/04/01 80/04/02		K A	80040400B3 80040400P3	80040400B1 80040400B0	80/03/11 80/02/08	50-445 G 70-1151
8004030186 8004030190	8004030181 8004030183	80/04/01 80/04/02	50-361 50-339	A A	8004040094 8004040096	8004040089 8004040091	80/02/26 80/03/10	50-313 G 50-317 P
8004030193	8004030183	80/04/02	50-339	A	8004040097	8004040080	80/02/08	70-1151 50-445 Q
8004030194 8004030195	8004030172 8004030183	80/03/28 80/04/02	50-339	P A	8004040101 8004040102	8004040098 8004040095 8004040100	80/03/11 80/02/07 80/02/2B	50-445 Q 40-8135 QA999
8004030197 8004030200	8004030194 8004030183	80/03/31 80/04/02	50-334 50-339	R A	8004040104 8004040105	8004040091	80/03/10	50-317 P
8004030202 8004030205	8004030199 8004030183	80/03/28 80/04/02	50-249 50-339	P A	8004040107 8004040114	8004040091 8004040110	80/03/10	50-317 P XPDRTLIC
8004030206 8004030214	8004030183 8004030212	B0/04/02 80/03/26	50-337	A R	8004040117 8004040120	8004040113	80/03/12	70-143 CONTRACT
8004030218	8004030216	80/03/28	50-333	B	8004040122	8004040111	80/02/06	GA999
8004030220 8004030221	8004030217 8004030219	80/03/38	50-338	R B	8004040124 8004040125	8004040121 8004040084	80/03/26 80/02/12	71-9010 50-416 0
8004030224 8004030226	8004030223 8004030225	80/03/31	50-338	8 9	8004040132 8004040133	8004040115 8004040128	80/03/18 80/02/19	50-346 Q 50-267 Q
8004030237	8004030235	80/03/19	QA999		8004040136	8004040128	80/02/19	50-267 G 70-27
8004030238 8004030239	8004030236 8004030235	80/04/01 80/03/19 80/03/19	50-338 9779 97740	Ŕ	8004040137 8004040139 8004040140	8004040130 8004040126 8004040128	80/02/04 80/03/17 80/02/19	50-312 0 50-267 0
8004030242 8004030243 8004030244	8004030235 8004030240 8004030235	80/04/01 80/03/19	50-344 GA999	P	8004040144 800404014	B004040130	80/02/06	70-27
8004030247	8004030230	80/02/28	50-298	a	80040			
8004030252 8004030255	8004030251 8004030251	80/02/14	50-306 50-306	Q Q	8004C 8004I			
8004030256 8004030264	8004030249 8004030260	80/03/26 79/11/13	50-250 50-320	B 0	800#			
8004030270	8004030246	80/03/28	50-280	В				
8004030278 8004030279	8004030273 8004030272	80/03/27 80/03/12	50-333 50-320	영 P				
8004030280 8004030283	8004030274 8004030272	80/03/07 80/03/12	XPORTLIC 50-320	P				
8004030285	8004030282	80/03/25	50-335	8				
8004030290 8004030308	8004030232 8004030303	80/03/31 80/03/27 80/03/27	AEE-06 AIDA AIDA	P				
8004030312 8004030316	8004030303 8004030303	80/03/27	FOIA					
8004030319 8004030321	8004030303 8004030303	80/03/27 80/03/27	FOIA FOIA					
8004030324 8004030327	8004030303 8004030303	80/03/27 80/03/27	FOIA FOIA					
8004030328	8004030303	\$0/03/27	FOIA					
0004030330 0004030333	8004030303 8004030329	80/03/27 80/03/20	40-2061 50-312	o .				
8004030340 8004030350	8004030335 8004030347	80/03/20 80/03/24	COMM1881	e G				
8004030359	8004030354	80/03/05	71-9142					

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			ACCESSION				
	ATE SUBJECT	E	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	,
8004040197 8004040191 80/ 8004040198 8004040184 80/ 8004040199 8004040195 80/ 8004040206 8004040205 80/	02/27 CONTRACT 03/21 50-445 02/16 50-10 03/30 50-245 02/13 50-566	- 6 8 9 9	8004040409 8004040410 8004040411 8004040413 8004040418	8004040394 8004040405 8004040407 8004040400 8004040414	80/03/24 80/02/16 80/02/08 80/03/31 80/02/16	50-293 50-331	6000
8004040217 8004040212 807 8004040222 8004040201 807 8004040233 8004040202 807	02/15 70-82 03/19 CONTRACT 02/15 50-416 03/05 50-320 02/28 50-320	6 6	3004040422 3004040424 3004040426 3004040427 3004040430	8004040419 8004040420 8004040416 8004040419 8004040420	80/03/24 80/02/06 80/04/01 80/03/24 80/02/06	FOIA 50-424 50-321 FOIA 50-424	0 5 0
8004040242 8004040232 807 8004040245 8004040214 807 8004040248 8004040215 807	03/03 50-320 02/05 50-280 03/03 50-320 03/03 50-320 02/05 50-280	3 7 8	8004040431 8004040432 8004040434 9004040437 8004040438	B004040421 B004040417 B004040425 B004040417 B004040427	80/03/05 80/03/24 80/03/28 80/03/24 80/03/31	FOIA 50-335 FOIA	H R 8
8004040254 8004040247 807 8004040256 8004040246 807 8004040257 8004040247 807	03/03 50-320 03/26 50-336 01/29 ACR8 02/28 50-320 03/03 50-320	6 1	B004040440 B004040442 B004040443 B004040444 B004040445	8004040436 8004040419 8004040425 8004040436 8004040439	80/02/16 80/03/24 80/03/28 80/02/16 80/03/18	50-315	Q Q Q
8004040262 8004040252 807 8004040263 8004040223 807 8004040265 8004040218 807	02/05 50-280 02/05 50-285 03/03 50-320 03/03 50-320 02/05 50-409	E E E E E E E E E E E E E E E E E E E	B004040446 B004040447 B004040448 B004040449 B004040452	B004040419 B004040439 B004040425 B004040439 B004040437	80/03/24 80/03/18 80/03/28 80/03/18 80/03/18		0 R Q
8004040275 8004040271 807 8004040277 8004040272 807 8004040280 8004040278 807	03/11 NUREG 01/17 ACRS 03/11 NUREG 03/28 50-341 01/17 ACRS	6 6	B004040453 B004040454 B004040464 B004040475 B004040479	8004040450 8004040435 8004040435 8004040471 8004040476	80/02/13 80/03/07 80/03/07 80/02/16 80/03/10	40-2061 CONTRACT CONTRACT 50-329 QA999	Q
8004040289 8004040232 80/ 8004040292 8004040283 80/ 8004040295 8004040291 80/	03/27 50-219 02/05 50-280 01/17 ACRS 03/29 50-317 03/29 50-317	1 6 6 1 5	8004070007 8004070009 8004070014 8004070015 8004070020	8004070003 8004070006 8004070010 8004070011 8004070018	80/03/07 80/03/14 80/03/17 80/03/07 80/03/17	CONTRACT CONTRACT 71-7079 50-320 71-7080	Р
8004040298 8004040283 807 8004040299 8004040285 807 8004040301 8004040291 807	03/31 50-261 01/17 ACR8 02/20 50-315 03/29 50-317 04/02 50-158	6 1 1	8004070022 8004070032 8004070034 8004070036 8004070037	8004070021 8004070025 8004070027 8004070033 8004070035	80/03/10 80/03/20 60/03/08 80/03/19 80/03/07	71-185 CONTRACT XPORTLIC 50-285 50-400	G G
8004040324 8004040317 807 8004040332 8004040329 807 8004040333 8004040326 807	703/31 50-261 703/31 50-272 703/31 50-271 703/31 TOPREP 703/31 TOPREP	3 3 8	B004070042 B004070043 B004070049 B004070054 B004070059	B004070040 B004070035 B004070046 B004070046 B004070046	80/03/21 80/03/07 80/03/03 80/03/03 80/03/03	50-271 50-400 70-143 70-143 70-143	P Q
8004040337 B004040316 B07 8004040343 B004040340 B07 8074040444 B004040336 B07	703/30 50-213 702/20 50-295 704/01 50-358 703/27 50-320 701/22 50-458	1 6 1 8 3 8	8004070060 8004070063 8004070066 8004070071 8004070077	8004070057 9004070056 9004070054 8004070070 9004070075	80/03/11 80/03/24 80/03/26 80/03/17 80/03/17	50~498 50~281 50~281 50~483 50~327	G G O H H
8004040348 8004040476 807 8004040349 8004040336 807 8004040350 8004040340 807	703/13 50-250 703/10 0A999 703/27 50-320 704/01 50-358 703/13 50-250	8 3 1	8004070079 8004070081 8004070083 8004070087 8004070090	B004070076 B004070076 B004070076 B004070076 B004070076	80/03/04 80/03/04 80/03/04 80/03/04 80/03/04	9A999 9A999 9A999 9A999 9A999	
8004040355 B004040340 B0/ B004040356 B004040335 B0/ B004040359 B004040354 B0/	703/10 QA999 704/01 50-358 701/22 50-458 703/31 50-334 703/13 50-250	[8004070091 8004070098 8004070099 8004070100 8004070104	8004070076 8004070094 8004070089 8004070096 8004070089	80/03/04 79/12/31 80/03/04 80/02/22 80/03/04	QA999 50-3 40-6329 CONTRACT 40-6329	Р
8004040364 8004040363 807 8004040365 8004040328 807 8004040367 8004040363 807	703/10 GA979 701/30 50-458 703/13 50-250 701/30 50-458 703/27 50-483	A E E E E E E E E E E E E E E E E E E E	8004070106 8004070107 8004070109 8004070110 8004070111	8004070102 8004070089 8004070102 8004070102 8004070102	80/03/05 80/03/04 80/03/05 80/03/05 80/03/05	50-443 40-6329 50-443 50-443 50-443	Q Q Q Q
8004040373 8004040370 807 8004040376 8004040371 807 8004040383 8004040358 807	702/22 50-458 702/22 50-458 703/31 50-255 703/10 50-269 702/28 50-458	4 6 8 9 6	8004070112 8004070117 8004070118 8004070119 8004070120	8004070105 8004070114 8004070113 8004070115 8004070114	80/02/07 80/03/04 80/03/11 80/02/07 80/03/04	70-1100 50-322 50-368 70-398 50-322	G G
8004040387 8004040380 807 8004040387 8004040385 807 8004040371 8004040377 807	(02/28 50-458 (03/31 50-250 (04/02 50-2 (03/27 50-438 (03/31 50-250	2 5 6	8004070121 8004070123 8004070132 8004070135 8004070137	B004070114 B004070114 B004070129 B004070130 B004070129	80/03/04 80/03/04 80/03/05 80/03/06 80/03/05	50-322 50-322 50-155 50-341 50-155	Q Q H G H
8004040402 8004040358 80/ 8004040403 8004040398 80/ 8004040406 8004040396 80/	702/13 50-315 703/10 50-269 703/10 71-35 703/28 50-220 703/28 50-220	1 1 1	8004070140 8004070142 8004070152 8004070155 8004070158	8004070125 8004070139 8004070147 8004070144 9004070150	80/02/25 80/02/29 80/03/13 80/02/20 80/03/17	CONTRACT 50-295 71-24 40-6659 50-438	ç q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER					
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 159UED	SUBJECT CATEGOR	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8004070159 8004070162 8004070164 8004070165 8004070166	8004070144 8004070157 8004070144 8004070160 8004070157	80/02/12 80/02/10 80/02/10 80/02/20	40-6659 50-10 40-6659 50-313 50-10	о р о	8004070382 8004070385 8004070385 8004070371 8004070372	8004070379 8004070379 8004070383 8004070379 8004070383	80/03/07 80/03/07 80/02/27 80/03/07 80/02/27	50-387 50-387 70-364 50-387 70-364	0 0
8004070148 6004070149 6004070170 6004070171 8004070173	8004070150 8004070144 8004070160 8004070167 8004070167	80/03/17 80/02/20 60/03/10 60/02/15 60/02/15	50-438 40-6659 50-313 50-483 50-483	G P Q Q	8004070394 8004070396 8004070401 8004070403 8004070414	8004070383 8004070379 8004070383 8004070287 8004070410	80/02/27 80/03/07 80/02/27 80/03/31 80/03/13	70-364 50-387 70-364 50-313 27-47	Q P
8004070174 8004070177 8004070178 8004070180 8004070183	8004070172 8004070150 8004070175 8004070148 8004070179	80/02/07 80/03/17 80/02/20 80/03/14 80/03/19	50-373 50-438 50-275 8ECY 50-250	0 0 F	B004070416 B004070420 B004070421 B004070426 B0040B0005	8004070409 8004070409 8004070418 8004070417 8004080003	80/03/07 80/03/07 80/03/13 80/03/11 80/03/13	50-289 50-289 50-10 State Pro	G H Og P
8004070188 8004070199 8004070202 8004070205 8004070207	8004070184 8004070195 8004070187 8004070194 8004070203	80/03/04 80/02/26 80/02/26 80/03/19 80/02/07	50 324 50-334 PR 50-3 70-1100	P G H	8004080008 8004080011 8004080013 8004080014 8004080015	8004080003 8004080003 8004080003 8004080009 8004080010	80/03/13 80/03/13 80/03/13 80/03/14 80/03/17	50-295 50-295 50-295 XPDRTLIC 50-250	P P G
8004070208 8004070214 8004070217 8004070218 8004070223	8004070194 8004070194 8004070211 8004070213 8004070213	80/03/19 80/03/19 80/02/07 80/02/28 80/02/28	50-3 50-3 70-135 50-245 50-245	H	8004080023 8004080025 8004080027 8004080027 8004080030	8004080010 8004080019 8004080010 8004080021 8004080010	80/03/19 80/04/01 80/03/19 80/03/11 80/03/19	50-250 50-259 50-250 50-348 50-250	0 0 0
8004070224 8004070226 8004070227 8004070231 8004070233	8004070174 8004070213 8004070194 8004070213 8004070194	80/03/19 80/02/28 80/03/19 80/02/28 80/03/19	50-3 50-245 50-3 50-245 50-3	H G H	8004080033 8004080034 8004080036 8004080038 8004080040	8004080028 8004080021 8004080031 8004080010 8004080021	80/03/13 80/03/11 80/03/07 80/03/19 80/03/11	50-445 50-349 TOPREP 50-250 50-348	M Q Q
8004070236 8004070241 8004070255 8004070256 8004070259	8004070234 8004070239 8004070251 8004070252 8004070251	80/03/27 80/01/10 80/03/12 80/03/25 80/03/12	50~349 ACR8 50~528 50~331 50~528	A B R S	8004080042 8004080043 8004080051 8004080051 8004080053	8004080039 8004080021 8004080037 8004080045 8004080047	80/03/20 80/03/11 80/03/31 80/03/21	XPORTLIC 50-348 COMMISSI 50-289 50-309	G
8004070268 8004070271 8004070276 8004070280 8004070283	8004070246 8004070270 8004070275 8004070277 8004070281	60/03/13 80/03/26 60/03/28 60/03/31 60/04/01	50-336 50-277 50-317 50-334 50-321	P R R R	8004080057 8004080059 8004080060 8004080060 8004080066	8004080055 8004080037 8004080046 8004080037 8004080037	80/02/28 80/03/11 80/03/11 80/03/11	40-3453 COMMISSI FOIA COMMISSI COMMISSI	ON
8004070285 8004070289 8004070291 8004070294 8004070298	8004070284 8004070288 8004070290 8004070293 8004070297	60/03/31 16/60/08 16/60/08 16/60/08	50-289 50-260 50-289 50-329 50-334	P B P R I	6004080067 8004080074 8004080076 8004080060 8004080080	8004080062 8004080062 8004080046 8004080046 8004080078	80/03/31 80/03/31 80/03/18 80/03/18 80/03/13	50-255 50-255 FOIA FOIA 50-275	0
8004070300 8004070302 8004070306 8004070309 8004070310	8004070296 8004070299 8004070290 8004070307 8004070308	80/03/28 80/03/31 80/03/31 80/04/02 80/03/31	50~333 50~443 50~289 50~338 50~382	R P S	8004080084 8004080085 8004080090 8004080090 8004080095	8004080046 8004080079 8004080078 8004080046 8004080046	80/03/18 80/03/25 80/03/13 80/03/18 80/03/18	FOIA XPORTLIC 50-295 50-150 FOIA	0
8004070315 8004070316 8004070321 8004070322 8004070323	8004070295 8004070312 8004070317 8004070320 8004070319	80/03/06 80/03/25 80/03/28 80/03/31 80/03/31	50-400 50-312 50-18 50-255 50-287	9 1 9	800408097 8004080098 8004080108 8004080108 8004080110	8004080073 8004080046 8004080046 8004080071 8004080046	80/03/18 80/03/18 80/03/18 80/03/14 80/03/18	71-9019 FOIA 50-193 COMMISSI FOIA	I DN
8004070324 8004070325 8004070329 8004070330 8004070331	8004070314 8004070319 8004070328 8004070327 8004070295	80/03/04 80/03/31 80/03/31 80/03/26	50-344 50-289 50-433 50-269 50-400	8 R S Q	8004080112 8004080114 800408015 800408015 8004080120	8004080107 8004080109 8004080046 8004080046 8004080046	80/03/18 80/03/19 80/03/18 80/03/18	71-9089 50-354 FOIA FOIA FOIA	8
8004070337 8004070339 8004070342 8004070343 8004070345	8004070333 8004070335 8004070338 8004070335 8004070338	80/04/04 80/03/31 80/03/31 80/03/31 80/03/31	50-324 50-320 50-206 50-320 50-206	S R R R	8004080123 8004080124 8004080127 8004080127 8004080127	8004080046 8004080046 8004080105 8004080122 8004080046	80/03/18 80/03/18 80/03/10 80/02/25 80/03/18	FOIA FOIA CONTRACT 50-338 FOIA	g G
8004070346 8004070347 8004070348 8004070352 8004070355	8004070341 8004070335 8004070338 8004070338 8004070353	80/03/31 80/03/31 80/03/31 80/03/31 80/03/17	50~334 50~320 50~206 50~206 WABTE MG	R R R R	B004080133 B004080134 B004080140 B004080140 B004080141	8004080044 8004080044 8004080044 8004080135 8004080137	80/03/18 80/03/18 80/03/18 80/02/25 80/03/07	FOIA FOIA FOIA 27-47 50-289	U
8004070357 8004070358 8004070359 8004070363 8004070370	8004070338 8004070354 8004070353 8004070360 8004070367	80/03/31 80/02/05 80/03/17 80/04/01 80/03/25	50~206 50~273 WASTE MG TOPREP 50~397	R Q T	8004080142 8004080146 8004080147 8004080148 8004080150	800408044 904080137 804080145 804080446 804080139	80\03\18 80\03\18 80\03\18 80\03\18	FOIA 50-289 27-47 FOIA 50-289	9
8004070371 8004070372 8004070373 8004070374 8004070375	8004070367 8004070367 8004070364 8004070367 8004070341	80/03/25 80/03/25 80/03/25 80/03/25	50-397 50-397 50-367 50-397 50-334	8 H A 8	8004080163 8004080164 8004080167 8004080168 8004080173	8004080159 8004080157 8004080139 8004080160 8004080046	79/09/17 80/03/13 80/02/22 80/03/11 80/03/16	40-2061 50-142 50-289 50-546 FOLA	U Q A

ACCESSION NUMBER			ACCESSION NUMBER	
PRINCIPAL ENCLOSURE DOCUMENT		SUBJECT CATEODRY	PRINCIPAL DATE ENCLOSURE DOCUMENT ISSUED	SUBJECT CATEGORY
8034040197 800404019 8004040198 800404018 8004040197 800404019 8004040206 800404020 8004040208 800404020	1 80/02/29 4 80/03/21 5 80/02/16 5 80/03/30	CONTRACT 50-445 M 50-10 G 50-245 R 50-566 G	8004040410 8004040407 80/02/14 5 8004040411 8004040407 80/02/03 5 8004040413 8004040400 80/03/31 5	0-478 8 0-263 0 0-273 0 0-331 9 0-546 0
8004040213 800404020 8004040217 800404021 8004040222 800404020 8004040233 800404020 8004040234 800404022	2 B0/03/19 1 B0/02/15 2 80/03/05	70-82 CONTRACT 50-414 Q 50-320 H 50-320 H	8004040424 8004040420 80/02/06 5 8004040426 8004040416 80/04/01 5 8004040427 8004040419 80/03/24 F	OIA 0-424 Q 0-321 S DIA 0-424 Q
8004040237 800404021 8004040242 800404023 8004040245 800404021 8004040248 800404021 8004040250 800404023	2 80/02/05 4 80/03/03 5 80/03/03	50-320 H 50-280 H 50-320 H 50-320 H	8004040432 8004040419 80/03/24 F 8004040404 8004040425 80/03/28 5 8004040437 8004040419 80/03/24 F	0-320 H 0IA 0-335 R 0IA 0-366 S
8004040253 800404021 8004040254 800404024 8004040256 800404024 8004040257 800404024 8004040258 800404022	9 80/03/26 6 80/01/29 7 80/02/28	50-320 H 50-336 F ACRS 50-320 H 50-320 H	8004040442 8004040419 80/03/24 F 8004040443 8004040425 80/03/28 5 8004040444 8004040436 80/02/16 5	0-315 0 0IA 0-335 R 0-315 Q 0-302 0
8004040259 800404023 8004040262 800404025 8004040263 800404023 8004040265 800404021 8004040267 800404026	2 80/02/05 3 80/03/03 8 80/03/03	50-280 0 50-285 0 50-320 F 50-320 F 50-409 0	8004040447 8004040439 80/03/18 5 8004040448 8004040425 80/03/28 5 8004040449 8004040439 80/03/18 5	0-8760 0-302 @ 0-335 R 0-302 @ 0-302 @
8004040274 800404027 8004040275 800404027 8004040277 800404027 8004040280 800404027 8004040287 800404028	1 60/01/17 2 60/03/11 8 60/03/28	NUREG ACRB NUREG 50-341 A	B004040454 8004040435 80/03/07 C 8004040464 8004040435 80/03/07 C 8004040475 8004040471 80/02/16 5	0-2061 ONTRACT ONTRACT 0-327 0 A999
8004040288 800404028 8004040289 800404023 8004040272 800404025 8004040275 800404025 8004040276 800404025	80/02/05 80/01/17 1 80/03/29	50-219 5 50-280 0 ACRS 50-317 0 50-317 0	8004070009 8004070006 80/03/14 0 8004070014 8004070010 80/03/17 7 8004070015 8004070011 88/03/07 8	ONTRACT ONTRACT 1-9079 0-320 P 1-9080
8004040277 800404025 8004040278 800404028 8004040279 800404028 8004040301 800404025 8004040311 800404030	90/01/17 95 80/02/20 91 80/03/29	50-261 F ACRS 50-315 C 50-317 C 50-155 F	8004070032 8004070029 80/03/20 0 8004070034 8004070029 80/03/08 8 8004070034 8004070033 80/03/19 8	1-185 DNTRACT PORTLIC 0-285 G 0-400 G
8004040323 800404033 8004040324 800404033 8004040333 800404033 8004040333 800404033	7 80/03/31 9 80/03/31 8 80/03/31	50-261 F 50-272 S 50-271 S TOPREP TOPREP	8 8004070043 8004070039 80/03/07 8 8 8004070049 8004070046 80/03/03 7 8 8004070054 8004070046 80/03/09 7	0-271 P 0-400 G 0-143 0-143
8004040338 800404031 8004040339 800404031 8004040343 800404034 8004040344 800404033 8004040345 800404033	6 80/02/20 80/04/01 86 80/03/27	50-213 F 50-275 C 50-358 S 50-320 E 50-458 A	9004070053 8004070056 80/03/26 8 8004070056 8004070056 80/03/26 8 8004070071 8004070070 80/03/17 3	00-498 Q 00-281 Q 00-281 Q 00-483 H 00-327 H
8004040347 800404032 8004040348 800404047 8004040347 800404032 8004040350 800404034 8004040351 800404034	6 80/03/10 6 80/03/27 0 80/04/01	50-250 (0A979 50-320 8 50-358 1 50-250 (8004070081 8004070076 80/03/04 0 8004070083 9004070076 80/03/04 0 8004070087 8004070076 80/03/04 0	14999 14999 14999 14999
8004040352 800404047 8004040355 800404034 8004040356 800404033 8004040359 800404033 8004040360 800404032	0 80/04/01 5 80/01/22 4 80/03/31	GA999 90-358 1 50-458 A 50-334 F 50-250 G	8004070098 8004070094 79/12/31 8 8004070099 8004070089 80/03/04 4 8004070100 8004070096 80/02/22 0	14797 50-3 P 10-4329 50NTRACT 10-4329
8004040361 800404047 8004040364 800404036 8004040365 800404032 8004040367 800404036 8004040368 800404036	3 80/01/30 8 80/01/30 9 80/01/30	0A797 30-458 A 50-250 G 50-458 A 50-483 E	8004070107 8004070089 80/03/04 8 8004070109 8004070102 80/03/05 8 8004070110 8004070102 80/03/05 8	60-443 Q 10-6327 30-443 Q 50-443 Q
8004040372 800404037 8004040373 800404037 8004040374 800404037 8004040383 800404035 8004040384 800404037	0 80/02/22 1 80/03/31 8 80/03/10	50-458 A 50-458 A 50-255 R 50-269 G 50-458 A	8004070117 8004070114 80/03/04 5 8004070118 8004070113 80/03/11 5 8004070117 8004070115 80/02/07 7	70-1100 50-322
8004040386 800404037 8004040387 800404038 8004040389 800404038 8004040371 800404037 800404037 800404038	0 B0/03/31 5 B0/04/02 7 B0/03/27	50-458 A 50-250 R 50-2 P 50-438 8 50-250 R	8004070123 8004070114 80/03/04 5 8004070132 8004070127 80/03/05 8004070135 8004070130 80/03/06 5	30-322 0 30-322 0 30-155 H 30-341 0 50-155 H
8004040377 800404037 8004040402 800404035 8004040403 800404037 8004040404 800404037 80040404040 800404040	6 80/03/10 6 80/03/10	50-315 G 50-269 G 71-35 50-298 R 50-220 R	8004070142 8004070139 80/02/29 5 8004070152 8004070147 80/03/13 8004070155 8004070144 80/02/20 4	ONTRACT 80-295 G 71-24 80-6659 50-438 G

SUBJECT CATEGORY

0

q

P P P

M Q

50-387 50-387 70-364 50-387 70-364

70-364 50-387 70-364 50-313 27-47

50-287 Q 50-287 Q 50-10 H State Prog 50-295 P

50-275 50-275 50-275 XPORTLIC 50-250

50-250 50-259 50-250 50-348 50-250

50-445 50-348 TOPREP 50-250 50-348

XPORTLIC 50-348 Q COMMISSION 50-207 Q 50-307 P

40-3453 COMMIBBION FOIA COMMISSION COMMISSION

50-255 50-255 FOIA FOIA 50-295

FOIA XPORTLIC 50-295 50-150 FOIA

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSIO					ACCEBBI	ON NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE
B004070159 B004070162	B004070144 B004070157	80/02/20	40-6659 50-10 40-6659		80040703B 80040703B	8004070379 8004070379	80/03/07 80/03/07 80/03/27
8004070144 8004070165 8004070166	8004070144 8004070160 8004070157	80/02/12 80/03/10 80/02/20	50-313 50-10	P Q	8004070391 8004070391 8004070391	8004070377 8004070383	80/03/07 80/02/27
8004070168 8004070169 8004070170 8004070171	8004070144 8004070160 8004070167	80/03/17 80/02/20 80/03/10 80/02/15	50-438 40~6659 50-313 50-483	Q P Q	800407039- 800407039- 800407040: 8004070400	8004070377 8004070383	80/02/27 80/03/07 80/02/27 80/03/31
8004070173 8004070174	8004070167 8004070172	80/02/15	50~483 50~373	a	800407041	8004070410	80/03/13 80/03/07
8004070177 8004070178 8004070180 8004070183	8004070150 8004070175 8004070148 8004070179	80/03/17 80/02/20 80/03/14 80/03/17	50-438 50-275 8ECY 50-250	0 0 F	800407042(800407042) 800407042(800408000)	8004070418 6004070417	80/03/07 80/03/13 80/03/11 80/03/13
8004070188 8004070199 8004070202 8004070205 8004070207	8004070184 8004070195 8004070187 8004070194 8004070203	80/03/04 80/02/26 80/02/26 80/03/19 80/02/07	50 -324 50 -334 PR 50-3 70-1100	e a H	B0040B0001 B0040B001 B0040B001 B0040B001 B0040B001	8004080003 8004080003 8004080009	80/03/13 80/03/13 80/03/13 80/03/14 80/03/19
8004070208 8004070214 8004070217 8004070218 8004070223	8004070194 8004070194 8004070211 8004070213 8004070213	80/03/19 80/03/19 80/02/07 80/02/28 80/02/28	50-3 50-3 70-135 50-245 50-245	H G G	B0040B002: B0040B002: B0040B002: B0040B002: B0040B003:	8004080019 8004080010 8004080021	80/03/19 80/04/01 80/03/19 80/03/11 80/03/19
8004070224 8004070226 8004070227 8004070231 8004070233	6004070194 6004070213 6004070194 6004070213 6004070194	80/03/19 80/02/29 80/03/19 80/02/29 80/03/19	50-3 50-245 50-3 50-245 50-3	H G H	800408003 800408003 800408003 800408003 800408004	8004080021 8004080031 8004080010	80/03/13 80/03/11 80/03/07 80/03/19 80/03/11
8004070236 8004070241 8004070255 8004070256 8004070258	8004070234 8004070239 8004070251 8004070252 8004070251	80/03/27 80/01/10 80/03/12 80/03/25 80/03/12	50-369 ACR8 50-528 50-331 50-528	A S R S	8004080042 8004080044 8004080004 8004080055 8004080055	8004080021 8004080037 8004080045	80/03/20 80/03/11 80/03/31 80/03/21
8004070248 8004070271 8004070276 8004070280 8004070283	8004070266 8004070270 8004070275 8004070277 8004070281	80/03/13 80/03/26 80/03/28 80/03/31 80/04/01	50-334 50-277 50-317 50-334 50-321	P R R R	8004080057 8004080055 8004080066 8004080066 8004080066	8004080037 8004080046 8004080037	80/02/28 80/03/11 80/03/18 80/03/11
8004070285 8004070287 8004070291 8004070294 8004070298	8004070284 8004070288 8004070290 8004070293 8004070297	80/03/31 80/03/31 80/03/31 80/03/31 80/03/31	50-289 50-260 50-289 50-329 50-334	P 8 P R 1	800408006; 800408007; 800408007; 800408008; 800408008;	8004080062 8004080046 8004080046	80/03/31 80/03/31 80/03/18 80/03/18
8004070300 8004070302 8004070306 8004070309 8004070310	8004070296 8004070299 8004070290 8004070307 8004070308	80/03/28 80/03/31 80/03/31 80/04/02 80/03/31	50-333 50-443 50-269 50-338 50-382	# 1 9 5 8	800408008 800408008 800408008 800408009 800408099	8004080079 8004080078 8004080044	80/03/18 80/03/13 80/03/18 80/03/18
8004070315 8004070316 8004070321 8004070322 8004070323	8004070295 8004070312 8004070317 8004070320 8004070319	80/03/06 80/03/25 80/03/28 80/03/31	50-400 50-312 50-18 50-255 50-289	G 9 1 9	8004080097 8004080097 8004080107 8004080107 8004080117		
8004070324 8004070325 8004070329 8004070330 8004070331	8004070314 8004070317 8004070328 8004070327 8004070295	80/03/26 80/03/31 80/03/28 80/03/06	50-346 50-287 50-433 50-269 50-400	8 P R 9 G	800408011 800408011 8004080111 8004080111		
8004070337 8004070339 8004070342 8004070343 8004070345	8004070333 8004070335 8004070338 8004070335 8004070338	80/04/04 80/03/31 80/03/31 80/03/31 80/03/31	50-324 50-320 50-206 50-320 50-206	\$ R R R			
8004070346 8004070347 8004070348 8004070352 8004070355	8004070341 8004070335 8004070338 8004070338 8004070353	80/03/31 80/03/31 80/03/31 80/03/31 80/03/17	50-334 50-320 50-206 50-206 WASTE MG	B R R R			
8004070357 8004070358 8004070359 8004070363 8004070370	8004070338 8004070354 8004070353 8004070360 8004070367	80/03/31 80/02/05 80/03/17 80/04/01 80/03/25	50-206 50-293 WASTE MG TOPREP 50-397	R Q T			
8004070371 8004070372 8004070373 8004070374 8004070375	8004070367 8004070367 8004070364 8004070367 8004070341	80/03/25 80/03/25 80/03/13 80/03/25 80/03/31	50-397 50-397 50-367 50-397 50-334	AAHAS			

ACCESS!ON				ACCESS10	ON NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	ENCLOSURE	DOCUMENT ISS	ATE SUBJECT SUED CATEGORY
8004080176 8004080179 8004080183 8004080184 8004080186	8004080137 8004080046 8004080178 8004080046 8004080180	80/02/22 80/03/18 80/03/19 80/03/18 80/03/14	50-289 G FOIA 50-339 G FOIA 50-155 G	8004080424 8004080427 8004080435 8004080433 8004080438	8004080420 80/0 8004080422 80/0 8004080429 80/0 8004080436 80/0	03/27 50-445 M 04/02 50-267 B 03/12 50-454 Q 04/01 50-255 R 02/28 50-317 P
8004080168 8004080190 8004080192 8004080196 8004080200	8004080046 8004080182 8004080046 8004080046 8004080175	90/03/18 90/02/27 90/03/18 90/03/18 90/03/17	FOIA 50-373 Q FOIA FOIA 50-289 Q	8004080446 8004080450 8004080459 8004080459 8004080454	8004080442 80/0 8004080448 80/0 8004080453 80/0 8004080455 80/0	04/01 50-344 R 02/19 50-213 Q 04/03 50-325 B 04/04 50-369 A 04/04 50-369 A
8004080202 8004080204 8004080206 8004080208 8004080210	8004080046 8004080046 8004080173 8004080046 8004080207	80/03/18 80/03/18 80/03/05 80/03/18 80/02/24	FOIA FOIA 50-3 U FOIA 40-1341	6004080462 6004080463 6004080464 8004080467 8004080475	8004080456 80/0 8004080458 80/0 8004080457 80/0	04/01 50-305 8 03/26 50-249 8 03/28 50-324 6 04/01 50-305 8 04/02 50-155 8
8004080211 8004080213 8004080216 8004080218 8004080220	8004080046 8004080179 8004080046 8004080212 8004080217	80/03/18 80/03/11 80/03/19 80/03/06 80/02/29	FOIA 70-2254 FOIA 50-387 U 50-183 R	8004080476 8004080482 8004080483 8004080484 8004080484 8004080486	8004080474 80/0 8004080477 80/0 8004080478 80/0 8004080474 80/0	04/04 50-269 8 04/02 50-280 8 04/02 50-206 8 04/03 50-282 8 04/02 50-280 8
8004080222 8004080227 8004080229 8004080230 8004080231	8004080046 8004080223 8004080223 8004080179 8004080223	80/03/18 80/03/07 80/03/07 80/03/11 80/03/07	FOIA COMMISSION COMMISSION 70-2254 COMMISSION	8004080487 8004080488 8004080496 8004080498 8004080501	8004080480 8070 8004080487 8070 8004080491 8070	04/01 50-133 8 04/02 50-318 8 04/04 50-29 B 04/04 50-206 P 03/31 50-348 R
8004080234 8004080241 8004080248 8004080250 8004080259	8004080223 8004080237 8004080199 8004080243 8004080104	80/03/07 80/03/18 80/03/11 80/03/06 80/03/25	COMMISSION CONTRACT 70-2254 COMMISSION XPORTLIC	8004080504 8004080504 8004080507 8004080507 8004080512	8004080491 80/6 8004080500 80/6 8004080506 80/6	04/02 50-334 I 04/04 50-206 P 04/03 50-317 8 04/01 50-344 P 04/02 50-267 9
8004080262 8004080264 8004080265 8004080266 8004080267	8004080255 8004080260 8004080257 8004080258 8004080255	80/03/14 80/03/10 80/03/20 80/03/17 80/03/14	0A999 50-409 U 50-335 R 50-333 G 0A999	B0040B0521 B0040B0524 80040B0524 B0040B0527 B0040B0531	8004080511 B0/0 8004080519 B0/0 8004080510 B0/0	03/28 50-387 8 04/01 50-293 R 04/02 50-327 8 04/02 50-316 8 03/31 50-331 8
8004080271 8004080272 8004080274 8004080276 8004080279	8004080258 8004080255 8004080258 8004080255 8004080255	80/03/17 80/03/14 80/03/17 80/03/14 80/03/14	50-333 G 97779 50-333 G 97779	8004080533 8004080545 8004080545 8004080547 8004080547	B004080528 B076 B004080510 B076 B004080540 B076	04/01 50-272 9 04/03 50-338 8 04/02 50-316 8 04/02 50-348 8 03/25 50-10 8
8004080280 8004080282 8004080285 8004080287 8004080289	8004080275 8004080258 8004080273 8004080255 8004080286	80/03/19 80/03/19 80/03/06 80/03/14 80/02/29	50-320 U 50-333 Q 50-445 M QA999 50-18 R	E004080551 8004080554 8004080564 8004080564 80040805570	8004080552 8076 8004080552 8076 8004080557 8076	03/31 50-54 R 04/02 50-348 8 03/28 50-249 8 04/01 50-245 I 03/19 70-143
8004080297 8004080300 8004080301 8004080303 8004080305	8004080291 8004080288 8004080271 8004080279 8004080288	80/03/17 80/03/13 80/03/17 80/03/27 80/03/13	QA999 40-1341 QA999 XPORTLIC 40-1341	8004080575 8004080581 8004080599 8004080594 8004080594	8004080557 80/9 8004080557 80/9 8004080588 80/9	03/31 50-325 8 04/01 50-245 I 04/01 50-245 I 02/26 50-155 @ 04/01 50-348 8
6004080306 6004080307 6004080310 8004080313 6004080314	8004080291 8004080288 8004080294 8004080308 8004080288	80/03/17 80/03/13 80/02/20 80/02/27 80/03/13	QA999 40-1341 50-237 P 50-73 R 40-1341	8004080597 8004080608 8004080608 8004080610 8004080622	8004080600 B0/0 8004080601 B0/0 8004080603 B0/0	02/05 70~364 02/25 50~267 0 03/31 50~250 9 03/28 CONTRACT 04/02 50~327 B
8004080316 8004080323 8004080325 8004080327 8004080330	8004080291 8004080317 8004080320 8004080320 8004080320	80/03/17 80/03/14 80/03/19 80/03/19 80/03/19	GA979 COMMISSION 50-280 P 50-280 P	8004080623 8004080628 8004080628 8004080631 8004080633	8004080417 80/0 8004080415 80/0 8004080415 80/0	01/07 ACR8 02/29 50-254 Q 01/09 ACR8 01/09 ACR8 02/20 50-373 Q
B004080333 B004080340 B004080341 B004080343 B004080344	8004080324 8004080326 8004080324 8004080334 8004080324	80/03/08 80/01/14 80/03/08 80/03/14 80/03/08	50-317 Q CONTRACT 50-317 Q 70-135 50-317 Q	8004080537 8004080540 8004080646 8004080647 8004080647	8004080637 80/9 8004080615 80/9 8004080629 80/9	01/09 ACRB 03/18 50-263 Q 01/09 ACRB 02/20 50-373 Q 03/24 50-341 Q
8004080346 8004080352 8004080354 8004080359 8004080365	8004080334 8004080324 8004080334 8004080358	80/03/14 80/03/08 80/03/14 80/03/05 80/03/14	70-135 50-317 Q 70-135 50-70 R QA999	8004080653 8004080653 8004080666 8004080661 8004080696	8004080615 80/ 8004080654 80/ 8004080615 80/	03/11 50-309 H 01/09 ACRB 03/14 50-387 A 01/09 ACRB 02/14 50-285 Q
8004080369 8004080379 8004080380 8004080382 8004080389	8004080358 8004080358 8004080374 8004080358 8004080358	80/03/14 41/20/08 20/40/08 41/20/08 41/20/08	QA999 QA999 50-302 P QA999 QA999	8004080707 8004080714 8004080733 8004090008 8004090017	8004080703 80/ 8004080580 80/ 8004090005 80/	03/31 50-289 P 03/31 50-289 P 02/04 70-135 03/19 50-272 0 03/31 71-380
8004080394 8004080405 8004080408 8004080411 8004080412	8004080390 8004080402 8004080402 8004080406 8004080402	80/03/91 40/03/08 40/03/08 90/03/91 80/03/06	50-272 P 50-255 P 50-255 P 50-309 R 50-255 P	8004070035 800407004 8004070041 8004070045 8004090059	8004090032 80/ 8004090032 80/ 8004090032 80/	03/18 50-321 0 03/18 50-321 0 03/18 50-321 0 03/18 50-321 0 03/10 0A979

ACCESS	ION NUMBER								
ENCLOSURE	POCOMENI	IECHE	SUB		ACCESE	PRINCIPAL	DATE	SUBJE	ст
800409007 800409007	1 800409005			GORY	£NCL D∃URE	DOCUMENT	ISSUED	CATEG	98V
800409007 800409008	B00409006	7 60/02/2 7 60/02/2	2 0A999	1	800409037 600409037	7 8004090371	80/03/20	50~409 0A999	₽.
800409008	800407005	7 80/02/2 8 80/02/2	2 04999		600407037 600407038	0 8004090375	80/03/31	70- (25) 50-54 04999	R
800409008 8004090108	800409010	2 90.000			800409038 800409038			50~255	a
8004090112 8004090121 800409013	800409010 800409011	2 80/03/1	3 70-12	57	800407038 800407039	6 8004090371	80/03/20	QA999 50~438	a
8004090137	4.07013	0 80\05\5	2 50-33		800407037 800407040	4 8004090389		50~255 50~518	P 0
8004090138 8004090140	800409013	1 80/02/0	50-21		800407040		00/02/12	50~293	G
8004090146 8004090146	B00400014	B0/03/2	50-54	5 0	800407040; 800407041; 800407041;	8004090405	80/03/13 80/02/20 80/03/13	70~135 50~327 70~135	a
8004090153	8004090151	1 80/02/0		-	B00409042		80/02/14	50-219	G
8004090159 8004090143	8004070151 8004090133	80/02/01	50-31	3 a	8004090424 8004090424		80/03/24 80/04/01	50~346 50~327	G B
8004090169 8004090169	8004090165 8004090166	5 80/01/01	PR		5004090431 8004090433	8004090429	80/03/18 80/04/03	50-305 50-327	8
8004090170 8004090174	B004090166 B004090166	80/03/12	50-250	-	800409043E 800409044C		60/02/13	50-352	G -
8004090194 8004090195	8004090191 8004090173	B0/02/29	50-184	a	8004070441 8004070441 8004070457	8004090432	80/04/03 80/02/26 80/04/03	50-333 50-443 50-327	9
8004090196	8004090188	80/02/15		o o	8004090464 8004090472	8004090461	80/03/26 80/04/03	TOPREP 50-293	6 P
8004090200 8004090202 8004090203	8004090191 8004090198	80/03/21		0 21	B004090473		80/03/06	50-293	Q.
8004090210 8004090211	8004090201 8004090205		71-373	a	800409 04 75 8004090476	8004090470	80/03/31 80/04/03	50-293 50-293	M P
6004090215	8004090191 8004090205	80/03/10		_	8004090478 8004090479		80/04/03 80/04/03	50-320 50-320	1
8004090219 8004090219	8004070214 8004070217	80/03/13 80/03/21 80/03/31	50-201 71-372	<u>a</u>	8004070480 80040704 9 1	8004090477 8004090477	80/04/03 80/04/03	50-320 50-320	I I
8004090221 8004090225	B004090205 B004090220	80/03/13 80/03/17	50-335 50-201 71-9	R Q	8004070482 8004070483	8004090477 8004090477	B0/04/03 B0/04/03	50-320 50-320	Ĭ I
8004090224	8004090222	80/03/21	71-375		8004070484	9004090477	80/04/03	50-320	Ĭ
8004090230 8004090235 8004090237	8004070227 8004070232	80/03/21 80/03/13	71-165 70-143		8004090485 8004100005 8004100007	8004090263 8004100001	80/03/17	GENTRACT GA999	
8004090240	8004070232 8004070232	80/03/13 80/03/13	70-143 70-143		8004100D07 8004100D01	8004100003 8004100003 6004100003	80/03/05 80/03/05 80/03/05	50-184 50-184	G G
8004090244 8004090246	8004090232 8004090238	80/03/13 80/03/04	70-143 50-219	Q.	8004100014	B004100003	80/03/05	50-184 50-164	() ()
B004090249 B004090251	800409023B 800409024B	80/03/04	50-219 50-329	Q X	8004100015 8004100016	B004100010 B004100013	80/03/24 80/02/21	50-289 50-346	Ģ G
8004090252 8004090256	8004090245	80/02/19	50-259	a	8004100022 8004100023	B004100013 B004100020	80/02/21	50-346 CONTRACT	0
8004090258 8004090262	8004090238 8004090248 8004090238	80/03/04 80/03/31 80/03/04	50-219 50-329	K	8004100030 8004100034	B004100026 B004100031	80/02/19 80/02/19	70-820	
8004090269 8004090273	8004070260 8004070270	80/03/04 80/03/20 80/03/27	50-219 50-586 71-377	G H	8004100038 8004100039	8004100036 8004100033	80/03/28	9A999 71-9020 1OCFR	
8004090274	8004090268	80/03/10	50-320	н	8004100040	8004100035	80/03/11	5D-443	æ
8004090277 8004090276	8004090275 8004090272	80/03/19	50-250 50-373	F O	8004100045 8004100050 8004100051	8004100041 8004100041	80/02/26	PR PR	
8004090279 8004090283	8004090276 8004090281	80/03/10 80/03/17	50-320 50-289	H	8004100055 8004100056	8004100045 8004100041	80/02/26	50-416 PR	Q.
8004090285 8004090287	8004090280 8004090282	B0/02/04 B0/03/14	70-135 0A999		8004100068				
8004090290 8004090291	8004090282 8004090284	80/03/14 80/02/21	0A999 50-348	a	8004100070 8004100077				
8004090293	80040902B2	80/03/14	QA979		8004100091 8004100092				
8004090295 8004090299 8004090301	8004090289 8004090282 8004090297	80/03/17 80/03/14	50-289 0A999	•	8004100098 8004100103				
8004070302 8004070304	8004070277 8004070274 8004070303	80/01/28 80/02/21 80/04/03	SECY 70-1201 50-298	R	8004100102 8004100111				
8004090306	8004090297	80/01/28	SECY	1,	8004100112				
8004090310 8004090311	8004070307 8004070308	80/02/15 80/04/02	0A979 50-336	s	8004100127 8004100126 8004100130				
8004090315 8004090317	8004070313 8004070314	80/04/03 80/03/06	50-302 50-355	8	8004100142 8004100145				
8004090320 8004090327	8004070318 8004070317	80/04/02 80/02/25	50~333 50-2	R	8004100150				
8004090330 8004090336	8004090329 8004090333	80/03/26 80/04/03	50-219 50-327	9	8004100154 8004100157				
8004090345	B004090341	80/04/03	50-416	A	8004100158 8004100160				
8004090350 8004090355	8004070341 8004070351	80/04/03	50-416 50-302	A	8004100164 8004100168				
8004090361 8004090368	8004090356 8004090365	80/03/19 80/04/04	70-143 50-416 50-280	M G	8004100173 8004100192				
8004090374	8004090366	80/02/21	JU-48U	u	8004100188				

ACCESSION					AC	CESSION				
ENCLOSURE	PRINCIPAL	DATE	SUBJECT CATEGORY	,	ENCLD		PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8004100191 8004100194 8004100200 8004100201 8004100202	8004100185 8004100189 8004100198 8004100197 8004100195	80/03/17 80/03/24 80/03/31 80/03/13 80/02/20	70-33 CONTRACT 71-6679 70-135 50-250	a	80041 80041 80041	100431 100432 100436	8004100428 8004100429 8004100426 8004100435 8004100435	80/03/31 80/03/31 80/02/26 80/03/13 80/03/13	10CFR 50-10 50-287	— М 0 0
8004100204 8004100207 8004100208 8004100209 8004100216	8004100197 8004100192 8004100205 8004100197 8004100212	80/03/13 80/02/28 80/03/28 80/03/13 80/03/28	70-135 50-254 71-5908 70-135 71-6272	a	80041 80041 80041	100447 100450 100455	8004100442 8004100442 8004100440 8004100451 8004100440	80/03/20 80/03/20 80/02/26 80/03/19 80/02/26	30-498 30-514 50-155	M T Q T
8004100219 8004100223 8004100224 8004100225 8004100227	8004100214 8004100214 8004100220 8004100214 8004100226	80/03/18 80/03/18 80/03/28 80/03/18 80/04/01	50-201 50-201 71-6574 50-201 71-97	0 0	80041 80041 80041	100463 100465 100467	8004100451 8004100454 8004100451 8004100458 8004100451	80/03/19 80/03/14 80/03/19 80/03/21 80/03/19	70-1151 50-155 50-251	Q Q P Q
8004100230 8004100234 8004100236 8004100242 8004100244	8004100228 8004100214 8004100231 8004100239 8004100233	80/03/28 80/03/18 80/04/01 80/03/27 80/04/03	71-9073 50-201 71-96 71-49 50-133	G I	60041 80041 80041	100472 100473 100475	B004100456 B004100440 B004100458 B004100458 8004100476	80/03/14 80/02/26 80/03/21 80/03/21 80/03/17	50-251 50-251	T P P
8004100244 8004100251 8004100252 8004100254 8004100255	8004100241 8004100241 8004100245 8004100250 8004100241	80/03/31 80/03/31 80/03/03 80/03/28 80/03/31	50-312 50-312 50-329 71-9009 50~312	P Q P	80041 80041 80041	100482 100490 100491	8004100451 8004100455 8004100485 8004100487 8004100481	80/03/19 80/03/14 80/03/28 80/03/25 80/02/04	70-1151 REVIEW GR MISC	9 P Q
8004100257 8004100262 8004100263 8004100266 8004100267	8004100249 8004100259 8004100249 8004100249 8004100260	80/03/26 80/03/26 80/02/26 80/02/26	40-8452 71-4078 40-8452 40-8452 50-329	o	80041 80041 80041	100500 100503 100505	8004100485 8004100492 8004100481 8004100481 9004100481	80/03/28 80/03/15 80/02/04 80/02/04 80/02/04	50-566 50-566	P G G
8004100272 8004100273 8004100275 8004100276 8004100278	8004100249 8004100264 8004100268 8004100249 8004100271	80/03/26 80/03/13 80/03/21 80/02/26 80/03/26	40-8452 50-344 50-250 40-8452 50-445	Q P M	80041 80041 80041	100513 100519 100520	8004100508 8004100509 800410050B 8004100517 800410050B	80/03/04 80/02/12 80/03/04 80/03/20 80/03/04	COMM18810 50-320 080	0 N 0
8004100281 8004100282 8004100283 8004100284	8004100268 8004100264 8004100269 8004100268 8004100279	80/03/21 80/03/13 80/03/03 80/03/21 80/03/17	50-250 50-344 50-282 50-250 50-289	P 0 0 P 0	80041 80041 80041	100524 100525 100528	8004100518 8004100523 8004100514 8004100518 8004100508	80/02/22 80/03/20 80/03/10 80/02/22 80/03/04	CONTRACT 50-445 50-254	Q M Q
8004100268 8004100287 8004100270 8004100271 8004100275	8004100264 8004100265 8004100267 8004100287 8004100264	80/03/13 80/03/11 80/03/03 80/03/31	50-344 50-155 50-282 50-544 50-344	0 F 0 0	80041 80041 80041	100344 100551 100555	8004100529 8004100540 8004100548 8004100550 8004100552	80/03/20 80/02/15 80/02/13 80/02/05 80/04/07	CONTRACT PR 40-261 70-135 50-445	H
8004100298 8004100298 8004100303 8004100324 8004100332	8004100293 8004100293 8004100264 8004100315 8004100329	80/03/13 80/03/13 80/03/13 80/02/08 80/04/01	50-155 50-155 50-344 50-313 71-273	000	80041 80041 80041	100567 100575 100576	8004100563 8004100563 8004100573 8004100572 8004100574	80/03/14 80/03/14 80/03/28 80/03/18 80/03/27	50-287 50-320 CONTRACT	6 6 H H
8004100335 8004100341 8004100342 8004100345 8004100349	8004100315 8004100336 8004100339 8004100340 8004100346	80/02/08 80/04/01 80/03/27 80/04/04 80/04/01	50-313 71-116 CONTRACT 50-261 71-367	9	80041 80041 80041	00400 204001 804001	8004100581 8004100596 8004100595 8004100606 8004100604	80/03/27 90/03/28 80/02/26 90/03/12 80/02/28	CONTRACT 50~556	H G B
8004100355 8004100356 8004100357 8004100358 8004100363	8004100352 8004100352 8004100354 8004100347 8004100360	80/04/01 80/04/01 80/02/15 80/02/27 80/03/24	50-217 50-219 CONTRACT 50-334 CONTRACT	Q	80041 80041 80041	100612 100613 110018	8004100595 8004100604 8004100611 8004110015 8004110014	80/02/26 80/02/28 80/03/12 80/03/12 80/04/03	PR 50-311 70-1151	9 8 9
8004100367 8004100369 8004100373 8004100374 8004100377	8004100365 8004100366 8004100347 8004100370 8004100372	80/03/24 80/03/17 80/02/27 80/03/31 80/02/29	50-302 CONTRACT 50-334 50-29 50-150	P Q R Q	80041 80041 80041	110027 110037 110044	8004110022 8004110015 8004110031 8004110031 8004110038	80/03/19 80/03/12 80/03/25 80/03/25 80/04/02	70-1151 GA999 GA999	F
8004100381 8004100382 8004100383 8004100387 8004100389	8004100375 8004100347 8004100380 8004100384 8004100386	60/03/20 60/02/27 80/02/29 80/04/01 80/04/07	50~320 50~334 50~182 50~327 50~293	0 0 A P	80041 90041 80041	1 10064 1 10081 1 10105	8004110031 8004110031 8004110077 8004110079 8004110121	80/03/25 80/03/25 80/03/20 80/03/14 80/04/02	MISC	0 H
8004100370 8004100391 8004100399 8004100402 8004100404	8004100384 8004100347 8004100376 8004100375 8004100403	80/04/01 90/02/27 90/04/03 80/03/17 90/04/03	50-329 50-334 50-255 50-395 50-255	A 0 8 0 5	B0041 B0041 B0041	1 10151 1 10152 1 10162	8004110144 8004110142 8004110150 8004110155 8004110157	80/03/05 80/04/02 80/02/26 80/03/10 80/03/26	50-440 50-289	0 0
800410040B 8004100409 8004100412 8004100415 8004100416	8004100140 8004100395 8004100395 8004100413 8004100395	80/02/22 80/03/17 80/03/17 80/04/03 80/03/17	50-10 50-375 50-375 50-255 50-375	0 0 5 0	80041 80041 80041	1 10174 1 10223 1 10225	8004110157 8004110150 8004110216 8004110216 8004110230	80/03/26 90/02/26 90/04/01 90/04/01 80/03/05	TOPREP TOPREP	0 0

ACCEBBIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO	
8004110274 8004110271 8004110300 8004110327 8004110386	8004110259 8004110284 8004110284 8004110318 8004110378	80/03/03 80/02/29 80/02/29 80/04/01 80/04/03	50-151 50-456 50-456 50-483 50-346	9 9 9
8004110442 8004110444 8004110449 8004110463 8004110475	8004110437 8004110434 8004110445 8004110457 8004110474	80/04/03 80/04/04 80/03/04 80/04/02 80/04/03	50-286 50-29 50-315 50-245 50-311	S P R P
8004110476 8004110483 8004110488 8004110490 8004110494	8004110472 8004110479 8004110485 8004110487 8004110492	80/04/02 80/04/03 80/04/02 80/04/03 80/03/31	90-366 50-366 50-346 50-346 50-272	8 8 8
8004110498 8004110500 8004110514 8004110524 8004110525	8004110487 8004110497 8004110503 8004110520 8004110519	80/03/27 80/04/03 80/02/27 80/02/28 80/03/17	50-285 50-272 50-259 50-282 50-259	0 0 0 P P
8004110525 8004110527 8004110531 8004110533 8004110536	8004110519 8004110519 8004110519 8004110529 8004110529	80/03/17 80/03/17 80/03/17 80/04/01 80/04/01	50-259 50-259 50-259 50-250 50-250	P P Q G
8004110346 8004110349 8004110550 8004110556 8004110566	8004110541 8004110545 8004110543 8004110548 8004110562	80/03/03 80/03/25 80/03/04 80/03/24 80/03/25	50-289 70-2479 50-243 50-546 50-302	0 0 0
8004110567 8004110575 8004140007 8004140008 8004140013	8004110561 8004110572 8004140004 8004140003 8004140004	80/03/17 80/02/27 80/03/31 80/04/03 80/03/31	50-289 50-395 50-289 50-445 50-289	0 0 0 0
8004140015 8004140017 8004140018 8004140017 8004140020	8004140011 8004140004 8004140011 8004140004 8004140011	80/03/24 80/03/31 80/03/24 80/03/31 80/03/24	0A979 50-289 0A979 50-289 0A999	0 0
8004140023 8004140026 8004140027 8004140028 8004140029	8004140004 8004140022 8004140024 8004140004 8004140011	80/03/31 80/01/17 80/03/17 80/03/31 80/03/24	50-289 50-155 71-249 50-289 QA999	0 Н
8004140031 8004140032 8004140034 8004140037 8004140038	8004140022 8004140004 8004140011 8004140011 8004140004	80/01/17 80/03/31 80/03/24 80/03/24 80/03/31	50-155 50-289 0A999 0A999 50-269	H O
8004140040 8004140043 8004140044 8004140045 8004140048	8004140011 8004140011 8004140041 8004140004 8004140041	80/03/24 80/03/24 80/03/10 80/03/31 80/03/10	QA999 QA999 50-155 50-289 50-155	000
8004140049 8004140051 8004140052 8004140054 8004140055	B004140046 B004140004 B004140047 B004140050 B004140050	80/02/28 80/03/31 80/01/17 80/02/29 80/02/29	50-458 50-289 PR 50-334 50-334	Q Q P P
8004140057 8004140058 8004140059 8004140062 8004140065	8004140004 8004140050 8004140041 8004140004	80/03/31 80/02/29 80/03/10 80/03/31 80/03/31	50-287 50-334 50-155 50-287 50-287	G P G G G
8004140067 8004140070 8004140072 8004140073 8004140076	8004140061 8004140060 8004140068 8004140060 8004140061	80/03/15 80/03/17 80/03/21 80/03/17 80/03/15	50-320 70-1308 PRM 70-1308 50-320	0
8004140077 8004140080 8004140082 8004140084 8004140088	8004140074 8004140074 8004140078 8004140074 8004140085	80/03/17 80/03/17 80/03/03 80/03/17 80/03/20	50-289 50-289 70-1308 50-289 GRO	G 0
8004140075 8004140097 8004140100 8004140104 8004140116	8004140072 8004140073 8004140076 8004140078 8004140113	80/03/20 80/03/24 80/02/08 80/03/21 80/03/20	MISC 50-339 PR 50-443 TOPREP	H

ENGLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC CATEOD	
8004140117	8004140111	80/03/18	50-320	Q
8004140124	8004140114	80/03/31	FOIA	
8004140126	B00414006B	80/03/21	PRM	
8004140127	8004140125	80/03/19		
			50-367	Q
8004140128	8004140068	80/03/21	PRM	
E004140130	B004140125	80/03/19	50-347	Q
8004140131	8004140114	80/03/31	FOIA	
8004140133	8004140068	80/03/21	PRM	
8004140135	8004140060	80/03/21	PRM	
8004140139	8004140048	80/03/21	PRM	
B004140140	8004140069	80/03/21	PRM	
B004140145	8004140068	80/03/21	PRM	
B004140157	B004140154	80/04/04	50-309	R
B0041401B0	8004140169	80/03/31		
			50-10	U
8004140190	8004140186	80/03/26	50-339	н
8004140195	8004140186	80/03/26	50-339	Н
8004140197	8004140183	80/03/28	50-10	U
8004140210	8004140177	80/03/20	40E-06	a
B004140215	8004140208	80/03/28	50-10	υ
8004140224	6004140219	80/04/11	50-281	Ē
8004140230	8004140225	80/03/31	50-10	υ
8004140238	8004140235	80/03/28	50-409	ŭ
8004140262	8004140252	80/03/25	50-358	ŭ
8004140303	8004140299	80/03/21	50-309	U
8004140304	8004140279	80/03/21	50-309	U
8004140311	8004140310	80/04/07	50-293	P
B004140314	8004140312	80/04/01	50-407	P
8004140319	8004140317	80/04/08	50~352	1
8004140322	8004140306	80/03/18	50-295	R
8004140323	8004140320	80/04/09	50-272	8
8004140332	6004140327	80/04/09	50-327	Р
B004140333				
	6004140328	80/04/07	50-313	8
B004140340	B004140330	80/03/19	50-10	R
8004140342	8004140337	80/04/09	50-293	8
8004140344	8004140337	80/04/10	50-282	R
E004140353	8004140350	80/04/07	50-346	R
8004140354	8004140348	80/04/08	50-369	Α
B00414035B	8004140348	80/04/08	50-369	Ä
8004140360	8004140356	80/04/08		8
8004140367	8004140365	80/04/07	50-313	Ř
8004140369	8004140363	80/04/10	50-331	8
8004140377	B004140372	80/04/03	50-320	8
8004140379	8004140374	80/03/21	50-266	U
8004140382	8004140380	80/04/09	50-331	P
8004140405	8004140397	80/04/03	50-312	8
8004140411	B004140406	80/04/03	50-220	R
8004140412	8004140409	80/04/09	50-272	8
8004140422			00-27E	
	8004140416	80/04/10	50-284	8
8004140429	ED04140423	80/03/21	50-237	8
8004140432	Bunganuage	90 104 109	EV-241	a
8004140436				
8004140437				
B004140440				
8004140444				
86				
-				

ACCEBBION NUMBER

ACCESS101	NUMBER				ACCESSIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Υ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8004150110 8004150116 8004150117 8004150118 8004150120	8004150103 8004150103 8004150112 8004150115 8004150103	B0/03/27 B0/03/27 B0/03/19 79/12/10 B0/03/27	50-346 50-346 71-367 70-125/ 50-346	PP	8004150477 8004150479 8004150480 8004150481 8004150486	B004150472 B004150474 B004150473 B004150476 B004150483	80/03/28 80/04/11 80/04/11 80/04/07 80/04/10	50-304 50-255 50-537 50-364 50-318	S P A 8
8004150121 8004150125 8004150127 8004150133 8004150136	8004150112 8004150123 8004150123 8004150132 8004150126	80/03/19 80/03/19 80/03/19 80/03/18 80/04/01	71-367 71-116 71-116 71-97 90-321	Q	9004150487 9004150470 9004150473 8004150474 8004150476	8004150484 8004150484 8004150487 8004150485 8004150484	80/04/14 80/04/14 80/03/31 80/04/03 80/04/14	50-341 50-341 50-213 50-553 50-341	0 8 0
8004150141 8004150142 8004150143 8004150147 8004150147	8004150140 8004150126 8004150139 8004150126 8004150145	80/03/26 80/04/01 80/02/12 80/04/01 80/01/31	HUREG 50-321 50-352 50-321 QA999	0 0	8004150498 8004150510 8004150512 8004150513 8004150514	8004150462 8004150507 8004150500 8004150503 8004150504	80/03/26 80/04/09 80/04/11 80/04/03 80/04/11	50-265 50-315 50-327 50-237 50-271	9 6 6
8004150154 8004150155 8004150156 8004150171 8004150193	800415015) 8004150126 8004150131 8004150166 8004150187	80/04/01 80/04/01 80/04/01 80/03/13 80/02/28	50-335 50-321 50-335 CONTRACT 70-371	Р О Р	8004150520 8004150522 8004150526 8004150529 8004150531	8004150507 8004130515 8004150518 8004150516 8004150507	80/04/03 80/04/07 80/04/02 80/04/08 80/04/03	50-315 50-240 50-304 50-334 50-315	P 9 9 P
8004150200 8004150200 8004150202 8004150210 8004150216	8004150188 8004150197 8004150199 8004150209 8004150211	80/03/11 80/04/14 80/03/21 80/03/24 80/03/26	50-361 50-416 50-445 50-438 50-10	H M S H	8004150532 8004150533 8004150535 8004150535 8004150536	8004150524 8004150528 8004150516 8004150523 8004150525	80/04/09 80/04/08 80/04/08 80/04/11 80/04/10	50-305 50-327 50-334 50-259 50-259	8888
8004150239 8004150250 8004150252 8004150255 8004150260	8004150235 8004150246 8004150246 8004150246 8004150246	80/04/10 80/04/08 80/04/08 80/04/08 80/04/08	50-313 50-277 50-277 50-277 50-277	I I I	8004150537 8004150545 8004150546 8004150547 8004150547	8004150530 8004150516 8004150538 8004150539 8004150541	80/04/10 80/04/08 80/04/07 80/04/08 80/04/08	50-255 50-334 50-361 50-327 50-313	8 8 8
8004150278 8004150280 8004150284 8004150287 8004150305	B004150272 B004150270 B004150272 B004150281 B004150300	80/03/13 80/04/08 80/03/13 80/04/14 80/03/17	71-49 TOPREP 71-49 50-289 70-820	Ρ	8004150552 8004150555 8004150556 8004150558 8004150559	8004150542 8004150543 8004150544 8004150553 8004150551	80/04/09 80/04/08 80/04/10 80/04/11 80/04/09	50-267 50-263 50-255 50-272 50-327	8888
8004150319 8004150322 8004150325 8004150328 8004150331	8004150312 8004150320 8004150320 8004150316 8004150327	80/04/11 80/04/02 80/04/02 80/04/02 80/04/11	50-516 50-245 50-245 50-10 50-244	0 1 1 P	8004150564 8004150565 8004150570 8004150571 8004150572	8004150543 8004150554 8004150563 8004150543 8004150562	80/04/08 80/04/11 80/04/10 80/04/08 80/04/07	50-263 50-327 50-346 50-263 50-366	8 8
8004150332 8004150334 8004150335 8004150336 8004150347	8004150329 8004150329 8004150329 8004150333 8004150345	80/04/11 80/04/11 80/04/11 80/04/07 80/04/09	50-244 50-244 50-244 50-267 50-206	P P R R	8004150579 8004150580 8004150589 8004150589 8004150589	8004150567 8004150543 8004150573 8004150576 8004150543	80/04/09 80/04/08 80/04/08 80/04/02 80/04/08	50-348 50-243 50-259 50-293 50-243	F 8 8 8
8004150351 8004150352 8004150355 8004150361 8004150365	8004150349 8004150350 8004150354 8004150360 8004150363	80/04/11 80/04/11 80/04/09 80/04/11 80/04/08	50-287 50-29 50-305 50-271 50-316	P R R R	8004150590 8004150596 8004150598 8004150601 8004150603	8004150567 8004150581 8004150543 8004150567 8004150587	80/04/09 80/04/09 80/04/09 80/04/09 B0/04/10	50-368 50-305 50-263 50-368 50-282	F 88 F 8
8004150370 8004150371 8004150376 8004150384 8004150385	8004150367 8004150368 8004150374 8004150380 8004150383	80/04/11 80/04/08 80/04/09 80/04/09 80/04/10	50-309 50-315 50-261 50-244 50-366	R R R R	8004150609 8004150610 8004150611 8004150615 8004150617	8004150599 8004150543 8004150582 8004150608 8004150543	80/04/10 80/04/08 80/04/09 80/04/11 80/04/08	50-3 50-263 50-267 50-327 50-263	R 8 8 P 8
8004150387 8004150389 8004150390 8004150395 8004150396	8004150382 8004150386 8004150398 8004150391 8004150392	80/04/10 80/04/10 80/04/10 80/04/02 80/04/11	50-10 50-272 50-321 50-285 50-553	R R R R	9004150618 8004150620 9004150623 8004150634 8004150638	8004150605 8004150606 8004150543 8004150626 8004150624	80/04/11 80/04/10 80/04/08 80/04/09 80/04/10	50-368 50-317 50-263 50-247 50-318	8 8 8
'4 5 7	8004150399 8004150401 8004150320 8004150406 3004150414	80/04/10 80/04/10 80/04/02 80/04/08 80/04/03	50-321 50-243 50-245 50-250 50-518	R R I I S	8004130641 8004160007 8004160019 8004160030 8004160039	8004150630 8004160004 8004160004 8004160024 8004160034	80/04/07 80/03/20 80/03/20 80/03/10 80/03/26	50-313 50-272 50-272 CDMMI88 50-320	8 0 0 10N 19
	3004150416 3004150420 3004150426 3004150432 3004150435	80/04/03 80/04/11 80/04/11 80/04/09 80/04/07	50-373 50-382 50-348 50-267 50-275	A R S A	8004160050 8004160062 8004160072 8004160102 8004160118	8004160044 8004160057 8004160066 8004160096	80/02/27 80/02/27 80/02/27 80/02/29 80/04/01	50-445 50-553 50-327 PR 50-413	Q Q Q
	3004150440 3004150444 3004150437 3004150447 3004150451	80/04/07 80/04/08 80/04/01 80/04/07	50-344 50-324 50-390 50-348 50-366	8 8 8 8	8004160122 8004160133 8004160137 8004160138 6004160141	8004160116 8004160125 8004160125 8004160131 8004160125	80/04/01 80/03/24 80/03/24 80/03/28 80/03/24	50-413 50-293 50-293 50-289 50-293	Q Q Q
	3004150454 3004150459 3004150463 3004150457 3004150456	80/03/13 80/04/11 80/03/25 80/03/27 80/04/11	50-366 50-244 50-254 50-254 50-311	8 8 8	9004160146 8004160151 8004160153 8004160155 8004160159	8004160125 8004160078 8004160145 8004160078 8004160078	80/03/24 80/03/24 80/02/28 80/03/24 80/03/24	50-293 70-1251 50-293 70-1251 70-1251	G

ACCESS10	NUMBER				ACCESS10	IN NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		· ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8004160172 8004160176	8004160165 8004160173	80/02/29	50-277 50-3	0	6004170293	8004170288	80/02/26	50-272 0
8004160184 8004160187	8004160179 8004160183	80/04/01 80/04/07 80/03/21	50-320 50-277	H P G	8004170296 8004170300 8004170309	8004170292 8004170294 8004170304	80/03/26 80/03/26 80/02/07	50-424 0 50-289 P 50-334 0
8004160189	8004160183	80/03/21	50-277	G	8004170318	8004170316	80/03/31	50-317 F
8004160170 8004160171 8004160173	8004160186 8004160183 8004160186	80/03/12 80/03/21 80/03/12	COMMISSI 50-277 CDMMISSI	G	8004170323 8004170350	8004170316 8004170345	80/03/31 80/04/02	50-317 F 10CFR
8004160174 8004160176	8004160183 8004160186	80/03/21 80/03/12	50-277 COMMISSI	G	8004170352 8004180016 8004180066	8004170345 8004180008 8004180058	80/04/02 80/03/31 80/04/04	IOCFR COMMISSION 50-328 A
8004160179	8004160197	BO/04/11	50-269	G	B004180069	8004180062	80/03/19	71-96
8004160200 8004160202 8004160203	8004160186 8004160186 8004160186	80/03/12 80/03/12 80/03/12	COMMISSI COMMISSI	DN	8004180070 800418007B 8004180082	8004180058 8004180023 8004180023	80/04/04 80/03/31 80/03/31	50-328 A COMMISSION COMMISSION
8004140206	8004160186	80/03/12	COMMISS		B004180085	8004180023	B0/03/31	COMMISSION
8004160209 8004160210	8004160184 8004160197	80/03/12 80/04/11	COMM1551	G	B0041800B9 B004180092	8004180088 8004180088	80/03/14 80/03/14	XPORTLIC XPORTLIC
8004160212 8004160215 8004160218	8004160186 8004160186 8004160216	80/03/12 80/03/12 80/03/31	COMMISSI COMMISSI 50-518		8004180095 8004180097 8004180100	8004180023 8004180023 8004180023	80/03/31 80/03/31 80/03/31	COMMISSION COMMISSION
8004160219	8004160197	80/04/11	50-269	0	8004180101	8004180023	80/03/31	COMMISSION
8004160220 8004160221	8004160186 8004160197	80/03/12 80/04/11	COMMISS!	G	8004180103 8004180120	8004180023 8004180113	80/03/31 80/03/19	CDMH18810N 50-289 H
8004160224 8004160227	8004160197 8004160197	BO/04/11 BO/04/11	50-269 50-269	0	8004180124 8004180124	8004180121 8004180122	80/02/29 80/04/02	70-1113 50-301 Q
8004140230 8004160232	8004160197 8004160229	80/04/11 80/04/11	50-269 50-287	G S	B0D4180130 B004180142	8004180122 8004180128	80/04/02 80/03/25	50-301 0 COMMISSION
8004160235 8004160240 8004160243	8004160197 8004160197 8004160239	80/04/11 80/04/11	50-269 50-269 50-445	G	8004180147 8004180153	8004180138 8004180128	80/03/03 80/03/25	50-245 G COMMISSION
8004140243	8004160237	80/03/31 80/04/11	50-269	K G	9004180160 8004180164	8004180134 8004180128	80/03/25	50-339 A COMMISSION
8004160256 8004160259	8004160253 8004160253	BO/04/0B BO/04/0B	50-275 50-275	Ā	9004180167 8004180175	8004180151 8004180128	80/04/02	50-445 M COMM [88]ON
8004160260 8004160264	8004140253 8004160253	80/04/08 80/04/08	50-275 50-275	A	B004180181 B004180183	8004180172 8004180128	BO/03/27 BO/03/25	50-315 Å COMMI88ION
8004160267 8004160270	8004160253 8004160266	80/44/08	50-275 50-312	A R	8004180193 8004180197	8004180128 8004180128	80/03/25 80/03/25	COMMISSION
8004160271 8004160276	8004160253 8004160291	80/04/08 80/03/31	50-275 50-438	A 6	8004180199 8004180203	8004180187 8004180187	80/03/04	50-373 0 50-373 0
8004160298 8004170019	8004140290 8004170015	80/04/11	50-320 50-324	P P	8004180207 8004180208	8004180200 8004180111	80/03/2B 80/04/10	XPORTLIC 50-358 @
8004170020 8004170031	8004170015 8004170026	80/04/11 80/04/11	50-324 50-327	PS	8004180218 8004180220	8004180214 8004180211	80/02/21	50-478 Q COMMISSION
8004170035 8004170046	B004170028 B004170044	80/03/20 80/04/03	TOPREP 50-73	Р	8004180237 8004180238	9004180234 8004180233	80/03/28 80/03/20	50-3 H 50-387 T
8004170049 8004170051	8004170044 8004170045	80/04/03 80/04/10	50-73 50-528	P 9	6004180288 6004180284	8004180253 8004180256	80/03/28 80/04/14	50-220 P A E88-08
8004170052 8004170059	8004170050 8004170056	80/04/03 80/04/10	50-338 50-282	R	8004180277 8004180278	8004180253 8004180253	80/03/28	50-220 P
8004170067	8004170065	B0/04/11	50-327	K	8004180286	8004180281	EO/4/03	50-247 €
8004170073 8004170074 8004170106	8004170069 8004170071 8004170104	80/04/14 80/03/21 80/04/14	50-327 50-416 50-289	9 9	8004180294 8004180298 8004180307	8004180261 8004180277 8004180276	80/04/03 80/03/17 80/04/14	50-247 E COMMISSION 50-306 G
8004170115 8004170117	B004170107 B004170112	80/04/01 80/02/27	50-312 COMMISSI	G	8004180310 8004180311	8004180309 8004180304	80/03/27 80/03/18	XPORTLIC COMMISSION
8004170121 8004170129	B004170109 B004170109	B0/04/01 B0/04/01	50-312 50-312	g O	8004180314 8004180319	8004180309 8004180304	80/03/27 80/03/18	XPORTLIC COMMISSION
8004170140 8004170155	8004170104 8004170134 8004170148	B0/04/01 B0/04/15 B0/04/15	50-327 50-327	P	8004180320 8004180334	8004180318 8004180329	80/03/05 80/02/26	50-320 G 50-219 G
8004170191	8004170184	80/04/09	50-293	8	8004180337	8004180331	80/04/15	50-370 R
8004170199 8004170208 8004170211	8004170194 8004170203 8004170210	80/04/10 80/04/10 80/04/14	50-336 50-269 50-338	8 8 R	8004190339 8004180342 8004180348	9004180338 14E0814008 460814008	80/04/15 80/04/15 80/04/07	50-320 R 50-282 P 50-213 P
8004170212 8004170212	8004170210 8004170219	80/04/14 80/04/14	50-338 50-317	R	8004180347 8004180360	8004180345 8004180357	80/04/14	50~220 F 50~243 F
8004170226	8004170224	80/04/09	50-336	8	8004180362	8004180361	80/04/14	50-344 P
8004170227 8004170227 8004170230	8004170225 8004170225 8004170228	80/04/15 80/04/15 80/04/10	50-327 50-327 50-277	F F	6004180364 8004180364 8004180367	8004180359 8004180361 8004180365	80/04/04 80/04/14 80/04/11	50-314 F 50-344 P 50-328 S
8004170231	8004170225	80/04/15	50-327	F	8004180371	8004180369	80/04/15	50-271 R
8004170234 8004170236	B004170225 B004170233	B0/04/15 B0/04/09	50-327 50-133	F R	8004180374 8004180381	8004180373 8004180377	80/04/05	50-250 R 50-390 S
8004170244 8004170252 8004170256	8004170241 8004170246 8004170246	80/04/14 80/04/15 80/04/15	50~260 50-277 50-277	R P P	8004180386 8004180388 8004180394	8004180380 8004180383 8004180391	80/04/11 80/04/14 80/04/11	50-304 S 50-245 R 50-327 R
8004170257	8004170254	80/04/14	50-70	P	8004180395	8004180389	80/02/25	50-247 P
8004170258 8004170260	8004170255 8004170254 8004170255	80/04/14 80/04/14 80/04/14	50-255 50-70 50-255	9 9	8004180402 8004180404 8004180407	8004180396 8004180398 8004180399	80/03/12 80/04/11 80/04/08	50-155 0 50-336 B 50-327 B
8004170262 8004170281	8004170273	80/03/31	50-289	Ö	B0041B0411	8004180408	80/04/11	50-334 8

ACCESSION					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT CATEGORY	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	γ
8004180413 8004180416 8004180425 8004180433 8004180434	8004180410 8004180405 8004180418 8004180428 8004180426	80/04/14 80/04/10 80/04/14 80/04/14 80/04/15	50-261 50-305	5 T 5 R	8004210127 8004210129 8004210130 8004210132 8004210132	8004210125 8004210125 8004210126 8004210125 8004210125	80/03/27 80/03/27 80/03/18 80/03/27 80/03/19	50-155 50-155 70-1100 50-155 70-1100	P P
8004180439 8004180440 8004180441 8004180454 8004180456	8004180431 8004180437 8004180432 8004180450 8004180452	80/04/08 80/04/10 80/04/08 80/04/09 80/04/08	50-320 50-245 50-269 50-206 50-296	H 5 0 6 5	8004210135 8004210137 8004210138 8004210139 8004210142	8004210126 8004210134 8004210126 8004210126 8004210134	80/03/18 80/02/29 80/03/18 80/03/18 80/02/29	70-1100 50-359 70-1100 70-1100 50-359	a a
80 04180457 80 04180461 80 04180465 80 04180467 80 04180469	8004180451 8004180448 8004180460 8004180466 8004180462	80/04/08 80/04/14 80/04/07 80/04/14 80/04/15	50-260 50-286 50-327 50-344 50-302	S S S P 1	8004210143 8004210145 8004210149 8004210151 8004210159	8004210126 8004210126 8004210026 8004210146 8004210156	80/03/18 80/03/18 80/03/31 80/02/25 80/03/24	70-1100 70-1100 XPORTLIC 50-322 XPORTLIC	Q
8004180470 8004180471 8004180472 8004180474 8004180475	8004180466 8004180458 8004180468 8004180462 8004180464	80/04/14 80/04/14 80/04/11 80/04/15 80/04/11	50~344 50~244 50~263 50~302 50~282	P S I P	8004210160 8004210162 8004210166 8004210167 8004210171	8004210154 8004210155 8004210163 8004210155 8004210155	80/03/07 80/03/28 80/04/07 80/03/28 80/03/28	PR 70-1113 50-267 70-1113 70-1113	Q
8004180478 8004180483 8004180484 8004180491 8004180492	8004180462 8004180477 8004180462 8004180462 8004180489	80/04/15 80/04/14 80/04/15 80/04/15 80/04/10	50-302 50-305 50-302 50-302 50-309	I P I I S	8004210173 8004210174 8004210179 8004210184 8004210185	8004210169 8004210155 8004210175 8004210170 8004210182	80/02/28 80/03/28 80/02/29 80/03/25 80/04/14	50-293 70-1113 50-445 50-389 50-458	Q Q S I
8004180500 8004180503 8004180512 8004180522 8004180523	8004180462 8004180508 8004180515 8004180521	80/04/15 80/04/15 80/02/26 80/03/14 80/02/21	50-302 50-302 50-309 70-1007 50-344	1 1 0 0	8004210184 8004210188 8004210195 8004210194 8004210197	8004210183 8004210183 8004210191 8004210187 8004210192	80/03/11 80/04/03 80/03/28 80/03/07 80/03/14	50-361 50-553 50-269 50-243 50-317	0 0 0 R
8004180525 8004180527 8004180528 8004180530 8004180534	8004180515 8004180521 8004180524 8004180529 8004180533	80/03/14 80/02/21 80/02/09 80/03/08 80/02/26	70-1007 50-344 50-250 50-250 70-364	G R R	8004210199 8004210201 8004210205 8004210206 8004210207	8004210191 8004210193 8004210202 8004210204 8004210203	80/03/28 80/04/01 80/04/11 80/04/04 80/03/19	50-269 50-3 50-327 50-160 70-135	О Н Р
8004210009 8004210011 8004210018 8004210020 8004210021	8004210007 8004210003 8004210014 8004210015 8004210019	80/04/09 80/03/06 80/03/25 80/03/31 80/04/03	50-322 50-423 50-344 50-320 71-9142	G Q F Q	8004210212 8004210214 8004210215 8004210216 8004210218	8004210210 8004210203 8004210211 8004210203 8004210210	80/03/21 80/03/19 80/03/10 80/03/19 80/03/21	50-247 70-135 50-298 70-135 50-247	() () ()
8004210022 8004210024 8004210025 8004210030 8004210031	8004210013 8004210016 8004210013 8004210013 8004210028	80/04/08 80/03/26 80/04/08 80/04/08 80/03/26	FOIA 50-272 FOIA FOIA 50-339	Q Н	8004210219 8004210220 8004210222 8004210223 8004210229	8004210211 8004210217 8004210203 8004210208 8004210226	80/03/10 80/04/11 80/03/17 80/04/01 80/03/10	50-298 50-313 70-135 50-3 50-312	Q R H
8004210033 8004210034 8004210035 8004210042 8004210044	8004210013 8004210027 8004210029 8004210037 8004210039	80/04/08 80/03/05 80/03/05 80/02/26 80/03/26	FOIA 70-1100 40-672 71-6717 50-309	a	8004210237 8004210240 8004210241 8004210242 8004210243	8004210231 8004210238 8004210231 8004210234 8004210231	80/03/25 80/04/11 80/03/25 80/03/26 80/03/25	50-312 50-302 50-312 50-413 50-312	R Q Q
8004210045 8004210049 8004210052 8004210053 8004210057	8004210039 8004210039 8004210047 8004210039 8004210047	80/03/26 80/03/26 80/04/08 80/03/26 80/04/08	50-309 50-309 FOIA 50-309	0 0	8004210247 8004210248 8004210249 8004210250 8004210253	8004210234 8004210231 8004210246 8004210235 8004210251	80/03/28 80/03/25 80/04/14 80/03/10 80/04/10	50-413 50-312 50-245 50-287 50-213	G G R Q R
6004210060 6004210061 6004210062 6004210064 6004210065	8004210048 8004210056 8004210047 8004210056 8004210047	80/04/01 80/03/25 80/04/08 80/03/26 80/04/08	50-27 50-286 FDIA 50-286 FOIA	អ ០ ០	8004210256 8004210257 8004210258 8004210262 8004210264	8004210252 8004210254 8004210255 8004210259 8004210260	80/03/15 80/04/09 80/04/14 80/04/10 80/03/15	50-10 50-206 50-247 50-312 50-10	H 8 R 9 H
8004210069 8004210068 8004210070 8004210071 073	8004210053 8004210056 8004210059 8004210066	80/03/14 80/03/26 80/03/26 80/02/25 80/03/24	70-371 50-284 50-286 50-244 71-381	a a a	8004210266 8004210267 8004210271 8004210273 8004210276	8004210261 8004210265 8004210268 8004210270 8004210269	80/04/15 80/04/15 80/04/14 80/04/08 80/04/15	50-334 50-346 50-267 50-206 50-3	R S R S R
	8004210074 8004210075 8004210075 8004210075 8004210079	80/03/05 80/03/14 80/03/14 80/03/14 80/03/05	50-272 70-2478 70-2478 70-2478 50-277	a a	8004210278 8004210279 8004210280 8004210282 8004210288	8004210277 8004210272 8004210274 8004210275 8004210286	80/04/14 80/03/15 80/04/11 80/03/03 80/04/09	50-309 50-10 50-368 50-546 50-249	8 H R H
	8004210081 8004210081 8004210088 8004210088	80/01/16 80/01/16 80/02/28 80/04/01 80/02/28	70-135 70-135 70-1143 50-3 50-320	H 0	8004210290 8004210292 8004210296 8004210297 8004210300	8004210287 8004210289 8004210294 8004210295 8004210299	80/03/15 80/04/12 80/04/09 80/03/15 80/03/15	50-10 50-273 50-267 50-10 50-10	H 8 8 H
		30/03/06 30/03/04 30/03/18 30/03/05 80/03/04	70-371 50-302 CONTRACT 50-269 50-566	Q Q Q	8004210305 8004210306 8004210307 8004210310 8004210320	8004210302 8004210303 8004210303 8004210308 8004210315	80/03/15 80/03/24 80/03/24 80/03/15 80/04/01	50-10 TOPREP TOPREP 50-10 50-339	H H T

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION	NUMBER					IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8004210329 8004210329 8004210330 8004210331 8004210339	8004210322 8004210322 8004210326 8004210327 8004210334	80/03/28 80/03/28 80/02/27 80/02/16 80/03/05	50-275 50-275 50-219 50-305 50-333	 G G P	8004220187 8004220191 8004220193 8004220193 8004220202	8004220184 8004220185 8004220184 8004220020 8004220020	80/02/25 80/03/19 80/02/25 80/04/03 80/04/03	71-9130 50-320 71-9130 FOIA FOIA	н
8004210340 8004210344 8004210345 8004210346 8004210347	8004210335 8004210335 8004210343 8004210342 8004210335	80/04/15 80/04/15 80/03/05 80/03/26 80/04/15	50-320 50-320 50-245 50-320 50-320	Р О Р Р	8004220204 8004220210 8004220212 8004220214 8004220214	8004220188 8004220020 8004220020 8004220020 8004220020	80/03/31 80/04/03 80/04/03 80/04/03 80/04/03	50-249 FOIA FOIA FOIA	G
8004210349 8004210351 8004210355 8004210357 8004210358	8004210335 8004210342 8004210335 8004210350 8004210335	80/04/15 80/03/26 80/04/15 80/04/07 80/04/15	50-320 50-320 50-320 70-143 50-320	P P P	8004220221 8004220224 8004220227 8004220229 8004220231	8004220215 8004220223 7907100034 8004220020 8004220020	80/03/04 80/04/11 79/06/21 80/04/03 80/04/03	50-321 50-289 50-287 FOIA FOIA	G P G
8004210359 8004210360 8004210361 8004210366 8004210373	8004210350 8004210356 8004210353 8004210335 8004210363	80/04/07 80/03/24 80/04/15 80/04/15 80/03/24	70-143 50-320 FR 50-320 50-320	Н Р	8004220236 8004220236 8004220242 8004220243 8004220243	8004220020 7907100034 8004220020 8004220239 8004220232	80/04/03 79/06/21 80/04/03 80/03/24 80/02/29	FOIA FOIA FOIA 50-389 50-445	A Q
8004210376 8004210388 8004210391 8004210392 8004210393	8004210372 8004210387 8004210381 8004210386 8004210322	80/04/16 80/03/21 80/03/19 80/03/27 80/03/28	50-338 40-1162 50-320 50-445 50-275	P H M O	8004220245 8004220246 8004220250 8004220251 8004220252	7907100034 8004220020 8004220248 8004220020 8004220020	79/06/21 80/04/03 80/03/24 80/04/03 80/04/03	FOIA FOIA 50-389 FOIA FOIA	к
8004210394 8004210395 8004210397 8004210399 8004210400	8004210386 8004210322 8004210386 8004210378 8004210386	80/03/27 80/03/28 80/03/27 80/03/24 80/03/27	50-445 50-275 50-445 50-320 50-445	M M H M	8004220253 8004220255 8004220257 8004220263 8004220263	7907100034 6004220020 8004220020 6004220020 8004220020	79/06/21 80/04/03 80/04/03 80/04/03 80/04/03	FOIA FOIA FOIA FOIA	
8004210403 8004210417 8004210428 8004210431 8004210438	8004210402 8004210412 8004210422 8004210425 8004210432	80/03/22 11/60/08 12/60/08 01/40/08	50-320 50-361 50-312 50-367 50-445	H G G G	8004220273 8004220273 8004220282 8004220284 8004220284	800422026B 8004220020 8004220020 800422027B 8004220020	80/04/01 80/04/03 80/04/03 80/04/14 80/04/03	50-331 FDIA FOIA 50-301 FOIA	F
8004210443 8004210450 800422007 8004220017 8004220023	8004210432 8004210437 8004220004 8004220012 8004220012	80/03/10 80/02/27 80/03/24 80/03/17 80/03/17	50-445 50-219 50-286 50-316 50-316	0 0 0 P P	8004220293 8004220294 8004220304 8004220314 8004220315	8004220289 8004220020 8004220301 8004220303	80/04/18 80/04/03 80/04/17 80/04/03 80/03/05	50-416 FOIA 50-271 FOIA 70-2623	G R
8004220026 8004220027 8004220028 8004220033 8004220034	8004220018 8004220012 8004220020 8004220020 8004220012	79/12/28 80/03/17 80/04/03 80/04/03 80/03/17	70-135 50-316 FOIA FOIA 50-316	P	6004220317 8004220319 8004220321 8004220323 8004220323	6004220313 6004220020 6004220313 6004220020 8004220303	80/03/24 80/04/03 80/03/24 80/04/03 80/03/05	50-389 F01A 50-389 F01A 70-2623	C C
8004220037 8004220039 8004220041 8004220044 8004220051	8004220020 8004220012 8004220025 8004220020 8004220020	80/04/03 80/03/17 80/03/04 80/04/03 80/04/03	FOIA 50-316 70-371 FOIA FOIA	P	8004220327 8004220329 8004220330 8004220331 8004220337	8004220020 8004220020 8004220303 8004220303	80/04/03 80/04/03 80/04/03 80/03/05 80/04/03	FOIA FOIA FOIA 70-2623 FOIA	
8004220055 8004220056 8004220068 8004220075 8004220080	8004220043 8004220020 8004220054 8004220020 8004220020	80/03/25 80/04/03 79/11/14 80/04/03 80/04/03	71~379 FOIA 70~1143 FOIA FOIA		8004220341 8004220346 8004220346 8004220347 8004220351	8004220020 8004220303 8004220020 8004220340 8004220020	80/04/03 80/03/05 80/04/03 80/04/15 80/04/03	FOIA 70-2623 FOIA 50-259 FOIA	P
8004220092 8004220097 8004220101 8004220107 8004220116	8004220020 8004220020 8004220020 8004220020 8004220111	80/04/03 80/04/03 80/04/03 80/04/03 80/03/26	FOIA FOIA FOIA FOIA XPORTLIO	:	8004220353 8004220358 8004220358 8004220341	8004220303 8004220020 8004220340	80/03/05 80/04/03 80/04/15	70-2523 FOIA 50-259	P
8004220119 8004220120 8004220124 8004220125 8004220130	8004220105 8004220120 8004220112 8004220020 8004220020	80/03/28 80/04/03 80/03/19 80/04/03 80/04/03	50-491 F01A 50-320 F01A F01A	Ц					
8004220132 8004220134 8004220137 8004220143 8004220162	B004220020 B004220105 B004220020 B004220136 B004220159	80/04/03 80/03/28 80/04/03 80/03/13 80/03/03	FOIA 50-491 FOIA 50-320 50-320	о н					
8004220164 8004220165 8004220167 8004220171 8004220174	8004220020 8004220157 8004220020 8004220168 8004220020	80/04/03 80/03/04 80/04/03 80/03/19 80/04/03	FOIA 50-295 FOIA 50-320 FOIA	g K					
B004220175 B004220178 B004220180 B004220181 B004220186	8004220157 8004220020 8004220020 8004220173 8004220020	80/03/04 80/04/03 80/04/03 80/04/02 80/04/03	50-295 FOIA FOIA 50-320 FOIA	Ю					

TO PRINCIPAL DOCUMENTS

ACCESSION					ACCESSION				
ENCLOSURE	PRINCIPAL BOCUMENT	DATE 180ED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGORY	Y
8004220440 8004220442 8004220444 8004220447 8004220448	8004220427 8004220020 8004220020 8004220427 8004220427	B0/04/16 B0/04/03 B0/04/03 B0/04/16 B0/04/03	50-313 FGIA FOIA 50-313 FDIA		8004220635 8004220636 8004220637 8004220644 8004220648	8004220020 8004220428 8004220020 8004220020 8004220442	80/04/03 80/04/15 80/04/03 80/04/03 80/04/16	FOIA 50-366 FOIA FOIA 50-305	9
8004220450 8004220452 8004220453 8004220454 8004220454	8004220427 8004220020 8004220427 8004220427 8004220427	80/04/16 80/04/03 80/04/16 80/04/16 80/04/16	50-313 FDIA 50-313 50-313 50-313	F F F	8004220653 8004220658 8004220666 8004220667 8004220668	8004220646 8004220652 8004220657 8004220662 8004220660	80/04/15 80/04/17 80/04/16 80/04/15 80/04/14	50-338 50-366 50-346 50-366 50-298	55558
8004220458 8004220459 8004220461 8004220463 8004220465	8004220020 8004220455 8004220020 8004220020 8004220020	80/04/03 80/04/15 80/04/03 80/04/03 80/04/03	FDIA 50-375 FOIA FOIA FOIA	Q	8004220671 8004220679 8004220680 8004220681 8004220684	8004220664 8004220670 8004220669 8004220630 8004220675	80/04/16 80/04/18 80/04/18 80/04/17 80/04/17	50-366 50-336 50-260 50-10 50-321	9999
8004220466 8004220467 8004220468 8004220469 8004220470	8004220020 8004220020 8004220020 8004220020 8004220020	80/04/03 80/04/03 80/04/03 80/04/03 80/04/03	FOIA FOIA FOIA FOIA		8004220687 8004220690 8004220697 8004220699 8004220699	8004220676 8004220682 8004220692 8004220686 8004220693	80/04/15 80/04/14 80/04/18 80/04/18 80/04/10	50-325 50-269 50-275 50-259 50-249	S 8 8 8
8004220472 8004220473 8004220476 8004220479 8004220480	8004220020 8004220020 8004220020 8004220020 8004220020	80/04/03 80/04/03 80/04/03 80/04/03	FOIA FOIA FOIA FOIA		8004220702 8004220703 8004220704 8004220707 8004220710	8004220694 8004220691 8004220692 8004220698 8004220689	80/04/14 80/04/15 80/04/18 80/04/17 80/04/17	50-304 50-368 50-275 50-327 50-321	8 8 8 8 8
8004220482 8004220485 8004220486 8004220488 8004220491	8004220020 8004220020 8004220020 8004220020 8004220020	80/04/03 80/04/03 80/04/03 80/04/03	FOIA FOIA FOIA FOIA		8004220716 8004220717 8004220718 8004220719 8004220721	8004220692 8004220705 8004220706 8004220708 8004220713	B0/04/18 B0/04/17 B0/04/17 B0/04/16 B0/04/15	50-275 50-366 50-366 50-317 50-321	8 8 8
6004220499 8004220501 8004220506 8004220511 8004220512	8004220497 8004220464 8004220464 8004220508 8004220020	80/04/18 80/04/21 80/04/21 80/04/17 80/04/03	TOPREP 50-220 50-220 50-219 FOIA	P P P	8004220722 8004220727 8004220735 8004220736 8004220737	8004220715 8004220692 8004220726 8004220728 8004220728	80/04/16 80/04/18 80/04/17 80/04/15 80/04/18	50-327 50-275 50-366 50-366 50-275	5 4 5 8 4
8004220514 8004220517 8004220521 8004220528 8004220530	800422050B 8004220020 8004220020 8004220020 8004220522	80/04/17 80/04/03 80/04/03 80/04/03 80/04/17	50-219 FOIA FOIA FOIA 50-309	P P	8004220738 8004220740 8004220744 8004220746 8004220747	8004220729 8004220732 8004220692 8004220729 8004220730	80/04/09 80/04/15 80/04/18 80/04/09 80/04/15	50-348 50-324 50-275 50-348 50-482	5 8 8 1
8004220531 8004220532 8004220537 8004220544 8004220545	8004220523 8004220020 8004220020 8004220020 8004220542	80/04/15 80/04/03 80/04/03 80/04/03 80/04/11	50~259 FOIA FOIA FOIA 50~289	P P	8004220749 8004220750 8004220751 8004220755 8004220757	8004220741 8004220742 8004220692 8004220692 8004220753	80/04/17 80/04/18 80/04/18 80/04/18 80/04/16	50-286 50-259 50-275 50-275 50-327	88448
8004220546 8004220547 8004220548 8004220551 8004220552	8004220541 8004220538 8004220020 8004220020 8004220542	80/04/16 80/04/16 80/04/03 80/04/11	50-43B 50-325 FOIA FOIA 50-289	5 S	8004220758 8004220759 8004220761 8004220762 8004220764	8004220745 8004220730 8004220752 8004220754 8004220724	80/04/18 80/04/15 80/04/16 80/04/13 80/04/14	50-318 50-482 50-346 50-3 50-518	8 0 8
8004220557 8004220560 8004220562 8004220563 8004220567	8004220020 8004220558 8004220020 8004220558 8004220020	80/04/03 80/03/13 80/04/03 80/03/13 80/04/03	FOIA 50-111 FOIA 50-111 FOIA	R R	8004220769 8004220771 8004220772 8004220778 8004220790	8004220763 8004220767 8004220765 8004220775 8004220789	80/04/21 80/04/17 80/04/16 80/04/14 80/03/17	50-498 50-333 50-346 50-267 71-9019	K 8 1
8004220573 8004220577 8004220579 8004220581 8004220583	8004220020 8004220559 8004220020 8004220575 8004220572	80/04/03 80/04/15 80/04/03 80/04/17 80/04/15	FOIA 50-410 FOIA 50-155 50-324	g g g	8004230007 8004230014 8004230017 8004230023 8004230026	8004230002 8004230010 8004230010 8004230015 8004230009	80/04/11 80/04/04 80/04/04 80/04/10 80/02/22	50-445 50-266 50-266 FDIA 50-250	M G G
8004220585 8004220591 8004220593 8004220596 8004220598	8004220020 8004220020 8004220020 8004220586 8004220020	80/04/03 80/04/03 80/04/03 80/04/11 80/04/03	FOIA FOIA FOIA 50-295 FOIA	g	8004230029 8004230032 8004230040 8004230041 8004230045	8004230015 8004230015 8004230015 8004230033 8004230015	80/04/10 80/04/10 80/04/10 80/04/10 80/04/10	FOIA FOIA FOIA 50-445 FOIA	М
8004220602 8004220606 8004220608 8004220609 8004220612	8004220020 8004220020 8004220579 8004220020 8004220020	80/04/03 80/04/03 80/04/15 80/04/03 80/04/03	FOIA FOIA 50-325 FOIA FOIA	S	8004230044 8004230050 8004230060 8004230071 8004230074	8004230036 8004230015 8004230053 8004230059 8004230066	80/02/22 80/04/10 80/02/29 80/03/20 80/04/03	50-390 FOIA 50-201 50-352 50-445	G R G M
8004220616 8004220617 8004220618 8004220621 8004220622	8004220020 8004220615 8004220020 8004220614 8004220020	80/04/03 80/04/15 80/04/03 80/04/17 80/04/03	FOIA 50-366 FOIA 50-317 FOIA	8	8004230079 8004230089 8004230093 8004230096 8004230101	8004230059 8004230059 8004230091 8004230091 8004230091	80/03/20 80/03/20 76/11/24 76/11/24 76/11/24	50-352 50-352 50-367 50-367 50-367	9 9 9
8004220623 8004220625 8004220627 8004220631 8004220633	8004220613 8004220020 8004220020 8004220624 8004220020	80/04/09 80/04/03 80/04/03 80/04/11 80/04/03	50-265 FOIA FOIA 50-293 FOIA	\$ \$	8004230103 8004230110 8004230114 8004230118 8004230126	8004230078 8004230075 8004230057 8004230075 8004230123	80/04/11 80/03/21 80/03/20 80/03/21 80/04/08	50-275 COMM1881 50-352 COMM1881 SECY	G

ACCESS 10	NUMBER				ACCESS10				
ENCLOGURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Υ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	łΥ
8004230128 8004230130 8004230133 8004230136 8004230141	8004230120 8004230123 8004230129 8004230123 8004230123	80/03/03 80/04/08 80/03/26 80/04/08 80/04/08	50-309 SECY XPORTLIC SECY SECY	Œ	9004240155 8004240159 8004240170 8004240175 8004240175	8004240028 8004240153 8004240028 8004240163 8004240028	78/03/06 80/03/19 78/03/06 80/03/20 78/03/06	70-135 70-143 70-135 50-247 70-135	P
8004230144 8004230157 8004230162 8004230175 8004230179	8004230138 8004230138 8004230154 8004230167 8004230167	80/03/04 80/03/04 80/04/07 80/03/03 80/03/03	70-925 70-925 50-445 50-123 50-123	11 0 0	8004240183 8004240187 8004240190 8004240202 8004240207	8004240028 8004240028 8004240181 80042401B1 8004240201	/8/03/06 78/03/04 80/03/03 80/03/03 80/01/30	70-135 70-135 70-2805 70-2805 50-438	A
8004230189 8004230190 8004230236 8004230238 8004230246	8004230167 8004230185 8004230202 8004230231 8004230231	80/03/03 80/04/03 80/03/26 80/04/21 80/04/21	50-123 50-3 50-269 50-339 50-339	9 Н о Р Р	8004240209 8004240217 800424023 8004240276 8004240277	8004240178 8004240201 8004240251 8004240251 8004240267	80/03/10 80/01/30 80/03/14 80/03/14 80/01/23	40-8502 50-438 50-250 50-250 70-1308	A P P
8004230248 8004230249 8004230253 8004230255 8004230260	8004230237 8004230202 8004230237 8004230231 8004230231	80/04/08 80/03/26 80/04/08 80/04/21 80/04/21	50-460 50-269 50-460 50-339 50-339	0 0 0 P P	8004240282 8004240283 8004240283 8004240294 8004240307	B004240270 B004240251 B004240267 B004240267 B004240299	80/03/19 80/03/14 80/01/23 80/01/23 80/04/03	50-320 50-250 70-1308 70-1308 50-277	P P
8004230267 8004230271 8004230273 8004230276 8004230277	8004230202 8004230237 8004230239 8004230239 8004230202	80/03/26 80/04/08 80/04/08 80/04/08 80/03/26	50-269 50-460 50-460 50-460 50-269	0 0 0 0	8004240317 8004240320 8004240322 8004240328 8004240329	8004240307 8004240297 8004240314 8004240323 8004240299	80/04/15 80/04/03 80/02/28 80/04/18 80/04/03	50-250 50-277 71-107 50-267 50-277	S P S P
8004230287 8004230270 8004230302 8004230303 8004230307	8004230239 8004230239 8004230295 8004230300 8004230300	80/04/08 80/04/08 80/04/22 79/10/18 79/10/18	50-460 50-460 PROJ NUREG NUREG	G G	8004240331 8004240343 8004240352 8004240356 8004240360	8004240314 8004240334 8004240344 8004240350 8004240344	80/02/28 80/04/15 80/04/02 78/06/03 80/04/02	71-107 50-335 50-424 50-250 50-424	S Q R
8004230307 8004230313 8004230316 8004230317 8004230326	8004230299 8004230299 8004230299 8004230295 8004230321	80/04/14 80/04/14 80/04/14 80/04/22 79/08/04	50-213 50-213 50-213 PROJ 50-250	7 7 8	8004240363 8004240366 8004240375 8004240375 8004240378	8004240359 8004240362 8004240368 8004240369 8004240371	78/09/04 80/04/21 78/04/07 80/04/16 80/04/02	50-250 50-261 50-250 50-335 50-250	R S R S O
8004230332 8004230343 8004230348 8004230355 8004230357	8004230330 8004230341 8004230346 8004230351 8004230351	79/06/09 80/04/21 80/04/14 80/04/18 80/04/18	50-250 50-217 50-331 50-316 50-316	R P R 8	8004240383 8004240387 8004240389 8004240389 8004240390	8004240371 8004240371 8004240386 8004240384 8004240371	80/04/02 80/04/02 80/04/17 80/04/11 80/04/02	50~250 50~250 50~438 50~275 50~250	0 9 F 0
8004230359 8004230362 8004230411 8004230414 8004230419	8004230358 8004230380 8004230406 8004230409 8004230409	80/04/17 80/04/17 80/04/09 80/03/26 80/03/26	50-282 50-438 50-287 50-277 50-277	99 99 P	8004240392 8004240395 8004240396 8004240397 8004240398	8004240371 8004240374 8004240373 8004240374 8004240373	80/04/16 80/04/24 80/03/03 80/04/24 80/03/03	50-277 50-206 50-238 50-206 50-338	0 P 0 P
8004230432 8004230441 8004230444 8004230447 8004230464	8004230430 8004230407 8004230438 8004230438 8004230461	80/04/15 80/03/26 80/04/18 80/04/18 80/04/18	50-316 50-277 50-315 50-315 50-335	\$ P 8 9 P	8004240413 8004240415 8004240420 8004240422 8004240422	8004240408 8004240411 8004240416 8004240418 8004240421	80/03/03 80/04/10 80/03/31 79/01/05 80/04/22	50-280 50-259 50-128 50-250 50-445	Q R R R
8004230473 8004230487 8004230490 8004230495 8004230497	B004230471 B004230480 B004230484 B004230473 B004230477	80/04/16 80/04/17 79/07/07 80/04/15 80/04/09	50-313 50-282 50-250 50-289 50-293	S Q R R	8004240430 8004240432 8004240433 8004240434 8004240434	8004240425 8004240425 8004240421 8004240426 8004240437	80/03/28 80/04/16 80/04/22 80/03/28 80/04/01	50-491 50-219 50-445 50-491 50-213	Q R Q Q R
8004230507 8004230515 8004230525 8004230528 8004230527	8004230503 8004230504 8004230520 8004230523 8004230527	80/04/17 80/04/18 80/04/19 80/04/02 80/04/17	50-438 50-305 50-261 CONTRACT 50-438	8 8 8	8004240440 8004240444 8004240447 8004240452 8004240459	8004240434 8004240443 8004240441 8004240448 8004240455	78/12/06 78/10/07 80/03/19 78/05/06 78/08/10	50-250 50-250 50-320 50-250 50-250	R R H R
8004240006 8004240015 8004240038 8004240041 8004240046	8004240002 8004240007 8004240028 8004240033 8004240028	80/04/02 80/04/07 78/03/04 80/01/09 78/03/06	ORG CONTRACT 70-135 CONTRACT 70-135		8004240466 8004240474 8004240479 8004240483 8004240483	8004240463 B004240470 B004240472 B004240480 B004240480	78/11/04 78/07/01 80/04/03 80/04/09 80/04/09	50-250 50-250 50-320 50-286 50-286	R P P
8004240051 8004240056 8004240067 8004240071 8004240073	8004240047 8004240028 8004240063 8004240061 8004240028	80/04/03 78/03/06 80/03/24 80/04/07 78/03/06	CONTRACT 70-135 XPORTLIC 50-445 70-135	м	8004240487 8004240470 8004240472 8004240473 8004240501	8004240480 8004240485 8004240480 8004240485 8004240473	80/04/09 80/04/04 80/04/09 80/04/04 80/04/08	50-284 50-272 50-284 50-272 50-528	P 0 0
8004240081 8004240084 8004240089 8004240075 8004240104	8004240077 8004240028 8004240087 8004240028 8004240028	80/03/27 78/03/04 80/03/25 78/03/04 78/03/06	State Pro 70-135 50-334 70-135 70-135	P	8004240504 8004240507 8004240508 8004240511 8004240514	8004240480 8004240493 8004240506 8004240512	80/04/09 80/04/09 80/04/08 80/04/01 80/04/04	50-286 50-286 50-528 50-313 50-267	P G P O
8004240110 8004240114 8004240127 8004240137 8004240150	8004240028 8004240028 8004240028 8004240028 8004240028	78/03/06 78/03/06 78/03/04 78/03/06 78/03/06	70-135 70-135 70-135 70-135 70-135		8004240516 8004240516 8004240518 8004240522 8004240526	8004240493 8004240510 8004240480 8004240493 8004240524	80/04/08 80/04/04 80/04/07 80/04/08 80/03/20	50-528 50-247 50-286 50-528 50-346	0 P O F

TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			ACCESSION NUMBER	
PRINCIPAL	DATE	SUBJECT	PRINCIPAL DATE ENCLOSURE DOCUMENT 199UED	SUBJECT CATEGORY
ENCLOSURE DOCUMENT 8004240534 8004240532 8004240537 8004240532 8004240545 8004240541 8004240545 8004240541 8004240553 8004240541	155VED 50/04/09 60/04/04 60/03/31 60/04/09 80/04/02	50-443 H 50-219 G CONTRACT 50-275 G	8004280114 8004280112 80/04/10 8004280118 8004280112 80/04/10 8004280120 8004280113 80/04/09 8004280124 8004280113 80/03/24 8004280125 8004280115 80/03/12	50-514 D 50-514 D 50-284 P 50-272 Q 50-250 Q
8004240553 8004240554 8004240555 8004240558 8004250068 8004250006 8004250011 8004250006 8004250012 8004250006	80/03/06 80/03/21 80/04/03 80/03/31 80/04/03	70~135 50-446 G 50-302 P 50-556 G 50-302 P	B004280130	50-272 Q 71-9039 50-272 Q QA999 QA999
8004250015 8004250006 8004250022 8004250014 8004250030 8004250013 8004250033 8004250018 8004250041 8004250026	80/04/03 80/04/04 80/04/01 80/04/01 80/04/04	50-302 P CONTRACT 50-3 H 50-247 H 50-280 G	8004280143 8004280134 80/03/12 8004280144 8004280136 80/04/10 8004280147 8004280111 80/03/26 8004280149 8004280136 80/04/10 8004280151 8004280148 80/03/13	50-348 Q GA799 50-272 Q GA799 50-261 P
8004250042 8004250043 8004250054 8004250054 8004250059 8004250051 8004250052 8004250056	80/03/24 80/03/31 80/03/28 80/03/28 80/03/26	XPORTLIC CONTRACT 50-213 Q 50-213 Q 50-10 G	8004280153 8004280136 80/04/10 8004280154 8004280148 80/03/13 8004280157 8004280150 80/03/13 8004280162 8004280159 80/04/09 8004280174 8004280171 80/03/31	0A797 50-261 P 50-325 Q 50-311 A 50-354 B
8004250072 8004250068 8004250075 8004250063 8004250081 8004250053 8004250183 8004250079 8004250143 8004250132	80/03/29 80/03/20 80/03/20 80/03/20 80/03/24	State Prog 50-289 G 50-289 G 50-445 G 50-213 G	8004280180 8004280168 90/03/04 8004280186 8004280184 80/03/19 8004280195 8004280190 80/04/16 8004280196 8004280190 80/04/16 8004280202 8004280194 80/03/07	50-312 Q 50-298 Q 50-311 Q 50-311 Q 50-257 Q
8004250193 8004250178 8004250204 8004250178 8004250212 8004250178 8004250261 8004250251 8004250275 8004250251	80/03/21 80/03/21 80/03/21 80/04/09 80/04/09	50-280 F 50-280 F 50-280 F 50-261 G	8004280204 8004280197 80/04/14 8004280206 8004280200 60/04/07 8004280224 8004280210 80/03/26 8004280234 8004280230 80/03/31 8004280239 8004280229 80/04/22	50-3 P REVIEW ORP 50-312 O 50-320 R 50-327 P
8004250282 8004250251 8004250271 8004250251 8004250299 8004250233 8004250334 8004250330 8004250337 8004250336	80/04/09 80/04/09 80/03/17 80/04/02 80/04/04	50-241 0 50-261 0 50-313 0 50-269 0 50-29 0	B0042B0255 B0042B0247 B0/03/10	50-335 Q 70-1201 50-320 P 70-1319 50-320 H
8004250340 8004250330 8004250346 8004250330 8004250352 8004250347 8004250357 8004250330 8004250358 8004250350	80/04/02 80/04/02 80/04/21 80/04/03 80/04/21	50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269 (50-269	8004280288 8004280280 80/03/03 8004280299 8004280293 80/04/03 8004280300 8004280297 80/03/04	50-397 0 50-317 0 50-266 P 50-293 0 50-266 P
8004250359 8004250354 8004250369 8004250365 8004250379 8004250374 8004250389 8004250380 8004250389 8004250377	80/04/21 80/04/22 80/04/21 80/04/21 80/04/12	50-255 50-382 50-586 50-438 50-320	8004280304 8004280293 80/04/03 8004280310 8004280297 80/03/06 8004280314 8004280307 80/04/02	50-320 H 50-244 P 50-273 Q 71-5375 50-338 F
8004250394 8004250388 8004250399 8004250398 8004250407 8004250396 8004250408 8004250396 8004250412 8004250410	80/03/26 80/03/26 80/04/15 80/04/18 80/04/22	50-10 50-10 50-317 50-259 50-324	8004280337 8004280325 80/03/19 8004280344 8004280329 80/04/16 8004280350 8004280342 80/03/24	8tate Preg 50-320 H TOPREP 50-320 H 50-348 H
B004250417 B004250411 B004250420 B004250418 B004250424 B004250413 B004250428 B004250427 B004250432 B004250431	80/04/18 80/04/21 80/04/21 80/04/15 80/04/21	50-318 5 50-206 5 50-370 6 50-373 6	8004280364 8004280362 80/04/14 8004280369 8004280362 80/04/14 8004280371 8004280365 80/04/25	50-302 P 50-10 It 50-10 H 50-416 K 50-10 H
8004280009 8004280005 8004280013 8004280006 8004280014 8004280005 8004280021 8004280019 8004280022 8004280016	80/03/13 80/04/11 80/03/13 80/04/04 80/03/04	50-395 50-344 50-395 50-206 50-275	8004280379 8004280362 80/04/14 8004280381 8004280365 80/04/25 8004280382 8004280380 80/04/18	50-416 K 50-10 H 90-416 K 50-346 I 50-346 I
8004280025 8004280020 8004280039 8004280031 8004280039 8004280037 8004280044 8004280040 8004280046 8004280040		50-265 50-454 50-282 50-285 50-285	8004280412 8004280410 80/04/21 8004280414 8004280410 80/04/21 8004280418 8004280417 80/03/31	50-287 H 50-373 A 50-373 A 40-8681 50-366 8
8004280047 8004280040 8004280053 8004280045 8004280057 8004280050 8004280060 8004280056 8004280070 8004280056	80/03/18 80/03/18 80/03/25	50-285 XPORTLIC 50-324 40-1341 50-334	8004280425 8004280423 79/08/15 8004280427 8004280423 79/08/15 8004280436 8004280432 80/08/407	40-8581 40-8602 40-8602 50-438 8 50-438 8
8004280074 8004280086 8004280079 8004280065 8004280079 8004280065 8004280085 8004280065 8004280085	80/02/05 80/02/05 80/02/05	50-454 50-334 50-334 50-334 50-344	8004280458 8004280453 80/04/03 8004280459 8004280455 80/02/08	50-366 S 50-328 S COMMISSION 50-397 B 50-397 B
8004280070 8004280065 8004280074 8004280083 8004280075 8004280072 8004280107 8004280065 8004280107 8004280097	80/03/19 80/03/20 80/02/05	50-334 50-460 50-361 50-334 50-261	8004280496 8004280490 80703703 8004280505 8004280503 80703703 8004280507 8004280504 8070471	COMMISSION 50-327 8 50-318 8 TOPREP 50-546 R

SUBJECT CATEGORY

> > A 8 P 8 S

88908

8 8

SR

88888

9 9 5 R G

8 P 0

50-318 50-328 50-334 50-313 50-348

50~537 50-317 50-244 50-313 50-317

50-334 50-387 50-325 50-327 50-265

50-318 50-266 50-249 50-445 50-317

50-327 50-317 50-368 40-3453 50-370

50-328 50-390 50-312 50-321 50-390

50-301 50-317 TOPREP 50-321 50-344

50-301 50-333 50-295 50-317 50-302

50-312 50-325 50-275 50-272 50-445

50-317 50-369 50-275 50-334 50-333

CONTRACT 71-227 50-327 50-312 50-289

SECY 50-387 0 50-387 0 50-387 0

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION					ACCESSIO	IN HUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEGOS			PRINCIPAL	DATE
8004280522	B004280517	80/03/31			ENCLOBURE	DOCUMENT	1 SSUED
8004280524 8004280530	8004280516 8004280525	B0/04/17	50-416 50-438	5	8004270350 80042 9 0353	B004290345 B004290346	80/04/25 80/04/23
8004280532	8004280527	80/04/18 80/03/19	50-336 50-320	S H	8004270355 8004290366	8004290354 8004290361	80/04/25
8004280540	8004280535	B0/03/19	50-320	Н	8004290369	8004290367	80/04/22
8004280543 8004280544	8004280539 8004280537	80/04/21 80/04/07	50-458 50-390	R	8004290371 8004290377	8004270364	80/04/04
8004280545 8004280546	8004280542 8004280538	80/03/19 80/04/24	50-320	H	8004290381	8004290372 8004290378	B0/04/25 B0/04/25
8004280953	8004280550	80/03/24	50~346 50~320	B	80042703B5 80042903BB	8004290374 8004290382	80/04/22 80/04/25
8004280554 8004280557	8004280549	80/04/25	50-338	5	8004270373	8004290389	80/04/23
8004280959	8004280555 8004280552	80/04/24 80/04/23	50-155 50-333	F	8004290399 8004290401	8004270374 8004270397	80/04/18 80/04/24
8004280 5 64 8004280566	8004280562 8004280570	80/04/23 80/04/22	50-309 50-321	R	B004290406 B004290407	8004290400 8004290380	80/04/24 80/04/21
8004280568	8004280567	80/04/23	50~302	Р	8004290416	8004290410	80/04/25
8004280571 8004280575	8004280567 8004280572	80/04/23 80/04/24	50-302 50-346	PS	8004290425	8004290418	80/04/22
8004280579	8004280574	B0/03/25	50-298	8	8004270427 8004270437	8004290422 8004290430	80/04/22 80/04/21
8004280586	8004280576	80/04/21	50~325	5	8004270438	0004290433	80/04/25
8004280589 8004280592	8004280582 8004280583	80/04/22 80/04/22	50-321 50-324	5	8004290446 8004290447	8004270435 8004270440	80/04/25 80/04/25
8004280598 8004280599	8004280593 8004280587	80/04/18 80/04/21	50-259 50~324	6 5	8004270451 8004290452	8004270450 8004270449	80/04/17
8004280405	6004280596	80/04/21	50-382	8	B004290458	B004270453	80/03/24 80/04/22
600428060B 6004280616	8004280604	80/04/25	50-338	В	8004290461	8004270455	80/04/24
8004280617	8004280612 8004260614	80/04/24 80/04/24	50-280 50-255	5 F	8004270462 8004270465	8004290453 8004290454	80/04/22 80/04/21
8004280618 8004280621	8004280610 8004280614	80/04/11 80/04/24	50-416 50-255	6 F	8004290466 8004290467	8004290460 8004290453	BO/04/04 BO/04/22
8004280624	8004280614	80/04/24	50-255	F	8004290469	8004270464	80/04/16
8004280625 8004280626	8004280614 8004280612	80/04/24	50-255 50-280	F	8004290472 9004290474	8004270459	80/04/25
8004280627 8004280633	8004280614 8004280630	80/04/24	50-255	F	8004290477	8004290468 8004290460	80/04/21 80/04/04
		80/04/22	50-320	I	8004290478	8004270471	80/04/22
8004280634 8004280638	8004280628 8004280630	80/04/09 80/04/22	50-10 50-320	G I	8004270479 8004270482	8004290470 8004290476	80/04/17 80/04/25
8004290006 8004290011	8004270002 8004270005	80/04/04 80/04/07	50-264 50-298	9	9004270493 8004270494	8004290473 8004290475	80/04/22 80/04/25
8004290021	8004290016	80/04/03	0A999		6004270488	B004270480	80/04/16
8004270023 8004270027	8004270016 8004270016	80/04/03 80/04/03	0A777 0A777		B004290491 B004290494	8004290485	80/04/11
8004290031	8004290016	B0/04/03	GA999		8004290496	8004290487 8004290486	80/04/24 80/04/18
8004290041 8004290044	B004290036 B004290036	80/04/02 80/04/02	40-8602 40-8602		8004270497 8004270498	8004290499 8004290492	80/04/21 80/01/23
800429005B	E004270054	80/03/25	50-3	н	B004270499	8004290490	80/04/25
8004270068 8004270081	B004290064 B004290077	80/03/19 80/04/03	50~320 50-250	H F	8004290501 8004290504	8004270473 8004270502	80/04/24 80/04/22
B004270083 B004270085	8004290076 8004290080	80/03/19 80/04/08	50~320 50~123	H	8004290508 8004290511	8004270503 8004270504	80/04/22 80/04/24
8004290095	8004270092	80/04/24	50-334	r	8004270514	8004290509	80/01/01
8004290101	8004290092	80/04/24	50-334	T	6004290516	8004290513	80/04/10
8004290113 8004290115	8004270107 8004270110	80/03/20 80/04/16	CONTRACT 40-3453		8004270517 8004270524	8004290515 8004290338	80/04/25 80/04/17
8004270117	8004290110	80/04/16	40-3453		8004300005	8004300001	80/04/02
8004270121 8004290122	8004290110 8004290116	80/04/16 80/04/10	40-3453 50-324	q	8004300007 8004300008	8004300002 8004300004	80/03/11 80/03/10
8004290125 8004290128	8004270110 8004270116	80/04/16 80/04/10	40-3453 50-324	a	8004300009 8004300013	8004300006 8004300006	80/03/10 80/03/10
8004290135	8004270116	80/04/10	50-324	ä	Brossos.	000100000	00,00,10
8004270138	8004270137	80/04/11	50-313	P			
8004290141 8004290157	8004290116 8004290151	B0/04/10 B0/04/10	50-324 50-339	G G			
8004270176 8004270177	8004290148 8004290170	80/04/03 80/04/09	0A999 50-259	a			
8004290179	8004270168	80/04/03	QA999				
8004290186	B004290168 B004290168	80/04/03 80/04/03	0A999 QA999				
8004270201	8004290168	80/04/03	GA797				
8004270203	8004270168	80/04/03	QA999 QA999				
8004290212 8004290254	8004270148 8004270250	80/04/03 80/04/21	50-445	8			
8004290286 8004290303	8004270284 8004270297	80/04/21 80/04/21	50-348 50-245	P S			
8004270306	8004270278	80/04/17	50-266	ន			
8004290310 8004290316	B004270307	80/04/14 80/04/24	50-266 50-327	6			
8004290327 8004290335	8004270321 8004270327	80/04/23 80/04/24	50-305 50-328	8			
8004290336	8004270321	80/04/23	50-305	8			

ACCESS (OH	NUMBER					N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
					707400000	222422222		50 514	-
8004300045	8004300043	80/03/21	40-4492	_	8004300259 8004300260	8004300250 8004300205	80/04/04 80/04/07	50-344 50-269	a
8004300066	8004300006	80/03/10	50-387	Ģ	B004300264		80/04/04	50-344	p
8004300067	8004300006	80/03/10	50-387	G	8004300270		80/04/04	50-328	6
8004300068	8004300043	80/03/21	40-4492 50-387	G	8004300280		80/03/19	50-266	P
8004300069	8004300006	80/03/10	20-201	·	0004300200	2004300270	40/03/1/	J0-200	•
8004300070	8004300006	80/03/10	50-397	G	6004300285	8004300276	80/03/19	50-266	Р
8004300070	8004300000	80/03/10	50-397	Ğ	8004300287	8004300276	80/03/19	50-246	Р
8004300073	8004300006	80/03/10	50-38/	G	8004300290	8004300282	80/03/31	50-410	Q
8004300075	8004300043	80/03/21	40-4492		8004300296	8004300282	80/03/31	50-410	G.
8004300076	8004300006	80/03/10	50~387	0	8004300298	8004300273	80/02/29	50-397	Q.
				_					
8004300080	8004300006	80/03/10	50~387	٥	8004300299	8004300292	B0/04/11	50-3	U
8004300081	8004300043	80/03/21	40-4492		8004300301	8004300282	80/03/31	50-410	9
8004300083	8004300006	80/03/10	50-367	G	8004300309		80/03/31	50-410 50-225	Q.
8004300089	8004300006	80/03/10	50~387 QA999	G	8004300320		80/04/09 80/04/09	50-225	G G
2900E400B	8004300084	80/04/03	UATTT		B004300322	8004300317	80/04/07	20-552	•
8004300096	8004300090	80/04/09	50-566	a	8004300324	8004300317	80/04/09	50-225	æ
8004300078	8004300084	80/04/03	QA999	-	8004300328		80/04/09	50-225	ĕ
8004300100	8004300090	BO/04/09	50-546	Q	8004300337		80/04/08	50-306	ã
8004300103	8004300090	80/04/09	90~566	Ö	8004300350		80/04/28	50~546	Ā
8004300107	8004300084	80/04/03	0A979		8004300371		80/04/28	70-2909	
8004300108	8004300090	80/04/09	50-566	g	8004300376		80/04/24	50-352	6
8004300119	8004300112	80/04/07	50-395	Q	8004300376		80/04/28	70-2909	
8004300121	8004300117	80/01/31	50-528	Q.	8004300381		80/04/28	70-2909	_
8004300124	8004300112	80/04/07	50-375	0	8004300383		80/04/18	50-387	5
6004300128	8004300112	80/04/07	50-395	Q	8004300397	8004300390	80/04/24	50-518	8
8004300135	B004300112	80/04/07	50-395	Q	8004300419	8004300416	B0/04/25	50-247	Р
8004300151	8004300143	80/04/11	50-302	Q.	8004300423		80/04/25	50-247	P
8004300158	8004300143	80/04/11	50-302	ā	8004300433		80/04/04	50-312	à
8004300164	8004300143	80/04/11	50-302	0	8004300439		B0/04/04	50-312	G
8004300168	8004300162	B0/04/07	50-334	P	8004300448	8004300425	80/04/04	50-312	G
					202422042	8004300425	80/04/04	50-312	G
B004300171	8004300143	80/04/11	50-302 50-334	Q P	8004300453 8004300463		80/04/21	50-409	g
8004300174	8004300162	80/04/07 80/04/11	50-334 50-302	á	8004300474	8004300458	80/04/21	50-390	ū
8004300177	E4100E400B	80/04/11	50-483	ä	8004300484		80/04/08	50-395	ö
8004300178 8004300183	8004300162	E0/04/14	50-334	P	8004300493		80/04/08	50-375	ō
8004300183	800430018E	20104707	96.444	•	3507355473	404 1400 11 4			-
8004300184	8004300166	BO/04/14	50-483	Q	8004300519		80/04/07	90-350	0
8004300187	8004300143	80/04/11	50-302	a	8004300523	8004300514	80/03/21	50-498	a
8004300189	8004300166	80/04/14	50~483	Q	B004300528		80/03/21	50-544	٥
8004300194	8004300166	80/04/14	50-483	G	B004300536		B0/03/21	50-546	G
8004300214	8004300205	BO/04/07	50-247	0	8004300548	8004300544	80/03/21	50-10	Q
		00 (00 (07			0004000888	8004300544	80/03/21	50-10	G
8004300219	8004300215	80/03/27	WASTE MG	* *	8004300555 8004300586		B0/04/10	50-289	Ğ
8004300222	8004300217	80/03/05 80/03/26	50-244	Q	8004300590		80/04/18	50-272	Ğ
B004300227 B004300230	8004300223 8004300205	80/03/26	50-244	ä	800430059B		80/04/18	50-272	ă
8004300230	B004300203	80/03/26	50-244	Q.	8004300600		80/04/18	50-272	Ğ
3004300832	COUNTROLES	30,00,80	00 may	•	000100000				
8004300235	8004300223	80/03/26	50-244	G	8004300604		80/04/11	50-358	Œ
8004300237	8004300205	80/04/07	50-269	Q	8004300606		80/04/15	COMMISSI	
B004300244	8004300223	80/03/26	50-244	0	8004300607	8004300602	80/03/17	50-293	G
8004300245	8004300205	80/04/07	50-269	Q					
8004300255	8004300250	80/04/04	50-344	P					

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic another facility which may affect the subject
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical repo

B. UTILITY PRELIMINARY SAFETY ANALYS

This category is strictly limited to the items listed Category A.

- 1. Preliminary Safety Analysis Report (PSAR) si Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR)
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7 Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP)
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

ļ

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission Leview, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- Draft reports of action plans to accomplish generic tasks in the regulatory program.
 - with industry and internal correspondence regarding the methodologies, ogrammatic and technical aspects of issues.

ions and minutes.

and status reports on generic tasks addressing related aspects of generic

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria.
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professiona other than Regulatory Guides that pertain to the activiment; and emergency petitions not assigned Petition fo the Commission to take immediate action on some issu

 Meeting summaries and technical correspondence and international bodies, such as the Atomic Indu Energy Agency.

- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are.

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.
- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

l. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.

B. Utility PSAR and Amendments

- 1. PSARs submitted by the utility.
- 2. Amendments and changes to the PSAR.
- Transmittal letters.
- 4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

- 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.
- Q. Inspection Reports
 - 1. Inspection reports of the applicant's quality assurance program.
 - 2. Notices of deviations.
 - 3. Follow-up correspondence resolving deviations cited.

Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

Thus category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar Items and Policy Session Items.

NOTE. For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG — State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
 - Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility sixing.
 - . State Legislative Reports.
 - . Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and legulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.
- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.

- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC гоям 335 (7 77)	US NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1 REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol 2, No 4				
4 TITLE AND SUBT	ITLE (Add Volume No., if appropriate)		2 (Leave blank)				
Title Li	ist of Documents Made Publicly Availa April 1-30, 1980	ble	3 RECIPIENT'S ACCESSION NO				
7 AUTHOR(S)			5 DATE REPORT COMPLETED				
			MONTH May YEAR 1980				
9 PERFORMING OF	RGANIZATION NAME AND MAILING ADDRESS (Include	Zıp Code)	DATE REPORT ISSUED				
	f Technical Information and Document (ar Regulatory Commission	Control	MONTH July YEAR 1980				
Washington	, D.C. 20555		6 (Leave blank)				
			8 (Leave blank)				
12 SPONSORING O	RGANIZATION NAME AND MAILING ADDRESS (Include	Zıp Code)	10 PROJECT/TASK/WORK UNIT NO				
Division of	f Technical Information and Document (Control	TO THOSE OF TAUN, WORK GIVEN NO				
U.S. Nuclea	ar Regulatory Commission , D.C. 20555	ry Commission					
13 TYPE OF REPOR	RT	PERIOD COVER	RED (Inclusive dates)				
Monthly							
IS SUPPLEMENTAR	RY NOTES		14 (Leave plank)				
16 ABSTRACT (200) words or less)	<u> </u>					
This	s document is a monthly publication co	ontaining de	escriptions of				
info	ormation received and generated by the	e US NRC. T	This information				

includes (1) docketed material associated with civi plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through the U.S. Department of Energy's Technical Information Center under the title Power Reactor Docket Information (PRDI). This document replaces PRDI, which will no longer be prepared. This document contains the following indexes: Personal Author Index, Corporate Source Index, and Report Number Index.

17 KEY WORDS AND DOCUMENT ANALYSIS 17h IDENTIFIERS/OPEN-ENDED TERMS 19 SECURITY CLASS (Ins report) Unclassified 21 NO OF PAGES 18 AVAILABILITY STATEMENT 20 SECURITY CLASS (This page) Unclassified 22 PRICE Unlimited NRC FORM 335 (7 77)

17a DESCRIPTORS